

SEQU

GIP Report

NPS Guardwall/Rail Inventory Program
Sequoia National Park



Federal Lands Highway
Road Inventory Program

Prepared By:

Federal Highway Administration
Eastern Federal Lands Highway Division
Road Inventory Program (RIP)

Data Collection Date: October 2009
Report Date: November 2015

Sequoia National Park in California



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community
Esri, DeLorme, GEBCO, NOAA NGDC, and other contributors



Table of Contents

SECTION	PAGE NO.
1. INTRODUCTION	1 - 1
2. PARK BARRIER LOCATION MAPS Retaining Barrier Location Maps	2 - 1
3. TIER 1 - PARK BARRIER OVERVIEW	3 - 1
4. TIER 2 - ROUTE BARRIER OVERVIEW	4 - 1
5. TIER 3 - BARRIER DETAILS	5 - 1
6. APPENDIX A - SUMMARY OF GIP DEFINITIONS	A - 1

Introduction



Sequoia National Park



**Federal Lands Highway
Road Inventory Program**

Introduction

In support of the NPS Facility Management Software System (FMSS) asset management program, FHWA- contracted staff completed the Guardwall/Rail Inventory Program (GIP) inspections within selected National Park Service (NPS) units between 2010 and 2011. This inventory provides static information to FMSS regarding barrier characteristics such as height, length and location, as well as dynamic information about the condition of the barrier. In addition, when barrier deficiencies were identified, repair recommendations and estimated costs, suitable for use as FMSS work orders, were generated to bring the barrier back to its "new" condition.

In over 30 parks, numerous crashworthy barriers inspected maybe in poor condition by simply applying a new overlay of asphalt without milling previous layers. In instances such as this, basically the critical element of barrier height decreased as the elevation of the roadway increased. Resulting work orders were drafted to raise w-beam barriers or to remove and reset stone masonry barriers to their original design height.

This inventory provides static information and a condition assessment of each barrier inventoried. In addition, when barrier deficiencies were identified, repair recommendations and estimated costs were drafted to bring the barrier back to its "new" condition.

Drafted work orders have been classified as being either deferred maintenance or capital improvement. This classification is based on the type of work recommended, as defined below.

- *Deferred Maintenance* can be classified as repair or replace in kind. Work done to the barrier does not include any upgrading.
- *Capital Improvement* can be classified as upgrading part of or the entire existing barrier. Typically the upgrade will be from a non-crashworthy to a crashworthy device. Other examples of capital improvements would be the addition of a curb to improve drainage.

Care was taken to maintain the cultural significance of historic barriers located in the NPS. While historic traffic barriers likely would not withstand current crashworthiness performance criteria, they are considered by the NPS to be important resources for the historic and/or cultural value. Historic barriers may be "character defining features" that contribute to the cultural significance of historic roadways. As such, these barriers have resource value in and of themselves which may be somewhat independent from their functionality as barriers as previously defined. The consideration of both the crashworthiness and resource value of historic barriers was a significant challenge for the NPS and the FHWA when designing the GIP, to the point that for historic stone masonry barriers, the barrier height had to be more than 6-in below its design height before any work would be considered to deal with height issues. To preserve historic stone masonry barriers, typical drafted work orders for historic barriers were to remove and reset the barrier to the barrier's original design height on a concrete footer, as compared to replacing it with a similar crashworthy barrier.

This report is organized in a tiered approach from the broad park overview perspective (Tier 1) to a route overview perspective (Tier 2), then down to the details of each barrier (Tier 3). Tier 1 presents park barrier location maps and an overall park-specific summary narrative of the results of the guardwall/rail inventory program. Tier 2 presents route overview maps with associated barrier summary information. Tier 3 presents individual barrier information in a one-page detailed format, including a photograph of each barrier. Appendix A provides a condensed summary of guardwall/rail inventory definitions and assessment categories to assist in reading this report.

Park Barrier Location Maps



Sequoia National Park




Federal Lands Highway
Road Inventory Program

Sequoia National Park

BARRIER LOCATION MAP

Key Map



Sources: Esri, HERE, DeLorme, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

 RIP Collected Routes



Sequoia National Park


BARRIER LOCATION MAP

Map 1



Sources: Esri, HERE, DeLorme, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

- Barrier Locations
- RIP Collected Routes



Sequoia National Park

BARRIER LOCATION MAP

Map 2



Sources: Esri, HERE, DeLorme, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

● Barrier Locations


— RIP Collected Routes



Sequoia National Park

BARRIER LOCATION MAP


Map 3



Sources: Esri, HERE, DeLorme, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

 **Barrier Locations**


 **RIP Collected Routes**



Sequoia National Park

BARRIER LOCATION MAP

Map 4



Sources: Esri, HERE, DeLorme, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

● Barrier Locations


— RIP Collected Routes



Sequoia National Park

BARRIER LOCATION MAP

Map 5



Sources: Esri, HERE, DeLorme, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

- **Barrier Locations**
- **RIP Collected Routes**



Tier 1 Park Barrier Overview



Sequoia National Park



Federal Lands Highway
Road Inventory Program

Parkwide Summary: Sequoia National Park

Initial barrier inspections were conducted at Sequoia National Park in 2009, and encompassed all known barriers associated with Park roadways. In general, walls are not included in this assessment, but were inspected for Sequoia National Park in 2007 under a separate effort as part of the Retaining Wall Inventory Program (WIP). A report for WIP is available under separate cover.

All paved roadways and parking areas listed in the RIP Route Identification Report were inspected for barriers.

The following tables provide an overview of the findings of this inspection and assessment effort. In all, 75 barriers were inventoried on the routes listed below.

Table 1: Number of Barriers by Route

Route Number	Route Name	No. of Barriers
0010	GENERALS HIGHWAY HISTORIC	69
0100	CRYSTAL CAVE ROAD	5
0101	WUKSACHI ROAD	1

Due to the different GIP assessment criteria of barriers based on their intended use, barriers were classified as being either traffic barriers or non-traffic barriers.

- *Traffic* barriers are physical devices intended to keep vehicles or people from straying into dangerous or off-limits areas. For the purpose of this inventory, a traffic barrier is categorized as roadside hardware placed longitudinally, excluding pedestrian railing and fencing.
- *Non-traffic* barriers provide a physical delineation between public access areas and restricted or protected areas in locations such as a parking lot, viewpoint or turnout. **Non-traffic barriers which inhibit access of vehicles are included in this report; non-traffic barriers which only inhibit access of pedestrians or bicyclists are not included. For the purpose of this inventory, non-traffic barriers are guidewalls and guiderails. Note: rocks, stones, boulders, fences or curbs were excluded from this inventory.**

There are instances in parks where a single barrier can switch between being classified as a traffic barrier and a non-traffic barrier. Such instances typically occur at pullouts, where a traffic barrier along the road will continue through the pullout without interruption. In such instances, the traffic barrier and non-traffic barrier were assessed using different criteria. Due to the different criteria, the GIP database was designed to record the traffic barrier and non-traffic barrier as multiple distinct barriers, even though to the eye, they appear as one barrier. Other instances where a single barrier is split into multiple barriers would be when the barrier is placed continuously along two legs of an intersection, so that one portion of the barrier may be on one road and the remaining portion of the barrier is on a different road.

Table 2: Number of Barriers by Function

Barrier Function	No. of Barriers
TRAFFIC	73
NON-TRAFFIC	2

The following table shows the barrier types that were inventoried and assessed.

Table 3: Number of Barriers by Type

Primary Barrier Type	No. of Barriers
Other: Timber Rail On Timber Posts	1
W-Beam Weak Post	2
Stone Masonry With Concrete Core Wall	36
Other: Non-Standard Steel Barrier	9
Stone Masonry Without Concrete Core Wall	18
W-Beam Strong Post	9

The following table shows the number of barriers by one of four categories of recommended action along with associated work order costs and the number of barriers that are in each recommended action. All work order information is presented for individual barriers, even though some work orders were not accepted by the Park. Some work orders were later combined to simplify route deferred maintenance requests.

Table 4: Number of Barriers by Recommended Action and Associated 2008 Cost

Recommended Action	Repair Costs*	No. of Barriers
No Action	\$0	36
Monitor	\$0	0
Repair	\$2,665,143	31
Replace	\$167,127	8
Totals	\$2,832,270	75

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

The following table categorizes the number of barriers that fall into one of ten cost ranges, based on the prepared work orders. The locations, work descriptions, and cost of the recommended repairs for these barriers are listed by individual barrier in Tier 3 of this report.

Table 5: Number of Barriers Grouped by Associated 2008 Cost

Cost Range*	No. of Barriers
\$0	36
\$1 - \$25,000	16
\$25,001 - \$50,000	5
\$50,001 - \$100,000	8
\$100,001 - \$250,000	9
\$250,001 - \$500,000	1
\$500,001 - \$1,000,000	0
\$1,000,001 - \$2,000,000	0
\$2,000,001 - \$3,000,000	0
\$3,000,001 - \$4,000,000	0
Total Number of Barriers	75

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Data for end terminals was collected on the GIP data collection form and indicates if an end terminal meets current crashworthiness standards. End terminals are specially designed barrier ends that attenuate impacts to the ends of barriers. This is supplemental information that WASO designed into the inventory program.

A total of 9 end terminals were found on barriers at the Park. There are generally a greater number of end treatments than actual barriers because end treatments are located at both the beginning and end of each barrier.

Tier 2 Route Barrier Overview




Sequoia National Park



Federal Lands Highway
Road Inventory Program

Sequoia National Park

ROUTE 0010: GENERALS HIGHWAY HISTORIC




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0010-1.230-R 10/21/2009	157	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$198,880.00
SEQU-0010-1.264-R 10/21/2009	51	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-1.337-R 10/21/2009	597	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-1.498-R 10/21/2009	956	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-1.708-R 10/21/2009	350	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0010: GENERALS HIGHWAY HISTORIC




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0010-1.868-R 10/21/2009	707	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-2.169-R 10/21/2009	220	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-2.287-R 10/21/2009	169	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-2.375-R 10/21/2009	220	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-2.490-R 10/21/2009	190	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0010: GENERALS HIGHWAY HISTORIC




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0010-2.627-R 10/21/2009	243	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-3.936-R 10/21/2009	54	W-BEAM STRONG POST	NONE	NONE	\$2,283.00
SEQU-0010-3.941-L 10/21/2009	50	W-BEAM STRONG POST	NONE	NONE	\$2,206.00
SEQU-0010-3.980-L 10/21/2009	166	W-BEAM STRONG POST	NONE	NONE	\$3,856.00
SEQU-0010-4.132-R 10/21/2009	872	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0010: GENERALS HIGHWAY HISTORIC




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0010-4.531-R 10/21/2009	174	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-4.580-R 10/21/2009	121	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-4.615-R 10/21/2009	502	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-4.717-R 10/21/2009	576	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-4.898-R 10/21/2009	169	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0010: GENERALS HIGHWAY HISTORIC



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0010-5.005-R 10/21/2009	475	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-5.462-R 10/21/2009	143	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-5.593-R 10/21/2009	43	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-5.602-R 10/21/2009	51	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-5.685-R 10/21/2009	103	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0010: GENERALS HIGHWAY HISTORIC




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0010-5.810-R 10/21/2009	135	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-6.002-R 10/21/2009	1152	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$74,690.00
SEQU-0010-6.683-L 10/22/2009	267	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-7.306-L 10/22/2009	125	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$71,583.00
SEQU-0010-7.843-R 10/22/2009	337	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0010: GENERALS HIGHWAY HISTORIC



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0010-8.329-R 10/22/2009	379	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-9.464-L 10/22/2009	237	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-9.508-L 10/22/2009	111	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-10.835-L 10/22/2009	310	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0010-11.002-L 10/22/2009	1259	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0010: GENERALS HIGHWAY HISTORIC



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0010-11.255-R 10/22/2009	427	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$193,903.00
SEQU-0010-11.352-R 10/22/2009	189	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$167,475.00
SEQU-0010-11.394-R 10/22/2009	83	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$75,488.00
SEQU-0010-11.428-R 10/22/2009	46	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$34,018.00
SEQU-0010-11.447-R 10/22/2009	224	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$148,995.00

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0010: GENERALS HIGHWAY HISTORIC




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0010-11.504-R 10/22/2009	101	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$95,838.00
SEQU-0010-11.536-R 10/22/2009	165	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$160,628.00
SEQU-0010-11.618-R 10/22/2009	222	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$211,420.00
SEQU-0010-11.667-R 10/22/2009	172	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$131,230.00
SEQU-0010-11.712-R 10/22/2009	94	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$90,063.00

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0010: GENERALS HIGHWAY HISTORIC



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0010-11.730-R 10/22/2009	120	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$115,858.00
SEQU-0010-12.097-R 10/22/2009	82	W-BEAM STRONG POST	NONE	NONE	\$4,686.00
SEQU-0010-12.139-L 10/22/2009	246	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$108,158.00
SEQU-0010-12.196-L 10/22/2009	104	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$95,535.00
SEQU-0010-12.241-L 10/22/2009	70	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$68,640.00

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0010: GENERALS HIGHWAY HISTORIC



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0010-12.280-L 10/22/2009	166	W-BEAM STRONG POST	NONE	NONE	\$6,281.00
SEQU-0010-12.328-L 10/22/2009	184	W-BEAM STRONG POST	NONE	NONE	\$2,932.00
SEQU-0010-12.611-L 10/21/2009	180	W-BEAM STRONG POST	W-BEAM BCT	W-BEAM BCT	\$4,087.00
SEQU-0010-12.665-L 10/21/2009	724	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$452,788.00
SEQU-0010-12.851-L 10/21/2009	127	W-BEAM WEAK POST	W-BEAM BCT	W-BEAM BCT	\$4,279.00

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0010: GENERALS HIGHWAY HISTORIC



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0010-12.875-L 10/21/2009	666	W-BEAM WEAK POST	W-BEAM BCT	W-BEAM BCT	\$11,358.00
SEQU-0010-13.022-L 10/21/2009	242	W-BEAM STRONG POST	W-BEAM BCT	W-BEAM BCT	\$5,011.00
SEQU-0010-13.193-L 10/21/2009	84	OTHER: NON- STANDARD STEEL BARRIER	NONE	NONE	\$12,793.00
SEQU-0010-13.211-L 10/21/2009	162	OTHER: NON- STANDARD STEEL BARRIER	NONE	NONE	\$18,080.00
SEQU-0010-13.505-L 10/21/2009	212	OTHER: NON- STANDARD STEEL BARRIER	NONE	NONE	\$31,940.00

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0010: GENERALS HIGHWAY HISTORIC




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0010-13.545-L 10/21/2009	257	W-BEAM STRONG POST	NONE	NONE	\$6,474.00
SEQU-0010-13.621-L 10/21/2009	303	OTHER: NON-STANDARD STEEL BARRIER	NONE	NONE	\$26,300.00
SEQU-0010-14.280-L 10/21/2009	121	OTHER: NON-STANDARD STEEL BARRIER	NONE	NONE	\$14,625.00
SEQU-0010-15.216-L 10/21/2009	25	OTHER: TIMBER RAIL ON TIMBER POSTS	NONE	NONE	\$0.00
SEQU-0010-16.627-L 10/21/2009	124	OTHER: NON-STANDARD STEEL BARRIER	NONE	NONE	\$14,773.00

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0010: GENERALS HIGHWAY HISTORIC




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0010-19.043-L 10/21/2009	314	STONE MASONRY WITH CONCRETE CORE WALL	OTHER: STONE FLARED	NONE	\$0.00
SEQU-0010-26.290-R 10/20/2009	239	OTHER: NON- STANDARD STEEL BARRIER	NONE	NONE	\$20,466.00
SEQU-0010-30.215-R 10/20/2009	320	OTHER: NON- STANDARD STEEL BARRIER	NONE	NONE	\$27,720.00
SEQU-0010-30.939-R 10/20/2009	300	OTHER: NON- STANDARD STEEL BARRIER	NONE	NONE	\$26,730.00
*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.					

Sequoia National Park

ROUTE 0100: CRYSTAL CAVE ROAD




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0100-1.593-L 10/21/2009	60	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0100-1.607-L 10/21/2009	75	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0100-1.613-R 10/21/2009	44	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0100-1.634-L 10/21/2009	219	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00
SEQU-0100-1.644-R 10/21/2009	52	STONE MASONRY WITH CONCRETE CORE WALL	NONE	NONE	\$0.00

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0101: WUKSACHI ROAD



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Barrier ID Inspection Date	Barrier Length (Ft.)	Barrier Type	Barrier End Treatment		*Repair Cost
			Begin	End	
SEQU-0101-0.112-R 10/20/2009	185	STONE MASONRY WITHOUT CONCRETE CORE WALL	NONE	NONE	\$90,200.00

*2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Tier 3 Barrier Details



Sequoia National Park



**Federal Lands Highway
Road Inventory Program**

Barrier ID:	SEQU-0010-1.230-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	53.50		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	157		
Speed Limit (MPH):	15	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	LOW				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	19.2	Post Spacing (In.):	0.0
Height (In.):	13.6	Lateral Offset (In.):	17.2	Road Grade (%):	5.00
Physical Condition					
Barrier	Alignment and Height:	Alignment is off by less than 6 in. The height was 8 to 12 in below the 24-in design height.			
	Breaking and Cracking:	No major cracking 1 loose stone on top.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	Minor weathering of mortar.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-1.230-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	53.50

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$198880
Brief Workorder:	Raise guardwall 10-in. Remove and reset 157-ft of stone masonry guardwall on concrete footer to design height of 24-in.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 628 CF = \$157000. Remove and reset to 24 inches Structural Concrete at \$1000- per -Cu. Yd. for 12 CY = \$12000. Leveling pad Low Speed Traffic Control at \$1475- per -Day for 8 Day(s) = \$11800. low speed				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos

Condition photos are not available for SEQU-0010-1.230-R.

Barrier ID:	SEQU-0010-1.264-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	36.90		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	51		
Speed Limit (MPH):	15	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	LOW				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	19.2	Post Spacing (In.):	0.0
Height (In.):	18.2	Lateral Offset (In.):	52.2	Road Grade (%):	4.00
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height between 3 and 6-in below 24-in design height.			
	Breaking and Cracking:	Slight cracking in grout in a few areas about 1/8in no breaking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	Minor weathering some moss/lichen growing on stone.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-1.264-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:		36.90	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos

Condition photos are not available for SEQU-0010-1.264-R.

Barrier ID:	SEQU-0010-1.337-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	34.40		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	597		
Speed Limit (MPH):	15	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	26.0	Post Spacing (In.):	0.0
Height (In.):	29.2	Lateral Offset (In.):	41.5	Road Grade (%):	3.60
Physical Condition					
Barrier	Alignment and Height:	The alignment is off by less than 6 in. The height of the wall exceeds the design height of 27 in by 1-4 ins.			
	Breaking and Cracking:	No breaking or cracking.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-1.337-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	34.40

Repair Recommendations

Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_1.337_R_1.JPG

Barrier ID:	SEQU-0010-1.498-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	34.00		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	956		
Speed Limit (MPH):	15	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	26.5	Post Spacing (In.):	0.0
Height (In.):	28.5	Lateral Offset (In.):	17.2	Road Grade (%):	2.50
Physical Condition					
Barrier	Alignment and Height:	The alignment shows less than 6 in of deflection. The height of the wall exceeds the design height of 27 in by 0-4 ins.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-1.498-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:		34.00	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos

Condition photos are not available for SEQU-0010-1.498-R.

Barrier ID:	SEQU-0010-1.708-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	32.90		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	350		
Speed Limit (MPH):	15	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	27.0	Post Spacing (In.):	0.0
Height (In.):	29.0	Lateral Offset (In.):	18.2	Road Grade (%):	3.20
Physical Condition					
Barrier	Alignment and Height:	The alignment showed less than 6 in of deflection. The height of the wall was above the design height of 27 in by 1-3 ins.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-1.708-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:		32.90	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos

Condition photos are not available for SEQU-0010-1.708-R.

Barrier ID:	SEQU-0010-1.868-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	32.90		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	707		
Speed Limit (MPH):	15	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	25.5	Post Spacing (In.):	0.0
Height (In.):	28.0	Lateral Offset (In.):	20.0	Road Grade (%):	4.80
Physical Condition					
Barrier	Alignment and Height:	The alignment showed no deflection. The height of the wall is above the design height of 27 in by 0-2 in.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-1.868-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:		32.90	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_1.868_R_1.JPG

Barrier ID:	SEQU-0010-2.169-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	28.60		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	220		
Speed Limit (MPH):	15	Placement with Respect to Road:	INSIDE OF CURVE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	26.0	Post Spacing (In.):	0.0
Height (In.):	28.2	Lateral Offset (In.):	14.3	Road Grade (%):	6.10
Physical Condition					
Barrier	Alignment and Height:	The alignment showed no deflection. The height of the barrier was above the design height of 27 in by 1-2 in.			
	Breaking and Cracking:	No breaks or cracks.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-2.169-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:		28.60	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_2.169_R_1.JPG

Barrier ID:	SEQU-0010-2.287-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	21.30		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	169		
Speed Limit (MPH):	15	Placement with Respect to Road:	TANGENT		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	26.2	Post Spacing (In.):	0.0
Height (In.):	29.0	Lateral Offset (In.):	23.0	Road Grade (%):	5.30
Physical Condition					
Barrier	Alignment and Height:	The alignment showed no deflection. The height of the barrier exceeds the design height of 27 in by 1 in.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-2.287-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	21.30

Repair Recommendations

Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_2.287_R_1.JPG

Barrier ID:	SEQU-0010-2.375-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	25.50		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	220		
Speed Limit (MPH):	15	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	26.6	Post Spacing (In.):	0.0
Height (In.):	29.2	Lateral Offset (In.):	24.2	Road Grade (%):	4.40
Physical Condition					
Barrier	Alignment and Height:	The alignment showed no deflection. The height was above the design height of 27 in by 2-3 in.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-2.375-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:		25.50	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_2.375_R_1.JPG

Barrier ID:	SEQU-0010-2.490-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	28.20		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	190		
Speed Limit (MPH):	15	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	27.0	Post Spacing (In.):	0.0
Height (In.):	29.6	Lateral Offset (In.):	19.2	Road Grade (%):	7.40
Physical Condition					
Barrier	Alignment and Height:	The alignment showed no deflection. The height of the barrier exceeds the design height of 27 in by 2-3 in.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-2.490-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	28.20

Repair Recommendations

Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_2.490_R_1.JPG

Barrier ID:	SEQU-0010-2.627-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	28.20		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	243		
Speed Limit (MPH):	15	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	26.2	Post Spacing (In.):	0.0
Height (In.):	29.6	Lateral Offset (In.):	18.2	Road Grade (%):	5.60
Physical Condition					
Barrier	Alignment and Height:	The alignment was off by less than 6 in. The height is above the design height of 27 in by 2-4 in.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-2.627-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:		28.20	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_2.627_R_1.JPG

Barrier ID:	SEQU-0010-3.936-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	32.40		
Barrier Description					
Type:	W-BEAM STRONG POST	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	WOOD		
Blockout Type:	WOOD	Length (ft.):	54		
Speed Limit (MPH):	25	Placement with Respect to Road:	TANGENT		
Hazard Behind Barrier:	MEDIUM				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	75.0
Height (In.):	21.7	Lateral Offset (In.):	43.2	Road Grade (%):	0.30
Physical Condition					
Barrier	Alignment and Height:	Alignment is acceptable. Entire barrier is between 4-7in below the 27-in design height.			
	Breaking and Cracking:	Two blocks are broken in half.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	W-Beam is rusted with moss/lichen growing on it.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-3.936-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	32.40

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$2283
Brief Workorder:	Raise 54 feet of barrier up to 27-in design height. Replace two blocks.				
Workorder:	Adjust Guardrail at \$10- per -Lin. Ft. for 54 LF = \$540. Raise 54-ft of barrier up to 27-in design height. Replace block at \$30- per -Each for 2 Block(s) = \$60. Low Speed Traffic Control at \$1475- per -Day for 1 Day(s) = \$1475.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos

Condition photos are not available for SEQU-0010-3.936-R.

Barrier ID:	SEQU-0010-3.941-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	18.50		
Barrier Description					
Type:	W-BEAM STRONG POST	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	WOOD		
Blockout Type:	WOOD	Length (ft.):	50		
Speed Limit (MPH):	25	Placement with Respect to Road:	TANGENT		
Hazard Behind Barrier:	LOW				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	74.3
Height (In.):	23.0	Lateral Offset (In.):	52.0	Road Grade (%):	1.20
Physical Condition					
Barrier	Alignment and Height:	Alignment was off by less than 6 in. Entire barrier is between 2-7in below the 27-in design height.			
	Breaking and Cracking:	Small cracks less than 1/2 in. 1 broken block.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	Minor weathering on all blocks and posts.			
End Treatments	Alignment and Height:	Alignment acceptable. Height is within 1-in of 27-in design height.			
	Breaking and Cracking:	Spoon on end is bent.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			

Barrier ID:	SEQU-0010-3.941-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	18.50

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$2206
Brief Workorder:	Raise 50 feet of barrier to 27 inch design height. Replace 1 block.				
Workorder:	Adjust Guardrail at \$10- per -Lin. Ft. for 50 LF = \$500. Raise 50-ft of barrier up to 27-in design height. Replace block at \$30- per -Each for 1 Block(s) = \$30. Low Speed Traffic Control at \$1475- per -Day for 1 Day(s) = \$1475.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_3.941_L_1.JPG

Barrier ID:	SEQU-0010-3.980-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	35.50		
Barrier Description					
Type:	W-BEAM STRONG POST	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	WOOD		
Blockout Type:	WOOD	Length (ft.):	166		
Speed Limit (MPH):	25	Placement with Respect to Road:	TANGENT		
Hazard Behind Barrier:	LOW				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	75.0
Height (In.):	21.6	Lateral Offset (In.):	53.2	Road Grade (%):	6.20
Physical Condition					
Barrier	Alignment and Height:	Alignment has less than 6 in of deflection. Entire barrier is between 4-6in below the 27-in design height.			
	Breaking and Cracking:	2 broken and 3 cracked blocks over 1/2 in. 1 cracked post over 1/2 inch.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	Minor weathering on all posts and blocks.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-3.980-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	35.50

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$3856
Brief Workorder:	Raise 166 feet of W-beam to 27-in design height. Replace 1 post 5 blocks tighten loose hardware and re-orientate blocks.				
Workorder:	Adjust Guardrail at \$10- per -Lin. Ft. for 166 LF = \$1660. Raise 166-ft of barrier up to 27-in design height. Replace post at \$100- per -Each for 1 Post(s) = \$100. Replace block at \$30- per -Each for 5 Block(s) = \$150. Labor at \$60- per -Hour for 2 Hrs = \$120. Tighten loose hardware and re-orientate tilted blocks. Low Speed Traffic Control at \$1475- per -Day for 1 Day(s) = \$1475.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos

Condition photos are not available for SEQU-0010-3.980-L.

Barrier ID:	SEQU-0010-4.132-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	34.00		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	872		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	27.0	Lateral Offset (In.):	20.6	Road Grade (%):	8.20
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Entire barrier is between 1-in below to 1-in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-4.132-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:		34.00	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos

Condition photos are not available for SEQU-0010-4.132-R.

Barrier ID:	SEQU-0010-4.531-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	22.60		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	174		
Speed Limit (MPH):	25	Placement with Respect to Road:	INSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	28.0	Lateral Offset (In.):	15.3	Road Grade (%):	7.80
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Entire barrier is between 1-in below to 1-in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-4.531-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:		22.60	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_4.531_R_1.JPG

Barrier ID:	SEQU-0010-4.580-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	25.50		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	121		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	28.0	Lateral Offset (In.):	26.2	Road Grade (%):	8.20
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Entire barrier is between 1-in below to 1-in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-4.580-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	25.50

Repair Recommendations

Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_4.580_R_1.JPG

Barrier ID:	SEQU-0010-4.615-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	32.90		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	502		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	28.2	Lateral Offset (In.):	14.3	Road Grade (%):	8.30
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 1-2in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-4.615-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	32.90

Repair Recommendations

Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_4.615_R_1.JPG

Barrier ID:	SEQU-0010-4.717-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	32.90		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	576		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	27.2	Lateral Offset (In.):	15.0	Road Grade (%):	8.70
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Entire barrier is between 1-in below to 1-in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-4.717-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:		32.90	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_4.717_R_1.JPG

Barrier ID:	SEQU-0010-4.898-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	24.20		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	169		
Speed Limit (MPH):	25	Placement with Respect to Road:	INSIDE OF CURVE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	29.0	Lateral Offset (In.):	15.3	Road Grade (%):	9.10
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 0-2in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-4.898-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:		24.20	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_4.898_R_1.JPG

Barrier ID:	SEQU-0010-5.005-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	28.30		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	475		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	28.2	Lateral Offset (In.):	34.0	Road Grade (%):	6.00
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 0-2in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-5.005-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	28.30

Repair Recommendations

Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_5.005_R_1.JPG

Barrier ID:	SEQU-0010-5.462-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	31.20		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	143		
Speed Limit (MPH):	25	Placement with Respect to Road:	INSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	26.2	Lateral Offset (In.):	17.7	Road Grade (%):	7.80
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Entire barrier is between 0-1in below the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-5.462-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	31.20

Repair Recommendations

Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_5.462_R_1.JPG

Barrier ID:	SEQU-0010-5.593-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	7.00		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	NON-TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	43		
Speed Limit (MPH):	25	Placement with Respect to Road:	NON-TRAFFIC BARRIER		
Hazard Behind Barrier:	N/A				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	N/A
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	28.0	Lateral Offset (In.):	156.0	Road Grade (%):	0.00
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 1 in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-5.593-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	7.00

Repair Recommendations

Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_5.593_R_1.JPG

Barrier ID:	SEQU-0010-5.602-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	7.00		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	NON-TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	51		
Speed Limit (MPH):	25	Placement with Respect to Road:	NON-TRAFFIC BARRIER		
Hazard Behind Barrier:	N/A				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	N/A
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	22.7	Post Spacing (In.):	0.0
Height (In.):	26.7	Lateral Offset (In.):	21.2	Road Grade (%):	0.00
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 1 in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-5.602-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	7.00

Repair Recommendations

Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_5.602_R_1.JPG

Barrier ID:	SEQU-0010-5.685-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	25.50		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	103		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	29.0	Lateral Offset (In.):	24.0	Road Grade (%):	6.20
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 1 in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-5.685-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:		25.50	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_5.685_R_1.JPG

Barrier ID:	SEQU-0010-5.810-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	36.90		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	135		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	27.0	Lateral Offset (In.):	20.6	Road Grade (%):	6.40
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was at the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-5.810-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:		36.90	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_5.810_R_1.JPG

Barrier ID:	SEQU-0010-6.002-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	38.40		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	1152		
Speed Limit (MPH):	25	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	22.7	Post Spacing (In.):	0.0
Height (In.):	26.7	Lateral Offset (In.):	21.2	Road Grade (%):	6.50
Physical Condition					
Barrier	Alignment and Height:	Alignment had no deflection. Barrier was comprised of 2 distinct barriers. The first had a concrete core for 975 ft and was 0-2in above the 27-in design height. The second did not have a core was 177 ft long and 3-8in below the 24-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	Minor weathering moss/lichen growth toward end.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-6.002-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	38.40

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$74690
Brief Workorder:	Raise guardwall 2-in. Remove and reset 62-ft of stone masonry guardwall on concrete footer to adjacent 18-in height.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 236 CF = \$59000. [(2ft)(1.9ft)(62ft)] = 235.6 CF. Structural Concrete at \$1000- per -Cu. Yd. for 3 CY = \$3000. [(1.9ft)(0.5ft)(62ft)] /27 = 2.2 CY. Low Speed Traffic Control at \$1475- per -Day for 4 Day(s) = \$5900. 1 day removal 3 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_6.002_R_1.JPG

Barrier ID:	SEQU-0010-6.683-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	25.10		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	267		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	MEDIUM				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	27.7	Lateral Offset (In.):	51.7	Road Grade (%):	5.40
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 0-2in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-6.683-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:		25.10	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_6.683_L_1.JPG

Barrier ID:	SEQU-0010-7.306-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	55.20		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	125		
Speed Limit (MPH):	15	Placement with Respect to Road:	TANGENT		
Hazard Behind Barrier:	MEDIUM				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	17.2	Post Spacing (In.):	0.0
Height (In.):	11.3	Lateral Offset (In.):	15.0	Road Grade (%):	6.90
Physical Condition					
Barrier	Alignment and Height:	Alignment was off by less than 6 in. Height was 12-13in below the 24-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-7.306-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	55.20

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$71583
Brief Workorder:	Raise guardwall 12-in. Remove and reset 125-ft of stone masonry guardwall on 2 rows of new stone to raise barrier to the 24-in design height.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 94 CF = \$23500. [(0.5ft)(1.5ft)(125ft)] = 93.8 CF. Remove top layer of stones for 125-ft. Replace Stones at \$250- per -Each for 125 Unit(s) = \$31250. [(125ft) / (2 ft/stone)] x 2 rows = 125 stones. Insert new stone on retaining wall to increase barrier height then reset top layer of barrier. Low Speed Traffic Control at \$1475- per -Day for 7 Day(s) = \$10325. 2 days removal 5 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_7.306_L_1.JPG

Barrier ID:	SEQU-0010-7.843-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	23.70		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	337		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	MEDIUM				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	28.7	Lateral Offset (In.):	45.7	Road Grade (%):	5.20
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 0-4in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-7.843-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	23.70

Repair Recommendations

Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_7.843_R_1.JPG

Barrier ID:	SEQU-0010-8.329-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	22.60		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	379		
Speed Limit (MPH):	25	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	26.6	Lateral Offset (In.):	48.5	Road Grade (%):	5.20
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Entire barrier is between 2-in below to 1-in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-8.329-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:		22.60	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_8.329_R_1.JPG

Barrier ID:	SEQU-0010-9.464-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	34.00		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	237		
Speed Limit (MPH):	25	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	27.7	Lateral Offset (In.):	16.2	Road Grade (%):	7.20
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 0-1 in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-9.464-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:		34.00	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos

Condition photos are not available for SEQU-0010-9.464-L.

Barrier ID:	SEQU-0010-9.508-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	28.20		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	111		
Speed Limit (MPH):	25	Placement with Respect to Road:	INSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	26.7	Lateral Offset (In.):	22.2	Road Grade (%):	9.50
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Entire barrier is between 0-1in below the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-9.508-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	28.20

Repair Recommendations

Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos

Condition photos are not available for SEQU-0010-9.508-L.

Barrier ID:	SEQU-0010-10.835-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	36.90		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	310		
Speed Limit (MPH):	25	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.2	Post Spacing (In.):	0.0
Height (In.):	29.0	Lateral Offset (In.):	22.6	Road Grade (%):	7.30
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 1-2in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-10.835-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	36.90

Repair Recommendations

Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_10.835_L_1.JPG

Barrier ID:	SEQU-0010-11.002-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	41.40		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	1259		
Speed Limit (MPH):	25	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	24.0	Post Spacing (In.):	0.0
Height (In.):	28.0	Lateral Offset (In.):	20.3	Road Grade (%):	6.20
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Entire barrier is between 1-in below to 3-in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking.			
	Missing Elements:	No missing elements.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-11.002-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	41.40

Repair Recommendations

Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_11.002_L_1.JPG

Barrier ID:	SEQU-0010-11.255-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	27.00		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	427		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	21.6	Post Spacing (In.):	0.0
Height (In.):	23.2	Lateral Offset (In.):	59.2	Road Grade (%):	7.50
Physical Condition					
Barrier	Alignment and Height:	Barrier was comprised of 2 barriers. The first had a concrete core was 255ft long within 1-in of 27-in design height, alignment acceptable. The second had no core, was 172 ft long, 6-9in below 24-in design height, alignment was off by 6-12in.			
	Breaking and Cracking:	No breaking or cracking of new stone. Large cracks and broken stones on old section of barrier.			
	Missing Elements:	Several missing stones from the front and top of old barrier.			
	Corrosion and Weathering:	Weathered mortar on old barrier.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-11.255-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	27.00

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$193903
Brief Workorder:	Raise guardwall 8-in. Remove and reset 172-ft of stone masonry guardwall on concrete footer to design height of 24-in.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 620 CF = \$155000. [(2ft)(1.8ft)(172ft)] = 619.2 CF. Structural Concrete at \$1000- per -Cu. Yd. for 8 CY = \$8000. [(1.8ft)(0.67ft)(172ft)] /27 = 7.7 CY. Low Speed Traffic Control at \$1475- per -Day for 9 Day(s) = \$13275. 2 days removal 7 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos

Condition photos are not available for SEQU-0010-11.255-R.

Barrier ID:	SEQU-0010-11.352-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	41.50		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	189		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	16.2	Post Spacing (In.):	0.0
Height (In.):	20.2	Lateral Offset (In.):	19.2	Road Grade (%):	7.10
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height between 3 and 6-in below 24-in design height.			
	Breaking and Cracking:	Cracking of grout throughout barrier.			
	Missing Elements:	Scores of missing stones and mortar.			
	Corrosion and Weathering:	Highly weathered grout. Minimal erosion on back side of barrier.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-11.352-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	41.50

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$167475
Brief Workorder:	Raise guardwall 4-in. Remove and reset 189-ft of stone masonry guardwall on concrete footer to design height of 24-in.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 530 CF = \$132500. [(2ft)(1.4ft)(189ft)] = 529.2 CF. Structural Concrete at \$1000- per -Cu. Yd. for 5 CY = \$5000. [(1.4ft)(0.5ft)(189ft)] /27 = 4.9 CY. Low Speed Traffic Control at \$1475- per -Day for 10 Day(s) = \$14750. 2 days removal 8 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos

Condition photos are not available for SEQU-0010-11.352-R.

Barrier ID:	SEQU-0010-11.394-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	44.40		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	83		
Speed Limit (MPH):	25	Placement with Respect to Road:	INSIDE OF CURVE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	16.7	Post Spacing (In.):	0.0
Height (In.):	17.7	Lateral Offset (In.):	21.0	Road Grade (%):	6.00
Physical Condition					
Barrier	Alignment and Height:	Alignment off by 6 in. Height was 6-7in below the 24-in design height.			
	Breaking and Cracking:	Breaking and cracking of mortar throughout.			
	Missing Elements:	Scores of missing stones.			
	Corrosion and Weathering:	Wall is highly weathered. Minimal erosion on back side of wall.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-11.394-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	44.40

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$75488
Brief Workorder:	Raise guardwall 6-in. Remove and reset 83-ft of stone masonry guardwall on concrete footer to design height of 24-in.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 233 CF = \$58250. [(2ft)(1.4ft)(83ft)] = 232.4 CF. Structural Concrete at \$1000- per -Cu. Yd. for 3 CY = \$3000. [(1.4ft)(0.5ft)(83ft)] /27 = 2.2 CY. Low Speed Traffic Control at \$1475- per -Day for 5 Day(s) = \$7375. 1 day removal 4 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_11.394_R_1.JPG

Barrier ID:	SEQU-0010-11.428-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	58.70		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	46		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	19.0	Post Spacing (In.):	0.0
Height (In.):	7.0	Lateral Offset (In.):	21.2	Road Grade (%):	5.70
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 16-18in below the 24-in design height			
	Breaking and Cracking:	Minimal cracking or mortar. No breakage.			
	Missing Elements:	Two missing stones.			
	Corrosion and Weathering:	Minimal weathering and no erosion.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-11.428-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	58.70

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$34018
Brief Workorder:	Raise guardwall 16-in. Remove and reset 46-ft of stone masonry guardwall on 3 rows of new stone to raise barrier to the 24-in design height.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 37 CF = \$9250. $[(0.5\text{ft})(1.6\text{ft})(46\text{ft})] = 36.8 \text{ CF}$. Remove top layer of stones for 46 feet. Replace Stones at \$250- per -Each for 69 Unit(s) = \$17250. $[(46\text{ft}) / (2 \text{ ft/stone})] \times 3 \text{ rows} = 69 \text{ stones}$. Insert new stone on retaining wall to increase barrier height then reset top layer of barrier. Low Speed Traffic Control at \$1475- per -Day for 3 Day(s) = \$4425. 1 day removal 2 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_11.428_R_1.JPG

Barrier ID:	SEQU-0010-11.447-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	61.20		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	224		
Speed Limit (MPH):	15	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	18.2	Post Spacing (In.):	0.0
Height (In.):	8.7	Lateral Offset (In.):	15.3	Road Grade (%):	7.20
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 3-21in below the 24-in design height			
	Breaking and Cracking:	Some small stones are breaking off.			
	Missing Elements:	Some small missing stones throughout the section.			
	Corrosion and Weathering:	Grout was weathering some moss/lichen growth on stones.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-11.447-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	61.20

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$148995
Brief Workorder:	Raise guardwall 18-in. Remove and reset 209-ft of stone masonry guardwall on 3 rows of new stone to raise barrier to the adjacent 18-in height.				
Workorder:	<p>Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 157 CF = \$39250. $[(0.5ft)(1.5ft)(209ft)] = 156.8$ CF.</p> <p>Remove top layer of stones in barrier for 209 feet.</p> <p>Replace Stones at \$250- per -Each for 314 Unit(s) = \$78500. $[(209ft) / (2 ft/stone)] \times 3$ rows = 314 stones. Insert new stone on retaining wall to increase barrier height then reset top layer of barrier.</p> <p>Low Speed Traffic Control at \$1475- per -Day for 12 Day(s) = \$17700. 3 days removal 9 days installation.</p>				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_11.447_R_1.jpg

Barrier ID:	SEQU-0010-11.504-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	49.20		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	101		
Speed Limit (MPH):	15	Placement with Respect to Road:	INSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	18.2	Post Spacing (In.):	0.0
Height (In.):	15.6	Lateral Offset (In.):	17.0	Road Grade (%):	3.80
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 8-9in below the 24-in design height			
	Breaking and Cracking:	Some stones are breaking off in spots.			
	Missing Elements:	A few small missing stones throughout the wall.			
	Corrosion and Weathering:	Some moss/lichen growing on stone grout is corroding/weathering.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-11.504-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	49.20


Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$95838
Brief Workorder:	Raise guardwall 8-in. Remove and reset 101-ft of stone masonry guardwall on concrete footer to design height of 24-in.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 303 CF = \$75750. [(2ft)(1.5ft)(101ft)] = 303 Cf. Structural Concrete at \$1000- per -Cu. Yd. for 4 CY = \$4000. [(1.5ft)(0.67ft)(101ft)] /27 = 3.8 CY. Low Speed Traffic Control at \$1475- per -Day for 5 Day(s) = \$7375. 1 day removal 4 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_11.504_R_1.jpg

Barrier ID:	SEQU-0010-11.536-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	54.90		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	165		
Speed Limit (MPH):	15	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	18.2	Post Spacing (In.):	0.0
Height (In.):	13.3	Lateral Offset (In.):	18.0	Road Grade (%):	2.80
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 8-14in below the 24-in design height			
	Breaking and Cracking:	Breaking and cracking throughout barrier.			
	Missing Elements:	Several rocks are missing throughout barrier.			
	Corrosion and Weathering:	Some lichen and moss growing on wall. No corrosion visible to the eye.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-11.536-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	54.90

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$160628
Brief Workorder:	Raise guardwall 11-in. Remove and reset 165-ft of stone masonry guardwall on concrete footer to design height of 24-in.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 495 CF = \$123750. [(2ft)(1.5ft)(165ft)] = 495 CF. Structural Concrete at \$1000- per -Cu. Yd. for 9 CY = \$9000. [(1.5ft)(0.9ft)(165ft)] /27 = 8.3 CY. Low Speed Traffic Control at \$1475- per -Day for 9 Day(s) = \$13275. 2 days removal 7 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_11.536_R_1.jpg

Barrier ID:	SEQU-0010-11.618-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	54.90		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	222		
Speed Limit (MPH):	15	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	18.0	Post Spacing (In.):	0.0
Height (In.):	16.5	Lateral Offset (In.):	16.0	Road Grade (%):	2.00
Physical Condition					
Barrier	Alignment and Height:	The alignment is is off by 6 to 12 in. 70ft was 6-in below the 24-in design height and 152ft was 7-9in below the design height.			
	Breaking and Cracking:	There is approximately 180 LF of breaking or cracked grout and stone along wall.			
	Missing Elements:	There are about 15 SF of rock and grout missing along wall.			
	Corrosion and Weathering:	Freeze/thaw and falling rock are the causes of weathering. No corrosion.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-11.618-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	54.90

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$211420
Brief Workorder:	Raise guardwall 7-in. Remove and reset 222-ft of stone masonry guardwall on concrete footer to design height of 24-in.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 666 CF = \$166500. [(2ft)(1.5ft)(222ft)] = 666 CF. Structural Concrete at \$1000- per -Cu. Yd. for 8 CY = \$8000. [(1.5ft)(0.6ft)(222ft)] /27 = 7.4 CY. Low Speed Traffic Control at \$1475- per -Day for 12 Day(s) = \$17700. 3 days removal 9 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_11.618_R_1.jpg

Barrier ID:	SEQU-0010-11.667-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	46.20		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	172		
Speed Limit (MPH):	15	Placement with Respect to Road:	TANGENT		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	17.0	Post Spacing (In.):	0.0
Height (In.):	15.6	Lateral Offset (In.):	18.7	Road Grade (%):	0.70
Physical Condition					
Barrier	Alignment and Height:	The alignment is off by 6 to 12 in. The height is 3-6in below the 24-in design height for 34ft and 7-10in below for 138ft.			
	Breaking and Cracking:	Throughout the entire 172 ft there is breaking and cracking do to freeze/thaw cycles and rock falling across the road.			
	Missing Elements:	Several missing stones along entire 172 feet of barrier.			
	Corrosion and Weathering:	Freeze thaw and falling rock are the causes of weathering. No corrosion.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-11.667-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	46.20

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$131230
Brief Workorder:	Raise guardwall 3-in. Remove and reset 138-ft of stone masonry guardwall on concrete footer to adjacent 18-in height.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 414 CF = \$103500. [(2ft)(1.5ft)(138ft)] = 414 CF. Structural Concrete at \$1000- per -Cu. Yd. for 4 CY = \$4000. [(1.5ft)(0.5ft)(138ft)] /27 = 3.8 CY. Low Speed Traffic Control at \$1475- per -Day for 8 Day(s) = \$11800. 2 days removal 6 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_11.667_R_1.jpg

Barrier ID:	SEQU-0010-11.712-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	54.90		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	94		
Speed Limit (MPH):	15	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	17.0	Post Spacing (In.):	0.0
Height (In.):	16.7	Lateral Offset (In.):	22.2	Road Grade (%):	1.70
Physical Condition					
Barrier	Alignment and Height:	Alignment has deflection 6 in or less. Height was 7-8in below the 24-in design height.			
	Breaking and Cracking:	There was one 2in crack 17" long vertically.			
	Missing Elements:	A couple of missing stones about 2' by 2'.			
	Corrosion and Weathering:	Grout weathering away with some lichen/moss growing on the stones.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-11.712-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	54.90

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$90063
Brief Workorder:	Raise guardwall 7-in. Remove and reset 94-ft of stone masonry guardwall on concrete footer to design height of 24-in.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 282 CF = \$70500. [(2ft)(1.5ft)(94ft)] = 282 CF. Structural Concrete at \$1000- per -Cu. Yd. for 4 CY = \$4000. [(1.5ft)(0.6ft)(94ft)] /27 = 3.1 CY. Low Speed Traffic Control at \$1475- per -Day for 5 Day(s) = \$7375. 1 day removal 4 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_11.712_R_1.jpg

Barrier ID:	SEQU-0010-11.730-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	52.00		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	120		
Speed Limit (MPH):	15	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	18.2	Post Spacing (In.):	0.0
Height (In.):	15.5	Lateral Offset (In.):	25.2	Road Grade (%):	3.40
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 7-11 in below the 24-in design height.			
	Breaking and Cracking:	One 3in wide crack about 16" long vertically.			
	Missing Elements:	2' of wall missing at approach end.			
	Corrosion and Weathering:	Grout weathering away.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-11.730-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	52.00

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$115858
Brief Workorder:	Raise guardwall 8-in. Remove and reset 120-ft of stone masonry guardwall on concrete footer to design height of 24-in.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 360 CF = \$90000. [(2ft)(1.5ft)(120ft)] = 360 CF. Structural Concrete at \$1000- per -Cu. Yd. for 5 CY = \$5000. [(1.5ft)(0.67ft)(120ft)] /27 = 4.5 CY. Low Speed Traffic Control at \$1475- per -Day for 7 Day(s) = \$10325. 2 days removal 5 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_11.730_R_1.jpg

Barrier ID:	SEQU-0010-12.097-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	24.10		
Barrier Description					
Type:	W-BEAM STRONG POST	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	CORTEN		
Blockout Type:	WOOD	Length (ft.):	82		
Speed Limit (MPH):	15	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	0.0
Height (In.):	32.0	Lateral Offset (In.):	94.3	Road Grade (%):	8.10
Physical Condition					
Barrier	Alignment and Height:	Alignment is off by 6 to 12 in except for 24 ft which has less than 6 in deflection. Height was 5in above the 27 in design height.			
	Breaking and Cracking:	7 broken blocks 3 broken posts 52 ft of broken rail.			
	Missing Elements:	1 missing block.			
	Corrosion and Weathering:	Minor surface rusting.			
End Treatments	Alignment and Height:	Alignment acceptable. Height was 5-in above the 27-in design height.			
	Breaking and Cracking:	Approach end treatment bent.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	Minor surface rusting.			

Barrier ID:	SEQU-0010-12.097-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	24.10

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$4686
Brief Workorder:	Replace 52 feet of existing guardrail 8 blocks and 3 posts. Realign 82 feet of barrier.				
Workorder:	Replace rail at \$25- per -Lin. Ft. for 52 LF = \$1300. Replace block at \$30- per -Each for 8 Block(s) = \$240. Replace post at \$100- per -Each for 3 Post(s) = \$300. Adjust Guardrail at \$10- per -Lin. Ft. for 82 LF = \$820. Realign 82 feet of guardrail. Loader at \$125- per -Hour for 1 Hrs = \$125. Remove built up soil/material in front of guardrail. Low Speed Traffic Control at \$1475- per -Day for 1 Day(s) = \$1475.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_12.097_R_1.jpg

Barrier ID:	SEQU-0010-12.139-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	57.00		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	246		
Speed Limit (MPH):	15	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	17.0	Post Spacing (In.):	0.0
Height (In.):	17.2	Lateral Offset (In.):	0.0	Road Grade (%):	6.70
Physical Condition					
Barrier	Alignment and Height:	The alignment is within 6 in. Height was 4-6in below the 24-in design height for 134 ft and 7-8in below for 112 ft.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	A few stones are missing along barrier.			
	Corrosion and Weathering:	Some lichen growing on wall grout is loosening up do to freeze/thaw cycle.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-12.139-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	57.00

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$108158
Brief Workorder:	Raise guardwall 2-in. Remove and reset 112-ft of stone masonry guardwall on concrete footer to adjacent 18-in height.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 336 CF = \$84000. [(2ft)(1.5ft)(112ft)] = 336 CF. Structural Concrete at \$1000- per -Cu. Yd. for 4 CY = \$4000. [(1.5ft)(0.5ft)(112ft)] /27 = 3.1 CY. Low Speed Traffic Control at \$1475- per -Day for 7 Day(s) = \$10325. 2 days removal 5 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_12.139_L_1.jpg

Barrier ID:	SEQU-0010-12.196-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	53.50		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	104		
Speed Limit (MPH):	15	Placement with Respect to Road:	INSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	16.0	Post Spacing (In.):	0.0
Height (In.):	15.6	Lateral Offset (In.):	22.2	Road Grade (%):	5.90
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 7-10in below the 24-in design height			
	Breaking and Cracking:	3 ft at end is broken.			
	Missing Elements:	A few small various missing minor stones.			
	Corrosion and Weathering:	Some grouting starting to corrode and come apart moss/lichen growing on the stone.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-12.196-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	53.50

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$95535
Brief Workorder:	Raise guardwall 9-in. Remove and reset 104-ft of stone masonry guardwall on concrete footer to design height of 24-in.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 292 CF = \$73000. [(2ft)(1.4ft)(104ft)] = 291.2 CF. Structural Concrete at \$1000- per -Cu. Yd. for 5 CY = \$5000. [(1.4ft)(0.75ft)(104ft)] /27 = 4.1 CY. Low Speed Traffic Control at \$1475- per -Day for 6 Day(s) = \$8850. 1 day removal 5 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_12.196_L_1.jpg

Barrier ID:	SEQU-0010-12.241-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	57.70		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	70		
Speed Limit (MPH):	15	Placement with Respect to Road:	INSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	17.0	Post Spacing (In.):	0.0
Height (In.):	13.6	Lateral Offset (In.):	18.0	Road Grade (%):	7.60
Physical Condition					
Barrier	Alignment and Height:	The alignment is off by 12 in or more and is listing. Height was 7-12in below 24-in design height.			
	Breaking and Cracking:	5 SF of breaking and cracking.			
	Missing Elements:	Missing variety of stone work.			
	Corrosion and Weathering:	Grout is becoming loose do to freeze/thaw cycles.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-12.241-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	57.70

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$68640
Brief Workorder:	Raise guardwall 10-in. Remove and reset 210-ft of stone masonry guardwall on concrete footer to design height of 24-in.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 210 CF = \$52500. [(2ft)(1.5ft)(70ft)] = 210 CF. Structural Concrete at \$1000- per -Cu. Yd. for 4 CY = \$4000. [(1.5ft)(0.8ft)(70ft)] /27 = 3.1 CY. Low Speed Traffic Control at \$1475- per -Day for 4 Day(s) = \$5900. 1 day removal 3 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_12.241_L_1.jpg

Barrier ID:	SEQU-0010-12.280-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	33.00		
Barrier Description					
Type:	W-BEAM STRONG POST	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	CORTEN		
Blockout Type:	WOOD	Length (ft.):	166		
Speed Limit (MPH):	15	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	75.0
Height (In.):	25.7	Lateral Offset (In.):	31.2	Road Grade (%):	4.20
Physical Condition					
Barrier	Alignment and Height:	Alignment is deflecting less than 6 in. 121 ft of rail is 1-3in below the 27-in design height and 45 ft is within 1 in of design height.			
	Breaking and Cracking:	56 ft of rail is bent and 1 block is broken.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	Minor rusting.			
End Treatments	Alignment and Height:	Alignment had little deflection height was between 1-3in below the 27-in design height.			
	Breaking and Cracking:	Both ends are bent in.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	Minor rusting.			

Barrier ID:	SEQU-0010-12.280-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	33.00

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$6281
Brief Workorder:	Raise 121 feet of W-Beam to 27 inch design height. Replace 56 feet of rail and 1 broken block.				
Workorder:	Replace rail at \$25- per -Lin. Ft. for 56 LF = \$1400. Replace block at \$30- per -Each for 1 Block(s) = \$30. Adjust Guardrail at \$10- per -Lin. Ft. for 121 LF = \$1210. Raise 121-ft of barrier up to 27-in design height. Labor at \$60- per -Hour for 2 Hrs = \$120. Right the twisted blocks. Low Speed Traffic Control at \$1475- per -Day for 2 Day(s) = \$2950.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_12.280_L_1.jpg

Barrier ID:	SEQU-0010-12.328-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/22/2009	Barrier Rating:	34.40		
Barrier Description					
Type:	W-BEAM STRONG POST	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	WOOD		
Blockout Type:	WOOD	Length (ft.):	184		
Speed Limit (MPH):	15	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	76.3
Height (In.):	26.2	Lateral Offset (In.):	57.2	Road Grade (%):	6.80
Physical Condition					
Barrier	Alignment and Height:	The alignment varies 6 to 12 in. 93 ft was 1-3in below the 27-in design height and 20 ft was 4-in below.			
	Breaking and Cracking:	1 cracked block.			
	Missing Elements:	1 missing block.			
	Corrosion and Weathering:	Minor surface rusting.			
End Treatments	Alignment and Height:	Alignment acceptable. Height was 1-3in below the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			

Barrier ID:	SEQU-0010-12.328-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/22/2009	Barrier Rating:	34.40

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$2932
Brief Workorder:	Raise 113 feet of barrier to 27 inch design height; replace 2 blocks.				
Workorder:	Adjust Guardrail at \$10- per -Lin. Ft. for 113 LF = \$1130. Raise 113-ft of barrier up to 27-in design height. Replace block at \$30- per -Each for 2 Block(s) = \$60. Low Speed Traffic Control at \$1475- per -Day for 1 Day(s) = \$1475.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_12.328_L_1.jpg

Barrier ID:	SEQU-0010-12.611-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	34.40		
Barrier Description					
Type:	W-BEAM STRONG POST	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	WOOD		
Blockout Type:	WOOD	Length (ft.):	180		
Speed Limit (MPH):	25	Placement with Respect to Road:	INSIDE OF CURVE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	W-BEAM BCT	Is Beg. End Trtmt Crashworthy?:	NO	Approach Transition Type:	NONE
Ending End Trtmt Type:	W-BEAM BCT	Ending End Trtmt Crashworthy?:	NO		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	74.3
Height (In.):	27.2	Lateral Offset (In.):	10.0	Road Grade (%):	8.10
Physical Condition					
Barrier	Alignment and Height:	Height is within 1 in of the design height of 27 in. The alignment for the first 26 ft from the approach end has deflection greater than 12 in.			
	Breaking and Cracking:	92 ft of bent rail. 4 rotated blocks. 1 broken block.			
	Missing Elements:	1 missing block.			
	Corrosion and Weathering:	Minimal corrosion and weathering. No erosion along back of barrier.			
End Treatments	Alignment and Height:	End treatment knocked out of alignment by impact. Height within 1-in of 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			

Barrier ID:	SEQU-0010-12.611-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	34.40

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$4087
Brief Workorder:	Replace 72 feet of rail 2 blocks and realign 26 feet of barrier.				
Workorder:	Adjust Guardrail at \$10- per -Lin. Ft. for 26 LF = \$260. Realign 26 feet of barrier. Replace Rail at \$25- per -Lin. Ft. for 72 LF = \$1800. Replace Block at \$30- per -Each for 2 Block(s) = \$60. Labor at \$60- per -Hour for 2 Hrs = \$120. Right twisted blocks. Low Speed Traffic Control at \$1475- per -Day for 1 Day(s) = \$1475.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_12.611_L_1.jpg

Barrier ID:	SEQU-0010-12.665-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	64.40		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	724		
Speed Limit (MPH):	25	Placement with Respect to Road:	INSIDE OF CURVE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	18.7	Post Spacing (In.):	0.0
Height (In.):	19.6	Lateral Offset (In.):	21.5	Road Grade (%):	6.80
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. 260 ft was between 1-6in below the 24-in design height and 432 ft was 7-10in below and 32 ft was 15-23in below the design height.			
	Breaking and Cracking:	Several cracking/impact zones along the alignment.			
	Missing Elements:	Scores of missing stones on top in front of and along back of wall.			
	Corrosion and Weathering:	Weathering evident by missing stones and grout along most of the wall. No erosion evident at base of wall.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-12.665-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	64.40

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$452788
Brief Workorder:	Raise guardwall 2-in. Remove and reset 432-ft of stone masonry guardwall on concrete footer to adjacent 18-in height. Replace 32 feet of stone barrier w/o core wall.				
Workorder:	Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 1383 CF = \$345750. [(2ft)(1.6ft)(432ft)] = 1382.4 CF. Structural Concrete at \$1000- per -Cu. Yd. for 13 CY = \$13000. [(1.6ft)(0.5ft)(432ft)] /27 = 12.8 CY. Stone Masonry w/o Concrete Core at \$500- per -Lin. Ft. for 32 LF = \$16000. Replace 32 feet of barrier in pullout. Low Speed Traffic Control at \$1475- per -Day for 25 Day(s) = \$36875. 5 days removal 20 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_12.665_L_1.jpg

Barrier ID:	SEQU-0010-12.851-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	30.10		
Barrier Description					
Type:	W-BEAM WEAK POST	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	WOOD		
Blockout Type:	N/A	Length (ft.):	127		
Speed Limit (MPH):	25	Placement with Respect to Road:	TANGENT		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-2	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	W-BEAM BCT	Is Beg. End Trtmt Crashworthy?:	NO	Approach Transition Type:	NONE
Ending End Trtmt Type:	W-BEAM BCT	Ending End Trtmt Crashworthy?:	NO		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	73.0
Height (In.):	27.7	Lateral Offset (In.):	20.7	Road Grade (%):	5.10
Physical Condition					
Barrier	Alignment and Height:	The alignment has a deflection between 6-in and 12-in. The height was 1-3in below the 27-in design height for 39 ft and within 1 in for 88 ft.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	One missing post.			
	Corrosion and Weathering:	20 posts are rotting and eroding out.			
End Treatments	Alignment and Height:	Alignment deflection is between 6-in and 12-in. The height is within 1 in of the 27-in design height.			
	Breaking and Cracking:	39 ft of broken rail.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			

Barrier ID:	SEQU-0010-12.851-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	30.10

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$4279
Brief Workorder:	Raise 39 feet of guardrail up to the 27' design height; replace 39 feet of W-beam and 21 posts.				
Workorder:	Adjust Guardrail at \$10- per -Lin. Ft. for 39 LF = \$390. Raise 39-ft of barrier up to 27-in design height. Replace post at \$100- per -Each for 21 Post(s) = \$1050. Replace rail at \$25- per -Lin. Ft. for 39 LF = \$975. Low Speed Traffic Control at \$1475- per -Day for 1 Day(s) = \$1475.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_12.851_L_1.jpg

Barrier ID:	SEQU-0010-12.875-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	42.90		
Barrier Description					
Type:	W-BEAM WEAK POST	Barrier Function:	TRAFFIC		
Barrier Material:	GALVANIZED STEEL	Post Material:	WOOD		
Blockout Type:	N/A	Length (ft.):	666		
Speed Limit (MPH):	25	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-2	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	W-BEAM BCT	Is Beg. End Trtmt Crashworthy?:	NO	Approach Transition Type:	NONE
Ending End Trtmt Type:	W-BEAM BCT	Ending End Trtmt Crashworthy?:	NO		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	74.8
Height (In.):	27.5	Lateral Offset (In.):	22.2	Road Grade (%):	5.80
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height is within 1-in of 27-in design height.			
	Breaking and Cracking:	104 ft of bent or impacted rails. 33 broken or rotten posts.			
	Missing Elements:	No missing elements.			
	Corrosion and Weathering:	Erosion at base of rail - about 60 lf. Some paint peeling off rail.			
End Treatments	Alignment and Height:	Alignment acceptable. Height is within 1-in of 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			

Barrier ID:	SEQU-0010-12.875-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	42.90

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$11358
Brief Workorder:	Replace 104 feet of rail and 33 posts.				
Workorder:	Replace rail at \$25- per -Lin. Ft. for 104 LF = \$2600. Replace post at \$100- per -Each for 33 Post(s) = \$3300. Low Speed Traffic Control at \$1475- per -Day for 3 Day(s) = \$4425.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_12.875_L_1.jpg

Barrier ID:	SEQU-0010-13.022-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	42.70		
Barrier Description					
Type:	W-BEAM STRONG POST	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	WOOD		
Blockout Type:	WOOD	Length (ft.):	242		
Speed Limit (MPH):	25	Placement with Respect to Road:	BOTH INSIDE AND OUTSIDE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	W-BEAM BCT	Is Beg. End Trtmt Crashworthy?:	NO	Approach Transition Type:	NONE
Ending End Trtmt Type:	W-BEAM BCT	Ending End Trtmt Crashworthy?:	NO		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	74.3
Height (In.):	25.2	Lateral Offset (In.):	22.7	Road Grade (%):	7.10
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height is 1-3in below 27-in design height.			
	Breaking and Cracking:	4 rotated blocks. 24 ft of impacted rail.			
	Missing Elements:	2 missing blocks.			
	Corrosion and Weathering:	Minimal corrosion and weathering.			
End Treatments	Alignment and Height:	Alignment acceptable. Height is 1-3in below 27-in design height.			
	Breaking and Cracking:	No breaking or cracking observed.			
	Missing Elements:	No missing elements observed.			
	Corrosion and Weathering:	No corrosion or weathering observed.			

Barrier ID:	SEQU-0010-13.022-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	42.70

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$5011
Brief Workorder:	Replace 24 feet of rail. Raise 242-ft of barrier up to 27-in design height and replace 2 blocks.				
Workorder:	Replace rail at \$25- per -Lin. Ft. for 24 LF = \$600. Adjust Guardrail at \$10 - per -Lin.Ft. for 242 LF = \$2420. Raise 242-ft of barrier up to 27-in design height. Replace block at \$30- per -Each for 2 Block(s) = \$60. Low Speed Traffic Control at \$1475- per -Day for 1 Day(s) = \$1475.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos

Condition photos are not available for SEQU-0010-13.022-L.

Barrier ID:	SEQU-0010-13.193-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	35.50		
Barrier Description					
Type:	OTHER: NON-STANDARD STEEL BARRIER	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	CORTEN		
Blockout Type:	N/A	Length (ft.):	84		
Speed Limit (MPH):	25	Placement with Respect to Road:	TANGENT		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	119.3
Height (In.):	27.0	Lateral Offset (In.):	0.0	Road Grade (%):	8.10
Physical Condition					
Barrier	Alignment and Height:	The alignment has many areas of deflection between 6 in and greater than 12 in. 30 ft was 3-in below the 27-in design height. Rest of barrier was within 1 in.			
	Breaking and Cracking:	No breaking or cracking.			
	Missing Elements:	5 missing bolts.			
	Corrosion and Weathering:	On the approach end a bent shovel end has lots of surface rust along with rail sections.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-13.193-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	35.50

Repair Recommendations

Repair Action:	REPLACE	FMSS Work Type:	CAPITAL IMPROVEMENT	Repair Cost:	\$12793
Brief Workorder:	Replace non-standard steel guardrail with 24 feet of W-beam strong post guardrail and 2 crashworthy end terminals.				
Workorder:	Remove Guardrail at \$10- per -Lin. Ft. for 84 LF = \$840. W-Beam strong post at \$35- per -Lin. Ft. for 24 LF = \$840. W-beam tangent 350 compliant at \$3500- per -Each for 1 Unit(s) = \$3500. W-beam flared 350 compliant at \$3500- per -Each for 1 Unit(s) = \$3500. Low Speed Traffic Control at \$1475- per -Day for 2 Day(s) = \$2950.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_13.193_L_1.jpg

Barrier ID:	SEQU-0010-13.211-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	41.50		
Barrier Description					
Type:	OTHER: NON-STANDARD STEEL BARRIER	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	CORTEN		
Blockout Type:	N/A	Length (ft.):	162		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	121.0
Height (In.):	27.2	Lateral Offset (In.):	6.0	Road Grade (%):	5.70
Physical Condition					
Barrier	Alignment and Height:	The alignment is off by 6 to 12 in. 115 ft was 1-3in below the 27-in design height the rest was 0-3in above.			
	Breaking and Cracking:	The barrier has no cracking but twisting bending and deformed sections occur throughout.			
	Missing Elements:	No missing elements.			
	Corrosion and Weathering:	Several concrete fters are popping up paint is falling off of guardrail.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-13.211-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	41.50

Repair Recommendations

Repair Action:	REPLACE	FMSS Work Type:	CAPITAL IMPROVEMENT	Repair Cost:	\$18080
Brief Workorder:	Remove non-standard steel guardrail and replace with W-beam strong post and two crashworthy end terminals.				
Workorder:	Remove Guardrail at \$10- per -Lin. Ft. for 162 LF = \$2916. W-Beam strong post at \$35- per -Lin. Ft. for 102 LF = \$3570. W-beam tangent 350 compliant at \$3500- per -Each for 2 Unit(s) = \$7000. Low Speed Traffic Control at \$1475- per -Day for 2 Day(s) = \$2950. 1 day removal 1 day installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_13.211_L_1.jpg

Barrier ID:	SEQU-0010-13.505-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	50.00		
Barrier Description					
Type:	OTHER: NON-STANDARD STEEL BARRIER	Barrier Function:	TRAFFIC		
Barrier Material:	OTHER: STEEL	Post Material:	OTHER: STEEL		
Blockout Type:	N/A	Length (ft.):	212		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	120.3
Height (In.):	23.0	Lateral Offset (In.):	19.0	Road Grade (%):	7.70
Physical Condition					
Barrier	Alignment and Height:	Barrier is rotated outward for over half its length. Alignment varies along the entire length. Several impact locations. Height was 3-6in below the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking.			
	Missing Elements:	3 missing bolts.			
	Corrosion and Weathering:	Peeling paint on posts and rails and erosion along back of rail.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-13.505-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	50.00

Repair Recommendations

Repair Action:	REPLACE	FMSS Work Type:	CAPITAL IMPROVEMENT	Repair Cost:	\$31940
Brief Workorder:	Remove non-standard steel guardrail and replace with W-beam strong post and two crashworthy end terminals. Add structural backfill along back of rail for stability.				
Workorder:	<p>W-Beam strong post at \$35- per -Lin. Ft. for 152 LF = \$5320. Install 152 feet of W-beam strong post guardrail.</p> <p>Structural backfill at \$50- per -Cu. Yd. for 100 CY = \$7000. (200ft)(0.5 cy/ft) = 100 CY.</p> <p>Remove Guardrail at \$10- per -Lin. Ft. for 212 LF = \$3816. Remove 212 feet of existing guardrail.</p> <p>W-beam tangent 350 compliant at \$3500- per -Each for 2 Unit(s) = \$7000. Install 2 W-beam crashworthy end treatments.</p> <p>Low Speed Traffic Control at \$1475- per -Day for 4 Day(s) = \$5900. 2 days backfill 1 day removal 1 day installation.</p>				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_13.505_L_1.jpg

Barrier ID:	SEQU-0010-13.545-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	37.20		
Barrier Description					
Type:	W-BEAM STRONG POST	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	WOOD		
Blockout Type:	WOOD	Length (ft.):	257		
Speed Limit (MPH):	25	Placement with Respect to Road:	INSIDE OF CURVE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	75.0
Height (In.):	26.2	Lateral Offset (In.):	8.0	Road Grade (%):	7.60
Physical Condition					
Barrier	Alignment and Height:	Alignment is off by less than 6 in. The height was within 1-in of the 27-in design height. 160 ft of rail is impacted.			
	Breaking and Cracking:	3 blockouts rotated out of alignment. 2 broken blockouts.			
	Missing Elements:	3 bolts missing.			
	Corrosion and Weathering:	No corrosion - minimal weathering of posts and blockouts.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-13.545-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	37.20

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$6474
Brief Workorder:	Replace 168 feet of rail and 3 blockouts.				
Workorder:	Replace block at \$30- per -Each for 3 Block(s) = \$90. Replace rail at \$25- per -Lin. Ft. for 168 LF = \$4200. Labor at \$60- per -Hour for 2 Hrs = \$120. Replace missing bolts and right rotated blocks. Low Speed Traffic Control at \$1475- per -Day for 1 Day(s) = \$1475.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_13.545_L_1.jpg

Barrier ID:	SEQU-0010-13.621-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	48.40		
Barrier Description					
Type:	OTHER: NON-STANDARD STEEL BARRIER	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	CORTEN		
Blockout Type:	N/A	Length (ft.):	303		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	120.6
Height (In.):	24.7	Lateral Offset (In.):	37.0	Road Grade (%):	7.50
Physical Condition					
Barrier	Alignment and Height:	Alignment deflection is less than 6 in. 203 ft was 1-3in below the 27-in design height and 100 ft was 3-4in below.			
	Breaking and Cracking:	There is no breaking or cracking.			
	Missing Elements:	There are no missing elements.			
	Corrosion and Weathering:	There are a few rust spots occurring along the rail; the rust is surface rust no holes showing. Paint is peeling off the face of the steel barrier.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-13.621-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	48.40

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$26300
Brief Workorder:	Remove guardrail and replace with 243 feet of W-beam strong post and install two 350 compliant end terminals for 100 feet.				
Workorder:	Remove Guardrail at \$10- per -Lin. Ft. for 303 LF = \$5454. W-Beam strong post at \$35- per -Lin. Ft. for 243 LF = \$8505. Install 243 feet of W-beam strong post guardrail. W-beam tangent 350 compliant at \$3500- per -Each for 2 Unit(s) = \$7000. Install 2 W-beam crashworthy end treatments. Low Speed Traffic Control at \$1475- per -Day for 2 Day(s) = \$2950. 1 day removal 1 day installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_13.621_L_1.jpg

Barrier ID:	SEQU-0010-14.280-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	41.20		
Barrier Description					
Type:	OTHER: NON-STANDARD STEEL BARRIER	Barrier Function:	TRAFFIC		
Barrier Material:	OTHER: STEEL	Post Material:	OTHER: STEEL		
Blockout Type:	N/A	Length (ft.):	121		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	120.0
Height (In.):	21.2	Lateral Offset (In.):	43.0	Road Grade (%):	10.00
Physical Condition					
Barrier	Alignment and Height:	Alignment was off by more than 12 in. The portion of the barrier within i-in of the 27-in design height is severely misaligned due to impact(s). 61 ft was 0-4in above the 27-in design height and 70 ft was 1-3in below.			
	Breaking and Cracking:	No breaking or cracking.			
	Missing Elements:	No missing elements.			
	Corrosion and Weathering:	Paint on rail and posts is peeling.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-14.280-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	41.20

Repair Recommendations

Repair Action:	REPLACE	FMSS Work Type:	CAPITAL IMPROVEMENT	Repair Cost:	\$14625
Brief Workorder:	Remove existing non-standard steel barrier and replace with W-Beam strong post barrier and two crashworthy end terminals.				
Workorder:	<p>W-Beam strong post at \$35- per -Lin. Ft. for 61 LF = \$2135. Install 61 feet of W-beam strong post guardrail.</p> <p>W-beam tangent 350 compliant at \$3500- per -Each for 2 Unit(s) = \$7000. Install 2 non-flared tangent W-beam end treatment.</p> <p>Remove Guardrail at \$10- per -Lin. Ft. for 121 LF = \$1210.</p> <p>Low Speed Traffic Control at \$1475- per -Day for 2 Day(s) = \$2950. 1 day removal 1 day installation.</p>				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_14.280_L_1.jpg

Barrier ID:	SEQU-0010-15.216-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	20.70		
Barrier Description					
Type:	OTHER: TIMBER RAIL ON TIMBER POSTS	Barrier Function:	TRAFFIC		
Barrier Material:	OTHER: WOOD	Post Material:	WOOD		
Blockout Type:	N/A	Length (ft.):	25		
Speed Limit (MPH):	15	Placement with Respect to Road:	TANGENT		
Hazard Behind Barrier:	MEDIUM				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	20	Width (In.):	0.0	Post Spacing (In.):	120.0
Height (In.):	30.0	Lateral Offset (In.):	40.0	Road Grade (%):	3.10
Physical Condition					
Barrier	Alignment and Height:	Alignment deflection was less than 6 in. Barrier was 10in above the 20-in design height.			
	Breaking and Cracking:	There was no breaking or cracking.			
	Missing Elements:	There were no missing elements.			
	Corrosion and Weathering:	The wood was painted/stained. No corrosion or weathering was observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-15.216-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:		20.70	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_15.216_L_1.jpg

Barrier ID:	SEQU-0010-16.627-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	29.70		
Barrier Description					
Type:	OTHER: NON-STANDARD STEEL BARRIER	Barrier Function:	TRAFFIC		
Barrier Material:	OTHER: STEEL	Post Material:	WOOD		
Blockout Type:	N/A	Length (ft.):	124		
Speed Limit (MPH):	25	Placement with Respect to Road:	TANGENT		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	120.3
Height (In.):	28.7	Lateral Offset (In.):	65.6	Road Grade (%):	8.10
Physical Condition					
Barrier	Alignment and Height:	Alignment is off by more than 12 in. Height was 0-3in above the 27-in design height. Several impacts along rail are evident.			
	Breaking and Cracking:	1 post cracked from top through to base.			
	Missing Elements:	2 bolts missing.			
	Corrosion and Weathering:	Painted steel rail has peeling paint. Some minor erosion on back side of rail need to be monitored.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-16.627-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	29.70

Repair Recommendations

Repair Action:	REPLACE	FMSS Work Type:	CAPITAL IMPROVEMENT	Repair Cost:	\$14773
Brief Workorder:	Remove guardrail and replace with W-beam strong post and install two 350 compliant end terminals.				
Workorder:	<p>Remove Guardrail at \$10- per -Lin. Ft. for 124 LF = \$1240.</p> <p>W-Beam strong post at \$35- per -Lin. Ft. for 64 LF = \$2240. Install 64 feet of W-beam strong post guardrail.</p> <p>W-beam tangent 350 compliant at \$3500- per -Each for 1 Unit(s) = \$3500. Install 1 non-flared tangent W-beam end treatment.</p> <p>W-beam flared 350 compliant at \$3500- per -Each for 1 Unit(s) = \$3500. Install 1 flared W-beam end treatment.</p> <p>Low Speed Traffic Control at \$1475- per -Day for 2 Day(s) = \$2950. 1 day removal 1 day installation.</p>				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_16.627_L_1.jpg

Barrier ID:	SEQU-0010-19.043-L				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/21/2009	Barrier Rating:	28.00		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	314		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	MEDIUM				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	OTHER: STONE FLARED	Is Beg. End Trtmt Crashworthy?:	NO	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	28.0	Post Spacing (In.):	0.0
Height (In.):	33.7	Lateral Offset (In.):	31.2	Road Grade (%):	3.20
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 6-7in above the 27-in design height.			
	Breaking and Cracking:	There is no breaking or cracking.			
	Missing Elements:	There are no missing elements.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-19.043-L		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/21/2009	Barrier Rating:	28.00

Repair Recommendations

Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_19.043_L_1.jpg

Barrier ID:	SEQU-0010-26.290-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/20/2009	Barrier Rating:	32.20		
Barrier Description					
Type:	OTHER: NON-STANDARD STEEL BARRIER	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	WOOD		
Blockout Type:	N/A	Length (ft.):	239		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	MEDIUM				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	120.3
Height (In.):	21.7	Lateral Offset (In.):	70.0	Road Grade (%):	1.60
Physical Condition					
Barrier	Alignment and Height:	Alignment is off by more than 12 in posts bent due to impact causing the rail to be unaligned by over a ft in sections. Height was 4-7in below 27-in design height.			
	Breaking and Cracking:	Rail bent and damaged throughout the entire length of guardrail.			
	Missing Elements:	Approximately 10 missing bolts.			
	Corrosion and Weathering:	Rust and paint peeling off the rail.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-26.290-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/20/2009	Barrier Rating:	32.20

Repair Recommendations

Repair Action:	REPLACE	FMSS Work Type:	CAPITAL IMPROVEMENT	Repair Cost:	\$20466
Brief Workorder:	Remove non-standard steel barrier and replace with W-Beam strong post barrier and two crashworthy end terminals.				
Workorder:	<p>Remove Guardrail at \$10- per -Lin. Ft. for 239 LF = \$2390.</p> <p>W-Beam strong post at \$35- per -Lin. Ft. for 179 LF = \$6265. Install 179 feet of W-beam strong post guardrail.</p> <p>W-beam tangent 350 compliant at \$3500- per -Each for 2 Unit(s) = \$7000. Install 2 non-flared tangent W-beam end treatments.</p> <p>Low Speed Traffic Control at \$1475- per -Day for 2 Day(s) = \$2950. 1 day removal 1 day installation.</p>				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos

Condition photos are not available for SEQU-0010-26.290-R.

Barrier ID:	SEQU-0010-30.215-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/20/2009	Barrier Rating:	38.00		
Barrier Description					
Type:	OTHER: NON-STANDARD STEEL BARRIER	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	CORTEN		
Blockout Type:	N/A	Length (ft.):	320		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	MEDIUM				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	119.0
Height (In.):	23.0	Lateral Offset (In.):	39.2	Road Grade (%):	1.90
Physical Condition					
Barrier	Alignment and Height:	The alignment is off by 6-12 in. Height was 2-6in below the 27-in design height.			
	Breaking and Cracking:	The barrier is bent in several places due to impacts.			
	Missing Elements:	There are no missing elements.			
	Corrosion and Weathering:	The guardrail has rust and paint is peeling off.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-30.215-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/20/2009	Barrier Rating:	38.00

Repair Recommendations

Repair Action:	REPLACE	FMSS Work Type:	CAPITAL IMPROVEMENT	Repair Cost:	\$27720
Brief Workorder:	Remove non-standard steel barrier and replace with W-Beam strong post barrier and two crashworthy end terminals.				
Workorder:	Remove Guardrail at \$10- per -Lin. Ft. for 320 LF = \$3200. W-Beam strong post at \$35- per -Lin. Ft. for 260 LF = \$9100. Install 260 feet of W-beam strong post guardrail. W-beam tangent 350 compliant at \$3500- per -Each for 2 Unit(s) = \$7000. Install 2 non-flared tangent W-beam end treatments. Low Speed Traffic Control at \$1475- per -Day for 4 Day(s) = \$5900. 2 days removal 2 days installation.				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_30.215_R_1.JPG

Barrier ID:	SEQU-0010-30.939-R				
Route Name:	GENERALS HIGHWAY HISTORIC				
Inspection Date:	10/20/2009	Barrier Rating:	38.00		
Barrier Description					
Type:	OTHER: NON-STANDARD STEEL BARRIER	Barrier Function:	TRAFFIC		
Barrier Material:	WEATHERING STEEL/CORTEN	Post Material:	CORTEN		
Blockout Type:	N/A	Length (ft.):	300		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	MEDIUM				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	0.0	Post Spacing (In.):	118.6
Height (In.):	23.2	Lateral Offset (In.):	42.2	Road Grade (%):	2.60
Physical Condition					
Barrier	Alignment and Height:	Alignment is acceptable. Entire barrier is between 3-4in below the 27-in design height.			
	Breaking and Cracking:	The barrier is bent in several places due to impacts.			
	Missing Elements:	One missing bolt.			
	Corrosion and Weathering:	The guardrail has rust and paint is peeling off.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0010-30.939-R		
Route Name:	GENERALS HIGHWAY HISTORIC		
Inspection Date:	10/20/2009	Barrier Rating:	38.00


Repair Recommendations

Repair Action:	REPLACE	FMSS Work Type:	CAPITAL IMPROVEMENT	Repair Cost:	\$26730
Brief Workorder:	Remove existing non-standard steel barrier and replace with W-Beam strong post barrier and two crashworthy end terminals.				
Workorder:	<p>Remove Guardrail at \$10- per -Lin. Ft. for 300 LF = \$3000.</p> <p>W-Beam strong post at \$35- per -Lin. Ft. for 240 LF = \$8400. Install 240 feet of W-beam strong post guardrail.</p> <p>W-beam tangent 350 compliant at \$3500- per -Each for 2 Unit(s) = \$7000. Install 2 non-flared tangen W-beam end treatments.</p> <p>Low Speed Traffic Control at \$1475- per -Day for 4 Day(s) = \$5900. 2 days removal 2 days installation.</p>				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0010: GENERALS HIGHWAY HISTORIC

Barrier Condition Photos



SEQU_0010_30.939_R_1.jpg

Barrier ID:	SEQU-0100-1.593-L				
Route Name:	CRYSTAL CAVE ROAD				
Inspection Date:	10/21/2009	Barrier Rating:	11.10		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	60		
Speed Limit (MPH):	25	Placement with Respect to Road:	TANGENT		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	26.7	Post Spacing (In.):	0.0
Height (In.):	31.7	Lateral Offset (In.):	96.0	Road Grade (%):	5.50
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 4-5in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking.			
	Missing Elements:	No missing elements.			
	Corrosion and Weathering:	No corrosion or weathering.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0100-1.593-L				
Route Name:	CRYSTAL CAVE ROAD				
Inspection Date:	10/21/2009	Barrier Rating:		11.10	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0100: CRYSTAL CAVE ROAD

Barrier Condition Photos



SEQU_0100_1.593_L_1.JPG

Barrier ID:	SEQU-0100-1.607-L				
Route Name:	CRYSTAL CAVE ROAD				
Inspection Date:	10/21/2009	Barrier Rating:	14.00		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	75		
Speed Limit (MPH):	25	Placement with Respect to Road:	TANGENT		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	26.0	Post Spacing (In.):	0.0
Height (In.):	29.7	Lateral Offset (In.):	32.0	Road Grade (%):	5.70
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 2-3in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking.			
	Missing Elements:	No missing elements.			
	Corrosion and Weathering:	No corrosion or weathering.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0100-1.607-L				
Route Name:	CRYSTAL CAVE ROAD				
Inspection Date:	10/21/2009	Barrier Rating:		14.00	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0100: CRYSTAL CAVE ROAD

Barrier Condition Photos



SEQU_0100_1.607_L_1.JPG

Barrier ID:	SEQU-0100-1.613-R				
Route Name:	CRYSTAL CAVE ROAD				
Inspection Date:	10/21/2009	Barrier Rating:	22.80		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	44		
Speed Limit (MPH):	15	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	EXTREME				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	26.0	Post Spacing (In.):	0.0
Height (In.):	29.7	Lateral Offset (In.):	12.0	Road Grade (%):	2.20
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 2-4in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking.			
	Missing Elements:	No missing elements.			
	Corrosion and Weathering:	No corrosion or weathering.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0100-1.613-R				
Route Name:	CRYSTAL CAVE ROAD				
Inspection Date:	10/21/2009	Barrier Rating:		22.80	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0100: CRYSTAL CAVE ROAD

Barrier Condition Photos



SEQU_0100_1.613_R_1.jpg

Barrier ID:	SEQU-0100-1.634-L				
Route Name:	CRYSTAL CAVE ROAD				
Inspection Date:	10/21/2009	Barrier Rating:	29.70		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	219		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	26.0	Post Spacing (In.):	0.0
Height (In.):	30.0	Lateral Offset (In.):	13.6	Road Grade (%):	6.50
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 3in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking.			
	Missing Elements:	No missing elements.			
	Corrosion and Weathering:	No corrosion or weathering.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0100-1.634-L		
Route Name:	CRYSTAL CAVE ROAD		
Inspection Date:	10/21/2009	Barrier Rating:	29.70

Repair Recommendations

Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0100: CRYSTAL CAVE ROAD

Barrier Condition Photos



SEQU_0100_1.634_L_1.JPG

Barrier ID:	SEQU-0100-1.644-R				
Route Name:	CRYSTAL CAVE ROAD				
Inspection Date:	10/21/2009	Barrier Rating:	21.20		
Barrier Description					
Type:	STONE MASONRY WITH CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	CONCRETE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	52		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	HIGH				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	TL-3	Is Barrier Crashworthy?:	YES
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	27	Width (In.):	26.0	Post Spacing (In.):	0.0
Height (In.):	30.7	Lateral Offset (In.):	18.0	Road Grade (%):	0.50
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 3-5in above the 27-in design height.			
	Breaking and Cracking:	No breaking or cracking.			
	Missing Elements:	No missing elements.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0100-1.644-R				
Route Name:	CRYSTAL CAVE ROAD				
Inspection Date:	10/21/2009	Barrier Rating:		21.20	
Repair Recommendations					
Repair Action:	NO ACTION	FMSS Work Type:	N/A	Repair Cost:	\$0
Brief Workorder:	N/A				
Workorder:					

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park
ROUTE 0100: CRYSTAL CAVE ROAD

Barrier Condition Photos



SEQU_0100_1.644_R_1.jpg

Barrier ID:	SEQU-0101-0.112-R				
Route Name:	WUKSACHI ROAD				
Inspection Date:	10/20/2009	Barrier Rating:	53.00		
Barrier Description					
Type:	STONE MASONRY WITHOUT CONCRETE CORE WALL	Barrier Function:	TRAFFIC		
Barrier Material:	STONE	Post Material:	N/A		
Blockout Type:	N/A	Length (ft.):	185		
Speed Limit (MPH):	25	Placement with Respect to Road:	OUTSIDE OF CURVE		
Hazard Behind Barrier:	MEDIUM				
Barrier Crashworthiness					
Appropriate Test Level:	TL-1	Barrier Test Level:	NCW	Is Barrier Crashworthy?:	NO
Beg. End Trtmt Type:	NONE	Is Beg. End Trtmt Crashworthy?:	N/A	Approach Transition Type:	NONE
Ending End Trtmt Type:	NONE	Ending End Trtmt Crashworthy?:	N/A		
Average Measurements					
Design Height (In.):	24	Width (In.):	22.7	Post Spacing (In.):	0.0
Height (In.):	16.5	Lateral Offset (In.):	14.6	Road Grade (%):	6.40
Physical Condition					
Barrier	Alignment and Height:	Alignment acceptable. Height was 7-9in below the 24-in design height			
	Breaking and Cracking:	The ending end of the stone wall had 10 ft with missing/cracked grout.			
	Missing Elements:	No missing elements.			
	Corrosion and Weathering:	No corrosion or weathering observed.			
End Treatments	Alignment and Height:				
	Breaking and Cracking:				
	Missing Elements:				
	Corrosion and Weathering:				

Barrier ID:	SEQU-0101-0.112-R		
Route Name:	WUKSACHI ROAD		
Inspection Date:	10/20/2009	Barrier Rating:	53.00

Repair Recommendations

Repair Action:	REPAIR	FMSS Work Type:	DEFERRED MAINTENANCE	Repair Cost:	\$90200
Brief Workorder:	Raise guardwall 7-in. Remove and reset 185-ft of stone masonry guardwall on 1 row of new stone to raise barrier to the 24-in design height.				
Workorder:	<p>Remove & reset stone masonry guardwall at \$250- per -Cu. Ft. for 176 CF = \$44000. $[(0.5\text{ft})(1.9\text{ft})(185\text{ft})] = 175.8 \text{ CF}$.</p> <p>Remove top layer of stone in barrier for 185 feet.</p> <p>Replace Stones at \$250- per -Each for 93 Unit(s) = \$23250. $[(185\text{ft}) / (2 \text{ ft/stone})] \times 1 \text{ row} = 93 \text{ stones}$. Insert new stone on retaining wall to increase barrier height. then reset top layer of barrier.</p> <p>Low Speed Traffic Control at \$1475- per -Day for 10 Day(s) = \$14750. 2 days removal 8 days installation.</p>				

2008 cost estimate (ASTM Class D), preliminary for comparison to other repair costs only.

Sequoia National Park

ROUTE 0101: WUKSACHI ROAD

Barrier Condition Photos



SEQU_0101_0.112_R_1.JPG

Appendix A

Summary of GIP Definitions and Assessment



Sequoia National Park



Federal Lands Highway
Road Inventory Program

Appendix A:

Guardwall/Rail Inventory Program (GIP)

EXPLANATION OF REPORT TERMS

The Guardwall/rail Inventory Program (GIP) was commissioned by WASO to identify deferred maintenance related to barriers in National Parks that have more than one mile of guardwall or guardrail. GIP was designed jointly by the NPS and FHWA and the inventory process records both static characteristics of the barrier (e.g., length, height, etc.) as well as dynamic information about the condition of the barrier.

Barriers that traverse bridges are not included in this inventory, these barriers are covered in FHWA's Bridge Inventory Program (BIP); however, barriers that are approaches to bridges were part of this inventory.

The following discussion highlights each of the elements found in the reports.

Static Barrier Characteristics

BARRIER TYPE

Refers to both the design and the construction materials used:

- W-Beam, Strong Post
- W-Beam, Weak Post
- Thrie Beam/Modified Thrie Beam
- Box Beam
- Steel-Backed Timber, w/ Blockout
- Steel-Backed Timber, w/o Blockout
- Steel-Backed Log Rail
- High Tension Cable
- Three-Strand Cable
- Stone Masonry, w/o Concrete Core Wall
- Stone Masonry, w/ Concrete Core Wall
- Random Rubble Cavity Wall
- Concrete Barrier
- Concrete, with Simulated Stone Face
- W-Beam (Double Face), Strong Post
- Steel-Backed Timber (Double Face)
- Other: *Completed by field crew*

BARRIER MATERIAL

The type of material of which the barrier is composed:

- Cable
- Concrete
- Galvanized Steel
- Log/Timber/Wood
- Steel-Backed Timber/Log
- Weathering Steel/Corten
- Stone
- Other: *Completed by field crew*

LENGTH

The longitudinal distance between the beginning and end of the barrier. It should include the length of end treatments in the overall length of the barrier. For roadside barriers, this can be calculated from the start and end locations.

BARRIER FUNCTION: Traffic or Non-Traffic Barrier.

Due to the different GIP assessment criteria of barriers based on their intended use, barriers were classified as being either traffic barriers or non-traffic barriers.

Traffic barriers are physical devices intended to keep vehicles or people from straying into dangerous or off-limits areas. For the purpose of this inventory and assessment, a traffic barrier is categorized as roadside hardware placed longitudinally, excluding pedestrian railing and fencing.

Non-traffic barriers provide a physical delineation between public access areas and restricted or protected areas in locations such as a parking lot, viewpoint or turnout. Non-traffic barriers which inhibit access of vehicles are included in this report; non-traffic barriers which only inhibit access of pedestrians or bicyclists are not included. For the purpose of this inventory, non-traffic barriers are guidewalls and guiderails. Note: rocks, stones, boulders, fences or curbs were excluded from this inventory.

There are instances in parks where a single barrier can switch between being classified as a traffic barrier and a non-traffic barrier. Such instances typically occur at pullouts, where a traffic barrier along the road will continue through the pullout without interruption. In such instances, the traffic barrier and non-traffic barrier were assessed using different criteria. Due to the different criteria, the GIP database was designed to record the traffic barrier and non-traffic barrier as two distinct barriers, even though to the eye, they appear as one barrier. Other instances where a single barrier is split into multiple barriers would be when the barrier is placed continuously along two legs of an intersection, so that one portion of the barrier may be on one road and the remaining portion of the barrier is on a different road.

POST MATERIAL

The type or material that the barrier’s supporting posts are made of:

- Galvanized Steel
- Wood
- Corten
- Other: *Completed by field crew*
- N/A

BLOCKOUT TYPE

The type of blockout or of what it is comprised:

- Wood
- Plastic
- Steel
- N/A

BARRIER PLACEMENT WITH RESPECT TO ROADWAY

To identify the roadway alignment the barrier is located upon:

- Tangent
- Inside of Curve
- Both Inside and Outside of Curve
- Outside of Curve

POSTED SPEED LIMIT

The posted speed limit of the roadway section.

HAZARD BEHIND BARRIER

A qualitative description of the severity of the hazard behind the barrier:

- Low
- Medium
- High
- Extreme

APPROPRIATE TEST LEVEL (TL) FOR ROAD

Based on the posted speed limit, the NCHRP 350 Crashworthiness test level appropriate for the roadway.

- TL-1, 30 mph and lower
- TL-2, 35-45 mph
- TL-3, 50 mph and higher

BARRIER TEST LEVEL (TL)

A traffic barrier is crashworthy if it was successfully crash tested under *NCHRP Report 350* at speeds along the park road or parkway or if it was accepted through analysis by FHWA, based on similarity to other crashworthy critical design element features. Non-traffic barriers are classified at N/A.

- TL-1
- TL-2
- TL-3
- No
- N/A – Non-Traffic Barrier

IS BARRIER CRASHWORTHY

This compared the appropriate crashworthy test level required for the posted speed limit to the barrier's test level.

- Yes
- No

BEGINNING END TREATMENT TYPE

An end treatment is safety hardware that mitigates impacts to the ends of a barrier. Most common end treatments are for w-beam systems. Note that stonemasonry barriers typically do not have end treatments.

The beginning end treatment is based on the travel lane closest to the barrier. A vehicle traveling in the lane closest to the barrier will encounter the barrier's beginning end treatment first. It is not based on the RIP primary direction. Identifies the barrier's beginning end treatment type:

- W-Beam Flared 350 Compliant
- W-Beam Tangent 350 Complaint
- W-Beam Buried End
- W-Beam Trailing End/CRG
- W-Beam BCT, Flared
- W-Beam, Turn Down
- SBT/Log, Flared
- SBT/Log, Buried
- Median Treatments
- Box Beam
- Cable
- Crash Cushions/Attenuator
- Other: *Completed by field crew*
- None

IS BEGINNING END TREATMENT CRASHWORTHY

Identifies if the barrier's beginning end treatment (based on direction of travel for the travel lane closest to barrier) is crashworthy, based on NCHRP-350.

- Yes
- No
- N/A

APPROACH TRANSITION TYPE

A transition is safety hardware designed to be placed between two different types of barrier. Most common transition types are between bridge rail and w-beam systems.

This identifies the barrier's transition type:

- Bridge Rail, W-Beam
- Bridge Rail, SBT
- Rigid W-Beam, W-Beam
- Rigid SBT (Wall), SBT
- Concrete/Masonry, W-Beam
- Concrete/Masonry, SBT
- Concrete/Masonry, Thrie Beam
- Other: *Completed by field crew*
- None

ENDING END TREATMENT TYPE

The ending end treatment is based on the travel lane closest to the barrier. A vehicle traveling in the lane closest to the barrier will encounter the barrier's ending end treatment last, after passing the rest of the barrier. It is not based on the RIP primary direction. Identifies the barrier's ending end treatment type:

- W-Beam Flared 350 Compliant
- W-Beam Tangent 350 Complaint
- W-Beam Buried End
- W-Beam Trailing End/CRG
- W-Beam BCT, Flared
- W-Beam, Turn Down
- SBT/Log, Flared
- SBT/Log, Buried
- Median Treatments
- Box Beam
- Cable
- Crash Cushions/Attenuator
- Other: *Completed by field crew*
- None

IS ENDING END TREATMENT CRASHWORTHY

Identifies if the barrier's ending end treatment (based on direction of travel for the travel lane closest to barrier) is crashworthy, based on NCHRP-350.

- Yes
- No
- N/A

BARRIER DESIGN HEIGHT

Identifies the barrier's original "as-built" design height:

- 27-in, W-beam, Steel-Backed Timber, Stone Masonry w/ Concrete Core Wall
- 24-in, Stone Masonry w/o Concrete Core Wall, Log on Log
- 20-in, Timber on Wood Posts, Timber on Concrete Posts, Timber on Granite Posts
- 18/24-in, Crenellated Stone Masonry Barrier
- 18/24-in, Dry Stack Stone Wall
- 31-in, Steel-Backed Log
- 32-in, Jersey Barrier

AVERAGE MEASUREMENTS

Minimum of three measurements taken on each barrier.

First measurement approximately 50-ft from the beginning of the barrier, measured from the extreme ends of the barrier's end treatment/transition. Do not take a measurement along the end treatment
Measure and record measurement every 200-ft thereafter for the run of barrier

Last measurement approximately 50-ft from the end of the barrier. Do not take a measurement along the end treatment

If a barrier is less than 300-ft, even say 45-ft, a minimum of three measurements were still taken.

AVERAGE WIDTH

The width of the barrier. Only recorded for guardwalls; not guardrail.

AVERAGE POST SPACING

The spacing of the barrier's (not the end treatments') posts. Only recorded for guardrails; not guardwalls or non-traffic barriers.

AVERAGE BARRIER HEIGHT

The average barrier height. If the barrier has crenellations, the height is measured in the non-crenellated sections of the barrier. If the average lateral offset is less than or equal to 4-ft, average barrier height is measured from the roadway; if the average lateral offset is greater than 4-ft, average barrier height is measured at the barrier face.

AVERAGE LATERAL OFFSET

Determine the average distance between the barrier and the edge of roadway. If a white edgeline is present on the roadway, average lateral offset is measured from the outside edge of the white line to the barrier face. If no white edgeline is present, average lateral offset is measured from the edge of pavement to the barrier face.

AVERAGE ROAD GRADE and UPHILL OR DOWNHILL

Determine an average roadway grade at each barrier location, based on the direction of travel in the lane closest to the barrier.

DYNAMIC BARRIER CHARACTERISTICS – CONDITION ASSESSMENT NARRATIVES

Field crews were directed to write a narrative of the barrier's physical condition. To keep consistency between field crews, all narratives were based on severity and distress criteria, which were developed jointly by the NPS and FHWA. Condition assessments were based on barrier type and can be found directly after this description of report elements.

BARRIER ALIGNMENT/HEIGHT

Narrative completed by field crew describing the barrier's alignment and height. Height comments are based on the barrier's original "as-built" design height.

BARRIER BREAKING/CRACKING

Narrative completed by field crew describing any barrier breaking or cracking found during the inspection.

BARRIER MISSING ELEMENTS

Narrative completed by field crew describing any barrier missing elements encountered during the inspection.

BARRIER CORROSION/WEATHERING

Narrative completed by field crew describing and corrosion or weathering issues associated with the barrier.

END TREATMENTS ALIGNMENT/HEIGHT

Narrative completed by field crew describing the barrier end treatment's alignment and height, when present. Height comments are based on the end treatment's original "as-built" design height.

END TREATMENTS BREAKING/CRACKING

Narrative completed by field crew describing any barrier end treatment's breaking or cracking found during the inspection.

END TREATMENTS MISSING ELEMENTS

Narrative completed by field crew describing any barrier end treatment missing elements encountered during the inspection.

END TREATMENTS CORROSION/WEATHERING

Narrative completed by field crew describing and corrosion or weathering issues associated with the barrier's end treatments.

BARRIER PHOTOGRAPHS

During the inspection, the field crews photographed the beginning end (based on the closest lane's direction of travel) of each barrier. Additional photographs were taken of any unusual deficiencies encountered. Up to two photographs of the barrier are included in this report.

CONDITION AND SEVERITY DISTRESS TABLES

Due to the extreme number of possible conditions of the barrier, transition and end treatment, the following descriptions and matrices are guidelines created to help classify the condition of the element. While the distinction between good and fair is needed, the distinction between fair and poor is much more important since this is the threshold that defines if the element is slightly compromised or is not functional.

In all likelihood, according to these guidelines different portions of an element (most likely a barrier) may be classified differently; however, a single classification will need to be provided for the element. The survey team will use their professional judgment to determine this single classification. The single classification of each element should be considered an index value that provides a general indicator of overall performance, but not necessarily indicate that a specific treatment is warranted. The specific work order that is prepared based on the observed deficiencies will be a much more definitive indicator of the appropriate treatment based on existing distresses. The overall condition will be used as part of the risk assessment tool to evaluate the risk to driver safety associated with the physical condition of the barrier.

GOOD

The barrier performs as intended. The barrier is in fairly straight alignment but may have some small amount that is slightly out of alignment. While the height of the barrier may vary over its run, the height is relatively consistent and is close to its original “as-built” design height. Minor cracks may be visually observed on some the posts, though these cracks are neither long nor deep and the only hardware missing are isolated nuts and bolts. Minor surface corrosion on small portions of the surface is visible but there is no decay associated with connections.

The end treatment performs as intended. The end treatment is in good alignment and tension is acceptable. While the end treatment may exhibit some dents, there are no cracked rails, posts, blocks or any missing elements. Corrosion and erosion, while present, are at a minimum.

In general, all distresses observed, either in isolation or in combination, do not seriously affect the ability of the element to serve the intended functions of protecting drivers from a roadside hazard and/or contributing to the cultural value of the roadway corridor. Keep in mind that “intended function” is a relative term. In many cases, older designs were “intended” to protect drivers but would not be considered fully functional in that regard by today’s standards.

FAIR

The barrier is slightly compromised. The barrier is noticeably out of alignment and the height along the run of barrier varies considerably. Cracks and broken elements are visible from the roadside. The barrier may be missing elements, such as nuts, bolts, blockouts or even a post. Surface corrosion is visible on a fair amount of the barrier but connections will still provide element interlock. Decay and minor erosion, while not always visible, may begin to reduce element strength and individual post stability.

The end treatment is slightly compromised. The end treatment may be somewhat out of alignment, have low cable anchor tension or isolated broken or cracked rail, posts or blocks. Corrosion and erosion are evident.

In general, the distresses observed, either in isolation or combination, may generate unpredictable outcomes related to the functions of the element stated above.

POOR

The barrier is not functional. The barrier will not function as intended. Any of the following could mean that the barrier is in poor condition: The barrier has fallen out of alignment or its height varies greatly from the designed height. Cracks and broken elements are visible from the roadside. The barrier is missing several elements, such as nuts, bolts, blockouts or consecutive posts. Corrosion, causing structural compromise is significant and obvious. Erosion around posts will reduce the barrier's strength and capacity.

The end treatment is not functional. The end treatment does not function as intended. There is no tension in the cable anchor. A significant portion of the end treatment has broken, cracked or dented elements. Elements are missing and corrosion or erosion is significant.

In general, the distresses observed clearly illustrate the inability of the element to perform the intended functions.

CONDITION AND SEVERITY DISTRESS TABLES – BARRIERS

Condition and Severity Distress Table for Semi-Rigid Barriers (including barriers with posts, rail elements and blocks).

	GOOD	FAIR	POOR
Alignment/Design Height			
	<ul style="list-style-type: none"> Alignment off by less than 6" 	<ul style="list-style-type: none"> Alignment off by 6"-12" 	<ul style="list-style-type: none"> Alignment off by more than 12"
	<ul style="list-style-type: none"> Within 1" of <i>design height</i> 	<ul style="list-style-type: none"> Less than 3" lower than <i>design height</i> 	<ul style="list-style-type: none"> Greater than 3" lower than <i>design height</i>
Breaking/Cracking, an member, post or rail – due to impact loading			
	<ul style="list-style-type: none"> Metal – no twisting/bending, tears or cracking 	<ul style="list-style-type: none"> Metal – no cracking or tearing (but minor twisting/bending is ok) 	<ul style="list-style-type: none"> Metal – any cracks or tears
	<ul style="list-style-type: none"> Wood – no impact related cracking 	<ul style="list-style-type: none"> Wood – maybe cracked but retains original cross section 	<ul style="list-style-type: none"> Wood – cracks or tears that deform original section
	<ul style="list-style-type: none"> Isolated broken blocks 	<ul style="list-style-type: none"> Two Consecutive broken blocks 	<ul style="list-style-type: none"> Consecutive broken blocks (three or more consecutive)
Missing Elements			
	<ul style="list-style-type: none"> No bolts and nuts missing 	<ul style="list-style-type: none"> One or two bolt/nut missing at one rail/rail connection 	<ul style="list-style-type: none"> Three or more bolts/nuts missing at one rail/rail connection
	<ul style="list-style-type: none"> n/a 	<ul style="list-style-type: none"> Two consecutive missing blocks 	<ul style="list-style-type: none"> Three or more consecutive missing blocks
	<ul style="list-style-type: none"> n/a 	<ul style="list-style-type: none"> n/a 	<ul style="list-style-type: none"> One missing rail element or post
Corrosion/Decay/Weathering, all posts, rails and blocks – due to aging			
	<ul style="list-style-type: none"> Loss of 5% or less of cross section 	<ul style="list-style-type: none"> Loss of 5% to 50% of cross section 	<ul style="list-style-type: none"> Loss of 50% or more of cross section
	<ul style="list-style-type: none"> Erosion (less than 8" of post exposed below original groundline) 	<ul style="list-style-type: none"> Erosion around posts (8" or more of post exposed below original groundline) for one 	<ul style="list-style-type: none"> Erosion around consecutive posts (more than 8" of post exposed below original groundline)

Condition and Severity Distress Table for Rigid Concrete Barriers (including pre-cast).

GOOD				FAIR				POOR							
Alignment/Design Height															
				<ul style="list-style-type: none"> Alignment off by less than 6" 				<ul style="list-style-type: none"> Alignment off by 6"-12" 				<ul style="list-style-type: none"> Alignment off by more than 12" 			
				<ul style="list-style-type: none"> Within 1" of <i>design height</i> 				<ul style="list-style-type: none"> Less than 3" lower than <i>design height</i> 				<ul style="list-style-type: none"> Greater than 3" lower than <i>design height</i> 			
Breaking/Cracking– due to impact loading															
				<ul style="list-style-type: none"> Minor cracks (less than ¼") present 				<ul style="list-style-type: none"> Cracking present ¼" or greater but no displacement or discontinuity in face 				<ul style="list-style-type: none"> Barrier displaced and/or discontinuous 			
				<ul style="list-style-type: none"> n/a 				<ul style="list-style-type: none"> Pieces broken from barrier 3" deep or less without exposing rebar 				<ul style="list-style-type: none"> Cracking exposes rebar 			
				<ul style="list-style-type: none"> n/a 				<ul style="list-style-type: none"> n/a 				<ul style="list-style-type: none"> Pieces broken from face greater than 3" deep 			
Missing Elements															
				<ul style="list-style-type: none"> n/a 				<ul style="list-style-type: none"> n/a 				<ul style="list-style-type: none"> n/a 			
Corrosion/Decay/Weathering – due to aging															
				<ul style="list-style-type: none"> Surface corrosion on less than 5% of the run 				<ul style="list-style-type: none"> Surface corrosion on between 5-25% of the run 				<ul style="list-style-type: none"> Surface corrosion on more than 25% of the run 			
				<ul style="list-style-type: none"> n/a 				<ul style="list-style-type: none"> Spalling 3" deep or less without exposing rebar 				<ul style="list-style-type: none"> Spalling greater than 3" deep 			
				<ul style="list-style-type: none"> Erosion (less than 8" below groundline) around base 				<ul style="list-style-type: none"> Erosion (8" or more below groundline) around base 				<ul style="list-style-type: none"> Erosion (8" or more below groundline) 			
				<ul style="list-style-type: none"> n/a 				<ul style="list-style-type: none"> Less than 50% undermined (less than half barrier width) 				<ul style="list-style-type: none"> 50% or more undermined (less than half barrier width) 			

Condition and Severity Distress Table for Rigid Stone/Masonry Barriers (including all types of stone or masonry barriers).

GOOD		FAIR		POOR	
Alignment/Design Height					
	<ul style="list-style-type: none"> Alignment (off by less than 6") 	<ul style="list-style-type: none"> Alignment (off by 6"-12") 	<ul style="list-style-type: none"> Alignment (off by more than 12") 		
	<ul style="list-style-type: none"> Within 3" of <i>design height</i> 	<ul style="list-style-type: none"> Between 3.1 - 6" lower than <i>design height</i> 	<ul style="list-style-type: none"> Greater than 6.1" lower than <i>design height</i> 		
Breaking/Cracking – due to impact loading					
	<ul style="list-style-type: none"> Minor cracks (less than ¼") present 	<ul style="list-style-type: none"> Cracks, less than ½" present 	<ul style="list-style-type: none"> Cracks greater than ½" present 		
		<ul style="list-style-type: none"> Stones broken/displaced extending less than 1/3 of width of barrier 	<ul style="list-style-type: none"> Stones broken/displaced extending 1/3 width or more through the barrier 		
Missing Elements					
	<ul style="list-style-type: none"> n/a 	<ul style="list-style-type: none"> n/a 	<ul style="list-style-type: none"> n/a 		
Corrosion/Decay/Weathering – due to aging					
	<ul style="list-style-type: none"> Cracks in mortar joints 1/4" or less and/or single loose or missing stones 	<ul style="list-style-type: none"> Mortar joints deteriorated resulting in two - three loose or missing adjacent stones (without impact) 	<ul style="list-style-type: none"> Mortar joints deteriorated resulting in more than three continuous/adjacent loose or missing stones (without impact) 		
	<ul style="list-style-type: none"> Erosion (less than 8" below groundline) around base 	<ul style="list-style-type: none"> Erosion (8" or more below groundline) around base 	<ul style="list-style-type: none"> Erosion (8" or more below groundline) 		
	<ul style="list-style-type: none"> n/a 	<ul style="list-style-type: none"> Less than 50% undermined (less than half barrier width) 	<ul style="list-style-type: none"> 50% or more undermined (less than half barrier width) 		

Condition and Severity Distress Table for Flexible Barriers, (including cable barriers and weak-post systems designed without blocks).

	GOOD	FAIR	POOR
Alignment/Tension/Design Height			
	<ul style="list-style-type: none"> No bent posts 	<ul style="list-style-type: none"> Bent posts; one to three consecutive posts 	<ul style="list-style-type: none"> Bent posts; four or more consecutive posts
	<ul style="list-style-type: none"> Cable has tension 	<ul style="list-style-type: none"> Cable under-tensioned/sagging 	<ul style="list-style-type: none"> No cable tension
	<ul style="list-style-type: none"> Less than 1" too low 	<ul style="list-style-type: none"> 1-3" too low 	<ul style="list-style-type: none"> Greater than 3" too low
Breaking/Cracking			
	<ul style="list-style-type: none"> No cracked or broken posts 	<ul style="list-style-type: none"> One to three isolated broken posts 	<ul style="list-style-type: none"> Four or more consecutive broken posts
	<ul style="list-style-type: none"> n/a 	<ul style="list-style-type: none"> Cable frayed 	<ul style="list-style-type: none"> Cable broken or severed
Missing Elements			
	<ul style="list-style-type: none"> No bolts and nuts missing at anchors 	<ul style="list-style-type: none"> n/a 	<ul style="list-style-type: none"> Bolts and nuts missing or loose at anchors
	<ul style="list-style-type: none"> n/a 	<ul style="list-style-type: none"> n/a 	<ul style="list-style-type: none"> Any missing posts or cable for any length of run
Corrosion/Decay/Weathering – due to aging			
	<ul style="list-style-type: none"> Loss of 5% or less of cable cross section 	<ul style="list-style-type: none"> Loss of 5% to 15% of cable cross section 	<ul style="list-style-type: none"> Loss of 15% or more of cross section
	<ul style="list-style-type: none"> Erosion (less than 8" of post exposed below original groundline) 	<ul style="list-style-type: none"> Erosion around one post (8" or more of post exposed below original groundline) 	<ul style="list-style-type: none"> Erosion around consecutive posts (more than 8" of post exposed below original groundline)

CONDITION AND SEVERITY DISTRESS TABLES – END TREATMENTS

Condition and Severity Distress Table for Flexible End Treatments, (including cable end terminals).

	GOOD	FAIR	POOR
Alignment/Tension			
	<ul style="list-style-type: none"> Alignment off by less than 4" 	<ul style="list-style-type: none"> Alignment off by 4"-8" 	<ul style="list-style-type: none"> Alignment off by more than 8"
	<ul style="list-style-type: none"> Adequate cable tension 	<ul style="list-style-type: none"> Low cable anchor tension 	<ul style="list-style-type: none"> No cable anchor tension
Breaking/Cracking – due to impact loading			
	<ul style="list-style-type: none"> No broken or cracked elements 	<ul style="list-style-type: none"> Minor cable fraying but still with adequate tension 	<ul style="list-style-type: none"> Broken or cracked cables or posts
	<ul style="list-style-type: none"> No damage to posts, cable or anchor 	<ul style="list-style-type: none"> Slight damage to posts without cracking or tearing (<i>but minor twisting/bending on isolated posts is OK</i>) 	<ul style="list-style-type: none"> Cable broken or severed on any cable
Missing Elements			
	<ul style="list-style-type: none"> No bolts and nuts missing at anchors; No missing cables 	<ul style="list-style-type: none"> n/a 	<ul style="list-style-type: none"> Any missing element (post, cable, bolts, nuts, or anchor)
Corrosion/Decay/Weathering – due to aging			
	<ul style="list-style-type: none"> Loss of 5% or less of cable cross section 	<ul style="list-style-type: none"> Loss of 5% to 15% of cable cross section 	<ul style="list-style-type: none"> Loss of 15% or more of cross section
	<ul style="list-style-type: none"> Connections weathered but still provide element interlock on less than 5% of the end treatment 	<ul style="list-style-type: none"> Connections weathered but still provide element interlock on between 5% to 15% of the end treatment 	<ul style="list-style-type: none"> Connections weathered but still provide element interlock on more than 15% of the end treatment

Condition and Severity Distress Table for Semi-Rigid End Treatments, including Flared and Tangent

				GOOD	FAIR	POOR
Alignment/Tension						
	<ul style="list-style-type: none"> Alignment of flares and offsets off by less than 4” 	<ul style="list-style-type: none"> Alignment of flares and offsets off by 4”-8” 	<ul style="list-style-type: none"> Alignment of flares and offsets off by more than 8” 			
	<ul style="list-style-type: none"> Within 1” of <i>design height</i> 	<ul style="list-style-type: none"> Less than 3” lower than <i>design height</i> 	<ul style="list-style-type: none"> Greater than 3” lower than <i>design height</i> 			
For <i>Aesthetic Barriers</i> (i.e. – SBT and SBL guardrail) that do not have crashworthy terminals:	<ul style="list-style-type: none"> Approach barrier terminals are buried, anchored, and flared away from the travel lane 	<ul style="list-style-type: none"> Approach barrier terminals are buried, anchored, and flared away from the travel lane 	<ul style="list-style-type: none"> Approach barrier ends are NOT buried, anchored, nor flared away from the travel lane 			
Breaking/Cracking – due to impact loading						
	<ul style="list-style-type: none"> Metal – no twisting/bending, tears or cracking 	<ul style="list-style-type: none"> Metal – no cracking or tearing (but minor twisting or bending is ok) 	<ul style="list-style-type: none"> Metal – any cracks or tears 			
	<ul style="list-style-type: none"> Wood – no impact related cracking 	<ul style="list-style-type: none"> Wood – maybe cracked but retains original cross section 	<ul style="list-style-type: none"> Wood – cracks or tears that deform original section 			
	<ul style="list-style-type: none"> No broken blocks 	<ul style="list-style-type: none"> One broken block 	<ul style="list-style-type: none"> Two consecutive broken blocks 			
Missing Elements						
	<ul style="list-style-type: none"> No missing elements, including breakaway cables and struts 	<ul style="list-style-type: none"> Isolated bolts, nuts, or blocks loose on non-consecutive posts 	<ul style="list-style-type: none"> Any missing element, including blocks, rails, posts cables, or struts 			
	<ul style="list-style-type: none"> No bolts, nuts, or blocks missing or loose 	<ul style="list-style-type: none"> Breakaway strut present but vertical height off by more than 2” 	<ul style="list-style-type: none"> Missing nuts / bolts on consecutive posts 			
Corrosion/Decay/Weathering – due to aging						
	<ul style="list-style-type: none"> Surface corrosion / decay / connections weathered with a loss of 5% or less of cross section of interlocking elements 	<ul style="list-style-type: none"> Surface corrosion / decay / connections weathered with between 5-25% loss of cross section along transition interlocking elements 	<ul style="list-style-type: none"> Surface corrosion / decay / connections weathered with more than 25% loss of cross section along transition interlocking elements 			
	<ul style="list-style-type: none"> Erosion (less than 8” of post exposed below original groundline) 	<ul style="list-style-type: none"> Erosion around 1 post (8” or more of post exposed below original groundline) 	<ul style="list-style-type: none"> Erosion around consecutive posts (8” or more of post exposed below original groundline) 			

SPECIFIC RISK ELEMENTS

The potential risk to a motorist after a vehicle impacts a traffic barrier depends on the crashworthiness of the traffic barrier as well as traffic exposure factors. Variables relating to the roadside, the traffic barrier's crashworthiness and traffic data include the following:

ADT. The number of vehicles (in both directions) that travel the roadway on which the traffic barrier is located.

Barrier Crashworthy. A traffic barrier is crashworthy if it was successfully crash tested under NCHRP Report 350 at speeds along the park road or parkway or if it was accepted through analysis by FHWA, based on similarity to other crashworthy critical design element features. If crashworthy, the appropriate test level also needs to be recorded. For crashworthy barriers, the barrier test level will be compared to the test level appropriate for the roadway (based solely on posted speed limit). The intent is to record situations in which a crashworthy barrier of a lower test level is installed on a roadway which should have a barrier of a higher test level.

Barrier Height. Determined from barrier height as collected in the physical condition assessment. The database will compare this value to the NCHRP test level height that is appropriate for the posted speed of the road and barrier type.

End Treatment Crashworthy. An end treatment is crashworthy if it has been successfully crash tested. This is for the approach end treatment, which is defined as the end treatment which a vehicle will first pass when traveling on the same side of the road as the barrier.

Existing Roadway Features. The list of roadway features is limited to the following, all of which have a documented history of reducing the number of crashes, and are found later in the GIP as possible countermeasures.

Centerline pavement markings	Grooved pavement surface
Edgeline pavement markings	Delineators on curve and tangent
Wider centerline	Chevrons
Wider edgeline	Warning sign
Centerline rumble strips	Flashing beacon on warning sign
Shoulder rumble strips	Lighting
Barrier reflectors	Speed feedback sign

Factored Crash Rate. The average annual number of crashes (on the overall road and by barrier segment), over the last 5 years. If the road has an ADT of less than 1000, evaluate a minimum of 7 to 10 years of crash data, if available.

Lateral Offset of Barrier from Edge of Traveled Way. The distance from the edge of traveled way to the face of the barrier is useful for determining impact to asset during different types of construction. Two or three measurements will be taken – beginning, middle and end of barrier run (not including the end treatments) – and the average will be used.

Posted Speed Limit. The posted speed limit(s) of the roadway section.

Roadway Grade and Uphill or Downhill. Is refers to the grade of the roadway, in the direction of travel closest to the barrier.

Severity of the Hazard behind Barrier. A rating system based on photos will be used to rate the severity of the hazard behind the barrier. Choices include:

- Low
- Medium
- High
- Extreme

RISK ASSESSMENT AND RISK SCORE

The following table shows the variables relating to the overall roadway safety in the vicinity of barriers. In addition, the table illustrates the range of values considered for each variable and associated levels of risk. For categorization purposes, variables have been placed into one of three categories: segment, site or barrier variables. The “Associated Risk” column identifies the relative risk posed by each variable. This looks at the relative risk of the each variable itself and is only a cursory evaluation.

A Risk Score or Rating (“Barrier Rating” on Tier 3 Barrier page) was created for each barrier based on the table values. The level of risk tolerated is dependent on the category of road, which will be discussed in subsequent pages.

Once the inventory has been conducted, a total risk value can be assigned to each barrier. A comparison of the relative risk to an acceptable risk threshold will be performed in order to analyze the overall risk of a given barrier.

Variable and Associated Levels of Risk

VARIABLE	RANGE	ASSOCIATED RISK
SEGMENT VARIABLES		
ADT	0 – 1000	0.0
	1001 – 4000	2.9
	4001 – 8000	5.7
	8001 – 20,000	7.1
	20,001 and greater	8.6
Crash Factor	0	0.0
	0.1 – 5.0	4.2
	5.1 – 20.0	8.7
	20.1 – 30.0	17.1
	30.1 – 75.0	25.8
	75.1 and greater	34.2
Posted Speed Limit	15 – 25 mph	0.0
	30 – 40 mph	4.3
	45 and higher	8.6
SITE VARIABLES		
Barrier Placement w/ Respect to Roadway Geometry	Tangent	0.0
	Inside of curve	2.9
	Both inside and outside of curve	8.6
Severity of Hazard behind the Barrier	Outside of curve	8.6
	Low severity	2.6
	Medium severity	5.1
	High severity	6.9
Longitudinal Length of Barrier	Extreme severity	8.6
	1 – 250-ft	0.0
	251 – 750-ft	2.9
	751 – ft and greater	5.7
Lateral Offset of Barrier from Edge of Traveled Way	4.1 – ft and greater	0.0
	2 – 4-ft	2.9
	less than 2-ft	5.7
Roadway Grade	Uphill/level/downgrade less than 3%	0.0
	Mild downgrade (3 – 6%)	4.3
	Steep downgrade (greater than 6%)	8.6
BARRIER VARIABLES		
Actual Barrier Height (compared to test level height)	0 – 1-in lower	0.0
	1.1 – 4-in lower	4.4
	4.1 – 7-in lower	12.9
	7.1 – 12-in lower	19.4
	12.1-in and greater lower	21.5
Dynamic Barrier Condition Rating (based on design height)	0 – 25	0.0
	26 – 200	4.4
	201 – 400	8.6
	401 – 600	12.9
	601 – 800	17.1
	801 and above	21.5
Barrier Conformance with Current Crashworthiness Criteria	Yes	0.0
	No	5.7
Maximum Total Possible Risk Score		100

REPLACEMENT/REPAIR STRATEGIES

Information is integrated by combining static data on barrier type, materials, dimensions, etc. with the condition and risk assessments, and the asset management roadway categories (which include cultural and historic resource considerations) to come up with actionable repair strategies for barriers. In addition, repair costs are accounted for so that estimates can be made for repair actions identified. Costed repair estimates, or work orders, then form the basis for estimating deferred maintenance associated with roadside barriers.

Repair recommendations generated by this assessment are intended to provide an estimated cost of deferred maintenance of barriers. As such, the evaluation is not rigorous and may be changed when a more detailed review and assessment at a project level is completed. In addition, any repairs or replacements that are recommended by this inventory and assessment process must be vetted through a project selection, planning and design process, including compliance with the National Historic Preservation Act (NHPA) and the National Environmental Policy Act (NEPA).

Many park barriers are located in harsh environments where freeze-thaw cycles, avalanche impacts, surface erosion, rockfall and vehicle impacts damage them; consequently, they are showing signs of fatigue, at times serious. Whenever possible, historic barriers are repaired or rehabilitated in place so that the historic significance can be preserved; however, removal or reconstruction, which is typically the least preferred alternative, is at times necessary.

Barrier deficiencies can generally be categorized into one of two categories:

- Barriers that pose an unacceptable risk to the traveling public (as determined by the risk assessment methods described in Chapter Seven and including standards found in NCHRP Report 350), or
- Damaged barriers, due to either crash impacts, other loadings (e.g., snow / avalanche, etc) or deteriorated parts (from age / weathering).

Outside of the national park system, barriers that do not meet NCHRP Report 350 crashworthiness standards are typically removed and a barrier of a crashworthy design is constructed in its place. However given the sensitive natural and cultural environments found within the national park system, deficient barriers not meeting national crashworthiness standards may warrant no action, particularly where risk is low.

The type of repair strategy is often dependent on the barrier deficiency and its cultural context. Typically barriers that do not meet current crashworthiness criteria may be replaced while damaged or deteriorated barriers can be repaired. However, under unique situations found in certain national parks and as evaluated using the risk assessment and asset management roadway categories, some barriers that do not meet current crashworthiness criteria may warrant no action being taken for their replacement or repair.

Risk assessment and asset management roadway categories are integrated in the following table, which establishes different risk thresholds within each roadway category. In essence, a higher level of risk will be tolerated in Asset Management Roadway Category A, as demonstrated by the higher risk threshold (90), while less risk will be tolerated in Roadway Category B (70) and even less risk in Roadway Category C (50).

Asset Management Roadway Categories, Risk Thresholds and Treatment Recommendations.

ASSET MANAGEMENT ROADWAY CATEGORY	RISK THRESHOLD	PROGRAM-LEVEL TREATMENT RECOMMENDATION
A	90-100	1. Identify measures other than barrier replacement that could be taken to reduce risk (including engineering countermeasures). 2. Corrective action (including reconstruct/replacement, if necessary) needed to reduce risk below 90.
	Below 90	1. Identify measures that could be taken to reduce risk (including engineered countermeasures). 2. Identify repairs needed to improve physical condition/maintain historic integrity. 3. When condition is good and risk is acceptable, no action is necessary.
B	70-100	1. Identify measures that could be taken to reduce risk (including engineered countermeasures). 2. Corrective action (including reconstruct/replacement, if necessary) needed to reduce risk below 70.
	Below 70	1. Identify measures that could be taken to reduce risk (including engineered countermeasures). 2. Identify repairs needed to improve physical condition/maintain historic integrity. 3. When condition is good and risk is acceptable, no action is necessary.
C	50-100	1. Identify measures that could be taken to reduce risk (including engineered countermeasures). 2. Corrective action (including reconstruct/replacement, if necessary) needed to reduce risk below 50.
	Below 50	1. Identify measures that could be taken to reduce risk (including engineered countermeasures). 2. Identify repairs needed to improve physical condition/maintain historic integrity. 3. When condition is good and risk is acceptable, no action is necessary.

Fourteen engineering countermeasures have been specifically selected for use with the GIP risk assessment tool, and are show in the next table. This is an all-inclusive list of available countermeasures for the risk assessment toll; countermeasures not on the list should not be considered.

The concept of employing countermeasures is evident with barriers that have a risk score just above the risk threshold. For such barriers, installing countermeasures should reduce the future number of crashes by a given amount, based on the countermeasure. Depending on the factored crash rate, reducing the number of crashes will lower the overall risk score. Thus, barriers that were classified as “reconstruct/replace” may be able to be reclassified as “repair”.

The decision to include any of the engineering countermeasures can be done only when the risk score is over the risk threshold by three points or less. When countermeasures are employed to reduce the risk score, they must be based on engineering judgment. The GIP database will allow the user to select up to three countermeasures to reduce the risk score under the threshold, based on crash reduction factors from the FHWA publication “Desktop Reference for Crash Reduction Factors” FHWA-SA-07-015.

Proposed Countermeasures.

COUNTERMEASURE	CRASH REDUCTION FACTOR
Speed Feedback Signs	0.46
Flashing Beacons On Warning Signs	0.30
Centerline Pavement Marking	0.30
Lighting	0.25
Chevrons	0.20
Warning Signs	0.20
Barrier Reflectors	0.16
Grooved Pavement Surface	0.15
Edgeline Pavement Marking	0.12
Shoulder Rumble Strips	0.12
Delineators on Curve and Tangent	0.05
Centerline Rumble Strips	0.04
Wider Edgeline	0.02
Wider Centerline	0.02

Maintaining Barriers As Is

Individual barrier elements and roadside conditions are interrelated. Sometimes, barrier deficiencies will be obvious and the best course of action is apparent; however, in context sensitive environments barrier deficiencies may be marginal and a decision will be based on judgment.

If risk is low (as determined by the assessment of variables such as traffic speeds, volumes), it may be acceptable for an historical or culturally significant barrier that does not meet current crashworthiness standards to remain until changes in risk factors would require an upgrading.

If the maintaining barrier as is alternative is the preferred choice through this approach, low cost mitigation measures may be considered to improve safety, such as improving roadside delineation (e.g., pavement markings / rumble strip(e)s, etc.), improving visibility (e.g., advance warning signs, increased sign size, etc.), upgrading the roadway shoulder, or improving skid resistance of the road surface. Although these measures will not reduce crash severity of an errant vehicle impact, these improvements have been tried or proven to reduce the frequency or probability of a vehicle striking the barrier.

Barrier Repair

If a barrier has been damaged due to a crash or there are parts that have deteriorated due to age or weathering but the majority of the barrier meets current crashworthiness standards and is functionally sound, repairing the system can be considered a viable option. Examples of these improvements include replacing damaged timber rail, removing a corroded, weathered steel post and replacing with new, upgraded guardrail blockouts to meet standards on high speed facilities or repointing, resetting or replacing loose or missing stones on the concrete corewalls of stone masonry guardwalls. Pursuing a repair approach should be the first consideration for Roadway Category A and B road assets.

For barriers that do not meet crashworthiness criteria but are functionally sound and have been determined good candidates to be maintained as-is based on the risk assessment and application of asset management roadway categories, repair could include measures such as repointing deteriorated masonry, re-setting or replacing loose, broken or missing stones, restoring walls to their original height (by adding a concrete footing, for example), restoring or improving drainage through or under walls or restoring wall foundations. Alterations to improve safety may also be considered, such as adding or changing end treatments or other mitigation measures as mentioned above.

For historic, stone masonry barriers that have a risk score below the threshold, it is possible that portions of the barrier need to be removed and reset in order increase the height of the barrier. The following guidelines are provided to assist in determining when this should be done and to what height the barrier should be rebuilt:

1. If all or a portion of stone masonry guardwall has a deficient height based upon the Severity Description Charts, that is, at worst, within the fair category, do not raise it. (Other work besides raising the barrier can be specified.)
2. If a portion of a stone masonry guardwall has a deficiency in height based upon the Severity Description Charts, considered “poor” (assumed typically to be less than 18-in) write a work order to raise the poor segment to the height of the adjacent barrier with a non-poor height.
3. If the entire stone masonry guardwall is in poor condition due to height based upon the Severity Description Charts– write a work order to raise the entire segment to its design height (assumed typically to be 24-in).

For aesthetic barrier systems used on many park roads and parkways, there is not a sufficient bid history database for estimating costs to repair or replace individual elements of the system, such as posts or rail. Usually repair of an aesthetic barrier system, such as steel-backed timber guardrail consists of removing and resetting the post or rail section or raising the guardrail to meet standard height requirements.

Barrier Replacement/Reconstruction

If the risk analysis, including the application of asset management roadway categories, indicates the barrier poses an unacceptable safety risk, the first step should be an analysis to determine if there are mitigating measures that can be applied to reduce the risk to an acceptable level without the need to reconstruct the barrier. A second step is to determine if the barrier is needed. If it is practical to eliminate the shielded hazard (by removal, relocation or redesign) removal of the barrier should be considered. However, if the shielded hazard cannot be eliminated or if it is determined inappropriate to remove the barrier (e.g., it is historically significant and/or contributes to the historical or aesthetic significance of the associated road, district or landscape), reconstruction or replacement of the barrier to meet current criteria for crashworthiness may be the appropriate recommended treatment.

The typical reconstruction option used by the NPS for stone masonry guardwalls is to document then dismantle the existing barrier, construct a concrete core and build a stone masonry veneer around the concrete core using the original wall materials and using stone masonry designs that are compatible with the historic road, district or landscape. A number of concrete core stone masonry barrier types have been designed for use in national parks, including 18-in, 22-in, 24-in and 27-in barriers; however, not all have been crash tested or otherwise determined to meet current criteria for crashworthiness.

WORK ORDERS

Work order preparation is essentially determining and documenting the repair actions needed to correct the deficiencies observed during the condition assessment. Barriers are relatively simple structures so this determination can be made by trained inspectors. Keep in mind that this is not a design environment and that more rigorous analysis (if needed) may change the work that is actually performed. The intent of this effort is to prepare a credible estimate of deferred maintenance that may or may not be directly actionable. Simple repairs and/or those that require no compliance with environmental policies (which may be a large percentage of the work orders) can probably be executed without modification.

Once a repair strategy is determined, a cost must be developed for the proposed action. Work orders will be classified as being either deferred maintenance or capital improvement. This classification is based on the type of work recommended, as defined below.

Definition: *Deferred Maintenance* can be classified as repair or replace in kind. Work done to the barrier does not include any upgrading.

Definition: *Capital Improvement* can be classified as upgrading existing barrier. Typically the upgrade will be from a non-crashworthy to a crashworthy device. Other examples of capital improvements would be the addition of a curb to improve drainage or the inclusion of any countermeasure.

There are four types of work:

- No Action
- Monitor
- Repair
- Replace

“No Action” – if risk is low (based on the GIP risk score), a barrier that does not meet current crashworthy performance standards may be acceptable to remain until changes in risk factors would require upgrading.

“Monitor” – if risk is low (based on the GIP risk score), a barrier that does not meet current crashworthy performance standards may be acceptable to remain until changes in risk factors would require upgrading, however, if conditions exist that the park should monitor (e.g., erosion), then “monitor” can be selected as a recommended action.

“Repair” – considered when a barrier damaged by impact deteriorated due to age/weathering and the barrier is functionally sound in a low risk environment. The goal is to bring the barrier back to its “new” condition.

“Replacement/Reconstruction” – when a barrier poses an unacceptable safety risk:

1. If the risk score is less than 3 points above the risk threshold, determine if countermeasures can reduce risk so the barrier can be repaired.
2. Determine if the barrier is warranted and either shielded hazard or barrier itself can be removed (only when barrier NOT considered historically/culturally significant)

For all barrier repair/replace/reconstruction recommendations, the NPS will vet the recommendations through a project selection, planning and design process, including compliance with:

National Historic Preservation Act (NHPA)

National Environmental Policy Act (NEPA)

Aesthetic barriers are commensurate with an approved crashworthy design for the specific conditions at the barrier site as the basis for selecting a crashworthy structure. Types of barriers are generally selected based on emulating the existing types of barriers in the park.