CUVA Cycle 6

Final Report

Road Inventory and Condition Assessment of Paved Routes Cuyahoga Valley National Park







Federal Lands Highway
Road Inventory Program

Prepared By:

Federal Highway Administration Eastern Federal Lands Highway Division Road Inventory Program (RIP)

Report Date: October 2021






Table of Contents

SEC	TION	PAGE NO
1.	INTRODUCTION	1 - 1
2.	PARK ROUTE INVENTORY	
	Route ID Report, Subcomponent Report, and Changes Report (As Applicable)	2 - 1
3.	PARK SUMMARY INFORMATION	
	Parkwide Paved Route Condition Summary	3 - 1
	Explanation of Condition Descriptions	3 - 2
	Route-Level Condition Summary Reports for Data Collection Vehicle, Manually Rated, and Parking Area Routes (As Applicable)	3 - 3
4.	PARK ROUTE LOCATION MAPS	
	Route Location Key Map	4 - 1
	Route Location Area Map(s)	4 - 2
	Route Condition Key Map – PCR Mile by Mile	4 - 9 4 - 10
	Route Condition Area Map(s) – PCR Mile by Mile	4 - 10
5.	PAVED ROAD CONDITION RATING SHEETS	
	Paved Road Pages	5 - 1
6.	PAVED PARKING AREA CONDITION RATING SHEETS	
	Paved Parking Area Pages	6 - 1
7.	ROAD MILEPOST INFORMATION	
	Road Milepost Information and Logs	7 - 1
8.	APPENDIX	
	Improvements to the RIP Index Equations and Determination of PCR	8 - 1
	Description of the Rating System	8 - 2
	Explanation of the Condition Descriptions	8 - 3
	Description of Pavement Treatment Types	8 - 4
	Appendix A: Methodology for Determining Condition Ratings with the Data Collection Vehicle (DCV)	8 - 5
	Appendix B: Methodology for Determining Condition Ratings Using Manual Rating Procedures	8 - 20
	Appendix C: Description of Cycle 6 Deliverables	8 - 29
	Appendix D: Glossary of Terms and Abbreviations	8 - 32

Section 1 Introduction





Introduction

The Federal Highway Administration's (FHWA), Road Inventory Program (RIP) inventories all roads and parking areas in the National Park System, and performs condition inspections on all paved roads and parking areas for the National Park Service (NPS). This report contains the results of the Cycle 6 condition assessment of paved roads and parking lots for this park unit. This assessment was done using an automated, state-of-the-art pavement inspection vehicle as well as manual ratings. This information represents the condition of the paved assets at the time of the inspection. The pavement management system utilized by FHWA and the NPS uses these assessments to estimate future conditions and help prioritize pavement maintenance and rehabilitation projects. Further information about RIP data and its role in managing paved roads and bridges can be obtained by contacting the NPS Regional Transportation Program Manager.

A History of the Road Inventory Program:

The FHWA, in the mid-1970s, was charged with the task of identifying surface condition deficiencies and corrective priorities on NPS roads and parkways. Additionally, FHWA was tasked with establishing an integrated maintenance features inventory, locating features such as culverts, guardrails, and signs, among others, along NPS roads and parkways. As a result, in 1976 the NPS and FHWA entered into a Memorandum of Agreement (MOA) which established the RIP. This MOA was revised in 1980 to update RIP data collection standards and develop a long-range program to improve and maintain NPS roads to designated condition standards and establish a pavement management program.

The FHWA completed the initial phase of inventory in the early 1980s. As a result of this effort, each NPS unit included in the collection received a RIP Report known as the "Brown Book" which contained information that was inventoried during this first RIP phase. In the 1990s, a cyclical program was developed, and since then five cycles of collection have been completed. Cycle 6 is currently in progress. A summary of the RIP collection cycles is shown in the table below.

Cycle	Years	Parks Collected
Cycle 1	1994 - 1997	° 44 Large Parks
Cycle 2	1997 - 2001	79 Large Parks5 Small Parks
Cycle 3	2001 - 2004	All Large ParksAll Small Parks
Cycle 4	2006 - 2010	86 Large ParksSeveral Small Parks
Cycle 5	2010 - 2014	 All Large Parks (Only functional class 1, 2, 7, and new/modified routes collected) All Small Parks (all roads and parking areas collected)
Cycle 6	2014 – 2020 (±)	 All roads and parking areas collected at all Parks Additional partial collections of functional class 1, 2, and 7 roads at Large Parks Cycle 6 is expected to last 6 years

Note: Large Parks have ≥ 10 Paved Miles; Small Parks have < 10 Paved Miles

Since 1984, the Road Inventory Program has been funded through the Federal Lands Highway Park Roads and Parkways (PRP) Program. Currently, coordination of the RIP with Federal Lands Highway (FLH) is under the NPS Washington Headquarters Park Facility Management Division. The FLH Washington office coordinates policy and prepares national reports and needs assessment studies for Congress.

In 1998, the Transportation Equity Act for the 21st Century (TEA-21) amended Title 23 U.S.C., and inserted Section 204(a)(6) requiring the FHWA and NPS, to develop by rule, a Pavement Management System (PMS) applied to park roads and parkways serving the National Park System.

In 2012, the Moving Ahead for Progress in the 21st Century Act (MAP-21) amended Title 23 U.S.C., and under Section 203(c)(1-2) stated that the National Park Service in cooperation with the DOT/FHWA, shall maintain a comprehensive national inventory of their transportation facilities, with the goal of quantifying transportation infrastructure needs within the National Park System.

A History of the Pavement Management System:

In 2005, the FHWA began implementing the use of a pavement management system to assist the NPS in prioritizing Pavement Maintenance and Rehabilitation activities. The system used by FHWA is the Highway Pavement Management Application (HPMA), which has the ability to store inventory and condition data from RIP and forecast future performance using prediction models. Outputs include performance and condition reports at the National, Regional, Park, or Route level. Regional prioritized lists and optimizations have been produced for most regions, and the Service's overall roadway Deferred Maintenance is calculated via the HPMA.

Overview of Cycle 6:

Cycle 6 launched in the spring of 2014 and will again comprise all NPS park units that are served by paved roads and/or parking areas. For Cycle 6, all paved roads (approximately 5,700 miles) and parking areas will be collected in all parks at least once, while the primary routes (functional class 1, 2, and 7 roads) at Large Parks will have additional collections. These multiple collections will provide updated condition data on a majority of the NPS's primary road network and help build a better pavement management system, allowing for more accurate pavement performance prediction models.

FLH is responsible for the accuracy of all data presented in this report. Any questions or comments concerning the contents of this report should be directed to the national RIP Coordinator located in Ashburn, Virginia.

Respectfully,

FHWA RIP Team

FHWA/Eastern Federal Lands 22001 Loudoun County Parkway Building E-2, Suite 200 Ashburn, VA 20147 (571) 434-1574 FHWA/Central Federal Lands 12300 West Dakota Ave Lakewood, CO 80228 (720) 963-3556

Section 2 Park Route Inventory





Page 1 of 9

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 10/15/2021

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

DCV = Data Collection Vehicle
MRL = Manually Rated Line

 $\mathsf{MRP} = \mathsf{Manually} \; \mathsf{Rated} \; \mathsf{Polygon}$

PKG = Parking Areas NC = Not Collected

CUVA

	ROAD INVENTORY (1100 SERIES FMSS LOCATIONS)															
Route No.	Cycle Collected	lteration Collected	FMSS Number	Concession	Route Name	Route Desc	ription To	Maintenance District	FLTP	Paved Miles	Unpaved Miles	Total Mileage	Function Class	Area (SQ FT)	Surf. Type	Area Map
0100	6	1	42378		ND BRECKSVILLE STATION ROAD	NPS)	TO ROUTE 0905 (ND BRECKSVILLE STATION PARKING)	NORTH	YES	0.21	0.00	0.21	2		AS	2
0101ZZ	6	1	42380		SD CUYAHOGA VALLEY EEC ROADS	FROM OAK HILL ROAD (NON NPS)	TO ROUTE 0101ZZ (SD CUYAHOGA VALLEY EEC ROADS)	SOUTH	YES	0.52	0.00	0.52	2		AS	3A
0202	6	1	24583		SD OCTAGON ROAD		TO ROUTE 0918 (SD OCTAGON PARKING)	SOUTH	YES	0.45	0.00	0.45	3		AS	4
0203	6	1	24494		SD LEDGES ROAD	, , ,	TO ROUTE 0920 (SD LEDGES PARKING) AND ROUTE 0921 (SD LEDGES OVERFLOW PARKING)	SOUTH	YES	0.33	0.00	0.33	2		AS	4
0207	6	1	25682		ND YOUTH HOSTEL ROAD	FROM ROUTE 0214 (ND STANFORD ROAD)	TO ROUTE 0973 (ND YOUTH HOSTEL PARKING)	NORTH	NO	0.00	0.08	0.08	3		GR	2
0209ZZ	6	1	25627		SD HOWE MEADOW (FESTIVAL SITES) ROADS	FROM RIVERVIEW ROAD (NON NPS)	TO ROUTE 0209ZZ (SD HOWE MEADOW (FESTIVAL SITES) ROADS)	SOUTH	NO	0.00	1.25	1.25	3		GR	5A
0210	6	1	69864		SD CVEEC NOVEMBER LODGE ROAD	FROM ROUTE 0927 (SD EEC LIPSCOMB CAMPUS PARKING)	TO END OF LOOP	SOUTH	YES	0.13	0.00	0.13	3		AS	3A
0211	NC		25816		ND PINE HILL ROAD	FROM PINE HILL ROAD (NON NPS)	TO TOW PATH TRAIL	NORTH	NO	0.00	0.32	0.32	6		GR	2
0214	6	1	241038		ND STANFORD ROAD	FROM ND STANFORD ROAD (NON NPS)	TO END AT CONSTRUCTION SITE	NORTH	YES	0.64	0.00	0.64	3		AS	1
0400	6	1	42391		ND FITZWATER MAINTENANCE YARD ROAD		TO ROUTE 0903 (ND FITZWATER MAINTENANCE YARD PARKING)	NORTH	NO	0.34	0.00	0.34	5		AS	1
0403	6	1	42478		SD IRA DORM ROAD	FROM MARTIN ROAD / IRA ROAD (NON NPS)	TO END OF LOOP	SOUTH	NO	0.10	0.00	0.10	5		AS	5
0435	NC		231216		SD VIRGINIA KENDALL DAM SERVICE ROAD	FROM TRUXELL ROAD (NON NPS)	TO END OF ROUTE AT DAM	SOUTH	NO	0.00	0.05	0.05	6		GR	4

Page 2 of 9

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 10/15/2021

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

DCV = Data Collection Vehicle MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

CUVA

	ROAD INVENTORY (1100 SERIES FMSS LOCATIONS)															
Route No.	Cycle Collected	Collected	FMSS Number	Concessio	Route Name	Route Desc	cription To	Maintenance District	FLTP	Paved Miles	Unpaved Miles	Total Mileage	Function Class	Area (SQ FT)	Surf. Type	Area Map
0436	NC		24663		ND 120 JAITE MILL ROAD	FROM VAUGHN ROAD (NON NPS)	TO END OF ROUTE AT JAITE	NORTH	NO	0.00	0.48	0.48	6		GR	2
0437	NC		25526		SD AP RADIO TOWER ROAD	FROM AKRON-PENINSULA ROAD (NON NPS)	TO END OF ROUTE AT RADIO TOWER	SOUTH	NO	0.00	0.28	0.28	6		GR	4
0438	NC		25590		SD CVEEC UNPAVED ROADS	FROM ROUTE 0210 (SD CVEEC NOVEMBER LODGE ROAD)	TO END OF ROUTE AT LAGOONS	SOUTH	NO	0.00	0.24	0.24	6		GR	3A
0439	NC		25667		SD VK 95 SHULZE ROAD	FROM KENDALL PARK ROAD (NON NPS)	TO END OF ROUTE AT BARN	SOUTH	NO	0.00	0.36	0.36	6		GR	4
0441	NC		25835		ND 92 HS HUEFNER ROAD	FROM RIVERVIEW ROAD (NON NPS)	TO END OF ROUTE AT BARN	NORTH	NO	0.00	0.14	0.14	6		GR	1
0442	NC		25836		SD VK 209 HAPPY DAYS PUMP HOUSE ROAD	FROM COUNTY ROAD 303 (WEST STREETSBORO ROAD) (NON NPS)	TO END OF ROUTE AT BRIDGE	SOUTH	NO	0.00	0.20	0.20	6		GR	4
0443	NC		69857		ND COONRAD RADIO TOWER ROAD	FROM ROUTE 0910 (ND COONRAD PARKING)	TO RADIO TOWER	NORTH	NO	0.00	0.29	0.29	6		GR	1
0444	NC				SD ARMINGTON POND ACCESS ROAD	FROM ROUTE 0950 (SD ARMINGTON POND PARKING)	TO END OF ROUTE AT CURVE PAST POND	SOUTH	NO	0.00	0.15	0.15	6		GR	4
0445	NC				ND TERRA VISTA ACCESS ROAD	FROM ROUTE 0955 (ND TERRA VISTA PARKING AREA)	TO END OF ROUTE	NORTH	NO	0.00	0.31	0.31	6		NV	1

				_	PAR	KING AREA INVENTORY	1300 SERIES FMSS LOCAT	ONS)					
Route	πţ	rtion ected	FMSS	cessio		Route D	escription	Maintenance	₽.	Access	Area	Surf.	Area
No.	ÿ.	Colle	Number	ទឹ	Route Name	From	То	District	Ξ.	Level	(SQ FT)	Туре	Мар
0900	6	1	42393		ND LOCK 39 TRAILHEAD PARKING	FROM ROCKSIDE ROAD (NON NPS)	TO PARKING	NORTH	YES	PUBLIC	22,142	AS	1
0902	6	1	23304		ND CANAL EXPLORATION CENTER PARKING	FROM HILLSIDE ROAD (NON NPS)	TO PARKING	NORTH	YES	PUBLIC	46,408	AS	1

Page 3 of 9

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 10/15/2021

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

DCV = Data Collection Vehicle
MRL = Manually Rated Line
MRP = Manually Rated Polygon

PKG = Parking Areas

NC = Not Collected

CUVA

	PARKING AREA INVENTORY (1300 SERIES FMSS LOCATIONS)												
Route	cle Ilected	lteration Collected	FMSS	ncession		Route De	escription	Maintenance District	FITP	Access Level	Area (SQ FT)	Surf.	
No.	ပဲပိ	≗ ა	Number	ပိ	Route Name	From	То	District	ш.	Level	(3Q FI)	Туре	Мар
0903	6	1	42397		ND FITZWATER MAINTENANCE YARD PARKING	FROM END OF ROUTE 0400 (ND FITZWATER MAINTENANCE YARD ROAD)	TO PARKING	NORTH	NO	NONPUBLIC	51,081	AS	1
0904	6	1	23310		ND FRAZEE HOUSE PARKING	FROM CANAL ROAD (NON NPS)	TO PARKING	NORTH	YES	PUBLIC	5,082	AS	1
0905	6	1	42399		ND BRECKSVILLE STATION PARKING	FROM END OF ROUTE 0100 (ND BRECKSVILLE STATION ROAD)	TO PARKING	NORTH	YES	PUBLIC	77,445	AS	2
0906	6	1	24492		ND CENTRAL MAINTENANCE & RECEIVING OFFICE PARKING	from riverview road (non nps)	TO RIVERVIEW ROAD (NON NPS)	NORTH	NO	NONPUBLIC	49,157	AS	2
0907	6	1	25882		ND RED LOCK TRAILHEAD PARKING	FROM HIGHLAND ROAD (NON NPS)	TO PARKING	NORTH	YES	PUBLIC	8,537	AS	2
0908A	6	1	24659		ND HEADQUARTERS PARKING A	FROM VAUGHN ROAD (NON NPS)	TO VAUGHN ROAD (NON NPS)	NORTH	YES	PUBLIC	6,482	AS	2
0908в	6	1	42479		ND HEADQUARTERS PARKING B	FROM VAUGHN ROAD (NON NPS)	TO PARKING	NORTH	YES	PUBLIC	10,916	AS	2
0909	6	1	24661		ND DUPLEX PARKING	FROM RIVERVIEW ROAD (NON NPS)	TO RIVERVIEW ROAD (NON NPS)	NORTH	NO	NONPUBLIC	12,660	AS	2
0910	6	1	24512		ND COONRAD PARKING	FROM RIVERVIEW ROAD (NON NPS)	TO ROUTE 0443 (ND COONRAD RADIO TOWER ROAD)	NORTH	YES	PUBLIC	17,052	AS	2
0911	6	1	24488		ND BRANDYWINE FALLS UPPER PARKING	FROM BRANDYWINE ROAD (NON NPS)	TO PARKING	NORTH	YES	PUBLIC	41,267	AS	2
0912	6	1	24482		ND BOSTON GENERAL STORE PARKING	FROM BOSTON MILLS ROAD (NON NPS)	TO PARKING	NORTH	YES	PUBLIC	25,753	AS	2
0913	6	1	42401		ND BIKE & HIKE TRAILHEAD PARKING	FROM BOSTON MILLS ROAD (NON NPS)	TO BOSTON MILLS ROAD (NON NPS)	NORTH	YES	PUBLIC	6,631	AS	2
0914	6	1	25891		ND LOCK 29 TRAILHEAD PARKING	FROM WEST MILL STREET (NON NPS)	TO PARKING	NORTH	YES	PUBLIC	28,775	СО	4

Page 4 of 9

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 10/15/2021

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

DCV = Data Collection Vehicle
MRL = Manually Rated Line
MRP = Manually Rated Polygon

PKG = Parking Areas

PKG = Parking Areas
NC = Not Collected

CUVA

	PARKING AREA INVENTORY (1300 SERIES FMSS LOCATIONS)												
Route	le ected	Iteration Collected	FMSS	cessio		Route De	escription	Maintenance	FLTP	Access	Area	Surf.	Area
No.	ς <u>ς</u>	a S	Number	ទ	Route Name	From	То	District	2	Level	(SQ FT)	Туре	Мар
0915	6	1	25822		ND SHADY KNOLL PICNIC AREA PARKING	FROM COUNTY ROAD 303 (WEST STREETSBORO ROAD) (NON NPS)	TO PARKING	NORTH	YES	PUBLIC	8,767	AS	4
0916	6	1	24591		ND HAPPY DAYS VISITOR CENTER PARKING	FROM COUNTY ROAD 303 (WEST STREETSBORO ROAD) (NON NPS)	TO PARKING	NORTH	YES	PUBLIC	47,402	AS	4
0917	6	1	42403		SD HAPPY DAYS VISITOR HANDICAP PARKING	FROM COUNTY ROAD 303 (WEST STREETSBORO ROAD) (NON NPS)	TO PARKING	SOUTH	YES	PUBLIC	1 <i>5,</i> 281	AS	4
0918	6	1	24586		SD OCTAGON PARKING	FROM END OF ROUTE 0202 (SD OCTAGON ROAD)	TO PARKING	SOUTH	YES	PUBLIC	49,840	AS	4
0919	6	1	25794		SD HORSESHOE POND PARKING	FROM MAJOR ROAD (NON NPS)	TO PARKING	SOUTH	YES	PUBLIC	9,253	AS	3
0920	6	1	24495		SD LEDGES PARKING	FROM ROUTE 0203 (SD LEDGES ROAD)	TO ROUTE 0203 (SD LEDGES ROAD)	SOUTH	YES	PUBLIC	60,828	AS	4
0921	6	1	42405		SD LEDGES OVERFLOW PARKING	FROM END OF ROUTE 0203 (SD LEDGES ROAD)	TO ROUTE 0972 (SD LEDGES STORAGE)	SOUTH	NO	NONPUBLIC	7,776	AS	4
0922	6	1	24497		SD VIRGINIA KENDALL LAKE MAINTENANCE PARKING	FROM TRUXELL ROAD (NON NPS)	TO ROUTE 0967 (SD VIRGINIA KENDALL UNPAVED MAINTENANCE PARKING)	SOUTH	NO	NONPUBLIC	18,575	AS	4
0923	6	1	23311		SD VIRGINIA KENDALL LAKE PARKING	FROM TRUXELL ROAD (NON NPS)	TO PARKING	SOUTH	YES	PUBLIC	86,073	AS	4
0924	6	1	25800		SD PINE HOLLOW PARKING	FROM QUICK ROAD (NON NPS)	TO QUICK ROAD (NON NPS)	SOUTH	YES	PUBLIC	<i>75</i> ,683	AS	4
0925	6	1	42468		SD CROW FOOT GULLY PARKING	FROM QUICK ROAD (NON NPS)	TO PARKING	SOUTH	YES	PUBLIC	21,435	AS	4
0926	6	1	24582		SD LITTLE MEADOW PARKING	FROM QUICK ROAD (NON NPS)	TO PARKING	SOUTH	YES	PUBLIC	25,042	AS	4
0927	6	1	42470		SD EEC LIPSCOMB CAMPUS PARKING	FROM ROUTE 0102Z (SD CVEEC LIPSCOMB PARKING ROAD)	TO ROUTE 0210 (SD CVEEC NOVEMBER LODGE ROAD)	SOUTH	YES	PUBLIC	4,686	AS	3A
0929	6	1	25593		SD EEC LIPSCOMB RECEIVING PARKING	FROM ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)	TO PARKING	SOUTH	NO	NONPUBLIC	3,551	AS	3A
0931	6	1	25591		SD EEC ADMINISTRATION PARKING	FROM ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)	TO ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)	SOUTH	YES	PUBLIC	23,358	AS	3A

Page 5 of 9

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 10/15/2021

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

DCV = Data Collection Vehicle
MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas
NC = Not Collected

CUVA

	PARKING AREA INVENTORY (1300 SERIES FMSS LOCATIONS)												
Route	le lected	lteration Collected	FMSS	cession		Route De	scription	Maintenance	FLTP	Access	Area	Surf.	Area
No.	ÿ <u>≅</u>	a S	Number	ទ	Route Name	From	То	District	글	Level	(SQ FT)	Туре	Мар
0933	6	1	42476		SD EEC WHITE PINE CAMPUS PARKING	ADJACENT TO ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)		SOUTH	YES	PUBLIC	1,798	AS	3A
0934	6	1	42477		SD HUNT FARM VISITOR INFORMATION CENTER PARKING	FROM BOLANZ ROAD (NON NPS)	TO PARKING	SOUTH	YES	PUBLIC	14,533	AS	3
0935	6	1	25654		SD IRA TRAILHEAD PARKING	FROM RIVERVIEW ROAD (NON NPS)	TO PARKING	SOUTH	YES	PUBLIC	24,324	AS	5
0936	6	1	25630		SD BOTZUM PARKING	FROM RIVERVIEW ROAD (NON NPS)	TO PARKING	SOUTH	YES	PUBLIC	70,931	AS	5
0937	6	1	25619		SD OAK HILL DAY USE PARKING	FROM OAK HILL ROAD (NON NPS)	TO PARKING	SOUTH	YES	PUBLIC	80,342	GR	3
0939	6	1	25813		SD WETMORE TRAILHEAD PARKING	FROM WETMORE ROAD (NON NPS)	TO WETMORE ROAD (NON NPS)	SOUTH	YES	PUBLIC	27,691	AS	4
0940	6	1	25542		SD COVERED BRIDGE PARKING	FROM EVERETT ROAD (NON NPS)	TO PARKING	SOUTH	YES	PUBLIC	15,288	AS	3
0941	6	1	86509		SD VALLEY PICNIC AREA PARKING	FROM RIVERVIEW ROAD (NON NPS)	TO PARKING	SOUTH	NO	PUBLIC	7,373	GR	3
0942	6	1	104188		nd Columbia run picnic Area	FROM RIVERVIEW ROAD (NON NPS)	TO PARKING	NORTH	NO	PUBLIC	6,591	GR	2
0943	6	1	25661		SD MAPLEWOOD PICNIC AREA	FROM AKRON-PENINSULA ROAD (NON NPS)	TO PARKING	SOUTH	NO	PUBLIC	3,723	GR	3
0944ZZ	6	1	49916		ND BLUE HEN FALLS PARKING AREAS	FROM BOSTON MILLS ROAD (NON NPS)	TO PARKING	NORTH	NO	PUBLIC	19,148	GR	2
0945	6	1	69860		ND PINE LANE TRAILHEAD PARKING	FROM COUNTY ROAD 303 (WEST STREETSBORO ROAD) (NON NPS)	TO PARKING	NORTH	YES	PUBLIC	22,894	AS	4
0946	6	1	24665		ND JAITE OVERFLOW PARKING	FROM VAUGHN ROAD (NON NPS)	TO PARKING	NORTH	NO	PUBLIC	6,151	GR	2
0947	6	1	86508		ND BOSTON MILLS TRAILHEAD PARKING	FROM BOSTON MILLS ROAD (NON NPS)	TO PARKING	NORTH	NO	PUBLIC	18,954	GR	2

Page 6 of 9

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 10/15/2021

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

DCV = Data Collection Vehicle
MRL = Manually Rated Line
MRP = Manually Rated Polygon

PKG = Parking Areas

NC = Not Collected

CUVA

	PARKING AREA INVENTORY (1300 SERIES FMSS LOCATIONS)												
Route No.	Cycle Collected	Iteration Collected	FMSS Number	Concession	Route Name	Route De	scription To	Maintenance District	FLTP	Access Level	Area (SQ FT)	Surf. Type	Area Map
0950	6	1	25825		SD ARMINGTON POND PARKING	FROM QUICK ROAD (NON NPS)	TO PARKING	SOUTH	NO	PUBLIC	14,452	GR	4
0951	6	1	24645		ND HINES HILL PARKING AREA	FROM HINES HILL ROAD (NON NPS)	TO PARKING	NORTH	YES	PUBLIC	25,410	AS	2
0952	NC		25831		ND HS SZCZUDLO PARKING (TRACT 106-09)	FROM SNOWVILLE ROAD (NON NPS)	TO PARKING	NORTH	NO	NONPUBLIC	2,886	GR	2
0954	6	1	25865		ND ROCKSIDE ROAD SHELTER PARKING	FROM OLD ROCKSIDE ROAD (NON NPS)	TO ROUTE 0964 (ND ROCKSIDE ROAD UNPAVED PARKING)	NORTH	YES	PUBLIC	61,172	AS	1
0955	6	1	10201 <i>7</i>		ND TERRA VISTA PARKING AREA	FROM TINKERS CREEK ROAD (NON NPS)	TO PARKING	NORTH	NO	PUBLIC	<i>7</i> ,296	GR	1
0956	6	1	25892		ND TOWPATH LOCK 29 OVERFLOW PARKING	FROM WEST MILL STREET (NON NPS)	TO PARKING	NORTH	NO	PUBLIC	32,854	GR	4
09 <i>57</i>	6	1	25657		SD INDIGO LAKE PARKING AREA	FROM RIVERVIEW ROAD (NON NPS)	TO PARKING	SOUTH	YES	PUBLIC	8,031	AS	5
0959	6	1	230909		ND TILDEN DRIVEWAY / PARKING	FROM STINE ROAD (NON NPS)	TO PARKING	NORTH	NO	PUBLIC	14,900	GR	3
0960	6	1	226198		ND CANCASCI DRIVE AND PARKING	FROM CHAFFEE ROAD (NON NPS)	TO PARKING	NORTH	YES	PUBLIC	6,659	AS	2
0962	NC		24648		ND HOMESTEAD PARKING (TRACT 113-02)	FROM COUNTY ROAD 303 (WEST STREETSBORO ROAD) (NON NPS)	TO PARKING	NORTH	Ю	NONPUBLIC	8,294	GR	4
0963	6	1	242362		ND FITZWATER ROAD TRAILHEAD PARKING	ADJACENT TO ROUTE 0400 (ND FITZWATER MAINTENANCE YARD ROAD)		NORTH	МО	PUBLIC	4,871	AS	1
0964	6	1			ND ROCKSIDE ROAD UNPAVED PARKING	FROM ROUTE 0954 (ND ROCKSIDE ROAD SHELTER PARKING)	TO ROUTE 0954 (ND ROCKSIDE ROAD SHELTER PARKING)	NORTH	NO	PUBLIC	33,388	GR	1
0965	6	1			SD CVEEC NOVEMBER LODGE PARKING	ADJACENT TO ROUTE 0210 (SD CVEEC NOVEMBER LODGE ROAD)		SOUTH	YES	PUBLIC	528	AS	3A
0966	6	1			ND BIKE AND HIKE TH OVERFLOW PARKING	FROM AKRON-PENINSULA ROAD (NON NPS)	TO PARKING	NORTH	NO	PUBLIC	16,395	GR	2

Page 7 of 9

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 10/15/2021

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

DCV = Data Collection Vehicle MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

PARKING AREA INVENTORY (1300 SERIES FMSS LOCATIONS)													
Route	Cycle Collected	ation ected	FMSS	cessi		Route De	scription	Maintenance	FLTP	Access	Area	Surf.	Area
No.	ی ق	o Te	Number	ŝ	Route Name	From	То	District	글	Level	(SQ FT)	Туре	Мар
0967	6	1			SD VIRGINIA KENDALL UNPAVED MAINTENANCE PARKING	FROM ROUTE 0922 (SD VIRGINIA KENDALL LAKE MAINTENANCE PARKING)	TO PARKING	SOUTH	NO	NONPUBLIC	64,511	NV	44
0968	NC				SD JYUROVAT PARKING	FROM COUNTY ROAD 303 (WEST STREETSBORO ROAD) (NON NPS)	TO PARKING	SOUTH	МО	NONPUBLIC	6,627	GR	4
0969	6	1			SD CARTER GENERAL STORE PARKING (SHRO)	FROM EVERETT ROAD (NON NPS)	TO PARKING	SOUTH	NO	NONPUBLIC	3,070	AS	3
0970	6	1	246335		ND BOSTON VISITOR CENTER PARKING A	FROM RIVERVIEW ROAD (NON NPS)	TO PARKING	NORTH	МО	NONPUBLIC	38 , 987	СО	2
0971	6	1	246337		ND BOSTON VISITOR CENTER PARKING B	FROM RIVERVIEW ROAD (NON NPS)	TO BOSTON MILLS ROAD (NON NPS)	NORTH	NO	NONPUBLIC	21,156	со	2
0972	NC				SD LEDGES STORAGE	FROM ROUTE 0921 (SD LEDGES OVERFLOW PARKING)	TO PARKING	SOUTH	NO	NONPUBLIC	8,684	GR	2
0973	6	1			ND YOUTH HOSTEL PARKING	FROM ROUTE 0207 (ND YOUTH HOSTEL ROAD)	TO PARKING	NORTH	Ŋ	PUBLIC	6,140	GR	2

Page 8 of 9

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 10/15/2021

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

DCV = Data Collection Vehicle MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

Cycle 6 Summary Totals for Cuyahoga Valley National Park

Cycle 6 Route Totals

	NPS Maintained	Concessionaire Maintained	Park Totals
Paved Roads, Data Collection Vehicle Rated (Miles)	2.71	0	2.71
Paved Roads, Manually Rated Length (Miles)	0	0	0
Paved Roads, Manually Rated Area (Sq. Ft.)	0	0	0
Unpaved Roads (Miles)	4.17	0	4.17
Paved Parking (Sq. Ft.)	1,214,281	0	1,214,281
Unpaved Parking (Sq. Ft.)	358,709	0	358,709

Cycle 6 Lane Miles and Overall Pavement Condition

	Lanes Miles*	Pavement Condition Rating**
Data Collection Vehicle Routes	4.82	78
Manually Rated Roads	0	N/A
Parking Areas	20.91	80

^{*} Equivalent Lane Miles are calculated by route using the following equations:

- DCV and MRLs = $(PAVE_WIDTH \times PAVED_MI) / 11$ foot lane

- MRPs and PKGs = $SQ_{FEET} / 5280 / 11$ foot lane

-Excellent = 97

-Good = 90

-Fair = 73

-Poor = 53, 30, or 0

-Construction / Not Rated = -1

^{**}Parking and Manually Rated Routes are assigned the following PCR values based on the type of observed distresses:

Page 9 of 9

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 10/15/2021

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas

NC = Not Collected

General Park Road Functional Classification (FC) Table

FC	Туре	User Access	Description	Route Numbers
1	Principal Park Road Rural Parkway	Public	Roads which constitute the main access route, circulatory tour, or thoroughfare for park visitors. Rural Parkways (e.g. Natchez Trace) are numbered 0001 - 0009.	0001 - 0009 0010 - 0099
2	Connector Park Road	Public	Roads which provide access within a park to areas of scenic, scientific, recreational or cultural interest, such as overlooks, campgrounds, etc.	0100 - 0199
3	Special Purpose Park Road	Public	Roads which provide circulation within public areas, such as campgrounds, picnic areas, visitor center complexes, concessionaire facilities, etc. These roads generally serve low-speed traffic and are often designed for one-way circulation.	0200 - 0299
4	Primitive Park Road	Public	Roads which provide circulation through remote areas and/or access to primitive campgrounds and undeveloped areas. These roads frequently have no minimum design standards and their use may be limited to specially equipped vehicles. Note: Functional Classes 3 and 4 have the same route numbers because, historically, they were numbered similarly.	0200 - 0299
5	Administrative Park Road	Public	All public roads intended for access to administrative developments or structures such as park offices, employee quarters, or utility areas.	0400 - 0499
6	Administrative Park Road (Restricted Access)	Nonpublic	All roads normally closed to the public, including patrol roads, truck trails, and other similar roads. Note: Functional Classes 5 and 6 have the same route numbers because historically they were numbered similarly and often there is little distinction between these routes. For example, because utility areas and employee housing are often closed to the public, this restriction would result in classification of FC 6 rather than FC 5.	0400 - 0499
7	Urban Parkway	Public	These facilities serve high volumes of park and non-park related traffic and are restricted, limited-access facilities in an urban area. This category of roads primarily encompasses the major parkways which serve as gateways to our nation's capital. Other major park roads or portions thereof, however, may be included in this category.	0001 - 0009
8	City Street	Public	City streets are usually extensions of the adjoining street system that are owned and maintained by the National Park Service. The construction and/or reconstruction should conform with accepted local engineering practice and local conditions.	0600 - 0699
N/A	Non-NPS Roads	Public	State, County, or City owned roads which border, traverse, or provide access to Park Facilities or Locations. Non-NPS roads are not assigned functional classes and are driven for GPS and Video Log only.	5000 - 5999

Surface
Types

- AS Asphaltic Concrete Pavement
- BR Brick or Pavers Road Bed
- CB Cobble Stone Road Bed
- CO Portland Cement Concrete Pavement
- GR Gravel Road Bed
- NV Native or Dirt Material Road Bed
- OT Other Materials Road Bed

A park road system contains those roads within or giving access to a park or other unit of the NPS which are administered by the NPS, or by the Service in cooperation with other agencies. The assignment of a functional classification (FC) to a park road is not based on traffic volumes or design speed, but on the intended use or function of that road or route.

The historic route numbering system also included a 300 series for interpretive roads, and a 500 series for one-way roads. There are approximately 250 roads nationwide which are designated by the 300 and 500 series. The numbers for these roads will be maintained for reporting consistency. However, since these interpretive and one-way routes are not as clearly tied to a specific functional class, the 300 and 500 series will be discontinued for future use.

Page 1 of 2

NPS / RIP Subcomponent Details for CUVA

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 10/15/2021

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Paved Routes, Non-NPS

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

DCV = Data Collection Vehicle
MRL = Manually Rated Line

 $\mathsf{MRP} = \mathsf{Manually} \; \mathsf{Rated} \; \mathsf{Polygon}$

PKG = Parking Areas
NC = Not Collected

		SUMMARY ROUTE INVENTORY FOR ROADS (1100 SERIES FMSS LOCATIONS)												
	Solected Nomber Nomber Nomber Nomber Nomber Nomber Nomber Nomber Solected Nomber Nomb						Route Description			Paved	Unpaved	Total	rction ss	Area
١	Number	Number	∛ 8	Coll	ខឹ	Route Name	From	То	듄	Miles	Miles	Mileage	<u> </u>	(SQ FT)
(0101ZZ	42380	6	1		SD CUYAHOGA VALLEY EEC ROADS	FROM OAK HILL ROAD (NON NPS)	TO ROUTE 0101ZZ (SD CUYAHOGA VALLEY EEC ROADS)	YES	0.52	0.00	0.52	2	
(0209ZZ	25627	6	1		SD HOWE MEADOW (FESTIVAL SITES) ROADS	FROM RIVERVIEW ROAD (NON NPS)	TO ROUTE 0209ZZ (SD HOWE MEADOW (FESTIVAL SITES) ROADS)	ОИ	0.00	1.25	1.25	3	

	SUMMARY ROUTE INVENTORY FOR PARKING AREAS (1300 SERIES FMSS LOCATIONS)										
	Route FMSS 9 5 5 7 8 Route Name From To						FLT .	User Access	Area (SQ FT)		
0	944ZZ	49916	6		ND BLUE HEN FALLS PARKING AREAS	FROM BOSTON MILLS ROAD (NON NPS)	TO PARKING	NO	PUBLIC	19,148	

CUVA-	0101Z	Z Su	bcc	omp	oonent Breakdown							_	
Route	Route FMSS 의 보이 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등										Total	ctionc	Area
Number	Number	ςς 0 0 0	Coll Coll	S	Route Name	From	То	Ē	Miles	Miles	Mileage	<u> </u>	(SQ FT)
0101Z	42380	6	1		SD CUYAHOGA VALLEY EEC ROAD	FROM OAK HILL ROAD (NON NPS)	TO END OF LOOP	YES	0.38	0.00	0.38	2	
0102Z	42380	6	1		SD CVEEC LIPSCOMB PARKING ROAD	FROM ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)	TO ROUTE 0927 (SD EEC LIPSCOMB CAMPUS PARKING)	YES	0.05	0.00	0.05	2	
0204Z	42380	6	1		SD EEC LIPSCOMB CAMPUS ROAD	FROM ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)	TO ROUTE 0102Z (SD CVEEC LIPSCOMB PARKING ROAD)	YES	0.04	0.00	0.04	2	
0205Z	42380	6	1		SD EEC ADMINISTRATION ROAD	FROM ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)	TO ROUTE 0102Z (SD CVEEC LIPSCOMB PARKING ROAD)	YES	0.04	0.00	0.04	2	

Page 2 of 2

NPS / RIP Subcomponent Details for CUVA

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 10/15/2021

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Paved Routes, Non-NPS

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

CUVA

CUVA-	0209Z	Z Su	bcc	mp	oonent Breakdown							=	
Route	FMSS Number	cle lected	ation lected	ncessio		Route Des	cription	_ و	Paved	Unpaved		nction	Area
Number	Number	٥٥	₹ 3	Š	Route Name	From	То	<u> </u>	Miles	Miles	Mileage	₽ŏ	(SQ FT)
0209AZ	25627	6	1		SD HOWE MEADOW ROAD A	FROM RIVERVIEW ROAD (NON NPS)	TO END OF LOOP AND ROUTE 0209BZ (SD HOWE MEADOW ROAD B)	NO	0.00	0.15	0.15	3	
0209BZ	25627	6	1		SD HOWE MEADOW ROAD B	FROM ROUTE 0209AZ (SD HOWE MEADOW ROAD A)	TO ROUTE 0209AZ (SD HOWE MEADOW ROAD A)	NO	0.00	0.19	0.19	3	
0209CZ	25627	6	1		SD HOWE MEADOW ROAD C	FROM ROUTE 0209BZ (SD HOWE MEADOW ROAD B)	TO ROUTE 0209JZ (SD HOWE MEADOW ROAD J)	NO	0.00	0.07	0.07	3	
0209DZ	25627	6	1		SD HOWE MEADOW ROAD D	FROM ROUTE 0209BZ (SD HOWE MEADOW ROAD B)	TO ROUTE 0209IZ (SD HOWE MEADOW ROAD I)	NO	0.00	0.08	0.08	3	
0209EZ	25627	6	1		SD HOWE MEADOW ROAD E	FROM ROUTE 0209AZ (SD HOWE MEADOW ROAD A)	TO RIVERVIEW ROAD (NON NPS)	NO	0.00	0.26	0.26	3	
0209FZ	25627	6	1		SD HOWE MEADOW ROAD F	FROM ROUTE 0209CZ (SD HOWE MEADOW ROAD C)	TO END OF ROUTE IN FIELD	NO	0.00	0.10	0.10	3	
0209GZ	25627	6	1		SD HOWE MEADOW ROAD G	FROM ROUTE 0209EZ (SD HOWE MEADOW ROAD E)	TO ROUTE 0209CZ (SD HOWE MEADOW ROAD C)	NO	0.00	0.11	0.11	3	
0209HZ	25627	6	1		SD HOWE MEADOW ROAD H	FROM START IN FIELD	TO ROUTE 0209CZ (SD HOWE MEADOW ROAD C)	NO	0.00	0.10	0.10	3	
0209IZ	25627	6	1		SD HOWE MEADOW ROAD I	FROM START IN FIELD	TO ROUTE 0209CZ (SD HOWE MEADOW ROAD C)	NO	0.00	0.10	0.10	3	
0209JZ	25627	6	1		SD HOWE MEADOW ROAD J	FROM ROUTE 0209CZ (SD HOWE MEADOW ROAD C)	TO END OF ROUTE IN FIELD	NO	0.00	0.10	0.10	3	

CUVA-	0944Z	Z Su	bco	mٍ۲	oonent Breakdown					
Route	FMSS	le ected	ution ected	cessio		Route Desc	ription		User	Area
Number	Number	ζς S	Coll	ទឹ	Route Name	From	То	Ē	Access	(SQ FT)
0944AZ	49916	6	1		ND BLUE HEN FALLS PARKING AREA	FROM BOSTON MILLS ROAD (NON NPS)	TO PARKING	NO	PUBLIC	8,971
0944BZ	49916	6	1		ND BLUE HEN FALLS OVERFLOW PARKING AREA	FROM BOSTON MILLS ROAD (NON NPS)	TO PARKING	МО	PUBLIC	10,177

Route Identification Changes to Paved Routes from Previous Cycle Cuyahoga Valley National Park

	ROUTES REMOVED FROM PREVIOUS INVENTORY:										
Route No.	Route Name	Type of Change	Comments								
0103	ND BRANDYWINE FALLS ENTRANCE ROAD	OTHER	INCORPORATED INTO ROUTE 911 / FMSS #24488 (ND BRANDYWINE FALLS UPPER PARKING).								
0200	ND OLD ROCKSIDE ROAD	OTHER	INCORPORATED INTO ROUTE 954 / FMSS #25865 (ND ROCKSIDE ROAD SHELTER PARKING).								
0201	ND PINE LANE TRAILHEAD ROAD	OTHER	INCORPORATED INTO ROUTE 945 / FMSS #69860 (ND PINE LANE TRAILHEAD PARKING).								
0212	SD CVEEC WHITE PINE CIRCLE ROAD	OTHER	COMBINED INTO ROUTE 0101Z IN CYCLE 6.								
0434	ND BRANDYWINE FALLS LOWER ROAD	OTHER	REMOVED IN CYCLE 6; COUNTY EASEMENT.								

	ROUTES ADDED FROM PREVIOUS INVENTORY:										
Route No.	Route Name	Type of Change	Comments								
0965	SD CVEEC NOVEMBER LODGE PARKING	OTHER	PAVED PARKING AREA ADDED IN CYCLE 6.								
0969	SD CARTER GENERAL STORE PARKING (SHRO)	OTHER	PAVED PARKING AREA ADDED IN CYCLE 6.								
0970	ND BOSTON VISITOR CENTER PARKING A	OTHER	PAVED PARKING AREA ADDED IN CYCLE 6.								
0971	ND BOSTON VISITOR CENTER PARKING B	OTHER	PAVED PARKING AREA ADDED IN CYCLE 6.								

	ROUTES MODIFIED FROM PREVIOUS INVENTORY:										
Route No.	Route Name	Type of Change	Comments								
0101ZZ	SD CUYAHOGA VALLEY EEC ROADS	ROUTES COMBINED	CYCLE 5 ROUTES 0101, 0102, 0204, AND 0205 COMBINED UNDER ROUTE 0101ZZ.								
0202	SD OCTAGON ROAD	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS CHANGED FROM 2 TO 3.								
0214	ND STANFORD ROAD	LENGTH CHANGE	ROUTE SHORTENED DUE TO BRIDGE CONSTRUCTION (1.48 MILES TO 0.64 MILES).								
0403	SD IRA DORM ROAD	OTHER	NAME UPDATED FROM "SD HINE HOUSE LOOP ROAD" TO "SD IRA DORM ROAD". FUNCTIONAL CLASS CHANGED FROM 2 TO 5.								

Route Identification Changes to Paved Routes from Previous Cycle Cuyahoga Valley National Park

	ROUTES	MODIFIED FROM PREV	VIOUS INVENTORY:
Route No.	Route Name	Type of Change	Comments
0902	ND CANAL EXPLORATION CENTER PARKING	ROUTE NAME	NAME UPDATED FROM "ND CANAL VISITOR CENTER PARKING".
0909	ND DUPLEX PARKING	SQ FEET CHANGE	GPS / GEOMETRY UPDATED TO REFLECT FIELD CONDITIONS.
0911	ND BRANDYWINE FALLS UPPER PARKING	SQ FEET CHANGE	GPS/GEOMETRY UPDATED TO INCORPORATE ROUTE 0103. SQ FT UPDATED.
0914	ND LOCK 29 TRAILHEAD PARKING	SQ FEET CHANGE	GPS / GEOMETRY UPDATED TO REFLECT FIELD CONDITIONS.
0917	SD HAPPY DAYS VISITOR HANDICAP PARKING	SQ FEET CHANGE	GPS / GEOMETRY UPDATED TO REFLECT FIELD CONDITIONS.
0921	SD LEDGES OVERFLOW PARKING	SQ FEET CHANGE	GPS / GEOMETRY UPDATED TO REFLECT FIELD CONDITIONS.
0925	SD CROW FOOT GULLY PARKING	SQ FEET CHANGE	GPS / GEOMETRY UPDATED TO REFLECT FIELD CONDITIONS.
0926	SD LITTLE MEADOW PARKING	SQ FEET CHANGE	GPS / GEOMETRY UPDATED TO REFLECT FIELD CONDITIONS.
0927	SD EEC LIPSCOMB CAMPUS PARKING	SQ FEET CHANGE	GPS / GEOMETRY UPDATED TO REFLECT FIELD CONDITIONS.
0929	SD EEC LIPSCOMB RECEIVING PARKING	SQ FEET CHANGE	GPS / GEOMETRY UPDATED TO REFLECT FIELD CONDITIONS.
0939	SD WETMORE TRAILHEAD PARKING	SURFACE TYPE CHANGE	SURFACE UPDATED FROM GRAVEL TO ASPHALT. GPS AND SQ FT UPDATED.
0940	SD COVERED BRIDGE PARKING	SURFACE TYPE CHANGE	SURFACE UPDATED FROM GRAVEL TO ASPHALT. GPS AND SQ FT UPDATED.
0945	ND PINE LANE TRAILHEAD PARKING	SURFACE TYPE CHANGE	SURFACE UPDATED FROM GRAVEL TO ASPHALT. GPS AND SQ FT UPDATED. INCORPORATED ROUTE 0201.
0951	ND HINES HILL PARKING AREA	SURFACE TYPE CHANGE	SURFACE UPDATED FROM GRAVEL TO ASPHALT. GPS AND SQ FT UPDATED.
0954	ND ROCKSIDE ROAD SHELTER PARKING	SQ FEET CHANGE	GPS/GEOMETRY UPDATED TO INCORPORATE ROUTE 0200. SQ FT UPDATED.
0957	SD INDIGO LAKE PARKING AREA	SURFACE TYPE CHANGE	SURFACE UPDATED FROM GRAVEL TO ASPHALT. GPS AND SQ FT UPDATED.

Section 3 Park Summary Information





Parkwide Paved Route Condition Summary Cuyahoga Valley National Park

Table 1: Paved Route Miles and Parking Area Square Footages by Access Level and PCR


Breakdown of Pavement Condition Rating (PCR) Based on Access Level

	POOR	FAIR	GOOD	EXCELLENT	
	(PCR of 0 - 60)	(PCR of 61 - 84)	(PCR of 85 - 94)	(PCR of 95 -100)	
		PAVED	ROADS		
Functional Class	Length (miles)	Length (miles)	Length (miles)	Length (miles)	Total Mileage by FC
1					
2	0.28	0.17	0.21	0.40	1.06
3	0.18	0.55	0.32	0.17	1.22
4					
5	0.02	0.04	0.08	0.20	0.34
6					
7					
8					
Total Mileage by PCR	0.48	0.76	0.61	0.77	2.61
		PAVED P	ARKING		
Access Level	Area (sq. ft.)	Area (sq. ft.)	Area (sq. ft.)	Area (sq. ft.)	Total Area
PUBLIC	189,891	172,399	570,295	75,683	1,008,268
NONPUBLIC	31,235	103,308	11,327	60,143	206,013
Total Area by PCR	221,126	275,707	581,622	135,826	1,214,281

NOTES:

- 1. Data are reported in the table only for paved roads and parking lots that received a condition rating.
- 2. Non-linear roads (MRP collected routes) are measured by area and converted to equivalent route miles based on a 22-ft pavement width in order to be included in the mileage totals for paved roads shown above.
- 3. Quantities in the table above are derived from the route condition data within the PMS_20, PMS_MRL, PMS_MRP, and PMS_PKG tables in the Park geodatabase.

Parkwide Condition Percentages



Road Condition Percentages

Parking Area Condition Percentages

Figure 1: Pavement Condition Rating Breakdown for Paved Roads and Parking Areas

Explanation of the Excellent, Good, Fair, and Poor Condition Descriptions

The Road Inventory Program aims to provide assistance in translating the excellent / good / fair / poor rating categories into pavement needs categories. The PCR can be used to indicate the place in the Pavement Life Cycle and the type of treatments that should be considered now and into the future.

- Excellent / New: PCR of 95-100
 - o Pavements in this range will require only spot repairs
- Good: PCR of 85-94
 - o Pavements in this range will likely be candidates for Preventive Maintenance. Examples include Chip and Slurry Seals, Micro Surfacing and Thin Overlays.
- Fair: PCR of 61-84
 - o Pavements in this range will likely be candidates of Light Rehabilitation (L3R). Examples include singlelift overlays up to 2.5 inches in total thickness, milling and overlays.
- Poor: PCR of 0-60
 - o Pavements in this range will likely be candidates of Heavy Rehabilitation or Reconstruction (H3R or 4R). Examples include Pulverization, Multiple Lift Overlays, and Reconstruction.

CONDITION CATEGORIES AND TREATMENTS EXCELLENT / Localized Repairs Only GOOD / Preventive Maintenance FAIR / Light Rehabilitation POOR / Heavy Rehabilitation Reconstruction Pavement Age

At this time, specific Maintenance and Rehabilitation activities should be evaluated and recommended at the project level. Site-specific conditions that influence treatment type should be determined based on performing a subsurface investigation and/or pavement condition survey, and not be based solely on RIP data. Additionally, RIP produces a snapshot of conditions at the time in which the data were collected. For further information or to obtain additional Pavement Management System's data from our Highway Pavement Management Application (HPMA) please contact the Eastern Federal Lands pavement team.



Cycle 6 - Road Inventory Program

Road Condition Summary Report for Data Collection Vehicle (DCV) Rated Roads

Cuyahoga Valley National Park

Condition (Rating / Index) Legend

EXCELLENT (95 - 100)

GOOD (85 - 94)

FAIR (61 - 84)
POOR (0 - 60)

NR = NOT RATED

Notes:

- This condition summary report contains only the roads rated with the Data Collection Vehicle (DCV).
- Condition on roads that were manually rated and parking areas are shown in separate reports.
- Route-level scores shown on this page may not represent scores at smaller intervals (due to rollup calculations).
- Additional details on individual road ratings at 0.10-mile and 1-mile intervals can be found in Section 5 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

Route No.	Route-	Level Condition for Roads Rated with the Data Collection Veh	nicle (DCV) Functions Class	ıl Surf. Type	Paved Length (Miles)	Pavement Condition Rating (PCR)	ughne: lex (RC	ırface (ating (9	Structural Crack Index	Alligator Crack Index	Longitudinal Cracking Index	Transverse Cracking Index	Patch / Pothole Index	Rutting Index
CUVA-0100	42378	ND BRECKSVILLE STATION ROAD	2	AS	0.21	7	NR	7	7	98	9	79	100	91
CUVA-0101Z	42380	SD CUYAHOGA VALLEY EEC ROAD	2	AS	0.38	95	NR	95	97	100	97	95	100	98
CUVA-0102Z	42380	SD CVEEC LIPSCOMB PARKING ROAD	2	AS	0.05	91	NR	91	99	100	99	96	100	91
CUVA-0202	24583	SD OCTAGON ROAD	3	AS	0.45	87	NR	87	87	100	87	99	100	97
CUVA-0203	24494	SD LEDGES ROAD	2	AS	0.33	82	NR	82	82	100	82	97	100	99
CUVA-0204Z	42380	SD EEC LIPSCOMB CAMPUS ROAD	2	AS	0.04	88	NR	88	99	100	99	88	100	95
CUVA-0205Z	42380	SD EEC ADMINISTRATION ROAD	2	AS	0.04	90	NR	90	93	100	93	90	100	94
CUVA-0210	69864	SD CVEEC NOVEMBER LODGE ROAD	3	AS	0.13	95	NR	95	96	100	96	96	100	95
CUVA-0214	241038	ND STANFORD ROAD	3	AS	0.64	70	57	78	86	100	86	100	78	87
CUVA-0400	42391	ND FITZWATER MAINTENANCE YARD ROAD	5	AS	0.34	91	NR	91	91	100	91	98	100	97
CUVA-0403	42478	SD IRA DORM ROAD	5	AS	0.10	95	NR	95	100	100	100	100	100	95

Data Collection Date: 10/2020



Cycle 6 - Road Inventory Program

Parking Area Condition Summary Report

GOOD (90) FAIR (73)

Condition (Rating / Index) Legend

EXCELLENT (97)

POOR* (0, 30, 53)

NR = NOT RATED

Cuyahoga Valley National Park

Notes:

- A PCR of 0 indicates a paved parking area in very poor condition. Individual distresses could not be identified.
- Additional details on individual parking areas can be found in Section 6 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

							Asphalt Surface Distresses			Concrete Surface Distresses							
Route No.	FMSS No.	Condition Rating Details for Paved Parking Areas Route Name	User Access	Surf. Type	Area (Sq. Ft.)	Pavement Condition Rating (PCR)	Alligator Cracking	Longitudinal / Tranverse Cracking	Rutting / Distortions	Potholes / Patching	HMA Patching	Surface Raveling / Bleeding	Joint Faulting	Slab Cracking	Joint Distresses	' ∓	Potholes / Patching
CUVA-0900	42393	ND LOCK 39 TRAILHEAD PARKING	PUBLIC	AS	22,142	90	97	90	97	97	97	90					
CUVA-0902	23304	ND CANAL EXPLORATION CENTER PARKING	PUBLIC	AS	46,408	90	90	90	97	97	97	97					
CUVA-0903	42397	ND FITZWATER MAINTENANCE YARD PARKING	NONPUBLIC	. AS	51,081	73	73	90	73	90	90	97					
CUVA-0904	23310	ND FRAZEE HOUSE PARKING	PUBLIC	AS	5,082	90	97	90	97	97	90	97				-	
CUVA-0905	42399	ND BRECKSVILLE STATION PARKING	PUBLIC	AS	77,445	53	53	53	97	97	97	90					
CUVA-0906	24492	ND CENTRAL MAINTENANCE & RECEIVING OFFICE PARKING	NONPUBLIC	. AS	49,157	73	73	90	73	97	97	97					
CUVA-0907	25882	ND RED LOCK TRAILHEAD PARKING	PUBLIC	AS	8,537	53	53	90	90	97	97	90					
CUVA-0908A	24659	ND HEADQUARTERS PARKING A	PUBLIC	AS	6,482	73	73	90	90	97	97	90					
CUVA-0908B	42479	ND HEADQUARTERS PARKING B	PUBLIC	AS	10,916	90	90	90	97	97	97	90				-	
CUVA-0909	24661	ND DUPLEX PARKING	NONPUBLIC	C AS	12,660	53	73	53	97	97	97	97					
CUVA-0910	24512	ND COONRAD PARKING	PUBLIC	AS	17,052	53	73	53	90	97	90	90					
CUVA-0911	24488	ND BRANDYWINE FALLS UPPER PARKING	PUBLIC	AS	41,267	90	90	90	97	97	97	90					
CUVA-0912	24482	ND BOSTON GENERAL STORE PARKING	PUBLIC	AS	25,753	73	90	90	73	97	97	90					
CUVA-0913	42401	ND BIKE & HIKE TRAILHEAD PARKING	PUBLIC	AS	6,631	90	97	90	97	97	97	97					
CUVA-0914	25891	ND LOCK 29 TRAILHEAD PARKING	PUBLIC	CO	28,775	73							90	90	73	90	73
CUVA-0915	25822	ND SHADY KNOLL PICNIC AREA PARKING	PUBLIC	AS	8,767	53	53	90	90	97	97	90					
CUVA-0916	24591	ND HAPPY DAYS VISITOR CENTER PARKING	PUBLIC	AS	47,402	53	73	53	97	97	97	97					
CUVA-0917	42403	SD HAPPY DAYS VISITOR HANDICAP PARKING	PUBLIC	AS	15,281	90	97	97	97	97	97	90					
CUVA-0918	24586	SD OCTAGON PARKING	PUBLIC	AS	49,840	90	90	90	90	97	97	90					
CUVA-0919	25794	SD HORSESHOE POND PARKING	PUBLIC	AS	9,253	30	30	90	97	97	97	90					
CUVA-0920	24495	SD LEDGES PARKING	PUBLIC	AS	60,828	90	90	90	97	97	97	90					
CUVA-0921	42405	SD LEDGES OVERFLOW PARKING	NONPUBLIC	. AS	7,776	90	97	90	97	97	97	90					
CUVA-0922	24497	SD VIRGINIA KENDALL LAKE MAINTENANCE PARKING	NONPUBLIC	C AS	18,575	53	53	90	90	97	90	90					
CUVA-0923	23311	SD VIRGINIA KENDALL LAKE PARKING	PUBLIC	AS	86,073	90	90	90	97	90	97	90					
CUVA-0924	25800	SD PINE HOLLOW PARKING	PUBLIC	AS	75,683	97	97	97	97	97	97	97					
CUVA-0925	42468	SD CROW FOOT GULLY PARKING	PUBLIC	AS	21,435	53	73	53	90	97	97	90					

Data Collection Date: 10/2019



Cycle 6 - Road Inventory Program

Parking Area Condition Summary Report

EXCELLENT (97) GOOD (90) FAIR (73) POOR* (0, 30, 53) NR = NOT RATED

Condition (Rating / Index) Legend

Cuyahoga Valley National Park

Notes:

- A PCR of 0 indicates a paved parking area in very poor condition. Individual distresses could not be identified.
- Additional details on individual parking areas can be found in Section 6 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

							Asphalt Surface Distresses Concre			ncrete Surface Distresses							
Route No.	FMSS No.	Condition Rating Details for Paved Parking Areas Route Name	User Access	Surf. Type	Area (Sq. Ft.)	Pavement Condition Rating (PCR)	Alligator Cracking	Longitudinal / Tranverse Cracking	Rutting / Distortions	Potholes / Patching	HMA Patching	Surface Raveling / Bleeding	Joint Faulting	Slab Cracking	Joint Distresses	Delamination / Pop-Outs	Potholes / Patching
CUVA-0926	24582	SD LITTLE MEADOW PARKING	PUBLIC	AS	25,042	90	97	97	97	97	97	90					
CUVA-0927	42470	SD EEC LIPSCOMB CAMPUS PARKING	PUBLIC	AS	4,686	90	97	90	97	97	97	97					
CUVA-0929	25593	SD EEC LIPSCOMB RECEIVING PARKING	NONPUBLIC	C AS	3,551	90	97	90	97	90	97	97					
CUVA-0931	25591	SD EEC ADMINISTRATION PARKING	PUBLIC	AS	23,358	90	97	90	97	97	97	97					
CUVA-0933	42476	SD EEC WHITE PINE CAMPUS PARKING	PUBLIC	AS	1,798	90	97	90	97	97	97	97					
CUVA-0934	42477	SD HUNT FARM VISITOR INFORMATION CENTER PARKING	PUBLIC	AS	14,533	73	73	90	90	97	90	90					
CUVA-0935	25654	SD IRA TRAILHEAD PARKING	PUBLIC	AS	24,324	73	73	90	97	97	97	97					
CUVA-0936	25630	SD BOTZUM PARKING	PUBLIC	AS	70,931	90	90	90	90	97	97	90					
CUVA-0939	25813	SD WETMORE TRAILHEAD PARKING	PUBLIC	AS	27,691	73	97	97	97	97	97	73					
CUVA-0940	25542	SD COVERED BRIDGE PARKING	PUBLIC	AS	15,288	73	97	97	97	97	97	73					
CUVA-0945	69860	ND PINE LANE TRAILHEAD PARKING	PUBLIC	AS	22,894	73	73	90	97	97	97	73					
CUVA-0951	24645	ND HINES HILL PARKING AREA	PUBLIC	AS	25,410	90	97	97	97	97	97	90					
CUVA-0954	25865	ND ROCKSIDE ROAD SHELTER PARKING	PUBLIC	AS	61,172	90	97	90	90	97	97	90					
CUVA-0957	25657	SD INDIGO LAKE PARKING AREA	PUBLIC	AS	8,031	90	97	97	97	97	97	90					
CUVA-0960	226198	ND CANCASCI DRIVE AND PARKING	PUBLIC	AS	6,659	73	97	97	90	97	97	73					
CUVA-0963	242362	ND FITZWATER ROAD TRAILHEAD PARKING	PUBLIC	AS	4,871	90	97	90	97	97	97	97					
CUVA-0965		SD CVEEC NOVEMBER LODGE PARKING	PUBLIC	AS	528	90	97	90	97	97	97	97					
CUVA-0969		SD CARTER GENERAL STORE PARKING (SHRO)	NONPUBLIC	C AS	3,070	73	90	97	97	97	97	73					
CUVA-0970	246335	ND BOSTON VISITOR CENTER PARKING A	NONPUBLIC	CO	38,987	97							97	97	97	97	97
CUVA-0971	246337	ND BOSTON VISITOR CENTER PARKING B	NONPUBLIC	ССО	21,156	97							97	97	97	97	97

Data Collection Date: 10/2019


Section 4 Park Route Location Maps





Cuyahoga Valley National Park ROUTE LOCATION MAP

Key Map




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community


NPS Collected Routes

	Miles	
0	3.5	7

Cuyahoga Valley National Park ROUTE LOCATION MAP




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community




Cuyahoga Valley National Park

ROUTE LOCATION MAP AREA MAP 2




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community




Cuyahoga Valley National Park


ROUTE LOCATION MAP




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community



Cuyahoga Valley National Park ROUTE LOCATION MAP




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community



Cuyahoga Valley National Park


ROUTE LOCATION MAP AREA MAP 4




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community



Cuyahoga Valley National Park ROUTE LOCATION MAP




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community




Cuyahoga Valley National Park ROUTE LOCATION MAP

AREA MAP 5A




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community




Cuyahoga Valley National Park

ROUTE CONDITION MAP PCR - MILE BY MILE Key Map




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community







ROUTE CONDITION MAP PCR - MILE BY MILE AREA MAP 1




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community






ROUTE CONDITION MAP PCR - MILE BY MILE AREA MAP 2




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community




	Miles				
0	1.5	3			

ROUTE CONDITION MAP PCR - MILE BY MILE AREA MAP 3




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community





ROUTE CONDITION MAP **PCR - MILE BY MILE AREA MAP 3A**




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend - Pavement Condition Rating (PCR) **Not Rated** Fair (61-84) **Excellent (95 - 100)** Poor (0 - 60) Good (85 - 94) Colors on map represent condition scores at 1-mile intervals. See Appendix for definitions and formulas


Only Data Collection Vehicle and Manually Rated Roads are displayed

	Miles	
0	0.2	0.4

ROUTE CONDITION MAP PCR - MILE BY MILE AREA MAP 4




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community




Miles
0 1 2



ROUTE CONDITION MAP PCR - MILE BY MILE AREA MAP 5



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community



Miles 1



Section 5 **Paved Road Condition Rating Sheets**




Cuyahoga Valley National Park



Cuyahoga Valley National Park ROUTE 0100: ND BRECKSVILLE STATION ROAD


Data Collection Vehicle (DCV) Rating



	Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60	_		(85 - 94)	Excellent (Not Ra	ted	
Colors	on map represent cond	dition scores at 0.10-mile	intervals. Se	e Appendix fo	or definitions	and formulas.		
Inspection Date:	10/18/2020	Beginning Section MP	0					
Paved Length (Mile	es): 0.21	Section Length (MI)	0.21					
Surface Type:	ASPHALT	Route Summary				•		
Roadway Condition	ı Information							
Pavement Conditio	n Rating (PCR)	7	7					
Surface Condition R	ating (SCR)	7	7					
Roughness Conditio	n Index (RCI)	N/A	N/A					
Distress Index Valu	es							
Structural Crack In	dex	7	7					
Alligator Crack Ind	lex	98	98					
Longitudinal Crack	Index	9	9					
Transverse Crackin	ig Index	79	79					
Patching Index		100	100					
Rutting Index		91	91					
International Rougl	hness Index (IRI)	N/A	N/A					
Lane & Width Info	rmation							
Number of Lanes		2	2					
Paved Width (ft)		23.6	23.6					
Lane Width (ft)		11.3	11.3					

ROUTE 0101ZZ: SD CUYAHOGA VALLEY EEC ROADS

Summary Route



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: The weighted average summary PCR value is calculated from only the sections of road where the PCR was collected. The overall PCR for the summary route may not reflect individual subcomponent ratings.

summary route may not r	ummary route may not reflect individual subcomponent ratings.							
	Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60)	Fair (6	1- 84)	Good	(85 - 94)	Excellent (95 - 100)	Not Ra	ted
	•	See Apper	ndix for def	initions and f	ormulas			
Inspection Date:	10/18/2020							
Paved Length (Miles	s): 0.52							
Surface Type:	ASPHALT	Route Sumn	nary			•		
Roadway Condition	Information							
Pavement Condition	Rating (PCR)	94						
Lane & Width Inform	mation							
Number of Lanes		1						
Paved Width (ft)		18.	8					
Lane Width (ft)		12						

ROUTE 0101Z: SD CUYAHOGA VALLEY EEC ROAD

Subcomponent of Route CUVA-0101ZZ

Data Collection Vehicle (DCV) Rating



	Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60	_		(85 - 94)	Excellent (Not Ra	ted	
	<u> </u>	dition scores at 0.10-mile		,	5			
Inspection Date:	10/18/2020	Beginning Section MP	0					
Paved Length (Mile	es): 0.38	Section Length (MI)	0.38					
Surface Type:	ASPHALT	Route Summary			!	!		
Roadway Condition	n Information							
Pavement Conditio	on Rating (PCR)	95	95					
Surface Condition R	Rating (SCR)	95	95					
Roughness Conditio	on Index (RCI)	N/A	N/A					
Distress Index Valu	es							
Structural Crack In	ıdex	97	97					
Alligator Crack Ind	dex	100	100					
Longitudinal Crack	x Index	97	97					
Transverse Crackin	ng Index	95	95					
Patching Index		100	100					
Rutting Index		98	98					
International Rough	hness Index (IRI)	N/A	N/A					
Lane & Width Info	rmation							
Number of Lanes		2	2					
Paved Width (ft)		20.1	20.1					
Lane Width (ft)		12.1	12.1					

Cuyahoga Valley National Park ROUTE 0102Z: SD CVEEC LIPSCOMB PARKING ROAD

Subcomponent of Route CUVA-0101ZZ Data Collection Vehicle (DCV) Rating




	Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60)	Fair (6		(85 - 94)	Excellent (Not Ra	ted	
Colors on n	nap represent con-	dition scores at 0.10-mile	e intervals. Se	`		and formulas.		
Inspection Date:	10/18/2020	Beginning Section MP	0					
Paved Length (Miles):	0.05	Section Length (MI)	0.05					
Surface Type:	ASPHALT	Route Summary				•		
Roadway Condition In:	formation							
Pavement Condition R	ating (PCR)	91	91					
Surface Condition Ratin	g (SCR)	91	91					
Roughness Condition In	dex (RCI)	N/A	N/A					
Distress Index Values								
Structural Crack Index		99	99					
Alligator Crack Index		100	100					
Longitudinal Crack Ind	lex	99	99					
Transverse Cracking In	ndex	96	96					
Patching Index		100	100					
Rutting Index		91	91					
International Roughnes	ss Index (IRI)	N/A	N/A					
Lane & Width Informa	ation							
Number of Lanes		2	2					
Paved Width (ft)		19.2	19.2					
Lane Width (ft)		9.8	9.8					

ROUTE 0204Z: SD EEC LIPSCOMB CAMPUS ROAD

Subcomponent of Route CUVA-0101ZZ

Data Collection Vehicle (DCV) Rating




	Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60			(85 - 94)	Excellent (Not Ra	ted	
· ·	· .	dition scores at 0.10-mile	· /					
Inspection Date:	10/18/2020	Beginning Section MP	0					
Paved Length (Mile	es): 0.04	Section Length (MI)	0.04					
Surface Type:	ASPHALT	Route Summary		!			!	
Roadway Condition	n Information							
Pavement Condition	on Rating (PCR)	88	88					
Surface Condition F	Rating (SCR)	88	88					
Roughness Condition	on Index (RCI)	N/A	N/A					
Distress Index Valu	ies							
Structural Crack In	ndex	99	99					
Alligator Crack Inc	dex	100	100					
Longitudinal Cracl	k Index	99	99					
Transverse Crackin	ng Index	88	88					
Patching Index		100	100					
Rutting Index		95	95					
International Roug	hness Index (IRI)	N/A	N/A					
Lane & Width Info	rmation							
Number of Lanes		1	1					
Paved Width (ft)		11.8	11.8					
Lane Width (ft)		11.8	11.8					

ROUTE 0205Z: SD EEC ADMINISTRATION ROAD

Subcomponent of Route CUVA-0101ZZ

Data Collection Vehicle (DCV) Rating



Pour	Route Condition Legend – Pavement Condition Rating (PCR)							
		(85 - 94)	Excellent (95 - 100)	Not Rated				
	ondition scores at 0.10-mile	· /						
			Appendix for definition	ils and formulas.				
Inspection Date: 10/18/2020	Beginning Section MP	0						
Paved Length (Miles): 0.04	Section Length (MI)	0.04						
Surface Type: ASPHALT	Route Summary			•				
Roadway Condition Information								
Pavement Condition Rating (PCR)	90	90						
Surface Condition Rating (SCR)	90	90						
Roughness Condition Index (RCI)	N/A	N/A						
Distress Index Values								
Structural Crack Index	93	93						
Alligator Crack Index	100	100						
Longitudinal Crack Index	93	93						
Transverse Cracking Index	90	90						
Patching Index	100	100						
Rutting Index	94	94						
International Roughness Index (IRI)	N/A	N/A						
Lane & Width Information								
Number of Lanes	1	1						
Paved Width (ft)	14	14						
Lane Width (ft)	14	14						

ROUTE 0202: SD OCTAGON ROAD

Data Collection Vehicle (DCV) Rating



Rou	Route Condition Legend – Pavement Condition Rating (PCR)							
		(85 - 94)	Excellent (95 - 100)	Not Rated				
` /	condition scores at 0.10-mile	× /						
Inspection Date: 10/18/2020	Beginning Section MP							
_ =	<u> </u>							
Paved Length (Miles): 0.45	Section Length (MI)	0.45						
Surface Type: ASPHALT	Route Summary							
Roadway Condition Information								
Pavement Condition Rating (PCR)	87	87						
Surface Condition Rating (SCR)	87	87						
Roughness Condition Index (RCI)	N/A	N/A						
Distress Index Values								
Structural Crack Index	87	87						
Alligator Crack Index	100	100						
Longitudinal Crack Index	87	87						
Transverse Cracking Index	99	99						
Patching Index	100	100						
Rutting Index	97	97						
International Roughness Index (IRI)	N/A	N/A						
Lane & Width Information								
Number of Lanes	2	2						
Paved Width (ft)	19.4	19.4						
Lane Width (ft)	9.8	9.8						

ROUTE 0203: SD LEDGES ROAD


Data Collection Vehicle (DCV) Rating



	Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60	_		(85 - 94)	Excellent (Not Ra	ted	
Colors o	on map represent con-	dition scores at 0.10-mile	intervals. Se	`		and formulas.		
Inspection Date:	10/18/2020	Beginning Section MP	0					
Paved Length (Miles	s): 0.33	Section Length (MI)	0.33					
Surface Type:	ASPHALT	Route Summary				•		
Roadway Condition	Information							
Pavement Condition	n Rating (PCR)	82	82					
Surface Condition Ra	ating (SCR)	82	82					
Roughness Condition	n Index (RCI)	N/A	N/A					
Distress Index Value	es							
Structural Crack Inc	lex	82	82					
Alligator Crack Inde	ex	100	100					
Longitudinal Crack	Index	82	82					
Transverse Cracking	g Index	97	97					
Patching Index		100	100					
Rutting Index		99	99					
International Rough	ness Index (IRI)	N/A	N/A					
Lane & Width Infor	mation							
Number of Lanes		2	2					
Paved Width (ft)		18.5	18.5					
Lane Width (ft)		8.7	8.7					

Cuyahoga Valley National Park ROUTE 0210: SD CVEEC NOVEMBER LODGE ROAD


Data Collection Vehicle (DCV) Rating



R	Route Condition Legend – Pavement Condition Rating (PCR)							
		1 (85 - 94)	Excellent (95 - 100)	Not Rated				
	nt condition scores at 0.10-mi	× /						
Inspection Date: 10/18/2020	Beginning Section M							
Paved Length (Miles): 0.13	Section Length (MI)	0.13						
Surface Type: ASPHALT	Route Summary		!					
Roadway Condition Information								
Pavement Condition Rating (PCR)	95	95						
Surface Condition Rating (SCR)	95	95						
Roughness Condition Index (RCI)	N/A	N/A						
Distress Index Values								
Structural Crack Index	96	96						
Alligator Crack Index	100	100						
Longitudinal Crack Index	96	96						
Transverse Cracking Index	96	96						
Patching Index	100	100						
Rutting Index	95	95						
International Roughness Index (IR	I) N/A	N/A						
Lane & Width Information								
Number of Lanes	1	1						
Paved Width (ft)	12.2	12.2						
Lane Width (ft)	12.2	12.2		1 1				

ROUTE 0214: ND STANFORD ROAD


Data Collection Vehicle (DCV) Rating



Ro	Route Condition Legend – Pavement Condition Rating (PCR)							
		(85 - 94)	Excellent (95 - 100)	Not Rated				
` /	condition scores at 0.10-mile	V						
Inspection Date: 10/18/2020	Beginning Section MP							
Paved Length (Miles): 0.64	Section Length (MI)	0.64						
Surface Type: ASPHALT	Route Summary		!					
Roadway Condition Information								
Pavement Condition Rating (PCR)	70	70						
Surface Condition Rating (SCR)	78	78						
Roughness Condition Index (RCI)	57	57						
Distress Index Values								
Structural Crack Index	86	86						
Alligator Crack Index	100	100						
Longitudinal Crack Index	86	86						
Transverse Cracking Index	100	100						
Patching Index	78	78						
Rutting Index	87	87						
International Roughness Index (IRI)	250	250						
Lane & Width Information								
Number of Lanes	2	2						
Paved Width (ft)	17.8	17.8						
Lane Width (ft)	8.9	8.9						

ROUTE 0400: ND FITZWATER MAINTENANCE YARD ROAD


Data Collection Vehicle (DCV) Rating



Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60	_		(85 - 94)	Excellent (Not Ra	ted
Colors	on map represent cond	dition scores at 0.10-mile	intervals. Se	e Appendix fo	or definitions	and formulas.	
Inspection Date:	10/18/2020	Beginning Section MP	0				
Paved Length (Mile	es): 0.34	Section Length (MI)	0.34				
Surface Type:	ASPHALT	Route Summary		•		•	
Roadway Condition	n Information						
Pavement Conditio	on Rating (PCR)	91	91				
Surface Condition R	Rating (SCR)	91	91				
Roughness Conditio	on Index (RCI)	N/A	N/A				
Distress Index Valu	ies						
Structural Crack In	ıdex	91	91				
Alligator Crack Inc	dex	100	100				
Longitudinal Crack	k Index	91	91				
Transverse Crackin	ng Index	98	98				
Patching Index		100	100				
Rutting Index		97	97				
International Roug	hness Index (IRI)	N/A	N/A				
Lane & Width Info	rmation						
Number of Lanes		2	2				
Paved Width (ft)		27.7	27.7				
Lane Width (ft)		11.2	11.2				


ROUTE 0403: SD IRA DORM ROAD

Data Collection Vehicle (DCV) Rating



Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60)	Fair (6)		1 (85 - 94)	Excellent (Not Ra	ted
		dition scores at 0.10-mi	× /	`			
	•	Beginning Section M		с пррепаіх іс І	or definitions	dia formatas.	
1 *	/2020						
Paved Length (Miles): 0.1		Section Length (MI)	0.1				
Surface Type: ASPH	IALT	Route Summary		•			
Roadway Condition Informa	ation						
Pavement Condition Rating	(PCR)	95	95				
Surface Condition Rating (SC	R)	95	95				
Roughness Condition Index (F	RCI)	N/A	N/A				
Distress Index Values							
Structural Crack Index		100	100				
Alligator Crack Index		100	100				
Longitudinal Crack Index		100	100				
Transverse Cracking Index		100	100				
Patching Index		100	100				
Rutting Index		95	95				
International Roughness Ind	ex (IRI)	N/A	N/A				
Lane & Width Information							
Number of Lanes		2	2				
Paved Width (ft)		13.9	13.9				
Lane Width (ft)		9.3	9.3				

Section 6 Paved Parking Area Condition Rating Sheets



Cuyahoga Valley National Park



ROUTE 0900: ND LOCK 39 TRAILHEAD PARKING

Manual Rating

FROM ROCKSIDE ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	42393	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
22,142	0.381	NOT APPLICABLE	NOT APPLICABLE
Curb Type		Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
PREVENTIVE MAINTENANCE		GOOI	O / 90

Route Condition Legend - Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated











ROUTE 0902: ND CANAL EXPLORATION CENTER PARKING

Manual Rating

FROM HILLSIDE ROAD (NON NPS)

TO PARKING

FMSS Number	User Access	Surface Type		
23304	PUBLIC	ASPHALT		
Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation		
0.799	4	DO NOTHING		
Curb Type		Curb & Gutter Type		
CRETE	NO CURB AND GUTTER			
Pavement Recommendation		ating / PCR		
PREVENTIVE MAINTENANCE		O / 90		
	23304 Lane Miles (11' Widths) 0.799 Type CRETE commendation	23304 PUBLIC Lane Miles (11' Widths) Curb Reveal (Inches) 0.799 4 Type Curb & G CRETE NO CURB A commendation Condition R		

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated











ROUTE 0903: ND FITZWATER MAINTENANCE YARD PARKING

Manual Rating

FROM END OF ROUTE 0400 (ND FITZWATER MAINTENANCE YARD ROAD)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type	
10/25/2019	42397	NONPUBLIC	ASPHALT	
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation	
51,081	0.879	3	DO NOTHING	
Curb	Curb Type		utter Type	
STO	STONE		ND GUTTER	
Pavement Recommendation		Condition R	ating / PCR	
LIGHT 3R TREATMENTS		FAIR / 73		
Douts Condition Logard Devemont Condition Dating (DCD)				

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated











ROUTE 0904: ND FRAZEE HOUSE PARKING

Manual Rating

FROM CANAL ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	23310	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
5,082	0.088	NOT APPLICABLE	NOT APPLICABLE
Curb Type		Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
PREVENTIVE MAINTENANCE		GOOI	O / 90

Route Condition Legend - Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated












ROUTE 0905: ND BRECKSVILLE STATION PARKING

Manual Rating

FROM END OF ROUTE 0100 (ND BRECKSVILLE STATION ROAD)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type		
10/25/2019	42399	PUBLIC	ASPHALT		
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation		
77,445	1.333	NOT APPLICABLE	NOT APPLICABLE		
Curb	Type	Curb & G	utter Type		
NO C	CURB	NO CURB AND GUTTER			
Pavement Rec	commendation	Condition R	ating / PCR		
HEAVY 3R T	REATMENTS	POOR	2 / 53		
	Route Condition Legend – Pavement Condition Rating (PCR)				
Poor (0 - 60)	Fair (61- 84) Good ((85 - 94) Excellent (95 - 10	0) Not Rated		
	See Appendix for definitions and formulas				



ROUTE 0906: ND CENTRAL MAINTENANCE & RECEIVING OFFICE PARKING


Manual Rating


FROM RIVERVIEW ROAD (NON NPS)

TO RIVERVIEW ROAD (NON NPS)

Inspection Date	FMSS Number	User Access	Surface Type		
10/25/2019	24492	NONPUBLIC	ASPHALT		
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation		
49,157	0.846	NOT APPLICABLE	NOT APPLICABLE		
Curb Type		Curb & Gutter Type			
NO CURB		NO CURB AND GUTTER			
Pavement Recommendation		Condition Rating / PCR			
LIGHT 3R TI	REATMENTS	FAIR	/ 73		
	Route Condition Legend – Pavement Condition Rating (PCR)				
Poor (0 - 60)	Fair (61- 84) Good ((85 - 94) Excellent (95 - 10	0) Not Rated		
See Appendix for definitions and formulas					

Note: No photos available for this parking area.





ROUTE 0907: ND RED LOCK TRAILHEAD PARKING

Manual Rating

FROM HIGHLAND ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	25882	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
8,537	0.147	NOT APPLICABLE	NOT APPLICABLE
Curb	Туре	Curb & Gutter Type	
NO (NO CURB		ND GUTTER
Pavement Recommendation		Condition R	Rating / PCR
HEAVY 3R TREATMENTS		POOR	2 / 53
Route Condition Legend - Payament Condition Rating (PCR)			

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)


Not Rated











ROUTE 0908A: ND HEADQUARTERS PARKING A

Manual Rating

FROM VAUGHN ROAD (NON NPS)

TO VAUGHN ROAD (NON NPS)

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	24659	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
6,482	0.112	NOT APPLICABLE	NOT APPLICABLE
Curb Type		Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
LIGHT 3R TREATMENTS		FAIR	. / 73

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)


Not Rated











ROUTE 0908B: ND HEADQUARTERS PARKING B

Manual Rating

FROM VAUGHN ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	42479	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
10,916	0.188	NOT APPLICABLE	NOT APPLICABLE
Curb	Curb Type		utter Type
NO (CURB	NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
PREVENTIVE MAINTENANCE		GOOI	O / 90
	(C I'' D ((DCD)		

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)


Not Rated











ROUTE 0909: ND DUPLEX PARKING

Manual Rating

FROM RIVERVIEW ROAD (NON NPS)

TO RIVERVIEW ROAD (NON NPS)

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	24661	NONPUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
12,660	0.218	1	DO NOTHING
Curb Type		Curb & Gutter Type	
WOOD		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
HEAVY 3R TREATMENTS		POOR / 53	
HEAVY 3R TREATMENTS		POOF	2 / 53

Route Condition Legend - Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated











ROUTE 0910: ND COONRAD PARKING

Manual Rating

FROM RIVERVIEW ROAD (NON NPS)

TO ROUTE 0443 (ND COONRAD RADIO TOWER ROAD)

Inspection Date	FMSS Number	User Access	Surface Type	
10/25/2019	24512	PUBLIC	ASPHALT	
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation	
17,052	0.294	NOT APPLICABLE	NOT APPLICABLE	
Curb Type		Curb & Gutter Type		
NO CURB		NO CURB AND GUTTER		
Pavement Recommendation		Condition Rating / PCR		
HEAVY 3R TREATMENTS		POOR / 53		
Route Condition Legend – Pavement Condition Rating (PCR)				
Poor (0 - 60)		(85 - 94) Excellent (95 - 10	0) Not Rated	
See Appendix for definitions and formulas				











ROUTE 0911: ND BRANDYWINE FALLS UPPER PARKING

Manual Rating

FROM BRANDYWINE ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	24488	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
41,267	0.711	NOT APPLICABLE	NOT APPLICABLE
Curb Type		Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
PREVENTIVE MAINTENANCE		GOOD / 90	

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)


Not Rated











ROUTE 0912: ND BOSTON GENERAL STORE PARKING

Manual Rating

FROM BOSTON MILLS ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	24482	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
25,753	0.443	NOT APPLICABLE	NOT APPLICABLE
Curb Type		Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
LIGHT 3R TREATMENTS		FAIR / 73	

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated











ROUTE 0913: ND BIKE & HIKE TRAILHEAD PARKING

Manual Rating

FROM BOSTON MILLS ROAD (NON NPS)

TO BOSTON MILLS ROAD (NON NPS)

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	42401	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
6,631	0.114	NOT APPLICABLE	NOT APPLICABLE
Curb Type		Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
PREVENTIVE MAINTENANCE		GOOD / 90	

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)


Not Rated











ROUTE 0914: ND LOCK 29 TRAILHEAD PARKING

Manual Rating

FROM WEST MILL STREET (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/24/2019	25891	PUBLIC	CONCRETE
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
28,775	0.495	NOT APPLICABLE	NOT APPLICABLE
Curb Type		Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
LIGHT 3R TREATMENTS		FAIR / 73	

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated











ROUTE 0915: ND SHADY KNOLL PICNIC AREA PARKING

Manual Rating

FROM COUNTY ROAD 303 (WEST STREETSBORO ROAD) (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/24/2019	25822	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
8,767	0.151	NOT APPLICABLE	NOT APPLICABLE
Curb Type		Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
HEAVY 3R TREATMENTS		POOR / 53	
Route Condition Legend – Pavement Condition Rating (PCR)			

Poor (0 - 60)

Fair (61-84)

Good (85 - 94)


Excellent (95 - 100)


Not Rated











ROUTE 0916: ND HAPPY DAYS VISITOR CENTER PARKING

Manual Rating

FROM COUNTY ROAD 303 (WEST STREETSBORO ROAD) (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/24/2019	24591	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
47,402	0.816	NOT APPLICABLE	NOT APPLICABLE
Curb	Туре	Curb & Gutter Type	
NO C	CURB	NO CURB AND GUTTER	
Pavement Rec	commendation	Condition Rating / PCR	
HEAVY 3R TREATMENTS		POOR / 53	
Route Condition Legend – Pavement Condition Rating (PCR)			

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated











ROUTE 0917: SD HAPPY DAYS VISITOR HANDICAP PARKING

Manual Rating

FROM COUNTY ROAD 303 (WEST STREETSBORO ROAD) (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	42403	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
15,281	0.263	5	DO NOTHING
Curb	Туре	Curb & Gutter Type	
STONE		NO CURB AND GUTTER	
Pavement Rec	commendation	Condition Rating / PCR	
PREVENTIVE MAINTENANCE		GOOD / 90	

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)


Not Rated











ROUTE 0918: SD OCTAGON PARKING

Manual Rating

FROM END OF ROUTE 0202 (SD OCTAGON ROAD)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/24/2019	24586	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
49,840	0.858	NOT APPLICABLE	NOT APPLICABLE
Curb	Туре	Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Rec	commendation	Condition Rating / PCR	
PREVENTIVE N	PREVENTIVE MAINTENANCE		O / 90

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated









ROUTE 0919: SD HORSESHOE POND PARKING

Manual Rating

FROM MAJOR ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	25794	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
9,253	0.159	NOT APPLICABLE	NOT APPLICABLE
Curb	Type Curb & Gutter Type		utter Type
NO CURB		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
RECONSTRUCTION		POOR	2 / 30

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)


Not Rated











ROUTE 0920: SD LEDGES PARKING

Manual Rating

FROM ROUTE 0203 (SD LEDGES ROAD)

TO ROUTE 0203 (SD LEDGES ROAD)

Inspection Date	FMSS Number	User Access	Surface Type
10/24/2019	24495	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
60,828	1.047	NOT APPLICABLE	NOT APPLICABLE
Curb	Туре	Curb & Gutter Type	
NO (CURB	NO CURB AND GUTTER	
Pavement Re	commendation	Condition Rating / PCR	
PREVENTIVE I	MAINTENANCE	GOOD / 90	
Pouts Condition Legand Devement Condition Pating (PCP)			

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated









ROUTE 0921: SD LEDGES OVERFLOW PARKING

Manual Rating

FROM END OF ROUTE 0203 (SD LEDGES ROAD)

TO ROUTE 0972 (SD LEDGES STORAGE)

Inspection Date	FMSS Number	User Access	Surface Type
10/24/2019	42405	NONPUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
7,776	0.134	NOT APPLICABLE	NOT APPLICABLE
Curb	Curb Type		utter Type
NO C	CURB	NO CURB AND GUTTER	
Pavement Rec	commendation	Condition Rating / PCR	
PREVENTIVE N	MAINTENANCE	GOOD / 90	
Route Condition Legend – Pavement Condition Rating (PCR)			

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated









ROUTE 0922: SD VIRGINIA KENDALL LAKE MAINTENANCE PARKING

Manual Rating

FROM TRUXELL ROAD (NON NPS)

TO ROUTE 0967 (SD VIRGINIA KENDALL UNPAVED MAINTENANCE PARKING)


Inspection Date	FMSS Number		User Access			Surface Type
10/25/2019	24497		NO	ONPUBLIC		ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Wid	lths)	Curb Reveal (Inches)		Curl	b Recommendation
18,575	0.32		NOT .	APPLICABLE	NO	OT APPLICABLE
Curb Type Curb & Gutter		utter Typ	pe			
NO (CURB		NO CURB AND GUTTER		TER	
Pavement Re	commendation		Condition Rating / PCR		CR	
HEAVY 3R T	REATMENTS		POOR / 53			
Route Condition Legend – Pavement			ment Cond	lition Rating (PCR)		
Poor (0 - 60)	Fair (61- 84)	Good (8	35 - 94)	Excellent (95 - 10	0)	Not Rated

Fair (61- 84) Good (85 - 94) **Excellent (95 - 100)**









ROUTE 0923: SD VIRGINIA KENDALL LAKE PARKING

Manual Rating

FROM TRUXELL ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/24/2019	23311	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
86,073	1.482	NOT APPLICABLE	NOT APPLICABLE
Curb	Туре	Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Rec	ment Recommendation		Rating / PCR
PREVENTIVE N	MAINTENANCE	GOOI	O / 90

Route Condition Legend - Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated











ROUTE 0924: SD PINE HOLLOW PARKING

Manual Rating

FROM QUICK ROAD (NON NPS)

TO QUICK ROAD (NON NPS)

Inspection Date	FMSS Number	User Access	Surface Type
10/24/2019	25800	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
75,683	1.303	NOT APPLICABLE	NOT APPLICABLE
Curb	Type	Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Rec	Pavement Recommendation		ating / PCR
DO NO	THING	EXCELLENT / 97	

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated











ROUTE 0925: SD CROW FOOT GULLY PARKING

Manual Rating

FROM QUICK ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/24/2019	42468	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
21,435	0.369	NOT APPLICABLE	NOT APPLICABLE
Curl	Туре	Curb & Gutter Type	
NO	CURB	NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
HEAVY 3R 7	HEAVY 3R TREATMENTS		2 / 53
	D . C 11.1 T 1 D	C HI D II (DCD)	

Route Condition Legend - Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated











ROUTE 0926: SD LITTLE MEADOW PARKING

Manual Rating

FROM QUICK ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/24/2019	24582	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
25,042	0.431	NOT APPLICABLE	NOT APPLICABLE
Curb	Туре	Curb & Gutter Type	
NO C	CURB	NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
PREVENTIVE N	MAINTENANCE	GOOD / 90	

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated











ROUTE 0927: SD EEC LIPSCOMB CAMPUS PARKING

Manual Rating

FROM ROUTE 0101ZZ (SD CUYAHOGA VALLEY EEC ROADS)

TO ROUTE 0210 (SD CVEEC NOVEMBER LODGE ROAD)


Inspection Date	FMSS Number	User Access	Surface Type			
10/25/2019	42470	PUBLIC	ASPHALT			
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation			
4,686	0.081	NOT APPLICABLE	NOT APPLICABLE			
Curl	Curb Type Curb & Gutter Type		utter Type			
NO	NO CURB AND GUTTER		ND GUTTER			
Pavement Re	Recommendation Condition Rating / PCR		Rating / PCR			
PREVENTIVE MAINTENANCE		GOOD / 90				
	Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated						
See Appendix for definitions and formulas						











ROUTE 0929: SD EEC LIPSCOMB RECEIVING PARKING

Manual Rating

FROM ROUTE 0101ZZ (SD CUYAHOGA VALLEY EEC ROADS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	25593	NONPUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
3,551	0.061	NOT APPLICABLE	NOT APPLICABLE
Curb Type		Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
PREVENTIVE MAINTENANCE		GOOI	O / 90

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated


See Appendix for definitions and formulas



Note: Parking area consists of multiple surface types: Asphalt is 2,039 square feet; Concrete is 1,512 square feet.







ROUTE 0931: SD EEC ADMINISTRATION PARKING

Manual Rating

FROM ROUTE 0101ZZ (SD CUYAHOGA VALLEY EEC ROADS)

TO ROUTE 0101ZZ (SD CUYAHOGA VALLEY EEC ROADS)

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	25591	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
23,358	0.402	NOT APPLICABLE	NOT APPLICABLE
Curb Type		Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
PREVENTIVE MAINTENANCE		GOOD / 90	
Route Condition Legend – Pavement Condition Rating (PCR)			

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated










ROUTE 0933: SD EEC WHITE PINE CAMPUS PARKING

Manual Rating

ADJACENT TO ROUTE 0101ZZ (SD CUYAHOGA VALLEY EEC ROADS)

Inspection Date	FMSS Number	User Access	Surface Type	
10/25/2019	42476	PUBLIC	ASPHALT	
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation	
1,798	0.031	NOT APPLICABLE	NOT APPLICABLE	
Curb Type		Curb & Gutter Type		
NO CURB		NO CURB AND GUTTER		
Pavement Recommendation		Condition R	ating / PCR	
PREVENTIVE I	PREVENTIVE MAINTENANCE		GOOD / 90	
Route Condition Legend – Pavement Condition Rating (PCR)				
Poor (0 - 60)			0) Not Rated	
See Appendix for definitions and formulas				



ROUTE 0934: SD HUNT FARM VISITOR INFORMATION CENTER PARKING

Manual Rating

FROM BOLANZ ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	42477	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
14,533	0.25	NOT APPLICABLE	NOT APPLICABLE
Curb	Curb Type Curb & Gutter Type		utter Type
NO (NO CURB		ND GUTTER
Pavement Recommendation		Condition Rating / PCR	
LIGHT 3R T	LIGHT 3R TREATMENTS		/ 73
			·

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)


Not Rated











ROUTE 0935: SD IRA TRAILHEAD PARKING

Manual Rating

FROM RIVERVIEW ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	25654	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
24,324	0.419	NOT APPLICABLE	NOT APPLICABLE
Curb Type		Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Recommendation Condition Rating / PCR		ating / PCR	
LIGHT 3R TI	LIGHT 3R TREATMENTS		/ 73

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated











ROUTE 0936: SD BOTZUM PARKING

Manual Rating

FROM RIVERVIEW ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	25630	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
70,931	1.221	6	DO NOTHING
Curb Type		Curb & Gutter Type	
CONCRETE		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
PREVENTIVE MAINTENANCE		GOOD / 90	

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated











ROUTE 0939: SD WETMORE TRAILHEAD PARKING

Manual Rating

FROM WETMORE ROAD (NON NPS)

TO WETMORE ROAD (NON NPS)

Inspection Date	FMSS Number	User Access	Surface Type
10/24/2019	25813	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
27,691	0.477	NOT APPLICABLE	NOT APPLICABLE
Curb Type		Curb & Gutter Type	
NO	CURB	NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
LIGHT 3R TREATMENTS FAIR / 73		/ 73	
		C HI D II (DCD)	

Route Condition Legend - Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)


Not Rated











ROUTE 0940: SD COVERED BRIDGE PARKING

Manual Rating

FROM EVERETT ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	25542	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
15,288	0.263	NOT APPLICABLE	NOT APPLICABLE
Curb	Curb Type Curb & Gutter Type		utter Type
NO C	NO CURB		ND GUTTER
Pavement Recommendation		Condition Rating / PCR	
LIGHT 3R TREATMENTS		FAIR	/ 73
			·

Route Condition Legend - Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated











ROUTE 0945: ND PINE LANE TRAILHEAD PARKING

Manual Rating


FROM COUNTY ROAD 303 (WEST STREETSBORO ROAD) (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/24/2019	69860	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
22,894	0.394	NOT APPLICABLE	NOT APPLICABLE
Curb Type		Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
LIGHT 3R TREATMENTS		FAIR / 73	
Route Condition Legend – Pavement Condition Rating (PCR)			
Page (0 60) Fair (61 84) Cond (85 94) Evenlent (95 100) Not Rated			Not Rated









ROUTE 0951: ND HINES HILL PARKING AREA

Manual Rating

FROM HINES HILL ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	24645	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
25,410	0.438	NOT APPLICABLE	NOT APPLICABLE
Curb Type		Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
PREVENTIVE MAINTENANCE		GOOI	O / 90

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)


Not Rated











ROUTE 0954: ND ROCKSIDE ROAD SHELTER PARKING

Manual Rating

FROM OLD ROCKSIDE ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	25865	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
61,172	1.053	NOT APPLICABLE	NOT APPLICABLE
Curk	Curb Type Curb & Gutter		utter Type
NO (NO CURB AND GUTTER		ND GUTTER
Pavement Recommendation Co		Condition R	Rating / PCR
PREVENTIVE I	PREVENTIVE MAINTENANCE		O / 90
Route Condition Legend - Present Condition Rating (PCR)			

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)


Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated





ROUTE 0957: SD INDIGO LAKE PARKING AREA

Manual Rating

FROM RIVERVIEW ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	25657	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
8,031	0.138	NOT APPLICABLE	NOT APPLICABLE
Curb Type		Curb & Gutter Type	
NO CURB		NO CURB AND GUTTER	
Pavement Recommendation		Condition Rating / PCR	
PREVENTIVE MAINTENANCE		GOOD / 90	

Route Condition Legend - Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)


Not Rated











ROUTE 0960: ND CANCASCI DRIVE AND PARKING

Manual Rating

FROM CHAFFEE ROAD (NON NPS)

TO PARKING

Inspection Date	nspection Date FMSS Number		Surface Type	
10/25/2019	226198	PUBLIC	ASPHALT	
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation	
6,659	0.115	NOT APPLICABLE	NOT APPLICABLE	
Curb	Туре	Curb & Gutter Type		
NO C	CURB	NO CURB A	ND GUTTER	
Pavement Rec	commendation	Condition R	Rating / PCR	
LIGHT 3R TI	REATMENTS	FAIR	. / 73	

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated












Cuyahoga Valley National Park ROUTE 0963: ND FITZWATER ROAD TRAILHEAD PARKING

Manual Rating

ADJACENT TO ROUTE 0400 (ND FITZWATER MAINTENANCE YARD ROAD)

Inspection Date	FMSS Number	User Access	Surface Type	
10/25/2019	242362	PUBLIC	ASPHALT	
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation	
4,871	0.084	NOT APPLICABLE	NOT APPLICABLE	
Curb	Туре	Curb & Gutter Type		
NO (CURB	NO CURB AND GUTTER		
Pavement Re	commendation	Condition Rating / PCR		
PREVENTIVE I	MAINTENANCE	GOOI	O / 90	
	Route Condition Legend - Pav	ement Condition Rating (PCR)		
Poor (0 - 60)	Fair (61- 84) Good ((85 - 94) Excellent (95 - 10	0) Not Rated	
	See Appendix for def	initions and formulas		



ROUTE 0965: SD CVEEC NOVEMBER LODGE PARKING

Manual Rating

ADJACENT TO ROUTE 0210 (SD CVEEC NOVEMBER LODGE ROAD)

Inspection Date	FMSS Number	User Access	Surface Type	
10/25/2019		PUBLIC	ASPHALT	
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation	
528	0.009	NOT APPLICABLE	NOT APPLICABLE	
Curb	Туре	Curb & Gutter Type		
NO C	CURB	NO CURB A	ND GUTTER	
Pavement Rec	commendation	Condition R	ating / PCR	
PREVENTIVE N	MAINTENANCE	GOOI	O / 90	
Route Condition Legend – Pavement Condition Rating (PCR)				

Poor (0 - 60) Fai

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated



ROUTE 0969: SD CARTER GENERAL STORE PARKING (SHRO)

Manual Rating

FROM EVERETT ROAD (NON NPS)

TO PARKING

Inspection Date	Inspection Date FMSS Number		Surface Type
10/25/2019		NONPUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
3,070	0.053	NOT APPLICABLE	NOT APPLICABLE
Curb	Type	Curb & G	utter Type
NO C	CURB	NO CURB A	ND GUTTER
Pavement Rec	commendation	Condition R	Rating / PCR
LIGHT 3R TI	REATMENTS	FAIR	. / 73

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)


Not Rated











ROUTE 0970: ND BOSTON VISITOR CENTER PARKING A

Manual Rating

FROM RIVERVIEW ROAD (NON NPS)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	246335	NONPUBLIC	CONCRETE
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
38,987	0.671	NOT APPLICABLE	NOT APPLICABLE
Curb	Туре	Curb & G	utter Type
NO C	CURB	NO CURB A	ND GUTTER
Pavement Rec	commendation	Condition R	Rating / PCR
DO NO	THING	EXCELL	ENT / 97

Route Condition Legend - Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated











ROUTE 0971: ND BOSTON VISITOR CENTER PARKING B

Manual Rating

FROM RIVERVIEW ROAD (NON NPS)

TO BOSTON MILLS ROAD (NON NPS)

Inspection Date	FMSS Number	User Access	Surface Type
10/25/2019	246337	NONPUBLIC	CONCRETE
Area (Sq. Ft.)	Lane Miles (11' Widths)	Curb Reveal (Inches)	Curb Recommendation
21,156	0.364	NOT APPLICABLE	NOT APPLICABLE
Curb	Type	Curb & G	utter Type
NO C	CURB	NO CURB A	ND GUTTER
Pavement Rec	commendation	Condition R	Rating / PCR
DO NO	THING	EXCELL	ENT / 97

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated











Section 7 Road Milepost Information



Cuyahoga Valley National Park



Road Milepost Information

This report section contains road milepost information for all paved roads in the park that were collected with the Data Collection Vehicle (DCV). The milepost data is obtained from the DCV by using a distance measuring instrument (DMI) that is calibrated to record mileage to the nearest thousandth of a mile. Park roads that were manually rated did not have milepost data collected, and thus are not included in this report section.

For Cycle 6, the information presented in this section differs from previous RIP cycles in that it does not contain the roadside features inventories for the paved park roads. Some examples of the features previously collected are signs, culverts/drop inlets, guardrails, curbing, pullouts, etc. If the park was collected in a previous RIP cycle, then the latest features data can be obtained by referencing the following:

Where to find the latest Features Inventories for NPS Parks:

- For Small Parks (parks with less than 10 miles of paved roads):
 - o Refer to Cycle 5 data (collected 2010 2014)
 - Features were reported in Section 9 of the *Cycle 5* RIP report
 - Video of features can be viewed using the PathViewVO program and Cycle 5 data
- For Large Parks (parks with more than 10 miles of paved roads):
 - o Refer to Cycle 4 data (collected 2006 2009)
 - Features were reported in Section 9 of the *Cycle 4* RIP report
 - Video of features can be viewed using the *VisiData* program and *Cycle 4* data
 - O Note: Features inventories were updated in Large Parks in *Cycle 5* only on a route by route basis if the route was new or modified in *Cycle 5*. If this is the case for a particular route, then features for the route can be obtained using the *PathViewVO* program and *Cycle 5* data (same as above for Small parks).

Milepost Events Verified in Cycle 6

In Cycle 6, the following events were collected and reported in Section 7 of this report:

- Intersections with roads and parking areas
- All bridges and culverts with BIP Numbers (bridge inspection program numbers)
- Mile Marker Signs
- One-Way travel directions
- Overpasses
- Tunnels
- Low Water Crossings (LWCR)
- Surface type changes
- Construction areas where no pavement condition data was obtained

GPS Mileage Matching

A consistent survey milepost and constant route length as recorded by the Data Collection Vehicle (DCV) is a challenge to maintain from one collection cycle to the next. The challenge is due to many factors such as driver characteristics, DMI calibration, tire pressure etc. After Cycle 4 (~2010), a decision was made to hold constant the length of roads so long as there was no physical change from reconstruction projects or realignments that would result in a change to the length of a road. Consequently, the "GPS Mileage Match" was implemented to specify which cycle the route length is being matched. Route mileages and GPS are matched to a previous collection whenever there is no physical change to a route alignment. The route mileage and GPS is not matched to previous cycles whenever it is determined that a road length and GPS needs to be updated. When this happens the GPS and length is updated to the cycle that displays the change, and that collection cycle is used as the matching cycle in subsequent collections of the road. Thus, the Cycle 6 GIS could be either the survey length collected in Cycle 4, Cycle 5, or Cycle 6 and therefore, may not match the survey milepost displayed in the latest Cycle 6 DCV video which is viewable in *PathView VO*.

The features inventories and road logs collected on NPS routes contain mileposts that are determined from the corresponding cycle that the GPS is matched to. Therefore, the mileposts contained in the Cycle 4 or 5 features inventories or the Cycle 6 road logs may not exactly match the survey milepost collected in the latest Cycle 6 video of the road.

Locating Mile Marker Signs

For routes that have mile marker signs along them, the milepost reported by RIP will most likely not line up exactly with the sign located in the field. This could be happening for many reasons, most likely due to either the error falling within the acceptable calibration range of the vehicle, or the level of accuracy that the mile marker signs were placed in the field.

Because mile marker signs are important features in many project plans and location descriptions, RIP is reporting locations of mile marker signs in three ways in Cycle 6:

- 1. Mileposts from Cycle 6 GIS: the official RIP milepost taken from the features inventories and the matching GPS/mileage cycle as described above. This is the milepost that should be used on project plans and when finding locations in the field
- 2. Mileposts from Cycle 6 Video: milepost shown to help locate the mile marker sign in the latest *Path View VO* video.
- 3. Latitude / Longitude: a constant way of locating a mile marker sign so long as the park has not moved the sign

The mileposts from Cycle 6 Video and GIS should be nearly the same, but on longer roads it has been observed that the Video milepost deviates more from the official GIS milepost that comes from the matching cycle.

CUVA: Route Milepost Log

ROUTE 0100: ND BRECKSVILLE STATION ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

FROM	TO			
MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	PAVED ROUTE (RIVERVIEW ROAD / NON NPS)
0.00	0.00	INTERSECTION	L	PAVED ROUTE (RIVERVIEW ROAD / NON NPS)
0.20	0.20	RAILROAD CROSSING	N/A	N/A
0.21	0.21	INTERSECTION	N/A	ROUTE 0905 (ND BRECKSVILLE STATION PARKING)

ROUTE 0101Z: SD CUYAHOGA VALLEY EEC ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	PAVED ROUTE (OAK HILL ROAD / NON NPS)
0.00	0.00	INTERSECTION	L	PAVED ROUTE (OAK HILL ROAD / NON NPS)
0.10	0.10	INTERSECTION	L	ROUTE 0102Z (SD CVEEC LIPSCOMB PARKING ROAD)
0.14	0.14	INTERSECTION	L	ROUTE 0204Z (SD EEC LIPSCOMB CAMPUS ROAD)
0.16	0.16	INTERSECTION	L	ROUTE 0929 (SD EEC LIPSCOMB RECEIVING PARKING)
0.28	0.28	INTERSECTION	R	ROUTE 0931 (SD EEC ADMINISTRATION PARKING)
0.28	0.28	INTERSECTION	L	ROUTE 0205Z (SD EEC ADMINISTRATION ROAD)
0.29	0.29	INTERSECTION	R	ROUTE 0931 (SD EEC ADMINISTRATION PARKING)
0.29	0.29	INTERSECTION	L	ROUTE 0205Z (SD EEC ADMINISTRATION ROAD)
0.33	0.33	ONE-WAY START	N/A	N/A
0.33	0.33	INTERSECTION	L	ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD) (OPPOSITE)
0.38	0.38	INTERSECTION	R	ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)
0.38	0.38	ONE-WAY END	N/A	N/A

CUVA: Route Milepost Log

ROUTE 0102Z: SD CVEEC LIPSCOMB PARKING ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)
0.00	0.00	INTERSECTION	L	ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)
0.02	0.02	INTERSECTION	R	ROUTE 0204Z (SD EEC LIPSCOMB CAMPUS ROAD)
0.05	0.05	INTERSECTION	N/A	ROUTE 0927 (SD EEC LIPSCOMB CAMPUS PARKING)

ROUTE 0202: SD OCTAGON ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	PAVED ROUTE (TRUXELL ROAD / NON NPS)
0.00	0.00	INTERSECTION	L	PAVED ROUTE (TRUXELL ROAD / NON NPS)
0.45	0.45	INTERSECTION	N/A	ROUTE 0918 (SD OCTAGON PARKING)

ROUTE 0203: SD LEDGES ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	PAVED ROUTE (KENDALL PARK ROAD / TRUXELL ROAD / NON NPS)
0.00	0.00	INTERSECTION	R	PAVED ROUTE (KENDALL PARK ROAD / TRUXELL ROAD / NON NPS)
0.25	0.25	INTERSECTION	L	ROUTE 0920 (SD LEDGES PARKING)
0.33	0.33	INTERSECTION	L	ROUTE 0920 (SD LEDGES PARKING)
0.33	0.33	INTERSECTION	N/A	ROUTE 0921 (SD LEDGES OVERFLOW PARKING)

CUVA: Route Milepost Log

ROUTE 0204Z: SD EEC LIPSCOMB CAMPUS ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)
0.00	0.00	INTERSECTION	L	ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)
0.00	0.00	ONE-WAY START	N/A	N/A
0.04	0.04	INTERSECTION	L	ROUTE 0102Z (SD CVEEC LIPSCOMB PARKING ROAD)
0.04	0.04	ONE-WAY END	N/A	N/A
0.04	0.04	INTERSECTION	R	ROUTE 0102Z (SD CVEEC LIPSCOMB PARKING ROAD)

ROUTE 0205Z: SD EEC ADMINISTRATION ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)
0.00	0.00	ONE-WAY START	N/A	
0.00	0.00	INTERSECTION	N/A	ROUTE 0931 (SD EEC ADMINISTRATION PARKING)
0.02	0.02	INTERSECTION	R	PAVED SERVICE ROAD
0.04	0.04	ONE-WAY END	N/A	
0.04	0.04	INTERSECTION	R	ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)
0.04	0.04	INTERSECTION	N/A	ROUTE 0931 (SD EEC ADMINISTRATION PARKING)
0.04	0.04	INTERSECTION	L	ROUTE 0101Z (SD CUYAHOGA VALLEY EEC ROAD)

ROUTE 0210: SD CVEEC NOVEMBER LODGE ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0927 (SD EEC LIPSCOMB CAMPUS PARKING)
0.10	0.10	INTERSECTION	R	ROUTE 0965 (SD CVEEC NOVEMBER LODGE PARKING)
0.11	0.11	INTERSECTION	R	ROUTE 0438 (SD CVEEC UNPAVED ROADS)
0.13	0.13	INTERSECTION	N/A	ROUTE 0210 (SD CVEEC NOVEMBER LODGE ROAD)
0.13	0.13	INTERSECTION	L	ROUTE 0210 (SD CVEEC NOVEMBER LODGE ROAD)

CUVA: Route Milepost Log

ROUTE 0214: ND STANFORD ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM	TO			
MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	PAVED ROUTE (STANFORD ROAD / NON NPS)
0.45	0.45	INTERSECTION	R	ROUTE 0207 (ND YOUTH HOSTEL ROAD)
0.64	0.64	INTERSECTION	N/A	END AT GATE

ROUTE 0400: ND FITZWATER MAINTENANCE YARD ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	PAVED ROUTE (CANAL ROAD / NON NPS)
0.00	0.00	INTERSECTION	L	PAVED ROUTE (CANAL ROAD / NON NPS)
0.00	0.04	BRIDGE	N/A	6160-036 (WASTE WIER BRIDGE)
0.04	0.09	BRIDGE	N/A	6160-035 (FITZWATER ROAD BRIDGE)
0.17	0.17	INTERSECTION	L	ROUTE 0963 (ND FITZWATER ROAD TRAILHEAD PARKING)
0.30	0.30	RAILROAD CROSSING	N/A	N/A
0.34	0.34	INTERSECTION	N/A	ROUTE 0903 (ND FITZWATER MAINTENANCE YARD PARKING)

ROUTE 0403: SD IRA DORM ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	PAVED ROUTE (MARTIN ROAD / NON NPS)
0.00	0.00	INTERSECTION	R	PAVED ROUTE (IRA ROAD / NON NPS)
0.04	0.04	INTERSECTION	R	UNPAVED ROUTE
0.04	0.04	INTERSECTION	L	ROUTE 0403 (SD IRA DORM ROAD)
0.10	0.10	INTERSECTION	N/A	ROUTE 0403 (SD IRA DORM ROAD)
0.10	0.10	INTERSECTION	L	ROUTE 0403 (SD IRA DORM ROAD)

Section 8 Appendix



Cuyahoga Valley National Park



Improvements to the RIP Index Equations and Determination of PCR

In 2005, the Federal Highway Administration (FHWA) began implementing the use of a Pavement Management System (PMS) to assist the National Park Service (NPS) in prioritizing Pavement Maintenance and Rehabilitation activities. The PMS used by FHWA is the Highway Pavement Management Application (HPMA) which has the ability to store inventory and condition data from the Road Inventory Program (RIP) and forecast future performance using prediction models. Outputs include performance and condition reports at the National, Region, Park, or Route level. A regional prioritized list and optimization have been produced for most regions and the Federal Highway Deferred Maintenance is calculated via the HPMA as well.

In an effort to improve the accuracy of treatment recommendations and pavement condition descriptions the distresses and indexes that comprise the Pavement Condition Rating (PCR), an extensive study was completed throughout 2010 that has resulted in changes to the RIP condition reporting method and specifically, the calculation of PCR. It was determined that a better representation of PCR could be achieved by modifying the relative impact certain distresses would have on the overall rating.

Through the use of HPMA data, it was noted that false failure indicators existed with the existing PCR model, and that it would be necessary to reduce their impact. The distresses affected in this way were Rutting and Roughness. Conversely, experience showed that roadways with extensive cracking present were often shown to have a high PCR. Therefore, the crack index models were adjusted to be more sensitive to changes in crack severity or quantity. It was also determined that these issues were not due to a problem with data acquisition (i.e. the RIP "van"), but with the way the collected data was processed. The final change was to provide guidance on when to use the Roughness Condition Index (RCI) in the PCR calculation. Roughness data is of little value to determining overall condition on routes that, due to their length or geometrics, have lower vehicle operating speeds. Therefore, in Cycle 5, only routes that have lengths of one half mile or greater and posted speed limits of 25 mph or greater will have RCI reported and included in the PCR calculations.

Additionally, methodologies were updated in 2013 for Manually Rated Routes (paved routes that the collection vehicle is unable to drive) as well as Parking Areas to provide more accurate condition data to the HPMA. These updated methodologies allow for the efficient assessment of pavement conditions using a visual inspection method to denote specific distresses. These distresses are indicative of current conditions, the causes for current and future deterioration, and identify the level of targeted repair and rehabilitation practices required.

The changes that were implemented were endorsed by management at both the FHWA and NPS. In order to show the effectiveness of these changes, several sites were ground truth tested in early 2014 to ensure that an improvement was achieved between the relationship of PCR and the actual Maintenance and Rehabilitation needs that were represented. The changes will allow greater use of RIP and HPMA data for not simply condition data reporting, but also as a reliable tool for project identification and selection.

Description of the Rating System

The Federal Highway Administration, National Park Service Road Inventory Program (NPS-RIP), collects roadway condition data on paved surfaces (asphalt, concrete, brick, and cobblestone) on roads, parkways, and parking areas in national parks nationwide. The road surface condition data is collected using an automated Data Collection Vehicle (DCV) and manually using Manually Rated Route (MRR) procedures. Roads having brick or cobblestone surfacing are not normally surveyed with the DCV, but are manually rated for condition rating.

The FHWA RIP is implemented based on the premise that an accurate pavement surface condition assessment can be accomplished using automated crack detection technology as applied to digital images. Various methods of pavement condition assessment have been developed over the years with varying degrees of accuracy and acceptance. The use of digital photography to record pavement images and subsequent crack detection and classification has undergone continuous improvements over the past decade. Digital cameras with increasingly superior resolution and high definition have become more affordable, and the proprietary programming code and algorithms have been improved in crack detection software.

With the use of quality digital photography and automated crack detection software, FHWA RIP is tasked with executing a pavement condition assessment on a network of roughly 5,700 miles of National Park Service roads and parkways. Because a subset of roads will be collected multiple times this cycle, the total collection length will be around 13,000 miles. Foremost in setting up the basis of pavement distress identification is employing the distress identification protocols used by FHWA. There is no single distress identification system that is universal among entities conducting a program of distress identification. For the purpose of the NPS RIP, FHWA employs distress identification protocols that are specific to this program.

FHWA has referenced the "Distress Identification Manual for the Long-Term Pavement Performance Program", Publication No. FHWA-RD 03-031, June 2003, as the point-of- reference for distress types on NPS pavement. In truth, the FHWA RIP distress types are similar to those described in the LTPP manual with some modifications. This document, "Distress Identification Manual for the NPS Road Inventory Program, Cycle 6, 2014-2020" was developed using the "Distress Identification Manual for the Long-Term Pavement Performance Program" as a guideline. Definitions of severity levels based on crack width contained in this document adhere to the LTPP Distress ID Manual. Modifications have been made to the definition of Alligator and Longitudinal Cracking and determination of Alligator Cracking severity. This manual also addresses Rutting and Roughness and its application to RIP.

Cycle 6 has launched in the spring of 2014 and will again comprise all parks, large and small, that are served by paved roads and/or parking areas. For Cycle 6, roughly 333 large and small parks will have all paved routes and parking areas collected at least once in the cycle, some will have multiple collections depending on the size of the park and the functional class of the route.

This "Distress Identification Manual for the NPS Road Inventory Program, Cycle 6, 2014-2020" will be used as a reference resource in crack detection and classification, determination of distress severity and extent, and in the calculation of distress index values for the FHWA RIP Cycle 6.


Explanation of the Condition Descriptions

In addition to the RIP Index changes that were implemented in Cycle 5, we will also aim to provide greater assistance in translating good/fair/poor categories into pavement needs categories. The PCR can be used to indicate the place in the Pavement Life Cycle and the types of treatments that should be considered now and into the future.

- Excellent/New: PCR of 95-100. Pavements in this range will require only spot repairs
- Good: PCR of 85-94. Pavements in this range will likely be candidates for preventive maintenance. Examples include Chip and Slurry Seals, Micro Surfacing and Thin Overlays.
- Fair: PCR of 61-84. Pavements in this range will likely be candidates of Light Rehabilitation (L3R). Examples include single-lift overlays up to 2.5 inches in total thickness, milling and overlays.
- Poor: PCR of 60 or below. Pavements in this range will likely be candidates of Heavy Rehabilitation or Reconstruction (H3R or 4R). Examples include Pulverization, Multiple Lift Overlays, and Reconstruction.

At this time, specific maintenance and rehabilitation activities should be evaluated and recommended at the project level. Site-specific conditions that influence treatment type should be determined based on performing a subsurface investigation and/or pavement condition survey, and not be based solely on RIP data. Additionally, RIP produces a snapshot of conditions the year in which the data was collected. For further information or to obtain additional PMS data from our (HPMA) please contact the Eastern Federal Lands pavement team.

Condition Categories and Treatments



Description of Pavement Treatment Types

- 1. **Preventive Maintenance** is a planned strategy of cost-effective treatments to an existing roadway system and its appurtenances that preserves the system, retards future deterioration, and maintains or improves the functional condition of the system (without significantly increasing the structural capacity). Preventive maintenance is typically applied to pavements in good condition having significant remaining service life. As a major component of pavement preservation, preventive maintenance is a strategy of extending the service life by applying cost-effective treatments to the surface or near-surface of structurally sound pavements. Examples of preventive treatments include asphalt crack sealing, chip sealing, slurry or micro-surfacing, thin and ultrathin hot-mix asphalt overlay, concrete joint sealing, diamond grinding, dowel-bar retrofit, and isolated, partial and/or full-depth concrete repairs to restore functionality of individual slabs.
- 2. Pavement Rehabilitation consists of structural enhancements that extend the service life of an existing pavement and/or improve its load carrying capacity. Rehabilitation techniques include restoration treatments and structural overlays. Rehabilitation projects extend the life of existing pavement structures either by restoring existing structural capacity through the elimination of age-related, environmental cracking of embrittled pavement surface or by increasing pavement thickness to strengthen existing pavement sections to accommodate existing or projected traffic loading conditions. Two sub-categories result from these distinctions, which are directly related to the restoration or increase of structural capacity.
 - **Light Rehabilitation** (**L3R**) Examples include single-lift overlays up to 2.5 inches in total thickness and milling and overlays for flexible pavements
 - **Heavy Rehabilitation (H3R)** Requires rehabilitation with grade improvement. H3R stands for resurfacing, restoration, and rehabilitation projects. H3R projects typically involve multi-depth (overlays greater than 2.5 inches) pavement improvement work (short of full-depth replacement) and targeted safety improvements. H3R projects generally involve retention of the existing three-dimensional alignment.
- 3. **Reconstruction** (4R) is defined as the replacement of the entire existing pavement structure by the placement of the equivalent or increased pavement structure. Reconstruction usually requires the complete removal and replacement of the existing pavement structure. Reconstruction may utilize either new or recycled materials incorporated into the materials used for the reconstruction of the complete pavement section. Reconstruction is required when a pavement has either failed or has become functionally obsolete.

Appendix A

Methodology for Determining Condition Ratings with the Data Collection Vehicle (DCV)

Surface Distresses Identified by the Data Collection Vehicle

Surface Condition Rating – SCR

Surface distresses are measured in the primary lane only. In the classification and measurement of all paved surface condition data, results will be reported in the database in record intervals of 0.02 miles (105.6 feet) (smallest granularity) along the route.

Surface distresses and rutting are determined from digital images that provide both the longitudinal and transverse profile. The images also provide an elevation profile of the road, creating a 3-dimensional image of the paved surface.

- Transverse Cracks
- Longitudinal Cracks
- Alligator Cracks
- Patching/Potholes
- Rutting

Each of the five surface distresses is assigned a computed surface distress index

- Transverse Crack Index
- Longitudinal Crack Index
- Alligator Crack Index
- Patching/Pothole Index
- Rutting Index

Surface distress data are classified as listed above, measured for severity, and quantified for extent. Classification, severity, and extent of these five surface distresses comprise the three main elements for calculation of Surface Condition Rating (SCR).

In addition to the five surface distresses, a Structural Crack Index is computed, which is a combination of the Longitudinal Crack Index and the Alligator Crack Index. The Structural Crack Index is then used in lieu of the LC and AC indices to compute SCR.

Roughness Condition Index - RCI

Additional condition data measured by DCV (lasers and accelerometers)

• Roughness (IRI)

Roughness is measured by FHWA's DCV and reported as International Roughness Index (IRI) in inches/mile. Using IRI, the Roughness Condition Index (RCI) is computed.

Pavement Condition Rating - PCR

Using the SCR (computed from the five surface distresses) and the RCI, an overall Pavement Condition Rating (PCR) is computed. The formula for PCR is:

Asphalt PCR =
$$(0.60 * SCR) + (0.40 * RCI)$$

Concrete PCR = RCI

A detailed description of each distress index formula, roughness index formula, SCR and PCR is provided in this document.

Each classified surface distress will fall into one or more severity - LOW, MEDIUM, or HIGH based on criteria listed. For each severity, an extent is established based on the measured quantity of the distress within that severity. Within each severity individual distresses are assigned a Maximum Allowable Extent (MAE). For example, LOW severity transverse cracking may be allowed up to 21.1 cracks within a 0.02 mile interval before it reaches MAE and fails.

The index formulas are based on a scale of 0 to 100. A PCR index value of 100 would indicate a "new" road with no measurable distresses or rough ride. A PCR value of 60 is determined to be terminable serviceability and the road is considered failed. The range of index values with condition descriptors is:

POOR = (less than or equal to 60), FAIR= (61 – 84), GOOD= (85 - 94), EXCELLENT= (95 - 100)

Index values are generally computed based on cumulative deducts of the measured severities. As shown in the index formulas below, as any single severity reaches or exceeds MAE, the index computes to a value of 60 or less, and the road fails for that 0.02 interval.

Note: As a result of a unique combination of measured surface distresses and IRI, index values occasionally compute to less than 0 or greater than 100. In this instance, an index value less than 0 defaults to 0. Index values greater than 100 defaults to 100. For all indices, a higher value indicates a better road condition, and a lower value indicates a poorer road condition.

On the following page, Table 1 summarizes the different types of distresses measured.

ASPHALT-SURFACED PAVEMENT DISTRESS TYPES WITH RUTTING AND ROUGHNESS					
Distress Type	Units Of Measure	Converted To	Defined Severity Levels?	Measured By	
Alligator Cracking	Square Feet	Percent of Lane Per 0.02 Mile	Yes	3 Dimensional pavement imaging system	
Transverse Cracking	Linear feet	Number of Cracks Per 0.02 Mile	Yes	3 Dimensional pavement imaging system	
Longitudinal Cracking	Linear feet	Percent of Lane Length Per 0.02 Mile	Yes	3 Dimensional pavement imaging system	
Patching / Potholes	Square Feet	Percent of Lane Per 0.02 Mile	No	3 Dimensional pavement imaging system	
Rutting	Inches	Rut Depth Per 0.02 Mile	Yes	3 Dimensional pavement imaging system	
Roughness	IRI	*RCI Per 0.02 Mile	No	DCV – Lasers / Accelerometers	

^{*}Note: Roughness is measured on concrete roadways, but surface distresses and rutting are not measured.

For concrete, PCR = RCI

Table 1. Distress summary

Alligator Cracking

Description:

Alligator cracking is considered a combination of fatigue and block cracking. It is a series of interconnected cracks in various stages of development. Alligator cracking develops into a many-sided pattern that resembles chicken wire or alligator skin. It can occur anywhere in the road lane. Alligator cracking must have a quantifiable area.

Severity Levels:

LOW

An area with little to no interconnecting cracks with no visible spalling. Cracks are less than or equal to a mean width of 0.25 in. (6mm). Cracks in the pattern are no further apart than 1 foot (0.328 m). May be sealed cracks with sealant in good condition and a crack width that cannot be determined.

MEDIUM

An area of interconnected cracks that form a complete pattern. Cracks may be slightly spalled. Cracks are greater than 0.25 in. (6 mm) but less than or equal to 0.75 in. (19 mm) or any crack with a mean width less than or equal to 0.75 in. (19 mm) and adjacent low severity cracking. Cracks in the pattern are no further apart than 6 in. (150 mm).

HIGH

An area of interconnected cracks forming a complete pattern. Cracks are moderately or severely spalled. Cracks are greater than 0.75 in. (19mm) or any crack with a mean width less than or equal to 0.75 in. (19mm) and adjacent medium to high severity random cracking.

A combination of observed crack width and crack pattern is used to determine overall severity of alligator cracking. Based on above description of each severity, the highest level of crack width and crack pattern determines overall severity as shown in Table 2.

ALLIGATOR CRACKING SEVERITY LEVELS					
	CRACK	CRACK PATTERN			
	SEVERITY	LOW	MED	HIGH	
CD A CIZ	LOW	LOW	MED	HIGH	
CRACK WIDTH	MED	MED	MED	HIGH	
WIDIII	HIGH	HIGH	HIGH	HIGH	

Table 2. Alligator Crack Severity Levels

Longitudinal Cracking

Description:

Longitudinal cracking occurs predominantly parallel to the pavement centerline. It can occur anywhere within the lane. Longitudinal cracks occurring in the wheelpath may be noteworthy.

Severity Levels:

LOW

Cracks with a mean width less than or equal to 0.25 in. (6 mm). This also includes sealed cracks with sealant in good condition and a width that cannot be determined.

MEDIUM

Cracks with a mean width greater than 0.25 in. (6 mm) but less than 0.75 in. (19 mm). Also, any crack with a mean width less than 0.75 in. (19 mm) and adjacent random low severity cracking.

HIGH

Cracks with a mean width greater than 0.75 in. (19 mm). Also, any crack with a mean width less than 0.75 in. (19 mm) and adjacent random medium to high severity cracking.

Transverse Cracking

Description:

Transverse cracking occurs predominantly perpendicular to the pavement centerline. It can occur anywhere within the lane.

Severity Levels:

LOW

Cracks with a mean width of less than or equal to 0.25 in. (6 mm). Sealed cracks with sealant in good condition and a width that cannot be determined.

MEDIUM

Cracks with a mean width greater 0.25 in. (6 mm) and less than or equal to 0.75 in. (19 mm). Also, any crack with a mean width less than 0.75 in. (19 mm) and adjacent random low severity cracking.

HIGH

Cracks with a mean width greater than 0.75 in. (19 mm). Also, any crack with a mean width less than 0.75 in. (19 mm) and adjacent random medium to high severity cracking.

Patching and Potholes

Description:

Patching is an area of pavement surface that has been removed and replaced with patching material or an area of pavement surface that has had additional patching material applied. Patching may encompass partial lane or full lane width. On full lane width patching; the total, contiguous length of patch may not exceed 0.100 mi. (0.161 km). (Any full-lane patch exceeding 0.100 mi. in length is considered a pavement change). Patching must have a quantifiable area.

Potholes are bowl-shaped holes of various sizes occurring in the pavement surface.

Manhole covers should not be rated as patches unless there is obvious patching around the manhole.

Speed bumps should not be rated as patches

Severity Levels:

There are no stratified severities for Patching and Potholes. They either are present or they are not.

RUTTING

Description:

Rutting is a longitudinal surface depression in the wheelpath.

Severity Levels:

LOW

Ruts with a measured depth of 0.20 inches to 0.49 inches Ruts less than 0.20 in. are not included in the distress calculations.

MEDIUM

Ruts with a measured depth of 0.50 inches to 0.99 inches

HIGH

Ruts with a measured depth greater than 1.00 inch

ROUGHNESS

Description:

Roughness is the measurement of the unevenness of the pavement in the direction of travel. It is measured in units of IRI (International Roughness Index), inches per mile, and is indicative of ride comfort.

Severity Levels:

There are no stratified severity levels for roughness. The roughness (or smoothness) of a road surface can be defined by IRI in the following table.

IRI DESCRIPTIONS				
Type of Road	Typical IRI (in/mile)			
New Road, no noticeable roughness	<90			
Small level of roughness	90 – 126			
Road of average roughness	126 – 190			
Road with above average roughness	190 – 253			
Road with severe roughness	253 – 380			
Nearly impassable	>380			

Table 3. International Roughness Index

Roughness Collection Parameters

On shorter roads with a lower speed limit the usefulness in collecting and reporting IRI is negligible. Lower, inconsistent speeds can lead to a less accurate IRI value. Therefore RIP has put in place the following protocols for reporting IRI.

International Roughness Index (IRI) is not reported on routes with the following criteria:

- Posted speed limit is less than 25 mph
- Length of route is less than 0.50 miles

When a collected route has a posted speed limit of at least 25 mph and length of at least 0.50 miles, IRI will be collected except on road sections where the speed is less than 20 mph

Other situations may arise where the speed and length factors are met, but reporting IRI could lead to an inaccurate PCR. RIP will determine whether or not it is reasonable to report IRI on these routes on a case by case basis.

Index Formulas

Note: All index formulas listed below contain MAE applicable to 0.02 mile (105.6 feet) interval.

Alligator Crack Index

AC INDEX =
$$100 - 40 * [(\%LOW / 35) + (\%MED / 15) + (\%HI / 5)]$$

Where:

The values %LOW, %MED and %HI report the percentage of the observed pavement (0.02 mile, primary lane) that contains alligator cracking within the respective severities. These values range from 0 to 100.

%LOW = Percent of total area (primary lane, 0.02 in length), low severity %MED = Percent of total area (primary lane, 0.02 in length), medium severity %HI = Percent of total area (primary lane, 0.02 in length), high severity

Percent of total area is computed as:

square foot area of alligator crack severity (0.02 mile)*(lane width)

In AC_INDEX, the denominators 35, 15, and 5 are the Maximum Allowable Extents (MAE) for each severity. In other words, we will allow up to 35% of low severity alligator cracking for a 0.02 interval before failure, 15% for medium severity, and so on. As you can see, if any single severity reaches MAE the resulting index value is 60, or failure.

Longitudinal Crack Index

$$LC_{INDEX} = 100 - 40 * [(\%LOW / 175) + (\%MED / 75) + (\%HI / 25)]$$

Where:

The values %LOW, %MED, and %HI report the length of longitudinal cracking within each severity as a percent of the section length (0.02 mile, primary lane). These values are greater than or equal to 0 and can exceed 100.

%LOW = Percent of interval length (primary lane, 0.02 in length), low severity %MED = Percent of interval length (primary lane, 0.02 in length), medium severity %HI = Percent of interval length (primary lane, 0.02 in length), high severity

Percent of interval length is computed as:

length of respective longitudinal cracking (0.02 mile)*(105.6 ft.)

In LC_INDEX, the denominators 175, 75, and 25 are the Maximum Allowable Extents (MAE) for each severity. In other words, we will allow up to 175% of low severity longitudinal cracking for a 0.02 interval before failure, 75% for medium severity, and so on. As you can see, if any single severity reaches MAE the resulting index value is 60, or failure.

Structural Crack Index

$$SC_{INDEX} = [100 - ((100 - AC_{INDEX}) + (100 - LC_{INDEX}))]$$

Structural Crack Index is a combination of Alligator Cracking and Longitudinal Cracking, and is used in the SCR formula in lieu of AC and LC separately.

Transverse Crack Index

$$TC_{INDEX} = 100 - 40 * [(LOW / 21.1) + (MED / 4.4) + (HI / 2.6)]$$

Where:

The values LOW, MED and HI report a count of the total number of transverse cracks (reported to three decimals) within each severity level, where one transverse crack is equal to the lane width. These values are greater than or equal to 0.

LOW = Number of cracks in interval (primary lane, 0.02 in length), low severity MED = Number of cracks in interval (primary lane, 0.02 in length), medium severity HI = Number of cracks in interval (primary lane, 0.02 in length), high severity

Number of cracks is computed as:

Total length of transverse cracks
Lane width

In TC_INDEX, the denominators 21.1, 4.4, and 2.6 are the Maximum Allowable Extents (MAE) for each severity. In other words, we will allow up to 21.1 low severity transverse cracks for a 0.02 interval before failure, 4.4 cracks for medium severity, and so on. As you can see, if any single severity reaches MAE the resulting index value is 60, or failure.

Patching Index

PATCH_INDEX =
$$(100 - 40) * (\% PATCHING / 80)$$

Where:

The value %PATCHING reports the percentage of the observed pavement (0.02 mile, primary lane) that contains patching/potholes. This value ranges from 0 to 100.

%PATCHING = Percent of total area (primary lane, 0.02 in length)

Percent of total area is computed as:

square foot area of patching/potholes (0.02 mile)*(lane width)

There are no severity levels for patching. It either exists or does not.

There are no severity levels for patching. It either exists or does not. In PATCH_INDEX, the denominator 80 is the Maximum Allowable Extent (MAE) for each severity. In other words, we will allow up to 80% patching for a 0.02 interval before failure. As you can see, if patching/potholes reaches MAE the resulting index value is 60, or failure.

Rutting Index

RUT_INDEX =
$$100 - 40 * [(\%LOW / 535) + (\%MED / 205) + (\%HI / 40)]$$

Where:

20 rut depth measurements are taken per 0.02 interval for each of 2 wheel paths (left and right), resulting in a total of 40 measurements taken for both wheel paths. Each wheelpath is analyzed independently for rut severities. The values %LOW, %MED and %HI report the percentage of the 40 measurements within that severity. These values range from 0 to 200.

%LOW = Percent of LOW ruts in left wheelpath based on 20 ruts, plus percent of LOW ruts in right wheelpath based on 20 ruts.

%MED = Percent of MED ruts in left wheelpath based on 20 ruts, plus percent of MED ruts in right wheelpath based on 20 ruts.

%HI = Percent of HI ruts in left wheelpath based on 20 ruts, plus percent of HI ruts in right wheel path based on 20 ruts.

Percent of rut measurements within each severity can also be computed as:

$$\frac{(total\ number\ of\ ruts\ within\ each\ severity\ in\ both\ wheelpaths)}{20}\times 100$$

In RUT_INDEX, the denominators 535, 205, and 40 are the Maximum Allowable Extents for each severity; Low, Medium, and High, respectively. Only the MAE for high severity rutting can fail a section, since 200% of *only* low severity ruts would yield a rut index of 85 and 200% of *only* medium severity ruts would yield a rut index of 61.

Roughness Condition Index (Asphalt)

$$RCI = 32 * [5 * (2.718282^{(-.0041 * AVG IRI)})]$$

Where:

The value AVG IRI reports the average value of the Left IRI and Right IRI measurements for the interval (0.02 mile, primary lane). This value can range from approximately 40 to 999.0.

Average IRI is computed as:

There is no applicable threshold for failure for this index.

Roughness Condition Index (Concrete)

$$RCI = (-0.0012)(IRI^2) + (0.0499)(IRI) + 99.542$$

For concrete, PCR = RCI

Surface Condition Rating Index

SCR = Lowest Index Value Of: [SC_INDEX, TC_INDEX, PATCH_INDEX, RUT_INDEX]

Note: The modified SCR equation above combines AC_INDEX and LC_INDEX, and considers that a single AC/LC index value of the Structural Crack Index (SC_INDEX). The lowest of the four computed index values (SC_INDEX, TC_INDEX, PATCH_INDEX, or RUT_INDEX) becomes the SCR.

Where:

See above for determinations of SC_INDEX, TC_INDEX, PATCH_INDEX and RUT_INDEX.

The threshold for failure for this index is SCR = 60.Data Collection Vehicle Subsystems

Data on paved roads is collected by FHWA using a Pathway Services Inc. Data Collection Vehicle (DCV), called a PathRunner. The DCV is driven in the primary-direction lane at posted speed limits and less.

Cameras

Forward-facing and rear-facing video is collected as jpeg digital imagery files at a frequency of every 26.4feet.

Two forward-facing cameras are mounted above the vehicle cab, one pointed straight ahead and the other to the right shoulder providing seamless roughly 120 degree viewing. A third camera is mounted in the rear of the vehicle, recording the left shoulder.

CAMERA SPECIFICATIONS TWO FORWARD / ONE REAR FACING CAMERA			
Camera lens/type	Prosilica GT 2750 (GigE Technology)		
Image format	*.jpg		
Image resolution	2750 x 2200, 18 frames/second		
Image pixel size	depends on distance		
Zoom ratio	16mm Fixed		
	Aperture Range F 1.8 – Infinity (P-Iris,		
Iris range	Automatic		

Pavement Imaging and Rutting

High resolution rutting data and surface imaging are collected in a single data stream using a three-dimensional (3D) pavement surface transverse profile data acquisition system. The 3D camera captures a laser line as it is projected over the pavement surface and uses the location of this line to measure the height deviations of the pavement surface. These height deviations can be used to calculate rutting in both wheelpaths. These deviations also provide a grayscale image detailing the change in height throughout the surface, i.e. providing depth measurements for cracking.

THREE-DIMENSIONAL PAVEMENT SURFACE AND TRANSVERSE PROFILE DATA ACQUISITION SYSTEM				
Surface Image Specifications				
Image size	1536 pixels/scan @3000 Hz			
Image width	4 meters (3950 mm nominal)			
Laser class	3B			
Power	16W (Two lasers @ 8W Ea)			
Vehicle speed limitations	62 mph			
Environment	Dry pavement, day or night			
Sensor size (approximate)	1536 pixels x 512 pixels			
Image display length	26.4 feet			
Rutting Specifications				
Reported rut depth units	Inches			
Vehicle speed limitations	Up to 62 mph			
Sampling rate	3000 profiles/second			
Transverse resolution	1536 points/profile			
Transverse field-of-view	14 feet			
Depth accuracy (nominal)	<1mm			
Environment	Dry pavement, day or night, above 32 degrees F			
Adherence to specifications	ASTM E1703M-95 (reapproved 2005)			

Distance Measuring Instrument (DMI)

The DMI (Distance Measuring Instrument) obtains road length measurements that are accurate to 0.15% for speeds up to 60 mph. The DMI is connected to the hub of the rear wheel on the driver's side, and is calibrated to the revolutions of the rear vehicle axle on a regular basis.

Roughness (IRI)

IRI SPECIFICATIONS				
Reported IRI units	Inches/mile			
Vehicle speed limitations	12-62 mph			
IRI equipment certification	Texas Transportation Institute (TTI)			
Wavelengths accommodated	0.5 feet to 300 feet			
IRI computed & reported	World Bank Technical Paper Number 46			
Environment	Dry pavement, day or night, above 32 degrees			
Adherence to specifications	ASTM E950 Class 1 & AASHTO M 328			

The collection system includes a South Dakota type laser profiler manufactured based on active Class 1 ASTM E950 standards. The dynamic profile of the pavement surface is collected from which the IRI roughness data is computed. The sensors include one accelerometer on each wheelpath, one height sensor (laser) on each wheelpath, and a distance transducer.

GPS & Inertial Systems

GPS is collected by an onboard system employing Omnistar real time correction and a spinning gyroscope to provide accurate positioning data in instances of satellite obstruction. All GPS coordinates are tied to an image and linear distance measurements.

GPS SPECIFICATIONS				
Static accuracy	Sub-meter			
Dynamic accuracy	2-3 meters			
Receiver	12 satellite tracking			
Coordinate system	Lat Lon WGS 84			
Environment	Day or night			
Cross-slope	± 1.75%			
Grade	± 1.75%			
Adherence to specifications	ASTM E1703M-95 (reapproved 2005)			

*NOTE – GPS accuracy is dependent on many different factors. Satellite constellation, tree coverage, GPS receiver quality, and real-time correction availability can all affect the locational and elevation accuracies. The elevation (z coordinate) accuracy is less dependable than locational or horizontal accuracy (x/y coordinates or latitude/longitude). In areas of heavy tree coverage or poor satellite constellations, elevation data can vary by as much as +/- 100 feet.

Appendix B

Methodology for Determining Condition Ratings Using Manual Rating Procedures

Description of Manual Rating Methods

In 2013, the Federal Highway Administration updated existing Manual Rating Procedures in an effort to better align pavement conditions for Manually Rated Routes and Parking with the Highway Pavement Management Application (HPMA). HPMA is the Pavement Management System used by the FHWA to store inventory and condition data from the Road Inventory Program (RIP) and forecast future performance using prediction models. HPMA uses pavement condition data (collected by the Road Inventory Program) to develop life cycles for pavements and recommend treatments to maximize useable pavement life while minimizing costs associated with maintenance and repair.

The Federal Highway Administration (FHWA) developed a set of manual rating methods for pavement that are appropriate for Federal Roadways. Two different methods were developed for linear roads and a separate method was developed for parking areas and nonlinear roads. These methods employ a 0 to 100 rating scale and improve consistency and objectivity in the manual evaluation of surface distresses. They are compatible with ratings that are collected by the automated Data Collection Vehicle (DCV).

- The first of the two manual evaluation methods for roads uses rating criteria to assign index values to each distress type based on a visual evaluation of severity and extent.
- The second manual evaluation method for roads is very time demanding and is best employed on only a select set of routes which may have the highest visitor use and require a more intensive assessment. This method will be used for the Manual Rating of Function Class 1, 2, 7, and 8 Roads. This method is based on measurements that are recorded for each instance of a surface distress. These measurements are converted into index values using conversion formulas.
- Parking areas and non-linear roads are rated similar to the first method shown above, however, there are some slight differences due to the non-linear nature.

The details and criteria used for each of these rating methods are outlined below.

Visual Inspection Method for Manually Rating Secondary Roads

The visual inspection method for manually rated roads uses condition rating criteria that have been developed by FHWA. This criteria is based on a visual evaluation of the severity and extent of distresses to determine the overall condition of the roadway. This method is used for secondary roads that are Functional Class 3, 4, 5, and 6. This constitutes the majority of manually rated roads collected by the Road Inventory Program.

Rating Section Lengths

For this method, Manually Rated Roads are rated in sections. These sections may be made based on length of changes in surface type or condition as described below. The ratings are then aggregated to give an overall rating for the Route:

- Rating sections should be no longer than 0.25 miles in order to keep the area being rated manageable.
- A new rating section may be started based on changes in condition, width, or surface type if these changes represent a significant portion of the route (are not isolated instances).
- If the road condition, width, and surface type remain constant then new sections do not need to be created unless the road exceeds 0.25 miles.

Rating Criteria

For this method, Manually Rated Roads are evaluated using a visual inspection of the six distress types listed below. Each distress is assigned one of five index values. An overall Surface Condition Rating (SCR) and Pavement Condition Rating (PCR) are calculated based on these index values.

- Alligator Cracking
 - o Rating based on percentage of road surface affected
- Longitudinal Cracking
 - o Rating based on severity level (crack width) and percentage of road section length of longitudinal cracks
- Transverse Cracking
 - o Rating based on crack width, crack spacing, and percentage of surface affected
- Patching
 - o Rating based on percentage of road surface affected
- Rutting
 - o Rating based on percentage of road section length affected by visible rutting (>1 inch depth) that requires remediation
- Roughness
 - o Manual assessments of roughness are not made due to the subjectivity of the measurement. Therefore, roughness is not incorporated into the PCR calculation of manually rated roads.

Concrete Routes also receive a PCR rating based on visual evaluation of the following six distress types.

- Slab Faulting at Joints
- Slab Cracking and breakup
- Surface Delamination and Pop-outs
- Joint Distresses
- Patching

Distress Measurement Method for Manually Rating Primary Roads

A more intensive and time demanding assessment than our standard method was developed for Primary roads that are functional class 1, 2, 7, or 8. These high visitation roads are usually accessible by the automated Data Collection Vehicle but in rare instances may need to be manually rated. The method developed is based on measuring each instance of a distress. These measurements are totaled over each section length being measured and are then converted into index values between 0 and 100 (100 being a road with no distress) using index formula equations outlined below. The goal of this method is to produce measured index values which are directly comparable to the automated DCV.

Rating Section Lengths

For the distress measurement method roads are broken into sections in order to rate. Distress measurements are totaled for each section separately in order to determine the index value for that particular section. The section length to be rated is determined based on the following rules:

- Rating sections are between 0.25 and 0.50 miles long
- A new rating section is created if there is a significant change in condition or pavement width
- If there are no significant changes in condition or pavement width, rating sections are broken at equal intervals, typically 0.50 miles

Manual Distress Measurements

Alligator Cracking

- Alligator cracking is measured by area (square feet). Instances of Alligator cracking are measured along the length and multiplied by the average width of the distressed area.
- The index for alligator cracking takes the total area of cracking compared to the interval length and converts it to a percentage. That percentage is then input into an index formula that yields a value between 0 and 100 (0 being the most distressed).
- Severity levels are not defined for manually measured Alligator cracks. The Alligator Crack Index formula is calculated based on an assumption of medium severity.

Longitudinal Cracking

- Longitudinal cracking (cracking in the direction parallel to the roadway) is measured by length (ft.).
- The index for longitudinal cracking takes the total length of cracking compared to the interval length and converts it to a percentage broken down by severity. That percentage is then input into a formula that yields a value between 0 and 100 (0 being the most distressed).
- Two severity levels are defined for manually measured Longitudinal Cracks. Lower severity cracks are those with a mean width of less than 0.25 inches. Sealed cracks with sealant in good condition are also considered lower severity. Higher severity cracks are those with a mean width of greater than 0.25 inches.

Transverse Cracking

- Transverse cracking (cracking in the direction perpendicular to the roadway) is measured by length (ft).
- The index for transverse cracking takes the total number of cracks (1 crack would encompass the full lane) broken down by severity. The total numbers of each severity are then put into a formula that yields a value between 0 and 100 (0 being the most distressed).
- Two severity levels are defined for manually measured Transverse Cracks. Lower severity cracks are those with a mean width of less than or equal to 0.25 inches. Sealed cracks with sealant in

good condition are also considered lower severity. Higher severity cracks are those with a mean width of greater than 0.25 inches.

Patching and Potholes

- Patching and Potholes are measured by area (square feet). Instances of Patching are measured along the length and multiplied by the average width of the patch.
- Instances of full lane width patching cannot be longer than 0.100 miles, otherwise is should be considered a pavement change rather than a distress.
- There are no stratified severities for Patching. It is either present or it is not.

Rutting

- Visible rutting is measured by length (ft.) in each wheel path. Only visible ruts are rated, which are ruts greater than 1 inch deep.
- All rutting recorded in a manual rating is considered to be high severity (> 1 inch). Lesser severities are generally not distinguishable in a visual inspection.

Roughness

• Manual assessments of roughness are not made due to the subjectivity of the measurement. Therefore, roughness is not incorporated into the PCR calculation of manually rated roads.

Index Formulas for Distress Measurement Method:

The method used to convert distress measurements into index values is shown below. The Surface Condition Rating and Pavement Condition Rating are calculated based on these index values.

Alligator Crack Index for Manual Rating:

AC INDEX =
$$100 - 40 * (\% ALLIGATOR / 15)$$

Where:

% ALLIGATOR = Percent of total area of section being rated that contains Alligator cracking.

Longitudinal Crack Index for Manual Rating:

$$LC_{INDEX} = 100 - 40 * [(\%LOW / 175) + (\%MED / 75)]$$

Where:

%LOW = Percent length of longitudinal cracks where crack width less than or equal to 0.25 inches

%HIGH = Percent length of longitudinal cracks where crack width greater than 0.25 inches

Transverse Crack Index for Manual Rating:

$$TC_{INDEX} = (100 - 40) * [(LOW / 21.1) + (MED / 4.4)]$$

Where:

LOW = Count of the total number of transverse cracks within the section length where one transverse crack is equal to the lane width and the crack width ≤ 0.25 inches HIGH = Count of the total number of transverse cracks within the section length where one transverse crack is equal to the lane width and the crack width ≥ 0.25 inches

Number of cracks is computed as:

Total length of transverse cracks/Lane width

Patching Index for Manual Rating:

Where:

%PATCHING = Percentage of pavement section that contains patching/potholes.

Rutting Index for Manual Rating:

$$RUT_INDEX = 100 - 40 * (\% RUTTING / 40)$$

Where:

%RUTTING = Percentage length of high severity rutting within the section being measured.

Method for Manually Rating Paved Parking Areas and Non-Linear Roads

Parking areas are evaluated based on a visual inspection using condition rating criteria that has been developed by FHWA. This criteria is based on a visual evaluation of the severity and extent of distresses to determine the overall condition of the parking area. This overall condition rating is linked to the level of repair and rehabilitation practices required.

A distress index is determined for each of the distresses listed below for Asphalt and Concrete Parking areas. The overall Pavement Condition Rating (PCR) of the parking lot is driven by the most severe distress present.

Rating Criteria:

Asphalt Parking Distress Types

- Alligator Cracking
 - o Rating based on percentage of road surface affected
- Longitudinal, Transverse and Block cracking
 - o Rating based on crack width, crack spacing, and percentage of surface affected
- Rutting and Distortions
 - o Rating based on percentage of road surface affected
- Hot Mix Asphalt Patches
 - o Rating based on overall percentage of HMA patches
- Potholes and Cold Patches
 - o Rating based on percentage of road surface affected
- Surface Raveling and Bleeding
 - o Rating based on percentage of road surface affected

Concrete Parking Distress Types

- Slab Faulting at Joints
 - o Rating based on height differential between adjacent slabs or pieces of broken slabs
- Slab Cracking and breakup
 - o Rating based on quantity of cracks and if slab is acting to able distribute load as designed
- Surface Delamination and Pop-outs
 - o Rating based on percentage of road surface affected to include pop-outs, spalls and surface delamination
- Joint Distresses
 - o Rating based on sealant condition and concrete distresses at/or adjacent to joints
- Patching
 - o Rating based on percentage of road surface affected

Curb Inspection and Treatments

During inspections of manually rated parking lots and routes, the curb reveal and overall curb condition are evaluated. The curb condition is used to determine a recommendation.

Curb Reveal

The vertical distance on the curb face from the gutter flow line or pavement surface to the top of curb. When resurfacing adjacent to curb, the resulting curb reveal should be no less than 4 inches. Additionally, when resurfacing adjacent to a gutter, the resulting pavement surface should be flush with the gutter pan. In cases where a resurfacing would violate either of these parameters, the surface may need to be milled or removed to adjust to these field conditions.

Curb Recommendations

The following treatment categories are based on the overall percentage of distresses along the entire curb structure for a specific pavement structure. Distresses include spalling, cracking, loss of material and any other damage which prevents the curb from conveying storm runoff or failing to perform in its intended function.

- Overall curb damage ranging 0%-5%:
 - o DO NOTHING
- Overall curb damage ranging 5%-20%
 - o LIGHT REPAIR
- Overall curb damage ranging 20%-50%
 - o MODERATE REPAIR
- Overall curb damage greater than 50%:
 - o REPLACE

GPS for Manually Rated Roads and Parking

GPS information for Manually Collected Cycle 6 Routes will be recorded using the latest hardware and software by TRIMBLE 6000 Series GeoXT. Cycle 6 GPS collection units will allow access to GPS and GLONASS, improving overall GPS reliability, accuracy and precision to submeter accuracy. Additionally, the new GPS units have an enhanced ability to collect accurate signals underneath tree cover or adjacent to buildings or natural terrain with extreme vertical gradations that typically reduce GPS accuracy. Trees and buildings create "satellite shadows", limiting the areas where you can reliably collect high-accuracy GPS data. The updated GPS receiver will deliver improved usable data under tree canopy or in natural or urban canyons. Routes that were previously collected accurately will not be recollected in Cycle 6.

TRIMBLE 6000 SERIES GeoXT GPS SPECIFICATIONS			
Receiver	Trimble Maxwell™ 6 GNSS chipset		
Channels	220 channels		
Systems	GPS / GLONASS / WAAS		
Accuracy	Sub-meter		
Operation Temperature	-20 °C to +60 °C (-4 °F to +140 °F)		
Cellular and Wireless	UMTS / HSDPA / GPRS / EDGE / Wi-Fi / Bluetooth		
Internal Still Camera w/ GEOTAG ability	Autofocus 5 MP (JPG) and WMV w/ Audio		

Appendix C Description of Cycle 6 Deliverables

Final Report Delivery

The Final Report will contain all data collected by Manual Inspection and the Data Collection Vehicle. All information provided in the Interim Report will be included in the Final report. Manually collected information reported in the Interim Report may be updated in the Final Report if pavement conditions have substantially changed between the Manual Inspection and Data Collection Vehicle Inspection or other unforeseen circumstances.

The final report will be released approximately 8 months after the Data Collection Vehicle completes its collection of that specific park.

Data included in the Final Report package consists of the following:

- Condition Photos: All photos taken during Cycle 6.
- **Data Video:** Data and video of each route collected by the DCV will viewable through PATHVIEW software. PATHVIEW Software and training will be provided to NPS personnel by Eastern Federal Lands.
- **GPS on All Rated Routes:** All GPS data collected from the DCV will be provided. Parking areas, some roads, and other paved areas that are not fully drivable with the DCV are collected manually by field technicians. GPS is collected for these routes using portable Trimble GPS units.
 - o GPS will be provided as Shapefiles and KMLs
 - o All GPS data related to road collection with be linear referenced to the collected length
- Geodatabase Background and Metadata: In addition to this park report, a geodatabase containing both tabular and spatial data specific to this park has been provided.
 - o All data disseminated in the preceding report has been obtained from the tables and fields within said geodatabase. The geodatabase can be referenced for tabular data via Microsoft Access or for both tabular and spatial data via ESRI's ArcGIS Suite of software which consists of; ArcMap, ArcCatalog and ArcExplorer.
 - o Consolidating the RIP data into one database creates a seamless relationship of tables and geographic data. It allows RIP to facilitate easier updates and enhancements in the future. A geodatabase can be thought of as simply a database containing spatial data. A complete and thorough description of the tables and fields contained within this geodatabase can be found in the metadata. The metadata is attached directly within the geodatabase and can be accessed via ESRI's ArcCatalog.
- **Report (RIP Report and Route ID):** A PDF report will be provided that includes a list of all routes and key data. Condition reports for each route will be included. All changes, additions and deletions to any route will be included in the report. Features along routes will not be collected in Cycle 6.

Partial DCV Collections

Additional Partial DCV Collections may be done on specific parks depending on their size and overall mileage of routes within its boundaries during Cycle 6. Parks with greater than 10 miles of paved roadways will receive at least one additional Partial DCV collection during Cycle 6. Data collected during these Partial DCV Collections will not result in the delivery of an additional report to the park.

Data collected by the DCV during Partial DCV Collection will be used to improve HPMA modeling by providing additional "snapshots in time" of park pavement conditions. This improved HMPA modeling will assist in the programing and budgeting of future projects which will help maximize the life of pavement infrastructures.

Instead of receiving a report of conditions collected during the Partial DCV collection, the park will receive a formal letter from the Road Inventory Program requesting coordination for the additional Partial DCV collection, identifying the dates of the Partial DCV Collection and will reinforce the purpose and importance of the Partial DCV Collection.

Appendix D Glossary of Terms and Abbreviations

Glossary of Terms and Abbreviations

TERM OR ABBREVIATION	DESCRIPTION OR DEFINITION
AC	Alligator Cracking
CRS	Condition Rating Sheets (Section 5)
Curb Recommendation	Curb remediation based on overall percentage of curb distress
Curb Reveal	Height of curb exposed from gutter flow line to top of curb
DCV	Data Collection Vehicle
Excellent	Excellent rating with an index value of 95 to 100
Fair	Fair rating with an index value from 61 to 84
FUNCT_CLASS	Functional Classification (see Route ID, Section 2)
Good	Good rating with an index value from 85 to 94
IRI	International Roughness Index
HPMA	Highway Pavement Management Application
Lane Width	Width from road centerline to fogline, or from centerline to edge- of-pavement when no fogline exists
LC	Longitudinal Cracking
MRR	Manually Rated Route
MRL	Manually Rated Line
MRP	Manually Rated Polygon
N/A	Not Applicable
NC	Not Collected
PATCH	Patching and Potholes
Paved Width	Width from edge-of-pavement to edge-of-pavement
PCR	Pavement Condition Rating
PKG	Parking Area
Poor	Poor rating with an index value of 0 to 60
RCI	Roughness Condition Index
SC	Structural Cracking
SCR	Surface Condition Rating
TC	Transverse Cracking