

Final Report

Road Inventory and Condition Assessment of Paved Routes Gateway National Recreation Area





Federal Lands Highway Road Inventory Program Prepared By: Federal Highway Administration Eastern Federal Lands Highway Division Road Inventory Program (RIP)

Report Date: September 2022

Gateway National Recreation Area in New Jersey and New York



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community Esri, Garmin, GEBCO, NOAA NGDC, and other contributors

N

Table of Contents

SECT	ION	PAGE NO.
1.	INTRODUCTION	1 - 1
2.	PARK ROUTE INVENTORY Route ID Report, Subcomponent Report, and Changes Report (As Applicable)	2 - 1
3.	PARK SUMMARY INFORMATION	
	Parkwide Paved Route Condition Summary	3 - 1
	Explanation of Condition Descriptions	3 - 2
	Route-Level Condition Summary Reports for Data Collection Vehicle, Manually Rated, and Parking Area Routes (As Applicable)	3 - 3
4.	PARK ROUTE LOCATION MAPS	
	Route Location Key Map	4 - 1
	Route Location Area Map(s)	4 - 2
	Route Condition Key Map – PCR Mile by Mile	4 - 18
	Route Condition Area Map(s) – PCR Mile by Mile	4 - 19
5.	PAVED ROAD CONDITION RATING SHEETS	
	Paved Road Pages	5 - 1
6.	PAVED PARKING AREA CONDITION RATING SHEETS	
	Paved Parking Area Pages	6 - 1
7.	ROAD MILEPOST INFORMATION	
	Road Milepost Information and Logs	7 - 1
8.	APPENDIX	
	Improvements to the RIP Index Equations and Determination of PCR	8 - 1
	Description of the Rating System	8 - 2
	Explanation of the Condition Descriptions	8 - 3
	Description of Pavement Treatment Types	8 - 4
	Appendix A: Methodology for Determining Condition Ratings with the Data Collection Vehicle (DCV)	8 - 5
	8 - 20	
	Appendix C: Description of Cycle 6 Deliverables	8 - 29
	Appendix D: Glossary of Terms and Abbreviations	8 - 32

Section 1 Introduction





Introduction

The Federal Highway Administration's (FHWA), Road Inventory Program (RIP) inventories all roads and parking areas in the National Park System, and performs condition inspections on all paved roads and parking areas for the National Park Service (NPS). This report contains the results of the Cycle 6 condition assessment of paved roads and parking lots for this park unit. This assessment was done using an automated, state-of-the-art pavement inspection vehicle as well as manual ratings. This information represents the condition of the paved assets at the time of the inspection. The pavement management system utilized by FHWA and the NPS uses these assessments to estimate future conditions and help prioritize pavement maintenance and rehabilitation projects. Further information about RIP data and its role in managing paved roads and bridges can be obtained by contacting the NPS Regional Transportation Program Manager.

A History of the Road Inventory Program:

The FHWA, in the mid-1970s, was charged with the task of identifying surface condition deficiencies and corrective priorities on NPS roads and parkways. Additionally, FHWA was tasked with establishing an integrated maintenance features inventory, locating features such as culverts, guardrails, and signs, among others, along NPS roads and parkways. As a result, in 1976 the NPS and FHWA entered into a Memorandum of Agreement (MOA) which established the RIP. This MOA was revised in 1980 to update RIP data collection standards and develop a long-range program to improve and maintain NPS roads to designated condition standards and establish a pavement management program.

The FHWA completed the initial phase of inventory in the early 1980s. As a result of this effort, each NPS unit included in the collection received a RIP Report known as the "Brown Book" which contained information that was inventoried during this first RIP phase. In the 1990s, a cyclical program was developed, and since then five cycles of collection have been completed. Cycle 6 is currently in progress. A summary of the RIP collection cycles is shown in the table below.

Cycle	Years	Parks Collected
Cycle 1	1994 - 1997	° 44 Large Parks
Cycle 2	1997 - 2001	 79 Large Parks 5 Small Parks
Cycle 3	2001 - 2004	 All Large Parks All Small Parks
Cycle 4	2006 - 2010	 86 Large Parks Several Small Parks
Cycle 5	2010 - 2014	 All Large Parks (Only functional class 1, 2, 7, and new/modified routes collected) All Small Parks (all roads and parking areas collected)
Cycle 6	2014 – 2020 (±)	 All roads and parking areas collected at all Parks Additional partial collections of functional class 1, 2, and 7 roads at Large Parks Cycle 6 is expected to last 6 years

Note: Large Parks have ≥ 10 Paved Miles; Small Parks have < 10 Paved Miles

Since 1984, the Road Inventory Program has been funded through the Federal Lands Highway Park Roads and Parkways (PRP) Program. Currently, coordination of the RIP with Federal Lands Highway (FLH) is under the NPS Washington Headquarters Park Facility Management Division. The FLH Washington office coordinates policy and prepares national reports and needs assessment studies for Congress.

In 1998, the Transportation Equity Act for the 21st Century (TEA-21) amended Title 23 U.S.C., and inserted Section 204(a)(6) requiring the FHWA and NPS, to develop by rule, a Pavement Management System (PMS) applied to park roads and parkways serving the National Park System.

In 2012, the Moving Ahead for Progress in the 21st Century Act (MAP-21) amended Title 23 U.S.C., and under Section 203(c)(1-2) stated that the National Park Service in cooperation with the DOT/FHWA, shall maintain a comprehensive national inventory of their transportation facilities, with the goal of quantifying transportation infrastructure needs within the National Park System.

A History of the Pavement Management System:

In 2005, the FHWA began implementing the use of a pavement management system to assist the NPS in prioritizing Pavement Maintenance and Rehabilitation activities. The system used by FHWA is the Highway Pavement Management Application (HPMA), which has the ability to store inventory and condition data from RIP and forecast future performance using prediction models. Outputs include performance and condition reports at the National, Regional, Park, or Route level. Regional prioritized lists and optimizations have been produced for most regions, and the Service's overall roadway Deferred Maintenance is calculated via the HPMA.

Overview of Cycle 6:

Cycle 6 launched in the spring of 2014 and will again comprise all NPS park units that are served by paved roads and/or parking areas. For Cycle 6, all paved roads (approximately 5,700 miles) and parking areas will be collected in all parks at least once, while the primary routes (functional class 1, 2, and 7 roads) at Large Parks will have additional collections. These multiple collections will provide updated condition data on a majority of the NPS's primary road network and help build a better pavement management system, allowing for more accurate pavement performance prediction models.

FLH is responsible for the accuracy of all data presented in this report. Any questions or comments concerning the contents of this report should be directed to the national RIP Coordinator located in Ashburn, Virginia.

Respectfully,

FHWA RIP Team

FHWA/Eastern Federal Lands 22001 Loudoun County Parkway Building E-2, Suite 200 Ashburn, VA 20147 (571) 434-1574 FHWA/Central Federal Lands 12300 West Dakota Ave Lakewood, CO 80228 (720) 963-3556

Section 2 Park Route Inventory





Cycle 6 NPS / RIP Route ID Report Page 1 of 27 Federal Lands Highway Report Date: 09/22/2022 (Numerical By Summary Route and Subcomponent #) **Road Inventory Program** Black = Non-NPS Routes = Concession Route Shading Color Key White = Paved Routes, DCV Driven Grey = Paved Routes, DCV not Driven Yellow = Unpaved Routes, DCV not Driven Blue = Paved Parking Areas Green = Unpaved Parking Areas DCV = Data Collection Vehicle MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas

NC = Not Collected

	ROAD INVENTORY (1100 SERIES FMSS LOCATIONS)															
Route	cle llected	lteration Collected	FMSS	ncessic	D . N	Route Dese	cription	Maintenance	FLTP		Unpaved		nctior ass	Area	Surf.	Area
No.	ပိပိ	≗°	Number	ů	Route Name	From	То	District	료	Miles	Miles	Mileage	39	(SQ FT)	Туре	Мар
0030	6	2	21206		BUFFALO ROAD	FROM HYLAN BOULEVARD	to end of pavement	STATEN ISLAND	YES	1.75	0.00	1.75	1		AS	1D
0060	6	2	29627		HARTSHORNE DRIVE (NORTHBOUND)	FROM STATE HIGHWAY 36	TO ROUTE 0665 (KEARNY DRIVE) AT MP 0.35 ON LEFT	SANDY HOOK	YES	5.28	0.00	5.28	1		AS	2A,2B,2C
0061	6	2	29628		HARTSHORNE DRIVE (SOUTHBOUND)	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))	TO STATE HIGHWAY 36	SANDY HOOK	YES	3.75	0.00	3.75	1		AS	2B,2C
0062	6	2	112822		PENNSYLVANIA AVENUE LANDFILL ACCESS ROADS	FROM BELT PARKWAY	TO END	JAMAICA BAY	YES	0.00	0.36	0.36	1		GR	3A
0063	6	2	112826		NS FOUNTAIN AVENUE LANDFILL ACCESS ROADS	FROM BELT PARKWAY	TO LANDFILL	JAMAICA BAY	YES	0.18	0.00	0.18	1		AS	3A
0110	6	2	36000		DAVIS ROAD	FROM ROUTE 0216 (HERO ROAD) AT MP 0.33 ON LEFT	TO ROUTE 0211 (SOUTH BARRETT ROAD) AT MP 0.14 ON RIGHT	JAMAICA BAY	YES	0.50	0.00	0.50	1		со	3E
0111	6	2	31597		SHORE ROAD	FROM END OF ROUTE 0216 (HERO ROAD) AND ROUTE 0979 (BAY 17/18 PARKING AREA)	TO END	JAMAICA BAY	YES	0.26	0.00	0.26	4		со	3E
0130	6	2	21211		MILLER FIELD ENTRANCE ROAD	FROM NEW DORP LANE AT PARK BOUNDARY	TO BEGINNING OF ROUTE 0132A (VISITOR CENTER (SANCHEZ ROAD EAST))	STATEN ISLAND	YES	0.38	0.00	0.38	2		AS	1C
0132A	6	2	21212		VISITOR CENTER (SANCHEZ ROAD EAST)	FROM END OF ROUTE 0130 (MILLER FIELD ENTRANCE ROAD)	TO ROUTE 0951 (CIRCLE PARKING)	STATEN ISLAND	YES	0.20	0.00	0.20	2		AS	1C
0132B	6	2	21213		HOUSING ACCESS (SANCHEZ ROAD WEST)	FROM ROUTE 0951 (CIRCLE PARKING)	TO ROUTE 0953C (NEW DORP HIGH SCHOOL PARKING C)	STATEN ISLAND	YES	0.27	0.00	0.27	2		AS	1C
0160	6	2	29629		ATLANTIC DRIVE	FROM INTERSECTION OF ROUTE 0672 (FORD ROAD) ROUTE 0667 (NORTH BRAGG DRIVE) AND 0668 (SOUTH BRAGG DRIVE)	TO ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 3.69 ON RIGHT	Sandy Hook	YES	1.91	0.00	1.91	2		AS	2A

Page 2 of 27 Report Date: 0		Cycle 6 NPS / RIP Rout (Numerical By Summary Route and Su	Federal Lands Highway Road Inventory Program	
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Non-NPS Routes	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line

MRP = Manually Rated Polygon PKG = Parking Areas

NC = Not Collected

	ROAD INVENTORY (1100 SERIES FMSS LOCATIONS)															
Route No.	Cycle Collected	lteration Collected	FMSS Number	Concessic	Route Name	Route Dese From	cription To	Maintenance District	FLTP	Paved Miles	Unpaved Miles	Total Mileage	Functior Class	Area (SQ FT)	Surf. Type	Area Map
0161	6	2			HARTSHORNE DRIVE (SOUTHBOUND) RAMP K	FROM ROUTE 0061 (HARTSHORNE DRIVE (SOUTHBOUND))	TO ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))	Sandy Hook	YES	0.29	0.00	0.29	2		AS	2C
0162	6	2			HARTSHORNE DRIVE (SOUTHBOUND) RAMP L	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))	TO ROUTE 0061 (HARTSHORNE DRIVE (SOUTHBOUND))	SANDY HOOK	YES	0.18	0.00	0.18	2		со	2C
0163ZZ	6	2	36014		RANGE ROADS	FROM ROUTE 0224 (BEACH 193RD STREET)	TO END	JAMAICA BAY	YES	0.97	0.00	0.97	3		AS	3D,3E
0200	6	2	31602		FLOYD BENNETT FIELD ENTRANCE ROAD	FROM FLATBUSH AVENUE	TO END	JAMAICA BAY	YES	1.30	0.00	1.30	1		AS	ЗВ
0201	6	2	31604		RANGER ROAD	FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD) AT MP 0.36 ON LEFT	TO ROUTE 0970 (FISHING ACCESS PARKING) AND END OF ROUTE 0465 (BUILDING 272 ACCESS ROAD)	JAMAICA BAY	YES	0.56	0.00	0.56	3		AS	ЗВ
0203	6	2	31603		ENTERPRISE AVENUE	FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD) AT MP 0.53 ON LEFT	TO ROUTE 0201 (RANGER ROAD) AT MP 0.29 ON RIGHT	JAMAICA BAY	YES	0.15	0.00	0.15	3		AS	3B
0205	6	2	36005		RIDING ACADEMY ACCESS ROAD	FROM BELT PARKWAY RAMP	TO END OF LOOP	JAMAICA BAY	YES	0.20	0.00	0.20	3		AS	3A
0206	6	2	36006		TAXIWAY C ACCESS ROAD	FROM ROUTE 0201 (RANGER ROAD)	TO ROUTE 0410 (TAXIWAY C)	JAMAICA BAY	YES	0.10	0.00	0.10	3		AS	ЗВ
0211	6	2	36007		SOUTH BARRETT ROAD	FROM BEGINNING OF ROUTE 0215 (ATHLETIC DRIVE) ON RIGHT	TO ROUTE 5411 (BEACH 169TH STREET)	JAMAICA BAY	YES	0.17	0.00	0.17	3		AS	ЗE
0212	6	2	36008		HEINZELMAN ROAD	FROM ROUTE 0214 (HAHN ROAD)	TO ROUTE 5000 (ROCKAWAY POINT BOULEVARD)	JAMAICA BAY	YES	0.12	0.00	0.12	1		AS	3E
0213	6	2	36009		WORCESTER ROAD	FROM ROUTE 0211 (SOUTH BARRETT ROAD)	TO ROUTE 0214 (HAHN ROAD)	JAMAICA BAY	YES	0.08	0.00	0.08	3		AS	3E
0214	6	2	31600		HAHN ROAD	FROM ROUTE 5411 (BEACH 169TH STREET)	TO ROUTE 0216 (HERO ROAD)	JAMAICA BAY	YES	0.29	0.00	0.29	1		AS	ЗE

Page 3 of 27 Report Date: 0		Cycle 6 NPS / RIP Rout (Numerical By Summary Route and Su	Federal Lands Highway Road Inventory Program	
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Non-NPS Routes	= Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line

MRP = Manually Rated Polygon

- PKG = Parking Areas
- NC = Not Collected

	ROAD INVENTORY (1100 SERIES FMSS LOCATIONS)															
Route	cle Ilected	lteration Collected	FMSS	ncessic	Devile Marrie	Route Desc	•	Maintenance District	FLTP		Unpaved	Total Mileage	nctior ass	Area	Surf.	Area
No.	ပိပိ	≗ °	Number	ŝ	Route Name	From	То	District	<u> </u>	Miles	Miles	Mileage	30	(SQ FT)	Туре	Мар
0215	6	2	36011		ATHLETIC DRIVE	0211 (SOUTH BARRETT ROAD) ON LEFT	TO INTERSECTION OF ROUTE 0214 (HAHN ROAD) AND ROUTE 0228 (THEATER ROAD)	JAMAICA BAY	YES	0.10	0.00	0.10	3		AS	3E
0216	6	2	31596		HERO ROAD	POINT BOULEVARD) SIDE OF	TO BEGINNING OF ROUTE 0111 (SHORE ROAD) ON RIGHT AND ROUTE 0979 (BAY 17/18 PARKING AREA)	JAMAICA BAY	YES	0.36	0.00	0.36	3		AS	3E
0222	6	2	36015		BREEZY POINT SURF CLUB ENTRANCE ROAD		TO ROUTE 0996 (BREEZY POINT SURF CLUB PARKING)	JAMAICA BAY	YES	0.38	0.00	0.38	3		AS	3C
0224	6	2	36017		BEACH 193RD STREET	POINT BOULEVARD)	TO ROUTE 0234 (SILVER GULL BEACH CLUB ENTRANCE ROAD)	JAMAICA BAY	YES	0.20	0.00	0.20	3		AS	3D
0225	6	2	36019		POST OFFICE ROAD	BARRETT ROAD)	TO ROUTE 5000 (ROCKAWAY POINT BOULEVARD)	JAMAICA BAY	YES	0.04	0.00	0.04	3		со	3E
0226	6	2	36020		NORTH BARETTE	FROM ROUTE 0225 (POST OFFICE ROAD)	TO ROUTE 0212 (HEINZELMAN ROAD)	JAMAICA BAY	YES	0.07	0.00	0.07	3		со	ЗE
0227ZZ	6	2	36021		ROMERO ROAD EAST AND WEST		TO ROUTE 0226 (NORTH BARETTE)	JAMAICA BAY	YES	0.05	0.00	0.05	3		со	3E
0228	6	2	36022		THEATER ROAD	FROM ROUTE 0214 (HAHN ROAD) AND ROUTE 0215 (ATHLETIC DRIVE)	TO ROUTE 0216 (HERO ROAD)	JAMAICA BAY	YES	0.19	0.00	0.19	3		AS	3E
0229	6	2	36023		CHAPEL ROAD	FROM ROUTE 0214 (HAHN ROAD)	TO END OF PAVEMENT	JAMAICA BAY	YES	0.06	0.00	0.06	3		AS	3E
0230	6	2	31599		STEELE ROAD	FROM ROUTE 021 <i>5</i> (ATHLETIC DRIVE)	TO ROUTE 0213 (WORCESTER ROAD)	JAMAICA BAY	YES	0.05	0.00	0.05	3		AS	3E
0232ZZ	6	2	21207		BULKHEAD ROADS	FROM ROUTE 0030 (BUFFALO ROAD) AT MP 1.02 ON RIGHT	TO END	STATEN ISLAND	NO	0.00	0.89	0.89	3		GR	1D

Page 4 of 27 Report Date: 0		Cycle 6 NPS / RIP Route (Numerical By Summary Route and Su	Federal Lands Highway Road Inventory Program	
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven Black = Non-NPS Routes Blue = Paved Parking Areas Green = Unpaved Parking Areas		Concession Route
	Yellow = Unpaved Routes, DCV not Driven			
			_	DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon

GATE	Gateway	National	Recreation	Area
------	---------	----------	------------	------

	ROAD INVENTORY (1100 SERIES FMSS LOCATIONS)															
Route No.	Cycle Collected	lteration Collected	FMSS Number	Concessic	Route Name	Route Dese	cription To	Maintenance District	FLTP	Paved Miles	Unpaved Miles	Total Mileage	Functior Class	Area (SQ FT)	Surf. Type	Area Map
0234	6	2	112212		SILVER GULL BEACH CLUB ENTRANCE ROAD	FROM ROUTE 0224 (BEACH 193RD STREET)	TO ROUTE 0224 (BEACH 193RD STREET)	JAMAICA BAY	YES	0.19	0.00	0.19	3		AS	3D
0235	6	2	112714		ROCKAWAY POINT YACHT CLUB ROAD	FROM ROUTE 5000 (ROCKAWAY POINT BOULEVARD)	TO ROUTE 1 000 (ROCKAWAY POINT YACHT CLUB PARKING)	JAMAICA BAY	YES	0.26	0.00	0.26	3		AS	3D
0237	6	2	245345		BALLFIELDS ROAD	FROM ROUTE 0437 (ACCESS TO ATHLETIC FIELD ROAD)	TO HYLAND BOULEVARD	STATEN ISLAND	NO	0.00	0.33	0.33	3		GR	۱D
0402	6	2	36026		COMMUNITY GARDEN ACCESS ROAD	FROM ROUTE 0965A (COMMUNITY GARDENS PARKING)	TO ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))	JAMAICA BAY	YES	0.24	0.00	0.24	5		AS	3в
0403	6	2	36027		RUNWAY C	FROM EAST END OF RUNWAY	TO ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))	JAMAICA BAY	YES	1.10	0.00	1.10	5		AS	ЗВ
0405	6	2	36028		ΤΑΧΙΨΑΥ Β	FROM ROUTE 0406 (TAXIWAY A)	TO ROUTE 0403 (RUNWAY C)	JAMAICA BAY	YES	0.50	0.00	0.50	5		AS	ЗВ
0406	6	2	36029		ΤΑΧΙΨΑΥ Α	FROM ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))	TO END OF ROAD AT HANGAR B GATE	JAMAICA BAY	YES	0.69	0.00	0.69	5		со	ЗВ
0408	6	2	36030		RUNWAY A (SOUTHERN RUNWAY)	FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)	TO DEAD END AND ROUTE 0403 (RUNWAY C) ON RIGHT	JAMAICA BAY	YES	1.09	0.00	1.09	5		AS	3B
0410	6	2	36031		ΤΑΧΙΨΑΥ C	FROM ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))	TO RUNWAY	JAMAICA BAY	YES	0.35	0.00	0.35	5		AS	ЗВ
0415	6	2	36034		NIKE MAINTENANCE ROAD	FROM ROUTE 0163ZZ (RANGE ROADS)	TO END	JAMAICA BAY	YES	0.18	0.00	0.18	5		AS	ЗE
0419	6	2	36035		JAMAICA BAY RESIDENCE ROAD	FROM ROUTE 5005S (CROSS BAY BOULEVARD (SOUTHBOUND))	to Route 1001 (Wildlife Refuge Building 101 Parking)	JAMAICA BAY	YES	0.02	0.00	0.02	5		AS	3A
0437	6	2	21210		ACCESS TO ATHLETIC FIELD ROAD	FROM INTERSECTION OF ROUTE 0030 (BUFFALO ROAD) AT MP 0.53 ON RIGHT AND ROUTE 0473 (HARBOR ROAD)	TO ROUTE 0232ZZ (BULKHEAD ROADS)	STATEN ISLAND	YES	0.89	0.00	0.89	5		AS	1D

Page 5 of 27 Report Date: 09		Cycle 6 NPS / RIP Route (Numerical By Summary Route and Sub	Federal Lands Highway Road Inventory Program	
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven Black = Non-NPS Routes Blue = Paved Parking Areas Green = Unpaved Parking Areas		= Concession Route
	Yellow = Unpaved Routes, DCV not Driven			
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon

MRP = Manually Rate PKG = Parking Areas

NC = Not Collected

	ROAD INVENTORY (1100 SERIES FMSS LOCATIONS)															
Route No.	Cycle Collected	lteration Collected	FMSS Number	Concessio	Route Name	Route Dese From	cription To	Maintenance District	FLTP	Paved Miles	Unpaved Miles	Total Mileage	Function Class	Area (SQ FT)	Surf. Type	Area Map
0438	6	2	21203		AYERS ROAD		TO END OF PAVEMENT (NAVY LODGE)	STATEN ISLAND	YES	0.31	0.00	0.31	5		AS	1 B
0439	6	2	21204		PATH ROAD (NAVY LODGE)	FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	TO ROUTE 0960A (NAVY LODGE AREA PARKING)	STATEN ISLAND	YES	0.09	0.00	0.09	5		AS	1B
0440ZZ	6	2	21182		NY AVENUE / BATTERY ROAD	FROM END OF ROUTE 0442 (NORTH ROAD) ON LEFT AT PARK BOUNDARY	TO BEGINNING OF ROUTE 5004 (MCCLEAN AVENUE)	STATEN ISLAND	YES	0.65	0.00	0.65	1		AS	1B
0441	6	2	21181		MONT SEC AVENUE	FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	TO INTERSECTION OF ROUTE 0445 (HUDSON ROAD / STATEN ISLAND) ROUTE 0446 (BATTERY WEED ROAD) AND 0959B (FORT WADSWORTH BUILDING 109 PARKING)		YES	0.14	0.00	0.14	2		AS	1A
0442	6	2	21184		NORTH ROAD	WADSWORTH BUILDING 109	TO BEGINNING OF ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD) ON LEFT	STATEN ISLAND	YES	0.14	0.00	0.14	5		AS	1A
0443	6	2	21185		SOUTH ROAD	FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	TO ROUTE 0441 (MONT SEC AVENUE)	STATEN ISLAND	YES	0.14	0.00	0.14	5		AS	1A
0444	6	2	21186		CLIFTON ROAD	FROM ROUTE 0443 (SOUTH ROAD)	TO END OF PAVEMENT (TENNIS COURT PARKING)	STATEN ISLAND	YES	0.07	0.00	0.07	5		AS	1A
0445	6	2	21180		HUDSON ROAD / STATEN ISLAND	FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	TO INTERSECTION OF ROUTE 0441 (MONT SEC AVENUE) ROUTE 0446 (BATTERY WEED ROAD) AND ROUTE 0959B (FORT WADSWORTH BUILDING 109 PARKING)		YES	0.53	0.00	0.53	2		AS	1A,1B

Page 6 of 27 Report Date: 0	9/22/2022	Cycle 6 NPS / RIP Rou (Numerical By Summary Route and S	•	Federal Lands Highway Road Inventory Program
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Non-NPS Routes	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon

	ROAD INVENTORY (1100 SERIES FMSS LOCATIONS)															
Route	:le lected	lteration Collected	FMSS	Icessia		Route Des	cription	Maintenance	۹		Unpaved		nction	Area	Surf.	Area
No.	δð	Sol Iter	Number	ŝ	Route Name	From	To	District	FLTP	Miles	Miles	Mileage	Ξů	(SQ FT)	Туре	Мар
0446	6	2	21178		BATTERY WEED ROAD	FROM ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)	TO INTERSECTION OF ROUTE 0441 (MONT SEC AVENUE) ROUTE 0445 (HUDSON ROAD / STATEN ISLAND) AND ROUTE 0959B (FORT WADSWORTH BUILDING 109 PARKING)	STATEN ISLAND	YES	0.44	0.00	0.44	2		AS	1A,1B
0447	6	2	21192		TOMPKINS ROAD	FROM INTERSECTION OF ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD) AND ROUTE 0448 (MARSHALL ROAD)	TO BARRIER OFF OF ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)	STATEN ISLAND	YES	0.15	0.00	0.15	5		AS	1A
0448	6	2	21191		MARSHALL ROAD	FROM INTERSECTION OF ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD) AND ROUTE 0447 (TOMPKINS ROAD)	TO ROUTE 0449 (COAST GUARD DRIVE) AT JERSEY BARRIER	STATEN ISLAND	YES	0.24	0.00	0.24	5		AS	1A
0449	6	2	21187		COAST GUARD DRIVE	FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	TO ROUTE 0448 (MARSHALL ROAD) AT JERSEY BARRIER	STATEN ISLAND	YES	0.38	0.00	0.38	5		AS	1A
0450	6	2	21189		DRUM AVENUE	FROM ROUTE 0449 (COAST GUARD DRIVE)	TO ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	STATEN ISLAND	YES	0.21	0.00	0.21	5		AS	1A
0451	6	2	21188		MOLONY DRIVE	FROM ROUTE 0449 (COAST GUARD DRIVE)	TO ROUTE 0450 (DRUM AVENUE)	STATEN ISLAND	YES	0.07	0.00	0.07	5		AS	1A
0452	6	2	21193		USS NEW MEXICO COURT	FROM ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)	TO END OF LOOP	STATEN ISLAND	YES	0.09	0.00	0.09	5		AS	1 B
0453	6	2	21197		USS NORTH CAROLINA ROAD	FROM ROUTE 0438 (AYERS ROAD)	to route 0445 (hudson Road / Staten Island)	STATEN ISLAND	YES	0.74	0.00	0.74	3		AS	1 B
0454	6	2	21202		USS CONNECTICUT COURT	FROM ROUTE 0453 (USS NORTH CAROLINA ROAD)	TO ROUTE 0453 (USS NORTH CAROLINA ROAD)	STATEN ISLAND	YES	0.14	0.00	0.14	5		AS	1 B
0455	6	2	21201		USS ARIZONA LANE	FROM ROUTE 0456 (USS IOWA CIRCLE)	TO ROUTE 0454 (USS CONNECTICUT COURT)	STATEN ISLAND	YES	0.03	0.00	0.03	5		AS	1 B
0456	6	2	21200		USS IOWA CIRCLE	FROM END OF ROUTE 0457 (USS MISSOURI LANE)	TO END OF LOOP	STATEN ISLAND	YES	0.24	0.00	0.24	5		AS	1 B

Cycle 6 NPS / RIP Route ID Report Page 7 of 27 Federal Lands Highway Report Date: 09/22/2022 (Numerical By Summary Route and Subcomponent #) **Road Inventory Program** Black = Non-NPS Routes = Concession Route Shading Color Key White = Paved Routes, DCV Driven Grey = Paved Routes, DCV not Driven Yellow = Unpaved Routes, DCV not Driven Blue = Paved Parking Areas Green = Unpaved Parking Areas DCV = Data Collection Vehicle MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

	ROAD INVENTORY (1100 SERIES FMSS LOCATIONS)															
Route No.	Cycle Collected	lteration Collected	FMSS Number	Concessio	Route Name	Route Desc	ription To	Maintenance District	FLTP	Paved Miles	Unpaved Miles	Total Mileage		Area (SQ FT)	Surf. Type	Area Map
0457	6	2	21199		USS MISSOURI LANE	FROM ROUTE 0458 (USS TENNESSEE ROAD)	TO ROUTE 0456 (USS IOWA CIRCLE) ON LEFT AND RIGHT	STATEN ISLAND	YES	0.04	0.00	0.04	5		AS	1 B
0458	6	2	21196		USS TENNESSEE ROAD	FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	TO ROUTE 0453 (USS NORTH CAROLINA ROAD)	STATEN ISLAND	YES	0.23	0.00	0.23	5		AS	1 B
0459	6	2	21198		USS FLORIDA COURT	FROM ROUTE 0458 (USS TENNESSEE ROAD)	TO END OF LOOP	STATEN ISLAND	YES	0.17	0.00	0.17	5		AS	1B
0460	6	2	29987		NORTH MAINTENANCE AREA ACCESS ROAD	FROM INTERSECTION OF ROUTE 0665 (KEARNY DRIVE) AND ROUTE 0660 (CANFIELD ROAD)	TO INTERSECTION OF ROUTE 0658 (KILPATRICK ROAD) AND ROUTE 0672 (FORD ROAD)	SANDY HOOK	YES	0.14	0.00	0.14	5		AS	2A
0461	6	2	29990		SAND SHED ROAD	FROM ROUTE 0476 (CAMPSITE ROAD)	TO END OF PAVEMENT	Sandy Hook	YES	0.08	0.00	0.08	5		со	2B
0462	6	2	29993		RANDOLPH ROAD	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 4.1	TO BIKE TRAIL	SANDY HOOK	YES	0.26	0.00	0.26	5		AS	2B
0464	6	2	31605		AVIATION ROAD	FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)	TO END OF LOOP	JAMAICA BAY	YES	0.39	0.00	0.39	5		AS	ЗВ
0465	6	2	36037		BUILDING 272 ACCESS ROAD	FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)	TO ROUTE 0201 (RANGER ROAD)	JAMAICA BAY	YES	0.18	0.00	0.18	5		AS	ЗВ
0470	6	2	36038		JACOB RIIS SERVICE ROAD	FROM BEACH CHANNEL DRIVE	TO JACOB RIIS PARK ROAD	JAMAICA BAY	YES	0.32	0.00	0.32	5		со	3F
0471	6	2	21195		LOOP ROAD	FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	TO ROUTE 0458 (USS TENNESSEE ROAD)	STATEN ISLAND	YES	0.14	0.00	0.14	5		AS	1 B
0472	6	2	21194		RANGE ROAD (STATEN ISLAND)	FROM ROUTE 0453 (USS NORTH CAROLINA ROAD)	TO END OF PAVEMENT	STATEN ISLAND	YES	0.08	0.00	0.08	5		AS	1 B
0473	6	2	33207		HARBOR ROAD	FROM INTERSECTION OF ROUTE 0030 (BUFFALO ROAD) AT MP 0.53 LEFT AND ROUTE 0437 (ACCESS TO ATHLETIC FIELD ROAD)	TO END OF PAVEMENT	STATEN ISLAND	NO	0.22	0.00	0.22	6		AS	1D

Page 8 of 27 Report Date: 0		Cycle 6 NPS / RIP Route (Numerical By Summary Route and Su	• • • • • • • • • • • • • • • • • • •	Federal Lands Highway Road Inventory Program
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Non-NPS Routes	= Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon

	ROAD INVENTORY (1100 SERIES FMSS LOCATIONS)															
Route No.	Cycle Collected	lteration Collected	FMSS Number	Concessio	Route Name	Route Dese	cription To	Maintenance District	FLTP	Paved Miles	Unpaved Miles	Total Mileage	Function Class	Area (SQ FT)	Surf. Type	Area Map
0474ZZ	6	2	33210		MILLER FIELD RESIDENCE ROAD	FROM ROUTE 0132B (HOUSING ACCESS (SANCHEZ ROAD WEST)) AT MP 0.09	to route 0132b (Housing Access (Sanchez Road West)) at mp 0.17 and Mason Avenue	STATEN ISLAND	YES	0.21	0.00	0.21	5		AS	1C
0475	6	2	36039		DAVIS ACCESS ROAD	FROM BEACH 169TH STREET	TO ROUTE 0110 (DAVIS ROAD)	JAMAICA BAY	YES	0.04	0.00	0.04	5		со	3E
0476	6	2	30000		CAMPSITE ROAD	FROM ROUTE 0914 (LOT "H" CAMPGROUND PARKING)	TO END OF LOOP	SANDY HOOK	YES	0.17	0.00	0.17	3		AS	2B
0477ZZ	6	2	30011		NIKE RADAR SITE ROADS	FROM ROUTE 0913 (LOT "L" NIKE RADAR SITE PARKING)	TO END OF PAVEMENT	SANDY HOOK	YES	0.43	0.00	0.43	5		AS	2B
0479	6	2	30018		FISHERMAN'S PARKING ACCESS	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 2.96	TO END	Sandy hook	YES	0.24	0.00	0.24	2		AS	2B
0480	6	2	33613		SERVICE ROAD / KINGMAN AND MILLS ROAD	FROM ROUTE 0061 (HARTSHORNE DRIVE (SOUTHBOUND))	TO END	SANDY HOOK	YES	0.18	0.00	0.18	5		AS	2B
0481	6	2	33625		South maintenance Shop road a	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 2.73	TO END	SANDY HOOK	YES	0.14	0.00	0.14	5		AS	2B
0482	6	2	33627		South maintenance Shop road b	FROM ROUTE 0481 (SOUTH MAINTENANCE SHOP ROAD A)	TO END	SANDY HOOK	YES	0.06	0.00	0.06	5		AS	2B
0483ZZ	6	2	33628		South maintenance Shop road c	FROM END OF ROUTE 0481 (SOUTH MAINTENANCE SHOP ROAD A)	TO ROUTE 0909B (MAINTENANCE PARKING EAST) AND ROUTE 0909C (MAINTENANCE PARKING WEST)	Sandy hook	YES	0.10	0.00	0.10	5		AS	2В
0484	6	2	33629		NORTH BEACH SERVICE ROAD	FROM ROUTE 0160 (ATLANTIC DRIVE)	TO ROUTE 0930 (NORTH BEACH PARKING)	SANDY HOOK	YES	0.29	0.00	0.29	5		AS	2A
0485	6	2	33630		GUNNISON ROAD MAST BUS ACCESS	FROM ROUTE 0671 (NEW GUNNISON ROAD)	TO ROUTE 0659 (OLD TRAILER CAMP LANE MAST)	SANDY HOOK	NO	0.00	0.05	0.05	2		GR	2A

Page 9 of 27 Report Date: 0		Cycle 6 NPS / RIP Rout (Numerical By Summary Route and St	•	Federal Lands Highway Road Inventory Program
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Non-NPS Routes	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas

NC = Not Collected

				Ę		ROAD INVENTORY (1100 SERIES FMSS	LOCATION	S)				a			
Route No.	Cycle Collected	lteration Collected	FMSS Number	Concessio	Route Name	Route Desc	cription To	Maintenance District	FLTP	Paved Miles	Unpaved Miles	Total Mileage		Area (SQ FT)	Surf. Type	Area Map
0492	6	2	21208		GREAT KILLS ACCESS TO BEACH (CROOKS POINT)	FROM END OF ROUTE 0030 (BUFFALO ROAD)	TO ROUTE 1007 (GREAT KILLS CROOKS POINT PARKING A)	STATEN ISLAND	NO	0.00	0.35	0.35	3		GR	1D
0493	6	2			CROOKS POINT FISHING ROAD	ACCESS TO BEACH (CROOKS	TO ROUTE 1005 (GREAT KILLS CROOKS POINT PARKING B)	STATEN ISLAND	NO	0.00	0.34	0.34	3		GR	1D
0494	NC		21216		MFR431 SERVICE ROAD	FROM BADEN PLACE	TO REAR OF BLDG 6	STATEN ISLAND	NO	0.00	0.63	0.63	6		GR	1C
0495	NC		31392		RD-RD-4 NORTH DIKE ROAD	FROM ROUTE 5005N (CROSS BAY BOULEVARD (NORTHBOUND))	TO MTA RAILROAD TRACKS	JAMAICA BAY	NO	0.00	0.33	0.33	6		GR	ЗА
0496ZZ	NC		77685		RD-WDSC- SPRING CREEK ROADS	FROM CROSS BAY BOULEVARD	TO 165TH AVENUE	JAMAICA BAY	NO	0.00	2.78	2.78	6		GR	3A
0497	6	2	115727		NYPD ROAD 1	FROM NYPD AREA 1	TO NYPD TRAINING AREA	JAMAICA BAY	NO	0.12	0.00	0.12	6		AS	3B
0498	6	2	115728		NYPD ROAD 2	FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)	TO ROUTE 0497 (NYPD ROAD 1)	JAMAICA BAY	NO	0.09	0.00	0.09	6		AS	ЗВ
0499	6	2	21179		WR175 DOCK ROAD	FROM ROUTE 0502 (DOCK ROAD)	TO END	STATEN ISLAND	NO	0.00	0.01	0.01	6		GR	1A
0500	6	2	245335		CENTRAL RUNWAY	FROM ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))	TO ROUTE 0403 (RUNWAY C)	JAMAICA BAY	YES	0.95	0.00	0.95	5		AS	ЗВ
0501	6	2	245337		FIRE ROAD	FROM ROUTE 0030 (BUFFALO ROAD)	TO ROUTE 0237 (BALLFIELDS ROAD)	STATEN ISLAND	NO	0.00	0.37	0.37	5		GR	۱D
0502	6	2	245349		DOCK ROAD	FROM ROUTE 0446 (BATTERY WEED ROAD) ON RIGHT	TO END	STATEN ISLAND	NO	0.03	0.00	0.03	2		AS	1A
0504ZZ	6	2			SOUTHERN RUNWAY	FROM ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))	to route 0200 (floyd Bennett field entrance Road)	JAMAICA BAY	YES	0.96	0.00	0.96	5		AS	3B
0505	6	2	33670		MAINTENANCE GAS STATION ROAD	FROM ROUTE 0481 (SOUTH MAINTENANCE SHOP ROAD A)	TO PARKING	SANDY HOOK	NO	0.06	0.00	0.06	6		AS	2В

Page 10 of 27 Report Date: 0		Cycle 6 NPS / RIP Route (Numerical By Summary Route and Sul	•	Federal Lands Highway Road Inventory Program
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Non-NPS Routes	= Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
			_	DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon

	ROAD INVENTORY (1100 SERIES FMSS LOCATIONS)															
Route	cle llected	lteration Collected	FMSS	ncessic		Route Des	cription	Maintenance	FLTP		Unpaved		nctior	Area	Surf.	Area
No.	ວ ວິ	S F	Number	Ŝ	Route Name	From	То	District	E	Miles	Miles	Mileage	ΞQ	(SQ FT)	Туре	Мар
0657	6	2	33631		HANAKI ROAD	FROM ROUTE 0665 (KEARNY DRIVE)	TO ROUTE 0669 (KNOX ROAD NORTH)	SANDY HOOK	YES	0.07	0.00	0.07	5		AS	2A
0658	6	2	33632		KILPATRICK ROAD	FROM ROUTE 0667 (NORTH BRAGG DRIVE - UNPAVED SEGMENT)	TO ROUTE 0668 (SOUTH BRAGG DRIVE)	Sandy Hook	YES	0.27	0.00	0.27	5		AS	2A
0659	6	2	33638		OLD TRAILER CAMP LANE MAST	FROM ROUTE 0662ZZ (MAGRUDER ROADS)	TO END	SANDY HOOK	YES	0.13	0.00	0.13	5		AS	2A
0660	6	2	33646		CANFIELD ROAD	FROM INTERSECTION OF ROUTE 0460 (NORTH MAINTENANCE AREA ACCESS ROAD) AND ROUTE 0665 (KEARNY DRIVE) ON RIGHT	TO ROUTE 0668 (SOUTH BRAGG DRIVE)	SANDY HOOK	YES	0.21	0.00	0.21	5		AS	2A
0661ZZ	6	2	33647		HUDSON ROADS	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))	TO ROUTE 0668 (SOUTH BRAGG DRIVE)	SANDY HOOK	YES	0.72	0.00	0.72	2		AS	2A
0662ZZ	6	2	33648		MAGRUDER ROADS	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))	TO ROUTE 0923 (BUILDING 53 AND BUILDING 60 PARKING) AND ROUTE 0661ZZ (HUDSON ROADS)	SANDY HOOK	YES	0.53	0.00	0.53	2		AS	2A
0663	6	2	33649		PENNINGTON STREET	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 4.65	TO ROUTE 0662ZZ (MAGRUDER ROADS)	Sandy hook	YES	0.14	0.00	0.14	2		AS	2A
0664	6	2	33650		KESSLER ROAD	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))	TO ROUTE 0665 (KEARNY DRIVE)	SANDY HOOK	YES	0.48	0.00	0.48	5		AS	2A
0665	6	2	33651		KEARNY DRIVE	FROM ROUTE 0661ZZ (HUDSON ROADS)	TO INTERSECTION OF ROUTE 0660 (CANFIELD ROAD) AND ROUTE 0460 (NORTH MAINTENANCE AREA ACCESS ROAD)	Sandy hook	YES	0.53	0.00	0.53	2		AS	2A
0666	6	2	33652		LAWSON LANE	FROM ROUTE 0665 (KEARNY DRIVE)	TO ROUTE 0664 (KESSLER ROAD)	Sandy Hook	YES	0.07	0.00	0.07	5		AS	2A
0667	6	2	33653		NORTH BRAGG DRIVE	FROM ROUTE 0672 (FORD ROAD)	TO ROUTE 1036 (PARKING LOT M)	SANDY HOOK	NO	0.00	0.23	0.23	5		GR	2A

Page 11 of 27 Report Date: 0		Cycle 6 NPS / RIP Rou (Numerical By Summary Route and S	•	Federal Lands Highway Road Inventory Program
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Non-NPS Routes	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas

NC = Not Collected

	ROAD INVENTORY (1100 SERIES FMSS LOCATIONS)															
Route No.	Cycle Collected	lteration Collected	FMSS Number	Concessic	Route Name	Route Dese From	cription To	Maintenance District	FLTP	Paved Miles	Unpaved Miles	Total Mileage	Functior Class	Area (SQ FT)	Surf. Type	Area Map
0668	6	2	33654		SOUTH BRAGG DRIVE		TO INTERSECTION OF ROUTE 0667 (NORTH BRAGG DRIVE) ROUTE 0160 (ATLANTIC DRIVE) AND ROUTE 0672 (FORD ROAD)	Sandy hook	YES	0.29	0.00	0.29	2		AS	2A
0669	6	2	33655		KNOX ROAD NORTH	FROM ROUTE 0660 (CANFIELD ROAD)	TO ROUTE 0668 (SOUTH BRAGG DRIVE)	SANDY HOOK	YES	0.12	0.00	0.12	2		AS	2A
0670	6	2	33656		OLD GUNNISON ROAD/MAST WAY	FROM ROUTE 0662ZZ (MAGRUDER ROADS)	TO END	SANDY HOOK	YES	0.15	0.00	0.15	5		AS	2A
0671	6	2	33657		NEW GUNNISON ROAD	FROM ROUTE 0160 (ATLANTIC DRIVE)	TO ROUTE 0662ZZ (MAGRUDER ROADS)	Sandy Hook	YES	0.28	0.00	0.28	2		AS	2A
0672	6	2	33658		FORD ROAD	0667 (NORTH BRAGG DRIVE)	TO INTERSECTION OF ROUTE 0658 (KILPATRICK ROAD) AND ROUTE 0460 (NORTH MAINTENANCE AREA ACCESS ROAD)	Sandy Hook	YES	0.11	0.00	0.11	2		AS	2A
0674	6	2	33659		MERCER ROAD	FROM ROUTE 0665 (KEARNY DRIVE)	TO ROUTE 0661ZZ (HUDSON ROADS)	SANDY HOOK	YES	0.11	0.00	0.11	5		AS	2A
0675ZZ	6	2	33660		MCNAIR ROADS	FROM ROUTE 0665 (KEARNY DRIVE)	TO ROUTE 0661ZZ (HUDSON ROADS)	Sandy Hook	YES	0.21	0.00	0.21	5		AS	2A

Cycle 6 NPS / RIP Route ID Report Page 12 of 27 Federal Lands Highway Report Date: 09/22/2022 (Numerical By Summary Route and Subcomponent #) **Road Inventory Program** Black = Non-NPS Routes White = Paved Routes, DCV Driven Grey = Paved Routes, DCV not Driven = Concession Route Shading Color Key Yellow = Unpaved Routes, DCV not Driven Blue = Paved Parking Areas Green = Unpaved Parking Areas DCV = Data Collection Vehicle MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

	NON-NPS ROADS INVENTORY													
Route No.	Cycle Collected	lteration Collected	FMSS Number		Route Des	cription To	Maintenance District	FLTP	Paved Miles	Unpaved Miles	Total Total	Area (SQ FT)	Surf. Type	Area Map
5000	6	2	245346	ROCKAWAY POINT BOULEVARD	FROM BEGINNING OF ROUTE 0222 (BREEZY POINT SURF CLUB ENTRANCE ROAD)	TO BEGINNING OF ROUTE 5001 (BEACH CHANNEL DRIVE)	JAMAICA BAY	NO	2.76	0.00	2.76		AS	3D,3E
5001	6	2	245347	BEACH CHANNEL DRIVE	FROM END OF ROUTE 5000 (ROCKAWAY POINT BOULEVARD)	TO BEGINNING OF ROUTE 5003 (ROCKAWAY BEACH BOULEVARD)	JAMAICA BAY	NO	0.95	0.00	0.95		AS	3E,3F
5002	6	2	245348	RIIS CIRCLE	FROM END OF ROUTE 5001 (BEACH CHANNEL DRIVE)	TO BEACH 149TH STREET	JAMAICA BAY	NO	0.26	0.00	0.26		AS	3F
5003	6	2	31595	ROCKAWAY BEACH BOULEVARD	FROM INTERSECTION OF ROUTE 5001 (BEACH CHANNEL DRIVE) AND ROUTE 5002 (RIIS CIRCLE)	TO END OF LOOP	JAMAICA BAY	NO	0.85	0.00	0.85		AS	3F
5004	6	2		MCCLEAN AVENUE	FROM END OF ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	TO LILY POND AVENUE	STATEN ISLAND	NO	0.14	0.00	0.14		AS	1B
5005N	6	2		CROSS BAY BOULEVARD (NORTHBOUND)	FROM INTERSECTION OF CROSS BAY BOULEVARD AND W 2ND ROAD	TO INTERSECTION OF CROSS BAY BOULEVARD AND 165TH AVENUE	JAMAICA BAY	NO	2.55	0.00	2.55		AS	3A
50055	6	2		CROSS BAY BOULEVARD (SOUTHBOUND)	FROM INTERSECTION OF CROSS BAY BOULEVARD AND 165TH AVENUE	TO INTERSECTION OF CROSS BAY BOULEVARD AND W 2ND ROAD	JAMAICA BAY	NO	2.56	0.00	2.56		AS	3A
5006N	6	2		FLATBUSH AVENUE (NORTHBOUND)	FROM MARINE PARKWAY BRIDGE	TO FLATBUSH AVENUE	JAMAICA BAY	NO	1.40	0.00	1.40		AS	ЗВ
5006S	6	2		FLATBUSH AVENUE (SOUTHBOUND)	FROM FLATBUSH AVENUE	TO MARINE PARKWAY BRIDGE	JAMAICA BAY	NO	1.39	0.00	1.39		AS	ЗВ
5204	6	2	36004	CANARSIE PIER	FROM BELT PARKWAY RAMP	TO END OF LOOP	JAMAICA BAY	NO	0.27	0.00	0.27		AS	3A
5411	6	2	31593	BEACH 169TH STREET	FROM ROUTE 5000 (ROCKAWAY POINT BOULEVARD)	TO BEACH 169TH STREET NON NPS AT PAVEMENT CHANGE	JAMAICA BAY	NO	0.18	0.00	0.18		AS	3E

Page 13 of 27 Report Date: 0		Cycle 6 NPS / RIP Rou (Numerical By Summary Route and S	Federal Lands Highway Road Inventory Program	
Shading Color Key White = Paved Routes, DCV Driven		Grey = Paved Routes, DCV not Driven	Black = Non-NPS Routes	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon

	PARKING AREA INVENTORY (1300 SERIES FMSS LOCATIONS)												
Route	Cycle Collected	ation lected	FMSS	cessio		Route De	scription	Maintenance	FLTP	Access	Area	Surf.	Area
No.	Š₿	Lter Coll	Number	Con	Route Name	From	То	District	E	Level	(SQ FT)	Туре	Мар
0900	6	2	33662		ENTRANCE STATION PARKING A	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))	TO PARKING	SANDY HOOK	YES	PUBLIC	11,444	AS	2C
0901	6	2	36103		GATEWAY SPORTS PARKING	FROM ROUTE 5006S (FLATBUSH AVENUE (SOUTHBOUND))	TO ROUTE 5006S (FLATBUSH AVENUE (SOUTHBOUND))	JAMAICA BAY	YES	PUBLIC	77,652	AS	ЗВ
0902	6	2	36105		GATEWAY MARINA PARKING	FROM ROUTE 5006S (FLATBUSH AVENUE (SOUTHBOUND))	TO PARKING	JAMAICA BAY	YES	PUBLIC	79,073	AS	ЗВ
0905	6	2	33663		SANDY HOOK VISITOR CENTER PARKING	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 2.20	TO PARKING	SANDY HOOK	YES	PUBLIC	22,979	AS	2C
0906ZZ	6	2	36107		JACOB RIIS PARKING	FROM ROCKAWAY BEACH BOULEVARD	TO ROUTE 5000 (ROCKAWAY POINT BOULEVARD)	JAMAICA BAY	YES	PUBLIC	2,641,982	со	3F
0907	6	2	33664		RANGER STATION PARKING A EAST	ADJACENT TO ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 2.47		SANDY HOOK	YES	PUBLIC	5,249	AS	2C
0908	6	2	33665		RANGER PARKING B NORTH	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))	TO ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) OPPOSITE DIRECTION	SANDY HOOK	YES	PUBLIC	5,841	AS	2C
0909B	6	2	33668		MAINTENANCE PARKING EAST	FROM END OF ROUTE 0483ZZ (SOUTH MAINTENANCE SHOP ROAD C)	TO PARKING	SANDY HOOK	NO	NONPUBLIC	8,823	со	2B
0909C	6	2	33669		MAINTENANCE PARKING WEST	ADJACENT TO ROUTE 0483ZZ (SOUTH MAINTENANCE SHOP ROAD C)		SANDY HOOK	NO	NONPUBLIC	2,923	со	2B
0910A	6	2	33671		MAINTENANCE SHOP EMPLOYEE PARKING	FROM ROUTE 0481 (SOUTH MAINTENANCE SHOP ROAD A)	TO PARKING	SANDY HOOK	NO	NONPUBLIC	15,098	AS	2B
0910B	6	2	33672		MAINTENANCE HEAVY VEHICLE PARKING	ADJACENT TO ROUTE 0481 (SOUTH MAINTENANCE SHOP ROAD A)		SANDY HOOK	NO	NONPUBLIC	9,018	AS	2B
0911	6	2	33673		MISSILE PARKING LOT	ADJACENT TO ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 2.7		SANDY HOOK	NO	PUBLIC	8,846	AS	2B
0913	6	2	33675		LOT "L" NIKE RADAR SITE PARKING	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 3.74	TO ROUTE 0477ZZ (NIKE RADAR SITE ROADS)	SANDY HOOK	YES	PUBLIC	18,316	AS	2B

Page 14 of 27 Report Date: 0		Cycle 6 NPS / RIP Rout (Numerical By Summary Route and Su	Federal Lands Highway Road Inventory Program	
Shading Color Key White = Paved Routes, DCV Driven		Grey = Paved Routes, DCV not Driven	Black = Non-NPS Routes	= Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon

	PARKING AREA INVENTORY (1300 SERIES FMSS LOCATIONS)												
Route	le ected	ation lected	FMSS	cessio		Route De	scription	Maintenance	FLTP	Access	Area	Surf.	Area
No.	င် ဗီ	Lter Coll	Number	Con	Route Name	From	То	District	E	Level	(SQ FT)	Туре	Мар
0914	6	2	33677		LOT "H" CAMPGROUND PARKING	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 4.0	TO ROUTE 0476 (CAMPSITE ROAD)	SANDY HOOK	YES	PUBLIC	11,386	AS	2B
0915	6	2	33678		WATER TREATMENT PLANT PARKING	FROM ROUTE 0462 (RANDOLPH ROAD)	TO PARKING	SANDY HOOK	NO	NONPUBLIC	8,385	AS	2В
0916	6	2	34239		GUARDIAN PARK PARKING	FROM ROUTE 0662ZZ (MAGRUDER ROADS)	TO PARKING	SANDY HOOK	YES	PUBLIC	18,668	AS	2A
091 <i>7</i>	6	2	34785		DAYCARE #335 AND #18 PARKING	FROM ROUTE 0663 (PENNINGTON STREET)	TO ROUTE 0664 (KESSLER ROAD)	SANDY HOOK	YES	PUBLIC	22,683	AS	2A
0918A	6	2	35211		NOAA LAB A PARKING SOUTH	FROM ROUTE 0662ZZ (MAGRUDER ROADS)	TO ROUTE 1037 (NOAA SERVICE PARKING LOT)	SANDY HOOK	YES	PUBLIC	16,929	AS	2A
0918B	6	2	35212		NOAA LAB B PARKING NORTH	FROM ROUTE 0662ZZ (MAGRUDER ROADS)	TO ROUTE 0671 (NEW GUNNISON ROAD)	SANDY HOOK	YES	PUBLIC	20,577	AS	2A
0919	6	2	34806		BUILDING 74 EAST PARKING	FROM ROUTE 0662ZZ (MAGRUDER ROADS)	TO PARKING	SANDY HOOK	YES	PUBLIC	3,037	AS	2A
0920	6	2	35189		MARINE ACADEMY CAFETERIA #77 PARKING	FROM ROUTE 0659 (OLD TRAILER CAMP LANE MAST)	TO PARKING	SANDY HOOK	NO	NONPUBLIC	10,410	AS	2A
0921	6	2	35190		MAST PARKING LOT "N"	FROM ROUTE 0662ZZ (MAGRUDER ROADS)	TO ROUTE 0670 (OLD GUNNISON ROAD/MAST WAY)	SANDY HOOK	NO	NONPUBLIC	39,728	AS	2A
0922	6	2	35191		MAST SCHOOL OFFICES TEACHERS PARKING	FROM ROUTE 0670 (OLD GUNNISON ROAD/MAST WAY)	TO PARKING	SANDY HOOK	NO	NONPUBLIC	6,787	AS	2A
0923	6	2	35192		BUILDING 53 AND BUILDING 60 PARKING	FROM ROUTE 0661ZZ (HUDSON ROADS)	TO INTERSECTION OF ROUTE 0674 (MERCER ROAD) AND ROUTE 0675ZZ (MCNAIR ROADS)	Sandy Hook	YES	PUBLIC	1 <i>5</i> ,608	AS	2A
0924	6	2	35193		BUILDING 40/ POST OFFICE/ GYM PARKING	ADJACENT TO ROUTE 0675ZZ (MCNAIR ROADS)		SANDY HOOK	YES	PUBLIC	1,835	AS	2A
0925	6	2	35194		LIGHTHOUSE PARKING	ADJACENT TO ROUTE 0674 (MERCER ROAD)		SANDY HOOK	YES	PUBLIC	13,504	AS	2A

Page 15 of 27 Report Date: 0		Cycle 6 NPS / RIP Rour (Numerical By Summary Route and S	Federal Lands Highway Road Inventory Program	
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Non-NPS Routes	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon

	PARKING AREA INVENTORY (1300 SERIES FMSS LOCATIONS)												
Route	e ected	lteration Collected	FMSS	cessio		Route De	scription	Maintenance	FLTP	Access	Area	Surf.	Area
No.	S C C	Coll Coll	Number	Con	Route Name	From	То	District	5	Level	(SQ FT)	Туре	Мар
0926	6	2	35195		LAWSON LANE PARKING	ADJACENT TO ROUTE 0666 (LAWSON LANE)		SANDY HOOK	YES	PUBLIC	4,730	AS	2A
0927	6	2	35196		BUILDING 32 PARK RANGER PARKING	FROM ROUTE 0665 (KEARNY DRIVE)	TO PARKING	SANDY HOOK	NO	NONPUBLIC	31,695	AS	2A
0928A	6	2	35213		NORTH MAINTENANCE EMPLOYEE PARKING A	FROM ROUTE 0460 (NORTH MAINTENANCE AREA ACCESS ROAD)	TO PARKING	SANDY HOOK	NO	NONPUBLIC	25,189	AS	2A
0928B	6	2	21822		NORTH MAINTENANCE EMPLOYEE PARKING B	ADJACENT TO ROUTE 0460 (NORTH MAINTENANCE AREA ACCESS ROAD) ON RIGHT		SANDY HOOK	NO	NONPUBLIC	2,030	AS	2A
0929	6	2	35197		GUNNISON BEACH PARKING	FROM ROUTE 0671 (NEW GUNNISON ROAD)	TO INTERSECTION OF ROUTE 0671 (NEW GUNNISON ROAD) AND ROUTE 0160 (ATLANTIC DRIVE)	SANDY HOOK	YES	PUBLIC	281,839	AS	2A
0930	6	2	35198		NORTH BEACH PARKING	FROM ROUTE 0160 (ATLANTIC DRIVE)	TO ROUTE 0160 (ATLANTIC DRIVE) AND ROUTE 0484 (NORTH BEACH SERVICE ROAD)	SANDY HOOK	YES	PUBLIC	139,821	AS	2A
0931	6	2	35200		EMPLOYEE PULLOUT GUNNISON PARKING	FROM ROUTE 0160 (ATLANTIC DRIVE)	TO PARKING	SANDY HOOK	NO	NONPUBLIC	5,684	AS	2A
0933	6	2	35202		FEE COLLECTORS PARKING	FROM ROUTE 0061 (HARTSHORNE DRIVE (SOUTHBOUND))	TO PARKING	SANDY HOOK	NO	NONPUBLIC	12,152	AS	2C
0934	6	2	35203		QUARTER 600 PARKING	FROM ROUTE 0061 (HARTSHORNE DRIVE (SOUTHBOUND))	TO ROUTE 0061 (HARTSHORNE DRIVE (SOUTHBOUND))	SANDY HOOK	NO	NONPUBLIC	9,784	AS	2C
0935	6	2	35204		SEWAGE PLANT PARKING	FROM ROUTE 0160 (ATLANTIC DRIVE) AT MP 0.79	TO ROUTE 0160 (ATLANTIC DRIVE)	SANDY HOOK	NO	NONPUBLIC	7,562	AS	2A
0936	6	2	35205		FORT HANCOCK THEATER PARKING	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 5.20	TO ROUTE 0665 (KEARNY DRIVE)	SANDY HOOK	YES	PUBLIC	9,055	AS	2A
0937	6	2	35206		BUILDING 58 PARKING	FROM ROUTE 0662ZZ (MAGRUDER ROADS)	TO PARKING	SANDY HOOK	YES	PUBLIC	3,600	AS	2A
0938	6	2	35207		AREA B PARKING LOT B	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 0.63	TO ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))	SANDY HOOK	YES	PUBLIC	100,876	AS	2C

Page 16 of 27 Report Date: 0		Cycle 6 NPS / RIP Route (Numerical By Summary Route and Sul	Federal Lands Highway Road Inventory Program	
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Non-NPS Routes	= Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon

_													
				_	PAR	KING AREA INVENTORY (1300 SERIES FMSS LOCATI	ONS)					
Route	cted	ion cted	FMSS	ession		Route De	scription	Maintenance	•	Access	Area	Surf.	Area
No.	Cycle Colle	lteration Collected	Number	Conc	Route Name	From	То	District	FLTP	Level	(SQ FT)	Туре	Мар
0939	6	2	35208		AREA C PARKING LOT C	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 1.42	TO PARKING	SANDY HOOK	YES	PUBLIC	99,865	AS	2C
0940ZZ	6	2	25235		GREAT KILLS ENTRANCE PARKING AREAS	ADJACENT TO ROUTE 0030 (BUFFALO ROAD) AT MP 0.05 LEFT AND RIGHT		STATEN ISLAND	YES	PUBLIC	17,240	AS	1D
0941	6	2	25236		USPP/RANGER PARKING	FROM ROUTE 0030 (BUFFALO ROAD) AT MP 0.88 RIGHT	TO ROUTE 0030 (BUFFALO ROAD)	STATEN ISLAND	YES	PUBLIC	22,469	AS	1D
0942	6	2	25237		GK AREA "A" PARKING	FROM ROUTE 0030 (BUFFALO ROAD) AT MP 0.93 LEFT	TO ROUTE 0030 (BUFFALO ROAD)	STATEN ISLAND	YES	PUBLIC	130,313	AS	1D
0943	6	2	25238		BOAT LAUNCH PARKING	FROM ROUTE 0030 (BUFFALO ROAD) AT MP 1.16	TO PARKING	STATEN ISLAND	YES	PUBLIC	77,744	AS	1D
0944	6	2	25239		GK AREA "E" PARKING	FROM ROUTE 0030 (BUFFALO ROAD) AT MP 1.32	TO PARKING	STATEN ISLAND	YES	PUBLIC	32,340	AS	1D
0945	6	2	25240		GK AREA "F" PARKING	FROM ROUTE 0030 (BUFFALO ROAD) AT MP 1.43	TO ROUTE 0030 (BUFFALO ROAD)	STATEN ISLAND	YES	PUBLIC	23,924	AS	1D
0946	6	2	25241		BEACH CENTER PARKING	FROM ROUTE 0030 (BUFFALO ROAD) AT MP 1.67	TO ROUTE 0030 (BUFFALO ROAD) AND ROUTE 0947 (BEACH PICKUP AREA)	STATEN ISLAND	YES	PUBLIC	47,532	AS	1D
0947	6	2	25242		BEACH PICKUP AREA	FROM ROUTE 0030 (BUFFALO ROAD) AT MP 1.57	TO ROUTE 0030 (BUFFALO ROAD) AND ROUTE 0946 (BEACH CENTER PARKING)	STATEN ISLAND	YES	PUBLIC	8,943	AS	1D
0948	6	2	25247		MILLER FIELD PARKING LOT (BALL FIELD)	FROM ROUTE 0130 (MILLER FIELD ENTRANCE ROAD) AT MP 0.09	TO ROUTE 0130 (MILLER FIELD ENTRANCE ROAD)	STATEN ISLAND	YES	PUBLIC	102,825	AS	1C
0949	6	2	25248		RANGER STATION PARKING	ADJACENT TO ROUTE 0132A (VISITOR CENTER (SANCHEZ ROAD EAST))		STATEN ISLAND	YES	PUBLIC	7,061	AS	1C
0951	6	2	25250		CIRCLE PARKING	FROM ROUTE 0132A (VISITOR CENTER (SANCHEZ ROAD EAST))	TO ROUTE 0132B (HOUSING ACCESS (SANCHEZ ROAD WEST))	STATEN ISLAND	YES	PUBLIC	87,373	AS	1C
0952	6	2	25251		RESIDENCE PARKING	FROM ROUTE 0132B (HOUSING ACCESS (SANCHEZ ROAD WEST))		STATEN ISLAND	YES	PUBLIC	6,156	AS	1C
0953A	6	2	25252		NEW DORP HIGH SCHOOL PARKING A	FROM END OF ROUTE 0132B (HOUSING ACCESS (SANCHEZ ROAD WEST))	TO ROUTE 0953C (NEW DORP HIGH SCHOOL PARKING C)	STATEN ISLAND	YES	PUBLIC	43,438	AS	1C

Page 17 of 27 Report Date: 0		Cycle 6 NPS / RIP Route (Numerical By Summary Route and Sul	Federal Lands Highway Road Inventory Program	
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Non-NPS Routes	= Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon

	PARKING AREA INVENTORY (1300 SERIES FMSS LOCATIONS)												
Route	Cycle Collected	ation lected	FMSS	Icessio		Route De	scription	Maintenance	FLTP	Access	Area	Surf.	Area
No.	δõ	Ler Col	Number	Ŝ	Route Name	From	То	District	5	Level	(SQ FT)	Туре	Мар
0953C	6	2	105114		NEW DORP HIGH SCHOOL PARKING C	FROM ROUTE 0953A (NEW DORP HIGH SCHOOL PARKING A)	TO NEW DORP LANE	STATEN ISLAND	YES	PUBLIC	53,104	AS	1C
0953D	6	2			NEW DORP HIGH SCHOOL PARKING D	FROM ROUTE 0953C (NEW DORP HIGH SCHOOL PARKING C)	TO ROUTE 0953C (NEW DORP HIGH SCHOOL PARKING C)	STATEN ISLAND	YES	PUBLIC	19,687	AS	1C
0954	6	2	25222		MAIN GATE PARKING	FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	TO PARKING	STATEN ISLAND	YES	PUBLIC	5,790	AS	1A
0955AZZ	6	2	33184		COAST GUARD AREA PARKING A	ADJACENT TO ROUTE 0449 (COAST GUARD DRIVE) ON RIGHT		STATEN ISLAND	YES	PUBLIC	24,970	AS	1A
0955B	6	2	33187		COAST GUARD AREA PARKING B	FROM ROUTE 0449 (COAST GUARD DRIVE) ON RIGHT	TO ROUTE 0449 (COAST GUARD DRIVE)	STATEN ISLAND	YES	PUBLIC	68,764	AS	1A
0955C	6	2	33188		USCG ACTIVITIES PARKING	FROM ROUTE 0449 (COAST GUARD DRIVE) ON RIGHT	TO ROUTE 0449 (COAST GUARD DRIVE)	STATEN ISLAND	YES	PUBLIC	6,350	AS	1A
0955D	6	2	33190		USCG GALLEY PARKING	ADJACENT TO ROUTE 0449 (COAST GUARD DRIVE) ON LEFT		STATEN ISLAND	YES	PUBLIC	2,994	AS	1A
0955E	6	2	33191		USCG GALLEY REAR PARKING AND FIRE LANE	FROM ROUTE 0449 (COAST GUARD DRIVE) ON LEFT	TO ROUTE 0450 (DRUM AVENUE)	STATEN ISLAND	YES	PUBLIC	12,433	AS	1A
0955F	6	2	33192		USCG PX PARKING	FROM ROUTE 0449 (COAST GUARD DRIVE)	TO MARSHALL ROAD AND ROUTE 0957A (THEATRE PARKING)	STATEN ISLAND	YES	PUBLIC	15,970	AS	1A
0956A	6	2	25223		DRUM AVENUE PARKING A	FROM ROUTE 0450 (DRUM AVENUE)	TO ROUTE 0450 (DRUM AVENUE)	STATEN ISLAND	NO	NONPUBLIC	1,455	AS	1A
0956B	6	2	33175		DRUM AVENUE CHAPEL PARKING	ADJACENT TO ROUTE 0450 (DRUM AVENUE)		STATEN ISLAND	YES	PUBLIC	2,861	AS	1A
0956C	6	2	331 <i>77</i>		DRUM AVENUE LOOP PARKING	FROM ROUTE 0450 (DRUM AVENUE)	TO ROUTE 0450 (DRUM AVENUE)	STATEN ISLAND	YES	PUBLIC	1,871	AS	1A
0956D	6	2	33180		DRUM AVENUE PARKING D	ADJACENT TO ROUTE 0450 (DRUM AVENUE)		STATEN ISLAND	YES	PUBLIC	2,520	AS	1A
0957A	6	2	33183		THEATRE PARKING	FROM ROUTE 0955F (USCG PX PARKING)	TO ROUTE 0451 (MOLONY DRIVE)	STATEN ISLAND	YES	PUBLIC	31,936	AS	1A

Page 18 of 27 Report Date: 0		Cycle 6 NPS / RIP Rout (Numerical By Summary Route and Su	Federal Lands Highway Road Inventory Program	
Shading Color Key White = Paved Routes, DCV Driven		Grey = Paved Routes, DCV not Driven	Black = Non-NPS Routes	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon

				_	PAR	KING AREA INVENTORY (1300 SERIES FMSS LOCA	TIONS)					
Route	rcle Ilected	lteration Collected	FMSS	ncession	N . N	Route De	•	Maintenance District	FLTP	Access Level	Area (SQ FT)	Surf. Type	Area Map
No.	ບີ ບໍ	≗ů	Number	ပိ	Route Name	From	То	Disirici	ш.	Levei	(30(11)	Type	Мар
0957B	6	2	25224		HAND BALL PARKING	FROM ROUTE 0448 (MARSHALL ROAD)	TO ROUTE 0450 (DRUM AVENUE)	STATEN ISLAND	YES	PUBLIC	12,070	AS	1A
0957C	6	2	25225		HQ B210 PARKING	FROM ROUTE 0448 (MARSHALL ROAD)	TO PARKING	STATEN ISLAND	YES	PUBLIC	91,846	AS	1A
0957D	6	2	25226		USPP PARKING B210	FROM ROUTE 0448 (MARSHALL ROAD)	TO PARKING	STATEN ISLAND	YES	PUBLIC	11,321	AS	1A
0958A	6	2	25227		FORT WADSWORTH VISITOR CENTER PARKING	FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	TO ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	STATEN ISLAND	YES	PUBLIC	95,655	AS	1A
0958B	6	2	25228		FT TOMPKINS PARKING	ADJACENT TO ROUTE 0447 (TOMPKINS ROAD) ON LEFT		STATEN ISLAND	YES	PUBLIC	2,505	AS	1A
0959A	6	2	25229		TENNIS COURT PARKING	FROM ROUTE 0444 (CLIFTON ROAD) ON LEFT	TO PARKING	STATEN ISLAND	YES	PUBLIC	2,845	AS	1A
0959B	6	2	25230		FORT WADSWORTH BUILDING 109 PARKING	FROM INTERSECTION OF ROUTE 0446 (BATTERY WEED ROAD) ROUTE 0445 (HUDSON ROAD / STATEN ISLAND) AND 0441 (MONT SEC AVENUE)	TO ROUTE 0442 (NORTH ROAD)	STATEN ISLAND	YES	PUBLIC	8,204	AS	1A
0960A	6	2	33194		NAVY LODGE AREA PARKING	FROM END OF ROUTE 0439 (PATH ROAD (NAVY LODGE))	TO PARKING	STATEN ISLAND	YES	PUBLIC	35,493	AS	1 B
0960B	6	2	25231		MCCLEAN ROAD PARKING	FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	TO ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	STATEN ISLAND	YES	PUBLIC	12,988	AS	1 B
0960C	6	2	33195		AYERS ROAD PARKING	ADJACENT TO ROUTE 0438 (AYERS ROAD)		STATEN ISLAND	YES	PUBLIC	2,131	AS	1 B
0961A	6	2	33196		ARMED FORCES RESERVE AREA PARKING	FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	TO PARKING	STATEN ISLAND	YES	PUBLIC	105,675	AS	1 B
0961B	6	2	33199		ARMED FORCES AREA B PARKING	FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	TO ROUTE 0471 (LOOP ROAD)	STATEN ISLAND	YES	PUBLIC	22,475	AS	1 B
0961C	6	2	33201		ARMED FORCES AREA C PARKING	FROM ROUTE 0471 (LOOP ROAD)	TO ROUTE 1015 (BUILDING 301 MAINTENANCE PARKING)	STATEN ISLAND	YES	PUBLIC	9,359	AS	1B
0961D	6	2	33202		FWR USPP SWAT PARKING	FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)	TO ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)	STATEN ISLAND	YES	PUBLIC	7,404	AS	1B

Page 19 of 27 Report Date: 0		Cycle 6 NPS / RIP Rout (Numerical By Summary Route and Su	Federal Lands Highway Road Inventory Program	
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven Black = Non-NPS Routes		= Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon PKG = Parking Areas

NC = Not Collected

	PARKING AREA INVENTORY (1300 SERIES FMSS LOCATIONS)												
Route	ile lected	lteration Collected	FMSS	Icessio		Route De	scription	Maintenance	FLTP	Access	Area	Surf.	Area
No.	ς Ω	Lter Col	Number	ð	Route Name	From	То	District	5	Level	(SQ FT)	Туре	Мар
0962A	6	2	25232		FWR BALL FIELD PARKING	FROM ROUTE 0453 (USS NORTH CAROLINA ROAD)	TO ROUTE 0446 (BATTERY WEED ROAD)	STATEN ISLAND	YES	PUBLIC	33,895	AS	1 B
0962B	6	2	25233		FWR CAMPGROUND PARKING AREA	ADJACENT TO ROUTE 0453 (USS NORTH CAROLINA ROAD)		STATEN ISLAND	YES	PUBLIC	2,122	AS	1 B
0963A	6	2	25234		FWR BATTERY WEED AREA A PARKING	ADJACENT TO ROUTE 0446 (BATTERY WEED ROAD)		STATEN ISLAND	YES	PUBLIC	2,842	AS	1A
0963C	6	2	33205		FWR BATTERY WEED AREA C PARKING	ADJACENT TO ROUTE 0446 (BATTERY WEED ROAD) ON RIGHT		STATEN ISLAND	YES	PUBLIC	2,130	AS	1A
0963D	6	2	33682		FWR BATTERY WEED AREA D PARKING	ADJACENT TO ROUTE 0446 (BATTERY WEED ROAD) ON LEFT		STATEN ISLAND	YES	PUBLIC	2,061	AS	1A
0964B	6	2	36140		SEWAGE TREATMENT PARKING IN JAMAICA BAY	FROM ROUTE 0464 (AVIATION ROAD) ON RIGHT	TO PARKING	JAMAICA BAY	YES	PUBLIC	5,830	AS	ЗВ
0964ZZ	6	2	36138		ENTRANCE AREA PARKING	FROM ROUTE 0464 (AVIATION ROAD) LEFT AND RIGHT	TO ROUTE 0464 (AVIATION ROAD)	JAMAICA BAY	YES	PUBLIC	33,806	AS	ЗВ
0965A	6	2	36141		COMMUNITY GARDENS PARKING	FROM ROUTE 0965B (RYAN VISITOR CENTER PARKING SE)	TO ROUTE 0402 (COMMUNITY GARDEN ACCESS ROAD)	JAMAICA BAY	YES	PUBLIC	176,975	со	ЗВ
0965B	6	2	36142		RYAN VISITOR CENTER PARKING SE	FROM ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))	TO ROUTE 0965A (COMMUNITY GARDENS PARKING) AND ROUTE 0965D (RYAN VISITOR CENTER PARKING)	JAMAICA BAY	YES	PUBLIC	56,849	AS	ЗВ
0965C	6	2	36143		AVIATOR CONCESSION PARKING	FROM ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))	TO ROUTE 0965D (RYAN VISITOR CENTER PARKING) AND ROUTE 0965F (RYAN CENTER EMPLOYEE PARKING)	JAMAICA BAY	YES	PUBLIC	1 <i>47</i> ,081	AS	ЗВ
0965D	6	2	36144		RYAN VISITOR CENTER PARKING	FROM ROUTE 0965B (RYAN VISITOR CENTER PARKING SE) AND ROUTE 0965C (AVIATOR CONCESSION PARKING)	TO ROUTE 5006N (FLATBUSH AVENUE (NORTHBOUND))	JAMAICA BAY	YES	PUBLIC	131,195	AS	ЗВ
0965E	6	2	36147		HANGAR 3 AND 4 PARKING AREA	FROM ROUTE 0965A (COMMUNITY GARDENS PARKING)	TO PARKING	JAMAICA BAY	NO	NONPUBLIC	162,379	BR	ЗВ
0965F	6	2	36368		RYAN CENTER EMPLOYEE PARKING	FROM ROUTE 0965C (AVIATOR CONCESSION PARKING)	TO ROUTE 0965B (RYAN VISITOR CENTER PARKING SE)	JAMAICA BAY	YES	PUBLIC	54,966	со	ЗВ

Page 20 of 27 Report Date: 0		Cycle 6 NPS / RIP Rou (Numerical By Summary Route and S	Federal Lands Highway Road Inventory Program	
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven Black = Non-NPS Routes		= Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon PKG = Parking Areas

NC = Not Collected

					PAR	KING AREA INVENTORY (1300 SERIES FMSS LOCATI	ONS)					
Route No.	ycle ollected	lteration Collected	FMSS Number	Concession	Route Name	Route De	scription To	Maintenance District	FLTP	Access Level	Area (SQ FT)	Surf. Type	Area Map
	00	±0		0		From	10				• • •		
0966	6	2	36108		MODEL AIRPLANE FIELD PARKING	FROM ROUTE 0403 (RUNWAY C)	TO ROUTE 0403 (RUNWAY C)	JAMAICA BAY	YES	PUBLIC	114,483	AS	3B
0967	6	2	36110		CAR TOP BOAT RAMP AND FISHING AREA PARKING	FROM ROUTE 0405 (TAXIWAY B)	TO ROUTE 0405 (TAXIWAY B) AND ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)	JAMAICA BAY	YES	PUBLIC	997,028	со	ЗВ
0968AZZ	6	2	31606		BUILDING 69 PARKING AREA AND USPP NORTH AND SOUTH PARKING AREAS	FROM ROUTE 0201 (RANGER ROAD)	TO PARKING	JAMAICA BAY	YES	PUBLIC	18,731	AS	3B
0968B	6	2	36369		NPS HEADQUARTERS (BUILDING 69 NORTH) AREA PARKING	ADJACENT TO ROUTE 0201 (RANGER ROAD)		JAMAICA BAY	YES	PUBLIC	1,953	AS	ЗВ
0968C	6	2	36371		NPS ECOLOGY VILLAGE PARKING	FROM ROUTE 0201 (RANGER ROAD)	TO PARKING	JAMAICA BAY	YES	PUBLIC	17,918	AS	ЗВ
0968EZZ	6	2	36374		NPS ENTERPRISE ROAD PARKINGS	ADJACENT TO ROUTE 0203 (ENTERPRISE AVENUE) ON LEFT		JAMAICA BAY	YES	PUBLIC	10,556	AS	ЗВ
0968F	6	2	36375		NPS BUILDING 62 AREA PARKING	FROM ROUTE 0203 (ENTERPRISE AVENUE)	TO PARKING	JAMAICA BAY	YES	PUBLIC	15,447	AS	ЗВ
0969	6	2	36111		POLY TECH AND SOCCER FIELD PARKING	FROM INTERSECTION OF ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD) AND ROUTE 0203 (ENTERPRISE AVENUE)	TO FLOYD BENNET FIELD	JAMAICA BAY	YES	PUBLIC	30,443	AS	3B
0970	6	2	36112		FISHING ACCESS PARKING	FROM END OF ROUTE 0201 (RANGER ROAD)	TO PARKING	JAMAICA BAY	YES	PUBLIC	21,099	AS	ЗВ
0971	6	2	36114		TYLUNAS HALL PARKING (NYC COLLECTION)	FROM ROUTE 1042AZ (JABA PARKING A)	TO PARKING	JAMAICA BAY	YES	PUBLIC	38,733	AS	ЗВ
0972A	6	2	36377		BUILDING 98 PARKING	FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD) AT MP 0.07 ON LEFT	TO ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)	JAMAICA BAY	YES	PUBLIC	28,869	AS	ЗВ

Page 21 of 27 Report Date: 0		Cycle 6 NPS / RIP Rout (Numerical By Summary Route and S	Federal Lands Highway Road Inventory Program		
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Concession Route		
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas			
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon	

	PARKING AREA INVENTORY (1300 SERIES FMSS LOCATIONS)												
				ç	PAR	KING AREA INVENTORY (1300 SERIES FMSS LOCATI	ONS)					
Route	e Scted	lteration Collected	FMSS	cessio		Route De	scription	Maintenance	4	Access	Area	Surf.	Area
No.	Cycl	ltera Collo	Number	Con	Route Name	From To		District	FLTP	Level	(SQ FT)	Туре	Map
0972B	6	2	36378		BUILDING 95 PARKING	FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD) AT MP 0.04 ON LEFT	TO ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)	JAMAICA BAY	YES	PUBLIC	17,350	AS	ЗВ
0974	6	2	36115		FT. TILDEN FISHERMEN'S PARKING	FROM ROUTE 0111 (SHORE ROAD)	TO PARKING	JAMAICA BAY	YES	PUBLIC	35,273	AS	3D
0975	6	2	35209		AREA D BEACH CENTER PARKING	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 2.04	TO PARKING	SANDY HOOK	YES	PUBLIC	277,235	AS	2C
0976A	6	2	36379		THEATER PARKING A	FROM ROUTE 0214 (HAHN ROAD)	TO ROUTE 0228 (THEATER ROAD)	JAMAICA BAY	YES	PUBLIC	110,301	AS	3E
0976B	6	2	36380		RAA T-7 PARKING B	ADJACENT TO ROUTE 0214 (HAHN ROAD)		JAMAICA BAY	YES	PUBLIC	4,982	AS	3E
0977	NC		36118		MOTOR POOL PARKING	ADJACENT TO ROUTE 0415 (NIKE MAINTENANCE ROAD)		JAMAICA BAY	NO	PUBLIC	25,339	GR	ЗE
0978	6	2	36119		BALL FIELD PARKING	ADJACENT TO ROUTE 0216 (HERO ROAD)		JAMAICA BAY	YES	PUBLIC	6,695	AS	ЗE
0979	6	2	36121		BAY 17/18 PARKING AREA	FROM ROUTE 0110 (DAVIS ROAD)	TO ROUTE 0110 (DAVIS ROAD) AND 0216 (HERO ROAD)	JAMAICA BAY	YES	PUBLIC	25,896	со	ЗE
0980	6	2	36123		DAVIS ACCESS ROAD PARKING	ADJACENT TO ROUTE 0475 (DAVIS ACCESS ROAD)		JAMAICA BAY	YES	PUBLIC	4,523	со	ЗE
0981	6	2	36126		QTS. 22/23 RESIDENCE ACCESS PARKING	FROM ROUTE 0110 (DAVIS ROAD)	TO PARKING	JAMAICA BAY	NO	NONPUBLIC	4,429	со	ЗE
0982A	6	2	36381		PICNIC PARKING A	FROM ROUTE 0110 (DAVIS ROAD)	TO PARKING	JAMAICA BAY	YES	PUBLIC	6,658	AS	3E
0982B	6	2	36382		PICNIC PARKING B	FROM ROUTE 0110 (DAVIS ROAD)	TO ROUTE 0110 (DAVIS ROAD)	JAMAICA BAY	YES	PUBLIC	10,567	AS	3E
0983A	6	2	36383		BUILDING 1 PARKING AREA A	FROM ROUTE 0214 (HAHN ROAD)	TO ROUTE 0983B (BUILDING 1 SOUTHSIDE PARKING AREA B)	JAMAICA BAY	YES	PUBLIC	6,348	AS	ЗE
0983B	6	2	36384		BUILDING 1 SOUTHSIDE PARKING AREA B	FROM ROUTE 0110 (DAVIS ROAD)	TO ROUTE 0983A (BUILDING 1 PARKING AREA A)	JAMAICA BAY	YES	PUBLIC	9,739	AS	ЗE

Page 22 of 27 Report Date: 0		Cycle 6 NPS / RIP Rout (Numerical By Summary Route and So	Federal Lands Highway Road Inventory Program	
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven Black = Non-NPS Routes		= Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas		
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon

	PARKING AREA INVENTORY (1300 SERIES FMSS LOCATIONS)												
Route	e ected	lteration Collected	FMSS	cessior		Route De	scription	Maintenance	۔	Access	Area	Surf.	Area
No.	0 C	ltero Coll	Number	Con	Route Name	From	То	District	FLTP	Level	(SQ FT)	Туре	Мар
0983C	6	2	36385		BUILDING 1 NORTHSIDE PARKING AREA C	FROM INTERSECTION OF ROUTE 0214 (HAHN ROAD) AND ROUTE 0212 (HEINZELMAN ROAD)	TO ROUTE 0214 (HAHN ROAD)	JAMAICA BAY	YES	PUBLIC	7,382	AS	3E
0983D	6	2	240516		BUILDING 1 PARKING NORTH	ADJACENT TO ROUTE 0214 (HAHN ROAD)		JAMAICA BAY	YES	PUBLIC	2,895	AS	ЗE
0984A	6	2	36386		BUILDING 149 PARKING AREA	FROM ROUTE 0212 (HEINZELMAN ROAD)	TO ROUTE 0212 (HEINZELMAN ROAD)	JAMAICA BAY	YES	PUBLIC	10,761	AS	ЗE
0984B	6	2	36387		COMMUNITY GARDEN AREA PARKING B	ADJACENT TO ROUTE 0213 (WORCESTER ROAD)		JAMAICA BAY	YES	PUBLIC	1,289	AS	ЗE
0986	6	2	36129		POST OFFICE PARKING	ADJACENT TO ROUTE 0225 (POST OFFICE ROAD)		JAMAICA BAY	YES	PUBLIC	1,732	со	ЗE
0987	6	2	36131		MAINTENANCE AREA PARKING (RIIS LDG)	FROM ROUTE 5000 (ROCKAWAY POINT BOULEVARD)	TO PARKING	JAMAICA BAY	YES	PUBLIC	30,430	со	ЗE
0988	6	2	36133		RIIS PARK BAY 3 EAST PARKING	FROM ROUTE 5003 (ROCKAWAY BEACH BOULEVARD)	TO BOARDWALK ACCESS ROAD	JAMAICA BAY	YES	PUBLIC	21,1 <i>57</i>	со	ЗF
0989	6	2	36135		CANARSIE PIER PARKING	FROM ROUTE 5204 (CANARSIE PIER)	TO PARKING	JAMAICA BAY	YES	PUBLIC	117,609	AS	3A
0990	6	2	36136		WILDLIFE REFUGE VISITOR PARKING	FROM ROUTE 5005S (CROSS BAY BOULEVARD (SOUTHBOUND))	TO PARKING	JAMAICA BAY	YES	PUBLIC	42,706	AS	3A
0991A	6	2	31395		NORTH CHANNEL BRIDGE PARKING / EASTSIDE	FROM ROUTE 5005N (CROSS BAY BOULEVARD (NORTHBOUND))	TO PARKING	JAMAICA BAY	YES	PUBLIC	18,769	AS	3A
0991B	6	2	31394		NORTH CHANNEL BRIDGE PARKING / WESTSIDE	FROM ROUTE 5005S (CROSS BAY BOULEVARD (SOUTHBOUND))	TO PARKING	JAMAICA BAY	YES	PUBLIC	20,642	AS	3A
0993	6	2	35210		PARKING LOT E	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 2.35	TO PARKING	SANDY HOOK	YES	PUBLIC	289,221	AS	2C
0994	6	2	25243		GREAT KILLS EDUCATION CENTER PARKING	FROM ROUTE 0232ZZ (BULKHEAD ROADS)	TO PARKING	STATEN ISLAND	YES	PUBLIC	3,489	со	1D
0996	6	2	112112		BREEZY POINT SURF CLUB PARKING	FROM END OF ROUTE 0222 (BREEZY POINT SURF CLUB ENTRANCE ROAD)	TO PARKING	JAMAICA BAY	YES	PUBLIC	334,242	AS	3C

Page 23 of 27 Report Date: 0	9/22/2022	Cycle 6 NPS / RIP Rout (Numerical By Summary Route and So	Federal Lands Highway Road Inventory Program	
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven Black = Non-NPS Routes		= Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon PKG = Parking Areas

NC = Not Collected

				E	PAR	KING AREA INVENTORY (1300 SERIES FMSS LOCATI	ONS)					
Route No.	Cycle Collected	lteration Collected	FMSS Number	Concessio	Route Name	Route De	scription To	Maintenance District	FLTP	Access Level	Area (SQ FT)	Surf. Type	Area Map
0997	NC		112115		BREEZY POINT SURF CLUB UNPAVED PARKING	ADJACENT TO ROUTE 0222 (BREEZY POINT SURF CLUB ENTRANCE ROAD)		JAMAICA BAY	NO	PUBLIC	37,596	SA	3C
0998	NC		112203		SILVER GULL BEACH CLUB UNPAVED PARKING	FROM ROUTE 0999ZZ (SILVER GULL BEACH CLUB PARKING)	TO PARKING	JAMAICA BAY	NO	PUBLIC	2,405	SA	3D
0999ZZ	6	2	112205		SILVER GULL BEACH CLUB PARKING	FROM ROUTE 0234 (SILVER GULL BEACH CLUB ENTRANCE ROAD) RIGHT AND LEFT	TO PARKING	JAMAICA BAY	YES	PUBLIC	110,898	AS	3D
1000	NC		112715		ROCKAWAY POINT YACHT CLUB PARKING	FROM END OF ROUTE 0235 (ROCKAWAY POINT YACHT CLUB ROAD)	TO PARKING	JAMAICA BAY	NO	PUBLIC	7,358	GR	3D
1001	NC		77672		WILDLIFE REFUGE BUILDING 101 PARKING	FROM ROUTE 0419 (JAMAICA BAY RESIDENCE ROAD)	TO PARKING	JAMAICA BAY	NO	NONPUBLIC	14,412	GR	3A
1002	6	2	93881		HAMILTON BEACH PARKING	FROM LOCKWOOD COURT	TO PARKING	JAMAICA BAY	YES	PUBLIC	11,195	AS	3A
1004	6	2	25254		PICNIC/BEACH AREA PARKING LOT E	FROM ROUTE 0130 (MILLER FIELD ENTRANCE ROAD)	TO ROUTE 0132A (VISITOR CENTER (SANCHEZ ROAD EAST))	STATEN ISLAND	YES	PUBLIC	52,677	AS	1C
1005	NC		25245		GREAT KILLS CROOKS POINT PARKING B	FROM END OF ROUTE 0493 (CROOKS POINT FISHING ROAD)	TO PARKING	STATEN ISLAND	NO	NONPUBLIC	7,277	GR	1D
1006	NC		25246		GREAT KILLS ATHLETIC FIELD PARKING	FROM ROUTE 0437 (ACCESS TO ATHLETIC FIELD ROAD)	TO PARKING	STATEN ISLAND	NO	PUBLIC	32,809	GR	۱D
1007	NC		25244		GREAT KILLS CROOKS POINT PARKING A	FROM END OF ROUTE 0492 (GREAT KILLS ACCESS TO BEACH (CROOKS POINT))	TO PARKING	STATEN ISLAND	NO	NONPUBLIC	34,345	GR	۱D
1008	NC		115508		GREAT KILLS EDUCATION OVERFLOW CENTER PARKING	ADJACENT TO ROUTE 0232ZZ (BULKHEAD ROADS)		STATEN ISLAND	NO	PUBLIC	33,119	GR	1D
1009	NC		91898		MILLER FIELD BEACH ENTRANCE PARKING	ADJACENT TO ROUTE 0130 (MILLER FIELD ENTRANCE ROAD) AND NEW DORP LANE		STATEN ISLAND	NO	PUBLIC	24,058	GR	۱C
1011	6	2	114406		MILLER FIELD AREA D PARKING LOT (FT. CAPODANO)	FROM ROUTE 0132A (VISITOR CENTER (SANCHEZ ROAD EAST))	TO FATHER CAPODANNO BOULEVARD	STATEN ISLAND	YES	PUBLIC	28,770	AS	1C

Page 24 of 27 Report Date: 09/22/2022		Cycle 6 NPS / RIP Rou (Numerical By Summary Route and S	-	Federal Lands Highway Road Inventory Program
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Non-NPS Routes	= Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon PKG = Parking Areas NC = Not Collected

	PARKING AREA INVENTORY (1300 SERIES FMSS LOCATIONS)												
				c	PAI	KING AREA INVENTORY (1300 SERIES FMSS LOCATI	ONS)					
Route	ile lected	ation lected	FMSS	Icession		Route De	escription	Maintenance	FLTP	Access	Area	Surf.	Area
No.	δõ	ltero Coll	Number	Š	Route Name	From	То	District	5	Level	(SQ FT)	Туре	Мар
1012	6	2	116079		GREAT KILLS MARINA PARKING	FROM ROUTE 0030 (BUFFALO ROAD)	TO PARKING	STATEN ISLAND	NO	NONPUBLIC	89,726	AS	1D
1013	6	2	239600		USPP STABLE PARKING	FROM ROUTE 0458 (USS TENNESSEE ROAD)	TO PARKING	STATEN ISLAND	YES	PUBLIC	3,738	AS	1 B
1014	6	2	239601		BUILDING 302 L-SHAPED PARKING	FROM ROUTE 0458 (USS TENNESSEE ROAD)	TO PARKING	STATEN ISLAND	YES	PUBLIC	24,868	AS	1B
1015	6	2	238599		BUILDING 301 MAINTENANCE PARKING	FROM ROUTE 0458 (USS TENNESSEE ROAD)	TO PARKING	STATEN ISLAND	YES	PUBLIC	10,048	AS	1B
1016ZZ	6	2	238264		RIIS LANDING PARKING AREAS	FROM ROUTE 5000 (ROCKAWAY POINT BOULEVARD) AND ROUTE 0987 (MAINTENANCE AREA PARKING (RIIS LDG))	TO PARKING	JAMAICA BAY	NO	NONPUBLIC	88,943	AS	3E
1017	6	2			BREEZY POINT SURF CLUB ENTRANCE PARKING	FROM ROUTE 0222 (BREEZY POINT SURF CLUB ENTRANCE ROAD)	TO ROUTE 0222 (BREEZY POINT SURF CLUB ENTRANCE ROAD)	JAMAICA BAY	NO	NONPUBLIC	8,858	AS	3C
1020	6	2	115709		NYPD PARKING 1	FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)	TO PARKING	JAMAICA BAY	NO	NONPUBLIC	66,030	AS	3B
1021	6	2	115710		NYPD PARKING 2	FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)	TO ROUTE 1020 (NYPD PARKING 1) AND ROUTE 1022 (NYPD PARKING 3)	JAMAICA BAY	NO	NONPUBLIC	27,080	AS	3B
1022	6	2	115711		NYPD PARKING 3	FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)	TO ROUTE 1021 (NYPD PARKING 2)	JAMAICA BAY	NO	NONPUBLIC	5,290	AS	3B
1023	6	2	115725		NYPD PARKING 4	FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)	TO ROUTE 1024 (NYPD PARKING 5)	JAMAICA BAY	NO	NONPUBLIC	24,059	AS	3B
1024	6	2	115726		NYPD PARKING 5	FROM ROUTE 1023 (NYPD PARKING 4)	TO ROUTE 1023 (NYPD PARKING 4)	JAMAICA BAY	NO	NONPUBLIC	53,985	AS	ЗB
1025	6	2	112823		PENNSYLVANIA AVENUE LANDFILL PARKING	FROM ROUTE 0062 (PENNSYLVANIA AVENUE LANDFILL ACCESS ROADS)	TO PARKING	JAMAICA BAY	NO	PUBLIC	52,403	AS	3A
1026	6	2	112827		FOUNTAIN AVENUE LANDFILL	FROM ROUTE 0063 (NS FOUNTAIN AVENUE LANDFILL ACCESS ROADS)	TO PARKING	JAMAICA BAY	NO	PUBLIC	54,184	AS	3A

Page 25 of 27 Report Date: 09/22/2022		Cycle 6 NPS / RIP Rou (Numerical By Summary Route and S	Federal Lands Highway Road Inventory Program	
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven Black = Non-NPS Routes		Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas Green = Unpaved Parking Areas		
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon

				E	PAR	KING AREA INVENTORY (1300 SERIES FMSS LOCAT	ONS)					
Route	cle llected	ation llected	FMSS	ncessio		Route De	scription	Maintenance	FLTP	Access	Area	Surf.	Area
No.	ູ້ ບໍ ້ ບໍ	ltera Coll	Number	Ŝ	Route Name	From	То	District		Level	(SQ FT)	Туре	Мар
1027	6	2	225810		AVIATOR SPORTS PAVED PARKING	FROM ROUTE 5006N (FLATBUSH AVENUE (NORTHBOUND))	TO ROUTE 0965C (AVIATOR CONCESSION PARKING)	JAMAICA BAY	YES	PUBLIC	276,599	со	3B
1028	6	2	227300		NC-S RIDING ACADEMY PARKING LOT	FROM ROUTE 0205 (RIDING ACADEMY ACCESS ROAD)	TO PARKING	JAMAICA BAY	YES	PUBLIC	17,146	AS	3A
1029	NC		28171		NDR LOT K PARKING LOT K UNPAVED	FROM ROUTE 0667 (NORTH BRAGG DRIVE)	TO PARKING	SANDY HOOK	NO	PUBLIC	101,943	GR	2A
1030	NC		89793		PARKING LOT F	FROM ROUTE 0479 (FISHERMAN'S PARKING ACCESS)	TO PARKING	SANDY HOOK	NO	PUBLIC	13,650	GR	2B
1031	NC		28170		DR PARKING J NORTH BEACH EXTENSION	FROM ROUTE 0160 (ATLANTIC DRIVE)	TO PARKING	SANDY HOOK	NO	PUBLIC	72,418	GR	2A
1032	NC		110635		ND NEW TENT CITY PARKING	FROM ROUTE 0659 (OLD TRAILER CAMP LANE MAST)	TO PARKING	SANDY HOOK	NO	PUBLIC	35,574	GR	2A
1035	6	2	245334		BEACH 222ND STREET PARKING	FROM ROUTE 0222 (BREEZY POINT SURF CLUB ENTRANCE ROAD)	TO PARKING	JAMAICA BAY	NO	PUBLIC	6,999	AS	3C
1036	6	2			PARKING LOT M	FROM ROUTE 0667 (NORTH BRAGG DRIVE - UNPAVED SEGMENT)	TO PARKING	SANDY HOOK	YES	PUBLIC	9,173	AS	2A
1037	6	2	30003		NOAA SERVICE PARKING LOT	FROM ROUTE 0918A (NOAA LAB A PARKING SOUTH)	TO ROUTE 0918B (NOAA LAB B PARKING NORTH)	SANDY HOOK	NO	NONPUBLIC	9,733	AS	2A
1038	NC				ARCHERY PARKING	ADJACENT TO ROUTE 0201 (RANGER ROAD)		JAMAICA BAY	NO	NONPUBLIC	3,090	GR	3B
1041	NC				GREAT KILLS MARINA UNPAVED PARKING	FROM ROUTE 1012 (GREAT KILLS MARINA PARKING)	TO ROUTE 1012 (GREAT KILLS MARINA PARKING)	STATEN ISLAND	NO	NONPUBLIC	119,424	GR	1D
1042ZZ	6	2	256345		JABA PARKING	FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)	TO PARKING	JAMAICA BAY	NO	NONPUBLIC	482,849	AS	ЗВ

Page 26 of 27 Report Date: 09/22/2022		Cycle 6 NPS / RIP Rou (Numerical By Summary Route and S	Federal Lands Highway Road Inventory Program	
Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Non-NPS Routes	= Concession Route
	Yellow = Unpayed Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon PKG = Parking Areas NC = Not Collected

Cycle 6 Summary Totals for Gateway National Recreation Area


Cycl	e 6 Route Totals	Cycle 6 Route Totals											
	NPS Maintained	Concessionaire Maintained	Park Totals										
Paved Roads, Data Collection Vehicle Rated (Miles)	35.13	0.83	35.96										
Paved Roads, Manually Rated Length (Miles)	5.50	0	5.50										
Paved Roads, Manually Rated Area (Sq. Ft.)	0	0	0										
Unpaved Roads (Miles)	6.67	0	6.67										
Paved Parking (Sq. Ft.)	9,618,793	534,866	10,153,659										
Unpaved Parking (Sq. Ft.)	519,863	44,954	564,817										

Cycle 6 Lane Miles and Overall Pavement Condition								
	Lanes Miles*	Pavement Condition Rating**						
Data Collection Vehicle Routes	93.97	53						
Manually Rated Roads	7.55	59						
Parking Areas	174.82	78						

* Equivalent Lane Miles are calculated by route using the following equations: - DCV and MRLs = (PAVE_WIDTH x PAVED_MI) / 11 foot lane - MRPs and PKGs = SQ_FEET / 5280 / 11 foot lane **Parking and Manually Rated Routes are assigned the following PCR values based on the type of observed distresses:

-Excellent = 97 -Good = 90 -Fair = 73 -Poor = 53, 30, or 0 -Construction / Not Rated = -1 Page 27 of 27

Cycle 6 NPS / RIP Route ID Report



NC = Not Collected

FC	Туре	User Access	Description	Route Numbers	Surface Types
1	Principal Park Road Rural Parkway	Public	Roads which constitute the main access route, circulatory tour, or thoroughfare for park visitors. Rural Parkways (e.g. Natchez Trace) are numbered 0001 - 0009.	0001 - 0009 0010 - 0099	AS - Asphaltic Concrete Pavement
2	Connector Park Road	Public	Roads which provide access within a park to areas of scenic, scientific, recreational or cultural interest, such as overlooks, campgrounds, etc.	0100 - 0199	BR - Brick or Pavers Road Bed CB - Cobble Stone Road Bed
3	Special Purpose Park Road	Public	Roads which provide circulation within public areas, such as campgrounds, picnic areas, visitor center complexes, concessionaire facilities, etc. These roads generally serve low-speed traffic and are often designed for one-way circulation.	0200 - 0299	CO - Portland Cement Concrete Paveme
4	Primitive Park Road	Public	Roads which provide circulation through remote areas and/or access to primitive campgrounds and undeveloped areas. These roads frequently have no minimum design standards and their use may be limited to specially equipped vehicles. Note: Functional Classes 3 and 4 have the same route numbers because, historically, they were numbered similarly.	0200 - 0299	NV - Native or Dirt Material Road Bed
5	Administrative Park Road	Public	All public roads intended for access to administrative developments or structures such as park offices, employee quarters, or utility areas.	0400 - 0499	OT - Other Materials Road Bed
6	Administrative Park Road (Restricted Access)	Nonpublic	All roads normally closed to the public, including patrol roads, truck trails, and other similar roads. Note: Functional Classe 5 and 6 have the same route numbers because historically they were numbered similarly and often there is little distinction between these routes. For example, because utility areas and employee housing are often closed to the public, this restriction would result in classification of FC 6 rather than FC 5.	0400 - 0499	
7	Urban Parkway	Public	These facilities serve high volumes of park and non-park related traffic and are restricted, limited-access facilities in an urban area. This category of roads primarily encompasses the major parkways which serve as gateways to our nation's capital. Other major park roads or portions thereof, however, may be included in this category.	0001 - 0009	
8	City Street	Public	City streets are usually extensions of the adjoining street system that are owned and maintained by the National Park Service. The construction and/or reconstruction should conform with accepted local engineering practice and local conditions.	0600 - 0699	
N/A	Non-NPS Roads	Public	State, County, or City owned roads which border, traverse, or provide access to Park Facilities or Locations. Non-NPS roads are not assigned functional classes and are driven for GPS and Video Log only.	5000 - 5999	

A park road system contains those roads within or giving access to a park or other unit of the NPS which are administered by the NPS, or by the Service in cooperation with other agencies. The assignment of a functional classification (FC) to a park road is not based on traffic volumes or design speed, but on the intended use or function of that road or route.

The historic route numbering system also included a 300 series for interpretive roads, and a 500 series for one-way roads. There are approximately 250 roads nationwide which are designated by the 300 and 500 series. The numbers for these roads will be maintained for reporting consistency. However, since these interpretive and one-way routes are not as clearly tie to a specific functional class, the 300 and 500 series will be discontinued for future use.

Page 1 of 11

Report Date: 09/22/2022

NPS / RIP Subcomponent Details for GATE

(Numerical By Summary Route and Subcomponent #)



Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Paved Routes, Non-NPS	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas

NC = Not Collected

	SUMMARY ROUTE INVENTORY FOR ROADS (1100 SERIES FMSS LOCATIONS)												
Route	FMSS Number	ile lected	lteration Collected	Icessio		Route Des	cription	. <u>c</u>		Unpaved	Total	nction Iss	Area
Number	Number	ပိုပို	lter Col	Con	Route Name	From	То	FLTP	Miles	Miles	Mileage	Ū. F	(SQ FT)
0163ZZ	36014	6	2		RANGE ROADS	FROM ROUTE 0224 (BEACH 193RD STREET)	TO END	YES	0.97	0.00	0.97	3	
0227ZZ	36021	6	2		ROMERO ROAD EAST AND WEST	FROM ROUTE 0211 (SOUTH BARRETT ROAD)	TO ROUTE 0226 (NORTH BARETTE)	YES	0.05	0.00	0.05	3	
0232ZZ	21207	6	2		BULKHEAD ROADS	FROM ROUTE 0030 (BUFFALO ROAD) AT MP 1.02 ON RIGHT	TO END	Ю	0.00	0.89	0.89	3	
0440ZZ	21182	6	2		NY AVENUE / BATTERY ROAD	FROM END OF ROUTE 0442 (NORTH ROAD) ON LEFT AT PARK BOUNDARY	TO BEGINNING OF ROUTE 5004 (MCCLEAN AVENUE)	YES	0.65	0.00	0.65	1	
0474ZZ	33210	6	2		MILLER FIELD RESIDENCE ROAD	FROM ROUTE 0132B (HOUSING ACCESS (SANCHEZ ROAD WEST)) AT MP 0.09	TO ROUTE 0132B (HOUSING ACCESS (SANCHEZ ROAD WEST)) AT MP 0.17 AND MASON AVENUE	YES	0.21	0.00	0.21	5	
0477ZZ	30011	6	2		NIKE RADAR SITE ROADS	FROM ROUTE 0913 (LOT "L" NIKE RADAR SITE PARKING)	TO END OF PAVEMENT	YES	0.43	0.00	0.43	5	
0483ZZ	33628	6	2		South maintenance shop road c	FROM END OF ROUTE 0481 (SOUTH MAINTENANCE SHOP ROAD A)	TO ROUTE 0909B (MAINTENANCE PARKING EAST) AND ROUTE 0909C (MAINTENANCE PARKING WEST)	YES	0.10	0.00	0.10	5	
0496ZZ	77685				RD-WDSC- SPRING CREEK ROADS	FROM CROSS BAY BOULEVARD	TO 165TH AVENUE	NO	0.00	2.78	2.78	6	
0504ZZ		6	2		SOUTHERN RUNWAY	FROM ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))	TO ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)	YES	0.96	0.00	0.96	5	
0661ZZ	33647	6	2		HUDSON ROADS	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))	TO ROUTE 0668 (SOUTH BRAGG DRIVE)	YES	0.72	0.00	0.72	2	
0662ZZ	33648	6	2		MAGRUDER ROADS	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))	TO ROUTE 0923 (BUILDING 53 AND BUILDING 60 PARKING) AND ROUTE 0661ZZ (HUDSON ROADS)	YES	0.53	0.00	0.53	2	
0675ZZ	33660	6	2		MCNAIR ROADS	FROM ROUTE 0665 (KEARNY DRIVE)	TO ROUTE 0661ZZ (HUDSON ROADS)	YES	0.21	0.00	0.21	5	

Page 2 of 11

Report Date: 09/22/2022

NPS / RIP Subcomponent Details for GATE

(Numerical By Summary Route and Subcomponent #)



 Shading Color Key
 White = Paved Routes, DCV Driven
 Grey = Paved Routes, DCV not Driven
 Black = Paved Routes, Non-NPS

 = Concession Route

 Yellow = Unpaved Routes, DCV not Driven
 Blue = Paved Parking Areas
 Green = Unpaved Parking Areas

 DCV = Data Collection Vehicle
 MRL = Manually Rated Line
 MRP = Manually Rated Polygon
 PKG = Parking Areas

NC = Not Collected

GATE Gateway National Recreation Area

SUMMARY ROUTE INVENTORY FOR PARKING AREAS (1300 SERIES FMSS LOCATIONS) Concessio lteration Collected User Area Route FMSS **Route Description** FTP (SQ FT) Access Number Number **Route Name** From То 0906ZZ 36107 2 JACOB RIIS PARKING FROM ROCKAWAY BEACH BOULEVARD TO ROUTE 5000 (ROCKAWAY POINT BOULEVARD) YES PUBLIC 2,641,982 6 25235 2 ADJACENT TO ROUTE 0030 (BUFFALO ROAD) AT MP 0.0 0940ZZ 6 GREAT KILLS ENTRANCE PARKING AREAS YES PUBLIC 17,240 LEFT AND RIGHT 0955AZZ 33184 2 COAST GUARD AREA PARKING A ADJACENT TO ROUTE 0449 (COAST GUARD DRIVE) ON YES PUBLIC 24,970 6 RIGHT 0964ZZ 36138 6 2 ENTRANCE AREA PARKING FROM ROUTE 0464 (AVIATION ROAD) LEFT AND RIGHT TO ROUTE 0464 (AVIATION ROAD) YES PUBLIC 33,806 2 0968AZZ 31606 BUILDING 69 PARKING AREA AND USPP YES PUBLIC 6 FROM ROUTE 0201 (RANGER ROAD) TO PARKING 18,731 NORTH AND SOUTH PARKING AREAS 2 0968EZZ 36374 6 NPS ENTERPRISE ROAD PARKINGS ADJACENT TO ROUTE 0203 (ENTERPRISE AVENUE) ON YES PUBLIC 10.556 LEFT 0999ZZ 112205 6 2 SILVER GULL BEACH CLUB PARKING FROM ROUTE 0234 (SILVER GULL BEACH CLUB TO PARKING YES PUBLIC 110,898 ENTRANCE ROAD) RIGHT AND LEFT 1016ZZ 238264 2 RIIS LANDING PARKING AREAS FROM ROUTE 5000 (ROCKAWAY POINT BOULEVARD) TO PARKING NO NONPUBLIC 88,943 6 AND ROUTE 0987 (MAINTENANCE AREA PARKING (RIIS LDG)) 1042ZZ 256345 2 JABA PARKING FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE TO PARKING NO NONPUBLIC 482,849 6 ROAD

Page 3 of 11

Report Date: 09/22/2022

NPS / RIP Subcomponent Details for GATE

(Numerical By Summary Route and Subcomponent #)



Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Paved Routes, Non-NPS	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon PKG = Parking Areas

NC = Not Collected

GATE Gateway National Recreation Area

	GATE-0	0163ZZ	Su	bcoı	mp	onent Breakdown							8	
	Route	FMSS Number		ation Ilected	ncessio		Route Des	cription	- ല		Unpaved		nction	Area (SQ FT)
Ļ	Number	Number	ູ້ ບໍ່ ບໍ່	Co He	Ŝ	Route Name	From	То	E	Miles	Miles	Mileage	ŢΩ	(SQ FI)
l	0163AZ	36014	6	2		RANGE ROAD	FROM ROUTE 0224 (BEACH 193RD STREET)	TO END	YES	0.21	0.00	0.21	3	
	0163BZ	36014	6	2		BPD RANGE ROAD	FROM ROUTE 0216 (HERO ROAD)	TO ROUTE 0224 (BEACH 193RD STREET)	NO	0.76	0.00	0.76	3	

GATE-	0227ZZ	. Su	bco	mp	onent Breakdown							_	
Route	FMSS	~ Ū	ation lected	Icession		Route Des	cription	~	Paved	Unpaved		nctionc ss	Area
Number	Number	C vello	lterd Coll	Con	Route Name	From	То	FLT	Miles	Miles	Mileage	Ga Fo	(SQ FT)
0227AZ	36021	6	2		ROMERO ROAD WEST	FROM ROUTE 0226 (NORTH BARETTE)	TO ROUTE 0211 (SOUTH BARRETT ROAD)	YES	0.03	0.00	0.03	3	
0227BZ	36021	6	2		ROMERO ROAD EAST	FROM ROUTE 0211 (SOUTH BARRETT ROAD)	TO ROUTE 0226 (NORTH BARETTE)	YES	0.03	0.00	0.03	3	

GATE-	0232ZZ	. Su	bco	mp	onent Breakdown							al	
Route	FMSS Number	/cle ollected	eration ollected	oncessio	Devile Marrie	Route De	_	- E			Total Mileage	unction ass	Area (SQ FT)
NUmber	NUmber	ບົບັ	≗ů	ů	Route Name	From	То	E	Miles	Miles	Mileage	ч С С	(5411)
0232AZ	21207	6	2		BULKHEAD ROAD	FROM ROUTE 0030 (BUFFALO ROAD) AT MP 1.02 ON RIGHT	TO END	NO	0.00	0.77	0.77	3	
0232BZ	21207	6	2		BULKHEAD SPUR	FROM ROUTE 0232AZ (BULKHEAD ROAD)	TO END	NO	0.00	0.12	0.12	3	

Page 4 of 11

Report Date: 09/22/2022

NPS / RIP Subcomponent Details for GATE

(Numerical By Summary Route and Subcomponent #)



Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Paved Routes, Non-NPS	Concession Route
	Yellow = Unpayed Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon PKG = Parking Areas

NC = Not Collected

GATE Gateway National Recreation Area

GATE-0440ZZ Subcomponent Breakdown lteration Collected Concessi Inpaved Total 년 Miles Mileage 문 **Route Description** Area Route FMSS **Paved Unpaved Total** Class Cycle Collec FLTP (SQ FT) Number Number Miles **Route Name** То From 0440AZ 21182 2 NY AVENUE FROM END OF ROUTE 0442 (NORTH ROAD) TO INTERSECTION OF ROUTE 0440BZ YES 0.40 0.00 0.40 6 1 ON LEFT AT PARK BOUNDARY (BATTERY ROAD) AND ROUTE 0445 (HUDSON ROAD / STATEN ISLAND) 0440BZ 21182 6 2 BATTERY ROAD FROM INTERSECTION ROUTE 0440AZ (NY TO BEGINNING OF ROUTE 5004 YES 0.25 0.00 0.25 1 AVENUE) AND ROUTE 0445 (HUDSON ROAD (MCCLEAN AVENUE) / STATEN ISLAND)

GATE-	0474ZZ	. Su	bco	mp	onent Breakdown							8	
Route Number	FMSS	/cle ollected	eration ollected	oncessio	Davida Nama	Route Des	•	£.	Paved Miles	Unpaved Miles	Total	unction lass	Area (SQ FT)
Number	Number	ບິບັ	≚υ	ů	Route Name	From	То	Ц	miles	miles	miedge	μŪ	(0 4 1 1)
0474AZ	33210	6	2		MILLER FIELD RESIDENCE ROAD A		TO ROUTE 0132B (HOUSING ACCESS (SANCHEZ ROAD WEST))AT MP 0.17 AND MASON AVENUE	YES	0.07	0.00	0.07	5	
0474BZ	33210	6	2		MILLER FIELD RESIDENCE ROAD B	FROM ROUTE 0474AZ (MILLER FIELD RESIDENCE ROAD A)	TO ROUTE 0494 (MFR431 SERVICE ROAD)	YES	0.03	0.00	0.03	5	
0474CZ	33210	6	2		MILLER FIELD RESIDENCE ROAD C	· · · · · · · · · · · · · · · · · · ·	TO ROUTE 0132B (HOUSING ACCESS (SANCHEZ ROAD WEST))AT MP 0.17 AND MASON AVENUE	YES	0.11	0.00	0.11	5	

Page 5 of 11

Report Date: 09/22/2022

NPS / RIP Subcomponent Details for GATE

(Numerical By Summary Route and Subcomponent #)



Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Paved Routes, Non-NPS	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon PKG = Parking Areas

NC = Not Collected

GATE Gateway National Recreation Area

GATE-0477ZZ Subcomponent Breakdown

Route	FMSS	le lected	ation lected	ıcession		Route Des	cription		Paved	Unpaved			Area
Route Number	Number	C vello	Lter Coll	Con	Route Name	From	То	FLT	Miles	Miles	Mileage	P. P.	(SQ FT)
0477AZ	30011	6	2		NIKE RADAR SITE ROAD A	FROM ROUTE 0913 (LOT "L" NIKE RADAR SITE PARKING)	TO END OF PAVEMENT	YES	0.24	0.00	0.24	5	
0477BZ	30011	6	2		NIKE RADAR SITE ROAD B	FROM ROUTE 0477AZ (NIKE RADAR SITE ROAD A)	TO END	YES	0.05	0.00	0.05	5	
0477CZ	30011	6	2		NIKE RADAR SITE ROAD C	FROM ROUTE 0477AZ (NIKE RADAR SITE ROAD A)	TO END	YES	0.14	0.00	0.14	5	

GATE-	0483ZZ	. Su	bco	mp	onent Breakdown							5	
Route	FMSS Number		ation llected	ncessio		Route De	scription	- 6	Paved	Unpaved		nction	Area
Number	Number	δõ	Ler Col	Ŝ	Route Name	From	То	EL	Miles	Miles	Mileage	Ξö	(SQ FT)
0483AZ	33628	6	2		SOUTH MAINTENANCE SHOP ROAD C - MAIN	FROM END OF ROUTE 0481 (SOUTH MAINTENANCE SHOP ROAD A)	TO END	YES	0.06	0.00	0.06	5	
0483BZ	33628	6	2		SOUTH MAINTENANCE SHOP ROAD C - SPUR	FROM ROUTE 0483AZ (SOUTH MAINTENANCE SHOP ROAD C - MAIN)	TO ROUTE 0909B (MAINTENANCE PARKING EAST)	YES	0.03	0.00	0.03	5	

Page 6 of 11

Report Date: 09/22/2022

NPS / RIP Subcomponent Details for GATE

(Numerical By Summary Route and Subcomponent #)



Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Paved Routes, Non-NPS	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon PKG = Parking Areas

NC = Not Collected

GATE Gateway National Recreation Area

GATE-0496ZZ Subcomponent Breakdown

Route Number	FMSS Number	Cycle Collected	lteration Collected	Concession.	Route Name	Route Des	cription To	FLTP -	Paved Miles	Unpaved Miles	Total Mileage		Area (SQ FT)
0496AZ	77685				RD-WDSC- SPRING CREEK ROAD A	FROM CROSS BAY BOULEVARD	TO END OF LOOP	NO	0.00	2.01	2.01	6	
0496BZ	77685				RD-WDSC- SPRING CREEK ROAD B	FROM ROUTE 0496AZ (RD-WDSC- SPRING CREEK ROAD A)	TO END	NO	0.00	0.13	0.13	6	
0496CZ	77685				RD-WDSC- SPRING CREEK ROAD C	FROM ROUTE 0496AZ (RD-WDSC- SPRING CREEK ROAD A)	TO ROUTE 0496AZ (RD-WDSC- SPRING CREEK ROAD A)	NO	0.00	0.51	0.51	6	
0496DZ	77685				RD-WDSC- SPRING CREEK ROAD D	FROM ROUTE 0496AZ (RD-WDSC- SPRING CREEK ROAD A)	TO END	NO	0.00	0.13	0.13	6	

GATE-0	0504ZZ	. Su	bco	mp	onent Breakdown							5	
Route	FMSS	le lected	ation lected	Icessio		Route Des	cription	. 4	Paved	Unpaved			Area
Number	FMSS Number	ပိုပ္ပို	lter Col	Co	Route Name	From	То	FLT	Miles	Miles	Mileage	Cla Cla	(SQ FT)
0504AZ		6	2		SOUTHERN RUNWAY A	FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)	TO END	YES	0.44	0.00	0.44	5	
0504BZ		6	2		SOUTHERN RUNWAY B	FROM ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))	TO END	YES	0.51	0.00	0.51	5	

Page 7 of 11

Report Date: 09/22/2022

NPS / RIP Subcomponent Details for GATE

(Numerical By Summary Route and Subcomponent #)



Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Paved Routes, Non-NPS	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon PKG = Parking Areas

NC = Not Collected

GATE Gateway National Recreation Area

GATE-0661ZZ Subcomponent Breakdown lteration Collected Cycle Collected Concessi Inpaved Total 년 Miles Mileage 문 **Route Description** Area Route FMSS Paved Unpaved Total Class FLTP (SQ FT) Number Number Miles **Route Name** То From 0661AZ 33647 6 2 HUDSON ROAD FROM ROUTE 0060 (HARTSHORNE DRIVE TO ROUTE 0668 (SOUTH BRAGG DRIVE) YES 0.66 0.00 0.66 2 (NORTHBOUND)) 0661BZ 33647 6 2 YES 0.03 0.00 0.03 2 HUDSON ROAD SPUR FROM ROUTE 0661AZ (HUDSON ROAD) TO ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) 6 2 YES 2 0661CZ 33647 HUDSON ROAD CUT-THRU FROM ROUTE 0665 (KEARNY DRIVE) TO ROUTE 0661AZ (HUDSON ROAD) 0.03 0.00 0.03

GATE-0662ZZ Subcomponent Breakdown													
Route Number	FMSS Number	Cycle Collected	lteration Collected	Concessic	Route Name	Route Des	cription To	FLTP	Paved Miles	Unpaved Miles	Total Mileage	Function Class	Area (SQ FT)
0662AZ	33648	6	2		MAGRUDER ROAD	FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))	TO ROUTE 0923 (BUILDING 53 AND BUILDING 60 PARKING) AND ROUTE 0661 AZ (HUDSON ROAD)	YES	0.45	0.00	0.45	2	
0662BZ	33648	6	2		MAGRUDER ROAD SPUR 1	FROM ROUTE 0662AZ (MAGRUDER ROAD)	TO ROUTE 0661AZ (HUDSON ROAD)	YES	0.06	0.00	0.06	2	
0662CZ	33648	6	2		MAGRUDER ROAD SPUR 2	FROM ROUTE 0662AZ (MAGRUDER ROAD)	TO ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))	YES	0.02	0.00	0.02	2	

Page 8 of 11

Report Date: 09/22/2022

NPS / RIP Subcomponent Details for GATE

(Numerical By Summary Route and Subcomponent #)



Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Paved Routes, Non-NPS	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon PKG = Parking Areas

NC = Not Collected

GATE Gateway National Recreation Area

GATE-0675ZZ Subcomponent Breakdown lteration Collected Concessi Jnpaved Total 5 Miles Mileage **Route Description** Area Route FMSS **Paved Unpaved Total** Class Cycle Collec FLTP (SQ FT) Number Number Miles **Route Name** То From 0675AZ 33660 6 2 MCNAIR ROAD FROM ROUTE 0665 (KEARNY DRIVE) TO ROUTE 0661AZ (HUDSON ROAD) YES 0.15 0.00 0.15 5 6 2 YES 5 0675BZ 33660 MCNAIR ROAD CUT-THRU B FROM ROUTE 0675AZ (MCNAIR ROAD) TO ROUTE 0665 (KEARNY DRIVE) 0.03 0.00 0.03 33660 2 YES 0.03 5 0675CZ 6 MCNAIR ROAD CUT-THRU C TO ROUTE 0674 (MERCER ROAD) 0.00 0.03 FROM ROUTE 0675AZ (MCNAIR ROAD)

GATE-0	GATE-0906ZZ Subcomponent Breakdown											
Route						Route Desc	ription	و ا	User	Area (SQ FT)		
Number	Number	ევ	≗°	ပိ	Route Name	From	То	E	Access	(302 FT)		
0906AZ	36107	6	2		JACOB RIIS PARKING A	FROM ROUTE 5003 (ROCKAWAY BEACH BOULEVARD)	TO ROUTE 0906BZ (JACOB RIIS PARKING B)	YES	PUBLIC	459,285		
0906BZ	36107	6	2		JACOB RIIS PARKING B	FROM ROUTE 0906AZ (JACOB RIIS PARKING A)	TO ROUTE 0906DZ (JACOB RIIS PARKING D)	YES	PUBLIC	421,175		
0906CZ	36107	6	2		JACOB RIIS PARKING C	FROM ROUTE 0906AZ (JACOB RIIS PARKING A)	TO ROUTE 0906EZ (JACOB RIIS PARKING E)	YES	PUBLIC	461,397		
0906DZ	36107	6	2		JACOB RIIS PARKING D	FROM ROUTE 0906BZ (JACOB RIIS PARKING B)	TO ROUTE 0906FZ (JACOB RIIS PARKING F)	YES	PUBLIC	436,725		
0906EZ	36107	6	2		JACOB RIIS PARKING E	FROM ROUTE 0906CZ (JACOB RIIS PARKING C)	TO ROUTE 5000 (ROCKAWAY POINT BOULEVARD)	YES	PUBLIC	529,252		
0906FZ	36107	6	2		JACOB RIIS PARKING F	FROM ROUTE 0906DZ (JACOB RIIS PARKING D)	TO ROUTE 5000 (ROCKAWAY POINT BOULEVARD)	YES	PUBLIC	334,148		

Page 9 of 11

Report Date: 09/22/2022

NPS / RIP Subcomponent Details for GATE

(Numerical By Summary Route and Subcomponent #)



User

Area

Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Paved Routes, Non-NPS	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon PKG = Parking Areas

NC = Not Collected

GATE **Gateway National Recreation Area**

GATE-0940ZZ Subcomponent Breakdown on ted ssion

Route	FMSS	a 2	atior lecte	cess		Route Desc	ription		User	Area
Number	Number	C CYe	Coll	Con	Route Name	From	То	FLTF	Access	(SQ FT)
0940AZ	25235	6	2		GREAT KILLS ENTRANCE PARKING A	ADJACENT TO ROUTE 0030 (BUFFALO ROAD) AT MP 0.05 ON LEFT		YES	PUBLIC	8,649
0940BZ	25235	6	2		GREAT KILLS ENTRANCE PARKING B	ADJACENT TO ROUTE 0030 (BUFFALO ROAD) AT MP 0.05 ON RIGHT		YES	PUBLIC	8,591

Route	FMSS	le ected	ation ected	cessio		Route Description		User	Area
Number	FMSS Number	C CYC	lter Coll	S Route Name	From	То	ЕГТЕ	Access	(SQ FT)
0955AAZ	33184	6	2	COAST GUARD ARE	A PARKING AAZ ADJACENT TO ROUTE 04 RIGHT	449 (COAST GUARD DRIVE) ON	YES	PUBLIC	7,021
0955ABZ	33184	6	2	COAST GUARD ARE	A PARKING ABZ ADJACENT TO ROUTE 04 RIGHT	449 (COAST GUARD DRIVE) ON	YES	PUBLIC	<i>7,77</i> 1
0955ACZ	33184	6	2	COAST GUARD ARE	A PARKING ACZ ADJACENT TO ROUTE 04 RIGHT	449 (COAST GUARD DRIVE) ON	YES	PUBLIC	10,178

GATE-0964ZZ Subcomponent Breakdown

Route	FMSS	le ected	ation lected	Icessic		Route Desc	ription		User	Area
Number	Number	Cycle Colle	ltero Coll	Con	Route Name	From	То	FLTE	Access	(SQ FT)
0964AAZ	36138	6	2		ENTRANCE AREA PARKING A	FROM ROUTE 0464 (AVIATION ROAD) ON RIGHT	TO ROUTE 0464 (AVIATION ROAD) ON RIGHT	YES	PUBLIC	16,877
0964ABZ	36138	6	2		ENTRANCE AREA PARKING B	FROM ROUTE 0464 (AVIATION ROAD) ON LEFT	TO ROUTE 0464 (AVIATION ROAD) ON LEFT	YES	PUBLIC	16,929

Page 10 of 11

Report Date: 09/22/2022

NPS / RIP Subcomponent Details for GATE

(Numerical By Summary Route and Subcomponent #)



Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Paved Routes, Non-NPS	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon PKG = Parking Areas NC = Not Collected

GATE Gateway National Recreation Area

GATE-0968AZZ Subcomponent Breakdown Route FMSS Paralle station Sollected Number Number Number Concessio User Area **Route Description** FLTP Access (SQ FT) **Route Name** То From 0968ABZ 31606 2 USPP PARKING NORTH FROM ROUTE 0201 (RANGER ROAD) TO PARKING YES PUBLIC 15,146 6 2 PUBLIC 0968ACZ 31606 USPP PARKING SOUTH YES 6 FROM ROUTE 0201 (RANGER ROAD) TO PARKING 3,585

GATE-0	GATE-0968EZZ Subcomponent Breakdown											
Route Number	FMSS Number	Cycle Collected	lteration Collected	Concessio	Route Name	Route Desc	ription To	FLTP	User Access	Area (SQ FT)		
0968EAZ	36374	6	2		NPS ENTERPRISE ROAD PARKING A	ADJACENT TO ROUTE 0203 (ENTERPRISE AVENUE) ON LEFT		YES	PUBLIC	5,110		
0968EBZ	36374	6	2		NPS ENTERPRISE ROAD PARKING B	ADJACENT TO ROUTE 0203 (ENTERPRISE AVENUE) ON LEFT		YES	PUBLIC	4,115		
0968ECZ	36374	6	2		NPS ENTERPRISE ROAD PARKING C	ADJACENT TO ROUTE 0203 (ENTERPRISE AVENUE) ON LEFT		YES	PUBLIC	1,331		

Page 11 of 11

Report Date: 09/22/2022

NPS / RIP Subcomponent Details for GATE

(Numerical By Summary Route and Subcomponent #)



Area

(SQ FT)

1,599

107,396

1,903

Shading Color Key	White = Paved Routes, DCV Driven	Grey = Paved Routes, DCV not Driven	Black = Paved Routes, Non-NPS	Concession Route
	Yellow = Unpaved Routes, DCV not Driven	Blue = Paved Parking Areas	Green = Unpaved Parking Areas	
				DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon PKG = Parking Areas

NC = Not Collected

GATE Gateway National Recreation Area

GATE-0999ZZ Subcomponent Breakdown lteration Collected Route FMSS _{ey} Number Number C S Concessi User **Route Description** FTP Access **Route Name** From То 0999AZ 112205 2 SILVER GULL BEACH CLUB PARKING A YES PUBLIC ADJACENT TO ROUTE 0234 (SILVER GULL BEACH CLUB 6 ENTRANCE ROAD) ON LEFT 0999BZ 112205 2 SILVER GULL BEACH CLUB PARKING B TO PARKING PUBLIC 6 FROM ROUTE 0234 (SILVER GULL BEACH CLUB YES ENTRANCE ROAD) ON RIGHT 0999CZ 112205 6 2 SILVER GULL BEACH CLUB PARKING C FROM ROUTE 0234 (SILVER GULL BEACH CLUB TO PARKING YES PUBLIC ENTRANCE ROAD) ON LEFT

GATE-1016ZZ Subcomponent Breakdown

Route	FMSS	le lected	ation lected	Icession		Route Description		User	Area	
Number	Number	C C	lter Coll	Con	Route Name	From	То	FLTI	Access	(SQ FT)
1016AZ	238264	6	2		RIIS LANDING PARKING A	FROM ROUTE 0987 (MAINTENANCE AREA PARKING (RIIS LDG))	TO PARKING	NO	NONPUBLIC	46,559
1016BZ	238264	6	2		RIIS LANDING PARKING B	FROM ROUTE 5000 (ROCKAWAY POINT BOULEVARD)	TO PARKING	NO	NONPUBLIC	42,384

GATE-	1042ZZ	Sul	bcoı	mp	onent Breakdown					
Route	FMSS	ചച	ation lected	Icessio		Koble Description		User	Area	
Number	Number	ပိုင်	Coll	Con	Route Name	From	То	FLTI	Access	(SQ FT)
1042AZ	256345	6	2		JABA PARKING A	FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)	TO ROUTE 1042BZ (JABA PARKING B)	NO	NONPUBLIC	295,165
1042BZ	256345	6	2		JABA PARKING B	FROM ROUTE 1042AZ (JABA PARKING A)	TO PARKING	NO	NONPUBLIC	187,684

	ROUTES REMOVED FROM PREVIOUS INVENTORY:					
Route No.	Route Name	Type of Change	Comments			
0488	SWINBURN PERIMETER ROAD	CLOSED/ABANDONED	ROAD REMOVED DURING ROUTE ID, INACTIVE IN FMSS. LOCATED ON ISLAND ADJACENT TO STATEN ISLAND.			
0490	ROAD IN FMSS. LOCATED ON ISLAND ADJAC		ROAD REMOVED DURING ROUTE ID, INACTIVE IN FMSS. LOCATED ON ISLAND ADJACENT TO STATEN ISLAND.			
0491	SERVICES ACCESS TO COMPLEX	CLOSED/ABANDONED	ROAD REMOVED DURING ROUTE ID.			
0909A	NIKE MISSILE SITE SILO AREA	CLOSED/ABANDONED	REMOVED FROM INVENTORY, PARK WILL CHANGE THE FACILITY TYPE.			
0912	FISHERMAN'S PARKING AREA "F"	CLOSED/ABANDONED	REMOVED. ROUTE IS A DUPLICATE OF ROUTE 1030.			
0950	RANGER STATION PARKING GOV	CLOSED/ABANDONED	REMOVED DURING ROUTE ID MEETING. ROUTE IS NO LONGER A PARKING AREA.			
0953B	NEW DORP HIGH SCHOOL PARKING B	CLOSED/ABANDONED	PARKING AREA COMBINED WITH ROUTE 0953A AND FORMER SEGMENT OF ROUTE 0132B.			
0955G	MALONY PARKING	CLOSED/ABANDONED	PARKING AREA REMOVED FROM INVENTORY, NO LONGER EXISTS.			
0963B	FWR BATTERY WEED AREA B PARKING	CLOSED/ABANDONED	REMOVED DURING ROUTE ID MEETING.			
0968AAZ	BUILDING 69 PARKING AREA	CLOSED/ABANDONED	PARKING LOT NO LONGER EXISTS AND BUILDING WAS DEMOLISHED.			
0968D	BUILDING 129 PARKING	CLOSED/ABANDONED	PARKING LOT REMOVED FROM INVENTORY; AREA IS GOING TO BE DEMOLISHED.			
0968G	NPS BUILDING 129 EAST AREA PARKING	CLOSED/ABANDONED	PARKING LOT REMOVED FROM INVENTORY; NO LONGER EXISTS.			
0995	PLUMB BEACH PARKING	CLOSED/ABANDONED	PARKING LOT REMOVED FROM INVENTORY; NOT MAINTAINED BY NPS.			
1010	MILLER FIELD HANGER 38 OVERFLOW PARKING	CLOSED/ABANDONED	PARKING LOT REMOVED DURING ROUTE ID. NO LONGER A PARKING AREA AND IS A CULTURAI LANDSCAPE AREA.			
1018	FORT TILDEN U.S. ARMY RESERVE PARKING	CLOSED/ABANDONED	PARKING LOT REMOVED DURING ROUTE ID MEETING; NPS NO LONGER MAINTAINS.			
1033	CROOKS POINT PARKING AREA	CLOSED/ABANDONED	REMOVED FROM RIP INVENTORY; DUPLICATE OF ROUTE 1005.			
1034	CROOKS POINT FISHING PARKING	CLOSED/ABANDONED	REMOVED FROM RIP INVENTORY; DUPLICATE OF ROUTE 1007.			

	ROUTE	CS ADDED FROM PREVI	OUS INVENTORY:
Route No.	Route Name	Type of Change	Comments
0500	CENTRAL RUNWAY	OTHER	NEW ROUTE ADDED AND EXTENDED TO INCLUDE PORTION OF ROUTE 0966.
0502	DOCK ROAD	OTHER	NEW ROUTE ADDED.
0953D	NEW DORP HIGH SCHOOL PARKING D	OTHER	PARKING AREA ADDED DURING ROUTE ID.
1035	BEACH 222ND STREET PARKING	OTHER	PARKING LOT ADDED DURING ROUTE ID MEETING.
1036	PARKING LOT M	OTHER	PARKING LOT ADDED DURING ROUTE ID MEETING.
5001	BEACH CHANNEL DRIVE	OTHER	NON-NPS ROAD ADDED AT ROUTE ID MEETING
5002	RIIS CIRCLE	OTHER	NON-NPS ROAD ADDED AT ROUTE ID MEETING
5003	ROCKAWAY BEACH BOULEVARD	OTHER	NON-NPS ROAD ADDED AT ROUTE ID MEETING
5004	MCCLEAN AVENUE	OTHER	NON-NPS ROAD ADDED AT ROUTE ID MEETING
5005N	CROSS BAY BOULEVARD (NORTHBOUND)	OTHER	NON-NPS ROAD ADDED AT ROUTE ID MEETING
5005S	CROSS BAY BOULEVARD (SOUTHBOUND)	OTHER	NON-NPS ROAD ADDED AT ROUTE ID MEETING
5006N	FLATBUSH AVENUE (NORTHBOUND)	OTHER	NON-NPS ROAD ADDED AT ROUTE ID MEETING
5006S	FLATBUSH AVENUE (SOUTHBOUND)	OTHER	NON-NPS ROAD ADDED AT ROUTE ID MEETING

	ROUTES MODIFIED FROM PREVIOUS INVENTORY:						
Route No. Route Name Type of Change Comments		Comments					
0063	NS FOUNTAIN AVENUE LANDFILL ACCESS ROADS	OTHER	NEW LENGTH COLLECTED IN CYCLE 6 AND SURFACE TYPE CHANGED FROM GRAVEL TO ASPHALT.				
0110	DAVIS ROAD	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS CHANGED FROM 2 TO 1.				

	ROUTES MODIFIED FROM PREVIOUS INVENTORY:					
Route No.	Route Name	Type of Change	Comments			
0111	SHORE ROAD	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS CHANGED FROM 2 TO 4.			
0132B	HOUSING ACCESS (SANCHEZ ROAD WEST)	LENGTH CHANGE	ROUTE LENGTH CHANGED FROM 0.34 TO 0.272.			
0162	HARTSHORNE DRIVE (SOUTHBOUND) RAMP L	SURFACE TYPE CHANGE	SURFACE TYPE CHANGED FROM ASPHALT TO CONCRETE.			
0163ZZ	RANGE ROADS	OTHER	ROUTE 0163 AND ROUTE 0217 COMBINED UNDEF ROUTE 0163ZZ AND FUNCTIONAL CLASS CHANGED FROM 2 TO 3.			
0200	FLOYD BENNETT FIELD ENTRANCE ROAD	ROUTE NAME	ROUTE NAME CHANGED FROM "FLOYD BENNETT DRIVE" TO "FLOYD BENNETT FIELD ENTRANCE ROAD".			
0211	SOUTH BARRETT ROAD	ROUTE NAME	NAME CHANGED FROM "BARRETT ROAD" TO "SOUTH BARRETT ROAD".			
0212	HEINZELMAN ROAD	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS CHANGED FROM 3 TO 1.			
0214	HAHN ROAD	OTHER	NAME CHANGED FROM "HAAN ROAD" TO "HAHN ROAD" AND FUNCTIONAL CLASS CHANGE FROM 3 TO 1.			
0227ZZ	ROMERO ROAD EAST AND WEST	OTHER	ROUTE SPLIT INTO SUBCOMPONENTS.			
0403	RUNWAY C	SURFACE TYPE CHANGE	SURFACE TYPE CHANGED FROM CONCRETE TO ASPHALT.			
0408	RUNWAY A (SOUTHERN RUNWAY)	ROUTE NAME	NAME CHANGED FROM "RUNWAY A" TO "RUNWAY A (SOUTHERN RUNWAY)".			
0440ZZ	NY AVENUE / BATTERY ROAD	ROUTE NAME	ROUTE SPLIT INTO SUBCOMPONENTS AND ROUTE NAME CHANGED FROM "NY AVENUE (W/ BATTERY ROAD)".			
0441	MONT SEC AVENUE	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS CHANGED FROM 5 TO 2.			
0445	HUDSON ROAD / STATEN ISLAND	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS CHANGED FROM 5 TO 2.			
0446	BATTERY WEED ROAD	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS CHANGED FROM 5 TO 2.			
0453	USS NORTH CAROLINA ROAD	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS CHANGED FROM 5 TO 3.			

Route No.	Route Name	Type of Change	Comments
0460	NORTH MAINTENANCE AREA ACCESS ROAD	ROUTE NAME	ROUTE NAME CHANGED FROM "FORD ROAD NORTH MAINTENANCE AREA ACCESS" TO " NORTH MAINTENANCE AREA ACCESS ROAD".
0464	AVIATION ROAD	LENGTH CHANGE	ROUTE LENGTH CHANGED SINCE ACCESS PORTION OF ROAD CHANGED.
0470	JACOB RIIS SERVICE ROAD	SURFACE TYPE CHANGE	SURFACE TYPE CHANGED FROM ASPHALT TO CONCRETE.
0473	HARBOR ROAD	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS CHANGED FROM 5 TO 6.
0474ZZ	MILLER FIELD RESIDENCE ROAD	OTHER	ROUTE NAME CHANGED FROM "MILLER FIELD RESIDENCE LOOP" TO ALIGN WITH FMSS. ROUTE SPLIT INTO SUBCOMPONENTS TO CAPTURE MULTIPLE SEGMENTS OF THE SHAPE.
0477ZZ	NIKE RADAR SITE ROADS	OTHER	MINOR NAME CHANGE FROM "NIKE RADAR SITE" TO "NIKE RADAR SITE ROADS". ROUTE SPLIT INTO SUBCOMPONENTS TO CAPTURE MULTIPLE SEGMENTS OF THE SHAPE.
0479	FISHERMAN'S PARKING ACCESS	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS CHANGED FROM 5 TO 2.
0480	SERVICE ROAD / KINGMAN AND MILLS ROAD	ROUTE NAME	ROUTE NAME CHANGED FROM "SERVICE ROAD" TO "SERVICE ROAD / KINGMAN AND MILLS ROAD"
0483ZZ	SOUTH MAINTENANCE SHOP ROAD C	OTHER	ROUTE SPLIT INTO SUBCOMPONENTS TO CAPTURE MULTIPLE SEGMENTS OF THE SHAPE.
0504ZZ	SOUTHERN RUNWAY	OTHER	ROUTE SPLIT INTO SUBCOMPONENTS TO CAPTURE MULTIPLE SEGMENTS OF THE SHAPE.
0505	MAINTENANCE GAS STATION ROAD	ROUTE NAME	ROUTE NAME CHANGED FROM "MAINTENANCI GAS STATION PARKING".
0661ZZ	HUDSON ROADS	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS UPDATED FROM 5 TO 2.
0662ZZ	MAGRUDER ROADS	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS UPDATED FROM 5 TO 2.
0663	PENNINGTON STREET	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS UPDATED FROM 5 TO 2.
0665	KEARNY DRIVE	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS UPDATED FROM 5 TO 2.

	ROUTES	MODIFIED FROM PRE	VIOUS INVENTORY:
Route No.	Route Name	Type of Change	Comments
0668	SOUTH BRAGG DRIVE	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS UPDATED FROM 5 TO 2.
0669	KNOX ROAD NORTH	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS UPDATED FROM 5 TO 2.
0671	NEW GUNNISON ROAD	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS UPDATED FROM 5 TO 2.
0672	FORD ROAD	FUNCTIONAL CLASS CHANGE	FUNCTIONAL CLASS UPDATED FROM 5 TO 2.
0674	MERCER ROAD	LENGTH CHANGE	ROUTE SHORTENED DURING ROUTE ID MEETING; PORTION COMBINED UNDER ROUTE 0925.
0905	SANDY HOOK VISITOR CENTER PARKING	SQ FEET CHANGE	GEOMETRY/GPS ADJUSTED.
0906ZZ	JACOB RIIS PARKING	ROUTE SPLIT	ROUTE SPLIT INTO SUBCOMPONENTS TO IMPROVE THE GEOMETRY/MAPPING.
0911	MISSILE PARKING LOT	OTHER	ROUTE NAME CHANGED FROM "MISSILE / N PARKING" TO "MISSILE PARKING LOT". USER ACCESS UPDATED FROM NON-PUBLIC TO PUBLIC.
0914	LOT "H" CAMPGROUND PARKING	ROUTE NAME	ROUTE NAME CHANGED FROM "LOT "H" HORSESHOE COVE PARKING" TO "LOT "H" CAMPGROUND PARKING".
0920	MARINE ACADEMY CAFETERIA #77 PARKING	OTHER	UPDATED USER ACCESS FROM PUBLIC TO NONPUBLIC.
0921	MAST PARKING LOT "N"	OTHER	ROUTE NAME CHANGED FROM "MARINE ACADEMY OF SCIENCES AND TECHNOLOGY PARKING" TO "MAST PARKING LOT "N"". USER ACCESS CHANGED FROM PUBLIC TO NONPUBLIC.
0922	MAST SCHOOL OFFICES TEACHERS PARKING	OTHER	UPDATED USER ACCESS FROM PUBLIC TO NONPUBLIC.
0927	BUILDING 32 PARK RANGER PARKING	OTHER	UPDATED USER ACCESS FROM PUBLIC TO NONPUBLIC.
0933	FEE COLLECTORS PARKING	OTHER	UPDATED USER ACCESS FROM PUBLIC TO NONPUBLIC.
0942	GK AREA "A" PARKING	ROUTE NAME	ROUTE NAME CHANGE FROM "AREA "A" PARKING" TO "GK AREA "A" PARKING"

	ROUTES MODIFIED FROM PREVIOUS INVENTORY:					
Route No.	Route Name	Type of Change	Comments			
0943	BOAT LAUNCH PARKING	SQ FEET CHANGE	GEOMETRY/GPS ADJUSTED			
0944	GK AREA "E" PARKING	ROUTE NAME	ROUTE NAME CHANGE FROM "AREA "E" PARKING" TO "GK AREA "E" PARKING"			
0945	GK AREA "F" PARKING	ROUTE NAME	ROUTE NAME CHANGE FROM "AREA "F" PARKING" TO "GK AREA "F" PARKING"			
0948	MILLER FIELD PARKING LOT (BALL FIELD)	ROUTE NAME	ROUTE NAME CHANGED FROM "MILLER FIELD ENTRANCE PARKING" TO "MILLER FIELD PARKING LOT (BALL FIELD)"			
0951	CIRCLE PARKING	SQ FEET CHANGE	GEOMETRY/GPS ADJUSTED			
0956A	DRUM AVENUE PARKING A	SQ FEET CHANGE	GEOMETRY/GPS ADJUSTED			
0957C	HQ B210 PARKING	ROUTE NAME	ROUTE NAME CHANGED FROM "Q B210 PARKING" TO "HQ B210 PARKING".			
0959B	FORT WADSWORTH BUILDING 109 PARKING	SQ FEET CHANGE	GEOMETRY/GPS ADJUSTED			
0961A	ARMED FORCES RESERVE AREA PARKING	SQ FEET CHANGE	GEOMETRY/GPS ADJUSTED TO ADD CONCRETE PORTION.			
0962B	FWR CAMPGROUND PARKING AREA	ROUTE NAME	ROUTE NAME CHANGED FROM "FWR PICNIC PARKING AREA" TO "FWR CAMPGROUND PARKING AREA".			
0965B	RYAN VISITOR CENTER PARKING SE	ROUTE NAME	ROUTE NAME CHANGED FROM "RYAN CENTER PARKING SE" TO "RYAN VISITOR CENTER PARKING SE".			
0965E	HANGAR 3 AND 4 PARKING AREA	OTHER	GEOMETRY/GPS ADJUSTED AND SURFACE TYPE CHANGED FROM ASPHALT TO BRICK.			
0966	MODEL AIRPLANE FIELD PARKING	OTHER	GEOMETRY/GPS ADJUSTED AND SURFACE TYPE CHANGED FROM CONCRETE TO ASPHALT.			
0971	TYLUNAS HALL PARKING (NYC COLLECTION)	SQ FEET CHANGE	GEOMETRY/GPS ADJUSTED. PART OF THIS PARKING LOT IS NOW 1042ZZ.			
0975	AREA D BEACH CENTER PARKING	SQ FEET CHANGE	GEOMETRY/GPS ADJUSTED			
0983C	BUILDING 1 NORTHSIDE PARKING AREA C	ROUTE NAME	ROUTE NAME CHANGE FROM "BUILDING 1 NORTHSIDE PARKING AREA B" TO "BUILDING 1 NORTHSIDE PARKING AREA C".			

	ROUTES MODIFIED FROM PREVIOUS INVENTORY:					
Route No.	Route Name	Type of Change	Comments			
0987	MAINTENANCE AREA PARKING (RIIS LDG)	SURFACE TYPE CHANGE	SURFACE TYPE CHANGED FROM ASPHALT TO CONCRETE.			
0993	PARKING LOT E	ROUTE NAME	ROUTE NAME CHANGED FROM "CDR PARKING E" TO "PARKING LOT E".			
1004	PICNIC/BEACH AREA PARKING LOT E	ROUTE NAME	ROUTE NAME CHANGED FROM "PICNIC AREA PARKING E" TO "PICNIC/BEACH AREA PARKING LOT E".			
1020	NYPD PARKING 1	ROUTE NAME	NAME CHANGE FROM "NYPD PARKING 1 WEST" TO "NYPD PARKING 1".			
1023	NYPD PARKING 4	SQ FEET CHANGE	GEOMETRY/GPS ADJUSTED			
1024	NYPD PARKING 5	SQ FEET CHANGE	GEOMETRY/GPS ADJUSTED			
1025	PENNSYLVANIA AVENUE LANDFILL PARKING	SURFACE TYPE CHANGE	SURFACE TYPE UPDATED FROM GRAVEL TO ASPHALT.			
1026	FOUNTAIN AVENUE LANDFILL	SURFACE TYPE CHANGE	SURFACE TYPE UPDATED FROM GRAVEL TO ASPHALT.			
1028	NC-S RIDING ACADEMY PARKING LOT	ROUTE NAME	ROUTE NAME CHANGED FROM "NC-S RIDING ACADEMY PARKING" TO "NC-S RIDING ACADEMY PARKING LOT"			
1037	NOAA SERVICE PARKING LOT	OTHER	CHANGED FROM ROAD TO PARKING; FORMERLY ROUTE 0478. NAME CHANGED FROM "NOAA SERVICE ROAD" TO "NOAA SERVICE PARKING LOT".			
1042ZZ	JABA PARKING	ROUTE SPLIT	ROUTE SPLIT INTO SUBCOMPONENTS. FORMERLY PART OF ROUTE 0971			
5000	ROCKAWAY POINT BOULEVARD	ROUTE NAME	NAME CHANGED FROM "ROCKAWAY POINT BOULEVARD/BEACH CHANNEL DRIVE" TO "ROCKAWAY POINT BOULEVARD".			

Section 3 Park Summary Information



Gateway National Recreation Area



Parkwide Paved Route Condition Summary Gateway National Recreation Area

Table 1: Paved Route Miles and Parking Area Square Footages by Access Level and PCR

	POOR (PCR of 0 - 60)	FAIR (PCR of 61 - 84)	GOOD (PCR of 85 - 94)	EXCELLENT (PCR of 95 -100)	
		PAVED	ROADS		
Functional Class	Length (miles)	Length (miles)	Length (miles)	Length (miles)	Total Mileage by FC
1	3.22	3.97	3.25	3.34	13.78
2	2.99	1.21	1.04	2.09	7.33
3	2.44	0.95	0.52	1.08	4.99
4		0.26			0.26
5	9.48	2.69	0.58	0.45	13.20
6	0.25	0.02			0.27
7					
8					
Total Mileage by PCR	18.38	9.11	5.39	6.96	39.84
		PAVED P	ARKING		
Access Level	Area (sq. ft.)	Area (sq. ft.)	Area (sq. ft.)	Area (sq. ft.)	Total Area
PUBLIC	1,458,884	1,890,159	5,103,436	481,096	8,933,575
NONPUBLIC	728,640	211,582	84,333	195,529	1,220,084
Total Area by PCR	2,187,524	2,101,741	5,187,769	676,625	10,153,659


Breakdown of Pavement Condition Rating (PCR) Based on Access Level

NOTES:

1. Data are reported in the table only for paved roads and parking lots that received a condition rating.

2. Non-linear roads (MRP collected routes) are measured by area and converted to equivalent route miles based on a 22-ft pavement width in order to be included in the mileage totals for paved roads shown above.


3. Quantities in the table above are derived from the route condition data within the PMS_20, PMS_MRL, PMS_MRP, and PMS_PKG tables in the Park geodatabase.



Parkwide Condition Percentages

Road Condition Percentages


Parking Area Condition Percentages



Explanation of the Excellent, Good, Fair, and Poor Condition Descriptions

The Road Inventory Program aims to provide assistance in translating the excellent / good / fair / poor rating categories into pavement needs categories. The PCR can be used to indicate the place in the Pavement Life Cycle and the type of treatments that should be considered now and into the future.

- Excellent / New: PCR of 95-100
 - o Pavements in this range will require only spot repairs
- Good: PCR of 85-94
 - o Pavements in this range will likely be candidates for Preventive Maintenance. Examples include Chip and Slurry Seals, Micro Surfacing and Thin Overlays.
- Fair: PCR of 61-84
 - o Pavements in this range will likely be candidates of Light Rehabilitation (L3R). Examples include singlelift overlays up to 2.5 inches in total thickness, milling and overlays.
- Poor: PCR of 0-60
 - o Pavements in this range will likely be candidates of Heavy Rehabilitation or Reconstruction (H3R or 4R). Examples include Pulverization, Multiple Lift Overlays, and Reconstruction.



CONDITION CATEGORIES AND TREATMENTS

At this time, specific Maintenance and Rehabilitation activities should be evaluated and recommended at the project level. Site-specific conditions that influence treatment type should be determined based on performing a subsurface investigation and/or pavement condition survey, and not be based solely on RIP data. Additionally, RIP produces a snapshot of conditions at the time in which the data were collected. For further information or to obtain additional Pavement Management System's data from our Highway Pavement Management Application (HPMA) please contact the Eastern Federal Lands pavement team.



Road Condition Summary Report for Data Collection Vehicle (DCV) Rated Roads

Gateway National Recreation Area

Condition (Rating / Index) Legend

EXCELLENT (95 - 100)
GOOD (85 - 94)
FAIR (61 - 84)
POOR (0 - 60)
NR = NOT RATED

Notes:

- Condition on roads that were manually rated and parking areas are shown in separate reports.
- Route-level scores shown on this page may not represent scores at smaller intervals (due to rollup calculations).
- Additional details on individual road ratings at 0.10-mile and 1-mile intervals can be found in Section 5 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

Route No.	<u>Route-</u> FMSS No.	Level Condition for Roads Rated with the Data Collectio Route Name	<u>n Vehicle (DCV)</u> Functiona Class	l Surf. Type	Paved Length (Miles)	vement Cond ting (PCR)	Roughness Condition Index (RCI)	Surface Condition Rating (SCR)	Structural Crack Index	<u> </u>	Longitudinal Cracking Index	Transverse Cracking Index	Patch / Pothole Index	Rutting Index
GATE-0030	21206	BUFFALO ROAD	1	AS	1.75	64	87	48	69	100	69	48	100	98
GATE-0060	29627	HARTSHORNE DRIVE (NORTHBOUND)	1	AS	5.28	82	88	78	78	100	78	79	100	98
GATE-0061	29628	HARTSHORNE DRIVE (SOUTHBOUND)	1	AS	3.75	89	100	82	89	100	89	82	100	99
GATE-0063	112826	NS FOUNTAIN AVENUE LANDFILL ACCESS ROADS	1	AS	0.18	96	NR	96	100	100	100	100	100	96
GATE-0110	36000	DAVIS ROAD	1	CO	0.50	73	NR	NR	NR	NR	NR	NR	NR	NR
GATE-0111	31597	SHORE ROAD	4	CO	0.26	73	NR	NR	NR	NR	NR	NR	NR	NR
GATE-0130	21211	MILLER FIELD ENTRANCE ROAD	2	AS	0.38	0	NR	0	0	91	0	17	100	92
GATE-0132A	21212	VISITOR CENTER (SANCHEZ ROAD EAST)	2	AS	0.20	59	NR	59	88	100	88	59	100	96
GATE-0132B	21213	HOUSING ACCESS (SANCHEZ ROAD WEST)	2	AS	0.27	85	NR	85	100	100	100	85	100	100
GATE-0160	29629	ATLANTIC DRIVE	2	AS	1.91	95	90	99	100	100	100	100	100	99
GATE-0161	N/A	HARTSHORNE DRIVE (SOUTHBOUND) RAMP K	2	AS	0.29	6	NR	6	6	100	6	9	100	97
GATE-0162	N/A	HARTSHORNE DRIVE (SOUTHBOUND) RAMP L	2	CO	0.18	97	NR	NR	NR	NR	NR	NR	NR	NR
GATE-0163AZ	36014	RANGE ROAD	3	CO	0.21	73	NR	NR	NR	NR	NR	NR	NR	NR
GATE-0200	31602	FLOYD BENNETT FIELD ENTRANCE ROAD	1	AS	1.30	69	64	72	82	100	82	72	100	96
GATE-0201	31604	RANGER ROAD	3	AS	0.56	21	NR	21	23	96	27	21	97	95
GATE-0203	31603	ENTERPRISE AVENUE	3	AS	0.15	20	NR	20	65	100	65	20	98	99
GATE-0206	36006	TAXIWAY C ACCESS ROAD	3	AS	0.10	17	NR	17	24	100	24	17	100	96
GATE-0211	36007	SOUTH BARRETT ROAD	3	AS	0.17	53	NR	88	NR	NR	NR	NR	NR	NR
GATE-0212	36008	HEINZELMAN ROAD	1	AS	0.12	0	NR	0	38	95	43	0	99	86



Road Condition Summary Report for Data Collection Vehicle (DCV) Rated Roads

Gateway National Recreation Area

Condition (Rating / Index) Legend

EXCELLENT (95 - 100)
GOOD (85 - 94)
FAIR (61 - 84)
POOR (0 - 60)
NR = NOT RATED

Notes:

- Condition on roads that were manually rated and parking areas are shown in separate reports.
- Route-level scores shown on this page may not represent scores at smaller intervals (due to rollup calculations).
- Additional details on individual road ratings at 0.10-mile and 1-mile intervals can be found in Section 5 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

Route No.	<u>Route-</u> FMSS No.	Level Condition for Roads Rated with the Data Collection Vehic Route Name	<u>le (DCV)</u> Functiona Class	ıl Surf. Type	Paved Length (Miles)	Pavement Condition Rating (PCR)	Roughness Condition Index (RCI)	Surface Condition Rating (SCR)	Structural Crack Index	Alligator Crack Index	Longitudinal Cracking Index	Transverse Cracking Index	Patch / Pothole Index	Rutting Index
GATE-0213	36009	WORCESTER ROAD	3	AS	0.08	0	NR	0	0	80	8	32	99	93
GATE-0214	31600	HAHN ROAD	1	AS	0.29	0	NR	0	15	99	16	0	99	94
GATE-0215	36011	ATHLETIC DRIVE	3	AS	0.10	36	NR	36	66	100	66	36	99	96
GATE-0216	31596	HERO ROAD	3	AS	0.36	29	NR	29	76	100	76	29	99	98
GATE-0222	36015	BREEZY POINT SURF CLUB ENTRANCE ROAD	3	AS	0.38	93	NR	93	100	100	100	98	100	93
GATE-0224	36017	BEACH 193RD STREET	3	AS	0.20	51	NR	51	61	100	61	51	100	97
GATE-0228	36022	THEATER ROAD	3	AS	0.19	13	NR	13	54	100	54	13	100	95
GATE-0234	112212	SILVER GULL BEACH CLUB ENTRANCE ROAD	3	AS	0.19	1	NR	1	33	100	33	1	97	91
GATE-0235	112714	ROCKAWAY POINT YACHT CLUB ROAD	3	AS	0.26	51	NR	51	77	98	79	51	100	93
GATE-0403	36027	RUNWAY C	5	AS	1.10	23	NR	NR	NR	NR	NR	NR	NR	NR
GATE-0405	36028	TAXIWAY B	5	AS	0.50	31	34	29	30	100	30	29	98	91
GATE-0406	36029	ΤΑΧΙΨΑΥ Α	5	CO	0.69	73	NR	NR	NR	NR	NR	NR	NR	NR
GATE-0408	36030	RUNWAY A (SOUTHERN RUNWAY)	5	AS	1.09	42	63	28	28	100	28	48	100	80
GATE-0410	36031	TAXIWAY C	5	AS	0.35	26	NR	26	26	100	26	51	100	94
GATE-0439	21204	PATH ROAD (NAVY LODGE)	5	AS	0.09	44	NR	44	44	100	44	59	99	87
GATE-0440AZ	21182	NY AVENUE	1	AS	0.40	52	NR	52	52	99	53	76	100	98
GATE-0440BZ	21182	BATTERY ROAD	1	AS	0.25	41	NR	41	41	100	41	49	99	97
GATE-0441	21181	MONT SEC AVENUE	2	AS	0.14	69	NR	69	69	100	69	89	100	98
GATE-0443	21185	SOUTH ROAD	5	AS	0.14	82	NR	82	87	99	88	82	100	95



Road Condition Summary Report for Data Collection Vehicle (DCV) Rated Roads

Gateway National Recreation Area

Condition (Rating / Index) Legend

EXCELLENT (95 - 100)
GOOD (85 - 94)
FAIR (61 - 84)
POOR (0 - 60)
NR = NOT RATED

Notes:

- Condition on roads that were manually rated and parking areas are shown in separate reports.
- Route-level scores shown on this page may not represent scores at smaller intervals (due to rollup calculations).
- Additional details on individual road ratings at 0.10-mile and 1-mile intervals can be found in Section 5 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

Route No.	<u>Route-</u> FMSS No.	Level Condition for Roads Rated with the Data Collection Ve Route Name	hicle (DCV) Functione Class	ıl Surf. Type	Paved Length (Miles)	Pavement Condition Rating (PCR)	Roughness Condition Index (RCI)	Surface Condition Rating (SCR)	Structural Crack Index	Alligator Crack Index	Longitudinal Cracking Index	Transverse Cracking Index	Patch / Pothole Index	Rutting Index
GATE-0445	21180	HUDSON ROAD / STATEN ISLAND	2	AS	0.53	8	21	0	0	90	0	0	100	91
GATE-0446	21178	BATTERY WEED ROAD	2	AS	0.44	0	NR	0	0	81	9	9	99	84
GATE-0447	21192	TOMPKINS ROAD	5	AS	0.15	0	NR	0	32	98	34	0	99	89
GATE-0448	21191	MARSHALL ROAD	5	AS	0.24	0	NR	0	0	39	0	0	100	91
GATE-0449	21187	COAST GUARD DRIVE	5	AS	0.38	0	NR	0	0	92	0	0	99	88
GATE-0450	21189	DRUM AVENUE	5	AS	0.21	0	NR	0	0	54	0	0	100	90
GATE-0451	21188	MOLONY DRIVE	5	AS	0.07	26	NR	26	35	100	35	26	100	97
GATE-0452	21193	USS NEW MEXICO COURT	5	AS	0.09	0	NR	0	0	86	0	0	100	95
GATE-0453	21197	USS NORTH CAROLINA ROAD	3	AS	0.74	94	NR	31	NR	NR	NR	NR	NR	NR
GATE-0454	21202	USS CONNECTICUT COURT	5	AS	0.14	28	NR	28	49	97	52	28	94	94
GATE-0455	21201	USS ARIZONA LANE	5	AS	0.03	8	NR	8	12	84	28	8	98	99
GATE-0456	21200	USS IOWA CIRCLE	5	AS	0.24	0	NR	0	0	87	0	0	93	93
GATE-0457	21199	USS MISSOURI LANE	5	AS	0.04	0	NR	0	0	60	0	0	99	94
GATE-0458	21196	USS TENNESSEE ROAD	5	AS	0.23	4	NR	0	0	84	0	0	99	93
GATE-0459	21198	USS FLORIDA COURT	5	AS	0.17	0	NR	0	0	75	0	0	98	88
GATE-0460	29987	NORTH MAINTENANCE AREA ACCESS ROAD	5	AS	0.14	0	NR	0	0	96	0	2	95	89
GATE-0462	29993	RANDOLPH ROAD	5	AS	0.26	12	NR	12	12	57	55	68	100	79
GATE-0464	31605	AVIATION ROAD	5	AS	0.39	50	NR	23	39	96	43	23	98	96
GATE-0465	36037	BUILDING 272 ACCESS ROAD	5	AS	0.18	23	NR	23	36	99	37	23	99	87



Road Condition Summary Report for Data Collection Vehicle (DCV) Rated Roads

Gateway National Recreation Area

Condition (Rating / Index) Legend

EXCELLENT (95 - 100)
GOOD (85 - 94)
FAIR (61 - 84)
POOR (0 - 60)
NR = NOT RATED

Notes:

- Condition on roads that were manually rated and parking areas are shown in separate reports.
- Route-level scores shown on this page may not represent scores at smaller intervals (due to rollup calculations).
- Additional details on individual road ratings at 0.10-mile and 1-mile intervals can be found in Section 5 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

Route No.	<u>Route-</u> FMSS No.	Level Condition for Roads Rated with the Data Collection N	<mark>/ehicle (DCV)</mark> Functiona Class	l Surf. Type	Paved Length (Miles)	Pavement Condition Rating (PCR)	Roughness Condition Index (RCI)	Surface Condition Rating (SCR)	Structural Crack Index	Alligator Crack Index	Longitudinal Cracking Index	Transverse Cracking Index	Patch / Pothole Index	Rutting Index
GATE-0470	36038	JACOB RIIS SERVICE ROAD	5	CO	0.32	61	NR	61	64	100	64	61	100	92
GATE-0479	30018	FISHERMAN'S PARKING ACCESS	2	AS	0.24	21	NR	21	56	100	56	21	100	98
GATE-0497	115727	NYPD ROAD 1	6	AS	0.12	21	NR	21	21	100	21	69	100	97
GATE-0498	115728	NYPD ROAD 2	6	AS	0.09	13	NR	13	13	100	13	48	98	97
GATE-0500	245335	CENTRAL RUNWAY	5	AS	0.95	25	63	0	0	94	0	0	97	92
GATE-0502	245349	DOCK ROAD	2	AS	0.03	16	NR	16	45	100	45	16	100	98
GATE-0504AZ		SOUTHERN RUNWAY A	5	AS	0.44	47	NR	47	60	100	60	47	100	95
GATE-0504BZ		SOUTHERN RUNWAY B	5	AS	0.51	7	17	0	0	99	0	0	26	93
GATE-0657	33631	HANAKI ROAD	5	AS	0.07	52	NR	52	93	100	93	52	100	95
GATE-0658	33632	KILPATRICK ROAD	5	AS	0.27	46	NR	46	78	100	78	46	98	95
GATE-0659	33638	OLD TRAILER CAMP LANE MAST	5	AS	0.13	95	NR	95	97	100	97	95	99	98
GATE-0660	33646	CANFIELD ROAD	5	AS	0.21	20	NR	20	58	100	58	20	99	97
GATE-0661AZ	33647	HUDSON ROAD	2	AS	0.66	89	77	97	98	100	98	98	99	97
GATE-0662AZ	33648	MAGRUDER ROAD	2	AS	0.45	28	NR	28	49	100	49	28	96	95
GATE-0663	33649	PENNINGTON STREET	2	AS	0.14	16	NR	16	33	96	37	16	100	96
GATE-0664	33650	KESSLER ROAD	5	AS	0.48	12	NR	12	32	92	40	12	98	81
GATE-0665	33651	KEARNY DRIVE	2	AS	0.53	80	55	97	99	100	99	99	100	97
GATE-0666	33652	LAWSON LANE	5	AS	0.07	97	NR	97	99	100	99	97	100	98
GATE-0668	33654	SOUTH BRAGG DRIVE	2	AS	0.29	0	NR	0	0	99	0	0	99	92



Road Condition Summary Report for Data Collection Vehicle (DCV) Rated Roads

Gateway National Recreation Area

Condition (Rating / Index) Legend

EXCELLENT (95 - 100)
GOOD (85 - 94)
FAIR (61 - 84)
POOR (0 - 60)
NR = NOT RATED

Notes:

- Condition on roads that were manually rated and parking areas are shown in separate reports.
- Route-level scores shown on this page may not represent scores at smaller intervals (due to rollup calculations).
- Additional details on individual road ratings at 0.10-mile and 1-mile intervals can be found in Section 5 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

Route No.	<u>Route-</u> FMSS No.	Level Condition for Roads Rated with the Data Collection Vehicle Route Name	<u>e (DCV)</u> Functiona Class	al Surf. Type	Paved Length (Miles)	Pavement Condition Rating (PCR)	Roughness Condition Index (RCI)	Surface Condition Rating (SCR)	Structural Crack Index	Alligator Crack Index	Longitudinal Cracking Index	Transverse Cracking Index	Patch / Pothole Index	Rutting Index
GATE-0669	33655	KNOX ROAD NORTH	2	AS	0.12	55	NR	55	73	100	73	55	100	97
GATE-0670	33656	OLD GUNNISON ROAD/MAST WAY	5	AS	0.15	100	NR	100	100	100	100	100	100	100
GATE-0671	33657	NEW GUNNISON ROAD	2	AS	0.28	44	NR	44	69	100	69	44	99	97
GATE-0672	33658	FORD ROAD	2	AS	0.11	89	NR	89	100	100	100	89	100	100
GATE-0674	33659	MERCER ROAD	5	AS	0.11	23	NR	23	59	100	59	23	100	97
GATE-0675AZ	33660	MCNAIR ROAD	5	AS	0.15	0	NR	0	7	97	10	0	100	97



Cycle 6 - Road Inventory Program Road Condition Summary Report for

Manually Rated Roads

Gateway National Recreation Area

Notes:

- This condition summary report contains only the roads that were manually rated.
 - MRL: Manually Rated Line (a linear road)
 - MRP: Manually Rated Polygon (a non-linear road)
- Condition on roads that were rated with the Data Collection Vehicle (DCV) are shown in a separate report.
- A road is manually rated when it is determined to be unsuitable for the DCV to drive.
- Additional details on individual road ratings at 0.10-mile and 1-mile intervals can be found in Section 5 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

Route No.	FMSS No.	Route-Level Condition for Manually Rated Line (MRL) Roads	Functiona Class	Surf. Type	Paved Length (Miles)	3 🕤	Roughness Condition Index (RCI)	Surface Condition Rating (SCR)	Structural Crack Index	Alligator Crack Index	Longitudinal Cracking Index	Transverse Cracking Index	Patch / Pothole Index	Rutting Index
GATE-0163BZ	36014	BPD RANGE ROAD	3	AS	0.76	30	NR	30	NR	30	53	53	73	90
GATE-0205	36005	RIDING ACADEMY ACCESS ROAD	3	AS	0.20	97	NR	97	NR	97	97	97	97	97
GATE-0225	36019	POST OFFICE ROAD	3	CO	0.04	90	NR	90	NR	NR	NR	NR	NR	NR
GATE-0226	36020	NORTH BARETTE	3	CO	0.07	73	NR	73	NR	NR	NR	NR	NR	NR
GATE-0227AZ	36021	ROMERO ROAD WEST	3	CO	0.03	90	NR	90	NR	NR	NR	NR	NR	NR
GATE-0227BZ	36021	ROMERO ROAD EAST	3	CO	0.03	90	NR	90	NR	NR	NR	NR	NR	NR
GATE-0229	36023	CHAPEL ROAD	3	AS	0.06	30	NR	30	NR	30	90	90	97	97
GATE-0230	31599	STEELE ROAD	3	AS	0.05	73	NR	73	NR	97	90	73	90	97
GATE-0402	36026	COMMUNITY GARDEN ACCESS ROAD	5	AS	0.24	53	NR	53	NR	53	90	90	97	97
GATE-0415	36034	NIKE MAINTENANCE ROAD	5	AS	0.18	53	NR	53	NR	53	73	73	90	90
GATE-0419	36035	JAMAICA BAY RESIDENCE ROAD	5	AS	0.02	73	NR	73	NR	73	90	90	90	97
GATE-0437	21210	ACCESS TO ATHLETIC FIELD ROAD	5	AS	0.89	NR	NR	NR	NR	NR	NR	NR	NR	NR
GATE-0438	21203	AYERS ROAD	5	AS	0.31	30	NR	30	NR	30	73	73	73	90
GATE-0442	21184	NORTH ROAD	5	AS	0.14	90	NR	90	NR	97	90	90	97	97
GATE-0444	21186	CLIFTON ROAD	5	AS	0.07	90	NR	90	NR	97	90	90	97	97
GATE-0461	29990	SAND SHED ROAD	5	CO	0.08	90	NR	90	NR	NR	NR	NR	NR	NR
GATE-0471	21195	LOOP ROAD	5	AS	0.14	30	NR	30	NR	30	73	73	90	97
GATE-0472	21194	RANGE ROAD (STATEN ISLAND)	5	AS	0.08	97	NR	97	NR	NR	NR	NR	NR	NR
GATE-0473	33207	HARBOR ROAD	6	AS	0.22	NR	NR	NR	NR	NR	NR	NR	NR	NR
GATE-0474AZ	33210	MILLER FIELD RESIDENCE ROAD A	5	AS	0.07	73	NR	73	NR	73	90	90	90	97
GATE-0474BZ	33210	MILLER FIELD RESIDENCE ROAD B	5	AS	0.03	90	NR	90	NR	90	97	90	90	97

EXCELLENT (95 - 100)	
GOOD (85 - 94)	
FAIR (61 - 84)	
POOR (0 - 60)	
NR = NOT RATED	



Cycle 6 - Road Inventory Program Road Condition Summary Report for

Manually Rated Roads

Gateway National Recreation Area

Notes:

- This condition summary report contains only the roads that were manually rated.
 - MRL: Manually Rated Line (a linear road)
 - MRP: Manually Rated Polygon (a non-linear road)
- Condition on roads that were rated with the Data Collection Vehicle (DCV) are shown in a separate report.
- A road is manually rated when it is determined to be unsuitable for the DCV to drive.
- Additional details on individual road ratings at 0.10-mile and 1-mile intervals can be found in Section 5 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

Route No.	FMSS No.	Route-Level Condition for Manually Rated Line (MRL) Roads	Functione Class	ıl Surf. Type	Paved Length (Miles)	ent Cor (PCR)	e ž	Surface Condition Rating (SCR)	Structural Crack Index	Alligator Crack Index	Longitudinal Cracking Index	Transverse Cracking Index	Patch / Pothole Index	Rutting Index
GATE-0474CZ	33210	MILLER FIELD RESIDENCE ROAD C	5	AS	0.11	73	NR	73	NR	73	90	90	97	97
GATE-0475	36039	DAVIS ACCESS ROAD	5	СО	0.04	90	NR	90	NR	NR	NR	NR	NR	NR
GATE-0476	30000	CAMPSITE ROAD	3	AS	0.17	73	NR	73	NR	73	73	73	97	97
GATE-0477AZ	30011	NIKE RADAR SITE ROAD A	5	AS	0.24	53	NR	53	NR	53	73	73	90	90
GATE-0477BZ	30011	NIKE RADAR SITE ROAD B	5	AS	0.05	90	NR	90	NR	90	90	90	97	97
GATE-0477CZ	30011	NIKE RADAR SITE ROAD C	5	AS	0.14	53	NR	53	NR	73	53	53	90	90
GATE-0480	33613	SERVICE ROAD / KINGMAN AND MILLS ROAD	5	AS	0.18	73	NR	73	NR	73	73	73	97	97
GATE-0481	33625	SOUTH MAINTENANCE SHOP ROAD A	5	AS	0.14	30	NR	30	NR	30	30	53	90	73
GATE-0482	33627	SOUTH MAINTENANCE SHOP ROAD B	5	AS	0.06	73	NR	73	NR	73	90	73	73	90
GATE-0483AZ	33628	SOUTH MAINTENANCE SHOP ROAD C - MAIN	5	AS	0.06	30	NR	30	NR	30	30	53	97	97
GATE-0483BZ	33628	SOUTH MAINTENANCE SHOP ROAD C - SPUR	5	AS	0.03	30	NR	30	NR	30	30	53	97	53
GATE-0484	33629	NORTH BEACH SERVICE ROAD	5	AS	0.29	73	NR	73	NR	73	90	90	73	97
GATE-0505	33670	MAINTENANCE GAS STATION ROAD	6	AS	0.06	53	NR	53	NR	53	73	90	90	97
GATE-0661BZ	33647	HUDSON ROAD SPUR	2	AS	0.03	100	NR	100	100	100	100	100	100	100
GATE-0661CZ	33647	HUDSON ROAD CUT-THRU	2	AS	0.03	98	NR	98	100	100	100	100	98	100
GATE-0662BZ	33648	MAGRUDER ROAD SPUR 1	2	AS	0.06	100	NR	100	100	100	100	100	100	100
GATE-0662CZ	33648	MAGRUDER ROAD SPUR 2	2	AS	0.02	45	NR	45	45	56	89	90	100	100
GATE-0675BZ	33660	MCNAIR ROAD CUT-THRU B	5	AS	0.03	73	NR	73	NR	90	90	73	90	97
GATE-0675CZ	33660	MCNAIR ROAD CUT-THRU C	5	AS	0.03	73	NR	73	NR	73	90	90	97	97

Condition (Rating / Index) Legend

EXCELLENT (95 - 100)
GOOD (85 - 94)
FAIR (61 - 84)
POOR (0 - 60)
NR = NOT RATED



Parking Area Condition Summary Report

Gateway National Recreation Area

Notes:

• A PCR of 0 indicates a paved parking area in very poor condition. Individual distresses could not be identified.

• Additional details on individual parking areas can be found in Section 6 of the Cycle 6 RIP Report.

• Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

Condition (Rating / Index) Legend

EXCELLENT (97)
GOOD (90)
FAIR (73)
POOR* (0, 30, 53)
NR = NOT RATED

Concrete Surface Distresses

Route No.	FMSS No.	Condition Rating Details for Paved Parking Areas	User Access	Surf. Type	Area (Sq. Ft.)	Pavement Condition Rating (PCR)	Alligator Cracking	Longitudinal / Tranverse Cracking	Rutting / Distortions	Potholes / Patching	HMA Patching	Surface Raveling / Bleeding	Joint Faulting	Slab Cracking	Joint Distresses	Delamination / Pop-Outs	Potholes / Patching
GATE-0900	33662	ENTRANCE STATION PARKING A	PUBLIC	AS	11,444	90	97	90	97	90	97	90					
GATE-0901	36103	GATEWAY SPORTS PARKING	PUBLIC	AS	77,652	73	90	90	97	90	73	90					
GATE-0902	36105	GATEWAY MARINA PARKING	PUBLIC	AS	79,073	30	30	53	73	30	97	73					
GATE-0905	33663	SANDY HOOK VISITOR CENTER PARKING	PUBLIC	AS	22,979	90	97	90	97	97	97	90					
GATE-0906AZ	36107	JACOB RIIS PARKING A	PUBLIC	CO	459,285	90							90	90	90	90	90
GATE-0906BZ	36107	JACOB RIIS PARKING B	PUBLIC	CO	421,175	90							90	90	90	90	90
GATE-0906CZ	36107	JACOB RIIS PARKING C	PUBLIC	CO	461,397	90							90	90	90	90	90
GATE-0906DZ	36107	JACOB RIIS PARKING D	PUBLIC	CO	436,725	90							90	90	90	90	90
GATE-0906EZ	36107	JACOB RIIS PARKING E	PUBLIC	CO	529,252	73							90	73	90	90	90
GATE-0906FZ	36107	JACOB RIIS PARKING F	PUBLIC	CO	334,148	73							90	73	90	90	90
GATE-0907	33664	RANGER STATION PARKING A EAST	PUBLIC	AS	5,249	90	97	90	97	97	97	90					
GATE-0908	33665	RANGER PARKING B NORTH	PUBLIC	AS	5,841	90	97	90	97	97	97	90					
GATE-0909B	33668	MAINTENANCE PARKING EAST	NONPUBLIC	CO	8,823	73							73	73	90	90	97
GATE-0909C	33669	MAINTENANCE PARKING WEST	NONPUBLIC	CO	2,923	73							73	73	90	90	97
GATE-0910A	33671	MAINTENANCE SHOP EMPLOYEE PARKING	NONPUBLIC	AS	15,098	30	90	90	97	30	90	73					
GATE-0910B	33672	MAINTENANCE HEAVY VEHICLE PARKING	NONPUBLIC	AS	9,018	53	53	90	97	53	97	73					
GATE-0911	33673	MISSILE PARKING LOT	PUBLIC	AS	8,846	90	90	90	97	97	97	90					
GATE-0913	33675	LOT "L" NIKE RADAR SITE PARKING	PUBLIC	AS	18,316	73	90	90	97	90	97	73					
GATE-0914	33677	LOT "H" CAMPGROUND PARKING	PUBLIC	AS	11,386	73	90	90	97	97	97	73					
GATE-0915	33678	WATER TREATMENT PLANT PARKING	NONPUBLIC	AS	8,385	53	73	53	97	73	97	90					
GATE-0916	34239	GUARDIAN PARK PARKING	PUBLIC	AS	18,668	90	97	90	97	97	97	90					
GATE-0917	34785	DAYCARE #335 AND #18 PARKING	PUBLIC	AS	22,683	90	97	90	97	97	97	90					
GATE-0918A	35211	NOAA LAB A PARKING SOUTH	PUBLIC	AS	16,929	53	90	53	97	90	97	90					
GATE-0918B	35212	NOAA LAB B PARKING NORTH	PUBLIC	AS	20,577	90	90	90	97	90	90	90					
GATE-0919	34806	BUILDING 74 EAST PARKING	PUBLIC	AS	3,037	90	90	90	97	97	97	90					
GATE-0920	35189	MARINE ACADEMY CAFETERIA #77 PARKING	NONPUBLIC	AS	10,410	90	97	90	97	97	97	97					



Parking Area Condition Summary Report

Gateway National Recreation Area

Notes:

• A PCR of 0 indicates a paved parking area in very poor condition. Individual distresses could not be identified.

• Additional details on individual parking areas can be found in Section 6 of the Cycle 6 RIP Report.

• Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

Condition (Rating / Index) Legend

EXCELLENT (97)
GOOD (90)
FAIR (73)
POOR* (0, 30, 53)
NR = NOT RATED

Concrete Surface Distresses

Route No.	FMSS No.	Condition Rating Details for Paved Parking Areas	User Access	Surf. Type	Area (Sq. Ft.)	Pavement Condition Rating (PCR)	Alligator Cracking	Longitudinal / Tranverse Cracking	Rutting / Distortions	Potholes / Patching	HMA Patching	Surface Raveling / Bleeding	Joint Faulting	Slab Cracking	Joint Distresses	Velamination / Pop-Outs Potholes / Patching
GATE-0921	35190	MAST PARKING LOT "N"	NONPUBLIC	C AS	39,728	90	97	90	97	97	97	97				
GATE-0922	35191	MAST SCHOOL OFFICES TEACHERS PARKING	NONPUBLIC	C AS	6,787	90	97	90	97	97	97	97				
GATE-0923	35192	BUILDING 53 AND BUILDING 60 PARKING	PUBLIC	AS	15,608	90	97	90	97	97	97	97				
GATE-0924	35193	BUILDING 40/ POST OFFICE/ GYM PARKING	PUBLIC	AS	1,835	97	97	97	97	97	97	97				
GATE-0925	35194	LIGHTHOUSE PARKING	PUBLIC	AS	13,504	53	53	90	97	73	97	90				
GATE-0926	35195	LAWSON LANE PARKING	PUBLIC	AS	4,730	97	97	97	97	97	97	97				
GATE-0927	35196	BUILDING 32 PARK RANGER PARKING	NONPUBLIC	C AS	31,695	97	97	97	97	97	97	97				
GATE-0928A	35213	NORTH MAINTENANCE EMPLOYEE PARKING A	NONPUBLIC	C AS	25,189	30	30	53	30	30	97	73				
GATE-0928B	21822	NORTH MAINTENANCE EMPLOYEE PARKING B	NONPUBLIC	C AS	2,030	0										
GATE-0929	35197	GUNNISON BEACH PARKING	PUBLIC	AS	281,839	90	90	90	97	97	90	90				
GATE-0930	35198	NORTH BEACH PARKING	PUBLIC	AS	139,821	90	97	90	97	90	97	90				
GATE-0931	35200	EMPLOYEE PULLOUT GUNNISON PARKING	NONPUBLIC	C AS	5,684	90	97	90	97	90	90	90				
GATE-0933	35202	FEE COLLECTORS PARKING	NONPUBLIC	C AS	12,152	73	90	90	97	73	90	90				
GATE-0934	35203	QUARTER 600 PARKING	NONPUBLIC	C AS	9,784	30	30	53	97	73	97	73				
GATE-0935	35204	SEWAGE PLANT PARKING	NONPUBLIC	C AS	7,562	90	90	90	97	97	90	90				
GATE-0936	35205	FORT HANCOCK THEATER PARKING	PUBLIC	AS	9,055	97	97	97	97	97	97	97				
GATE-0937	35206	BUILDING 58 PARKING	PUBLIC	AS	3,600	97	97	97	97	97	97	97				
GATE-0938	35207	AREA B PARKING LOT B	PUBLIC	AS	100,876	90	97	90	97	97	97	90				
GATE-0939	35208	AREA C PARKING LOT C	PUBLIC	AS	99,865	90	97	90	97	97	97	90				
GATE-0940AZ	25235	GREAT KILLS ENTRANCE PARKING A	PUBLIC	AS	8,649	90	97	90	97	97	97	97				
GATE-0940BZ	25235	GREAT KILLS ENTRANCE PARKING B	PUBLIC	AS	8,591	90	97	90	97	97	97	97				
GATE-0941	25236	USPP/RANGER PARKING	PUBLIC	AS	22,469	53	90	53	97	97	90	90				
GATE-0942	25237	GK AREA "A" PARKING	PUBLIC	AS	130,313	73	73	90	97	90	97	90				
GATE-0943	25238	BOAT LAUNCH PARKING	PUBLIC	AS	77,744	90	97	90	97	97	90	90				
GATE-0944	25239	GK AREA "E" PARKING	PUBLIC	AS	32,340	73	73	90	97	97	97	90				
GATE-0945	25240	GK AREA "F" PARKING	PUBLIC	AS	23,924	73	90	90	97	97	73	90				



Parking Area Condition Summary Report

Gateway National Recreation Area

Notes:

• A PCR of 0 indicates a paved parking area in very poor condition. Individual distresses could not be identified.

• Additional details on individual parking areas can be found in Section 6 of the Cycle 6 RIP Report.

• Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

Condition (Rating / Index) Legend

EXCELLENT (97)
GOOD (90)
FAIR (73)
POOR* (0, 30, 53)
NR = NOT RATED

Concrete Surface Distresses

Route No.	FMSS No.	Condition Rating Details for Paved Parking Areas	User Access	Surf. Type	Area (Sq. Ft.)	Pavement Condition Rating (PCR)	Alligator Cracking	Longitudinal / Tranverse Cracking	Rutting / Distortions	Potholes / Patching	HMA Patching	Surface Raveling / Bleeding	Joint Faulting	Slab Cracking	Joint Distresses	Delamination / Pop-Outs	Potholes / Patching
GATE-0946	25241	BEACH CENTER PARKING	PUBLIC	AS	47,532	53	90	53	97	97	97	90					
GATE-0947	25242	BEACH PICKUP AREA	PUBLIC	AS	8,943	90	90	90	97	97	90	90					
GATE-0948	25247	MILLER FIELD PARKING LOT (BALL FIELD)	PUBLIC	AS	102,825	53	73	53	97	97	97	90					
GATE-0949	25248	RANGER STATION PARKING	PUBLIC	AS	7,061	90	97	90	97	97	97	90					
GATE-0951	25250	CIRCLE PARKING	PUBLIC	AS	87,373	90	90	90	97	97	97	90					
GATE-0952	25251	RESIDENCE PARKING	PUBLIC	AS	6,156	90	90	90	97	90	97	90					
GATE-0953A	25252	NEW DORP HIGH SCHOOL PARKING A	PUBLIC	AS	43,438	90	97	90	97	97	97	97					
GATE-0953C	105114	NEW DORP HIGH SCHOOL PARKING C	PUBLIC	AS	53,104	90	97	90	97	97	97	97					
GATE-0953D	N/A	NEW DORP HIGH SCHOOL PARKING D	PUBLIC	AS	19,687	97	97	97	97	97	97	97					
GATE-0954	25222	MAIN GATE PARKING	PUBLIC	AS	5,790	90	90	90	97	90	90	90					
GATE-0955AAZ	33184	COAST GUARD AREA PARKING AAZ	PUBLIC	AS	7,021	90	90	90	97	97	97	97					
GATE-0955ABZ	33184	COAST GUARD AREA PARKING ABZ	PUBLIC	AS	7,771	90	90	90	97	90	90	90					
GATE-0955ACZ	33184	COAST GUARD AREA PARKING ACZ	PUBLIC	AS	10,178	53	53	90	97	90	90	90					
GATE-0955B	33187	COAST GUARD AREA PARKING B	PUBLIC	AS	68,764	90	90	90	97	90	90	90					
GATE-0955C	33188	USCG ACTIVITIES PARKING	PUBLIC	AS	6,350	53	90	53	97	97	97	90					
GATE-0955D	33190	USCG GALLEY PARKING	PUBLIC	AS	2,994	53	53	90	97	90	90	90					
GATE-0955E	33191	USCG GALLEY REAR PARKING AND FIRE LANE	PUBLIC	AS	12,433	73	73	90	97	90	90	90					
GATE-0955F	33192	USCG PX PARKING	PUBLIC	AS	15,970	73	73	90	97	90	97	90					
GATE-0956A	25223	DRUM AVENUE PARKING A	NONPUBLIC	C AS	1,455	97	97	97	97	97	97	97					
GATE-0956B	33175	DRUM AVENUE CHAPEL PARKING	PUBLIC	AS	2,861	53	53	90	97	90	97	90					
GATE-0956C	33177	DRUM AVENUE LOOP PARKING	PUBLIC	AS	1,871	53	90	53	97	97	90	90					
GATE-0956D	33180	DRUM AVENUE PARKING D	PUBLIC	AS	2,520	53	53	90	97	90	97	90					
GATE-0957A	33183	THEATRE PARKING	PUBLIC	AS	31,936	73	73	90	90	73	97	90					
GATE-0957B	25224	HAND BALL PARKING	PUBLIC	AS	12,070	90	90	90	97	90	97	90					
GATE-0957C	25225	HQ B210 PARKING	PUBLIC	AS	91,846	53	53	90	97	90	97	90					
GATE-0957D	25226	USPP PARKING B210	PUBLIC	AS	11,321	53	90	53	97	90	97	90					



Parking Area Condition Summary Report

Gateway National Recreation Area

Notes:

• A PCR of 0 indicates a paved parking area in very poor condition. Individual distresses could not be identified.

• Additional details on individual parking areas can be found in Section 6 of the Cycle 6 RIP Report.

• Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

Condition (Rating / Index) Legend

EXCELLENT (97)
GOOD (90)
FAIR (73)
POOR* (0, 30, 53)
NR = NOT RATED

Concrete Surface Distresses

Route No.	FMSS No.	Condition Rating Details for Paved Parking Areas	User Access	Surf. Type	Area (Sq. Ft.)	Pavement Condition Rating (PCR)	Alligator Cracking	Longitudinal / Tranverse Cracking	Rutting / Distortions	Potholes / Patching	HMA Patching	Surface Raveling / Bleeding	Joint Faulting	Slab Cracking	Joint Distresses	Delamination / Pop-Outs	
GATE-0958A	25227	FORT WADSWORTH VISITOR CENTER PARKING	PUBLIC	AS	95,655	97	97	97	97	97	97	97					
GATE-0958B	25228	FT TOMPKINS PARKING	PUBLIC	AS	2,505	73	73	90	97	90	90	90					
GATE-0959A	25229	TENNIS COURT PARKING	PUBLIC	AS	2,845	53	73	90	90	53	90	90					
GATE-0959B	25230	FORT WADSWORTH BUILDING 109 PARKING	PUBLIC	AS	8,204	53	97	53	97	97	97	90					
GATE-0960A	33194	NAVY LODGE AREA PARKING	PUBLIC	AS	35,493	73	90	90	97	90	73	97					
GATE-0960B	25231	MCCLEAN ROAD PARKING	PUBLIC	AS	12,988	30	30	90	97	73	73	90					
GATE-0960C	33195	AYERS ROAD PARKING	PUBLIC	AS	2,131	90	90	90	97	90	97	90					
GATE-0961A	33196	ARMED FORCES RESERVE AREA PARKING	PUBLIC	AS	105,675	90	90	90	97	97	97	97					
GATE-0961B	33199	ARMED FORCES AREA B PARKING	PUBLIC	AS	22,475	53	53	90	97	90	73	90					
GATE-0961C	33201	ARMED FORCES AREA C PARKING	PUBLIC	AS	9,359	53	90	53	97	90	90	90					
GATE-0961D	33202	FWR USPP SWAT PARKING	PUBLIC	AS	7,404	53	90	53	97	97	97	97					
GATE-0962A	25232	FWR BALL FIELD PARKING	PUBLIC	AS	33,895	97	97	97	97	97	97	97					
GATE-0962B	25233	FWR CAMPGROUND PARKING AREA	PUBLIC	AS	2,122	97	97	97	97	97	97	97					
GATE-0963A	25234	FWR BATTERY WEED AREA A PARKING	PUBLIC	AS	2,842	90	97	90	97	97	97	90					
GATE-0963C	33205	FWR BATTERY WEED AREA C PARKING	PUBLIC	AS	2,130	90	90	90	97	97	97	90					
GATE-0963D	33682	FWR BATTERY WEED AREA D PARKING	PUBLIC	AS	2,061	90	90	90	97	97	97	97					
GATE-0964AAZ	36138	ENTRANCE AREA PARKING A	PUBLIC	AS	16,877	90	97	90	97	97	97	90					
GATE-0964ABZ	36138	ENTRANCE AREA PARKING B	PUBLIC	AS	16,929	53	53	90	97	73	97	90					
GATE-0964B	36140	SEWAGE TREATMENT PARKING IN JAMAICA BAY	PUBLIC	AS	5,830	53	90	53	97	97	90	90					
GATE-0965A	36141	COMMUNITY GARDENS PARKING	PUBLIC	CO	176,975	73							90	73	90	90	90
GATE-0965B	36142	RYAN VISITOR CENTER PARKING SE	PUBLIC	AS	56,849	97	97	97	97	97	97	97					
GATE-0965C	36143	AVIATOR CONCESSION PARKING	PUBLIC	AS	147,081	97	97	97	97	97	97	97					
GATE-0965D	36144	RYAN VISITOR CENTER PARKING	PUBLIC	AS	131,195	90	90	90	97	90	90	90					
GATE-0965E	36147	HANGAR 3 AND 4 PARKING AREA	NONPUBLIC	BR	162,379	97											
GATE-0965F	36368	RYAN CENTER EMPLOYEE PARKING	PUBLIC	CO	54,966	53							53	73	90	97	90
GATE-0966	36108	MODEL AIRPLANE FIELD PARKING	PUBLIC	AS	114,483	30	30	53	90	73	90	73					



Parking Area Condition Summary Report

Gateway National Recreation Area

Notes:

• A PCR of 0 indicates a paved parking area in very poor condition. Individual distresses could not be identified.

• Additional details on individual parking areas can be found in Section 6 of the Cycle 6 RIP Report.

• Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

Condition (Rating / Index) Legend

EXCELLENT (97)
GOOD (90)
FAIR (73)
POOR* (0, 30, 53)
NR = NOT RATED

Concrete Surface Distresses

Route No.	FMSS No.	Condition Rating Details for Paved Parking Areas	User Access	Surf. Type	Area (Sq. Ft.)	Pavement Condition Rating (PCR)	Alligator Cracking	Longitudinal / Tranverse Cracking	Rutting / Distortions	Potholes / Patching	HMA Patching	Surface Raveling / Bleeding	Joint Faulting	Slab Cracking	Joint Distresses	Delamination / Pop-Outs	Potholes / Patching
GATE-0967	36110	CAR TOP BOAT RAMP AND FISHING AREA PARKING	PUBLIC	CO	997,028	90							90	90	97	97	97
GATE-0968ABZ	31606	USPP PARKING NORTH	PUBLIC	AS	15,146	53	53	90	90	73	97	90					
GATE-0968ACZ	31606	USPP PARKING SOUTH	PUBLIC	AS	3,585	30	30	90	97	73	97	90					
GATE-0968B	36369	NPS HEADQUARTERS (BUILDING 69 NORTH) AREA PARKING	PUBLIC	AS	1,953	90	97	90	97	97	90	90					
GATE-0968C	36371	NPS ECOLOGY VILLAGE PARKING	PUBLIC	AS	17,918	73	73	90	97	97	97	90					
GATE-0968EAZ	36374	NPS ENTERPRISE ROAD PARKING A	PUBLIC	AS	5,110	73	73	90	97	90	90	90					
GATE-0968EBZ	36374	NPS ENTERPRISE ROAD PARKING B	PUBLIC	AS	4,115	90	90	90	97	97	97	90					
GATE-0968ECZ	36374	NPS ENTERPRISE ROAD PARKING C	PUBLIC	AS	1,331	53	53	90	97	90	97	97					
GATE-0968F	36375	NPS BUILDING 62 AREA PARKING	PUBLIC	AS	15,447	53	53	90	97	90	97	90					
GATE-0969	36111	POLY TECH AND SOCCER FIELD PARKING	PUBLIC	AS	30,443	53	53	90	90	73	90	73					
GATE-0970	36112	FISHING ACCESS PARKING	PUBLIC	AS	21,099	30	30	53	90	90	90	73					
GATE-0971	36114	TYLUNAS HALL PARKING (NYC COLLECTION)	PUBLIC	AS	38,733	53	53	90	90	90	90	73					
GATE-0972A	36377	BUILDING 98 PARKING	PUBLIC	AS	28,869	30	30	90	97	73	90	73					
GATE-0972B	36378	BUILDING 95 PARKING	PUBLIC	AS	17,350	30	30	90	90	73	90	73					
GATE-0974	36115	FT. TILDEN FISHERMEN'S PARKING	PUBLIC	AS	35,273	90	90	90	97	97	90	90					
GATE-0975	35209	AREA D BEACH CENTER PARKING	PUBLIC	AS	277,235	90	90	90	97	97	90	90					
GATE-0976A	36379	THEATER PARKING A	PUBLIC	AS	110,301	90	90	90	97	97	97	90					
GATE-0976B	36380	RAA T-7 PARKING B	PUBLIC	AS	4,982	30	30	90	97	97	97	73					
GATE-0978	36119	BALL FIELD PARKING	PUBLIC	AS	6,695	90	97	90	97	97	90	90					
GATE-0979	36121	BAY 17/18 PARKING AREA	PUBLIC	CO	25,896	53							73	53	90	90	97
GATE-0980	36123	DAVIS ACCESS ROAD PARKING	PUBLIC	CO	4,523	30							53	30	73	90	97
GATE-0981	36126	QTS. 22/23 RESIDENCE ACCESS PARKING	NONPUBLIC	CO	4,429	90							90	90	90	90	97
GATE-0982A	36381	PICNIC PARKING A	PUBLIC	AS	6,658	90	90	90	90	97	90	90					
GATE-0982B	36382	PICNIC PARKING B	PUBLIC	AS	10,567	53	90	53	97	90	73	90					
GATE-0983A	36383	BUILDING 1 PARKING AREA A	PUBLIC	AS	6,348	73	90	90	97	97	73	90					
GATE-0983B	36384	BUILDING 1 SOUTHSIDE PARKING AREA B	PUBLIC	AS	9,739	53	90	53	97	97	97	90					



Parking Area Condition Summary Report

Gateway National Recreation Area

Notes:

• A PCR of 0 indicates a paved parking area in very poor condition. Individual distresses could not be identified.

• Additional details on individual parking areas can be found in Section 6 of the Cycle 6 RIP Report.

• Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

Condition (Rating / Index) Legend

EXCELLENT (97)
GOOD (90)
FAIR (73)
POOR* (0, 30, 53)
NR = NOT RATED

Concrete Surface Distresses

Route No.	FMSS No.	Condition Rating Details for Paved Parking Areas	User Access	Surf. Type	Area (Sq. Ft.)	Pavement Condition Rating (PCR)	Alligator Cracking	Longitudinal / Tranverse Cracking	Rutting / Distortions	Potholes / Patching	HMA Patching	Surface Raveling / Bleeding	Joint Faulting	Slab Cracking	Joint Distresses	Delamination / Pop-Outs	Potholes / Patching
GATE-0983C	36385	BUILDING 1 NORTHSIDE PARKING AREA C	PUBLIC	AS	7,382	53	90	53	97	90	97	90					
GATE-0983D	240516	BUILDING 1 PARKING NORTH	PUBLIC	AS	2,895	53	73	53	97	97	97	90					
GATE-0984A	36386	BUILDING 149 PARKING AREA	PUBLIC	AS	10,761	53	90	53	97	97	97	90					
GATE-0984B	36387	COMMUNITY GARDEN AREA PARKING B	PUBLIC	AS	1,289	90	90	90	97	97	97	90					
GATE-0986	36129	POST OFFICE PARKING	PUBLIC	CO	1,732	90							97	90	97	90	97
GATE-0987	36131	MAINTENANCE AREA PARKING (RIIS LDG)	PUBLIC	CO	30,430	73							90	73	90	73	90
GATE-0988	36133	RIIS PARK BAY 3 EAST PARKING	PUBLIC	CO	21,157	90							90	90	97	97	97
GATE-0989	36135	CANARSIE PIER PARKING	PUBLIC	AS	117,609	73	90	90	97	73	90	90					
GATE-0990	36136	WILDLIFE REFUGE VISITOR PARKING	PUBLIC	AS	42,706	90	90	90	97	97	97	90					
GATE-0991A	31395	NORTH CHANNEL BRIDGE PARKING / EASTSIDE	PUBLIC	AS	18,769	90	97	90	97	97	97	90					
GATE-0991B	31394	NORTH CHANNEL BRIDGE PARKING / WESTSIDE	PUBLIC	AS	20,642	90	97	97	97	97	97	90					
GATE-0993	35210	PARKING LOT E	PUBLIC	AS	289,221	90	90	90	97	90	90	90					
GATE-0994	25243	GREAT KILLS EDUCATION CENTER PARKING	PUBLIC	CO	3,489	90							97	97	90	90	97
GATE-0996	112112	BREEZY POINT SURF CLUB PARKING	PUBLIC	AS	334,242	53	53	53	90	73	73	73					
GATE-0999AZ	112205	SILVER GULL BEACH CLUB PARKING A	PUBLIC	AS	1,599	73	90	90	97	97	97	73					
GATE-0999BZ	112205	SILVER GULL BEACH CLUB PARKING B	PUBLIC	AS	107,396	53	53	53	90	73	73	73					
GATE-0999CZ	112205	SILVER GULL BEACH CLUB PARKING C	PUBLIC	AS	1,903	73	90	90	97	90	97	73					
GATE-1002	93881	HAMILTON BEACH PARKING	PUBLIC	AS	11,195	90	90	90	97	97	90	90					
GATE-1004	25254	PICNIC/BEACH AREA PARKING LOT E	PUBLIC	AS	52,677	90	97	90	97	97	97	90					
GATE-1011	114406	MILLER FIELD AREA D PARKING LOT (FT. CAPODANO)	PUBLIC	AS	28,770	53	73	53	97	97	97	90					
GATE-1012	116079	GREAT KILLS MARINA PARKING	NONPUBLIC	C AS	89,726	53	53	90	97	73	73	90					
GATE-1013	239600	USPP STABLE PARKING	PUBLIC	AS	3,738	53	53	53	90	90	90	90					
GATE-1014	239601	BUILDING 302 L-SHAPED PARKING	PUBLIC	AS	24,868	30	30	53	90	73	90	73					
GATE-1015	238599	BUILDING 301 MAINTENANCE PARKING	PUBLIC	AS	10,048	53	53	90	97	53	97	73					
GATE-1016AZ	238264	RIIS LANDING PARKING A	NONPUBLIC	C AS	46,559	53	73	53	90	90	97	90					
GATE-1016BZ	238264	RIIS LANDING PARKING B	NONPUBLIC	C AS	42,384	53	73	53	97	90	73	73					



Parking Area Condition Summary Report

Gateway National Recreation Area

Notes:

• A PCR of 0 indicates a paved parking area in very poor condition. Individual distresses could not be identified.

• Additional details on individual parking areas can be found in Section 6 of the Cycle 6 RIP Report.

• Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

Condition (Rating / Index) Legend

EXCELLENT (97)
GOOD (90)
FAIR (73)
POOR* (0, 30, 53)
NR = NOT RATED

Concrete Surface Distresses

Route No.	FMSS No.	Condition Rating Details for Paved Parking Areas	User Access	Surf. Type	Area (Sq. Ft.)	Pavement Condition Rating (PCR)	Alligator Cracking	Longitudinal / Tranverse Cracking	Rutting / Distortions	Potholes / Patching	HMA Patching	Surface Raveling / Bleeding	Joint Faulting	Slab Cracking	Joint Distresses	Delamination / Pop-Outs	Potholes / Patching
GATE-1017	N/A	BREEZY POINT SURF CLUB ENTRANCE PARKING	NONPUBLIC	C AS	8,858	53	53	53	97	73	73	90					
GATE-1020	115709	NYPD PARKING 1	NONPUBLIC	C AS	66,030	30	30	53	90	97	90	73					
GATE-1021	115710	NYPD PARKING 2	NONPUBLIC	C AS	27,080	30	30	53	73	30	90	73					
GATE-1022	115711	NYPD PARKING 3	NONPUBLIC	C AS	5,290	30	30	53	73	90	90	73					
GATE-1023	115725	NYPD PARKING 4	NONPUBLIC	C AS	24,059	30	30	90	97	30	73	73					
GATE-1024	115726	NYPD PARKING 5	NONPUBLIC	C AS	53,985	30	30	90	90	53	90	73					
GATE-1025	112823	PENNSYLVANIA AVENUE LANDFILL PARKING	PUBLIC	AS	52,403	97	97	97	97	97	97	97					
GATE-1026	112827	FOUNTAIN AVENUE LANDFILL	PUBLIC	AS	54,184	97	97	97	97	97	97	97					
GATE-1027	225810	AVIATOR SPORTS PAVED PARKING	PUBLIC	CO	276,599	73							73	90	97	97	90
GATE-1028	227300	NC-S RIDING ACADEMY PARKING LOT	PUBLIC	AS	17,146	30	53	53	90	30	97	73					
GATE-1035	245334	BEACH 222ND STREET PARKING	PUBLIC	AS	6,999	53	90	90	97	53	97	73					
GATE-1036	N/A	PARKING LOT M	PUBLIC	AS	9,173	0											
GATE-1037	30003	NOAA SERVICE PARKING LOT	NONPUBLIC	C AS	9,733	90	90	90	97	97	90	90					
GATE-1042AZ	256345	JABA PARKING A	NONPUBLIC	C AS	295,165	53	73	53	90	90	90	90					
GATE-1042BZ	256345	JABA PARKING B	NONPUBLIC	CO	187,684	73							90	73	90	90	90

Section 4 Park Route Location Maps




Gateway National Recreation Area




Gateway National Recreation Area ROUTE LOCATION MAP

KEY MAP



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community




0

Non-NPS Collected Routes

Ν


Gateway National Recreation Area ROUTE LOCATION MAP

MAP 1



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community


Note: Unique colors are used to differentiate roads



Non-NPS Collected Routes


Ν

ROUTE LOCATION MAP MAP 1A



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community


Note: Unique colors are used to differentiate roads



Non-NPS Collected Routes

ROUTE LOCATION MAP

MAP 1B




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

0.4

Note: Unique colors are used to differentiate roads

0




Non-NPS Collected Routes

Gateway National Recreation Area ROUTE LOCATION MAP MAP 1C



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads



Non-NPS Collected Routes

ROUTE LOCATION MAP

MAP 1D



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community


1.1

Note: Unique colors are used to differentiate roads

Non-NPS Collected Routes

ROUTE LOCATION MAP


MAP 2



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community



0



Non-NPS Collected Routes


ROUTE LOCATION MAP

MAP 2A



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads



Non-NPS Collected Routes

ROUTE LOCATION MAP

MAP 2B



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads

0

_

ROUTE LOCATION MAP

MAP 2C



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

1.5

Note: Unique colors are used to differentiate roads


0



Non-NPS Collected Routes

Gateway National Recreation Area ROUTE LOCATION MAP

MAP 3



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

5

Note: Unique colors are used to differentiate roads

0

Miles 2.5


Non-NPS Collected Routes

Gateway National Recreation Area ROUTE LOCATION MAP MAP 3A



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads



Non-NPS Collected Routes

ROUTE LOCATION MAP

MAP 3B




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

1.1

Note: Unique colors are used to differentiate roads

0

Non-NPS Collected Routes



N

ROUTE LOCATION MAP

MAP 3C



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads

Miles

0.7

Non-NPS Collected Routes

ROUTE LOCATION MAP

MAP 3D



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads

0

Non-NPS Collected Routes

ROUTE LOCATION MAP

MAP 3E




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

0.4




0



Non-NPS Collected Routes

ROUTE LOCATION MAP

MAP 3F




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community


0.5

Note: Unique colors are used to differentiate roads


Non-NPS Collected Routes


Gateway National Recreation Area ROUTE CONDITION MAP PCR - MILE BY MILE KEY MAP





Gateway National Recreation Area ROUTE CONDITION MAP PCR - MILE BY MILE MAP 1






ROUTE CONDITION MAP PCR - MILE BY MILE


MAP 1A





ROUTE CONDITION MAP PCR - MILE BY MILE MAP 1B






ROUTE CONDITION MAP PCR - MILE BY MILE MAP 1C




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community



ROUTE CONDITION MAP PCR - MILE BY MILE


MAP 1D






ROUTE CONDITION MAP PCR - MILE BY MILE


MAP 2







ROUTE CONDITION MAP PCR - MILE BY MILE MAP 2A






ROUTE CONDITION MAP PCR - MILE BY MILE MAP 2B






ROUTE CONDITION MAP

PCR - MILE BY MILE MAP 2C







Gateway National Recreation Area ROUTE CONDITION MAP

PCR - MILE BY MILE


MAP 3




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community




Gateway National Recreation Area ROUTE CONDITION MAP PCR - MILE BY MILE MAP 3A




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community



ROUTE CONDITION MAP PCR - MILE BY MILE MAP 3B




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community



ROUTE CONDITION MAP PCR - MILE BY MILE


MAP 3C





ROUTE CONDITION MAP PCR - MILE BY MILE MAP 3D





ROUTE CONDITION MAP PCR - MILE BY MILE

MAP 3E




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

		Route Condition	Legend – Pavement Cond	lition Rating (PCR)		
	Poor (0 - 60)	Fair (61- 84)	Good (85 - 94)	Excellent (95 - 100)	Not Rated	
	Colors on map r			e Appendix for definitions ar	nd formulas	_
		Only Data Collection	n Vehicle and Manually Rat	ed Roads are displayed		
	Miles					N
0	0.15	0.3				A

ROUTE CONDITION MAP PCR - MILE BY MILE MAP 3F



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community



Section 5 Paved Road Condition Rating Sheets



Gateway National Recreation Area



Gateway National Recreation Area ROUTE 0030: BUFFALO ROAD

Data Collection Vehicle (DCV) Rating




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60) Fair (1- 84) Good (85 - 94)		Excellent (95 - 100)		Not Rated		
Colors on map represent con	ndition scores at 0.10-mile	tion scores at 0.10-mile intervals. See Appendix for definitions and formulas.					
Inspection Date: 4/24/2021	Beginning Section MP	0	1				
Paved Length (Miles): 1.75	Section Length (MI)	1	0.75				
Surface Type: ASPHALT	Route Summary				•		
Roadway Condition Information							
Pavement Condition Rating (PCR)	64	56	73				
Surface Condition Rating (SCR)	48	38	61				
Roughness Condition Index (RCI)	87	84	92				
Distress Index Values							
Structural Crack Index	69	57	84				
Alligator Crack Index	100	100	100				
Longitudinal Crack Index	69	57	84				
Transverse Cracking Index	48	38	61				
Patching Index	100	100	100				
Rutting Index	98	98	98				
International Roughness Index (IRI)	148	157	135				
Lane & Width Information							
Number of Lanes	2	2	2				
Paved Width (ft)	27.6	27.9	27.2				
Lane Width (ft)	10.9	11	10.8				

Gateway National Recreation Area ROUTE 0060: HARTSHORNE DRIVE (NORTHBOUND)

Data Collection Vehicle (DCV) Rating




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60) Fair (1- 84) Good (85 - 94)		Excellent (95 - 100)		Not Rated		
Colors on map represent co	ndition scores at 0.10-mile	ition scores at 0.10-mile intervals. See Appendix for definitions and formulas.					
Inspection Date: 4/24/2021	Beginning Section MP	0	1	2	3	4	
Paved Length (Miles): 5.28	Section Length (MI)	1	1	1	1	1	
Surface Type: ASPHALT	Route Summary						
Roadway Condition Information							
Pavement Condition Rating (PCR)	82	38	91	95	92	75	
Surface Condition Rating (SCR)	78	7	87	94	86	75	
Roughness Condition Index (RCI)	88	84	97	96	100	75	
Distress Index Values							
Structural Crack Index	78	7	93	98	96	93	
Alligator Crack Index	100	100	100	100	100	100	
Longitudinal Crack Index	78	7	93	98	96	93	
Transverse Cracking Index	79	49	87	94	86	75	
Patching Index	100	100	100	100	100	100	
Rutting Index	98	96	99	99	99	98	
International Roughness Index (IRI)	147	158	121	124	109	184	
Lane & Width Information							
Number of Lanes	2	2	2	2	2	2	
Paved Width (ft)	27	33.1	25.2	31.2	24.3	23.6	
Lane Width (ft)	10.8	11.2	10.4	10.4	10.8	11.6	

Gateway National Recreation Area ROUTE 0060: HARTSHORNE DRIVE (NORTHBOUND)

Data Collection Vehicle (DCV) Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60) Fair (6	Good (85 - 94)		Excellent (95 - 10	Not Rated			
Colors on map represent con	ition scores at 0.10-mile intervals. See Appendix for definitions and formulas.						
Inspection Date: 4/24/2021	Beginning Section MP	5					
Paved Length (Miles): 5.28	Section Length (MI)	0.28					
Surface Type: ASPHALT	Route Summary						
Roadway Condition Information							
Pavement Condition Rating (PCR)	82	73					
Surface Condition Rating (SCR)	78	88					
Roughness Condition Index (RCI)	88	50					
Distress Index Values							
Structural Crack Index	78	92					
Alligator Crack Index	100	100					
Longitudinal Crack Index	78	92					
Transverse Cracking Index	79	88					
Patching Index	100	100					
Rutting Index	98	92					
International Roughness Index (IRI)	147	285					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	27	18.9					
Lane Width (ft)	10.8	10					


Gateway National Recreation Area ROUTE 0061: HARTSHORNE DRIVE (SOUTHBOUND)



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Condi	tion Rating (PCR)		
Poor (0 - 60)	61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Ra	ted
Colors on map represent co	ndition scores at 0.10-mile	e intervals. Se	e Appendix fo	or definitions	and formulas.	
Inspection Date: 4/24/2021	Beginning Section MP	0	1	2	3	
Paved Length (Miles): 3.75	Section Length (MI)	1	1	1	0.75	
Surface Type: ASPHALT	Route Summary					
Roadway Condition Information						
Pavement Condition Rating (PCR)	89	99	96	92	60	
Surface Condition Rating (SCR)	82	98	93	86	39	
Roughness Condition Index (RCI)	100	100	100	100	91	
Distress Index Values						
Structural Crack Index	89	99	99	97	49	
Alligator Crack Index	100	100	100	100	100	
Longitudinal Crack Index	89	99	99	97	49	
Transverse Cracking Index	82	98	93	86	39	
Patching Index	100	100	100	100	100	
Rutting Index	99	100	100	97	98	
International Roughness Index (IRI)	103	89	89	104	138	
Lane & Width Information						
Number of Lanes	2	2	2	2	2	
Paved Width (ft)	24.5	23.4	25.2	23.9	25.6	
Lane Width (ft)	10.5	10.5	10.5	10.4	10.4	

Gateway National Recreation Area ROUTE 0063: NS FOUNTAIN AVENUE LANDFILL ACCESS ROADS




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Cond	ition Rating (PCR)		
Poor (0 - 60) Fair (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated	
Colors on map represent condition scores at 0.10-mile intervals. See Appendix for definitions and formu					
Inspection Date: 4/23/2021	Beginning Section MP	0			
Paved Length (Miles): 0.18	Section Length (MI)	0.18			
Surface Type: ASPHALT	Route Summary		•		
Roadway Condition Information					
Pavement Condition Rating (PCR)	96	96			
Surface Condition Rating (SCR)	96	96			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	100	100			
Alligator Crack Index	100	100			
Longitudinal Crack Index	100	100			
Transverse Cracking Index	100	100			
Patching Index	100	100			
Rutting Index	96	96			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	26.6	26.6			
Lane Width (ft)	12.3	12.3			

Gateway National Recreation Area ROUTE 0110: DAVIS ROAD

Data Collection Vehicle (DCV) Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Rou	te Condition Legend – Pav	ement Cond	ition Rating (PCR)				
Poor (0 - 60) Fai	r (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated			
Colors on map represent	present condition scores at 0.10-mile intervals. See Appendix for definitions and formulas.						
Inspection Date: 4/23/2021	Beginning Section MP	0					
Paved Length (Miles): 0.5	Section Length (MI)	0.5					
Surface Type: CONCRETE	Route Summary		•	•			
Roadway Condition Information							
Pavement Condition Rating (PCR)	73	73					
Surface Condition Rating (SCR)	N/A	N/A					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	N/A	N/A					
Alligator Crack Index	N/A	N/A					
Longitudinal Crack Index	N/A	N/A					
Transverse Cracking Index	N/A	N/A					
Patching Index	N/A	N/A					
Rutting Index	N/A	N/A					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	1	1					
Paved Width (ft)	13.9	13.9					
Lane Width (ft)	11.4	11.4					

NOTE: MANUALLY RATED CONCRETE SECTION

Gateway National Recreation Area ROUTE 0111: SHORE ROAD

Data Collection Vehicle (DCV) Rating




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Condi	ition Rating (PCR)			
Poor (0 - 60) Fair (6	61-84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated		
Colors on map represent condition scores at 0.10-mile intervals. See Appendix for definitions and formulas.						
Inspection Date: 4/23/2021	Beginning Section MP	0				
Paved Length (Miles): 0.26	Section Length (MI)	0.26				
Surface Type: CONCRETE	Route Summary					
Roadway Condition Information						
Pavement Condition Rating (PCR)	73	73				
Surface Condition Rating (SCR)	N/A	N/A				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	N/A	N/A				
Alligator Crack Index	N/A	N/A				
Longitudinal Crack Index	N/A	N/A				
Transverse Cracking Index	N/A	N/A				
Patching Index	N/A	N/A				
Rutting Index	N/A	N/A				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	1	1				
Paved Width (ft)	16.3	16.3				
Lane Width (ft)	16.3	16.3				

NOTE: MANUALLY RATED CONCRETE SECTION


Gateway National Recreation Area ROUTE 0130: MILLER FIELD ENTRANCE ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Condition Legend – Pav	ement Condi	tion Rating (PCR)				
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 10	0) Not Rated			
Colors on map represent condition scores at 0.10-mile intervals. See Appendix for definitions and formulas.							
Inspection Date: 4/24/2021	Beginning Section MP	0					
Paved Length (Miles): 0.38	Section Length (MI)	0.38					
Surface Type: ASPHALT	Route Summary			• •			
Roadway Condition Information							
Pavement Condition Rating (PCR)	0	0					
Surface Condition Rating (SCR)	0	0					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	0	0					
Alligator Crack Index	91	91					
Longitudinal Crack Index	0	0					
Transverse Cracking Index	17	17					
Patching Index	100	100					
Rutting Index	92	92					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	27.2	27.2					
Lane Width (ft)	10.5	10.5					

Gateway National Recreation Area ROUTE 0132A: VISITOR CENTER (SANCHEZ ROAD EAST)



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Condition Legend – Pav	ement Condi	tion Rating (P	PCR)		
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (9	5 - 100)	Not Ra	ted
Colors on map represent condition scores at 0.10-mile intervals. See Appendix for definitions and formulas.						
Inspection Date: 4/24/2021	Beginning Section MP	0				
Paved Length (Miles): 0.2	Section Length (MI)	0.2				
Surface Type: ASPHALT	Route Summary					
Roadway Condition Information						
Pavement Condition Rating (PCR)	59	59				
Surface Condition Rating (SCR)	59	59				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	88	88				
Alligator Crack Index	100	100				
Longitudinal Crack Index	88	88				
Transverse Cracking Index	59	59				
Patching Index	100	100				
Rutting Index	96	96				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	22.6	22.6				
Lane Width (ft)	9.2	9.2				

Gateway National Recreation Area ROUTE 0132B: HOUSING ACCESS (SANCHEZ ROAD WEST)



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Cond	ition Rating (PCR)		
Poor (0 - 60) Fair (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated	
Colors on map represent condition scores at 0.10-mile intervals. See Appendix for definitions and formulas.					
Inspection Date: 4/24/2021	Beginning Section MP	0			
Paved Length (Miles): 0.27	Section Length (MI)	0.27			
Surface Type: ASPHALT	Route Summary		•	• •	
Roadway Condition Information					
Pavement Condition Rating (PCR)	85	85			
Surface Condition Rating (SCR)	85	85			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	100	100			
Alligator Crack Index	100	100			
Longitudinal Crack Index	100	100			
Transverse Cracking Index	85	85			
Patching Index	100	100			
Rutting Index	100	100			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	20.2	20.2			
Lane Width (ft)	8.8	8.8			

ROUTE 0160: ATLANTIC DRIVE



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Condi	tion Rating (P	PCR)		
Poor (0 - 60) Fair (0	61- 84) Good ((85 - 94)	Excellent (9	5 - 100)	Not Rat	ed
Colors on map represent condition scores at 0.10-mile intervals. See Appendix for definitions and formulas.						
Inspection Date: 4/24/2021	Beginning Section MP	0	1			
Paved Length (Miles): 1.91	Section Length (MI)	1	0.91			
Surface Type: ASPHALT	Route Summary					
Roadway Condition Information						
Pavement Condition Rating (PCR)	95	93	99			
Surface Condition Rating (SCR)	99	99	99			
Roughness Condition Index (RCI)	90	84	98			
Distress Index Values						
Structural Crack Index	100	100	99			
Alligator Crack Index	100	100	100			
Longitudinal Crack Index	100	100	99			
Transverse Cracking Index	100	100	99			
Patching Index	100	100	100			
Rutting Index	99	99	99			
International Roughness Index (IRI)	139	157	120			
Lane & Width Information						
Number of Lanes	2	2	2			
Paved Width (ft)	22.5	27.4	22.2			
Lane Width (ft)	11.4	12	10.7			

Gateway National Recreation Area ROUTE 0161: HARTSHORNE DRIVE (SOUTHBOUND) RAMP K



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	e Condition Legend – Pav	ement Cond	ition Rating (PCR)	
Poor (0 - 60) Fair	(61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent co	ondition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/24/2021	Beginning Section MP	0		
Paved Length (Miles): 0.29	Section Length (MI)	0.29		
Surface Type: ASPHALT	Route Summary		•	• •
Roadway Condition Information				
Pavement Condition Rating (PCR)	6	6		
Surface Condition Rating (SCR)	6	6		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	6	6		
Alligator Crack Index	100	100		
Longitudinal Crack Index	6	6		
Transverse Cracking Index	9	9		
Patching Index	100	100		
Rutting Index	97	97		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	1	1		
Paved Width (ft)	14.2	14.2		
Lane Width (ft)	11.8	11.8		

Gateway National Recreation Area ROUTE 0162: HARTSHORNE DRIVE (SOUTHBOUND) RAMP L



Data Collection Vehicle (DCV) Rating

Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Condi	tion Rating (PCR)			
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated		
Colors on map represent condition scores at 0.10-mile intervals. See Appendix for definitions and formulas.						
Inspection Date: 4/24/2021	Beginning Section MP	0				
Paved Length (Miles): 0.18	Section Length (MI)	0.17				
Surface Type: CONCRETE	Route Summary					
Roadway Condition Information						
Pavement Condition Rating (PCR)	97	97				
Surface Condition Rating (SCR)	N/A	N/A				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	N/A	N/A				
Alligator Crack Index	N/A	N/A				
Longitudinal Crack Index	N/A	N/A				
Transverse Cracking Index	N/A	N/A				
Patching Index	N/A	N/A				
Rutting Index	N/A	N/A				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	1	1				
Paved Width (ft)	14.7	14.7				
Lane Width (ft)	11.2	11.2				

NOTE: MANUALLY RATED CONCRETE SECTION

ROUTE 0163ZZ: RANGE ROADS

Summary Route




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: The weighted average summary PCR value is calculated from only the sections of road where the PCR was collected. The overall PCR for the summary route may not reflect individual subcomponent ratings.

Route Condition Legend – Pavement Condition Rating (PCR)								
Poor (0 - 60) Fair (6	1- 84) Good	1- 84) Good (85 - 94)		Excellent (95 - 100)		ted		
	See Appendix for det	finitions and f	formulas					
Inspection Date: 4/23/2021								
Paved Length (Miles): 0.97								
Surface Type: ASPHALT	Route Summary				•			
Roadway Condition Information								
Pavement Condition Rating (PCR)	43							
Lane & Width Information								
Number of Lanes	1							
Paved Width (ft)	13.3							
Lane Width (ft)	11.3							

ROUTE 0163AZ: RANGE ROAD

Subcomponent of Route GATE-0163ZZ Data Collection Vehicle (DCV) Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

	Route (Condition Legend – Pav	ement Condi	tion Rating (PCR)		
Poor (0 - 60)	Fair (6	1- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Ra	ted
Colors on	map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix fo	r definitions	s and formulas.	
Inspection Date:	4/23/2021	Beginning Section MP	0				
Paved Length (Miles):	: 0.21	Section Length (MI)	0.21				
Surface Type:	CONCRETE	Route Summary					
Roadway Condition I	nformation						
Pavement Condition H	Rating (PCR)	73	73				
Surface Condition Rati	ng (SCR)	N/A	N/A				
Roughness Condition I	ndex (RCI)	N/A	N/A				
Distress Index Values							
Structural Crack Index	X	N/A	N/A				
Alligator Crack Index		N/A	N/A				
Longitudinal Crack In	ıdex	N/A	N/A				
Transverse Cracking I	ndex	N/A	N/A				
Patching Index		N/A	N/A				
Rutting Index		N/A	N/A				
International Roughne	ess Index (IRI)	N/A	N/A				
Lane & Width Inform	ation						
Number of Lanes		2	2				
Paved Width (ft)		17.7	17.7				
Lane Width (ft)		8.8	8.8				

NOTE: MANUALLY RATED CONCRETE SECTION

Gateway National Recreation Area ROUTE 0163BZ: BPD RANGE ROAD

Subcomponent of Route GATE-0163ZZ

Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Condi	tion Rating (PCR)					
Poor (0 - 60) Fair (0	61- 84) Good (84) Good (85 - 94) Excellent (95 - 100)		Not Rated				
See Appendix for definitions and formulas								
Inspection Date: 3/3/2021	Beginning Section MP	0.00						
Paved Length (Miles): 0.76	Section Length (MI)	0.76						
Surface Type: ASPHALT	Route Summary		•					
Roadway Condition Information								
Pavement Condition Rating (PCR)	30	30						
Surface Condition Rating (SCR)	30	30						
Roughness Condition Index (RCI)	N/A	N/A						
Distress Index Values								
Structural Crack Index	N/A	N/A						
Alligator Crack Index	30	30						
Longitudinal Crack Index	53	53						
Transverse Cracking Index	53	53						
Patching Index	73	73						
Rutting Index	90	90						
International Roughness Index (IRI)	N/A	N/A						
Lane & Width Information								
Number of Lanes	2	1						
Paved Width (ft)	12	12						
Lane Width (ft)	12	12						

Gateway National Recreation Area ROUTE 0163BZ: BPD RANGE ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0163BZ_1.jpg



GATE_0163BZ_12.jpg



GATE_0163BZ_14.jpg



GATE_0163BZ_10.jpg




GATE_0163BZ_13.jpg



GATE_0163BZ_8.jpg


Gateway National Recreation Area ROUTE 0200: FLOYD BENNETT FIELD ENTRANCE ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Condi	tion Rating (P	PCR)	
Poor (0 - 60) Fair (61- 84) Good (1- 84) Good (85 - 94)		5 - 100)	Not Rated
Colors on map represent co	ndition scores at 0.10-mile	e intervals. Se	e Appendix for	definitions	and formulas.
Inspection Date: 4/23/2021	Beginning Section MP	0	1		
Paved Length (Miles): 1.3	Section Length (MI)	1	0.29		
Surface Type: ASPHALT	Route Summary				•
Roadway Condition Information					
Pavement Condition Rating (PCR)	69	74	50		
Surface Condition Rating (SCR)	72	79	47		
Roughness Condition Index (RCI)	64	67	54		
Distress Index Values					
Structural Crack Index	82	86	69		
Alligator Crack Index	100	100	100		
Longitudinal Crack Index	82	86	69		
Transverse Cracking Index	72	79	47		
Patching Index	100	100	99		
Rutting Index	96	97	93		
International Roughness Index (IRI)	224	214	264		
Lane & Width Information					
Number of Lanes	2	2	2		
Paved Width (ft)	27.1	28	24.3		
Lane Width (ft)	12.2	12.3	12.2		


ROUTE 0201: RANGER ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Cond	ition Rating (PCR)	
Poor (0 - 60) Fair (61- 84) Good	Good (85 - 94)		Not Rated
Colors on map represent co	ndition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/23/2021	Beginning Section MP	0		
Paved Length (Miles): 0.56	Section Length (MI)	0.56		
Surface Type: ASPHALT	Route Summary		•	
Roadway Condition Information				
Pavement Condition Rating (PCR)	21	21		
Surface Condition Rating (SCR)	21	21		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	23	23		
Alligator Crack Index	96	96		
Longitudinal Crack Index	27	27		
Transverse Cracking Index	21	21		
Patching Index	97	97		
Rutting Index	95	95		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	24.7	24.7		
Lane Width (ft)	12.2	12.2		

ROUTE 0203: ENTERPRISE AVENUE



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Cond	ition Rating (PCR)	
Poor (0 - 60) Fair	(61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent co	ondition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/23/2021	Beginning Section MP	0		
Paved Length (Miles): 0.15	Section Length (MI)	0.15		
Surface Type: ASPHALT	Route Summary		• •	•
Roadway Condition Information				
Pavement Condition Rating (PCR)	20	20		
Surface Condition Rating (SCR)	20	20		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	65	65		
Alligator Crack Index	100	100		
Longitudinal Crack Index	65	65		
Transverse Cracking Index	20	20		
Patching Index	98	98		
Rutting Index	99	99		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	27	27		
Lane Width (ft)	13.5	13.5		

ROUTE 0205: RIDING ACADEMY ACCESS ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated		
	See Appendix for def	initions and f	ormulas			
Inspection Date: 3/4/2021	Beginning Section MP	0.00				
Paved Length (Miles): 0.20	Section Length (MI)	0.20				
Surface Type: ASPHALT	Route Summary		•	•		
Roadway Condition Information						
Pavement Condition Rating (PCR)	97	97				
Surface Condition Rating (SCR)	97	97				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	N/A	N/A				
Alligator Crack Index	97	97				
Longitudinal Crack Index	97	97				
Transverse Cracking Index	97	97				
Patching Index	97	97				
Rutting Index	97	97				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	1	1				
Paved Width (ft)	11	11				
Lane Width (ft)	11	11				

Gateway National Recreation Area ROUTE 0205: RIDING ACADEMY ACCESS ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0205_1.jpg



GATE_0205_3.jpg



GATE_0205_5.jpg



GATE_0205_2.jpg




GATE_0205_4.jpg



GATE_0205_6.jpg

ROUTE 0206: TAXIWAY C ACCESS ROAD




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Condition Legend – Pav	ement Condi	tion Rating (PCR)			
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated		
Colors on map represent condition scores at 0.10-mile intervals. See Appendix for definitions and formulas.						
Inspection Date: 4/23/2021	Beginning Section MP	0				
Paved Length (Miles): 0.1	Section Length (MI)	0.1				
Surface Type: ASPHALT	Route Summary		•			
Roadway Condition Information						
Pavement Condition Rating (PCR)	17	17				
Surface Condition Rating (SCR)	17	17				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	24	24				
Alligator Crack Index	100	100				
Longitudinal Crack Index	24	24				
Transverse Cracking Index	17	17				
Patching Index	100	100				
Rutting Index	96	96				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	24.8	24.8				
Lane Width (ft)	12.4	12.4				

Gateway National Recreation Area ROUTE 0211: SOUTH BARRETT ROAD

Data Collection Vehicle (DCV) Rating




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated		
Colors on map represent con	dition scores at 0.10-mile	intervals. Se	e Appendix for definition	ons and formulas.		
Inspection Date: 4/23/2021	Beginning Section MP	0				
Paved Length (Miles): 0.17	Section Length (MI)	0.17				
Surface Type: ASPHALT	Route Summary					
Roadway Condition Information						
Pavement Condition Rating (PCR)	53	53				
Surface Condition Rating (SCR)	88	88				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	N/A	N/A				
Alligator Crack Index	N/A	N/A				
Longitudinal Crack Index	N/A	N/A				
Transverse Cracking Index	N/A	N/A				
Patching Index	N/A	N/A				
Rutting Index	N/A	N/A				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	1	1				
Paved Width (ft)	15.5	15.5				
Lane Width (ft)	15.5	15.5				

NOTE: MANUALLY RATED CONCRETE SECTION


ROUTE 0212: HEINZELMAN ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Condition Legend – Pav	ement Condi	tion Rating (PCI	R)	
Poor (0 - 60) Fair (6)	<mark>1- 84) Good (</mark>	(85 - 94)	Excellent (95 -	100) No	ot Rated
Colors on map represent condition scores at 0.10-mile intervals. See Appendix for definitions and formulas.					
Inspection Date: 4/23/2021	Beginning Section MP	0			
Paved Length (Miles): 0.12	Section Length (MI)	0.12			
Surface Type: ASPHALT	Route Summary			•	•
Roadway Condition Information					
Pavement Condition Rating (PCR)	0	0			
Surface Condition Rating (SCR)	0	0			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	38	38			
Alligator Crack Index	95	95			
Longitudinal Crack Index	43	43			
Transverse Cracking Index	0	0			
Patching Index	99	99			
Rutting Index	86	86			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	19	19			
Lane Width (ft)	8.8	8.8			

Gateway National Recreation Area ROUTE 0213: WORCESTER ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Condition Legend – Pav	ement Condi	ition Rating (PCR)	
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix for definitio	ns and formulas.
Inspection Date: 4/23/2021	Beginning Section MP	0		
Paved Length (Miles): 0.08	Section Length (MI)	0.08		
Surface Type: ASPHALT	Route Summary			
Roadway Condition Information				
Pavement Condition Rating (PCR)	0	0		
Surface Condition Rating (SCR)	0	0		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	0	0		
Alligator Crack Index	80	80		
Longitudinal Crack Index	8	8		
Transverse Cracking Index	32	32		
Patching Index	99	99		
Rutting Index	93	93		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	1	1		
Paved Width (ft)	14.9	14.9		
Lane Width (ft)	11.8	11.8		

Gateway National Recreation Area ROUTE 0214: HAHN ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Condition Legend – Pav	ement Condi	tion Rating (PCR)		
Poor (0 - 60) Fair (6	1- 84) Good (85 - 94)		Excellent (95 - 100)	Not Rated	
Colors on map represent condition scores at 0.10-mile intervals. See Appendix for definitions and formulas.					
Inspection Date: 4/23/2021	Beginning Section MP	0			
Paved Length (Miles): 0.29	Section Length (MI)	0.29			
Surface Type: ASPHALT	Route Summary				
Roadway Condition Information					
Pavement Condition Rating (PCR)	0	0			
Surface Condition Rating (SCR)	0	0			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	15	15			
Alligator Crack Index	99	99			
Longitudinal Crack Index	16	16			
Transverse Cracking Index	0	0			
Patching Index	99	99			
Rutting Index	94	94			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	20.8	20.8			
Lane Width (ft)	9.8	9.8			

Gateway National Recreation Area ROUTE 0215: ATHLETIC DRIVE




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Condition Legend – Pav	ement Condi	tion Rating (PCR	R)	
Poor (0 - 60) Fair (6	1- 84) Good (85 - 94)		Excellent (95 - 1	100) Not R	ated
Colors on map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix for det	finitions and formula	s.
Inspection Date: 4/23/2021	Beginning Section MP	0			
Paved Length (Miles): 0.1	Section Length (MI)	0.1			
Surface Type: ASPHALT	Route Summary				•
Roadway Condition Information					
Pavement Condition Rating (PCR)	36	36			
Surface Condition Rating (SCR)	36	36			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	66	66			
Alligator Crack Index	100	100			
Longitudinal Crack Index	66	66			
Transverse Cracking Index	36	36			
Patching Index	99	99			
Rutting Index	96	96			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	1	1			
Paved Width (ft)	14.1	14.1			
Lane Width (ft)	14.1	14.1			

Gateway National Recreation Area ROUTE 0216: HERO ROAD

Data Collection Vehicle (DCV) Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Condition Legend – Pav	ement Condi	tion Rating (P	CR)			
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95	- 100)	Not Rated		
Colors on map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix for	definitions	and formulas.		
Inspection Date: 4/23/2021	Beginning Section MP	0					
Paved Length (Miles): 0.36	Section Length (MI)	0.36					
Surface Type: ASPHALT	Route Summary						
Roadway Condition Information							
Pavement Condition Rating (PCR)	29	29					
Surface Condition Rating (SCR)	29	29					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	76	76					
Alligator Crack Index	100	100					
Longitudinal Crack Index	76	76					
Transverse Cracking Index	29	29					
Patching Index	99	99					
Rutting Index	98	98					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	19.5	19.5					
Lane Width (ft)	9.5	9.5					

NOTE: End of route is concrete starting at mile point 0.24.

Gateway National Recreation Area ROUTE 0222: BREEZY POINT SURF CLUB ENTRANCE ROAD




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6	61- 84) Good (85 - 94)		Excellent (95 -	100) Not Ra	Not Rated	
Colors on map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix for de	finitions and formulas		
Inspection Date: 4/23/2021	Beginning Section MP	0				
Paved Length (Miles): 0.38	Section Length (MI)	0.38				
Surface Type: ASPHALT	Route Summary			•	•	
Roadway Condition Information						
Pavement Condition Rating (PCR)	93	93				
Surface Condition Rating (SCR)	93	93				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	100	100				
Alligator Crack Index	100	100				
Longitudinal Crack Index	100	100				
Transverse Cracking Index	98	98				
Patching Index	100	100				
Rutting Index	93	93				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	26.1	26.1				
Lane Width (ft)	10.2	10.2				

ROUTE 0224: BEACH 193RD STREET





Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	e Condition Legend – Pav	ement Condi	tion Rating (PCR)		
Poor (0 - 60) Fair	(61- 84) Good	61- 84) Good (85 - 94)		Not Rated	
Colors on map represent co	ondition scores at 0.10-mile	e intervals. Se	e Appendix for definitio	ns and formulas.	
Inspection Date: 4/23/2021	Beginning Section MP	0			
Paved Length (Miles): 0.2	Section Length (MI)	0.2			
Surface Type: ASPHALT	Route Summary		•		
Roadway Condition Information					
Pavement Condition Rating (PCR)	51	51			
Surface Condition Rating (SCR)	51	51			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	61	61			
Alligator Crack Index	100	100			
Longitudinal Crack Index	61	61			
Transverse Cracking Index	51	51			
Patching Index	100	100			
Rutting Index	97	97			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	30.2	30.2			
Lane Width (ft)	15.1	15.1			

ROUTE 0225: POST OFFICE ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60) Fai	r (61- 84) Good (1- 84) Good (85 - 94)		Not Rated			
See Appendix for definitions and formulas							
Inspection Date: 3/3/2021	Beginning Section MP	0.00					
Paved Length (Miles): 0.04	Section Length (MI)	0.04					
Surface Type: CONCRETE	Route Summary		• •	• •			
Roadway Condition Information							
Pavement Condition Rating (PCR)	90	90					
Surface Condition Rating (SCR)	90	90					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	N/A	N/A					
Alligator Crack Index	N/A	N/A					
Longitudinal Crack Index	N/A	N/A					
Transverse Cracking Index	N/A	N/A					
Patching Index	N/A	N/A					
Rutting Index	N/A	N/A					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	1	1					
Paved Width (ft)	15	15					
Lane Width (ft)	15	15					

ROUTE 0225: POST OFFICE ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0225_1.jpg



GATE_0225_3.jpg



GATE_0225_5.jpg



GATE_0225_2.jpg




GATE_0225_4.jpg



GATE_0225_6.jpg

ROUTE 0226: NORTH BARETTE



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6	Good (85 - 94)		Excellent (95 - 100)	Not Rated		
See Appendix for definitions and formulas						
Inspection Date: 3/3/2021	Beginning Section MP	0.00				
Paved Length (Miles): 0.07	Section Length (MI)	0.07				
Surface Type: CONCRETE	Route Summary			• •		
Roadway Condition Information						
Pavement Condition Rating (PCR)	73	73				
Surface Condition Rating (SCR)	73	73				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	N/A	N/A				
Alligator Crack Index	N/A	N/A				
Longitudinal Crack Index	N/A	N/A				
Transverse Cracking Index	N/A	N/A				
Patching Index	N/A	N/A				
Rutting Index	N/A	N/A				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	20	20				
Lane Width (ft)	10	10				

Gateway National Recreation Area ROUTE 0226: NORTH BARETTE

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0226_2.jpg



GATE_0226_4.jpg



GATE_0226_7.jpg



GATE_0226_3.jpg



GATE_0226_6.jpg



GATE_0226_9.jpg

Gateway National Recreation Area ROUTE 0227ZZ: ROMERO ROAD EAST AND WEST

Summary Route

Rife. ON TIT	
F	
BARRETRD	

Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: The weighted average summary PCR value is calculated from only the sections of road where the PCR was collected. The overall PCR for the summary route may not reflect individual subcomponent ratings.

	Route C	Condition Legend – Pa	vement Cond	lition Rating (PCR)		
Poor (0 - 60) Fair (61		1- 84) Good (85 - 94		Excellent (95 - 100)		Not Rated	
	See Appendix for definitions and formulas						
Inspection Date:	3/3/2021						
Paved Length (Mile	es): 0.05						
Surface Type:	CONCRETE	Route Summary		•		•	
Roadway Condition Information							
Pavement Conditio	n Rating (PCR)	90					
Lane & Width Info	rmation						
Number of Lanes		2					
Paved Width (ft)		20					
Lane Width (ft)		10					

Gateway National Recreation Area ROUTE 0227AZ: ROMERO ROAD WEST

Subcomponent of Route GATE-0227ZZ Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pave	ement Condi	ition Rating (PCR)				
Poor (0 - 60) Fair (<mark>61- 84) Good (</mark>	85 - 94)	Excellent (95 - 100)	Not Rated			
See Appendix for definitions and formulas							
Inspection Date: 3/3/2021	Beginning Section MP	0.00					
Paved Length (Miles): 0.03	Section Length (MI)	0.03					
Surface Type: CONCRETE	Route Summary						
Roadway Condition Information							
Pavement Condition Rating (PCR)	90	90					
Surface Condition Rating (SCR)	90	90					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	N/A	N/A					
Alligator Crack Index	N/A	N/A					
Longitudinal Crack Index	N/A	N/A					
Transverse Cracking Index	N/A	N/A					
Patching Index	N/A	N/A					
Rutting Index	N/A	N/A					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	20	20					
Lane Width (ft)	10	10					

Gateway National Recreation Area ROUTE 0227AZ: ROMERO ROAD WEST

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0227AZ_1.jpg



GATE_0227AZ_3.jpg



GATE_0227AZ_5.jpg



GATE_0227AZ_2.jpg



GATE_0227AZ_4.jpg



GATE_0227AZ_6.jpg

Gateway National Recreation Area ROUTE 0227BZ: ROMERO ROAD EAST

Subcomponent of Route GATE-0227ZZ Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

F	Route Condition Legend –	Pavement Cond	ition Rating (PCR)				
Poor (0 - 60)	Fair (61- 84) G	ood (85 - 94)	Excellent (95 - 100)	Not Rated			
See Appendix for definitions and formulas							
Inspection Date: 3/3/2021	Beginning Section	MP 0.00					
Paved Length (Miles): 0.03	Section Length (N	II) 0.03					
Surface Type: CONCRET	TE Route Summary		•	•			
Roadway Condition Information							
Pavement Condition Rating (PCR	.) 90	90					
Surface Condition Rating (SCR)	90	90					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	N/A	N/A					
Alligator Crack Index	N/A	N/A					
Longitudinal Crack Index	N/A	N/A					
Transverse Cracking Index	N/A	N/A					
Patching Index	N/A	N/A					
Rutting Index	N/A	N/A					
International Roughness Index (II	RI) N/A	N/A					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	20	20					
Lane Width (ft)	10	10					

Gateway National Recreation Area ROUTE 0227BZ: ROMERO ROAD EAST

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0227BZ_1.jpg



GATE_0227BZ_3.jpg



GATE_0227BZ_5.jpg



GATE_0227BZ_2.jpg



GATE_0227BZ_4.jpg



GATE_0227BZ_7.jpg


ROUTE 0228: THEATER ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Rout	e Condition Legend – Pav	ement Cond	ition Rating (PCR)	
Poor (0 - 60) Fair	(61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent c	ondition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/23/2021	Beginning Section MP	0		
Paved Length (Miles): 0.19	Section Length (MI)	0.19		
Surface Type: ASPHALT	Route Summary			• •
Roadway Condition Information				
Pavement Condition Rating (PCR)	13	13		
Surface Condition Rating (SCR)	13	13		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	54	54		
Alligator Crack Index	100	100		
Longitudinal Crack Index	54	54		
Transverse Cracking Index	13	13		
Patching Index	100	100		
Rutting Index	95	95		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	23.4	23.4		
Lane Width (ft)	11.7	11.7		

ROUTE 0229: CHAPEL ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)								
Poor (0 - 60) F a	ir (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated				
	See Appendix for definitions and formulas							
Inspection Date: 3/3/2021	Beginning Section MP	0.00						
Paved Length (Miles): 0.06	Section Length (MI)	0.06						
Surface Type: ASPHALT	Route Summary							
Roadway Condition Information								
Pavement Condition Rating (PCR)	30	30						
Surface Condition Rating (SCR)	30	30						
Roughness Condition Index (RCI)	N/A	N/A						
Distress Index Values								
Structural Crack Index	N/A	N/A						
Alligator Crack Index	30	30						
Longitudinal Crack Index	90	90						
Transverse Cracking Index	90	90						
Patching Index	97	97						
Rutting Index	97	97						
International Roughness Index (IRI)) N/A	N/A						
Lane & Width Information								
Number of Lanes	1	1						
Paved Width (ft)	10	10						
Lane Width (ft)	10	10						

Gateway National Recreation Area ROUTE 0229: CHAPEL ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0229_1.jpg



GATE_0229_4.jpg



GATE_0229_7.jpg



GATE_0229_3.jpg




GATE_0229_6.jpg



GATE_0229_9.jpg

ROUTE 0230: STEELE ROAD

Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60) Fair	(61- 84) Good	1- 84) Good (85 - 94)		Not Rated			
See Appendix for definitions and formulas							
Inspection Date: 3/3/2021	Beginning Section MP	0.00					
Paved Length (Miles): 0.05	Section Length (MI)	0.05					
Surface Type: ASPHALT	Route Summary						
Roadway Condition Information							
Pavement Condition Rating (PCR)	73	73					
Surface Condition Rating (SCR)	73	73					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	N/A	N/A					
Alligator Crack Index	97	97					
Longitudinal Crack Index	90	90					
Transverse Cracking Index	73	73					
Patching Index	90	90					
Rutting Index	97	97					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	20	20					
Lane Width (ft)	10	10					

ROUTE 0230: STEELE ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0230_1.jpg



GATE_0230_3.jpg



GATE_0230_6.jpg



GATE_0230_2.jpg




GATE_0230_5.jpg



GATE_0230_7.jpg

Gateway National Recreation Area ROUTE 0234: SILVER GULL BEACH CLUB ENTRANCE ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Condition Legend – Pav	ement Condi	tion Rating (PCR)	
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 10	0) Not Rated
Colors on map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix for defir	itions and formulas.
Inspection Date: 4/23/2021	Beginning Section MP	0		
Paved Length (Miles): 0.19	Section Length (MI)	0.19		
Surface Type: ASPHALT	Route Summary		•	
Roadway Condition Information				
Pavement Condition Rating (PCR)	1	1		
Surface Condition Rating (SCR)	1	1		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	33	33		
Alligator Crack Index	100	100		
Longitudinal Crack Index	33	33		
Transverse Cracking Index	1	1		
Patching Index	97	97		
Rutting Index	91	91		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	1	1		
Paved Width (ft)	32.6	32.6		
Lane Width (ft)	19.3	19.3		


Gateway National Recreation Area ROUTE 0235: ROCKAWAY POINT YACHT CLUB ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated	
Colors on map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix for definiti	ons and formulas.	
Inspection Date: 4/23/2021	Beginning Section MP	0			
Paved Length (Miles): 0.26	Section Length (MI)	0.26			
Surface Type: ASPHALT	Route Summary				
Roadway Condition Information					
Pavement Condition Rating (PCR)	51	51			
Surface Condition Rating (SCR)	51	51			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	77	77			
Alligator Crack Index	98	98			
Longitudinal Crack Index	79	79			
Transverse Cracking Index	51	51			
Patching Index	100	100			
Rutting Index	93	93			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	1	1			
Paved Width (ft)	14.4	14.4			
Lane Width (ft)	14.4	14.4			

ROUTE 0402: COMMUNITY GARDEN ACCESS ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60) Fair (6	61- 84) Good (1- 84) Good (85 - 94)		Not Rated			
See Appendix for definitions and formulas							
Inspection Date: 3/4/2021	Beginning Section MP	0.00					
Paved Length (Miles): 0.24	Section Length (MI)	0.24					
Surface Type: ASPHALT	Route Summary			• •			
Roadway Condition Information							
Pavement Condition Rating (PCR)	53	53					
Surface Condition Rating (SCR)	53	53					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	N/A	N/A					
Alligator Crack Index	53	53					
Longitudinal Crack Index	90	90					
Transverse Cracking Index	90	90					
Patching Index	97	97					
Rutting Index	97	97					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	1	1					
Paved Width (ft)	24	24					
Lane Width (ft)	24	24					

Gateway National Recreation Area ROUTE 0402: COMMUNITY GARDEN ACCESS ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0402_3.jpg



GATE_0402_6.jpg



GATE_0402_8.jpg



GATE_0402_5.jpg



GATE_0402_7.jpg



GATE_0402_9.jpg

ROUTE 0403: RUNWAY C

Data Collection Vehicle (DCV) Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Condi	tion Rating (PCR)		
Poor (0 - 60) Fair (61- 84) Good (8		(85 - 94)	Excellent (9	95 - 100)	Not Rated	
Colors on map represent co	ndition scores at 0.10-mile	e intervals. Se	e Appendix fo	r definitions	and formulas.	
Inspection Date: 4/23/2021	Beginning Section MP	0	1			
Paved Length (Miles): 1.1	Section Length (MI)	1	0.1			
Surface Type: ASPHALT	Route Summary				• •	
Roadway Condition Information						
Pavement Condition Rating (PCR)	23	27	20			
Surface Condition Rating (SCR)	N/A	0	11			
Roughness Condition Index (RCI)	N/A	67	34			
Distress Index Values						
Structural Crack Index	N/A	0	11			
Alligator Crack Index	N/A	100	100			
Longitudinal Crack Index	N/A	0	11			
Transverse Cracking Index	N/A	0	22			
Patching Index	N/A	100	100			
Rutting Index	N/A	94	94			
International Roughness Index (IRI)	N/A	212	379			
Lane & Width Information						
Number of Lanes	4	4	4			
Paved Width (ft)	48	48	48			
Lane Width (ft)	11.8	11.8	11.6			

NOTE: MANUALLY RATED CONCRETE SECTION

ROUTE 0405: TAXIWAY B




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

R	oute Condition Legend – Pa	vement Cond	ition Rating (PCR)	
Poor (0 - 60)	air (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represe	nt condition scores at 0.10-mil	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/23/2021	Beginning Section MI	P 0		
Paved Length (Miles): 0.5	Section Length (MI)	0.5		
Surface Type: ASPHALT	Route Summary		•	•
Roadway Condition Information				
Pavement Condition Rating (PCR)	31	31		
Surface Condition Rating (SCR)	29	29		
Roughness Condition Index (RCI)	34	34		
Distress Index Values				
Structural Crack Index	30	30		
Alligator Crack Index	100	100		
Longitudinal Crack Index	30	30		
Transverse Cracking Index	29	29		
Patching Index	98	98		
Rutting Index	91	91		
International Roughness Index (IR	I) 380	380		
Lane & Width Information				
Number of Lanes	4	4		
Paved Width (ft)	48	48		
Lane Width (ft)	35.2	35.2		

ROUTE 0406: TAXIWAY A

Data Collection Vehicle (DCV) Rating




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

	Route Condition Legen	d – Pavement Cond	lition Rating (PCR)	
Poor (0 - 60)	Fair (61- 84)	Good (85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map repres	sent condition scores at 0	.10-mile intervals. S	ee Appendix for definition	ns and formulas.
Inspection Date: 4/23/2021	Beginning Sect	ion MP 0		
Paved Length (Miles): 0.69	Section Length	(MI) 0.69		
Surface Type: CONCRE	TE Route Summar	·y	• •	
Roadway Condition Information	n			
Pavement Condition Rating (PC	R) 73	73		
Surface Condition Rating (SCR)	N/A	N/A		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	N/A	N/A		
Alligator Crack Index	N/A	N/A		
Longitudinal Crack Index	N/A	N/A		
Transverse Cracking Index	N/A	N/A		
Patching Index	N/A	N/A		
Rutting Index	N/A	N/A		
International Roughness Index (I	(RI) N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	48	48		
Lane Width (ft)	71.5	71.5		

NOTE: MANUALLY RATED CONCRETE SECTION


ROUTE 0408: RUNWAY A (SOUTHERN RUNWAY)



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Rout	e Condition Legend – Pav	ement Condi	ition Rating (P	PCR)	
Poor (0 - 60) Fair	Poor (0 - 60) Fair (61- 84) Good (8		Excellent (9	5 - 100)	Not Rated
Colors on map represent c	ondition scores at 0.10-mile	e intervals. Se	e Appendix for	definitions	and formulas.
Inspection Date: 4/23/2021	Beginning Section MP	0	1		
Paved Length (Miles): 1.09	Section Length (MI)	1	0.09		
Surface Type: ASPHALT	Route Summary				
Roadway Condition Information					
Pavement Condition Rating (PCR)	42	39	46		
Surface Condition Rating (SCR)	28	21	56		
Roughness Condition Index (RCI)	63	67	31		
Distress Index Values					
Structural Crack Index	28	21	100		
Alligator Crack Index	100	100	100		
Longitudinal Crack Index	28	21	100		
Transverse Cracking Index	48	43	100		
Patching Index	100	100	100		
Rutting Index	80	82	56		
International Roughness Index (IRI)	228	213	398		
Lane & Width Information					
Number of Lanes	4	4	2		
Paved Width (ft)	86.5	82.6	129.4		
Lane Width (ft)	23.2	19	64.7		


ROUTE 0410: TAXIWAY C



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

	Route Condition Legend – Pa	vement Cond	ition Rating (PCR)	
Poor (0 - 60)	Fair (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map repres	ent condition scores at 0.10-mi	le intervals. Se	e Appendix for definition	as and formulas.
Inspection Date: 4/23/2021	Beginning Section M	P 0		
Paved Length (Miles): 0.35	Section Length (MI)	0.35		
Surface Type: ASPHALT	Route Summary		•	
Roadway Condition Information	L			
Pavement Condition Rating (PCI	R) 26	26		
Surface Condition Rating (SCR)	26	26		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	26	26		
Alligator Crack Index	100	100		
Longitudinal Crack Index	26	26		
Transverse Cracking Index	51	51		
Patching Index	100	100		
Rutting Index	94	94		
International Roughness Index (I	RI) N/A	N/A		
Lane & Width Information				
Number of Lanes	4	4		
Paved Width (ft)	48	48		
Lane Width (ft)	8.6	8.6		

ROUTE 0415: NIKE MAINTENANCE ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60) Fair (61- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated			
See Appendix for definitions and formulas							
Inspection Date: 3/3/2021	Beginning Section MP	0.00					
Paved Length (Miles): 0.18	Section Length (MI)	0.18					
Surface Type: ASPHALT	Route Summary						
Roadway Condition Information							
Pavement Condition Rating (PCR)	53	53					
Surface Condition Rating (SCR)	53	53					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	N/A	N/A					
Alligator Crack Index	53	53					
Longitudinal Crack Index	73	73					
Transverse Cracking Index	73	73					
Patching Index	90	90					
Rutting Index	90	90					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	20	20					
Lane Width (ft)	10	10					

Gateway National Recreation Area ROUTE 0415: NIKE MAINTENANCE ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0415_1.jpg



GATE_0415_4.jpg



GATE_0415_6.jpg



GATE_0415_11.jpg



GATE_0415_5.jpg



GATE_0415_7.jpg

ROUTE 0419: JAMAICA BAY RESIDENCE ROAD

Mar	ual Rating	
	Rte. 0419 0	

Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60)	Fair (6	6 <mark>1- 84) Good (</mark>	85 - 94)	Excellent (9	95 - 100)	Not Ra	ted
		See Appendix for defi	initions and f	ormulas			
Inspection Date:	3/4/2021	Beginning Section MP	0.00				
Paved Length (Miles)): 0.02	Section Length (MI)	0.02				
Surface Type:	ASPHALT	Route Summary				•	
Roadway Condition	Information						
Pavement Condition	Rating (PCR)	73	73				
Surface Condition Rat	ting (SCR)	73	73				
Roughness Condition	Index (RCI)	N/A	N/A				
Distress Index Values	5						
Structural Crack Inde	ex	N/A	N/A				
Alligator Crack Inde	X	73	73				
Longitudinal Crack I	ndex	90	90				
Transverse Cracking	Index	90	90				
Patching Index		90	90				
Rutting Index		97	97				
International Roughr	ness Index (IRI)	N/A	N/A				
Lane & Width Inform	nation						
Number of Lanes		2	2				
Paved Width (ft)		20	20				
Lane Width (ft)		10	10				

Gateway National Recreation Area ROUTE 0419: JAMAICA BAY RESIDENCE ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0419_1.jpg



GATE_0419_3.jpg



GATE_0419_5.jpg



GATE_0419_2.jpg



GATE_0419_4.jpg



GATE_0419_6.jpg

ROUTE 0437: ACCESS TO ATHLETIC FIELD ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)								
Poor (0 - 60) Fair (0	61- 84) Good (85 - 94)	Excellent (95 - 100)	Not Rated				
See Appendix for definitions and formulas								
Inspection Date: 3/4/2021	Beginning Section MP	0.00						
Paved Length (Miles): 0.89	Section Length (MI)	0.89						
Surface Type: ASPHALT	Route Summary		•	•				
Roadway Condition Information								
Pavement Condition Rating (PCR)	N/A	N/A						
Surface Condition Rating (SCR)	N/A	N/A						
Roughness Condition Index (RCI)	N/A	N/A						
Distress Index Values								
Structural Crack Index	N/A	N/A						
Alligator Crack Index	N/A	N/A						
Longitudinal Crack Index	N/A	N/A						
Transverse Cracking Index	N/A	N/A						
Patching Index	N/A	N/A						
Rutting Index	N/A	N/A						
International Roughness Index (IRI)	N/A	N/A						
Lane & Width Information								
Number of Lanes	1	1						
Paved Width (ft)	15	15						
Lane Width (ft)	15	15						

NOTE: NOT COLLECTED DUE TO RADIATION ZONE. HAZARDOUS AREA, MENTIONED BY LOCAL PARK POLICE AND POSTED SIGNAGE TO KEEP OUT.

Gateway National Recreation Area ROUTE 0437: ACCESS TO ATHLETIC FIELD ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0437_1.jpg



GATE_0437_2.jpg



GATE_0437_3.jpg




GATE_0437_5.jpg



GATE_0437_4.jpg

ROUTE 0438: AYERS ROAD

Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6)	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated			
See Appendix for definitions and formulas							
Inspection Date: 3/5/2021	Beginning Section MP	0.00					
Paved Length (Miles): 0.31	Section Length (MI)	0.31					
Surface Type: ASPHALT	Route Summary						
Roadway Condition Information							
Pavement Condition Rating (PCR)	30	30					
Surface Condition Rating (SCR)	30	30					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	N/A	N/A					
Alligator Crack Index	30	30					
Longitudinal Crack Index	73	73					
Transverse Cracking Index	73	73					
Patching Index	73	73					
Rutting Index	90	90					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	1	1					
Paved Width (ft)	20.2	20.2					
Lane Width (ft)	20.2	20.2					

ROUTE 0438: AYERS ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0438_10.jpg



GATE_0438_17.jpg



GATE_0438_5.jpg



GATE_0438_13.jpg



GATE_0438_18.jpg



GATE_0438_6.jpg

ROUTE 0439: PATH ROAD (NAVY LODGE)




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 -	100)	Not Rated	
Colors on map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix for de	finitions and for	rmulas.	
Inspection Date: 4/24/2021	Beginning Section MP	0				
Paved Length (Miles): 0.09	Section Length (MI)	0.09				
Surface Type: ASPHALT	Route Summary			•	•	
Roadway Condition Information						
Pavement Condition Rating (PCR)	44	44				
Surface Condition Rating (SCR)	44	44				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	44	44				
Alligator Crack Index	100	100				
Longitudinal Crack Index	44	44				
Transverse Cracking Index	59	59				
Patching Index	99	99				
Rutting Index	87	87				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	22.9	22.9				
Lane Width (ft)	10.9	10.9				

Gateway National Recreation Area ROUTE 0440ZZ: NY AVENUE / BATTERY ROAD

Summary Route




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: The weighted average summary PCR value is calculated from only the sections of road where the PCR was collected. The overall PCR for the summary route may not reflect individual subcomponent ratings.

	Route C	Condition Legend –	Pavement Cond	lition Rating (PCR)	
Poor (0 - 60) Fair (61		<mark>1- 84) Ga</mark>	od (85 - 94)	Excellent (95 - 100)	Not Rated
		See Appendix for	definitions and	formulas	
Inspection Date:	4/24/2021				
Paved Length (Mile	es): 0.65				
Surface Type:	ASPHALT	Route Summary			•
Roadway Condition	n Information				
Pavement Conditio	on Rating (PCR)	48			
Lane & Width Info	rmation				
Number of Lanes		2			
Paved Width (ft)		27.9			
Lane Width (ft)		14.7			

ROUTE 0440AZ: NY AVENUE

Subcomponent of Route GATE-0440ZZ Data Collection Vehicle (DCV) Rating




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95	5 - 100)	Not Ra	ted
Colors on map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix for	definitions	and formulas.	
Inspection Date: 4/24/2021	Beginning Section MP	0				
Paved Length (Miles): 0.4	Section Length (MI)	0.4				
Surface Type: ASPHALT	Route Summary					
Roadway Condition Information						
Pavement Condition Rating (PCR)	52	52				
Surface Condition Rating (SCR)	52	52				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	52	52				
Alligator Crack Index	99	99				
Longitudinal Crack Index	53	53				
Transverse Cracking Index	76	76				
Patching Index	100	100				
Rutting Index	98	98				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	27	27				
Lane Width (ft)	14.4	14.4				

Gateway National Recreation Area ROUTE 0440BZ: BATTERY ROAD

Subcomponent of Route GATE-0440ZZ Data Collection Vehicle (DCV) Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

R	oute Condition Legend – Pav	vement Cond	ition Rating (PCR)	
	, , , , , , , , , , , , , , , , , , ,	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represen	nt condition scores at 0.10-mil	e intervals. Se	ee Appendix for definition	ns and formulas.
Inspection Date: 4/24/2021	Beginning Section MF	0		
Paved Length (Miles): 0.25	Section Length (MI)	0.25		
Surface Type: ASPHALT	Route Summary		•	• •
Roadway Condition Information				
Pavement Condition Rating (PCR)	41	41		
Surface Condition Rating (SCR)	41	41		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	41	41		
Alligator Crack Index	100	100		
Longitudinal Crack Index	41	41		
Transverse Cracking Index	49	49		
Patching Index	99	99		
Rutting Index	97	97		
International Roughness Index (IR	I) N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	29.2	29.2		
Lane Width (ft)	15.1	15.1		

ROUTE 0441: MONT SEC AVENUE



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated		
Colors on map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix for definiti	ons and formulas.		
Inspection Date: 4/24/2021	Beginning Section MP	0				
Paved Length (Miles): 0.14	Section Length (MI)	0.14				
Surface Type: ASPHALT	Route Summary					
Roadway Condition Information						
Pavement Condition Rating (PCR)	69	69				
Surface Condition Rating (SCR)	69	69				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	69	69				
Alligator Crack Index	100	100				
Longitudinal Crack Index	69	69				
Transverse Cracking Index	89	89				
Patching Index	100	100				
Rutting Index	98	98				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	28.5	28.5				
Lane Width (ft)	14.1	14.1				

ROUTE 0442: NORTH ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6)	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated			
See Appendix for definitions and formulas							
Inspection Date: 3/5/2021	Beginning Section MP	0.00					
Paved Length (Miles): 0.14	Section Length (MI)	0.14					
Surface Type: ASPHALT	Route Summary						
Roadway Condition Information							
Pavement Condition Rating (PCR)	90	90					
Surface Condition Rating (SCR)	90	90					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	N/A	N/A					
Alligator Crack Index	97	97					
Longitudinal Crack Index	90	90					
Transverse Cracking Index	90	90					
Patching Index	97	97					
Rutting Index	97	97					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	20	20					
Lane Width (ft)	10	10					

Gateway National Recreation Area ROUTE 0442: NORTH ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0442_1.jpg



GATE_0442_3.jpg



GATE_0442_6.jpg



GATE_0442_2.jpg



GATE_0442_5.jpg



GATE_0442_7.jpg


ROUTE 0443: SOUTH ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6)	1- 84) Good ((85 - 94)	Excellent (95	- 100)	Not Ra	ted
Colors on map represent cond	lition scores at 0.10-mile	e intervals. Se	e Appendix for a	definitions	and formulas.	
Inspection Date: 4/24/2021	Beginning Section MP	0				
Paved Length (Miles): 0.14	Section Length (MI)	0.14				
Surface Type: ASPHALT	Route Summary					
Roadway Condition Information						
Pavement Condition Rating (PCR)	82	82				
Surface Condition Rating (SCR)	82	82				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	87	87				
Alligator Crack Index	99	99				
Longitudinal Crack Index	88	88				
Transverse Cracking Index	82	82				
Patching Index	100	100				
Rutting Index	95	95				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	22	22				
Lane Width (ft)	11	11				

ROUTE 0444: CLIFTON ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)								
Poor (0 - 60) Fair (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated				
	See Appendix for definitions and formulas							
Inspection Date: 3/5/2021	Beginning Section MP	0.00						
Paved Length (Miles): 0.07	Section Length (MI)	0.07						
Surface Type: ASPHALT	Route Summary		•	• •				
Roadway Condition Information								
Pavement Condition Rating (PCR)	90	90						
Surface Condition Rating (SCR)	90	90						
Roughness Condition Index (RCI)	N/A	N/A						
Distress Index Values								
Structural Crack Index	N/A	N/A						
Alligator Crack Index	97	97						
Longitudinal Crack Index	90	90						
Transverse Cracking Index	90	90						
Patching Index	97	97						
Rutting Index	97	97						
International Roughness Index (IRI)	N/A	N/A						
Lane & Width Information								
Number of Lanes	2	2						
Paved Width (ft)	20	20						
Lane Width (ft)	10	10						

ROUTE 0444: CLIFTON ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0444_2.jpg



GATE_0444_4.jpg



GATE_0444_6.jpg



GATE_0444_3.jpg



GATE_0444_5.jpg



GATE_0444_7.jpg

Gateway National Recreation Area ROUTE 0445: HUDSON ROAD / STATEN ISLAND



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 10	0) Not Rated			
Colors on map represent condition scores at 0.10-mile intervals. See Appendix for definitions and formulas.							
Inspection Date: 4/24/2021	Beginning Section MP	0					
Paved Length (Miles): 0.53	Section Length (MI)	0.53					
Surface Type: ASPHALT	Route Summary		•	• •			
Roadway Condition Information							
Pavement Condition Rating (PCR)	8	8					
Surface Condition Rating (SCR)	0	0					
Roughness Condition Index (RCI)	21	21					
Distress Index Values							
Structural Crack Index	0	0					
Alligator Crack Index	90	90					
Longitudinal Crack Index	0	0					
Transverse Cracking Index	0	0					
Patching Index	100	100					
Rutting Index	91	91					
International Roughness Index (IRI)	490	490					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	19.6	19.6					
Lane Width (ft)	9.8	9.8					

ROUTE 0446: BATTERY WEED ROAD






Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 1	00) Not Rated			
Colors on map represent condition scores at 0.10-mile intervals. See Appendix for definitions and formulas.							
Inspection Date: 4/24/2021	Beginning Section MP	0					
Paved Length (Miles): 0.44	Section Length (MI)	0.44					
Surface Type: ASPHALT	Route Summary		•	• •			
Roadway Condition Information							
Pavement Condition Rating (PCR)	0	0					
Surface Condition Rating (SCR)	0	0					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	0	0					
Alligator Crack Index	81	81					
Longitudinal Crack Index	9	9					
Transverse Cracking Index	9	9					
Patching Index	99	99					
Rutting Index	84	84					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	1	1					
Paved Width (ft)	12.3	12.3					
Lane Width (ft)	12.3	12.3					


ROUTE 0447: TOMPKINS ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60) Fair (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated			
Colors on map represent condition scores at 0.10-mile intervals. See Appendix for definitions and formulas.							
Inspection Date: 4/24/2021	Beginning Section MP	0					
Paved Length (Miles): 0.15	Section Length (MI)	0.15					
Surface Type: ASPHALT	Route Summary						
Roadway Condition Information							
Pavement Condition Rating (PCR)	0	0					
Surface Condition Rating (SCR)	0	0					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	32	32					
Alligator Crack Index	98	98					
Longitudinal Crack Index	34	34					
Transverse Cracking Index	0	0					
Patching Index	99	99					
Rutting Index	89	89					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	23.3	23.3					
Lane Width (ft)	11.6	11.6					


ROUTE 0448: MARSHALL ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Condi	ition Rating (PCR)				
Poor (0 - 60)	61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated			
Colors on map represent co	ndition scores at 0.10-mile	ion scores at 0.10-mile intervals. See Appendix for definitions and formulas.					
Inspection Date: 4/24/2021	Beginning Section MP	0					
Paved Length (Miles): 0.24	Section Length (MI)	0.24					
Surface Type: ASPHALT	Route Summary		•				
Roadway Condition Information							
Pavement Condition Rating (PCR)	0	0					
Surface Condition Rating (SCR)	0	0					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	0	0					
Alligator Crack Index	39	39					
Longitudinal Crack Index	0	0					
Transverse Cracking Index	0	0					
Patching Index	100	100					
Rutting Index	91	91					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	22	22					
Lane Width (ft)	10.7	10.7					


ROUTE 0449: COAST GUARD DRIVE



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Condition Legend – Pav	ement Condi	tion Rating (PCR)	1		
Poor (0 - 60) Fair (6	1- 84) Good (85 - 94)		Excellent (95 - 1	Not Rated		
Colors on map represent con	dition scores at 0.10-mile	ion scores at 0.10-mile intervals. See Appendix for definitions and formulas.				
Inspection Date: 4/24/2021	Beginning Section MP	0				
Paved Length (Miles): 0.38	Section Length (MI)	0.38				
Surface Type: ASPHALT	Route Summary			• •		
Roadway Condition Information						
Pavement Condition Rating (PCR)	0	0				
Surface Condition Rating (SCR)	0	0				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	0	0				
Alligator Crack Index	92	92				
Longitudinal Crack Index	0	0				
Transverse Cracking Index	0	0				
Patching Index	99	99				
Rutting Index	88	88				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	22.3	22.3				
Lane Width (ft)	11.3	11.3				


ROUTE 0450: DRUM AVENUE



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Condition Legend – Pav	ement Condi	tion Rating (PCR)	
Poor (0 - 60) Fair (6	L- 84) Good (85 - 94)		Excellent (95 - 10	0) Not Rated
Colors on map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix for defir	nitions and formulas.
Inspection Date: 4/24/2021	Beginning Section MP	0		
Paved Length (Miles): 0.21	Section Length (MI)	0.21		
Surface Type: ASPHALT	Route Summary			
Roadway Condition Information				
Pavement Condition Rating (PCR)	0	0		
Surface Condition Rating (SCR)	0	0		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	0	0		
Alligator Crack Index	54	54		
Longitudinal Crack Index	0	0		
Transverse Cracking Index	0	0		
Patching Index	100	100		
Rutting Index	90	90		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	20.2	20.2		
Lane Width (ft)	10.8	10.8		

ROUTE 0451: MOLONY DRIVE



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Ro	ute Condition Legend – Pav	vement Cond	ition Rating (PCR)	
Poor (0 - 60) F a	nir (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represen	t condition scores at 0.10-mil	e intervals. So	ee Appendix for definition	is and formulas.
Inspection Date: 4/24/2021	Beginning Section MF) 0		
Paved Length (Miles): 0.07	Section Length (MI)	0.07		
Surface Type: ASPHALT	Route Summary		• •	• •
Roadway Condition Information				
Pavement Condition Rating (PCR)	26	26		
Surface Condition Rating (SCR)	26	26		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	35	35		
Alligator Crack Index	100	100		
Longitudinal Crack Index	35	35		
Transverse Cracking Index	26	26		
Patching Index	100	100		
Rutting Index	97	97		
International Roughness Index (IRI) N/A	N/A		
Lane & Width Information				
Number of Lanes	1	1		
Paved Width (ft)	15.5	15.5		
Lane Width (ft)	15.5	15.5		

ROUTE 0452: USS NEW MEXICO COURT


|--|

Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Condition Legend – Pav	ement Condi	tion Rating (PCR)			
Poor (0 - 60) Fair (6	1- 84) Good (85 - 94)		Excellent (95 - 100)	Not Rated		
Colors on map represent con	dition scores at 0.10-mile	tion scores at 0.10-mile intervals. See Appendix for definitions and formulas.				
Inspection Date: 4/24/2021	Beginning Section MP	0				
Paved Length (Miles): 0.09	Section Length (MI)	0.09				
Surface Type: ASPHALT	Route Summary					
Roadway Condition Information						
Pavement Condition Rating (PCR)	0	0				
Surface Condition Rating (SCR)	0	0				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	0	0				
Alligator Crack Index	86	86				
Longitudinal Crack Index	0	0				
Transverse Cracking Index	0	0				
Patching Index	100	100				
Rutting Index	95	95				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	16.5	16.5				
Lane Width (ft)	8.2	8.2				

Gateway National Recreation Area ROUTE 0453: USS NORTH CAROLINA ROAD

Data Collection Vehicle (DCV) Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Condition Legend – Pav	ement Condi	tion Rating (PCR)	
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent cond	lition scores at 0.10-mile	intervals. Se	e Appendix for definitior	ns and formulas.
Inspection Date: 4/24/2021	Beginning Section MP	0		
Paved Length (Miles): 0.74	Section Length (MI)	0.74		
Surface Type: ASPHALT	Route Summary			
Roadway Condition Information				
Pavement Condition Rating (PCR)	94	94		
Surface Condition Rating (SCR)	31	31		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	N/A	N/A		
Alligator Crack Index	N/A	N/A		
Longitudinal Crack Index	N/A	N/A		
Transverse Cracking Index	N/A	N/A		
Patching Index	N/A	N/A		
Rutting Index	N/A	N/A		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	21.1	21.1		
Lane Width (ft)	8.6	8.6		

NOTE: MANUALLY RATED PCR BEYOND BARRIER


ROUTE 0454: USS CONNECTICUT COURT



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Cond	ition Rating (PCR)	
Poor (0 - 60) Fair (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent co	ndition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/24/2021	Beginning Section MP	0		
Paved Length (Miles): 0.14	Section Length (MI)	0.14		
Surface Type: ASPHALT	Route Summary		• •	•
Roadway Condition Information				
Pavement Condition Rating (PCR)	28	28		
Surface Condition Rating (SCR)	28	28		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	49	49		
Alligator Crack Index	97	97		
Longitudinal Crack Index	52	52		
Transverse Cracking Index	28	28		
Patching Index	94	94		
Rutting Index	94	94		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	28.7	28.7		
Lane Width (ft)	14.2	14.2		


ROUTE 0455: USS ARIZONA LANE



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Condi	tion Rating (P	CR)		
Poor (0 - 60) Fair (6	1- 84) Good (85 - 94)		Excellent (95	5 - 100)	Not Rat	ted
Colors on map represent con	dition scores at 0.10-mile	intervals. Se	e Appendix for	definitions	and formulas.	
Inspection Date: 4/24/2021	Beginning Section MP	0				
Paved Length (Miles): 0.03	Section Length (MI)	0.03				
Surface Type: ASPHALT	Route Summary					
Roadway Condition Information						
Pavement Condition Rating (PCR)	8	8				
Surface Condition Rating (SCR)	8	8				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	12	12				
Alligator Crack Index	84	84				
Longitudinal Crack Index	28	28				
Transverse Cracking Index	8	8				
Patching Index	98	98				
Rutting Index	99	99				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	23	23				
Lane Width (ft)	8.2	8.2				


ROUTE 0456: USS IOWA CIRCLE



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Rou	te Condition Legend – Pav	ement Cond	lition Rating (PCR)	
		(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent	condition scores at 0.10-mile	e intervals. Se	ee Appendix for definition	ns and formulas.
Inspection Date: 4/24/2021	Beginning Section MP	0		
Paved Length (Miles): 0.24	Section Length (MI)	0.24		
Surface Type: ASPHALT	Route Summary		• •	
Roadway Condition Information				
Pavement Condition Rating (PCR)	0	0		
Surface Condition Rating (SCR)	0	0		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	0	0		
Alligator Crack Index	87	87		
Longitudinal Crack Index	0	0		
Transverse Cracking Index	0	0		
Patching Index	93	93		
Rutting Index	93	93		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	29.1	29.1		
Lane Width (ft)	14.6	14.6		

ROUTE 0457: USS MISSOURI LANE




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Condi	tion Rating (PCR)				
Poor (0 - 60) Fair (0	61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated			
Colors on map represent cor	ndition scores at 0.10-mile	ion scores at 0.10-mile intervals. See Appendix for definitions and formulas.					
Inspection Date: 4/24/2021	Beginning Section MP	0					
Paved Length (Miles): 0.04	Section Length (MI)	0.04					
Surface Type: ASPHALT	Route Summary		•	• •			
Roadway Condition Information							
Pavement Condition Rating (PCR)	0	0					
Surface Condition Rating (SCR)	0	0					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	0	0					
Alligator Crack Index	60	60					
Longitudinal Crack Index	0	0					
Transverse Cracking Index	0	0					
Patching Index	99	99					
Rutting Index	94	94					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	32.3	32.3					
Lane Width (ft)	16.1	16.1					

ROUTE 0458: USS TENNESSEE ROAD

Data Collection Vehicle (DCV) Rating




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Rou	te Condition Legend – Pav	ement Cond	ition Rating (PCR)				
Poor (0 - 60)	r (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated			
Colors on map represent	condition scores at 0.10-mile	on scores at 0.10-mile intervals. See Appendix for definitions and formulas.					
Inspection Date: 4/24/2021	Beginning Section MP	0					
Paved Length (Miles): 0.23	Section Length (MI)	0.23					
Surface Type: ASPHALT	Route Summary			•			
Roadway Condition Information							
Pavement Condition Rating (PCR)	4	4					
Surface Condition Rating (SCR)	0	0					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	0	0					
Alligator Crack Index	84	84					
Longitudinal Crack Index	0	0					
Transverse Cracking Index	0	0					
Patching Index	99	99					
Rutting Index	93	93					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	25.3	25.3					
Lane Width (ft)	12.2	12.2					

NOTE: SECTION WITH MANUALLY RATED PCR DUE TO BARRIER


ROUTE 0459: USS FLORIDA COURT



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Condi	tion Rating (PCR)	
Poor (0 - 60) Fair (0	61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/24/2021	Beginning Section MP	0		
Paved Length (Miles): 0.17	Section Length (MI)	0.17		
Surface Type: ASPHALT	Route Summary		•	
Roadway Condition Information				
Pavement Condition Rating (PCR)	0	0		
Surface Condition Rating (SCR)	0	0		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	0	0		
Alligator Crack Index	75	75		
Longitudinal Crack Index	0	0		
Transverse Cracking Index	0	0		
Patching Index	98	98		
Rutting Index	88	88		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	23.3	23.3		
Lane Width (ft)	11.7	11.7		

Gateway National Recreation Area ROUTE 0460: NORTH MAINTENANCE AREA ACCESS ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Cond	ition Rating (PCR)	
Poor (0 - 60)	61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent co	ndition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/21/2021	Beginning Section MP	0		
Paved Length (Miles): 0.14	Section Length (MI)	0.14		
Surface Type: ASPHALT	Route Summary		• •	•
Roadway Condition Information				
Pavement Condition Rating (PCR)	0	0		
Surface Condition Rating (SCR)	0	0		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	0	0		
Alligator Crack Index	96	96		
Longitudinal Crack Index	0	0		
Transverse Cracking Index	2	2		
Patching Index	95	95		
Rutting Index	89	89		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	47.3	47.3		
Lane Width (ft)	23.6	23.6		

ROUTE 0461: SAND SHED ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

	Route	Condition Legend – Pave	ement Cond	ition Rating (PCR)				
Poor (0 - 6 0) Fair (<mark>61- 84) Good (</mark>	85 - 94)	Excellent (95 - 100)	Not Rated			
See Appendix for definitions and formulas								
Inspection Date:	3/6/2021	Beginning Section MP	0.00					
Paved Length (Mile	es): 0.08	Section Length (MI)	0.08					
Surface Type:	CONCRETE	Route Summary		•	•			
Roadway Condition	n Information							
Pavement Condition	on Rating (PCR)	90	90					
Surface Condition R	Rating (SCR)	90	90					
Roughness Condition	on Index (RCI)	N/A	N/A					
Distress Index Valu	es							
Structural Crack In	dex	N/A	N/A					
Alligator Crack Inc	lex	N/A	N/A					
Longitudinal Crack	c Index	N/A	N/A					
Transverse Crackir	ng Index	N/A	N/A					
Patching Index		N/A	N/A					
Rutting Index		N/A	N/A					
International Roug	hness Index (IRI)	N/A	N/A					
Lane & Width Info	rmation							
Number of Lanes		1	1					
Paved Width (ft)		11	11					
Lane Width (ft)		11	11					

ROUTE 0461: SAND SHED ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0461_1.jpg



GATE_0461_3.jpg



GATE_0461_6.jpg



GATE_0461_2.jpg




GATE_0461_5.jpg



GATE_0461_7.jpg

ROUTE 0462: RANDOLPH ROAD






Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Rou	te Condition Legend – Pav	ement Cond	ition Rating (PCR)	
Poor (0 - 60) Fair	: (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent of	condition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/24/2021	Beginning Section MP	0		
Paved Length (Miles): 0.26	Section Length (MI)	0.26		
Surface Type: ASPHALT	Route Summary		•	
Roadway Condition Information				
Pavement Condition Rating (PCR)	12	12		
Surface Condition Rating (SCR)	12	12		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	12	12		
Alligator Crack Index	57	57		
Longitudinal Crack Index	55	55		
Transverse Cracking Index	68	68		
Patching Index	100	100		
Rutting Index	79	79		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	1	1		
Paved Width (ft)	14.4	14.4		
Lane Width (ft)	12.3	12.3		

ROUTE 0464: AVIATION ROAD






Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Cond	ition Rating (PCR)	
Poor (0 - 60) Fair	(61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent co	ndition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/23/2021	Beginning Section MP	0		
Paved Length (Miles): 0.39	Section Length (MI)	0.39		
Surface Type: ASPHALT	Route Summary			• •
Roadway Condition Information				
Pavement Condition Rating (PCR)	50	50		
Surface Condition Rating (SCR)	23	23		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	39	39		
Alligator Crack Index	96	96		
Longitudinal Crack Index	43	43		
Transverse Cracking Index	23	23		
Patching Index	98	98		
Rutting Index	96	96		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	18.8	18.8		
Lane Width (ft)	9.3	9.3		

NOTE: MANUALLY RATED PCR DUE TO SAND ON THE REMAINDER OF THE ROUTE


ROUTE 0465: BUILDING 272 ACCESS ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60) Fair (6	61-84) Good	- 84) Good (85 - 94)		Not Rated			
Colors on map represent cor	dition scores at 0.10-mile	e intervals. Se	e Appendix for definitio	ns and formulas.			
Inspection Date: 4/23/2021	Beginning Section MP	0					
Paved Length (Miles): 0.18	Section Length (MI)	0.18					
Surface Type: ASPHALT	Route Summary						
Roadway Condition Information							
Pavement Condition Rating (PCR)	23	23					
Surface Condition Rating (SCR)	23	23					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	36	36					
Alligator Crack Index	99	99					
Longitudinal Crack Index	37	37					
Transverse Cracking Index	23	23					
Patching Index	99	99					
Rutting Index	87	87					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	23.5	23.5					
Lane Width (ft)	11.8	11.8					

Gateway National Recreation Area ROUTE 0470: JACOB RIIS SERVICE ROAD




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60) Fair (61- 84)		(85 - 94)	85 - 94) Excellent (95 - 100) Not F		Not Ra	ted	
Colors on map represent con	dition scores at 0.10-mile	intervals. Se	e Appendix for a	definitions	and formulas.		
Inspection Date: 4/23/2021	Beginning Section MP	0					
Paved Length (Miles): 0.32	Section Length (MI)	0.32					
Surface Type: CONCRETE	Route Summary						
Roadway Condition Information							
Pavement Condition Rating (PCR)	61	61					
Surface Condition Rating (SCR)	61	61					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	64	64					
Alligator Crack Index	100	100					
Longitudinal Crack Index	64	64					
Transverse Cracking Index	61	61					
Patching Index	100	100					
Rutting Index	92	92					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	20.3	20.3					
Lane Width (ft)	10.4	10.4					

ROUTE 0471: LOOP ROAD

Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)								
Poor (0 - 60) Fair (6	1- 84) Good (- 84) Good (85 - 94)		Not Rated				
See Appendix for definitions and formulas								
Inspection Date: 3/5/2021	Beginning Section MP	0.00						
Paved Length (Miles): 0.14	Section Length (MI)	0.14						
Surface Type: ASPHALT	Route Summary			• •				
Roadway Condition Information								
Pavement Condition Rating (PCR)	30	30						
Surface Condition Rating (SCR)	30	30						
Roughness Condition Index (RCI)	N/A	N/A						
Distress Index Values								
Structural Crack Index	N/A	N/A						
Alligator Crack Index	30	30						
Longitudinal Crack Index	73	73						
Transverse Cracking Index	73	73						
Patching Index	90	90						
Rutting Index	97	97						
International Roughness Index (IRI)	N/A	N/A						
Lane & Width Information								
Number of Lanes	2	2						
Paved Width (ft)	20	20						
Lane Width (ft)	10	10						

Gateway National Recreation Area ROUTE 0471: LOOP ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0471_1.jpg



GATE_0471_3.jpg



GATE_0471_7.jpg



GATE_0471_11.jpg




GATE_0471_6.jpg



GATE_0471_9.jpg

ROUTE 0472: RANGE ROAD (STATEN ISLAND)



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

	Route Condition Legend –	Pavement Cond	ition Rating (PCR)					
Poor (0 - 60)	Fair (61- 84) Go	od (85 - 94)	Excellent (95 - 100)	Not Rated				
See Appendix for definitions and formulas								
Inspection Date: 3/5/2021	Beginning Section	MP 0.00						
Paved Length (Miles): 0.08	Section Length (M	I) 0.08						
Surface Type: ASPHAL	Route Summary		•					
Roadway Condition Information	1							
Pavement Condition Rating (PC)	R) 97	97						
Surface Condition Rating (SCR)	97	97						
Roughness Condition Index (RCI)	N/A	N/A						
Distress Index Values								
Structural Crack Index	N/A	N/A						
Alligator Crack Index	N/A	N/A						
Longitudinal Crack Index	N/A	N/A						
Transverse Cracking Index	N/A	N/A						
Patching Index	N/A	N/A						
Rutting Index	N/A	N/A						
International Roughness Index (I	RI) N/A	N/A						
Lane & Width Information								
Number of Lanes	2	2						
Paved Width (ft)	16	16						
Lane Width (ft)	8	8						

ROUTE 0472: RANGE ROAD (STATEN ISLAND)

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0472_1.jpg



GATE_0472_2.jpg



GATE_0472_4.jpg



GATE_0472_10.jpg




GATE_0472_3.jpg



GATE_0472_9.jpg

ROUTE 0473: HARBOR ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)								
Poor (0 - 60) Fair (6	1- 84) Good (*	I- 84) Good (85 - 94) Excellent (95 - 100)						
See Appendix for definitions and formulas								
Inspection Date: 3/4/2021	Beginning Section MP	0.00						
Paved Length (Miles): 0.22	Section Length (MI)	0.22						
Surface Type: ASPHALT	Route Summary							
Roadway Condition Information								
Pavement Condition Rating (PCR)	N/A	N/A						
Surface Condition Rating (SCR)	N/A	N/A						
Roughness Condition Index (RCI)	N/A	N/A						
Distress Index Values								
Structural Crack Index	N/A	N/A						
Alligator Crack Index	N/A	N/A						
Longitudinal Crack Index	N/A	N/A						
Transverse Cracking Index	N/A	N/A						
Patching Index	N/A	N/A						
Rutting Index	N/A	N/A						
International Roughness Index (IRI)	N/A	N/A						
Lane & Width Information								
Number of Lanes	1	1						
Paved Width (ft)	15	15						
Lane Width (ft)	15	15						

NOTE: NOT COLLECTED DUE TO RADIATION ZONE. HAZARDOUS AREA, MENTIONED BY LOCAL PARK POLICE AND POSTED SIGNAGE TO KEEP OUT.

Gateway National Recreation Area ROUTE 0473: HARBOR ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0473_1.jpg

Gateway National Recreation Area ROUTE 0474ZZ: MILLER FIELD RESIDENCE ROAD

Summary Route



Sources: Esri, HERE, Garmin, Internap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: The weighted average summary PCR value is calculated from only the sections of road where the PCR was collected. The overall PCR for the summary route may not reflect individual subcomponent ratings.

Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60)	Fair (61- 84)	1- 84) Good (85 - 9		Excellent (95 - 100)		Not Rated	
	See	Appendix for d	efinitions and	formulas			
Inspection Date: 3/5/2021							
Paved Length (Miles): 0.21							
Surface Type: ASPHAI	T Route	Summary					
Roadway Condition Informatio	n						
Pavement Condition Rating (PC	CR)	76					
Lane & Width Information							
Number of Lanes		1					
Paved Width (ft)		12					
Lane Width (ft)		12					

Gateway National Recreation Area ROUTE 0474AZ: MILLER FIELD RESIDENCE ROAD A

Subcomponent of Route GATE-0474ZZ Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)								
Poor (0 - 60) Fair (6)	1- 84) Good (85 - 94)		Excellent (95 - 100)	Not Rated				
See Appendix for definitions and formulas								
Inspection Date: 3/5/2021	Beginning Section MP	0.00						
Paved Length (Miles): 0.07	Section Length (MI)	0.07						
Surface Type: ASPHALT	Route Summary		•	• •				
Roadway Condition Information								
Pavement Condition Rating (PCR)	73	73						
Surface Condition Rating (SCR)	73	73						
Roughness Condition Index (RCI)	N/A	N/A						
Distress Index Values								
Structural Crack Index	N/A	N/A						
Alligator Crack Index	73	73						
Longitudinal Crack Index	90	90						
Transverse Cracking Index	90	90						
Patching Index	90	90						
Rutting Index	97	97						
International Roughness Index (IRI)	N/A	N/A						
Lane & Width Information								
Number of Lanes	1	1						
Paved Width (ft)	12	12						
Lane Width (ft)	12	12						

Gateway National Recreation Area ROUTE 0474AZ: MILLER FIELD RESIDENCE ROAD A

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0474AZ_1.jpg



GATE_0474AZ_3.jpg



GATE_0474AZ_5.jpg



GATE_0474AZ_2.jpg



GATE_0474AZ_4.jpg



GATE_0474AZ_6.jpg

Gateway National Recreation Area ROUTE 0474BZ: MILLER FIELD RESIDENCE ROAD B

Subcomponent of Route GATE-0474ZZ Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6)			Excellent (95 - 100)	Not Rated		
See Appendix for definitions and formulas						
Inspection Date: 3/5/2021	Beginning Section MP	0.00				
Paved Length (Miles): 0.03	Section Length (MI)	0.03				
Surface Type: ASPHALT	Route Summary			• •		
Roadway Condition Information						
Pavement Condition Rating (PCR)	90	90				
Surface Condition Rating (SCR)	90	90				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	N/A	N/A				
Alligator Crack Index	90	90				
Longitudinal Crack Index	97	97				
Transverse Cracking Index	90	90				
Patching Index	90	90				
Rutting Index	97	97				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	1	1				
Paved Width (ft)	12	12				
Lane Width (ft)	12	12				

Gateway National Recreation Area ROUTE 0474BZ: MILLER FIELD RESIDENCE ROAD B

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0474BZ_1.jpg



GATE_0474BZ_2.jpg



GATE_0474BZ_3.jpg



GATE_0474BZ_5.jpg




GATE_0474BZ_4.jpg



GATE_0474BZ_6.jpg

Gateway National Recreation Area ROUTE 0474CZ: MILLER FIELD RESIDENCE ROAD C

Subcomponent of Route GATE-0474ZZ Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60)	ir (61- 84) Good	1- 84) Good (85 - 94)		Not Rated		
See Appendix for definitions and formulas						
Inspection Date: 3/5/2021	Beginning Section MP	0.00				
Paved Length (Miles): 0.11	Section Length (MI)	0.11				
Surface Type: ASPHALT	Route Summary			• •		
Roadway Condition Information						
Pavement Condition Rating (PCR)	73	73				
Surface Condition Rating (SCR)	73	73				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	N/A	N/A				
Alligator Crack Index	73	73				
Longitudinal Crack Index	90	90				
Transverse Cracking Index	90	90				
Patching Index	97	97				
Rutting Index	97	97				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	1	1				
Paved Width (ft)	12	12				
Lane Width (ft)	12	12				

Gateway National Recreation Area ROUTE 0474CZ: MILLER FIELD RESIDENCE ROAD C

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0474CZ_1.jpg



GATE_0474CZ_3.jpg



GATE_0474CZ_6.jpg



GATE_0474CZ_2.jpg




GATE_0474CZ_5.jpg



GATE_0474CZ_9.jpg

ROUTE 0475: DAVIS ACCESS ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6	Poor (0 - 60) Fair (61- 84) Good (Excellent (95 - 100)	Not Rated		
See Appendix for definitions and formulas						
Inspection Date: 3/3/2021	Beginning Section MP	0.00				
Paved Length (Miles): 0.04	Section Length (MI)	0.04				
Surface Type: CONCRETE	Route Summary					
Roadway Condition Information						
Pavement Condition Rating (PCR)	90	90				
Surface Condition Rating (SCR)	90	90				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	N/A	N/A				
Alligator Crack Index	N/A	N/A				
Longitudinal Crack Index	N/A	N/A				
Transverse Cracking Index	N/A	N/A				
Patching Index	N/A	N/A				
Rutting Index	N/A	N/A				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	15	15				
Lane Width (ft)	7.5	7.5				

ROUTE 0475: DAVIS ACCESS ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0475_1.jpg



GATE_0475_3.jpg



GATE_0475_5.jpg



GATE_0475_2.jpg




GATE_0475_4.jpg



GATE_0475_6.jpg

ROUTE 0476: CAMPSITE ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

	Route Condition Leg	end – Pavement Cond	lition Rating (PCR)				
Poor (0 - 60)	Fair (61- 84)	Good (85 - 94)	Excellent (95 - 100)	Not Rated			
See Appendix for definitions and formulas							
Inspection Date: 3/6/2021	Beginning Se	ection MP 0.00					
Paved Length (Miles): 0.17	Section Leng	th (MI) 0.17					
Surface Type: ASPHALT	Route Summ	ary	•				
Roadway Condition Information							
Pavement Condition Rating (PCF	R) 73	73					
Surface Condition Rating (SCR)	73	73					
Roughness Condition Index (RCI)	N/A	. N/A					
Distress Index Values							
Structural Crack Index	N/A	. N/A					
Alligator Crack Index	73	73					
Longitudinal Crack Index	73	73					
Transverse Cracking Index	73	73					
Patching Index	97	97					
Rutting Index	97	97					
International Roughness Index (II	RI) N/A	. N/A					
Lane & Width Information							
Number of Lanes	1	1					
Paved Width (ft)	11	11					
Lane Width (ft)	11	11					

Gateway National Recreation Area ROUTE 0476: CAMPSITE ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0476_1.jpg



GATE_0476_4.jpg



GATE_0476_7.jpg



GATE_0476_2.jpg




GATE_0476_6.jpg



GATE_0476_8.jpg

Gateway National Recreation Area ROUTE 0477ZZ: NIKE RADAR SITE ROADS

Summary Route




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: The weighted average summary PCR value is calculated from only the sections of road where the PCR was collected. The overall PCR for the summary route may not reflect individual subcomponent ratings.

Route Condition Legend – Pavement Condition Rating (PCR)								
Poor (0 - 60) Fair (6	1- 84) Good (85 - 94)		Excellent (95 - 100)		Not Rated			
	See Appendix for det	finitions and f	formulas					
Inspection Date: 3/6/2021								
Paved Length (Miles): 0.43								
Surface Type: ASPHALT	Route Summary							
Roadway Condition Information								
Pavement Condition Rating (PCR)	57							
Lane & Width Information								
Number of Lanes	1							
Paved Width (ft)	16							
Lane Width (ft)	16							

Gateway National Recreation Area ROUTE 0477AZ: NIKE RADAR SITE ROAD A

Subcomponent of Route GATE-0477ZZ Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)									
Poor (0 - 60) Fair (61- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated					
See Appendix for definitions and formulas									
Inspection Date: 3/6/2021	Beginning Section MP	0.00							
Paved Length (Miles): 0.24	Section Length (MI)	0.24							
Surface Type: ASPHALT	Route Summary			• •					
Roadway Condition Information									
Pavement Condition Rating (PCR)	53	53							
Surface Condition Rating (SCR)	53	53							
Roughness Condition Index (RCI)	N/A	N/A							
Distress Index Values									
Structural Crack Index	N/A	N/A							
Alligator Crack Index	53	53							
Longitudinal Crack Index	73	73							
Transverse Cracking Index	73	73							
Patching Index	90	90							
Rutting Index	90	90							
International Roughness Index (IRI)	N/A	N/A							
Lane & Width Information									
Number of Lanes	1	1							
Paved Width (ft)	16	16							
Lane Width (ft)	16	16							

Gateway National Recreation Area ROUTE 0477AZ: NIKE RADAR SITE ROAD A

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0477AZ_15.jpg



GATE_0477AZ_21.jpg



GATE_0477AZ_3.jpg



GATE_0477AZ_19.jpg




GATE_0477AZ_23.jpg



GATE_0477AZ_8.jpg

Gateway National Recreation Area ROUTE 0477BZ: NIKE RADAR SITE ROAD B

Subcomponent of Route GATE-0477ZZ Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route C	Route Condition Legend – Pavement Condition Rating (PCR)								
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94) Excellent (95 - 100)		Not Rated					
See Appendix for definitions and formulas									
Inspection Date: 3/6/2021	Beginning Section MP	0.00							
Paved Length (Miles): 0.05	Section Length (MI)	0.05							
Surface Type: ASPHALT	Route Summary		•	• •					
Roadway Condition Information									
Pavement Condition Rating (PCR)	90	90							
Surface Condition Rating (SCR)	90	90							
Roughness Condition Index (RCI)	N/A	N/A							
Distress Index Values									
Structural Crack Index	N/A	N/A							
Alligator Crack Index	90	90							
Longitudinal Crack Index	90	90							
Transverse Cracking Index	90	90							
Patching Index	97	97							
Rutting Index	97	97							
International Roughness Index (IRI)	N/A	N/A							
Lane & Width Information									
Number of Lanes	1	1							
Paved Width (ft)	16	16							
Lane Width (ft)	16	16							

Gateway National Recreation Area ROUTE 0477BZ: NIKE RADAR SITE ROAD B

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0477BZ_1.jpg



GATE_0477BZ_3.jpg



GATE_0477BZ_6.jpg



GATE_0477BZ_2.jpg




GATE_0477BZ_5.jpg



GATE_0477BZ_7.jpg

Gateway National Recreation Area ROUTE 0477CZ: NIKE RADAR SITE ROAD C

Subcomponent of Route GATE-0477ZZ Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)									
Poor (0 - 60) Fair (6	1- 84) Good (85 - 94)	Excellent (95 - 100)	Not Rated					
See Appendix for definitions and formulas									
Inspection Date: 3/6/2021	Beginning Section MP	0.00							
Paved Length (Miles): 0.14	Section Length (MI)	0.14							
Surface Type: ASPHALT	Route Summary								
Roadway Condition Information									
Pavement Condition Rating (PCR)	53	53							
Surface Condition Rating (SCR)	53	53							
Roughness Condition Index (RCI)	N/A	N/A							
Distress Index Values									
Structural Crack Index	N/A	N/A							
Alligator Crack Index	73	73							
Longitudinal Crack Index	53	53							
Transverse Cracking Index	53	53							
Patching Index	90	90							
Rutting Index	90	90							
International Roughness Index (IRI)	N/A	N/A							
Lane & Width Information									
Number of Lanes	1	1							
Paved Width (ft)	16	16							
Lane Width (ft)	16	16							

Gateway National Recreation Area ROUTE 0477CZ: NIKE RADAR SITE ROAD C

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0477CZ_10.jpg



GATE_0477CZ_14.jpg



GATE_0477CZ_22.jpg



GATE_0477CZ_13.jpg



GATE_0477CZ_20.jpg



GATE_0477CZ_7.jpg

ROUTE 0479: FISHERMAN'S PARKING ACCESS



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Cond	ition Rating (PCR)	
Poor (0 - 60) Fair	(61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent co	ndition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/24/2021	Beginning Section MP	0		
Paved Length (Miles): 0.24	Section Length (MI)	0.24		
Surface Type: ASPHALT	Route Summary		• •	
Roadway Condition Information				
Pavement Condition Rating (PCR)	21	21		
Surface Condition Rating (SCR)	21	21		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	56	56		
Alligator Crack Index	100	100		
Longitudinal Crack Index	56	56		
Transverse Cracking Index	21	21		
Patching Index	100	100		
Rutting Index	98	98		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	18.7	18.7		
Lane Width (ft)	9.8	9.8		

Gateway National Recreation Area ROUTE 0480: SERVICE ROAD / KINGMAN AND MILLS ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)										
Poor (0 - 60)	Fair (6	1- 84) Good (85 - 94) Excellent (95 - 100)			5 - 100)	Not Rated				
See Appendix for definitions and formulas										
Inspection Date: 3/6/2	2021	Beginning Section MP	0.00							
Paved Length (Miles): 0.18		Section Length (MI)	0.18							
Surface Type: ASP	HALT	Route Summary		··						
Roadway Condition Inform	nation									
Pavement Condition Rating	g (PCR)	73	73							
Surface Condition Rating (S	CR)	73	73							
Roughness Condition Index	(RCI)	N/A	N/A							
Distress Index Values										
Structural Crack Index		N/A	N/A							
Alligator Crack Index		73	73							
Longitudinal Crack Index		73	73							
Transverse Cracking Index		73	73							
Patching Index		97	97							
Rutting Index		97	97							
International Roughness In	dex (IRI)	N/A	N/A							
Lane & Width Information	1									
Number of Lanes	Number of Lanes		1							
Paved Width (ft)		11	11							
Lane Width (ft)		11	11							

Gateway National Recreation Area ROUTE 0480: SERVICE ROAD / KINGMAN AND MILLS ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0480_2.jpg



GATE_0480_4.jpg



GATE_0480_7.jpg



GATE_0480_3.jpg




GATE_0480_6.jpg



GATE_0480_9.jpg

ROUTE 0481: SOUTH MAINTENANCE SHOP ROAD A



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)									
Poor (0 - 60) Fa	air (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated					
See Appendix for definitions and formulas									
Inspection Date: 3/6/2021	Beginning Section MI	P 0.00							
Paved Length (Miles): 0.14	Section Length (MI)	0.14							
Surface Type: ASPHALT	Route Summary		• •	• •					
Roadway Condition Information									
Pavement Condition Rating (PCR)	30	30							
Surface Condition Rating (SCR)	30	30							
Roughness Condition Index (RCI)	N/A	N/A							
Distress Index Values									
Structural Crack Index	N/A	N/A							
Alligator Crack Index	30	30							
Longitudinal Crack Index	30	30							
Transverse Cracking Index	53	53							
Patching Index	90	90							
Rutting Index	73	73							
International Roughness Index (IRI) N/A	N/A							
Lane & Width Information									
Number of Lanes	1	1							
Paved Width (ft)	11	11							
Lane Width (ft)	11	11							

Gateway National Recreation Area ROUTE 0481: SOUTH MAINTENANCE SHOP ROAD A

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0481_2.jpg



GATE_0481_4.jpg



GATE_0481_8.jpg



GATE_0481_3.jpg




GATE_0481_7.jpg



GATE_0481_9.jpg

ROUTE 0482: SOUTH MAINTENANCE SHOP ROAD B



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Rout	e Condition Legend – Pav	ement Cond	ition Rating (PCR)							
Poor (0 - 60) Fair	(61- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated						
See Appendix for definitions and formulas										
Inspection Date: 3/6/2021	Beginning Section MP	0.00								
Paved Length (Miles): 0.06	Section Length (MI)	0.06								
Surface Type: ASPHALT	Route Summary			•						
Roadway Condition Information										
Pavement Condition Rating (PCR)	73	73								
Surface Condition Rating (SCR)	73	73								
Roughness Condition Index (RCI)	N/A	N/A								
Distress Index Values										
Structural Crack Index	N/A	N/A								
Alligator Crack Index	73	73								
Longitudinal Crack Index	90	90								
Transverse Cracking Index	73	73								
Patching Index	73	73								
Rutting Index	90	90								
International Roughness Index (IRI)	N/A	N/A								
Lane & Width Information										
Number of Lanes	1	1								
Paved Width (ft)	11	11								
Lane Width (ft)	11	11								

Gateway National Recreation Area ROUTE 0482: SOUTH MAINTENANCE SHOP ROAD B

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0482_1.jpg



GATE_0482_5.jpg



GATE_0482_8.jpg



GATE_0482_4.jpg




GATE_0482_6.jpg



GATE_0482_9.jpg

Gateway National Recreation Area ROUTE 0483ZZ: SOUTH MAINTENANCE SHOP ROAD C

Summary Route



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community


Note: The weighted average summary PCR value is calculated from only the sections of road where the PCR was collected. The overall PCR for the summary route may not reflect individual subcomponent ratings.

	Route Condition Legend – Pavement Condition Rating (PCR)								
Poor (0 - 60) Fair (61		1- 84) Good (85 - 94)		Excellent (95 - 100)		Not Rated			
		See Appendix for de	finitions and f	formulas					
Inspection Date:	3/6/2021								
Paved Length (Mile	s): 0.1								
Surface Type:	ASPHALT	Route Summary		•					
Roadway Condition	Information								
Pavement Condition	n Rating (PCR)	30							
Lane & Width Infor	rmation								
Number of Lanes		1							
Paved Width (ft)		11							
Lane Width (ft)		11							

Gateway National Recreation Area ROUTE 0483AZ: SOUTH MAINTENANCE SHOP ROAD C - MAIN

Subcomponent of Route GATE-0483ZZ





Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)									
Poor (0 - 60) Fair	(61- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated					
See Appendix for definitions and formulas									
Inspection Date: 3/6/2021	Beginning Section MP	0.00							
Paved Length (Miles): 0.06	Section Length (MI)	0.06							
Surface Type: ASPHALT	Route Summary			•					
Roadway Condition Information									
Pavement Condition Rating (PCR)	30	30							
Surface Condition Rating (SCR)	30	30							
Roughness Condition Index (RCI)	N/A	N/A							
Distress Index Values									
Structural Crack Index	N/A	N/A							
Alligator Crack Index	30	30							
Longitudinal Crack Index	30	30							
Transverse Cracking Index	53	53							
Patching Index	97	97							
Rutting Index	97	97							
International Roughness Index (IRI)	N/A	N/A							
Lane & Width Information									
Number of Lanes	1	1							
Paved Width (ft)	11	11							
Lane Width (ft)	11	11							

Gateway National Recreation Area ROUTE 0483AZ: SOUTH MAINTENANCE SHOP ROAD C - MAIN

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0483AZ_1.jpg



GATE_0483AZ_3.jpg



GATE_0483AZ_5.jpg



GATE_0483AZ_2.jpg




GATE_0483AZ_4.jpg



GATE_0483AZ_6.jpg

Gateway National Recreation Area ROUTE 0483BZ: SOUTH MAINTENANCE SHOP ROAD C - SPUR

Subcomponent of Route GATE-0483ZZ Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

	Route Cond	ition Legend – Pav	ement Cond	ition Rating (PC	R)					
Poor (0 - 60)	Fair (61- 84) Good	(85 - 94)	Excellent (95 -	- 100)	Not Rat	ted			
See Appendix for definitions and formulas										
Inspection Date: 3/6/20	021 Beg	inning Section MF	0.00							
Paved Length (Miles): 0.03	Sect	tion Length (MI)	0.03							
Surface Type: ASPH	IALT Rou	ite Summary								
Roadway Condition Informa	ation									
Pavement Condition Rating	(PCR)	30	30							
Surface Condition Rating (SC	R)	30	30							
Roughness Condition Index (F	RCI)	N/A	N/A							
Distress Index Values										
Structural Crack Index		N/A	N/A							
Alligator Crack Index		30	30							
Longitudinal Crack Index		30	30							
Transverse Cracking Index		53	53							
Patching Index		97	97							
Rutting Index		53	53							
International Roughness Inde	ex (IRI)	N/A	N/A							
Lane & Width Information										
Number of Lanes		1	1							
Paved Width (ft)		11	11							
Lane Width (ft)		11	11							

Gateway National Recreation Area ROUTE 0483BZ: SOUTH MAINTENANCE SHOP ROAD C - SPUR

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0483BZ_1.jpg





GATE_0483BZ_3.jpg



GATE_0483BZ_5.jpg




GATE_0483BZ_4.jpg



GATE_0483BZ_6.jpg

ROUTE 0484: NORTH BEACH SERVICE ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Condi	ition Rating (PCR)							
Poor (0 - 60) Fair (61- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated						
See Appendix for definitions and formulas										
Inspection Date: 3/6/2021	Beginning Section MP	0.00								
Paved Length (Miles): 0.29	Section Length (MI)	0.28								
Surface Type: ASPHALT	Route Summary			•						
Roadway Condition Information										
Pavement Condition Rating (PCR)	73	73								
Surface Condition Rating (SCR)	73	73								
Roughness Condition Index (RCI)	N/A	N/A								
Distress Index Values										
Structural Crack Index	N/A	N/A								
Alligator Crack Index	73	73								
Longitudinal Crack Index	90	90								
Transverse Cracking Index	90	90								
Patching Index	73	73								
Rutting Index	97	97								
International Roughness Index (IRI)	N/A	N/A								
Lane & Width Information										
Number of Lanes	1	1								
Paved Width (ft)	11	11								
Lane Width (ft)	11	11								

Gateway National Recreation Area ROUTE 0484: NORTH BEACH SERVICE ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0484_1.jpg



GATE_0484_5.jpg



GATE_0484_4.jpg



GATE_0484_6.jpg




GATE_0484_7.jpg



GATE_0484_8.jpg


ROUTE 0497: NYPD ROAD 1



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Rou	te Condition Legend – Pav	ement Cond	ition Rating (PCR)	
Poor (0 - 60) Fai	r (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent	condition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/23/2021	Beginning Section MP	0		
Paved Length (Miles): 0.12	Section Length (MI)	0.12		
Surface Type: ASPHALT	Route Summary		•	
Roadway Condition Information				
Pavement Condition Rating (PCR)	21	21		
Surface Condition Rating (SCR)	21	21		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	21	21		
Alligator Crack Index	100	100		
Longitudinal Crack Index	21	21		
Transverse Cracking Index	69	69		
Patching Index	100	100		
Rutting Index	97	97		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	4	4		
Paved Width (ft)	48	48		
Lane Width (ft)	19.6	19.6		

ROUTE 0498: NYPD ROAD 2




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60)	61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated	
Colors on map represent co	ndition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.	
Inspection Date: 4/23/2021	Beginning Section MP	0			
Paved Length (Miles): 0.09	Section Length (MI)	0.09			
Surface Type: ASPHALT	Route Summary		•		
Roadway Condition Information					
Pavement Condition Rating (PCR)	13	13			
Surface Condition Rating (SCR)	13	13			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	13	13			
Alligator Crack Index	100	100			
Longitudinal Crack Index	13	13			
Transverse Cracking Index	48	48			
Patching Index	98	98			
Rutting Index	97	97			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	40	40			
Lane Width (ft)	21.3	21.3			

ROUTE 0500: CENTRAL RUNWAY

Data Collection Vehicle (DCV) Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Condi	ition Rating (PCR)	
Poor (0 - 60)	61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent co	ndition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/23/2021	Beginning Section MP	0		
Paved Length (Miles): 0.95	Section Length (MI)	0.95		
Surface Type: ASPHALT	Route Summary		• •	
Roadway Condition Information				
Pavement Condition Rating (PCR)	25	25		
Surface Condition Rating (SCR)	0	0		
Roughness Condition Index (RCI)	63	63		
Distress Index Values				
Structural Crack Index	0	0		
Alligator Crack Index	94	94		
Longitudinal Crack Index	0	0		
Transverse Cracking Index	0	0		
Patching Index	97	97		
Rutting Index	92	92		
International Roughness Index (IRI)	229	229		
Lane & Width Information				
Number of Lanes	4	4		
Paved Width (ft)	48	48		
Lane Width (ft)	9.6	9.6		

NOTE: End of route is was not rated because it was a portion transferred from a parking area to Route 0500 after data collection.

ROUTE 0502: DOCK ROAD




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated	
Colors on map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix for definiti	ons and formulas.	
Inspection Date: 4/24/2021	Beginning Section MP	0			
Paved Length (Miles): 0.03	Section Length (MI)	0.03			
Surface Type: ASPHALT	Route Summary		•	• •	
Roadway Condition Information					
Pavement Condition Rating (PCR)	16	16			
Surface Condition Rating (SCR)	16	16			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	45	45			
Alligator Crack Index	100	100			
Longitudinal Crack Index	45	45			
Transverse Cracking Index	16	16			
Patching Index	100	100			
Rutting Index	98	98			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	1	1			
Paved Width (ft)	14.2	14.2			
Lane Width (ft)	14.2	14.2			

ROUTE 0504ZZ: SOUTHERN RUNWAY

Summary Route




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: The weighted average summary PCR value is calculated from only the sections of road where the PCR was collected. The overall PCR for the summary route may not reflect individual subcomponent ratings.

	Route C	Condition Legend – Pay	vement Cond	ition Rating (l	PCR)		
Poor (0 - 60) Fair (6	1- 84) Good	(85 - 94)	Excellent (9	95 - 100)	Not Ra	ted
		See Appendix for de	finitions and	formulas			
Inspection Date:	4/23/2021						
Paved Length (Mile	s): 0.95						
Surface Type:	ASPHALT	Route Summary				•	
Roadway Condition	Information						
Pavement Condition	n Rating (PCR)	26					
Lane & Width Info	rmation						
Number of Lanes		4					
Paved Width (ft)		48					
Lane Width (ft)		10.9					

ROUTE 0504AZ: SOUTHERN RUNWAY A

Subcomponent of Route GATE-0504ZZ Data Collection Vehicle (DCV) Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Cond	ition Rating (PCR)	
Poor (0 - 60) Fair	(61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent co	ondition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/23/2021	Beginning Section MP	0		
Paved Length (Miles): 0.44	Section Length (MI)	0.44		
Surface Type: ASPHALT	Route Summary			• •
Roadway Condition Information				
Pavement Condition Rating (PCR)	47	47		
Surface Condition Rating (SCR)	47	47		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	60	60		
Alligator Crack Index	100	100		
Longitudinal Crack Index	60	60		
Transverse Cracking Index	47	47		
Patching Index	100	100		
Rutting Index	95	95		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	4	4		
Paved Width (ft)	48	48		
Lane Width (ft)	11.6	11.6		

NOTE: Concrete section from mile point 0.30 to 0.42 not rated.

Gateway National Recreation Area ROUTE 0504BZ: SOUTHERN RUNWAY B

Subcomponent of Route GATE-0504ZZ Data Collection Vehicle (DCV) Rating




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95	- 100)	Not Ra	ted
Colors on map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix for d	lefinitions a	and formulas.	
Inspection Date: 4/23/2021	Beginning Section MP	0				
Paved Length (Miles): 0.51	Section Length (MI)	0.51				
Surface Type: ASPHALT	Route Summary					
Roadway Condition Information						
Pavement Condition Rating (PCR)	7	7				
Surface Condition Rating (SCR)	0	0				
Roughness Condition Index (RCI)	17	17				
Distress Index Values						
Structural Crack Index	0	0				
Alligator Crack Index	99	99				
Longitudinal Crack Index	0	0				
Transverse Cracking Index	0	0				
Patching Index	26	26				
Rutting Index	93	93				
International Roughness Index (IRI)	325	325				
Lane & Width Information						
Number of Lanes	4	4				
Paved Width (ft)	48	48				
Lane Width (ft)	10.3	10.3				

ROUTE 0505: MAINTENANCE GAS STATION ROAD

Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)							
Poor (0 - 60) Fa	air (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated			
See Appendix for definitions and formulas							
Inspection Date: 3/6/2021	Beginning Section MP	0.00					
Paved Length (Miles): 0.06	Section Length (MI)	0.06					
Surface Type: ASPHALT	Route Summary		• •	•			
Roadway Condition Information							
Pavement Condition Rating (PCR)	53	53					
Surface Condition Rating (SCR)	53	53					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	N/A	N/A					
Alligator Crack Index	53	53					
Longitudinal Crack Index	73	73					
Transverse Cracking Index	90	90					
Patching Index	90	90					
Rutting Index	97	97					
International Roughness Index (IRI) N/A	N/A					
Lane & Width Information							
Number of Lanes	1	1					
Paved Width (ft)	11	11					
Lane Width (ft)	11	11					

Gateway National Recreation Area ROUTE 0505: MAINTENANCE GAS STATION ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0505_1.jpg



GATE_0505_4.jpg



GATE_0505_6.jpg



GATE_0505_3.jpg




GATE_0505_5.jpg



GATE_0505_9.jpg

ROUTE 0657: HANAKI ROAD

Data Collection Vehicle (DCV) Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route	Condition Legend – Pav	ement Condi	ition Rating (PCR)	
Poor (0 - 60) Fair	(61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent co	ondition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/24/2021	Beginning Section MP	0		
Paved Length (Miles): 0.07	Section Length (MI)	0.07		
Surface Type: ASPHALT	Route Summary		•	
Roadway Condition Information				
Pavement Condition Rating (PCR)	52	52		
Surface Condition Rating (SCR)	52	52		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	93	93		
Alligator Crack Index	100	100		
Longitudinal Crack Index	93	93		
Transverse Cracking Index	52	52		
Patching Index	100	100		
Rutting Index	95	95		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	17.2	17.2		
Lane Width (ft)	8.6	8.6		


ROUTE 0658: KILPATRICK ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Rout	e Condition Legend – Pav	ement Cond	ition Rating (PCR)	
Poor (0 - 60) Fair	(61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent of	ondition scores at 0.10-mil	e intervals. Se	e Appendix for definition	ns and formulas.
Inspection Date: 4/24/2021	Beginning Section MP	0		
Paved Length (Miles): 0.27	Section Length (MI)	0.27		
Surface Type: ASPHALT	Route Summary		•	• •
Roadway Condition Information				
Pavement Condition Rating (PCR)	46	46		
Surface Condition Rating (SCR)	46	46		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	78	78		
Alligator Crack Index	100	100		
Longitudinal Crack Index	78	78		
Transverse Cracking Index	46	46		
Patching Index	98	98		
Rutting Index	95	95		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	21.2	21.2		
Lane Width (ft)	11.1	11.1		

ROUTE 0659: OLD TRAILER CAMP LANE MAST



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60)	(61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated	
Colors on map represent co	ndition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.	
Inspection Date: 4/24/2021	Beginning Section MP	0			
Paved Length (Miles): 0.13	Section Length (MI)	0.13			
Surface Type: ASPHALT	Route Summary				
Roadway Condition Information					
Pavement Condition Rating (PCR)	95	95			
Surface Condition Rating (SCR)	95	95			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	97	97			
Alligator Crack Index	100	100			
Longitudinal Crack Index	97	97			
Transverse Cracking Index	95	95			
Patching Index	99	99			
Rutting Index	98	98			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	20.2	20.2			
Lane Width (ft)	9.9	9.9			

ROUTE 0660: CANFIELD ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated	
Colors on map represent cond	dition scores at 0.10-mile	intervals. Se	e Appendix for definition	ons and formulas.	
Inspection Date: 4/24/2021	Beginning Section MP	0			
Paved Length (Miles): 0.21	Section Length (MI)	0.21			
Surface Type: ASPHALT	Route Summary				
Roadway Condition Information					
Pavement Condition Rating (PCR)	20	20			
Surface Condition Rating (SCR)	20	20			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	58	58			
Alligator Crack Index	100	100			
Longitudinal Crack Index	58	58			
Transverse Cracking Index	20	20			
Patching Index	99	99			
Rutting Index	97	97			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	18.5	18.5			
Lane Width (ft)	9.2	9.2			

ROUTE 0661ZZ: HUDSON ROADS

Summary Route



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: The weighted average summary PCR value is calculated from only the sections of road where the PCR was collected. The overall PCR for the summary route may not reflect individual subcomponent ratings.

Route Condition Legend – Pavement Condition Rating (PCR)											
Poor (0 - 60) Fair (6	61- 84) Good	Good (85 - 94)		Excellent (95 - 100)		Not Rated					
See Appendix for definitions and formulas											
Inspection Date: 4/24/2021											
Paved Length (Miles): 0.72											
Surface Type: ASPHALT	Route Summary										
Roadway Condition Information											
Pavement Condition Rating (PCR)	90										
Lane & Width Information											
Number of Lanes	2										
Paved Width (ft)	21.3										
Lane Width (ft)	10.8										

ROUTE 0661AZ: HUDSON ROAD

Subcomponent of Route GATE-0661ZZ Data Collection Vehicle (DCV) Rating




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)										
Poor (0 - 60) Fair (6	61- 84) Good (85 - 94)		Excellent (95 - 100)		Not Rated					
Colors on map represent condition scores at 0.10-mile intervals. See Appendix for definitions and formulas.										
Inspection Date: 4/24/2021	Beginning Section MP	0								
Paved Length (Miles): 0.66	Section Length (MI)	0.66								
Surface Type: ASPHALT	Route Summary				•					
Roadway Condition Information										
Pavement Condition Rating (PCR)	89	89								
Surface Condition Rating (SCR)	97	97								
Roughness Condition Index (RCI)	77	77								
Distress Index Values										
Structural Crack Index	98	98								
Alligator Crack Index	100	100								
Longitudinal Crack Index	98	98								
Transverse Cracking Index	98	98								
Patching Index	99	99								
Rutting Index	97	97								
International Roughness Index (IRI)	180	180								
Lane & Width Information										
Number of Lanes	2	2								
Paved Width (ft)	21.5	21.5								
Lane Width (ft)	10.9	10.9								

Gateway National Recreation Area ROUTE 0661BZ: HUDSON ROAD SPUR

Subcomponent of Route GATE-0661ZZ Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60)	(61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated	
	See Appendix for def	finitions and	formulas		
Inspection Date: 3/6/2021	Beginning Section MP	0.00			
Paved Length (Miles): 0.03	Section Length (MI)	0.03			
Surface Type: ASPHALT	Route Summary		• •	•	
Roadway Condition Information					
Pavement Condition Rating (PCR)	100	100			
Surface Condition Rating (SCR)	100	100			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	100	100			
Alligator Crack Index	100	100			
Longitudinal Crack Index	100	100			
Transverse Cracking Index	100	100			
Patching Index	100	100			
Rutting Index	100	100			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	19	19			
Lane Width (ft)	9.5	9.5			


Gateway National Recreation Area ROUTE 0661BZ: HUDSON ROAD SPUR

Condition Photos


Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0661BZ_1.jpg



GATE_0661BZ_3.jpg



GATE_0661BZ_5.jpg



GATE_0661BZ_2.jpg




GATE_0661BZ_4.jpg



GATE_0661BZ_6.jpg

Gateway National Recreation Area ROUTE 0661CZ: HUDSON ROAD CUT-THRU

Subcomponent of Route GATE-0661ZZ Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fai	r (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated		
	See Appendix for det	finitions and	formulas			
Inspection Date: 3/6/2021	Beginning Section MP	0.00				
Paved Length (Miles): 0.03	Section Length (MI)	0.03				
Surface Type: ASPHALT	Route Summary			•		
Roadway Condition Information						
Pavement Condition Rating (PCR)	98	98				
Surface Condition Rating (SCR)	98	98				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	100	100				
Alligator Crack Index	100	100				
Longitudinal Crack Index	100	100				
Transverse Cracking Index	100	100				
Patching Index	98	98				
Rutting Index	100	100				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	19	19				
Lane Width (ft)	9.5	9.5				

Gateway National Recreation Area ROUTE 0661CZ: HUDSON ROAD CUT-THRU

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0661CZ_1.jpg



GATE_0661CZ_3.jpg



GATE_0661CZ_5.jpg



GATE_0661CZ_2.jpg



GATE_0661CZ_4.jpg



GATE_0661CZ_6.jpg

Gateway National Recreation Area ROUTE 0662ZZ: MAGRUDER ROADS

Summary Route



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: The weighted average summary PCR value is calculated from only the sections of road where the PCR was collected. The overall PCR for the summary route may not reflect individual subcomponent ratings.

	Route C	Condition Legend –	Pavement Con	dition Rating (PCR)	
Poor (0 - 60) Fair (61		<mark>1- 84) Go</mark>	od (85 - 94)	Excellent (95 - 100)	Not Rated
See Appendix for definitions and formulas					
Inspection Date:	4/24/2021				
Paved Length (Mile	es): 0.53				
Surface Type:	ASPHALT	Route Summary		• •	
Roadway Condition	1 Information				
Pavement Conditio	n Rating (PCR)	34			
Lane & Width Info	rmation				
Number of Lanes		2			
Paved Width (ft)		30.8			
Lane Width (ft)		14.4			

Gateway National Recreation Area ROUTE 0662AZ: MAGRUDER ROAD

Subcomponent of Route GATE-0662ZZ Data Collection Vehicle (DCV) Rating




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60) Fair (0	61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated	
Colors on map represent cor	dition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ons and formulas.	
Inspection Date: 4/24/2021	Beginning Section MP	0			
Paved Length (Miles): 0.45	Section Length (MI)	0.45			
Surface Type: ASPHALT	Route Summary		• •		
Roadway Condition Information					
Pavement Condition Rating (PCR)	28	28			
Surface Condition Rating (SCR)	28	28			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	49	49			
Alligator Crack Index	100	100			
Longitudinal Crack Index	49	49			
Transverse Cracking Index	28	28			
Patching Index	96	96			
Rutting Index	95	95			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	32.3	32.3			
Lane Width (ft)	15	15			

Gateway National Recreation Area ROUTE 0662BZ: MAGRUDER ROAD SPUR 1

Subcomponent of Route GATE-0662ZZ Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated	
	See Appendix for def	initions and f	ormulas		
Inspection Date: 3/6/2021	Beginning Section MP	0.00			
Paved Length (Miles): 0.06	Section Length (MI)	0.06			
Surface Type: ASPHALT	Route Summary			• •	
Roadway Condition Information					
Pavement Condition Rating (PCR)	100	100			
Surface Condition Rating (SCR)	100	100			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	100	100			
Alligator Crack Index	100	100			
Longitudinal Crack Index	100	100			
Transverse Cracking Index	100	100			
Patching Index	100	100			
Rutting Index	100	100			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	24	24			
Lane Width (ft)	12	12			


Gateway National Recreation Area ROUTE 0662BZ: MAGRUDER ROAD SPUR 1

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0662BZ_1.jpg



GATE_0662BZ_4.jpg



GATE_0662BZ_6.jpg



GATE_0662BZ_2.jpg




GATE_0662BZ_5.jpg



GATE_0662BZ_7.jpg

Gateway National Recreation Area ROUTE 0662CZ: MAGRUDER ROAD SPUR 2

Subcomponent of Route GATE-0662ZZ Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60) Fair (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated	
	See Appendix for def	finitions and f	ormulas		
Inspection Date: 3/6/2021	Beginning Section MP	0.00			
Paved Length (Miles): 0.02	Section Length (MI)	0.02			
Surface Type: ASPHALT	Route Summary				
Roadway Condition Information					
Pavement Condition Rating (PCR)	45	45			
Surface Condition Rating (SCR)	45	45			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	45	45			
Alligator Crack Index	56	56			
Longitudinal Crack Index	89	89			
Transverse Cracking Index	90	90			
Patching Index	100	100			
Rutting Index	100	100			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	18	18			
Lane Width (ft)	9	9			

Gateway National Recreation Area ROUTE 0662CZ: MAGRUDER ROAD SPUR 2

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.





GATE_0662CZ_3.jpg



GATE_0662CZ_6.jpg



GATE_0662CZ_2.jpg




GATE_0662CZ_5.jpg



GATE_0662CZ_7.jpg

ROUTE 0663: PENNINGTON STREET





Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 100	D) Not Rated	
Colors on map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix for defini	itions and formulas.	
Inspection Date: 4/24/2021	Beginning Section MP	0			
Paved Length (Miles): 0.14	Section Length (MI)	0.14			
Surface Type: ASPHALT	Route Summary				
Roadway Condition Information					
Pavement Condition Rating (PCR)	16	16			
Surface Condition Rating (SCR)	16	16			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	33	33			
Alligator Crack Index	96	96			
Longitudinal Crack Index	37	37			
Transverse Cracking Index	16	16			
Patching Index	100	100			
Rutting Index	96	96			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	19.5	19.5			
Lane Width (ft)	9.8	9.8			


ROUTE 0664: KESSLER ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95	- 100)	Not Rat	ted
Colors on map represent con-	dition scores at 0.10-mile	intervals. Se	e Appendix for	definitions	and formulas.	
Inspection Date: 4/24/2021	Beginning Section MP	0				
Paved Length (Miles): 0.48	Section Length (MI)	0.48				
Surface Type: ASPHALT	Route Summary				•	
Roadway Condition Information						
Pavement Condition Rating (PCR)	12	12				
Surface Condition Rating (SCR)	12	12				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	32	32				
Alligator Crack Index	92	92				
Longitudinal Crack Index	40	40				
Transverse Cracking Index	12	12				
Patching Index	98	98				
Rutting Index	81	81				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	15.2	15.2				
Lane Width (ft)	7.6	7.6				


ROUTE 0665: KEARNY DRIVE



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60) Fa	ir (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated	
Colors on map represent	condition scores at 0.10-mile	e intervals. Se	ee Appendix for definition	ns and formulas.	
Inspection Date: 4/24/2021	Beginning Section MP	0			
Paved Length (Miles): 0.53	Section Length (MI)	0.53			
Surface Type: ASPHALT	Route Summary		•	•	
Roadway Condition Information					
Pavement Condition Rating (PCR)	80	80			
Surface Condition Rating (SCR)	97	97			
Roughness Condition Index (RCI)	55	55			
Distress Index Values					
Structural Crack Index	99	99			
Alligator Crack Index	100	100			
Longitudinal Crack Index	99	99			
Transverse Cracking Index	99	99			
Patching Index	100	100			
Rutting Index	97	97			
International Roughness Index (IRI)	259	259			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	26.6	26.6			
Lane Width (ft)	13.1	13.1			


ROUTE 0666: LAWSON LANE



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Rou	te Condition Legend – Pav	ement Cond	ition Rating (PCR)	
		(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represent	condition scores at 0.10-mile	e intervals. Se	ee Appendix for definition	ns and formulas.
Inspection Date: 4/24/2021	Beginning Section MP	0		
Paved Length (Miles): 0.07	Section Length (MI)	0.07		
Surface Type: ASPHALT	Route Summary		•	• •
Roadway Condition Information				
Pavement Condition Rating (PCR)	97	97		
Surface Condition Rating (SCR)	97	97		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	99	99		
Alligator Crack Index	100	100		
Longitudinal Crack Index	99	99		
Transverse Cracking Index	97	97		
Patching Index	100	100		
Rutting Index	98	98		
International Roughness Index (IRI)	N/A	N/A		
Lane & Width Information				
Number of Lanes	1	1		
Paved Width (ft)	15.8	15.8		
Lane Width (ft)	15.8	15.8		


ROUTE 0668: SOUTH BRAGG DRIVE



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated	
Colors on map represent con	dition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ons and formulas.	
Inspection Date: 4/24/2021	Beginning Section MP	0			
Paved Length (Miles): 0.29	Section Length (MI)	0.29			
Surface Type: ASPHALT	Route Summary		•		
Roadway Condition Information					
Pavement Condition Rating (PCR)	0	0			
Surface Condition Rating (SCR)	0	0			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	0	0			
Alligator Crack Index	99	99			
Longitudinal Crack Index	0	0			
Transverse Cracking Index	0	0			
Patching Index	99	99			
Rutting Index	92	92			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	22.7	22.7			
Lane Width (ft)	12.9	12.9			


ROUTE 0669: KNOX ROAD NORTH



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60) Fair	(61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated	
Colors on map represent co	ondition scores at 0.10-mile	e intervals. Se	e Appendix for definition	ns and formulas.	
Inspection Date: 4/24/2021	Beginning Section MP	0			
Paved Length (Miles): 0.12	Section Length (MI)	0.12			
Surface Type: ASPHALT	Route Summary		•	• •	
Roadway Condition Information					
Pavement Condition Rating (PCR)	55	55			
Surface Condition Rating (SCR)	55	55			
Roughness Condition Index (RCI)	N/A	N/A			
Distress Index Values					
Structural Crack Index	73	73			
Alligator Crack Index	100	100			
Longitudinal Crack Index	73	73			
Transverse Cracking Index	55	55			
Patching Index	100	100			
Rutting Index	97	97			
International Roughness Index (IRI)	N/A	N/A			
Lane & Width Information					
Number of Lanes	2	2			
Paved Width (ft)	19.8	19.8			
Lane Width (ft)	9.9	9.9			


ROUTE 0670: OLD GUNNISON ROAD/MAST WAY



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

R	oute Condition Legend – Pav	vement Cond	ition Rating (PCR)	
	, , , , , , , , , , , , , , , , , , ,	(85 - 94)	Excellent (95 - 100)	Not Rated
Colors on map represen	nt condition scores at 0.10-mil	e intervals. Se	ee Appendix for definition	1s and formulas.
Inspection Date: 4/24/2021	Beginning Section MI) 0		
Paved Length (Miles): 0.15	Section Length (MI)	0.15		
Surface Type: ASPHALT	Route Summary		•	• •
Roadway Condition Information				
Pavement Condition Rating (PCR)	100	100		
Surface Condition Rating (SCR)	100	100		
Roughness Condition Index (RCI)	N/A	N/A		
Distress Index Values				
Structural Crack Index	100	100		
Alligator Crack Index	100	100		
Longitudinal Crack Index	100	100		
Transverse Cracking Index	100	100		
Patching Index	100	100		
Rutting Index	100	100		
International Roughness Index (IR	I) N/A	N/A		
Lane & Width Information				
Number of Lanes	2	2		
Paved Width (ft)	23	23		
Lane Width (ft)	11.6	11.6		

ROUTE 0671: NEW GUNNISON ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (61- 84) Good (85 - 94)		Excellent (95 - 100)	Not Rated		
Colors on map represent con	ndition scores at 0.10-mile	ion scores at 0.10-mile intervals. See Appendix for definitions and formulas.				
Inspection Date: 4/24/2021	Beginning Section MP	0				
Paved Length (Miles): 0.28	Section Length (MI)	0.28				
Surface Type: ASPHALT	Route Summary		•	•		
Roadway Condition Information						
Pavement Condition Rating (PCR)	44	44				
Surface Condition Rating (SCR)	44	44				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	69	69				
Alligator Crack Index	100	100				
Longitudinal Crack Index	69	69				
Transverse Cracking Index	44	44				
Patching Index	99	99				
Rutting Index	97	97				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	22.6	22.6				
Lane Width (ft)	10.7	10.7				


ROUTE 0672: FORD ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated		
Colors on map represent con	dition scores at 0.10-mile	ion scores at 0.10-mile intervals. See Appendix for definitions and formulas.				
Inspection Date: 4/24/2021	Beginning Section MP	0				
Paved Length (Miles): 0.11	Section Length (MI)	0.11				
Surface Type: ASPHALT	Route Summary					
Roadway Condition Information						
Pavement Condition Rating (PCR)	89	89				
Surface Condition Rating (SCR)	89	89				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	100	100				
Alligator Crack Index	100	100				
Longitudinal Crack Index	100	100				
Transverse Cracking Index	89	89				
Patching Index	100	100				
Rutting Index	100	100				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	2	2				
Paved Width (ft)	30.1	30.1				
Lane Width (ft)	12.5	12.5				

ROUTE 0674: MERCER ROAD



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Rou	te Condition Legend – Pav	ement Cond	ition Rating (PCR)				
Poor (0 - 60) Fai	r (61- 84) Good	(85 - 94)	Excellent (95 - 100)	Not Rated			
Colors on map represent	condition scores at 0.10-mile	ion scores at 0.10-mile intervals. See Appendix for definitions and formulas.					
Inspection Date: 4/24/2021	Beginning Section MP	0					
Paved Length (Miles): 0.11	Section Length (MI)	0.11					
Surface Type: ASPHALT	Route Summary		•	•			
Roadway Condition Information							
Pavement Condition Rating (PCR)	23	23					
Surface Condition Rating (SCR)	23	23					
Roughness Condition Index (RCI)	N/A	N/A					
Distress Index Values							
Structural Crack Index	59	59					
Alligator Crack Index	100	100					
Longitudinal Crack Index	59	59					
Transverse Cracking Index	23	23					
Patching Index	100	100					
Rutting Index	97	97					
International Roughness Index (IRI)	N/A	N/A					
Lane & Width Information							
Number of Lanes	2	2					
Paved Width (ft)	18.8	18.8					
Lane Width (ft)	9.8	9.8					

ROUTE 0675ZZ: MCNAIR ROADS

Summary Route




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Note: The weighted average summary PCR value is calculated from only the sections of road where the PCR was collected. The overall PCR for the summary route may not reflect individual subcomponent ratings.

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6	1- 84) Good (85 - 94)		Excellent (95 - 100)		Not Rated	
	See Appendix for det	finitions and f	formulas			
Inspection Date: 4/24/2021						
Paved Length (Miles): 0.2						
Surface Type: ASPHALT	Route Summary		• • •			
Roadway Condition Information						
Pavement Condition Rating (PCR)	19					
Lane & Width Information						
Number of Lanes	1					
Paved Width (ft)	16.1					
Lane Width (ft)	16.1					

ROUTE 0675AZ: MCNAIR ROAD

Subcomponent of Route GATE-0675ZZ Data Collection Vehicle (DCV) Rating




Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (61- 84) Good (85 - 94)		Excellent (95 - 100)	Not Rated		
Colors on map represent co	ndition scores at 0.10-mile	ion scores at 0.10-mile intervals. See Appendix for definitions and formulas.				
Inspection Date: 4/24/2021	Beginning Section MP	0				
Paved Length (Miles): 0.15	Section Length (MI)	0.15				
Surface Type: ASPHALT	Route Summary		•	• •		
Roadway Condition Information						
Pavement Condition Rating (PCR)	0	0				
Surface Condition Rating (SCR)	0	0				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	7	7				
Alligator Crack Index	97	97				
Longitudinal Crack Index	10	10				
Transverse Cracking Index	0	0				
Patching Index	100	100				
Rutting Index	97	97				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	1	1				
Paved Width (ft)	16.2	16.2				
Lane Width (ft)	16.2	16.2				

Gateway National Recreation Area ROUTE 0675BZ: MCNAIR ROAD CUT-THRU B

Subcomponent of Route GATE-0675ZZ Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)								
Poor (0 - 60) Fair (6	6 <mark>1- 84) Good (</mark>	85 - 94)	Excellent (9	5 - 100)	Not Ra	ted	
	See Appendix for definitions and formulas							
Inspection Date:	3/6/2021	Beginning Section MP	0.00					
Paved Length (Mile	es): 0.03	Section Length (MI)	0.03					
Surface Type:	ASPHALT	Route Summary		•		•		
Roadway Condition	1 Information							
Pavement Conditio	n Rating (PCR)	73	73					
Surface Condition R	ating (SCR)	73	73					
Roughness Conditio	n Index (RCI)	N/A	N/A					
Distress Index Valu	es							
Structural Crack In	dex	N/A	N/A					
Alligator Crack Ind	lex	90	90					
Longitudinal Crack	Index	90	90					
Transverse Crackin	g Index	73	73					
Patching Index		90	90					
Rutting Index		97	97					
International Rough	hness Index (IRI)	N/A	N/A					
Lane & Width Info	rmation							
Number of Lanes		1	1					
Paved Width (ft)		16	16					
Lane Width (ft)		16	16					

Gateway National Recreation Area ROUTE 0675BZ: MCNAIR ROAD CUT-THRU B

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0675BZ_1.jpg



GATE_0675BZ_3.jpg



GATE_0675BZ_5.jpg



GATE_0675BZ_2.jpg



GATE_0675BZ_4.jpg



GATE_0675BZ_6.jpg

Gateway National Recreation Area ROUTE 0675CZ: MCNAIR ROAD CUT-THRU C

Subcomponent of Route GATE-0675ZZ Manual Rating



Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60) Fair (6	1- 84) Good ((85 - 94)	Excellent (95 - 100)	Not Rated		
	See Appendix for def	initions and f	formulas			
Inspection Date: 3/6/2021	Beginning Section MP	0.00				
Paved Length (Miles): 0.03	Section Length (MI)	0.03				
Surface Type: ASPHALT	Route Summary		•			
Roadway Condition Information						
Pavement Condition Rating (PCR)	73	73				
Surface Condition Rating (SCR)	73	73				
Roughness Condition Index (RCI)	N/A	N/A				
Distress Index Values						
Structural Crack Index	N/A	N/A				
Alligator Crack Index	73	73				
Longitudinal Crack Index	90	90				
Transverse Cracking Index	90	90				
Patching Index	97	97				
Rutting Index	97	97				
International Roughness Index (IRI)	N/A	N/A				
Lane & Width Information						
Number of Lanes	1	1				
Paved Width (ft)	16	16				
Lane Width (ft)	16	16				

Gateway National Recreation Area ROUTE 0675CZ: MCNAIR ROAD CUT-THRU C

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GATE_0675CZ_1.jpg



GATE_0675CZ_3.jpg



GATE_0675CZ_5.jpg



GATE_0675CZ_2.jpg



GATE_0675CZ_4.jpg



GATE_0675CZ_6.jpg

Section 6 Paved Parking Area Condition Rating Sheets



Gateway National Recreation Area




ROUTE 0900: ENTRANCE STATION PARKING A

Manual Rating

FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))

TO PARKING




Gateway National Recreation Area ROUTE 0901: GATEWAY SPORTS PARKING

Manual Rating

FROM ROUTE 5006S (FLATBUSH AVENUE (SOUTHBOUND))

TO ROUTE 5006S (FLATBUSH AVENUE (SOUTHBOUND))




Gateway National Recreation Area ROUTE 0902: GATEWAY MARINA PARKING

Manual Rating

FROM ROUTE 5006S (FLATBUSH AVENUE (SOUTHBOUND))

TO PARKING




Gateway National Recreation Area ROUTE 0905: SANDY HOOK VISITOR CENTER PARKING

Manual Rating

FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 2.20

TO PARKING



ROUTE 0906ZZ: JACOB RIIS PARKING

Summary Route Manual Rating


FROM ROCKAWAY BEACH BOULEVARD

TO ROUTE 5000 (ROCKAWAY POINT BOULEVARD)

Inspection Date	FMSS Number	User Access	Surface Type			
3/3/2021	36107	PUBLIC	CONCRETE			
Area (Sq. Ft.)	Lane Miles (11' Widths)	Condition Rating / PCR				
2,641,982	45.488	SUMMARY / 84				
Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60)	Fair (61- 84) Good ((85 - 94) Excellent (95 - 10	0) Not Rated			
See Appendix for definitions and formulas						

The condition shown on this page reflects the overall route condition and may not reflect individual subcomponent ratings.

Rte. 0906ZZ (6 Subcomponents)




Gateway National Recreation Area ROUTE 0906AZ: JACOB RIIS PARKING A

Subcomponent of Route GATE-0906ZZ Manual Rating

FROM ROUTE 5003 (ROCKAWAY BEACH BOULEVARD)

TO ROUTE 0906BZ (JACOB RIIS PARKING B)




Gateway National Recreation Area ROUTE 0906BZ: JACOB RIIS PARKING B

Subcomponent of Route GATE-0906ZZ Manual Rating

FROM ROUTE 0906AZ (JACOB RIIS PARKING A)

TO ROUTE 0906DZ (JACOB RIIS PARKING D)




Gateway National Recreation Area ROUTE 0906CZ: JACOB RIIS PARKING C

Subcomponent of Route GATE-0906ZZ Manual Rating

FROM ROUTE 0906AZ (JACOB RIIS PARKING A)

TO ROUTE 0906EZ (JACOB RIIS PARKING E)




Gateway National Recreation Area ROUTE 0906DZ: JACOB RIIS PARKING D

Subcomponent of Route GATE-0906ZZ Manual Rating

FROM ROUTE 0906BZ (JACOB RIIS PARKING B)

TO ROUTE 0906FZ (JACOB RIIS PARKING F)




Gateway National Recreation Area ROUTE 0906EZ: JACOB RIIS PARKING E

Subcomponent of Route GATE-0906ZZ Manual Rating

FROM ROUTE 0906CZ (JACOB RIIS PARKING C)

TO ROUTE 5000 (ROCKAWAY POINT BOULEVARD)




Gateway National Recreation Area ROUTE 0906FZ: JACOB RIIS PARKING F

Subcomponent of Route GATE-0906ZZ Manual Rating

FROM ROUTE 0906DZ (JACOB RIIS PARKING D)


TO ROUTE 5000 (ROCKAWAY POINT BOULEVARD)



Gateway National Recreation Area ROUTE 0907: RANGER STATION PARKING A EAST

Manual Rating

ADJACENT TO ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 2.47




Gateway National Recreation Area ROUTE 0908: RANGER PARKING B NORTH

Manual Rating

FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))


TO ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) OPPOSITE DIRECTION



Gateway National Recreation Area ROUTE 0909B: MAINTENANCE PARKING EAST

Manual Rating

FROM END OF ROUTE 0483ZZ (SOUTH MAINTENANCE SHOP ROAD C)




Gateway National Recreation Area

ROUTE 0909C: MAINTENANCE PARKING WEST

Manual Rating


ADJACENT TO ROUTE 0483ZZ (SOUTH MAINTENANCE SHOP ROAD C)



Gateway National Recreation Area ROUTE 0910A: MAINTENANCE SHOP EMPLOYEE PARKING

Manual Rating


FROM ROUTE 0481 (SOUTH MAINTENANCE SHOP ROAD A)



Gateway National Recreation Area ROUTE 0910B: MAINTENANCE HEAVY VEHICLE PARKING

Manual Rating


ADJACENT TO ROUTE 0481 (SOUTH MAINTENANCE SHOP ROAD A)



Gateway National Recreation Area ROUTE 0911: MISSILE PARKING LOT

Manual Rating

ADJACENT TO ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 2.7




Gateway National Recreation Area ROUTE 0913: LOT "L" NIKE RADAR SITE PARKING

Manual Rating

FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 3.74

TO ROUTE 0477ZZ (NIKE RADAR SITE ROADS)




Gateway National Recreation Area ROUTE 0914: LOT "H" CAMPGROUND PARKING

Manual Rating

FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 4.0


TO ROUTE 0476 (CAMPSITE ROAD)



Gateway National Recreation Area ROUTE 0915: WATER TREATMENT PLANT PARKING

Manual Rating


FROM ROUTE 0462 (RANDOLPH ROAD)



Gateway National Recreation Area ROUTE 0916: GUARDIAN PARK PARKING

Manual Rating

FROM ROUTE 0662ZZ (MAGRUDER ROADS)




Gateway National Recreation Area

ROUTE 0917: DAYCARE #335 AND #18 PARKING

Manual Rating

FROM ROUTE 0663 (PENNINGTON STREET)

TO ROUTE 0664 (KESSLER ROAD)




Gateway National Recreation Area ROUTE 0918A: NOAA LAB A PARKING SOUTH

Manual Rating

FROM ROUTE 0662ZZ (MAGRUDER ROADS)

TO ROUTE 1037 (NOAA SERVICE PARKING LOT)




Gateway National Recreation Area ROUTE 0918B: NOAA LAB B PARKING NORTH

Manual Rating

FROM ROUTE 0662ZZ (MAGRUDER ROADS)


TO ROUTE 0671 (NEW GUNNISON ROAD)



Gateway National Recreation Area ROUTE 0919: BUILDING 74 EAST PARKING

Manual Rating


FROM ROUTE 0662ZZ (MAGRUDER ROADS)



Gateway National Recreation Area ROUTE 0920: MARINE ACADEMY CAFETERIA #77 PARKING

Manual Rating

FROM ROUTE 0659 (OLD TRAILER CAMP LANE MAST)




Gateway National Recreation Area

ROUTE 0921: MAST PARKING LOT "N"

Manual Rating

FROM ROUTE 0662ZZ (MAGRUDER ROADS)


TO ROUTE 0670 (OLD GUNNISON ROAD/MAST WAY)



Gateway National Recreation Area ROUTE 0922: MAST SCHOOL OFFICES TEACHERS PARKING

Manual Rating

FROM ROUTE 0670 (OLD GUNNISON ROAD/MAST WAY)




Gateway National Recreation Area ROUTE 0923: BUILDING 53 AND BUILDING 60 PARKING

Manual Rating

FROM ROUTE 0661ZZ (HUDSON ROADS)


TO INTERSECTION OF ROUTE 0674 (MERCER ROAD) AND ROUTE 0675ZZ (MCNAIR ROADS)



Gateway National Recreation Area ROUTE 0924: BUILDING 40/ POST OFFICE/ GYM PARKING

Manual Rating


ADJACENT TO ROUTE 0675ZZ (MCNAIR ROADS)



Gateway National Recreation Area ROUTE 0925: LIGHTHOUSE PARKING

Manual Rating

ADJACENT TO ROUTE 0674 (MERCER ROAD)




Gateway National Recreation Area

ROUTE 0926: LAWSON LANE PARKING

Manual Rating


ADJACENT TO ROUTE 0666 (LAWSON LANE)



Gateway National Recreation Area ROUTE 0927: BUILDING 32 PARK RANGER PARKING

Manual Rating


FROM ROUTE 0665 (KEARNY DRIVE)



Gateway National Recreation Area ROUTE 0928A: NORTH MAINTENANCE EMPLOYEE PARKING A

Manual Rating


FROM ROUTE 0460 (NORTH MAINTENANCE AREA ACCESS ROAD)



Gateway National Recreation Area ROUTE 0928B: NORTH MAINTENANCE EMPLOYEE PARKING B

Manual Rating

ADJACENT TO ROUTE 0460 (NORTH MAINTENANCE AREA ACCESS ROAD) ON RIGHT




Gateway National Recreation Area

ROUTE 0929: GUNNISON BEACH PARKING

Manual Rating

FROM ROUTE 0671 (NEW GUNNISON ROAD)

TO INTERSECTION OF ROUTE 0671 (NEW GUNNISON ROAD) AND ROUTE 0160 (ATLANTIC DRIVE)




Gateway National Recreation Area ROUTE 0930: NORTH BEACH PARKING

Manual Rating

FROM ROUTE 0160 (ATLANTIC DRIVE)


TO ROUTE 0160 (ATLANTIC DRIVE) AND ROUTE 0484 (NORTH BEACH SERVICE ROAD)



Gateway National Recreation Area ROUTE 0931: EMPLOYEE PULLOUT GUNNISON PARKING

Manual Rating


FROM ROUTE 0160 (ATLANTIC DRIVE)



Gateway National Recreation Area ROUTE 0933: FEE COLLECTORS PARKING

Manual Rating

FROM ROUTE 0061 (HARTSHORNE DRIVE (SOUTHBOUND))




Gateway National Recreation Area ROUTE 0934: QUARTER 600 PARKING

Manual Rating

FROM ROUTE 0061 (HARTSHORNE DRIVE (SOUTHBOUND))

TO ROUTE 0061 (HARTSHORNE DRIVE (SOUTHBOUND))




Gateway National Recreation Area ROUTE 0935: SEWAGE PLANT PARKING

Manual Rating

FROM ROUTE 0160 (ATLANTIC DRIVE) AT MP 0.79

TO ROUTE 0160 (ATLANTIC DRIVE)




Gateway National Recreation Area ROUTE 0936: FORT HANCOCK THEATER PARKING

Manual Rating

FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 5.20

TO ROUTE 0665 (KEARNY DRIVE)




Gateway National Recreation Area

ROUTE 0937: BUILDING 58 PARKING

Manual Rating

FROM ROUTE 0662ZZ (MAGRUDER ROADS)




Gateway National Recreation Area ROUTE 0938: AREA B PARKING LOT B

Manual Rating

FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 0.63

TO ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))




ROUTE 0939: AREA C PARKING LOT C

Manual Rating

FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 1.42

TO PARKING



Gateway National Recreation Area ROUTE 0940ZZ: GREAT KILLS ENTRANCE PARKING AREAS


Summary Route Manual Rating

ADJACENT TO ROUTE 0030 (BUFFALO ROAD) AT MP 0.05 LEFT AND RIGHT

Inspection Date	FMSS Number	User Access	Surface Type		
3/5/2021	25235	PUBLIC	ASPHALT		
Area (Sq. Ft.)	Lane Miles (11' Widths)	Condition Rating / PCR			
17,240	0.297	SUMMARY / 90			
Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60)	Fair (61- 84) Good ((85 - 94) Excellent (95 - 10	0) Not Rated		
See Appendix for definitions and formulas					

The condition shown on this page reflects the overall route condition and may not reflect individual subcomponent ratings.






Gateway National Recreation Area ROUTE 0940AZ: GREAT KILLS ENTRANCE PARKING A

Subcomponent of Route GATE-0940ZZ Manual Rating


ADJACENT TO ROUTE 0030 (BUFFALO ROAD) AT MP 0.05 ON LEFT



Gateway National Recreation Area ROUTE 0940BZ: GREAT KILLS ENTRANCE PARKING B

Subcomponent of Route GATE-0940ZZ Manual Rating

ADJACENT TO ROUTE 0030 (BUFFALO ROAD) AT MP 0.05 ON RIGHT




ROUTE 0941: USPP/RANGER PARKING

Manual Rating

FROM ROUTE 0030 (BUFFALO ROAD) AT MP 0.88 RIGHT

TO ROUTE 0030 (BUFFALO ROAD)




ROUTE 0942: GK AREA "A" PARKING

Manual Rating

FROM ROUTE 0030 (BUFFALO ROAD) AT MP 0.93 LEFT

TO ROUTE 0030 (BUFFALO ROAD)




ROUTE 0943: BOAT LAUNCH PARKING

Manual Rating

FROM ROUTE 0030 (BUFFALO ROAD) AT MP 1.16

TO PARKING




ROUTE 0944: GK AREA "E" PARKING

Manual Rating

FROM ROUTE 0030 (BUFFALO ROAD) AT MP 1.32

TO PARKING




ROUTE 0945: GK AREA "F" PARKING

Manual Rating

FROM ROUTE 0030 (BUFFALO ROAD) AT MP 1.43

TO ROUTE 0030 (BUFFALO ROAD)




Gateway National Recreation Area ROUTE 0946: BEACH CENTER PARKING

Manual Rating

FROM ROUTE 0030 (BUFFALO ROAD) AT MP 1.67

TO ROUTE 0030 (BUFFALO ROAD) AND ROUTE 0947 (BEACH PICKUP AREA)




Gateway National Recreation Area ROUTE 0947: BEACH PICKUP AREA

Manual Rating

FROM ROUTE 0030 (BUFFALO ROAD) AT MP 1.57

TO ROUTE 0030 (BUFFALO ROAD) AND ROUTE 0946 (BEACH CENTER PARKING)




Gateway National Recreation Area ROUTE 0948: MILLER FIELD PARKING LOT (BALL FIELD)

Manual Rating

FROM ROUTE 0130 (MILLER FIELD ENTRANCE ROAD) AT MP 0.09


TO ROUTE 0130 (MILLER FIELD ENTRANCE ROAD)



Gateway National Recreation Area ROUTE 0949: RANGER STATION PARKING

Manual Rating

ADJACENT TO ROUTE 0132A (VISITOR CENTER (SANCHEZ ROAD EAST))




Gateway National Recreation Area ROUTE 0951: CIRCLE PARKING

Manual Rating

FROM ROUTE 0132A (VISITOR CENTER (SANCHEZ ROAD EAST))

TO ROUTE 0132B (HOUSING ACCESS (SANCHEZ ROAD WEST))




ROUTE 0952: RESIDENCE PARKING

Manual Rating

FROM ROUTE 0132B (HOUSING ACCESS (SANCHEZ ROAD WEST))

TO PARKING




Gateway National Recreation Area ROUTE 0953A: NEW DORP HIGH SCHOOL PARKING A

Manual Rating

FROM END OF ROUTE 0132B (HOUSING ACCESS (SANCHEZ ROAD WEST))

TO ROUTE 0953C (NEW DORP HIGH SCHOOL PARKING C)




Gateway National Recreation Area ROUTE 0953C: NEW DORP HIGH SCHOOL PARKING C

Manual Rating

FROM ROUTE 0953A (NEW DORP HIGH SCHOOL PARKING A)

TO NEW DORP LANE




Gateway National Recreation Area ROUTE 0953D: NEW DORP HIGH SCHOOL PARKING D

Manual Rating

FROM ROUTE 0953C (NEW DORP HIGH SCHOOL PARKING C)

TO ROUTE 0953C (NEW DORP HIGH SCHOOL PARKING C)




ROUTE 0954: MAIN GATE PARKING

Manual Rating

FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)

TO PARKING



Gateway National Recreation Area ROUTE 0955AZZ: COAST GUARD AREA PARKING A


Summary Route Manual Rating

ADJACENT TO ROUTE 0449 (COAST GUARD DRIVE) ON RIGHT

Inspection Date	FMSS Number	User Access	Surface Type		
3/5/2021	33184	PUBLIC	ASPHALT		
Area (Sq. Ft.)	Lane Miles (11' Widths)	Condition Rating / PCR			
24,970	0.43	SUMMARY / 75			
Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60)	Fair (61- 84) Good ((85 - 94) Excellent (95 - 10	0) Not Rated		
See Appendix for definitions and formulas					

The condition shown on this page reflects the overall route condition and may not reflect individual subcomponent ratings.


Rte. 0955AZZ (3 Subcomponents)



Gateway National Recreation Area ROUTE 0955AAZ: COAST GUARD AREA PARKING AAZ

Subcomponent of Route GATE-0955AZZ Manual Rating


ADJACENT TO ROUTE 0449 (COAST GUARD DRIVE) ON RIGHT



Gateway National Recreation Area ROUTE 0955ABZ: COAST GUARD AREA PARKING ABZ

Subcomponent of Route GATE-0955AZZ Manual Rating


ADJACENT TO ROUTE 0449 (COAST GUARD DRIVE) ON RIGHT



Gateway National Recreation Area ROUTE 0955ACZ: COAST GUARD AREA PARKING ACZ

Subcomponent of Route GATE-0955AZZ Manual Rating

ADJACENT TO ROUTE 0449 (COAST GUARD DRIVE) ON RIGHT




Gateway National Recreation Area ROUTE 0955B: COAST GUARD AREA PARKING B

Manual Rating

FROM ROUTE 0449 (COAST GUARD DRIVE) ON RIGHT

TO ROUTE 0449 (COAST GUARD DRIVE)




Gateway National Recreation Area ROUTE 0955C: USCG ACTIVITIES PARKING

Manual Rating

FROM ROUTE 0449 (COAST GUARD DRIVE) ON RIGHT


TO ROUTE 0449 (COAST GUARD DRIVE)



Gateway National Recreation Area ROUTE 0955D: USCG GALLEY PARKING

Manual Rating

ADJACENT TO ROUTE 0449 (COAST GUARD DRIVE) ON LEFT




Gateway National Recreation Area ROUTE 0955E: USCG GALLEY REAR PARKING AND FIRE LANE

Manual Rating

FROM ROUTE 0449 (COAST GUARD DRIVE) ON LEFT

TO ROUTE 0450 (DRUM AVENUE)




ROUTE 0955F: USCG PX PARKING

Manual Rating

FROM ROUTE 0449 (COAST GUARD DRIVE)

TO MARSHALL ROAD AND ROUTE 0957A (THEATRE PARKING)




ROUTE 0956A: DRUM AVENUE PARKING A

Manual Rating

FROM ROUTE 0450 (DRUM AVENUE)


TO ROUTE 0450 (DRUM AVENUE)



Gateway National Recreation Area ROUTE 0956B: DRUM AVENUE CHAPEL PARKING

Manual Rating

ADJACENT TO ROUTE 0450 (DRUM AVENUE)




Gateway National Recreation Area ROUTE 0956C: DRUM AVENUE LOOP PARKING

Manual Rating

FROM ROUTE 0450 (DRUM AVENUE)


TO ROUTE 0450 (DRUM AVENUE)



Gateway National Recreation Area ROUTE 0956D: DRUM AVENUE PARKING D

Manual Rating

ADJACENT TO ROUTE 0450 (DRUM AVENUE)




Gateway National Recreation Area ROUTE 0957A: THEATRE PARKING

Manual Rating

FROM ROUTE 0955F (USCG PX PARKING)

TO ROUTE 0451 (MOLONY DRIVE)




ROUTE 0957B: HAND BALL PARKING

Manual Rating

FROM ROUTE 0448 (MARSHALL ROAD)

TO ROUTE 0450 (DRUM AVENUE)




ROUTE 0957C: HQ B210 PARKING

Manual Rating

FROM ROUTE 0448 (MARSHALL ROAD)

TO PARKING




ROUTE 0957D: USPP PARKING B210

```
Manual Rating
```

FROM ROUTE 0448 (MARSHALL ROAD)

TO PARKING




Gateway National Recreation Area ROUTE 0958A: FORT WADSWORTH VISITOR CENTER PARKING

Manual Rating

FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)


TO ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)



Gateway National Recreation Area ROUTE 0958B: FT TOMPKINS PARKING

Manual Rating


ADJACENT TO ROUTE 0447 (TOMPKINS ROAD) ON LEFT



Gateway National Recreation Area ROUTE 0959A: TENNIS COURT PARKING

Manual Rating

FROM ROUTE 0444 (CLIFTON ROAD) ON LEFT




Gateway National Recreation Area ROUTE 0959B: FORT WADSWORTH BUILDING 109 PARKING

Manual Rating

FROM INTERSECTION OF ROUTE 0446 (BATTERY WEED ROAD) ROUTE 0445 (HUDSON ROAD / STATEN ISLAND) AND 0441 (MONT SEC AVENUE)

TO ROUTE 0442 (NORTH ROAD)




Gateway National Recreation Area

ROUTE 0960A: NAVY LODGE AREA PARKING

Manual Rating

FROM END OF ROUTE 0439 (PATH ROAD (NAVY LODGE))




Gateway National Recreation Area ROUTE 0960B: MCCLEAN ROAD PARKING

Manual Rating

FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)


TO ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)



Gateway National Recreation Area ROUTE 0960C: AYERS ROAD PARKING

Manual Rating


ADJACENT TO ROUTE 0438 (AYERS ROAD)



Gateway National Recreation Area ROUTE 0961A: ARMED FORCES RESERVE AREA PARKING

Manual Rating

FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)




Gateway National Recreation Area ROUTE 0961B: ARMED FORCES AREA B PARKING

Manual Rating

FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)

TO ROUTE 0471 (LOOP ROAD)




Gateway National Recreation Area ROUTE 0961C: ARMED FORCES AREA C PARKING

Manual Rating

FROM ROUTE 0471 (LOOP ROAD)

TO ROUTE 1015 (BUILDING 301 MAINTENANCE PARKING)




Gateway National Recreation Area ROUTE 0961D: FWR USPP SWAT PARKING

Manual Rating

FROM ROUTE 0440ZZ (NY AVENUE / BATTERY ROAD)

TO ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)




Gateway National Recreation Area ROUTE 0962A: FWR BALL FIELD PARKING

Manual Rating

FROM ROUTE 0453 (USS NORTH CAROLINA ROAD)


TO ROUTE 0446 (BATTERY WEED ROAD)



Gateway National Recreation Area ROUTE 0962B: FWR CAMPGROUND PARKING AREA

Manual Rating


ADJACENT TO ROUTE 0453 (USS NORTH CAROLINA ROAD)



Gateway National Recreation Area ROUTE 0963A: FWR BATTERY WEED AREA A PARKING

Manual Rating


ADJACENT TO ROUTE 0446 (BATTERY WEED ROAD)



Gateway National Recreation Area ROUTE 0963C: FWR BATTERY WEED AREA C PARKING

Manual Rating


ADJACENT TO ROUTE 0446 (BATTERY WEED ROAD) ON RIGHT



Gateway National Recreation Area ROUTE 0963D: FWR BATTERY WEED AREA D PARKING

Manual Rating

ADJACENT TO ROUTE 0446 (BATTERY WEED ROAD) ON LEFT



Gateway National Recreation Area ROUTE 0964ZZ: ENTRANCE AREA PARKING


Summary Route Manual Rating


FROM ROUTE 0464 (AVIATION ROAD) LEFT AND RIGHT

TO ROUTE 0464 (AVIATION ROAD)

Inspection Date	FMSS Number	User Access	Surface Type		
3/3/2021	36138	PUBLIC	ASPHALT		
Area (Sq. Ft.)	Lane Miles (11' Widths)	Condition Rating / PCR			
33,806	0.582	SUMMARY / 71			
Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60)	Fair (61- 84) Good ((85 - 94) Excellent (95 - 10	0) Not Rated		
See Appendix for definitions and formulas					

The condition shown on this page reflects the overall route condition and may not reflect individual subcomponent ratings.






Gateway National Recreation Area ROUTE 0964AAZ: ENTRANCE AREA PARKING A

Subcomponent of Route GATE-0964ZZ Manual Rating

FROM ROUTE 0464 (AVIATION ROAD) ON RIGHT

TO ROUTE 0464 (AVIATION ROAD) ON RIGHT




Gateway National Recreation Area ROUTE 0964ABZ: ENTRANCE AREA PARKING B

Subcomponent of Route GATE-0964ZZ Manual Rating

FROM ROUTE 0464 (AVIATION ROAD) ON LEFT


TO ROUTE 0464 (AVIATION ROAD) ON LEFT



Gateway National Recreation Area ROUTE 0964B: SEWAGE TREATMENT PARKING IN JAMAICA BAY

Manual Rating

FROM ROUTE 0464 (AVIATION ROAD) ON RIGHT




Gateway National Recreation Area ROUTE 0965A: COMMUNITY GARDENS PARKING

Manual Rating

FROM ROUTE 0965B (RYAN VISITOR CENTER PARKING SE)

TO ROUTE 0402 (COMMUNITY GARDEN ACCESS ROAD)




Gateway National Recreation Area ROUTE 0965B: RYAN VISITOR CENTER PARKING SE

Manual Rating

FROM ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))

TO ROUTE 0965A (COMMUNITY GARDENS PARKING) AND ROUTE 0965D (RYAN VISITOR CENTER PARKING)




Gateway National Recreation Area ROUTE 0965C: AVIATOR CONCESSION PARKING

Manual Rating

FROM ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))

TO ROUTE 0965D (RYAN VISITOR CENTER PARKING) AND ROUTE 0965F (RYAN CENTER EMPLOYEE PARKING)




Gateway National Recreation Area ROUTE 0965D: RYAN VISITOR CENTER PARKING

Manual Rating

FROM ROUTE 0965B (RYAN VISITOR CENTER PARKING SE) AND ROUTE 0965C (AVIATOR CONCESSION PARKING)

TO ROUTE 5006N (FLATBUSH AVENUE (NORTHBOUND))



Gateway National Recreation Area

ROUTE 0965E: HANGAR 3 AND 4 PARKING AREA

Manual Rating

FROM ROUTE 0965A (COMMUNITY GARDENS PARKING)




Gateway National Recreation Area ROUTE 0965F: RYAN CENTER EMPLOYEE PARKING

Manual Rating

FROM ROUTE 0965C (AVIATOR CONCESSION PARKING)

TO ROUTE 0965B (RYAN VISITOR CENTER PARKING SE)




Gateway National Recreation Area ROUTE 0966: MODEL AIRPLANE FIELD PARKING

Manual Rating

FROM ROUTE 0403 (RUNWAY C)

TO ROUTE 0403 (RUNWAY C)




Gateway National Recreation Area ROUTE 0967: CAR TOP BOAT RAMP AND FISHING AREA PARKING

Manual Rating

FROM ROUTE 0405 (TAXIWAY B)

TO ROUTE 0405 (TAXIWAY B) AND ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)



Gateway National Recreation Area

ROUTE 0968AZZ: BUILDING 69 PARKING AREA AND USPP NORTH AND SOUTH PARKING AREAS

Summary Route Manual Rating


FROM ROUTE 0201 (RANGER ROAD)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type		
3/3/2021	31606	PUBLIC	ASPHALT		
Area (Sq. Ft.)	Lane Miles (11' Widths)	Condition Rating / PCR			
18,731	0.323	SUMMARY / 49			
Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60)	Fair (61- 84) Good (Excellent (95 - 10	0) Not Rated		
See Appendix for definitions and formulas					

The condition shown on this page reflects the overall route condition and may not reflect individual subcomponent ratings.






Gateway National Recreation Area ROUTE 0968ABZ: USPP PARKING NORTH

Subcomponent of Route GATE-0968AZZ Manual Rating


FROM ROUTE 0201 (RANGER ROAD)



Gateway National Recreation Area ROUTE 0968ACZ: USPP PARKING SOUTH

Subcomponent of Route GATE-0968AZZ Manual Rating


FROM ROUTE 0201 (RANGER ROAD)



Gateway National Recreation Area ROUTE 0968B: NPS HEADQUARTERS (BUILDING 69 NORTH) AREA PARKING

Manual Rating


ADJACENT TO ROUTE 0201 (RANGER ROAD)



Gateway National Recreation Area ROUTE 0968C: NPS ECOLOGY VILLAGE PARKING

Manual Rating

FROM ROUTE 0201 (RANGER ROAD)



Gateway National Recreation Area ROUTE 0968EZZ: NPS ENTERPRISE ROAD PARKINGS


Summary Route Manual Rating

ADJACENT TO ROUTE 0203 (ENTERPRISE AVENUE) ON LEFT

Inspection Date	FMSS Number	User Access	Surface Type		
3/3/2021	36374	PUBLIC	ASPHALT		
Area (Sq. Ft.)	Lane Miles (11' Widths)	Condition Rating / PCR			
10,556	0.182	SUMMARY / 77			
Route Condition Legend – Pavement Condition Rating (PCR)					
Poor (0 - 60)	Fair (61- 84) Good ((85 - 94) Excellent (95 - 10	0) Not Rated		
See Appendix for definitions and formulas					

The condition shown on this page reflects the overall route condition and may not reflect individual subcomponent ratings.


Rte. 0968EZZ (3 Subcomponents)



Gateway National Recreation Area ROUTE 0968EAZ: NPS ENTERPRISE ROAD PARKING A

Subcomponent of Route GATE-0968EZZ Manual Rating


ADJACENT TO ROUTE 0203 (ENTERPRISE AVENUE) ON LEFT



Gateway National Recreation Area ROUTE 0968EBZ: NPS ENTERPRISE ROAD PARKING B

Subcomponent of Route GATE-0968EZZ Manual Rating


ADJACENT TO ROUTE 0203 (ENTERPRISE AVENUE) ON LEFT



Gateway National Recreation Area ROUTE 0968ECZ: NPS ENTERPRISE ROAD PARKING C

Subcomponent of Route GATE-0968EZZ Manual Rating


ADJACENT TO ROUTE 0203 (ENTERPRISE AVENUE) ON LEFT



ROUTE 0968F: NPS BUILDING 62 AREA PARKING

Manual Rating

FROM ROUTE 0203 (ENTERPRISE AVENUE)




Gateway National Recreation Area ROUTE 0969: POLY TECH AND SOCCER FIELD PARKING

Manual Rating

FROM INTERSECTION OF ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD) AND ROUTE 0203 (ENTERPRISE AVENUE)


TO FLOYD BENNET FIELD



Gateway National Recreation Area ROUTE 0970: FISHING ACCESS PARKING

Manual Rating


FROM END OF ROUTE 0201 (RANGER ROAD)



Gateway National Recreation Area ROUTE 0971: TYLUNAS HALL PARKING (NYC COLLECTION)

Manual Rating

FROM ROUTE 1042AZ (JABA PARKING A)




ROUTE 0972A: BUILDING 98 PARKING

Manual Rating

FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD) AT MP 0.07 ON LEFT

TO ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)




ROUTE 0972B: BUILDING 95 PARKING

Manual Rating

FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD) AT MP 0.04 ON LEFT


TO ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)



Gateway National Recreation Area ROUTE 0974: FT. TILDEN FISHERMEN'S PARKING

Manual Rating


FROM ROUTE 0111 (SHORE ROAD)



Gateway National Recreation Area ROUTE 0975: AREA D BEACH CENTER PARKING

Manual Rating

FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 2.04




ROUTE 0976A: THEATER PARKING A

Manual Rating

FROM ROUTE 0214 (HAHN ROAD)


TO ROUTE 0228 (THEATER ROAD)



ROUTE 0976B: RAA T-7 PARKING B

```
Manual Rating
```


ADJACENT TO ROUTE 0214 (HAHN ROAD)



Gateway National Recreation Area ROUTE 0978: BALL FIELD PARKING

Manual Rating

ADJACENT TO ROUTE 0216 (HERO ROAD)




ROUTE 0979: BAY 17/18 PARKING AREA

Manual Rating

FROM ROUTE 0110 (DAVIS ROAD)


TO ROUTE 0110 (DAVIS ROAD) AND 0216 (HERO ROAD)



ROUTE 0980: DAVIS ACCESS ROAD PARKING

Manual Rating


ADJACENT TO ROUTE 0475 (DAVIS ACCESS ROAD)



ROUTE 0981: QTS. 22/23 RESIDENCE ACCESS PARKING

Manual Rating


FROM ROUTE 0110 (DAVIS ROAD)



ROUTE 0982A: PICNIC PARKING A

Manual Rating

FROM ROUTE 0110 (DAVIS ROAD)




ROUTE 0982B: PICNIC PARKING B

Manual Rating

FROM ROUTE 0110 (DAVIS ROAD)

TO ROUTE 0110 (DAVIS ROAD)




Gateway National Recreation Area ROUTE 0983A: BUILDING 1 PARKING AREA A

Manual Rating

FROM ROUTE 0214 (HAHN ROAD)

TO ROUTE 0983B (BUILDING 1 SOUTHSIDE PARKING AREA B)




Gateway National Recreation Area ROUTE 0983B: BUILDING 1 SOUTHSIDE PARKING AREA B

Manual Rating

FROM ROUTE 0110 (DAVIS ROAD)

TO ROUTE 0983A (BUILDING 1 PARKING AREA A)




Gateway National Recreation Area ROUTE 0983C: BUILDING 1 NORTHSIDE PARKING AREA C

Manual Rating

FROM INTERSECTION OF ROUTE 0214 (HAHN ROAD) AND ROUTE 0212 (HEINZELMAN ROAD)


TO ROUTE 0214 (HAHN ROAD)



Gateway National Recreation Area ROUTE 0983D: BUILDING 1 PARKING NORTH

Manual Rating

ADJACENT TO ROUTE 0214 (HAHN ROAD)




ROUTE 0984A: BUILDING 149 PARKING AREA

Manual Rating

FROM ROUTE 0212 (HEINZELMAN ROAD)


TO ROUTE 0212 (HEINZELMAN ROAD)



Gateway National Recreation Area ROUTE 0984B: COMMUNITY GARDEN AREA PARKING B

Manual Rating


ADJACENT TO ROUTE 0213 (WORCESTER ROAD)



ROUTE 0986: POST OFFICE PARKING

Manual Rating


ADJACENT TO ROUTE 0225 (POST OFFICE ROAD)



Gateway National Recreation Area ROUTE 0987: MAINTENANCE AREA PARKING (RIIS LDG)

Manual Rating

FROM ROUTE 5000 (ROCKAWAY POINT BOULEVARD)




Gateway National Recreation Area ROUTE 0988: RIIS PARK BAY 3 EAST PARKING

Manual Rating

FROM ROUTE 5003 (ROCKAWAY BEACH BOULEVARD)


TO BOARDWALK ACCESS ROAD



Gateway National Recreation Area ROUTE 0989: CANARSIE PIER PARKING

Manual Rating


FROM ROUTE 5204 (CANARSIE PIER)



Gateway National Recreation Area ROUTE 0990: WILDLIFE REFUGE VISITOR PARKING

Manual Rating


FROM ROUTE 5005S (CROSS BAY BOULEVARD (SOUTHBOUND))



Gateway National Recreation Area ROUTE 0991A: NORTH CHANNEL BRIDGE PARKING / EASTSIDE

Manual Rating


FROM ROUTE 5005N (CROSS BAY BOULEVARD (NORTHBOUND))



Gateway National Recreation Area ROUTE 0991B: NORTH CHANNEL BRIDGE PARKING / WESTSIDE

Manual Rating


FROM ROUTE 5005S (CROSS BAY BOULEVARD (SOUTHBOUND))



ROUTE 0993: PARKING LOT E

Manual Rating


FROM ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) AT MP 2.35



Gateway National Recreation Area ROUTE 0994: GREAT KILLS EDUCATION CENTER PARKING

Manual Rating


FROM ROUTE 0232ZZ (BULKHEAD ROADS)



Gateway National Recreation Area ROUTE 0996: BREEZY POINT SURF CLUB PARKING

Manual Rating

FROM END OF ROUTE 0222 (BREEZY POINT SURF CLUB ENTRANCE ROAD)



Gateway National Recreation Area ROUTE 0999ZZ: SILVER GULL BEACH CLUB PARKING

Summary Route Manual Rating


FROM ROUTE 0234 (SILVER GULL BEACH CLUB ENTRANCE ROAD) RIGHT AND LEFT


TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type
3/3/2021	112205	PUBLIC	ASPHALT
Area (Sq. Ft.)	Lane Miles (11' Widths)	Condition Rating / PCR	
110,898	1.91	SUMMARY / 54	
Route Condition Legend – Pavement Condition Rating (PCR)			
Poor (0 - 60)	Fair (61- 84)Good ((85 - 94) Excellent (95 - 10	0) Not Rated
See Appendix for definitions and formulas			

The condition shown on this page reflects the overall route condition and may not reflect individual subcomponent ratings.








Gateway National Recreation Area ROUTE 0999AZ: SILVER GULL BEACH CLUB PARKING A

Subcomponent of Route GATE-0999ZZ Manual Rating


ADJACENT TO ROUTE 0234 (SILVER GULL BEACH CLUB ENTRANCE ROAD) ON LEFT



Gateway National Recreation Area ROUTE 0999BZ: SILVER GULL BEACH CLUB PARKING B

Subcomponent of Route GATE-0999ZZ Manual Rating


FROM ROUTE 0234 (SILVER GULL BEACH CLUB ENTRANCE ROAD) ON RIGHT



Gateway National Recreation Area ROUTE 0999CZ: SILVER GULL BEACH CLUB PARKING C

Subcomponent of Route GATE-0999ZZ Manual Rating


FROM ROUTE 0234 (SILVER GULL BEACH CLUB ENTRANCE ROAD) ON LEFT



Gateway National Recreation Area ROUTE 1002: HAMILTON BEACH PARKING

Manual Rating

FROM LOCKWOOD COURT




Gateway National Recreation Area ROUTE 1004: PICNIC/BEACH AREA PARKING LOT E

Manual Rating

FROM ROUTE 0130 (MILLER FIELD ENTRANCE ROAD)

TO ROUTE 0132A (VISITOR CENTER (SANCHEZ ROAD EAST))




Gateway National Recreation Area ROUTE 1011: MILLER FIELD AREA D PARKING LOT (FT. CAPODANO)

Manual Rating

FROM ROUTE 0132A (VISITOR CENTER (SANCHEZ ROAD EAST))


TO FATHER CAPODANNO BOULEVARD



Gateway National Recreation Area ROUTE 1012: GREAT KILLS MARINA PARKING

Manual Rating


FROM ROUTE 0030 (BUFFALO ROAD)



Gateway National Recreation Area ROUTE 1013: USPP STABLE PARKING

Manual Rating


FROM ROUTE 0458 (USS TENNESSEE ROAD)



Gateway National Recreation Area ROUTE 1014: BUILDING 302 L-SHAPED PARKING

Manual Rating


FROM ROUTE 0458 (USS TENNESSEE ROAD)



Gateway National Recreation Area ROUTE 1015: BUILDING 301 MAINTENANCE PARKING

Manual Rating

FROM ROUTE 0458 (USS TENNESSEE ROAD)



Gateway National Recreation Area ROUTE 1016ZZ: RIIS LANDING PARKING AREAS

Summary Route Manual Rating


FROM ROUTE 5000 (ROCKAWAY POINT BOULEVARD) AND ROUTE 0987 (MAINTENANCE AREA PARKING (RIIS LDG))

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type				
3/3/2021	238264	NONPUBLIC	ASPHALT				
Area (Sq. Ft.)	Lane Miles (11' Widths)	Condition R	ating / PCR				
88,943	1.532	SUMMARY / 53					
	Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60)	Fair (61- 84) Good ((85 - 94) Excellent (95 - 10	0) Not Rated				
See Appendix for definitions and formulas							

The condition shown on this page reflects the overall route condition and may not reflect individual subcomponent ratings.


Rte. 1016ZZ (2 Subcomponents)



Gateway National Recreation Area ROUTE 1016AZ: RIIS LANDING PARKING A

Subcomponent of Route GATE-1016ZZ Manual Rating


FROM ROUTE 0987 (MAINTENANCE AREA PARKING (RIIS LDG))



Gateway National Recreation Area ROUTE 1016BZ: RIIS LANDING PARKING B

Subcomponent of Route GATE-1016ZZ Manual Rating

FROM ROUTE 5000 (ROCKAWAY POINT BOULEVARD)




Gateway National Recreation Area ROUTE 1017: BREEZY POINT SURF CLUB ENTRANCE PARKING

Manual Rating

FROM ROUTE 0222 (BREEZY POINT SURF CLUB ENTRANCE ROAD)


TO ROUTE 0222 (BREEZY POINT SURF CLUB ENTRANCE ROAD)



Gateway National Recreation Area ROUTE 1020: NYPD PARKING 1

Manual Rating

FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)




Gateway National Recreation Area ROUTE 1021: NYPD PARKING 2

Manual Rating

FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)

TO ROUTE 1020 (NYPD PARKING 1) AND ROUTE 1022 (NYPD PARKING 3)




Gateway National Recreation Area ROUTE 1022: NYPD PARKING 3

Manual Rating

FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)

TO ROUTE 1021 (NYPD PARKING 2)




Gateway National Recreation Area ROUTE 1023: NYPD PARKING 4

Manual Rating

FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)

TO ROUTE 1024 (NYPD PARKING 5)




Gateway National Recreation Area ROUTE 1024: NYPD PARKING 5

Manual Rating

FROM ROUTE 1023 (NYPD PARKING 4)


TO ROUTE 1023 (NYPD PARKING 4)



Gateway National Recreation Area ROUTE 1025: PENNSYLVANIA AVENUE LANDFILL PARKING

Manual Rating

FROM ROUTE 0062 (PENNSYLVANIA AVENUE LANDFILL ACCESS ROADS)




Gateway National Recreation Area

ROUTE 1026: FOUNTAIN AVENUE LANDFILL

Manual Rating

FROM ROUTE 0063 (NS FOUNTAIN AVENUE LANDFILL ACCESS ROADS)




Gateway National Recreation Area ROUTE 1027: AVIATOR SPORTS PAVED PARKING

Manual Rating

FROM ROUTE 5006N (FLATBUSH AVENUE (NORTHBOUND))


TO ROUTE 0965C (AVIATOR CONCESSION PARKING)



Gateway National Recreation Area ROUTE 1028: NC-S RIDING ACADEMY PARKING LOT

Manual Rating


FROM ROUTE 0205 (RIDING ACADEMY ACCESS ROAD)



Gateway National Recreation Area ROUTE 1035: BEACH 222ND STREET PARKING

Manual Rating


FROM ROUTE 0222 (BREEZY POINT SURF CLUB ENTRANCE ROAD)



Gateway National Recreation Area ROUTE 1036: PARKING LOT M

Manual Rating

FROM ROUTE 0667 (NORTH BRAGG DRIVE - UNPAVED SEGMENT)




Gateway National Recreation Area ROUTE 1037: NOAA SERVICE PARKING LOT

Manual Rating

FROM ROUTE 0918A (NOAA LAB A PARKING SOUTH)

TO ROUTE 0918B (NOAA LAB B PARKING NORTH)



Gateway National Recreation Area

ROUTE 1042ZZ: JABA PARKING


Summary Route Manual Rating


FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)

TO PARKING

Inspection Date	FMSS Number	User Access	Surface Type				
3/3/2021	256345	NONPUBLIC	ASPHALT				
Area (Sq. Ft.)	Lane Miles (11' Widths)	Condition R	ating / PCR				
482,849	8.313	SUMMARY / 61					
	Route Condition Legend – Pavement Condition Rating (PCR)						
Poor (0 - 60)	Fair (61- 84) Good ((85 - 94) Excellent (95 - 10	0) Not Rated				
See Appendix for definitions and formulas							

The condition shown on this page reflects the overall route condition and may not reflect individual subcomponent ratings.






Gateway National Recreation Area ROUTE 1042AZ: JABA PARKING A

Subcomponent of Route GATE-1042ZZ Manual Rating

FROM ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)


TO ROUTE 1042BZ (JABA PARKING B)



Gateway National Recreation Area ROUTE 1042BZ: JABA PARKING B

Subcomponent of Route GATE-1042ZZ Manual Rating

FROM ROUTE 1042AZ (JABA PARKING A)



Section 7 Road Milepost Information



Gateway National Recreation Area



Road Milepost Information

This report section contains road milepost information for all paved roads in the park that were collected with the Data Collection Vehicle (DCV). The milepost data is obtained from the DCV by using a distance measuring instrument (DMI) that is calibrated to record mileage to the nearest thousandth of a mile. Park roads that were manually rated did not have milepost data collected, and thus are not included in this report section.

For Cycle 6, the information presented in this section differs from previous RIP cycles in that it does not contain the roadside features inventories for the paved park roads. Some examples of the features previously collected are signs, culverts/drop inlets, guardrails, curbing, pullouts, etc. If the park was collected in a previous RIP cycle, then the latest features data can be obtained by referencing the following:

Where to find the latest Features Inventories for NPS Parks:

- For Small Parks (parks with less than 10 miles of paved roads):
 - Refer to Cycle 5 data (collected 2010 2014)
 - Features were reported in Section 9 of the *Cycle 5* RIP report
 - Video of features can be viewed using the *PathViewVO* program and *Cycle 5* data
- For Large Parks (parks with more than 10 miles of paved roads):
 - Refer to Cycle 4 data (collected 2006 2009)
 - Features were reported in Section 9 of the *Cycle 4* RIP report
 - Video of features can be viewed using the *VisiData* program and *Cycle 4* data
 - Note: Features inventories were updated in Large Parks in *Cycle 5* only on a route by route basis if the route was new or modified in *Cycle 5*. If this is the case for a particular route, then features for the route can be obtained using the *PathViewVO* program and *Cycle 5* data (same as above for Small parks).

Milepost Events Verified in Cycle 6

In Cycle 6, the following events were collected and reported in Section 7 of this report:

- Intersections with roads and parking areas
- All bridges and culverts with BIP Numbers (bridge inspection program numbers)
- Mile Marker Signs
- One-Way travel directions
- Overpasses
- Tunnels
- Low Water Crossings (LWCR)
- Surface type changes
- Construction areas where no pavement condition data was obtained

GPS Mileage Matching

A consistent survey milepost and constant route length as recorded by the Data Collection Vehicle (DCV) is a challenge to maintain from one collection cycle to the next. The challenge is due to many factors such as driver characteristics, DMI calibration, tire pressure etc. After Cycle 4 (~2010), a decision was made to hold constant the length of roads so long as there was no physical change from reconstruction projects or realignments that would result in a change to the length of a road. Consequently, the "GPS Mileage Match" was implemented to specify which cycle the route length is being matched. Route mileages and GPS are matched to a previous collection whenever there is no physical change to a route alignment. The route mileage and GPS is not matched to previous cycles whenever it is determined that a road length and GPS needs to be updated. When this happens the GPS and length is updated to the cycle that displays the change, and that collection cycle is used as the matching cycle in subsequent collections of the road. Thus, the Cycle 6 GIS could be either the survey length collected in Cycle 4, Cycle 5, or Cycle 6 and therefore, may not match the survey milepost displayed in the latest Cycle 6 DCV video which is viewable in **PathView VO**.

The features inventories and road logs collected on NPS routes contain mileposts that are determined from the corresponding cycle that the GPS is matched to. Therefore, the mileposts contained in the Cycle 4 or 5 features inventories or the Cycle 6 road logs may not exactly match the survey milepost collected in the latest Cycle 6 video of the road.

Locating Mile Marker Signs

For routes that have mile marker signs along them, the milepost reported by RIP will most likely not line up exactly with the sign located in the field. This could be happening for many reasons, most likely due to either the error falling within the acceptable calibration range of the vehicle, or the level of accuracy that the mile marker signs were placed in the field.

Because mile marker signs are important features in many project plans and location descriptions, RIP is reporting locations of mile marker signs in three ways in Cycle 6:

- 1. Mileposts from Cycle 6 GIS: the official RIP milepost taken from the features inventories and the matching GPS/mileage cycle as described above. This is the milepost that should be used on project plans and when finding locations in the field
- 2. Mileposts from Cycle 6 Video: milepost shown to help locate the mile marker sign in the latest *PathView VO* video.
- 3. Latitude / Longitude: a constant way of locating a mile marker sign so long as the park has not moved the sign

The mileposts from Cycle 6 Video and GIS should be nearly the same, but on longer roads it has been observed that the Video milepost deviates more from the official GIS milepost that comes from the matching cycle.

ROUTE 0030: BUFFALO ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	PARK BOUNDARY	N/A	PAVED ROUTE (HYLAN BLVD / NON NPS)
0.00	0.00	INTERSECTION	L	ROUTE 0940AZ (GREAT KILLS ENTRANCE PARKING A)
0.00	0.00	INTERSECTION	R	ROUTE 0940BZ (GREAT KILLS ENTRANCE PARKING B)
0.53	0.53	INTERSECTION	R	ROUTE 0437 (ACCESS TO ATHLETIC FIELD ROAD)
0.53	0.53	INTERSECTION	L	ROUTE 0473 (HARBOR ROAD)
0.86	0.86	INTERSECTION	L	ROUTE 0942 (GK AREA "A" PARKING)
0.88	0.88	INTERSECTION	R	ROUTE 0941 (USPP/RANGER PARKING)
0.91	0.91	INTERSECTION	R	ROUTE 0941 (USPP/RANGER PARKING)
0.93	0.93	INTERSECTION	L	ROUTE 0942 (GK AREA "A" PARKING)
1.02	1.02	INTERSECTION	R	ROUTE 0232AZ (BULKHEAD ROAD)
1.16	1.16	INTERSECTION	R	ROUTE 0943 (BOAT LAUNCH PARKING)
1.32	1.32	INTERSECTION	R	ROUTE 0944 (GK AREA "E" PARKING)
1.43	1.43	INTERSECTION	R	ROUTE 0945 (GK AREA "F" PARKING)
1.52	1.52	INTERSECTION	R	ROUTE 0945 (GK AREA "F" PARKING)
1.53	1.53	INTERSECTION	R	UNPAVED PARKING
1.54	1.54	INTERSECTION	R	ROUTE 1012 (GREAT KILLS MARINA PARKING)
1.57	1.57	INTERSECTION	L	ROUTE 0947 (BEACH PICKUP AREA)
1.60	1.60	INTERSECTION	L	ROUTE 0947 (BEACH PICKUP AREA)
1.67	1.67	INTERSECTION	L	ROUTE 0946 (BEACH CENTER PARKING)
1.74	1.74	INTERSECTION	L	ROUTE 0946 (BEACH CENTER PARKING)
1.75	1.75	INTERSECTION	N/A	ROUTE 0492 (GREAT KILLS ACCESS TO BEACH (CROOKS POINT))

ROUTE 0060: HARTSHORNE DRIVE (NORTHBOUND)

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	PAVED ROUTE (OCEAN AVE STATE ROUTE 36 / NON NPS)
0.04	0.04	OVERPASS	N/A	N/A
0.18	0.18	OVERPASS	N/A	N/A

ROUTE 0060: HARTSHORNE DRIVE (NORTHBOUND)

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.21	0.21	INTERSECTION	L	ROUTE 0061 (HARTSHORNE DRIVE (SOUTHBOUND))
0.39	0.39	INTERSECTION	L	PAVED SPUR
0.41	0.41	INTERSECTION	L	PAVED SPUR
0.44	0.44	INTERSECTION	R	PAVED SPUR
0.47	0.47	INTERSECTION	R	ROUTE 0900 (ENTRANCE STATION PARKING A)
0.67	0.67	INTERSECTION	R	ROUTE 0938 (AREA B PARKING LOT B)
1.03	1.03	INTERSECTION	R	ROUTE 0938 (AREA B PARKING LOT B)
1.47	1.47	INTERSECTION	R	ROUTE 0939 (AREA C PARKING LOT C)
2.09	2.09	INTERSECTION	R	ROUTE 0975 (AREA D BEACH CENTER PARKING)
2.09	2.09	INTERSECTION	R	ROUTE 0975 (AREA D BEACH CENTER PARKING)
2.25	2.25	INTERSECTION	R	ROUTE 0905 (SANDY HOOK VISITOR CENTER PARKING)
2.39	2.39	INTERSECTION	R	ROUTE 0993 (PARKING LOT E)
2.48	2.48	INTERSECTION	L	PAVED SPUR
2.50	2.50	INTERSECTION	L	PAVED SPUR
2.51	2.51	INTERSECTION	R	ROUTE 0907 (RANGER STATION PARKING A EAST)
2.55	2.55	INTERSECTION	L	ROUTE 0908 (RANGER PARKING B NORTH)
2.75	2.75	INTERSECTION	L	ROUTE 0911 (MISSILE PARKING LOT)
2.76	2.76	INTERSECTION	L	PAVED SPUR
2.76	2.76	INTERSECTION	R	ROUTE 0481 (SOUTH MAINTENANCE SHOP ROAD A)
2.99	2.99	INTERSECTION	L	PAVED SPUR
2.99	2.99	INTERSECTION	R	ROUTE 0479 (FISHERMAN'S PARKING ACCESS)
3.72	3.72	INTERSECTION	L	PAVED SPUR
3.73	3.73	INTERSECTION	R	ROUTE 0160 (ATLANTIC DRIVE)
3.77	3.77	INTERSECTION	R	ROUTE 0913 (LOT "L" NIKE RADAR SITE PARKING)
3.78	3.78	INTERSECTION	L	ROUTE 0061 (HARTSHORNE DRIVE (SOUTHBOUND))
4.00	4.00	INTERSECTION	R	ROUTE 0914 (LOT "H" CAMPGROUND PARKING)
4.14	4.14	INTERSECTION	R	ROUTE 0462 (RANDOLPH ROAD)
4.53	4.53	INTERSECTION	R	ROUTE 0662AZ (MAGRUDER ROAD)
4.55	4.55	INTERSECTION	R	ROUTE 0662CZ (MAGRUDER ROAD SPUR 2)
4.67	4.67	INTERSECTION	R	ROUTE 0663 (PENNINGTON STREET)

Data Collected on 4/2021

ROUTE 0060: HARTSHORNE DRIVE (NORTHBOUND)

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
4.69	4.69	INTERSECTION	R	PAVED SPUR
4.74	4.74	INTERSECTION	R	ROUTE 0664 (KESSLER ROAD)
4.76	4.76	INTERSECTION	R	PAVED SPUR
5.00	5.00	INTERSECTION	R	ROUTE 0661AZ (HUDSON ROAD)
5.03	5.03	INTERSECTION	R	ROUTE 0661BZ (HUDSON ROAD SPUR)
5.22	5.22	INTERSECTION	L	UNPAVED ROUTE
5.22	5.22	INTERSECTION	R	ROUTE 0936 (FORT HANCOCK THEATER PARKING)
5.25	5.25	INTERSECTION	L	UNPAVED PARKING
5.26	5.26	INTERSECTION	L	PAVED ROUTE (US COAST GUARD ROAD / NON NPS)
5.26	5.26	INTERSECTION	R	ROUTE 0668 (SOUTH BRAGG DRIVE)
5.28	5.28	INTERSECTION	R	ROUTE 0665 (KEARNY DRIVE)
5.28	5.28	INTERSECTION	N/A	ROUTE 0665 (KEARNY DRIVE)

ROUTE 0061: HARTSHORNE DRIVE (SOUTHBOUND)

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5. **FROM** TO

MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.00	0.00	INTERSECTION	L	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.07	0.07	INTERSECTION	L	PAVED SPUR
0.80	0.80	INTERSECTION	L	PAVED SPUR
1.02	1.02	INTERSECTION	L	PAVED SPUR
1.24	1.24	INTERSECTION	L	ROUTE 0908 (RANGER PARKING B NORTH)
1.28	1.28	INTERSECTION	L	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
1.30	1.30	INTERSECTION	L	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
3.35	3.35	INTERSECTION	L	PAVED SPUR
3.35	3.35	INTERSECTION	L	PAVED SPUR
3.42	3.42	INTERSECTION	R	ROUTE 0933 (FEE COLLECTORS PARKING)
3.54	3.54	INTERSECTION	R	ROUTE 0934 (QUARTER 600 PARKING)
3.75	3.75	INTERSECTION	N/A	PAVED ROUTE (OCEAN AVE STATE ROUTE 36 / NON NPS)
3.75	3.75	INTERSECTION	L	PAVED ROUTE (OCEAN AVE STATE ROUTE 36 / NON NPS)
D (0 11	1 4/2021			

Data Collected on 4/2021

ROUTE 0063: NS FOUNTAIN AVENUE LANDFILL ACCESS ROADS

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPO	TO ST MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	PAVED ROAD (BELT PARKWAY / NON NPS)
0.00	0.00	INTERSECTION	R	PAVED ROAD (BELT PARKWAY / NON NPS)
0.18	0.18	INTERSECTION	N/A	ROUTE 1026 (FOUNTAIN AVENUE LANDFILL)

ROUTE 0110: DAVIS ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0216 (HERO ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0216 (HERO ROAD)
0.06	0.06	INTERSECTION	R	ROUTE 0979 (BAY 17/18 PARKING AREA)
0.13	0.13	INTERSECTION	R	ROUTE 0979 (BAY 17/18 PARKING AREA)
0.15	0.15	INTERSECTION	L	FIELD (GATED)
0.24	0.24	INTERSECTION	R	PAVED ROAD (Blocked)
0.28	0.28	INTERSECTION	R	ROUTE 0980 (DAVIS ACCESS ROAD PARKING)
0.28	0.28	INTERSECTION	R	ROUTE 0475 (DAVIS ACCESS ROAD)
0.31	0.31	INTERSECTION	L	ROUTE 0981 (QTS. 22/23 RESIDENCE ACCESS PARKING)
0.34	0.34	INTERSECTION	L	ROUTE 0982A (PICNIC PARKING A)
0.34	0.34	INTERSECTION	R	ROUTE 0982B (PICNIC PARKING B)
0.39	0.39	INTERSECTION	L	ROUTE 0983B (BUILDING 1 SOUTHSIDE PARKING AREA B)
0.41	0.41	INTERSECTION	R	ROUTE 0982B (PICNIC PARKING B)
0.42	0.42	INTERSECTION	R	ROUTE 0214 (HAHN ROAD)
0.42	0.42	INTERSECTION	L	ROUTE 0214 (HAHN ROAD)
0.50	0.50	INTERSECTION	L	ROUTE 0211 (SOUTH BARRETT ROAD)
0.50	0.50	INTERSECTION	R	ROUTE 0211 (SOUTH BARRETT ROAD)

ROUTE 0111: SHORE ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	SAND ROAD
0.10	0.10	INTERSECTION	R	BEACH ACCESS RAMP
0.15	0.15	INTERSECTION	R	BEACH ACCESS RAMP
0.20	0.20	INTERSECTION	R	BEACH ACCESS RAMP
0.26	0.26	INTERSECTION	L	ROUTE 0216 (HERO ROAD)
0.26	0.26	INTERSECTION	N/A	ROUTE 0979 (BAY 17/18 PARKING AREA)

ROUTE 0130: MILLER FIELD ENTRANCE ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	PAVED ROUTE (NEW DORP ROAD / NON NPS)
0.00	0.00	INTERSECTION	R	PAVED ROUTE (NEW DORP ROAD / NON NPS)
0.00	0.00	PARK BOUNDARY	N/A	PAVED ROUTE (CEDAR GROVE AVE / NON NPS)
0.09	0.09	INTERSECTION	L	ROUTE 0948 (MILLER FIELD PARKING LOT (BALL FIELD))
0.12	0.12	INTERSECTION	R	UNPAVED CONSTRUCTION AREA
0.16	0.16	INTERSECTION	L	ROUTE 0948 (MILLER FIELD PARKING LOT (BALL FIELD))
0.26	0.26	CULVERT	N/A	N/A
0.32	0.32	INTERSECTION	L	ROUTE 1004 (PICNIC/BEACH AREA PARKING LOT E)
0.38	0.38	INTERSECTION	N/A	ROUTE 0132A (VISITOR CENTER (SANCHEZ ROAD EAST))

ROUTE 0132A: VISITOR CENTER (SANCHEZ ROAD EAST)

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM	ТО			
MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0130 (MILLER FIELD ENTRANCE ROAD)
0.04	0.04	INTERSECTION	R	ROUTE 1011 (MILLER FIELD AREA D PARKING LOT (FT. CAPODANO))
0.04	0.04	INTERSECTION	L	ROUTE 1004 (PICNIC/BEACH AREA PARKING LOT E)
0.16	0.16	INTERSECTION	L	ROUTE 0949 (RANGER STATION PARKING)
0.20	0.20	INTERSECTION	N/A	ROUTE 0951 (CIRCLE PARKING)

ROUTE 0132B: HOUSING ACCESS (SANCHEZ ROAD WEST)

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0951 (CIRCLE PARKING)
0.13	0.13	INTERSECTION	R	ROUTE 0474AZ (MILLER FIELD RESIDENCE ROAD A)
0.15	0.15	INTERSECTION	R	ROUTE 0474AZ (MILLER FIELD RESIDENCE ROAD A)
0.17	0.17	INTERSECTION	R	ROUTE 0474CZ (MILLER FIELD RESIDENCE ROAD C)
0.21	0.21	INTERSECTION	R	ROUTE 0952 (RESIDENCE PARKING)
0.27	0.27	INTERSECTION	N/A	ROUTE 0953A (NEW DORP HIGH SCHOOL PARKING A)

ROUTE 0160: ATLANTIC DRIVE

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0672 (FORD ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0668 (SOUTH BRAGG DRIVE)
0.00	0.00	INTERSECTION	L	ROUTE 0667 (NORTH BRAGG DRIVE)
0.01	0.01	INTERSECTION	L	ROUTE 1031 (DR PARKING J NORTH BEACH EXTENSION)
0.18	0.18	INTERSECTION	L	ROUTE 0930 (NORTH BEACH PARKING)
0.27	0.27	INTERSECTION	L	ROUTE 0930 (NORTH BEACH PARKING)
0.64	0.64	INTERSECTION	R	ROUTE 0671 (NEW GUNNISON ROAD)
0.69	0.69	INTERSECTION	L	ROUTE 0931 (EMPLOYEE PULLOUT GUNNISON PARKING)
0.79	0.79	INTERSECTION	L	ROUTE 0935 (SEWAGE PLANT PARKING)
0.81	0.81	INTERSECTION	L	ROUTE 0935 (SEWAGE PLANT PARKING)
0.82	0.82	INTERSECTION	L	ROUTE 0160 (ATLANTIC DRIVE) OPPOSITE LANE
0.90	0.90	INTERSECTION	L	ROUTE 0160 (ATLANTIC DRIVE) OPPOSITE LANE
1.40	1.40	INTERSECTION	L	UNPAVED ROUTE
1.91	1.91	INTERSECTION	L	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
1.91	1.91	INTERSECTION	R	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))

ROUTE 0161: HARTSHORNE DRIVE (SOUTHBOUND) RAMP K

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.10	0.10	OVERPASS	N/A	HARTSHORNE DRIVE (SOUTHBOUND) RAMP L
0.29	0.29	INTERSECTION	L	PAVED ROUTE (OCEAN AVE STATE ROUTE 36 / NON-NPS)

ROUTE 0162: HARTSHORNE DRIVE (SOUTHBOUND) RAMP L

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO F MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	PAVED ROUTE (OCEAN AVE STATE ROUTE 36 / NON-NPS)
0.18	0.18	INTERSECTION	N/A	PAVED ROUTE (OCEAN AVE STATE ROUTE 36 / NON-NPS)

ROUTE 0163AZ: RANGE ROAD

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	SAND / BEACH ACCES
0.01	0.01	INTERSECTION	L	ROUTE 0974 (FT. TILDEN FISHERMEN'S PARKING)
0.02	0.02	INTERSECTION	L	ROUTE 0974 (FT. TILDEN FISHERMEN'S PARKING)
0.10	0.10	INTERSECTION	R	ROUTE 0163BZ (BPD RANGE ROAD)
0.21	0.21	INTERSECTION	R	ROUTE 0214 (HAHN ROAD)
0.21	0.21	INTERSECTION	L	ROUTE 0214 (HAHN ROAD)

ROUTE 0200: FLOYD BENNETT FIELD ENTRANCE ROAD

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 5006N (FLATBUSH AVENUE (NORTHBOUND))
0.00	0.00	INTERSECTION	L	ROUTE 5006N (FLATBUSH AVENUE (NORTHBOUND))
0.12	0.12	INTERSECTION	L	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD) CUT-THRU
0.18	0.18	INTERSECTION	L	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD) CUT-THRU
0.18	0.18	INTERSECTION	R	ROUTE 0464 (AVIATION ROAD)
0.27	0.27	INTERSECTION	L	ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))
0.36	0.36	INTERSECTION	L	ROUTE 0201 (RANGER ROAD)
0.37	0.37	INTERSECTION	R	PAVED PARKING (ARMED FORCES RESERVE CENTER / NON NPS)
0.42	0.42	INTERSECTION	L	PAVED ROUTE
0.42	0.42	INTERSECTION	R	PAVED ROUTE (LOOPING ROAD / NON NPS)
0.46	0.46	INTERSECTION	R	PAVED ROUTE (LOOPING ROAD / NON NPS)
0.53	0.53	INTERSECTION	L	ROUTE 0203 (ENTERPRISE AVENUE)
0.53	0.53	INTERSECTION	R	ROUTE 0969 (POLY TECH AND SOCCER FIELD PARKING)
0.61	0.61	INTERSECTION	R	ROUTE 0465 (BUILDING 272 ACCESS ROAD)
0.67	0.67	INTERSECTION	R	PAVED PARKING
0.75	0.75	INTERSECTION	R	ROUTE 0201 (RANGER ROAD)
0.76	0.76	INTERSECTION	L	ROUTE 0201 (RANGER ROAD)
0.91	0.91	INTERSECTION	R	ROUTE 0504BZ (SOUTHERN RUNWAY B)
1.03	1.03	INTERSECTION	L	ROUTE 0498 (NYPD ROAD 2)
1.08	1.08	INTERSECTION	L	ROUTE 1020 (NYPD PARKING 1)
1.10	1.10	INTERSECTION	L	ROUTE 1021 (NYPD PARKING 2)
1.13	1.13	INTERSECTION	L	ROUTE 1022 (NYPD PARKING 3)
1.13	1.13	INTERSECTION	R	ROUTE 1023 (NYPD PARKING 4)
1.15	1.15	INTERSECTION	L	ROUTE 0972B (BUILDING 95 PARKING)
1.17	1.17	INTERSECTION	L	ROUTE 0972B (BUILDING 95 PARKING)
1.17	1.17	INTERSECTION	R	ROUTE 0971 (TYLUNAS HALL PARKING (NYC COLLECTION))
1.21	1.21	INTERSECTION	L	ROUTE 0972A (BUILDING 98 PARKING)
1.30	1.30	INTERSECTION	L	ROUTE 0972A (BUILDING 98 PARKING)

ROUTE 0201: RANGER ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.00	0.00	INTERSECTION	L	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.03	0.03	INTERSECTION	R	ROUTE 0968ACZ (USPP PARKING SOUTH)
0.07	0.07	INTERSECTION	R	ROUTE 0968ABZ (USPP PARKING NORTH)
0.10	0.10	INTERSECTION	L	ROUTE 0206 (TAXIWAY C ACCESS ROAD)
0.16	0.16	INTERSECTION	L	ROUTE 0968B (NPS HEADQUARTERS (BUILDING 69 NORTH) AREA PARKING)
0.19	0.19	INTERSECTION	L	ROUTE 0968C (NPS ECOLOGY VILLAGE PARKING)
0.20	0.20	INTERSECTION	R	PAVED ROAD
0.26	0.26	INTERSECTION	R	PAVED PARKING
0.29	0.29	INTERSECTION	R	ROUTE 0203 (ENTERPRISE AVENUE)
0.40	0.40	INTERSECTION	L	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.40	0.40	INTERSECTION	R	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.45	0.45	INTERSECTION	L	ROUTE 1038 (ARCHERY PARKING)
0.49	0.49	INTERSECTION	R	PAVED PARKING
0.56	0.56	INTERSECTION	R	ROUTE 0465 (BUILDING 272 ACCESS ROAD)
0.56	0.56	INTERSECTION	N/A	ROUTE 0970 (FISHING ACCESS PARKING)

ROUTE 0203: ENTERPRISE AVENUE

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4. **FROM** TO

MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0969 (POLY TECH AND SOCCER FIELD PARKING)
0.00	0.00	INTERSECTION	R	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.00	0.00	INTERSECTION	L	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.03	0.03	INTERSECTION	L	ROUTE 0968EAZ (NPS ENTERPRISE ROAD PARKING A)
0.06	0.06	INTERSECTION	L	ROUTE 0968F (NPS BUILDING 62 AREA PARKING)
0.09	0.09	INTERSECTION	L	ROUTE 0968EBZ (NPS ENTERPRISE ROAD PARKING B)
0.11	0.11	INTERSECTION	R	ROUTE 0968ECZ (NPS ENTERPRISE ROAD PARKING C)
0.15	0.15	INTERSECTION	R	ROUTE 0201 (RANGER ROAD)
0.15	0.15	INTERSECTION	L	ROUTE 0201 (RANGER ROAD)

Data Collected on 4/2021

ROUTE 0206: TAXIWAY C ACCESS ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0201 (RANGER ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0201 (RANGER ROAD)
0.07	0.07	INTERSECTION	R	PAVED PARKING
0.10	0.10	INTERSECTION	L	ROUTE 0410 (TAXIWAY C)
0.10	0.10	INTERSECTION	R	ROUTE 0410 (TAXIWAY C)

ROUTE 0211: SOUTH BARRETT ROAD

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0215 (ATHLETIC DRIVE)
0.05	0.05	INTERSECTION	R	ROUTE 0213 (WORCESTER ROAD)
0.08	0.08	INTERSECTION	L	ROUTE 0212 (HEINZELMAN ROAD)
0.08	0.08	INTERSECTION	R	ROUTE 0212 (HEINZELMAN ROAD)
0.12	0.12	INTERSECTION	L	ROUTE 0227AZ (ROMERO ROAD WEST)
0.13	0.13	INTERSECTION	L	ROUTE 0227BZ (ROMERO ROAD EAST)
0.14	0.14	INTERSECTION	R	ROUTE 0110 (DAVIS ROAD)
0.15	0.15	INTERSECTION	L	ROUTE 0225 (POST OFFICE ROAD)
0.17	0.17	INTERSECTION	L	ROUTE 5411 (BEACH 169TH STREET)
0.17	0.17	INTERSECTION	R	ROUTE 5411 (BEACH 169TH STREET)

ROUTE 0212: HEINZELMAN ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0983C (BUILDING 1 NORTHSIDE PARKING AREA C)
0.00	0.00	INTERSECTION	R	ROUTE 0214 (HAHN ROAD)
0.00	0.00	INTERSECTION	L	ROUTE 0214 (HAHN ROAD)
0.01	0.01	INTERSECTION	L	ROUTE 0984A (BUILDING 149 PARKING AREA)
0.04	0.04	CULVERT	N/A	N/A
0.05	0.05	INTERSECTION	L	ROUTE 0984A (BUILDING 149 PARKING AREA)
0.08	0.08	INTERSECTION	L	ROUTE 0211 (SOUTH BARRETT ROAD)
0.08	0.08	INTERSECTION	R	ROUTE 0211 (SOUTH BARRETT ROAD)
0.10	0.10	INTERSECTION	R	ROUTE 0226 (NORTH BARETTE)
0.12	0.12	INTERSECTION	R	ROUTE 5000 (ROCKAWAY POINT BOULEVARD)
0.12	0.12	INTERSECTION	L	ROUTE 5000 (ROCKAWAY POINT BOULEVARD)

ROUTE 0213: WORCESTER ROAD

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0211 (SOUTH BARRETT ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0211 (SOUTH BARRETT ROAD)
0.02	0.02	INTERSECTION	R	ROUTE 0230 (STEELE ROAD)
0.06	0.06	INTERSECTION	L	ROUTE 0984B (COMMUNITY GARDEN AREA PARKING B)
0.08	0.08	INTERSECTION	R	ROUTE 0214 (HAHN ROAD)
0.08	0.08	INTERSECTION	L	ROUTE 0214 (HAHN ROAD)

ROUTE 0214: HAHN ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 5411 (BEACH 169TH STREET)
0.00	0.00	INTERSECTION	L	ROUTE 5411 (BEACH 169TH STREET)
0.02	0.02	INTERSECTION	R	ROUTE 0110 (DAVIS ROAD)
0.02	0.02	INTERSECTION	L	ROUTE 0110 (DAVIS ROAD)
0.04	0.04	INTERSECTION	R	ROUTE 0983D (BUILDING 1 PARKING NORTH)
0.06	0.06	INTERSECTION	L	ROUTE 0983A (BUILDING 1 PARKING AREA A)
0.08	0.08	INTERSECTION	L	ROUTE 0983C (BUILDING 1 NORTHSIDE PARKING AREA C)
0.09	0.09	INTERSECTION	L	ROUTE 0983C (BUILDING 1 NORTHSIDE PARKING AREA C)
0.10	0.10	INTERSECTION	R	ROUTE 0212 (HEINZELMAN ROAD)
0.13	0.13	INTERSECTION	R	ROUTE 0213 (WORCESTER ROAD)
0.14	0.14	INTERSECTION	L	ROUTE 0229 (CHAPEL ROAD)
0.18	0.18	INTERSECTION	R	ROUTE 0215 (ATHLETIC DRIVE)
0.18	0.18	INTERSECTION	L	ROUTE 0228 (THEATER ROAD)
0.20	0.20	INTERSECTION	L	ROUTE 0976A (THEATER PARKING A)
0.24	0.24	INTERSECTION	L	ROUTE 0976A (THEATER PARKING A)
0.27	0.27	INTERSECTION	L	ROUTE 0976B (RAA T-7 PARKING B)
0.29	0.29	INTERSECTION	N/A	PAVED ROAD
0.29	0.29	INTERSECTION	L	ROUTE 0216 (HERO ROAD)
0.29	0.29	INTERSECTION	R	ROUTE 0216 (HERO ROAD)

ROUTE 0215: ATHLETIC DRIVE

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0215 (ATHLETIC DRIVE)
0.00	0.00	INTERSECTION	L	ROUTE 0211 (SOUTH BARRETT ROAD)
0.02	0.02	INTERSECTION	L	ROUTE 0230 (STEELE ROAD)
0.10	0.10	INTERSECTION	N/A	ROUTE 0228 (THEATER ROAD)
0.10	0.10	INTERSECTION	R	ROUTE 0214 (HAHN ROAD)
0.10	0.10	INTERSECTION	L	ROUTE 0214 (HAHN ROAD)

Data Collected on 4/2021

ROUTE 0216: HERO ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 5000 (ROCKAWAY POINT BOULEVARD)
0.00	0.00	INTERSECTION	L	ROUTE 5000 (ROCKAWAY POINT BOULEVARD)
0.05	0.05	INTERSECTION	R	PAVED ROAD (FORT TILDEN U.S. ARMY RESERVE / NON-NPS) (GATED)
0.11	0.11	INTERSECTION	R	ROUTE 0978 (BALL FIELD PARKING)
0.15	0.15	INTERSECTION	R	UNPAVED ROAD
0.15	0.15	INTERSECTION	L	ROUTE 0214 (HAHN ROAD)
0.22	0.22	INTERSECTION	L	ROUTE 0228 (THEATER ROAD)
0.33	0.33	INTERSECTION	L	ROUTE 0110 (DAVIS ROAD)
0.36	0.36	INTERSECTION	R	ROUTE 0111 (SHORE ROAD)
0.36	0.36	INTERSECTION	L	ROUTE 0979 (BAY 17/18 PARKING AREA)

ROUTE 0222: BREEZY POINT SURF CLUB ENTRANCE ROAD

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	PARK BOUNDARY	N/A	ROUTE 1035 (BEACH 222ND STREET PARKING)
0.00	0.00	INTERSECTION	N/A	ROUTE 5000 (ROCKAWAY POINT BOULEVARD)
0.01	0.01	INTERSECTION	R	PAVED PARKING
0.10	0.10	INTERSECTION	L	ROUTE 1017 (BREEZY POINT SURF CLUB ENTRANCE PARKING)
0.10	0.10	INTERSECTION	R	UNPAVED PARKING
0.13	0.13	INTERSECTION	L	ROUTE 1017 (BREEZY POINT SURF CLUB ENTRANCE PARKING)
0.13	0.13	INTERSECTION	R	UNPAVED PARKING
0.19	0.19	INTERSECTION	L	ROUTE 0997 (BREEZY POINT SURF CLUB UNPAVED PARKING)
0.29	0.29	INTERSECTION	L	UNPAVED PARKING
0.33	0.33	INTERSECTION	L	UNPAVED PARKING
0.38	0.38	INTERSECTION	N/A	ROUTE 0996 (BREEZY POINT SURF CLUB PARKING)
0.38	0.38	INTERSECTION	L	ROUTE 0996 (BREEZY POINT SURF CLUB PARKING)

ROUTE 0224: BEACH 193RD STREET

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 5000 (ROCKAWAY POINT BOULEVARD)
0.00	0.00	INTERSECTION	R	ROUTE 5000 (ROCKAWAY POINT BOULEVARD)
0.10	0.10	INTERSECTION	L	ROUTE 0224 (BEACH 193RD STREET) CUT-THRU
0.19	0.19	INTERSECTION	L	ROUTE 0163AZ (RANGE ROAD)
0.20	0.20	INTERSECTION	N/A	ROUTE 0234 (SILVER GULL BEACH CLUB ENTRANCE ROAD)

ROUTE 0228: THEATER ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0214 (HAHN ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0214 (HAHN ROAD)
0.00	0.00	INTERSECTION	N/A	ROUTE 0215 (ATHLETIC DRIVE)
0.05	0.05	INTERSECTION	R	ROUTE 0976A (THEATER PARKING A)
0.06	0.06	INTERSECTION	R	ROUTE 0976A (THEATER PARKING A)
0.07	0.07	INTERSECTION	R	ROUTE 0976A (THEATER PARKING A)
0.12	0.12	INTERSECTION	R	ROUTE 0976A (THEATER PARKING A)
0.15	0.15	INTERSECTION	R	ROUTE 0976A (THEATER PARKING A)
0.17	0.17	INTERSECTION	R	ROUTE 0976A (THEATER PARKING A)
0.19	0.19	INTERSECTION	L	ROUTE 0216 (HERO ROAD)
0.19	0.19	INTERSECTION	R	ROUTE 0216 (HERO ROAD)

ROUTE 0234: SILVER GULL BEACH CLUB ENTRANCE ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0224 (BEACH 193RD STREET)
0.06	0.06	INTERSECTION	L	ROUTE 0999AZ (SILVER GULL BEACH CLUB PARKING A)
0.10	0.10	INTERSECTION	R	ROUTE 0999BZ (SILVER GULL BEACH CLUB PARKING B)
0.14	0.14	INTERSECTION	L	ROUTE 0999CZ (SILVER GULL BEACH CLUB PARKING C)
0.19	0.19	INTERSECTION	N/A	ROUTE 0224 (BEACH 193RD STREET) OPPOSITE LANE

Data Collected on 4/2021

ROUTE 0235: ROCKAWAY POINT YACHT CLUB ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 5000 (ROCKAWAY POINT BOULEVARD)
0.00	0.00	INTERSECTION	L	ROUTE 5000 (ROCKAWAY POINT BOULEVARD)
0.26	0.26	INTERSECTION	N/A	ROUTE 1000 (ROCKAWAY POINT YACHT CLUB PARKING)

ROUTE 0403: RUNWAY C

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	RIVER
0.10	0.10	INTERSECTION	R	ROTUE 0966 (MODEL AIRPLANE FIELD PARKING)
0.19	0.19	INTERSECTION	L	ROUTE 0405 (TAXIWAY B)
0.20	0.20	INTERSECTION	L	ROTUE 0966 (MODEL AIRPLANE FIELD PARKING)
0.44	0.44	INTERSECTION	L	ROUTE 0500 (CENTRAL RUNWAY)
1.10	1.10	INTERSECTION	L	ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))
1.10	1.10	INTERSECTION	R	ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))

ROUTE 0405: TAXIWAY B

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0406 (TAXIWAY A)
0.00	0.00	INTERSECTION	L	ROUTE 0406 (TAXIWAY A)
0.08	0.08	INTERSECTION	R	ROUTE 0967 (CAR TOP BOAT RAMP AND FISHING AREA PARKING)
0.16	0.16	INTERSECTION	R	ROUTE 0967 (CAR TOP BOAT RAMP AND FISHING AREA PARKING)
0.50	0.50	INTERSECTION	R	ROUTE 0403 (RUNWAY C)
0.50	0.50	INTERSECTION	L	ROUTE 0403 (RUNWAY C)
0.50	0.50	INTERSECTION	N/A	ROTUE 0966 (MODEL AIRPLANE FIELD PARKING)

ROUTE 0406: TAXIWAY A

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOS	TO T MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))
0.00	0.00	INTERSECTION	L	ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))
0.24	0.24	INTERSECTION	R	ROUTE 0500 (CENTRAL RUNWAY)
0.25	0.25	INTERSECTION	L	ROUTE 0504AZ (SOUTHERN RUNWAY A)
0.26	0.26	INTERSECTION	R	ROUTE 0504BZ (SOUTHERN RUNWAY B)
0.26	0.26	INTERSECTION	L	ROUTE 0500 (CENTRAL RUNWAY)
0.67	0.67	INTERSECTION	L	ROUTE 0405 (TAXIWAY B)
0.69	0.69	INTERSECTION	N/A	ROUTE 0406 (TAXIWAY A)

ROUTE 0408: RUNWAY A (SOUTHERN RUNWAY)

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4. FROM то

MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.58	0.58	INTERSECTION	R	ROUTE 0406 (TAXIWAY A)
0.58	0.58	INTERSECTION	L	ROUTE 0965B (RYAN VISITOR CENTER PARKING SE)
0.81	0.81	INTERSECTION	L	ROUTE 0965C (AVIATOR CONCESSION PARKING)
1.09	1.09	INTERSECTION	N/A	DEAD END
1.09	1.09	INTERSECTION	R	ROUTE 0403 (RUNWAY C)

ROUTE 0410: TAXIWAY C

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))
0.00	0.00	INTERSECTION	R	ROUTE 0408 (RUNWAY A (SOUTHERN RUNWAY))
0.09	0.09	INTERSECTION	R	ROUTE 0206 (TAXIWAY C ACCESS ROAD)
0.35	0.35	INTERSECTION	N/A	DEAD END

ROUTE 0439: PATH ROAD (NAVY LODGE)

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0440BZ (BATTERY ROAD)
0.00	0.00	INTERSECTION	L	ROUTE 0440BZ (BATTERY ROAD)
0.01	0.01	INTERSECTION	L	PAVED PARKING (NON NPS)
0.09	0.09	INTERSECTION	N/A	ROUTE 0960A (NAVY LODGE AREA PARKING)

ROUTE 0440AZ: NY AVENUE

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	PAVED ROUTE (BAY STREET / NON NPS)
0.00	0.00	INTERSECTION	L	ROUTE 0442 (NORTH ROAD)
0.00	0.00	PARK BOUNDARY	N/A	N/A
0.01	0.01	INTERSECTION	R	ROUTE 0954 (MAIN GATE PARKING)
0.03	0.03	INTERSECTION	L	ROUTE 0441 (MONT SEC AVENUE)
0.05	0.05	INTERSECTION	R	ROUTE 0449 (COAST GUARD DRIVE)
0.06	0.06	INTERSECTION	L	ROUTE 0443 (SOUTH ROAD)
0.14	0.14	INTERSECTION	R	ROUTE 0450 (DRUM AVENUE)
0.15	0.15	INTERSECTION	L	ROUTE 0958A (FORT WADSWORTH VISITOR CENTER PARKING)
0.23	0.23	INTERSECTION	L	ROUTE 0958A (FORT WADSWORTH VISITOR CENTER PARKING)
0.28	0.28	INTERSECTION	L	ROUTE 0447 (TOMPKINS ROAD)
0.28	0.28	INTERSECTION	R	ROUTE 0448 (MARSHALL ROAD)
0.30	0.30	OVERPASS	N/A	A STRUCTURE NUMBER HAS NOT BEEN ASSIGNED TO THIS BRIDGE (VERRAZANO-NARROWS BRIDGE/I-278)
0.33	0.33	INTERSECTION	R	ROUTE 0961A (ARMED FORCES RESERVE AREA PARKING)
0.36	0.36	INTERSECTION	R	ROUTE 0961A (ARMED FORCES RESERVE AREA PARKING)
0.38	0.38	INTERSECTION	L	ROUTE 0961D (FWR USPP SWAT PARKING)
0.40	0.40	INTERSECTION	L	ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)
0.40	0.40	INTERSECTION	R	ROUTE 0440BZ (BATTERY ROAD)

Data Collected on 4/2021

ROUTE 0440BZ: BATTERY ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0440AZ (NY AVENUE)
0.00	0.00	INTERSECTION	N/A	ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)
0.10	0.10	INTERSECTION	L	ROUTE 0961B (ARMED FORCES AREA B PARKING)
0.11	0.11	INTERSECTION	R	ROUTE 0961A (ARMED FORCES RESERVE AREA PARKING)
0.11	0.11	INTERSECTION	L	ROUTE 0961B (ARMED FORCES AREA B PARKING)
0.15	0.15	INTERSECTION	L	ROUTE 0471 (LOOP ROAD)
0.18	0.18	INTERSECTION	L	ROUTE 0458 (USS TENNESSEE ROAD)
0.22	0.22	INTERSECTION	L	ROUTE 0439 (PATH ROAD (NAVY LODGE))
0.25	0.25	INTERSECTION	N/A	ROUTE 5004 (MCCLEAN AVENUE)

ROUTE 0441: MONT SEC AVENUE

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4. **FROM** TO

MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0440AZ (NY AVENUE)
0.00	0.00	INTERSECTION	R	ROUTE 0440AZ (NY AVENUE)
0.13	0.13	INTERSECTION	R	ROUTE 0443 (SOUTH ROAD)
0.14	0.14	INTERSECTION	L	ROUTE 0959B (FORT WADSWORTH BUILDING 109 PARKING)
0.14	0.14	INTERSECTION	N/A	ROUTE 0446 (BATTERY WEED ROAD)
0.14	0.14	INTERSECTION	R	ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)

ROUTE 0443: SOUTH ROAD

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0440AZ (NY AVENUE)
0.00	0.00	INTERSECTION	R	ROUTE 0440AZ (NY AVENUE)
0.03	0.03	INTERSECTION	R	ROUTE 0444 (CLIFTON ROAD)
0.14	0.14	INTERSECTION	R	ROUTE 0441 (MONT SEC AVENUE)
0.14	0.14	INTERSECTION	L	ROUTE 0441 (MONT SEC AVENUE)

ROUTE 0445: HUDSON ROAD / STATEN ISLAND

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0440AZ (NY AVENUE)
0.00	0.00	INTERSECTION	N/A	ROUTE 0440BZ (BATTERY ROAD)
0.01	0.01	INTERSECTION	L	ROUTE 0961D (FWR USPP SWAT PARKING)
0.03	0.03	INTERSECTION	R	ROUTE 0452 (USS NEW MEXICO COURT)
0.09	0.09	INTERSECTION	R	ROUTE 0453 (USS NORTH CAROLINA ROAD)
0.13	0.13	INTERSECTION	R	ROUTE 0962A (FWR BALL FIELD PARKING)
0.14	0.14	INTERSECTION	R	ROUTE 0446 (BATTERY WEED ROAD)
0.21	0.21	OVERPASS	N/A	A STRUCTURE NUMBER HAS NOT BEEN ASSIGNED TO THIS BRIDGE (VERRAZANO-NARROWS BRIDGE/I-278)
0.21	0.21	INTERSECTION	L	UNPAVED PARKING (NY DOT MAINTENANCE / GATED)
0.53	0.53	INTERSECTION	R	ROUTE 0446 (BATTERY WEED ROAD)
0.53	0.53	INTERSECTION	N/A	ROUTE 0958B (FT TOMPKINS PARKING)
0.53	0.53	INTERSECTION	L	ROUTE 0441 (MONT SEC AVENUE)

ROUTE 0446: BATTERY WEED ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0962A (FWR BALL FIELD PARKING)
0.00	0.00	INTERSECTION	L	ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)
0.00	0.00	INTERSECTION	N/A	ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)
0.11	0.11	OVERPASS	N/A	A STRUCTURE NUMBER HAS NOT BEEN ASSIGNED TO THIS BRIDGE (VERRAZANO-NARROWS BRIDGE/I-278)
0.24	0.24	INTERSECTION	L	ROUTE 0963D (FWR BATTERY WEED AREA D PARKING)
0.24	0.24	RAILROAD XING	N/A	N/A
0.24	0.24	INTERSECTION	R	ROUTE 0963C (FWR BATTERY WEED AREA C PARKING)
0.24	0.24	RAILROAD XING	N/A	N/A
0.25	0.25	INTERSECTION	R	ROUTE 0502 (DOCK ROAD)
0.30	0.30	RAILROAD XING	N/A	N/A
0.30	0.30	INTERSECTION	L	ROUTE 0963A (FWR BATTERY WEED AREA A PARKING)
0.44	0.44	INTERSECTION	L	ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)
0.44	0.44	INTERSECTION	N/A	ROUTE 0441 (MONT SEC AVENUE)
0.44	0.44	INTERSECTION	R	ROUTE 0959B (FORT WADSWORTH BUILDING 109 PARKING)

Data Collected on 4/2021

ROUTE 0447: TOMPKINS ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0448 (MARSHALL ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0440AZ (NY AVENUE)
0.00	0.00	INTERSECTION	L	ROUTE 0440AZ (NY AVENUE)
0.14	0.14	INTERSECTION	L	ROUTE 0958B (FT TOMPKINS PARKING)
0.15	0.15	INTERSECTION	N/A	DEAD END

ROUTE 0448: MARSHALL ROAD

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0447 (TOMPKINS ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0440AZ (NY AVENUE)
0.00	0.00	INTERSECTION	L	ROUTE 0440AZ (NY AVENUE)
0.03	0.03	INTERSECTION	R	ROUTE 0957D (USPP PARKING B210)
0.17	0.17	INTERSECTION	L	PAVED ROUTE (NY DOT MAINTENANCE / GATED)
0.21	0.21	INTERSECTION	R	ROUTE 0957C (HQ B210 PARKING)
0.21	0.21	INTERSECTION	L	PAVED ROUTE (NY DOT MAINTENANCE / GATED)
0.23	0.23	INTERSECTION	R	ROUTE 0957B (HAND BALL PARKING)
0.24	0.24	PARK BOUNDARY	N/A	N/A
0.24	0.24	INTERSECTION	N/A	ROUTE 0449 (COAST GUARD DRIVE)

ROUTE 0449: COAST GUARD DRIVE

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	ONE-WAY START	N/A	N/A
0.00	0.00	INTERSECTION	R	ROUTE 0440AZ (NY AVENUE)
0.05	0.05	INTERSECTION	R	ROUTE 0955AAZ (COAST GUARD AREA PARKING AAZ)
0.06	0.06	INTERSECTION	L	ROUTE 0955C (USCG ACTIVITIES PARKING)
0.08	0.08	INTERSECTION	L	ROUTE 0955C (USCG ACTIVITIES PARKING)
0.08	0.08	INTERSECTION	R	ROUTE 0955B (COAST GUARD AREA PARKING B)
0.12	0.12	INTERSECTION	R	ROUTE 0955ABZ (COAST GUARD AREA PARKING ABZ)
0.14	0.14	INTERSECTION	L	ROUTE 0955D (USCG GALLEY PARKING)
0.16	0.16	INTERSECTION	R	ROUTE 0955B (COAST GUARD AREA PARKING B)
0.16	0.16	INTERSECTION	L	ROUTE 0955E (USCG GALLEY REAR PARKING AND FIRE LANE)
0.17	0.17	INTERSECTION	L	ROUTE 0955E (USCG GALLEY REAR PARKING AND FIRE LANE)
0.18	0.18	INTERSECTION	L	ROUTE 0451 (MOLONY DRIVE)
0.22	0.22	INTERSECTION	R	ROUTE 0955ACZ (COAST GUARD AREA PARKING ACZ)
0.23	0.23	INTERSECTION	L	RROUTE 0955F (USCG PX PARKING)
0.30	0.30	INTERSECTION	L	RROUTE 0955F (USCG PX PARKING)
0.33	0.33	INTERSECTION	L	ROUTE 0450 (DRUM AVENUE)
0.38	0.38	INTERSECTION	N/A	ROUTE 0448 (MARSHALL ROAD)
0.38	0.38	ONE-WAY END	N/A	N/A

ROUTE 0450: DRUM AVENUE

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0449 (COAST GUARD DRIVE)
0.00	0.00	INTERSECTION	L	ROUTE 0449 (COAST GUARD DRIVE)
0.01	0.01	INTERSECTION	L	ROUTE 0956D (DRUM AVENUE PARKING D)
0.01	0.01	INTERSECTION	R	ROUTE 0957B (HAND BALL PARKING)
0.03	0.03	INTERSECTION	R	ROUTE 0957B (HAND BALL PARKING)
0.03	0.03	INTERSECTION	L	ROUTE 0451 (MOLONY DRIVE)
0.05	0.05	INTERSECTION	L	ROUTE 0955E (USCG GALLEY REAR PARKING AND FIRE LANE)
0.05	0.05	ONE-WAY START	N/A	N/A
0.10	0.10	INTERSECTION	L	ROUTE 0956A (DRUM AVENUE PARKING A)
0.11	0.11	INTERSECTION	L	ROUTE 0956A (DRUM AVENUE PARKING A)
0.13	0.13	INTERSECTION	L	ROUTE 0956B (DRUM AVENUE CHAPEL PARKING)
0.14	0.14	INTERSECTION	R	ROUTE 0956C (DRUM AVENUE LOOP PARKING)
0.15	0.15	INTERSECTION	R	ROUTE 0956C (DRUM AVENUE LOOP PARKING)
0.21	0.21	INTERSECTION	L	ROUTE 0440AZ (NY AVENUE)
0.21	0.21	INTERSECTION	R	ROUTE 0440AZ (NY AVENUE)
0.21	0.21	ONE-WAY END	N/A	N/A

ROUTE 0451: MOLONY DRIVE

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0449 (COAST GUARD DRIVE)
0.00	0.00	INTERSECTION	R	ROUTE 0449 (COAST GUARD DRIVE)
0.04	0.04	INTERSECTION	R	ROUTE 0957A (THEATRE PARKING)
0.04	0.04	INTERSECTION	L	ROUTE 0955E (USCG GALLEY REAR PARKING AND FIRE LANE)
0.05	0.05	INTERSECTION	R	ROUTE 0957A (THEATRE PARKING)
0.07	0.07	INTERSECTION	R	ROUTE 0450 (DRUM AVENUE)
0.07	0.07	INTERSECTION	L	ROUTE 0450 (DRUM AVENUE)

ROUTE 0452: USS NEW MEXICO COURT

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)
0.00	0.00	INTERSECTION	L	ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)
0.06	0.06	INTERSECTION	L	ROUTE 0452 (USS NEW MEXICO COURT)
0.09	0.09	INTERSECTION	L	ROUTE 0452 (USS NEW MEXICO COURT)
0.09	0.09	INTERSECTION	N/A	ROUTE 0452 (USS NEW MEXICO COURT)

ROUTE 0453: USS NORTH CAROLINA ROAD

0.150.15ONE-WAY STARTN/AN/A0.380.38INTERSECTIONLROUTE 0458 (USS TENNESSEE ROAD)0.380.38ONE-WAY ENDN/AN/A0.580.58INTERSECTIONRROUTE 0472 (RANGE ROAD (STATEN ISLAND))	FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.080.08INTERSECTIONLROUTE 0454 (USS CONNECTICUT COURT)0.090.09INTERSECTIONLROUTE 0454 (USS CONNECTICUT COURT)0.150.15INTERSECTIONLPAVED ROUTE (USS CONNECTICUT COURT/ NON N0.150.15ONE-WAY STARTN/AN/A0.380.38INTERSECTIONLROUTE 0458 (USS TENNESSEE ROAD)0.380.38ONE-WAY ENDN/AN/A0.580.58INTERSECTIONRROUTE 0472 (RANGE ROAD (STATEN ISLAND))0.610.61INTERSECTIONRROUTE 0962B (FWR CAMPGROUND PARKING AREA0.720.72INTERSECTIONRROUTE 0962A (FWR BALL FIELD PARKING)	0.00	0.00	INTERSECTION	R	ROUTE 0438 (AYERS ROAD)
0.090.09INTERSECTIONLROUTE 0454 (USS CONNECTICUT COURT)0.150.15INTERSECTIONLPAVED ROUTE (USS CONNECTICUT COURT/ NON N0.150.15ONE-WAY STARTN/AN/A0.380.38INTERSECTIONLROUTE 0458 (USS TENNESSEE ROAD)0.380.38ONE-WAY ENDN/AN/A0.580.58INTERSECTIONRROUTE 0472 (RANGE ROAD (STATEN ISLAND))0.610.61INTERSECTIONRROUTE 0962B (FWR CAMPGROUND PARKING AREA0.720.72INTERSECTIONRROUTE 0962A (FWR BALL FIELD PARKING)	0.00	0.00	INTERSECTION	N/A	ROUTE 0438 (AYERS ROAD)
0.150.15INTERSECTIONLPAVED ROUTE (USS CONNECTICUT COURT/ NON N0.150.15ONE-WAY STARTN/AN/A0.380.38INTERSECTIONLROUTE 0458 (USS TENNESSEE ROAD)0.380.38ONE-WAY ENDN/AN/A0.580.58INTERSECTIONRROUTE 0472 (RANGE ROAD (STATEN ISLAND))0.610.61INTERSECTIONRROUTE 0962B (FWR CAMPGROUND PARKING AREA0.720.72INTERSECTIONRROUTE 0962A (FWR BALL FIELD PARKING)	0.08	0.08	INTERSECTION	L	ROUTE 0454 (USS CONNECTICUT COURT)
0.150.15ONE-WAY STARTN/AN/A0.380.38INTERSECTIONLROUTE 0458 (USS TENNESSEE ROAD)0.380.38ONE-WAY ENDN/AN/A0.580.58INTERSECTIONRROUTE 0472 (RANGE ROAD (STATEN ISLAND))0.610.61INTERSECTIONRROUTE 0962B (FWR CAMPGROUND PARKING AREA0.720.72INTERSECTIONRROUTE 0962A (FWR BALL FIELD PARKING)	0.09	0.09	INTERSECTION	L	ROUTE 0454 (USS CONNECTICUT COURT)
0.380.38INTERSECTIONLROUTE 0458 (USS TENNESSEE ROAD)0.380.38ONE-WAY ENDN/AN/A0.580.58INTERSECTIONRROUTE 0472 (RANGE ROAD (STATEN ISLAND))0.610.61INTERSECTIONRROUTE 0962B (FWR CAMPGROUND PARKING AREA0.720.72INTERSECTIONRROUTE 0962A (FWR BALL FIELD PARKING)	0.15	0.15	INTERSECTION	L	PAVED ROUTE (USS CONNECTICUT COURT/ NON NPS)
0.380.38ONE-WAY ENDN/AN/A0.580.58INTERSECTIONRROUTE 0472 (RANGE ROAD (STATEN ISLAND))0.610.61INTERSECTIONRROUTE 0962B (FWR CAMPGROUND PARKING AREA0.720.72INTERSECTIONRROUTE 0962A (FWR BALL FIELD PARKING)	0.15	0.15	ONE-WAY START	N/A	N/A
0.580.58INTERSECTIONRROUTE 0472 (RANGE ROAD (STATEN ISLAND))0.610.61INTERSECTIONRROUTE 0962B (FWR CAMPGROUND PARKING AREA0.720.72INTERSECTIONRROUTE 0962A (FWR BALL FIELD PARKING)	0.38	0.38	INTERSECTION	L	ROUTE 0458 (USS TENNESSEE ROAD)
0.610.61INTERSECTIONRROUTE 0962B (FWR CAMPGROUND PARKING AREA0.720.72INTERSECTIONRROUTE 0962A (FWR BALL FIELD PARKING)	0.38	0.38	ONE-WAY END	N/A	N/A
0.72 0.72 INTERSECTION R ROUTE 0962A (FWR BALL FIELD PARKING)	0.58	0.58	INTERSECTION	R	ROUTE 0472 (RANGE ROAD (STATEN ISLAND))
	0.61	0.61	INTERSECTION	R	ROUTE 0962B (FWR CAMPGROUND PARKING AREA)
0.74 0.74 INTERSECTION R ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)	0.72	0.72	INTERSECTION	R	ROUTE 0962A (FWR BALL FIELD PARKING)
	0.74	0.74	INTERSECTION	R	ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)
0.74 0.74 INTERSECTION L ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)	0.74	0.74	INTERSECTION	L	ROUTE 0445 (HUDSON ROAD / STATEN ISLAND)

ROUTE 0454: USS CONNECTICUT COURT

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0453 (USS NORTH CAROLINA ROAD)
0.00	0.00	INTERSECTION	L	ROUTE 0453 (USS NORTH CAROLINA ROAD)
0.08	0.08	INTERSECTION	R	ROUTE 0455 (USS ARIZONA LANE)
0.14	0.14	INTERSECTION	R	ROUTE 0453 (USS NORTH CAROLINA ROAD)
0.14	0.14	INTERSECTION	L	ROUTE 0453 (USS NORTH CAROLINA ROAD)

ROUTE 0455: USS ARIZONA LANE

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0456 (USS IOWA CIRCLE)
0.00	0.00	INTERSECTION	L	ROUTE 0456 (USS IOWA CIRCLE)
0.03	0.03	INTERSECTION	L	ROUTE 0454 (USS CONNECTICUT COURT)
0.03	0.03	INTERSECTION	R	ROUTE 0454 (USS CONNECTICUT COURT)

ROUTE 0456: USS IOWA CIRCLE

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0457 (USS MISSOURI LANE)
0.01	0.01	ONE-WAY START	N/A	N/A
0.01	0.01	INTERSECTION	L	ROUTE 0456 (USS IOWA CIRCLE)
0.12	0.12	INTERSECTION	R	ROUTE 0455 (USS ARIZONA LANE)
0.24	0.24	INTERSECTION	N/A	ROUTE 0456 (USS IOWA CIRCLE)
0.24	0.24	INTERSECTION	R	ROUTE 0456 (USS IOWA CIRCLE)
0.24	0.24	ONE-WAY END	N/A	N/A

ROUTE 0457: USS MISSOURI LANE

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0458 (USS TENNESSEE ROAD)
0.00	0.00	INTERSECTION	L	ROUTE 0458 (USS TENNESSEE ROAD)
0.04	0.04	INTERSECTION	N/A	ROUTE 0456 (USS IOWA CIRCLE)
0.04	0.04	INTERSECTION	L	ROUTE 0456 (USS IOWA CIRCLE)

ROUTE 0458: USS TENNESSEE ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4. FROM ТО

MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0440BZ (BATTERY ROAD)
0.00	0.00	INTERSECTION	L	ROUTE 0440BZ (BATTERY ROAD)
0.02	0.02	INTERSECTION	L	ROUTE 1015 (BUILDING 301 MAINTENANCE PARKING)
0.05	0.05	INTERSECTION	L	ROUTE 1014 (BUILDING 302 L-SHAPED PARKING)
0.06	0.06	INTERSECTION	L	ROUTE 1013 (USPP STABLE PARKING)
0.06	0.06	INTERSECTION	R	ROUTE 0438 (AYERS ROAD)
0.10	0.10	INTERSECTION	L	ROUTE 0471 (LOOP ROAD)
0.16	0.16	INTERSECTION	R	ROUTE 0457 (USS MISSOURI LANE)
0.17	0.17	INTERSECTION	L	ROUTE 0459 (USS FLORIDA COURT)
0.23	0.23	INTERSECTION	L	ROUTE 0453 (USS NORTH CAROLINA ROAD)
0.23	0.23	INTERSECTION	R	ROUTE 0453 (USS NORTH CAROLINA ROAD)

ROUTE 0459: USS FLORIDA COURT

MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0458 (USS TENNESSEE ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0458 (USS TENNESSEE ROAD)
0.13	0.13	INTERSECTION	L	ROUTE 0459 (USS FLORIDA COURT)
0.17	0.17	INTERSECTION	R	ROUTE 0459 (USS FLORIDA COURT)
0.17	0.17	INTERSECTION	L	ROUTE 0459 (USS FLORIDA COURT)

ROUTE 0460: NORTH MAINTENANCE AREA ACCESS ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0660 (CANFIELD ROAD)
0.00	0.00	INTERSECTION	N/A	ROUTE 0665 (KEARNY DRIVE)
0.12	0.12	INTERSECTION	L	ROUTE 0928A (NORTH MAINTENANCE EMPLOYEE PARKING A)
0.12	0.12	INTERSECTION	R	ROUTE 0928B (NORTH MAINTENANCE EMPLOYEE PARKING B)
0.14	0.14	INTERSECTION	L	ROUTE 0928A (NORTH MAINTENANCE EMPLOYEE PARKING A)
0.14	0.14	INTERSECTION	L	ROUTE 0658 (KILPATRICK ROAD)
0.14	0.14	INTERSECTION	N/A	ROUTE 0672 (FORD ROAD)
0.14	0.14	INTERSECTION	R	ROUTE 0658 (KILPATRICK ROAD)

ROUTE 0462: RANDOLPH ROAD

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.00	0.00	INTERSECTION	L	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.10	0.10	INTERSECTION	R	ROUTE 0915 (WATER TREATMENT PLANT PARKING)
0.26	0.26	INTERSECTION	N/A	PAVED TRAIL

ROUTE 0464: AVIATION ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.01	0.01	INTERSECTION	L	ROUTE 0964AAZ (ENTRANCE AREA PARKING A)
0.01	0.01	INTERSECTION	R	ROUTE 0964ABZ (ENTRANCE AREA PARKING B)
0.03	0.03	INTERSECTION	L	ROUTE 0964AAZ (ENTRANCE AREA PARKING A)
0.03	0.03	INTERSECTION	R	ROUTE 0964ABZ (ENTRANCE AREA PARKING B)
0.17	0.17	INTERSECTION	L	ROUTE 0964B (SEWAGE TREATMENT PARKING IN JAMAICA BAY)
0.21	0.21	INTERSECTION	R	PAVED PARKING
0.32	0.32	INTERSECTION	L	ROUTE 0464 (AVIATION ROAD)
0.39	0.39	INTERSECTION	L	ROUTE 0464 (AVIATION ROAD)
0.39	0.39	INTERSECTION	N/A	ROUTE 0464 (AVIATION ROAD)

ROUTE 0465: BUILDING 272 ACCESS ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM	то	2		-
MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.05	0.05	INTERSECTION	L	PAVED PARKING
0.08	0.08	INTERSECTION	R	PAVED PARKING (CONCRETE)
0.18	0.18	INTERSECTION	L	ROUTE 0201 (RANGER ROAD)
0.18	0.18	INTERSECTION	R	ROUTE 0970 (FISHING ACCESS PARKING)

ROUTE 0470: JACOB RIIS SERVICE ROAD

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 5001 (BEACH CHANNEL DRIVE)
0.00	0.00	INTERSECTION	R	PAVED ROUTE (BEACH CHANNEL DRIVE / NON NPS)
0.02	0.02	INTERSECTION	L	ROUTE 0470 (JACOB RIIS SERVICE ROAD) SPUR
0.03	0.03	INTERSECTION	R	PAVED PARKING
0.32	0.32	INTERSECTION	N/A	ROUTE 5003 (ROCKAWAY BEACH BOULEVARD)

ROUTE 0479: FISHERMAN'S PARKING ACCESS

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.00	0.00	INTERSECTION	R	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.24	0.24	INTERSECTION	N/A	ROUTE 1030 (PARKING LOT F)

ROUTE 0497: NYPD ROAD 1

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5. FROM то

MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	PAVED ROUTE (NYPD AREA 1) (BLOCKED BY JERSEY BARRIERS)
0.09	0.09	INTERSECTION	L	ROUTE 0498 (NYPD ROAD 2)
0.12	0.12	INTERSECTION	L	ROUTE 0504BZ (SOUTHERN RUNWAY B)
0.12	0.12	INTERSECTION	R	ROUTE 0504BZ (SOUTHERN RUNWAY B)

ROUTE 0498: NYPD ROAD 2

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5. FROM то

FROM MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.09	0.09	INTERSECTION	L	ROUTE 0497 (NYPD ROAD 1)
0.09	0.09	INTERSECTION	R	ROUTE 0497 (NYPD ROAD 1)

ROUTE 0500: CENTRAL RUNWAY

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6. FROM то

MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	FIELD/GRASS
0.10	0.10	INTERSECTION	R	ROUTE 0504BZ (SOUTHERN RUNWAY B)
0.10	0.10	INTERSECTION	L	ROUTE 0406 (TAXIWAY A)
0.11	0.11	INTERSECTION	R	ROUTE 0406 (TAXIWAY A)
0.11	0.11	INTERSECTION	L	ROUTE 0504AZ (SOUTHERN RUNWAY A)
0.74	0.74	INTERSECTION	R	ROUTE 0403 (RUNWAY C)
0.74	0.74	INTERSECTION	L	ROUTE 0403 (RUNWAY C)
$\mathbf{D} \leftarrow \mathbf{C} 11 \mathbf{c}$	1 4/2021			

Data Collected on 4/2021

ROUTE 0502: DOCK ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0446 (BATTERY WEED ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0446 (BATTERY WEED ROAD)
0.03	0.03	INTERSECTION	N/A	DEAD END

ROUTE 0504AZ: SOUTHERN RUNWAY A

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.11	0.11	INTERSECTION	L	ROUTE 0410 (TAXIWAY C)
0.13	0.13	INTERSECTION	R	ROUTE 0406 (TAXIWAY A)
0.44	0.44	INTERSECTION	N/A	ROUTE 0504BZ (SOUTHERN RUNWAY B)

ROUTE 0504BZ: SOUTHERN RUNWAY B

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0504AZ (SOUTHERN RUNWAY A)
0.50	0.50	INTERSECTION	L	RROUTE 0497 (NYPD ROAD 1)
0.51	0.51	INTERSECTION	R	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)
0.51	0.51	INTERSECTION	L	ROUTE 0200 (FLOYD BENNETT FIELD ENTRANCE ROAD)

ROUTE 0657: HANAKI ROAD

MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0665 (KEARNY DRIVE)
0.00	0.00	INTERSECTION	R	ROUTE 0665 (KEARNY DRIVE)
0.07	0.07	INTERSECTION	R	ROUTE 0669 (KNOX ROAD NORTH)
0.07	0.07	INTERSECTION	L	ROUTE 0669 (KNOX ROAD NORTH)

ROUTE 0658: KILPATRICK ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0667 (NORTH BRAGG DRIVE)
0.00	0.00	INTERSECTION	N/A	ROUTE 1029 (NDR LOT K PARKING LOT K UNPAVED)
0.00	0.00	INTERSECTION	R	ROUTE 0667 (NORTH BRAGG DRIVE)
0.04	0.04	INTERSECTION	R	ROUTE 0460 (NORTH MAINTENANCE AREA ACCESS ROAD)
0.04	0.04	INTERSECTION	L	ROUTE 0672 (FORD ROAD)
0.12	0.12	INTERSECTION	R	ROUTE 0660 (CANFIELD ROAD)
0.12	0.12	INTERSECTION	L	ROUTE 0660 (CANFIELD ROAD)
0.15	0.15	INTERSECTION	R	ROUTE 0660 (CANFIELD ROAD) CUT-THRU
0.15	0.15	INTERSECTION	R	ROUTE 0669 (KNOX ROAD NORTH)
0.15	0.15	INTERSECTION	L	ROUTE 0669 (KNOX ROAD NORTH)
0.27	0.27	INTERSECTION	L	ROUTE 0668 (SOUTH BRAGG DRIVE)
0.27	0.27	INTERSECTION	R	ROUTE 0668 (SOUTH BRAGG DRIVE)

ROUTE 0659: OLD TRAILER CAMP LANE MAST

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0662AZ (MAGRUDER ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0662AZ (MAGRUDER ROAD)
0.02	0.02	INTERSECTION	R	ROUTE 1032 (ND NEW TENT CITY PARKING)
0.04	0.04	INTERSECTION	R	ROUTE 0920 (MARINE ACADEMY CAFETERIA #77 PARKING)
0.06	0.06	INTERSECTION	R	ROUTE 0485 (GUNNISON ROAD MAST BUS ACCESS)
0.13	0.13	INTERSECTION	N/A	DEAD END

ROUTE 0660: CANFIELD ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0460 (NORTH MAINTENANCE AREA ACCESS ROAD)
0.00	0.00	INTERSECTION	N/A	PAVED ROUTE (USCG ENTRANCE (CANFIELD ROAD))
0.00	0.00	INTERSECTION	R	ROUTE 0665 (KEARNY DRIVE)
0.01	0.01	INTERSECTION	L	ROUTE 0460 (NORTH MAINTENANCE AREA ACCESS ROAD) SPUR
0.07	0.07	INTERSECTION	R	ROUTE 0669 (KNOX ROAD NORTH)
0.09	0.09	INTERSECTION	R	ROUTE 0658 (KILPATRICK ROAD) SPUR
0.12	0.12	INTERSECTION	R	ROUTE 0658 (KILPATRICK ROAD)
0.12	0.12	INTERSECTION	L	ROUTE 0658 (KILPATRICK ROAD)
0.15	0.15	INTERSECTION	R	PAVED ROUTE
0.16	0.16	INTERSECTION	L	UNPAVED PARKING
0.21	0.21	INTERSECTION	R	ROUTE 0668 (SOUTH BRAGG DRIVE)
0.21	0.21	INTERSECTION	L	ROUTE 0668 (SOUTH BRAGG DRIVE)

ROUTE 0661AZ: HUDSON ROAD

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.00	0.00	INTERSECTION	L	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.02	0.02	INTERSECTION	L	ROUTE 0661BZ (HUDSON ROAD SPUR)
0.03	0.03	INTERSECTION	L	ROUTE 0664 (KESSLER ROAD)
0.03	0.03	INTERSECTION	R	ROUTE 0664 (KESSLER ROAD)
0.08	0.08	INTERSECTION	L	ROUTE 0661CZ (HUDSON ROAD CUT-THRU)
0.11	0.11	INTERSECTION	L	ROUTE 0665 (KEARNY DRIVE)
0.16	0.16	INTERSECTION	L	ROUTE 0675AZ (MCNAIR ROAD)
0.18	0.18	INTERSECTION	R	ROUTE 0662AZ (MAGRUDER ROAD)
0.18	0.18	INTERSECTION	L	ROUTE 0923 (BUILDING 53 AND BUILDING 60 PARKING)
0.19	0.19	INTERSECTION	L	ROUTE 0925 (LIGHTHOUSE PARKING)
0.21	0.21	INTERSECTION	R	ROUTE 0662BZ (MAGRUDER ROAD SPUR 1)

ROUTE 0661AZ: HUDSON ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.29	0.29	INTERSECTION	L	UNPAVED ROUTE
0.60	0.60	INTERSECTION	R	UNPAVED PARKING
0.61	0.61	INTERSECTION	R	UNPAVED PARKING
0.66	0.66	INTERSECTION	R	ROUTE 0668 (SOUTH BRAGG DRIVE)
0.66	0.66	INTERSECTION	L	ROUTE 0668 (SOUTH BRAGG DRIVE)

ROUTE 0662AZ: MAGRUDER ROAD

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.00	0.00	INTERSECTION	N/A	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.02	0.02	INTERSECTION	L	ROUTE 0662BZ (MAGRUDER ROAD SPUR 1)
0.10	0.10	INTERSECTION	L	ROUTE 0916 (GUARDIAN PARK PARKING)
0.17	0.17	INTERSECTION	R	ROUTE 0918A (NOAA LAB A PARKING SOUTH)
0.21	0.21	INTERSECTION	L	ROUTE 0663 (PENNINGTON STREET)
0.26	0.26	INTERSECTION	R	ROUTE 0918B (NOAA LAB B PARKING NORTH)
0.27	0.27	INTERSECTION	L	ROUTE 0919 (BUILDING 74 EAST PARKING)
0.30	0.30	INTERSECTION	R	ROUTE 0671 (NEW GUNNISON ROAD)
0.34	0.34	INTERSECTION	R	ROUTE 0659 (OLD TRAILER CAMP LANE MAST)
0.36	0.36	INTERSECTION	R	ROUTE 0670 (OLD GUNNISON ROAD/MAST WAY)
0.37	0.37	INTERSECTION	R	ROUTE 0921 (MAST PARKING LOT "N")
0.40	0.40	INTERSECTION	R	ROUTE 0921 (MAST PARKING LOT "N")
0.42	0.42	INTERSECTION	R	ROUTE 0662BZ (MAGRUDER ROAD SPUR 1)
0.42	0.42	INTERSECTION	L	ROUTE 0937 (BUILDING 58 PARKING)
0.45	0.45	INTERSECTION	N/A	ROUTE 0923 (BUILDING 53 AND BUILDING 60 PARKING)
0.45	0.45	INTERSECTION	L	ROUTE 0661AZ (HUDSON ROAD)
0.45	0.45	INTERSECTION	R	ROUTE 0661AZ (HUDSON ROAD)

ROUTE 0663: PENNINGTON STREET

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.00	0.00	INTERSECTION	L	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.01	0.01	INTERSECTION	L	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND)) SPUR
0.07	0.07	INTERSECTION	L	ROUTE 0917 (DAYCARE #335 AND #18 PARKING)
0.14	0.14	INTERSECTION	L	ROUTE 0662AZ (MAGRUDER ROAD)
0.14	0.14	INTERSECTION	R	ROUTE 0662AZ (MAGRUDER ROAD)

ROUTE 0664: KESSLER ROAD

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.00	0.00	INTERSECTION	L	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.01	0.01	INTERSECTION	L	ROUTE 0664 (KESSLER ROAD) SPUR
0.03	0.03	INTERSECTION	R	ROUTE 0917 (DAYCARE #335 AND #18 PARKING)
0.28	0.28	INTERSECTION	R	ROUTE 0661AZ (HUDSON ROAD)
0.28	0.28	INTERSECTION	L	ROUTE 0661AZ (HUDSON ROAD)
0.31	0.31	INTERSECTION	R	ROUTE 0666 (LAWSON LANE)
0.48	0.48	INTERSECTION	L	ROUTE 0665 (KEARNY DRIVE)
0.48	0.48	INTERSECTION	R	ROUTE 0665 (KEARNY DRIVE)

ROUTE 0665: KEARNY DRIVE

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	N/A	ROUTE 0661AZ (HUDSON ROAD)
0.00	0.00	INTERSECTION	L	ROUTE 0661AZ (HUDSON ROAD)
0.03	0.03	INTERSECTION	L	ROUTE 0661CZ (HUDSON ROAD CUT-THRU)
0.04	0.04	INTERSECTION	L	ROUTE 0666 (LAWSON LANE)
0.05	0.05	INTERSECTION	R	ROUTE 0675BZ (MCNAIR ROAD CUT-THRU B)
0.12	0.12	INTERSECTION	R	ROUTE 0675AZ (MCNAIR ROAD)
0.15	0.15	INTERSECTION	R	ROUTE 0674 (MERCER ROAD)
0.22	0.22	INTERSECTION	R	ROUTE 0927 (BUILDING 32 PARK RANGER PARKING)
0.23	0.23	INTERSECTION	L	ROUTE 0664 (KESSLER ROAD)
0.26	0.26	INTERSECTION	L	ROUTE 0936 (FORT HANCOCK THEATER PARKING)
0.27	0.27	INTERSECTION	R	UNPAVED ROUTE
0.30	0.30	INTERSECTION	R	ROUTE 0668 (SOUTH BRAGG DRIVE) SPUR
0.31	0.31	INTERSECTION	R	ROUTE 0668 (SOUTH BRAGG DRIVE)
0.31	0.31	INTERSECTION	L	ROUTE 0668 (SOUTH BRAGG DRIVE)
0.35	0.35	INTERSECTION	L	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.38	0.38	INTERSECTION	R	UNPAVED ROUTE (EDUCATION CENTER)
0.49	0.49	INTERSECTION	R	ROUTE 0657 (HANAKI ROAD)
0.53	0.53	INTERSECTION	R	ROUTE 0660 (CANFIELD ROAD)
0.53	0.53	INTERSECTION	N/A	ROUTE 0460 (NORTH MAINTENANCE AREA ACCESS ROAD)
0.53	0.53	INTERSECTION	L	PAVED ROUTE (USCG ENTRANCE (CANFIELD ROAD))

ROUTE 0666: LAWSON LANE

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FRO MIL		TO MILEPOST	FEATURE	SIDE	COMMENT
0.00)	0.00	INTERSECTION	L	ROUTE 0665 (KEARNY DRIVE)
0.00)	0.00	INTERSECTION	R	ROUTE 0665 (KEARNY DRIVE)
0.03		0.03	INTERSECTION	R	ROUTE 0926 (LAWSON LANE PARKING)
0.07		0.07	INTERSECTION	L	ROUTE 0664 (KESSLER ROAD)
0.07		0.07	INTERSECTION	R	ROUTE 0664 (KESSLER ROAD)

Data Collected on 4/2021

ROUTE 0668: SOUTH BRAGG DRIVE

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.00	0.00	INTERSECTION	L	ROUTE 0060 (HARTSHORNE DRIVE (NORTHBOUND))
0.02	0.02	INTERSECTION	L	ROUTE 0665 (KEARNY DRIVE)
0.02	0.02	INTERSECTION	R	ROUTE 0665 (KEARNY DRIVE)
0.04	0.04	INTERSECTION	R	ROUTE 0665 (KEARNY DRIVE) SPUR
0.05	0.05	INTERSECTION	L	ROUTE 0658 (KILPATRICK ROAD)
0.05	0.05	INTERSECTION	R	UNPAVED ROUTE
0.14	0.14	INTERSECTION	L	ROUTE 0669 (KNOX ROAD NORTH)
0.19	0.19	INTERSECTION	R	ROUTE 0661AZ (HUDSON ROAD)
0.20	0.20	INTERSECTION	L	ROUTE 0660 (CANFIELD ROAD)
0.29	0.29	INTERSECTION	R	ROUTE 0160 (ATLANTIC DRIVE)
0.29	0.29	INTERSECTION	N/A	PAVED TRAIL
0.29	0.29	INTERSECTION	L	ROUTE 0672 (FORD ROAD)

ROUTE 0669: KNOX ROAD NORTH

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0660 (CANFIELD ROAD)
0.00	0.00	INTERSECTION	R	ROUTE 0660 (CANFIELD ROAD)
0.02	0.02	INTERSECTION	R	ROUTE 0657 (HANAKI ROAD)
0.06	0.06	INTERSECTION	L	ROUTE 0658 (KILPATRICK ROAD)
0.06	0.06	INTERSECTION	R	ROUTE 0658 (KILPATRICK ROAD)
0.12	0.12	INTERSECTION	R	ROUTE 0668 (SOUTH BRAGG DRIVE)
0.12	0.12	INTERSECTION	L	ROUTE 0668 (SOUTH BRAGG DRIVE)

ROUTE 0670: OLD GUNNISON ROAD/MAST WAY

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	R	ROUTE 0662AZ (MAGRUDER ROAD)
0.00	0.00	INTERSECTION	L	ROUTE 0662AZ (MAGRUDER ROAD)
0.11	0.11	INTERSECTION	L	ROUTE 0922 (MAST SCHOOL OFFICES TEACHERS PARKING)
0.15	0.15	INTERSECTION	R	UNPAVED ROUTE (ROUTE 0659 (OLD TRAILER CAMP LANE) CUT-THRU)
0.15	0.15	INTERSECTION	N/A	DEAD END

ROUTE 0671: NEW GUNNISON ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4. **FROM** TO

MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0929 (GUNNISON BEACH PARKING)
0.00	0.00	INTERSECTION	R	ROUTE 0160 (ATLANTIC DRIVE)
0.00	0.00	INTERSECTION	N/A	ROUTE 0160 (ATLANTIC DRIVE)
0.08	0.08	INTERSECTION	L	ROUTE 0929 (GUNNISON BEACH PARKING)
0.18	0.18	INTERSECTION	R	ROUTE 0485 (GUNNISON ROAD MAST BUS ACCESS)
0.22	0.22	INTERSECTION	R	ROUTE 0485 (GUNNISON ROAD MAST BUS ACCESS)
0.26	0.26	INTERSECTION	L	ROUTE 0918B (NOAA LAB B PARKING NORTH)
0.28	0.28	INTERSECTION	R	ROUTE 0662AZ (MAGRUDER ROAD)
0.28	0.28	INTERSECTION	L	ROUTE 0662AZ (MAGRUDER ROAD)

ROUTE 0672: FORD ROAD

MILEPOST	MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0668 (SOUTH BRAGG DRIVE)
0.00	0.00	INTERSECTION	R	PAVED TRAIL
0.00	0.00	INTERSECTION	N/A	ROUTE 0160 (ATLANTIC DRIVE)
0.11	0.11	INTERSECTION	R	ROUTE 0658 (KILPATRICK ROAD)
0.11	0.11	INTERSECTION	L	ROUTE 0658 (KILPATRICK ROAD)
0.11	0.11	INTERSECTION	N/A	ROUTE 0460 (NORTH MAINTENANCE AREA ACCESS ROAD)

ROUTE 0674: MERCER ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0665 (KEARNY DRIVE)
0.00	0.00	INTERSECTION	R	ROUTE 0665 (KEARNY DRIVE)
0.01	0.01	INTERSECTION	L	PAVED ROUTE (ALLEY)
0.02	0.02	INTERSECTION	R	ROUTE 0675CZ (MCNAIR ROAD CUT-THRU C)
0.09	0.09	INTERSECTION	R	UNPAVED ROUTE
0.09	0.09	INTERSECTION	L	UNPAVED ROUTE (ALLEY)
0.11	0.11	INTERSECTION	N/A	ROUTE 0925 (LIGHTHOUSE PARKING)

ROUTE 0675AZ: MCNAIR ROAD

FROM MILEPOST	TO MILEPOST	FEATURE	SIDE	COMMENT
0.00	0.00	INTERSECTION	L	ROUTE 0665 (KEARNY DRIVE)
0.00	0.00	INTERSECTION	R	ROUTE 0665 (KEARNY DRIVE)
0.01	0.01	INTERSECTION	L	ROUTE 0675CZ (MCNAIR ROAD CUT-THRU C)
0.09	0.09	INTERSECTION	R	ROUTE 0675BZ (MCNAIR ROAD CUT-THRU B)
0.11	0.11	INTERSECTION	L	ROUTE 0923 (BUILDING 53 AND BUILDING 60 PARKING)
0.13	0.13	INTERSECTION	R	ROUTE 0924 (BUILDING 40/ POST OFFICE/ GYM PARKING)
0.15	0.15	INTERSECTION	L	ROUTE 0661AZ (HUDSON ROAD)
0.15	0.15	INTERSECTION	R	ROUTE 0661AZ (HUDSON ROAD)

Section 8 Appendix



Gateway National Recreation Area



Improvements to the RIP Index Equations and Determination of PCR

In 2005, the Federal Highway Administration (FHWA) began implementing the use of a Pavement Management System (PMS) to assist the National Park Service (NPS) in prioritizing Pavement Maintenance and Rehabilitation activities. The PMS used by FHWA is the Highway Pavement Management Application (HPMA) which has the ability to store inventory and condition data from the Road Inventory Program (RIP) and forecast future performance using prediction models. Outputs include performance and condition reports at the National, Region, Park, or Route level. A regional prioritized list and optimization have been produced for most regions and the Federal Highway Deferred Maintenance is calculated via the HPMA as well.

In an effort to improve the accuracy of treatment recommendations and pavement condition descriptions the distresses and indexes that comprise the Pavement Condition Rating (PCR), an extensive study was completed throughout 2010 that has resulted in changes to the RIP condition reporting method and specifically, the calculation of PCR. It was determined that a better representation of PCR could be achieved by modifying the relative impact certain distresses would have on the overall rating.

Through the use of HPMA data, it was noted that false failure indicators existed with the existing PCR model, and that it would be necessary to reduce their impact. The distresses affected in this way were Rutting and Roughness. Conversely, experience showed that roadways with extensive cracking present were often shown to have a high PCR. Therefore, the crack index models were adjusted to be more sensitive to changes in crack severity or quantity. It was also determined that these issues were not due to a problem with data acquisition (i.e. the RIP "van"), but with the way the collected data was processed. The final change was to provide guidance on when to use the Roughness Condition Index (RCI) in the PCR calculation. Roughness data is of little value to determining overall condition on routes that, due to their length or geometrics, have lower vehicle operating speeds. Therefore, in Cycle 5, only routes that have lengths of one half mile or greater and posted speed limits of 25 mph or greater will have RCI reported and included in the PCR calculations.

Additionally, methodologies were updated in 2013 for Manually Rated Routes (paved routes that the collection vehicle is unable to drive) as well as Parking Areas to provide more accurate condition data to the HPMA. These updated methodologies allow for the efficient assessment of pavement conditions using a visual inspection method to denote specific distresses. These distresses are indicative of current conditions, the causes for current and future deterioration, and identify the level of targeted repair and rehabilitation practices required.

The changes that were implemented were endorsed by management at both the FHWA and NPS. In order to show the effectiveness of these changes, several sites were ground truth tested in early 2014 to ensure that an improvement was achieved between the relationship of PCR and the actual Maintenance and Rehabilitation needs that were represented. The changes will allow greater use of RIP and HPMA data for not simply condition data reporting, but also as a reliable tool for project identification and selection.

Description of the Rating System

The Federal Highway Administration, National Park Service Road Inventory Program (NPS-RIP), collects roadway condition data on paved surfaces (asphalt, concrete, brick, and cobblestone) on roads, parkways, and parking areas in national parks nationwide. The road surface condition data is collected using an automated Data Collection Vehicle (DCV) and manually using Manually Rated Route (MRR) procedures. Roads having brick or cobblestone surfacing are not normally surveyed with the DCV, but are manually rated for condition rating.

The FHWA RIP is implemented based on the premise that an accurate pavement surface condition assessment can be accomplished using automated crack detection technology as applied to digital images. Various methods of pavement condition assessment have been developed over the years with varying degrees of accuracy and acceptance. The use of digital photography to record pavement images and subsequent crack detection and classification has undergone continuous improvements over the past decade. Digital cameras with increasingly superior resolution and high definition have become more affordable, and the proprietary programming code and algorithms have been improved in crack detection software.

With the use of quality digital photography and automated crack detection software, FHWA RIP is tasked with executing a pavement condition assessment on a network of roughly 5,700 miles of National Park Service roads and parkways. Because a subset of roads will be collected multiple times this cycle, the total collection length will be around 13,000 miles. Foremost in setting up the basis of pavement distress identification is employing the distress identification protocols used by FHWA. There is no single distress identification system that is universal among entities conducting a program of distress identification. For the purpose of the NPS RIP, FHWA employs distress identification protocols that are specific to this program.

FHWA has referenced the "Distress Identification Manual for the Long-Term Pavement Performance Program", Publication No. FHWA-RD 03-031, June 2003, as the point-of- reference for distress types on NPS pavement. In truth, the FHWA RIP distress types are similar to those described in the LTPP manual with some modifications. This document, "Distress Identification Manual for the NPS Road Inventory Program, Cycle 6, 2014-2020" was developed using the "Distress Identification Manual for the Long-Term Pavement Performance Program" as a guideline. Definitions of severity levels based on crack width contained in this document adhere to the LTPP Distress ID Manual. Modifications have been made to the definition of Alligator and Longitudinal Cracking and determination of Alligator Cracking severity. This manual also addresses Rutting and Roughness and its application to RIP.

Cycle 6 has launched in the spring of 2014 and will again comprise all parks, large and small, that are served by paved roads and/or parking areas. For Cycle 6, roughly 333 large and small parks will have all paved routes and parking areas collected at least once in the cycle, some will have multiple collections depending on the size of the park and the functional class of the route.


This "Distress Identification Manual for the NPS Road Inventory Program, Cycle 6, 2014-2020" will be used as a reference resource in crack detection and classification, determination of distress severity and extent, and in the calculation of distress index values for the FHWA RIP Cycle 6.

Explanation of the Condition Descriptions

In addition to the RIP Index changes that were implemented in Cycle 5, we will also aim to provide greater assistance in translating good/fair/poor categories into pavement needs categories. The PCR can be used to indicate the place in the Pavement Life Cycle and the types of treatments that should be considered now and into the future.

- Excellent/New: PCR of 95-100. Pavements in this range will require only spot repairs
- Good: PCR of 85-94. Pavements in this range will likely be candidates for preventive maintenance. Examples include Chip and Slurry Seals, Micro Surfacing and Thin Overlays.
- Fair: PCR of 61-84. Pavements in this range will likely be candidates of Light Rehabilitation (L3R). Examples include single-lift overlays up to 2.5 inches in total thickness, milling and overlays.
- Poor: PCR of 60 or below. Pavements in this range will likely be candidates of Heavy Rehabilitation or Reconstruction (H3R or 4R). Examples include Pulverization, Multiple Lift Overlays, and Reconstruction.

At this time, specific maintenance and rehabilitation activities should be evaluated and recommended at the project level. Site-specific conditions that influence treatment type should be determined based on performing a subsurface investigation and/or pavement condition survey, and not be based solely on RIP data. Additionally, RIP produces a snapshot of conditions the year in which the data was collected. For further information or to obtain additional PMS data from our (HPMA) please contact the Eastern Federal Lands pavement team.



Condition Categories and Treatments

Pavement Age

Description of Pavement Treatment Types

- 1. **Preventive Maintenance** is a planned strategy of cost-effective treatments to an existing roadway system and its appurtenances that preserves the system, retards future deterioration, and maintains or improves the functional condition of the system (without significantly increasing the structural capacity). Preventive maintenance is typically applied to pavements in good condition having significant remaining service life. As a major component of pavement preservation, preventive maintenance is a strategy of extending the service life by applying cost-effective treatments to the surface or near-surface of structurally sound pavements. Examples of preventive treatments include asphalt crack sealing, chip sealing, slurry or micro-surfacing, thin and ultrathin hot-mix asphalt overlay, concrete joint sealing, diamond grinding, dowel-bar retrofit, and isolated, partial and/or full-depth concrete repairs to restore functionality of individual slabs.
- 2. Pavement Rehabilitation consists of structural enhancements that extend the service life of an existing pavement and/or improve its load carrying capacity. Rehabilitation techniques include restoration treatments and structural overlays. Rehabilitation projects extend the life of existing pavement structures either by restoring existing structural capacity through the elimination of age-related, environmental cracking of embrittled pavement surface or by increasing pavement thickness to strengthen existing pavement sections to accommodate existing or projected traffic loading conditions. Two sub-categories result from these distinctions, which are directly related to the restoration or increase of structural capacity.
 - Light Rehabilitation (L3R) Examples include single-lift overlays up to 2.5 inches in total thickness and milling and overlays for flexible pavements
 - Heavy Rehabilitation (H3R) Requires rehabilitation with grade improvement. H3R stands for resurfacing, restoration, and rehabilitation projects. H3R projects typically involve multi-depth (overlays greater than 2.5 inches) pavement improvement work (short of full-depth replacement) and targeted safety improvements. H3R projects generally involve retention of the existing three-dimensional alignment.
- 3. **Reconstruction** (4R) is defined as the replacement of the entire existing pavement structure by the placement of the equivalent or increased pavement structure. Reconstruction usually requires the complete removal and replacement of the existing pavement structure. Reconstruction may utilize either new or recycled materials incorporated into the materials used for the reconstruction of the complete pavement section. Reconstruction is required when a pavement has either failed or has become functionally obsolete.

Appendix A

Methodology for Determining Condition Ratings with the Data Collection Vehicle (DCV)

Surface Distresses Identified by the Data Collection Vehicle

Surface Condition Rating – SCR

Surface distresses are measured in the primary lane only. In the classification and measurement of all paved surface condition data, results will be reported in the database in record intervals of 0.02 miles (105.6 feet) (smallest granularity) along the route.

Surface distresses and rutting are determined from digital images that provide both the longitudinal and transverse profile. The images also provide an elevation profile of the road, creating a 3-dimensional image of the paved surface.

- Transverse Cracks
- Longitudinal Cracks
- Alligator Cracks
- Patching/Potholes
- Rutting

Each of the five surface distresses is assigned a computed surface distress index

- Transverse Crack Index
- Longitudinal Crack Index
- Alligator Crack Index
- Patching/Pothole Index
- Rutting Index

Surface distress data are classified as listed above, measured for severity, and quantified for extent. Classification, severity, and extent of these five surface distresses comprise the three main elements for calculation of Surface Condition Rating (SCR).

In addition to the five surface distresses, a Structural Crack Index is computed, which is a combination of the Longitudinal Crack Index and the Alligator Crack Index. The Structural Crack Index is then used in lieu of the LC and AC indices to compute SCR.

Roughness Condition Index - RCI

Additional condition data measured by DCV (lasers and accelerometers)

• Roughness (IRI)

Roughness is measured by FHWA's DCV and reported as International Roughness Index (IRI) in inches/mile. Using IRI, the Roughness Condition Index (RCI) is computed.

Pavement Condition Rating - PCR

Using the SCR (computed from the five surface distresses) and the RCI, an overall Pavement Condition Rating (PCR) is computed. The formula for PCR is:

Asphalt PCR = (0.60 * SCR) + (0.40 * RCI)Concrete PCR = RCI

A detailed description of each distress index formula, roughness index formula, SCR and PCR is provided in this document.

Each classified surface distress will fall into one or more severity - LOW, MEDIUM, or HIGH based on criteria listed. For each severity, an extent is established based on the measured quantity of the distress within that severity. Within each severity individual distresses are assigned a Maximum Allowable Extent (MAE). For example, LOW severity transverse cracking may be allowed up to 21.1 cracks within a 0.02 mile interval before it reaches MAE and fails.

The index formulas are based on a scale of 0 to 100. A PCR index value of 100 would indicate a "new" road with no measurable distresses or rough ride. A PCR value of 60 is determined to be terminable serviceability and the road is considered failed. The range of index values with condition descriptors is:

POOR = (less than or equal to 60), **FAIR**= (61 – 84), GOOD= (85 - 94), **EXCELLENT**= (95 - 100)

Index values are generally computed based on cumulative deducts of the measured severities. As shown in the index formulas below, as any single severity reaches or exceeds MAE, the index computes to a value of 60 or less, and the road fails for that 0.02 interval.

<u>Note:</u> As a result of a unique combination of measured surface distresses and IRI, index values occasionally compute to less than 0 or greater than 100. In this instance, an index value less than 0 defaults to 0. Index values greater than 100 defaults to 100. For all indices, a higher value indicates a better road condition, and a lower value indicates a poorer road condition.

On the following page, Table 1 summarizes the different types of distresses measured.

ASPHALT-SURFACED PAVEMENT DISTRESS TYPES WITH RUTTING AND ROUGHNESS				
Distress Type	Units Of Measure	Converted To	Defined Severity Levels?	Measured By
Alligator Cracking	Square Feet	Percent of Lane Per 0.02 Mile	Yes	3 Dimensional pavement imaging system
Transverse Cracking	Linear feet	Number of Cracks Per 0.02 Mile	Yes	3 Dimensional pavement imaging system
Longitudinal Cracking	Linear feet	Percent of Lane Length Per 0.02 Mile	Yes	3 Dimensional pavement imaging system
Patching / Potholes	Square Feet	Percent of Lane Per 0.02 Mile	No	3 Dimensional pavement imaging system
Rutting	Inches	Rut Depth Per 0.02 Mile	Yes	3 Dimensional pavement imaging system
Roughness	IRI	*RCI Per 0.02 Mile	No	DCV – Lasers / Accelerometers

*Note: Roughness is measured on concrete roadways, but surface distresses and rutting are not measured. For concrete, PCR = RCI

Table 1. Distress summary

Alligator Cracking

Description:

Alligator cracking is considered a combination of fatigue and block cracking. It is a series of interconnected cracks in various stages of development. Alligator cracking develops into a many-sided pattern that resembles chicken wire or alligator skin. It can occur anywhere in the road lane. Alligator cracking must have a quantifiable area.

Severity Levels:

LOW

An area with little to no interconnecting cracks with no visible spalling. Cracks are less than or equal to a mean width of 0.25 in. (6mm). Cracks in the pattern are no further apart than 1 foot (0.328 m). May be sealed cracks with sealant in good condition and a crack width that cannot be determined.

MEDIUM

An area of interconnected cracks that form a complete pattern. Cracks may be slightly spalled. Cracks are greater than 0.25 in. (6 mm) but less than or equal to 0.75 in. (19 mm) or any crack with a mean width less than or equal to 0.75 in. (19 mm) and adjacent low severity cracking. Cracks in the pattern are no further apart than 6 in. (150 mm).

HIGH

An area of interconnected cracks forming a complete pattern. Cracks are moderately or severely spalled. Cracks are greater than 0.75 in. (19mm) or any crack with a mean width less than or equal to 0.75 in. (19mm) and adjacent medium to high severity random cracking.

A combination of observed crack width and crack pattern is used to determine overall severity of alligator cracking. Based on above description of each severity, the highest level of crack width and crack pattern determines overall severity as shown in Table 2.

ALLIGATOR CRACKING SEVERITY LEVELS				
	CRACK	CRACK PATTERN		
	SEVERITY	LOW	MED	HIGH
	LOW	LOW	MED	HIGH
CRACK WIDTH	MED	MED	MED	HIGH
	HIGH	HIGH	HIGH	HIGH

Table 2. Alligator Crack Severity Levels

Longitudinal Cracking

Description:

Longitudinal cracking occurs predominantly parallel to the pavement centerline. It can occur anywhere within the lane. Longitudinal cracks occurring in the wheelpath may be noteworthy.

Severity Levels:

LOW

Cracks with a mean width less than or equal to 0.25 in. (6 mm). This also includes sealed cracks with sealant in good condition and a width that cannot be determined.

MEDIUM

Cracks with a mean width greater than 0.25 in. (6 mm) but less than 0.75 in. (19 mm). Also, any crack with a mean width less than 0.75 in. (19 mm) and adjacent random low severity cracking.

HIGH

Cracks with a mean width greater than 0.75 in. (19 mm). Also, any crack with a mean width less than 0.75 in. (19 mm) and adjacent random medium to high severity cracking.

Transverse Cracking

Description:

Transverse cracking occurs predominantly perpendicular to the pavement centerline. It can occur anywhere within the lane.

Severity Levels:

LOW

Cracks with a mean width of less than or equal to 0.25 in. (6 mm). Sealed cracks with sealant in good condition and a width that cannot be determined.

MEDIUM

Cracks with a mean width greater 0.25 in. (6 mm) and less than or equal to 0.75 in. (19 mm). Also, any crack with a mean width less than 0.75 in. (19 mm) and adjacent random low severity cracking.

HIGH

Cracks with a mean width greater than 0.75 in. (19 mm). Also, any crack with a mean width less than 0.75 in. (19 mm) and adjacent random medium to high severity cracking.

Patching and Potholes

Description:

Patching is an area of pavement surface that has been removed and replaced with patching material or an area of pavement surface that has had additional patching material applied. Patching may encompass partial lane or full lane width. On full lane width patching; the total, contiguous length of patch may not exceed 0.100 mi. (0.161 km). (Any full-lane patch exceeding 0.100 mi. in length is considered a pavement change). Patching must have a quantifiable area.

Potholes are bowl-shaped holes of various sizes occurring in the pavement surface.

Manhole covers should not be rated as patches unless there is obvious patching around the manhole.

Speed bumps should not be rated as patches

Severity Levels:

There are no stratified severities for Patching and Potholes. They either are present or they are not.

RUTTING

Description:

Rutting is a longitudinal surface depression in the wheelpath.

Severity Levels:

LOW

Ruts with a measured depth of 0.20 inches to 0.49 inches Ruts less than 0.20 in. are not included in the distress calculations.

MEDIUM

Ruts with a measured depth of 0.50 inches to 0.99 inches

HIGH

Ruts with a measured depth greater than 1.00 inch

ROUGHNESS

Description:

Roughness is the measurement of the unevenness of the pavement in the direction of travel. It is measured in units of IRI (International Roughness Index), inches per mile, and is indicative of ride comfort.

Severity Levels:

There are no stratified severity levels for roughness. The roughness (or smoothness) of a road surface can be defined by IRI in the following table.

IRI DESCRIPTIONS		
Type of Road	Typical IRI (in/mile)	
New Road, no noticeable roughness	<90	
Small level of roughness	90 - 126	
Road of average roughness	126 - 190	
Road with above average roughness	190 - 253	
Road with severe roughness	253 - 380	
Nearly impassable	>380	

Table 3. International Roughness Index

Roughness Collection Parameters

On shorter roads with a lower speed limit the usefulness in collecting and reporting IRI is negligible. Lower, inconsistent speeds can lead to a less accurate IRI value. Therefore RIP has put in place the following protocols for reporting IRI.

International Roughness Index (IRI) is not reported on routes with the following criteria:

- Posted speed limit is less than 25 mph
- Length of route is less than 0.50 miles

When a collected route has a posted speed limit of at least 25 mph and length of at least 0.50 miles, IRI will be collected except on road sections where the speed is less than 20 mph

Other situations may arise where the speed and length factors are met, but reporting IRI could lead to an inaccurate PCR. RIP will determine whether or not it is reasonable to report IRI on these routes on a case by case basis.

Index Formulas

Note: All index formulas listed below contain MAE applicable to 0.02 mile (105.6 feet) interval.

Alligator Crack Index

 $AC_INDEX = 100 - 40 * [(\% LOW / 35) + (\% MED / 15) + (\% HI / 5)]$

Where:

The values %LOW, %MED and %HI report the percentage of the observed pavement (0.02 mile, primary lane) that contains alligator cracking within the respective severities. These values range from 0 to 100.

%LOW = Percent of total area (primary lane, 0.02 in length), low severity %MED = Percent of total area (primary lane, 0.02 in length), medium severity %HI = Percent of total area (primary lane, 0.02 in length), high severity

Percent of total area is computed as:

square foot area of alligator crack severity (0.02 mile)*(lane width)

In AC_INDEX, the denominators 35, 15, and 5 are the Maximum Allowable Extents (MAE) for each severity. In other words, we will allow up to 35% of low severity alligator cracking for a 0.02 interval before failure, 15% for medium severity, and so on. As you can see, if any single severity reaches MAE the resulting index value is 60, or failure.

Longitudinal Crack Index

 $LC_INDEX = 100 - 40 * [(\% LOW / 175) + (\% MED / 75) + (\% HI / 25)]$

Where:

The values %LOW, %MED, and %HI report the length of longitudinal cracking within each severity as a percent of the section length (0.02 mile, primary lane). These values are greater than or equal to 0 and can exceed 100.

%LOW = Percent of interval length (primary lane, 0.02 in length), low severity %MED = Percent of interval length (primary lane, 0.02 in length), medium severity %HI = Percent of interval length (primary lane, 0.02 in length), high severity

Percent of interval length is computed as:

length of respective longitudinal cracking (0.02 mile)*(105.6 ft.)

In LC_INDEX, the denominators 175, 75, and 25 are the Maximum Allowable Extents (MAE) for each severity. In other words, we will allow up to 175% of low severity longitudinal cracking for a 0.02 interval before failure, 75% for medium severity, and so on. As you can see, if any single severity reaches MAE the resulting index value is 60, or failure.

Structural Crack Index

 $SC_INDEX = [100 - ((100 - AC_INDEX) + (100 - LC_INDEX))]$

Structural Crack Index is a combination of Alligator Cracking and Longitudinal Cracking, and is used in the SCR formula in lieu of AC and LC separately.

Transverse Crack Index

 $TC_INDEX = 100 - 40 * [(LOW / 21.1) + (MED / 4.4) + (HI / 2.6)]$

Where:

The values LOW, MED and HI report a count of the total number of transverse cracks (reported to three decimals) within each severity level, where one transverse crack is equal to the lane width. These values are greater than or equal to 0.

LOW = Number of cracks in interval (primary lane, 0.02 in length), low severity MED = Number of cracks in interval (primary lane, 0.02 in length), medium severity HI = Number of cracks in interval (primary lane, 0.02 in length), high severity

Number of cracks is computed as:

Total length of transverse cracks Lane width

In TC_INDEX, the denominators 21.1, 4.4, and 2.6 are the Maximum Allowable Extents (MAE) for each severity. In other words, we will allow up to 21.1 low severity transverse cracks for a 0.02 interval before failure, 4.4 cracks for medium severity, and so on. As you can see, if any single severity reaches MAE the resulting index value is 60, or failure.

Patching Index

PATCH_INDEX = (100 - 40) * (% PATCHING / 80)

Where:

The value %PATCHING reports the percentage of the observed pavement (0.02 mile, primary lane) that contains patching/potholes. This value ranges from 0 to 100.

%PATCHING = Percent of total area (primary lane, 0.02 in length)

Percent of total area is computed as:

square foot area of patching/potholes (0.02 mile)*(lane width)

There are no severity levels for patching. It either exists or does not.

There are no severity levels for patching. It either exists or does not. In PATCH_INDEX, the denominator 80 is the Maximum Allowable Extent (MAE) for each severity. In other words, we will allow up to 80% patching for a 0.02 interval before failure. As you can see, if patching/potholes reaches MAE the resulting index value is 60, or failure.

Rutting Index

RUT_INDEX = 100 - 40 * [(% LOW / 535) + (% MED / 205) + (% HI / 40)]

Where:

20 rut depth measurements are taken per 0.02 interval for each of 2 wheel paths (left and right), resulting in a total of 40 measurements taken for both wheel paths. Each wheelpath is analyzed independently for rut severities. The values %LOW, %MED and %HI report the percentage of the 40 measurements within that severity. These values range from 0 to 200.

- %LOW = Percent of LOW ruts in left wheelpath based on 20 ruts, plus percent of LOW ruts in right wheelpath based on 20 ruts.
- %MED = Percent of MED ruts in left wheelpath based on 20 ruts, plus percent of MED ruts in right wheelpath based on 20 ruts.
- %HI = Percent of HI ruts in left wheelpath based on 20 ruts, plus percent of HI ruts in right wheel path based on 20 ruts.

Percent of rut measurements within each severity can also be computed as:

(total number of ruts within each severity in both wheelpaths) 20 × 100

In RUT_INDEX, the denominators 535, 205, and 40 are the Maximum Allowable Extents for each severity; Low, Medium, and High, respectively. Only the MAE for high severity rutting can fail a section, since 200% of *only* low severity ruts would yield a rut index of 85 and 200% of *only* medium severity ruts would yield a rut index of 61.

Roughness Condition Index (Asphalt)

$$\mathbf{RCI} = 32 * [5 * (2.718282^{(-.0041 * AVG IRI)})]$$

Where:

The value AVG IRI reports the average value of the Left IRI and Right IRI measurements for the interval (0.02 mile, primary lane). This value can range from approximately 40 to 999.0.

Average IRI is computed as:

(Left wheelpath IRI) + (Right wheelpath IRI) 2

There is no applicable threshold for failure for this index.

Roughness Condition Index (Concrete)

 $\mathbf{RCI} = (-0.0012)(\mathbf{IRI}^2) + (0.0499)(\mathbf{IRI}) + 99.542$

For concrete, PCR = RCI

Surface Condition Rating Index

SCR = Lowest Index Value Of: [SC_INDEX, TC_INDEX, PATCH_INDEX, RUT_INDEX]

Note: The modified SCR equation above combines AC_INDEX and LC_INDEX, and considers that a single AC/LC index value of the Structural Crack Index (SC_INDEX). The lowest of the four computed index values (SC_INDEX, TC_INDEX, PATCH_INDEX, or RUT_INDEX) becomes the SCR.

Where:

See above for determinations of SC_INDEX, TC_INDEX, PATCH_INDEX and RUT_INDEX.

The threshold for failure for this index is SCR = 60.Data Collection Vehicle Subsystems

Data on paved roads is collected by FHWA using a Pathway Services Inc. Data Collection Vehicle (DCV), called a PathRunner. The DCV is driven in the primary-direction lane at posted speed limits and less.

Cameras

Forward-facing and rear-facing video is collected as jpeg digital imagery files at a frequency of every 26.4feet.

Two forward-facing cameras are mounted above the vehicle cab, one pointed straight ahead and the other to the right shoulder providing seamless roughly 120 degree viewing. A third camera is mounted in the rear of the vehicle, recording the left shoulder.

CAMERA SPECIFICATIONS TWO FORWARD / ONE REAR FACING CAMERA		
Camera lens/type	Prosilica GT 2750 (GigE Technology)	
Image format	*.jpg	
Image resolution	2750 x 2200, 18 frames/second	
Image pixel size	depends on distance	
Zoom ratio	16mm Fixed	
	Aperture Range F 1.8 – Infinity (P-Iris,	
Iris range	Automatic	

Pavement Imaging and Rutting

High resolution rutting data and surface imaging are collected in a single data stream using a threedimensional (3D) pavement surface transverse profile data acquisition system. The 3D camera captures a laser line as it is projected over the pavement surface and uses the location of this line to measure the height deviations of the pavement surface. These height deviations can be used to calculate rutting in both wheelpaths. These deviations also provide a grayscale image detailing the change in height throughout the surface, i.e. providing depth measurements for cracking.

PAVEMENT SURFACE AND TRANSVERSE PROFILE DATA ACQUISITION SYSTEM		
Surface Image Specifications		
Image size	1536 pixels/scan @3000 Hz	
Image width	4 meters (3950 mm nominal)	
Laser class	3B	
Power	16W (Two lasers @ 8W Ea)	
Vehicle speed limitations	62 mph	
Environment	Dry pavement, day or night	
Sensor size (approximate)	1536 pixels x 512 pixels	
Image display length	26.4 feet	
Rutting Specifications		
Reported rut depth units	Inches	
Vehicle speed limitations	Up to 62 mph	
Sampling rate	3000 profiles/second	
Transverse resolution	1536 points/profile	
Transverse field-of-view	14 feet	
Depth accuracy (nominal)	<1mm	
Environment	Dry pavement, day or night, above 32 degrees F	
Adherence to specifications	ASTM E1703M-95 (reapproved 2005)	

THREE-DIMENSIONAL

Distance Measuring Instrument (DMI)

The DMI (Distance Measuring Instrument) obtains road length measurements that are accurate to 0.15%for speeds up to 60 mph. The DMI is connected to the hub of the rear wheel on the driver's side, and is calibrated to the revolutions of the rear vehicle axle on a regular basis.

Roughness (IRI)

IRI SPECIFICATIONS		
Reported IRI units	Inches/mile	
Vehicle speed limitations	12-62 mph	
IRI equipment certification	Texas Transportation Institute (TTI)	
Wavelengths accommodated	0.5 feet to 300 feet	
IRI computed & reported	World Bank Technical Paper Number 46	
Environment	Dry pavement, day or night, above 32 degrees	
Adherence to specifications	ASTM E950 Class 1 & AASHTO M 328	

The collection system includes a South Dakota type laser profiler manufactured based on active Class 1 ASTM E950 standards. The dynamic profile of the pavement surface is collected from which the IRI roughness data is computed. The sensors include one accelerometer on each wheelpath, one height sensor (laser) on each wheelpath, and a distance transducer.

GPS & Inertial Systems

GPS is collected by an onboard system employing Omnistar real time correction and a spinning gyroscope to provide accurate positioning data in instances of satellite obstruction. All GPS coordinates are tied to an image and linear distance measurements.

GPS SPECIFICATIONS		
Static accuracy	Sub-meter	
Dynamic accuracy	2-3 meters	
Receiver	12 satellite tracking	
Coordinate system	Lat Lon WGS 84	
Environment	Day or night	
Cross-slope	± 1.75%	
Grade	± 1.75%	
Adherence to specifications	ASTM E1703M-95 (reapproved 2005)	

*NOTE – GPS accuracy is dependent on many different factors. Satellite constellation, tree coverage, GPS receiver quality, and real-time correction availability can all affect the locational and elevation accuracies. The elevation (z coordinate) accuracy is less dependable than locational or horizontal accuracy (x/y coordinates or latitude/longitude). In areas of heavy tree coverage or poor satellite constellations, elevation data can vary by as much as +/- 100 feet.

Appendix B

Methodology for Determining Condition Ratings Using Manual Rating Procedures

Description of Manual Rating Methods

In 2013, the Federal Highway Administration updated existing Manual Rating Procedures in an effort to better align pavement conditions for Manually Rated Routes and Parking with the Highway Pavement Management Application (HPMA). HPMA is the Pavement Management System used by the FHWA to store inventory and condition data from the Road Inventory Program (RIP) and forecast future performance using prediction models. HPMA uses pavement condition data (collected by the Road Inventory Program) to develop life cycles for pavements and recommend treatments to maximize useable pavement life while minimizing costs associated with maintenance and repair.

The Federal Highway Administration (FHWA) developed a set of manual rating methods for pavement that are appropriate for Federal Roadways. Two different methods were developed for linear roads and a separate method was developed for parking areas and nonlinear roads. These methods employ a 0 to 100 rating scale and improve consistency and objectivity in the manual evaluation of surface distresses. They are compatible with ratings that are collected by the automated Data Collection Vehicle (DCV).

- The first of the two manual evaluation methods for roads uses rating criteria to assign index values to each distress type based on a visual evaluation of severity and extent.
- The second manual evaluation method for roads is very time demanding and is best employed on only a select set of routes which may have the highest visitor use and require a more intensive assessment. This method will be used for the Manual Rating of Function Class 1, 2, 7, and 8 Roads. This method is based on measurements that are recorded for each instance of a surface distress. These measurements are converted into index values using conversion formulas.
- Parking areas and non-linear roads are rated similar to the first method shown above, however, there are some slight differences due to the non-linear nature.

The details and criteria used for each of these rating methods are outlined below.

Visual Inspection Method for Manually Rating Secondary Roads

The visual inspection method for manually rated roads uses condition rating criteria that have been developed by FHWA. This criteria is based on a visual evaluation of the severity and extent of distresses to determine the overall condition of the roadway. This method is used for secondary roads that are Functional Class 3, 4, 5, and 6. This constitutes the majority of manually rated roads collected by the Road Inventory Program.

Rating Section Lengths

For this method, Manually Rated Roads are rated in sections. These sections may be made based on length of changes in surface type or condition as described below. The ratings are then aggregated to give an overall rating for the Route:

- Rating sections should be no longer than 0.25 miles in order to keep the area being rated manageable.
- A new rating section may be started based on changes in condition, width, or surface type if these changes represent a significant portion of the route (are not isolated instances).
- If the road condition, width, and surface type remain constant then new sections do not need to be created unless the road exceeds 0.25 miles.

Rating Criteria

For this method, Manually Rated Roads are evaluated using a visual inspection of the six distress types listed below. Each distress is assigned one of five index values. An overall Surface Condition Rating (SCR) and Pavement Condition Rating (PCR) are calculated based on these index values.

- Alligator Cracking
 - o Rating based on percentage of road surface affected
- Longitudinal Cracking
 - o Rating based on severity level (crack width) and percentage of road section length of longitudinal cracks
- Transverse Cracking
 - o Rating based on crack width, crack spacing, and percentage of surface affected
- Patching
 - o Rating based on percentage of road surface affected
- Rutting
 - o Rating based on percentage of road section length affected by visible rutting (>1 inch depth) that requires remediation
- Roughness
 - o Manual assessments of roughness are not made due to the subjectivity of the measurement. Therefore, roughness is not incorporated into the PCR calculation of manually rated roads.

Concrete Routes also receive a PCR rating based on visual evaluation of the following six distress types.

- Slab Faulting at Joints
- Slab Cracking and breakup
- Surface Delamination and Pop-outs
- Joint Distresses
- Patching

Distress Measurement Method for Manually Rating Primary Roads

A more intensive and time demanding assessment than our standard method was developed for Primary roads that are functional class 1, 2, 7, or 8. These high visitation roads are usually accessible by the automated Data Collection Vehicle but in rare instances may need to be manually rated. The method developed is based on measuring each instance of a distress. These measurements are totaled over each section length being measured and are then converted into index values between 0 and 100 (100 being a road with no distress) using index formula equations outlined below. The goal of this method is to produce measured index values which are directly comparable to the automated DCV.

Rating Section Lengths

For the distress measurement method roads are broken into sections in order to rate. Distress measurements are totaled for each section separately in order to determine the index value for that particular section. The section length to be rated is determined based on the following rules:

- Rating sections are between 0.25 and 0.50 miles long
- A new rating section is created if there is a significant change in condition or pavement width
- If there are no significant changes in condition or pavement width, rating sections are broken at equal intervals, typically 0.50 miles

Manual Distress Measurements

Alligator Cracking

- Alligator cracking is measured by area (square feet). Instances of Alligator cracking are measured along the length and multiplied by the average width of the distressed area.
- The index for alligator cracking takes the total area of cracking compared to the interval length and converts it to a percentage. That percentage is then input into an index formula that yields a value between 0 and 100 (0 being the most distressed).
- Severity levels are not defined for manually measured Alligator cracks. The Alligator Crack Index formula is calculated based on an assumption of medium severity.

Longitudinal Cracking

- Longitudinal cracking (cracking in the direction parallel to the roadway) is measured by length (ft.).
- The index for longitudinal cracking takes the total length of cracking compared to the interval length and converts it to a percentage broken down by severity. That percentage is then input into a formula that yields a value between 0 and 100 (0 being the most distressed).
- Two severity levels are defined for manually measured Longitudinal Cracks. Lower severity cracks are those with a mean width of less than 0.25 inches. Sealed cracks with sealant in good condition are also considered lower severity. Higher severity cracks are those with a mean width of greater than 0.25 inches.

Transverse Cracking

- Transverse cracking (cracking in the direction perpendicular to the roadway) is measured by length (ft).
- The index for transverse cracking takes the total number of cracks (1 crack would encompass the full lane) broken down by severity. The total numbers of each severity are then put into a formula that yields a value between 0 and 100 (0 being the most distressed).
- Two severity levels are defined for manually measured Transverse Cracks. Lower severity cracks are those with a mean width of less than or equal to 0.25 inches. Sealed cracks with sealant in

good condition are also considered lower severity. Higher severity cracks are those with a mean width of greater than 0.25 inches.

Patching and Potholes

- Patching and Potholes are measured by area (square feet). Instances of Patching are measured along the length and multiplied by the average width of the patch.
- Instances of full lane width patching cannot be longer than 0.100 miles, otherwise is should be considered a pavement change rather than a distress.
- There are no stratified severities for Patching. It is either present or it is not.

Rutting

- Visible rutting is measured by length (ft.) in each wheel path. Only visible ruts are rated, which are ruts greater than 1 inch deep.
- All rutting recorded in a manual rating is considered to be high severity (> 1 inch). Lesser severities are generally not distinguishable in a visual inspection.

Roughness

• Manual assessments of roughness are not made due to the subjectivity of the measurement. Therefore, roughness is not incorporated into the PCR calculation of manually rated roads.

Index Formulas for Distress Measurement Method:

The method used to convert distress measurements into index values is shown below. The Surface Condition Rating and Pavement Condition Rating are calculated based on these index values.

Alligator Crack Index for Manual Rating:

AC_INDEX = 100 - 40 * (% ALLIGATOR / 15)

Where:

%ALLIGATOR = Percent of total area of section being rated that contains Alligator cracking.

Longitudinal Crack Index for Manual Rating:

 $LC_INDEX = 100 - 40 * [(\%LOW / 175) + (\%MED / 75)]$

Where:

%LOW = Percent length of longitudinal cracks where crack width less than or equal to 0.25 inches

%HIGH = Percent length of longitudinal cracks where crack width greater than 0.25 inches

Transverse Crack Index for Manual Rating:

 $TC_INDEX = (100 - 40) * [(LOW / 21.1) + (MED / 4.4)]$

Where:

LOW = Count of the total number of transverse cracks within the section length whereone transverse crack is equal to the lane width and the crack width <= 0.25 inchesHIGH = Count of the total number of transverse cracks within the section length whereone transverse crack is equal to the lane width and the crack width > 0.25 inches Number of cracks is computed as: Total length of transverse cracks/Lane width

Patching Index for Manual Rating:

PATCH_INDEX =(100 – 40) * (% PATCHING / 80)

Where:

%PATCHING = Percentage of pavement section that contains patching/potholes.

Rutting Index for Manual Rating:

RUT_INDEX = 100 - 40 * (% RUTTING / 40)

Where:

%RUTTING = Percentage length of high severity rutting within the section being measured.

Method for Manually Rating Paved Parking Areas and Non-Linear Roads

Parking areas are evaluated based on a visual inspection using condition rating criteria that has been developed by FHWA. This criteria is based on a visual evaluation of the severity and extent of distresses to determine the overall condition of the parking area. This overall condition rating is linked to the level of repair and rehabilitation practices required.

A distress index is determined for each of the distresses listed below for Asphalt and Concrete Parking areas. The overall Pavement Condition Rating (PCR) of the parking lot is driven by the most severe distress present.

Rating Criteria:

Asphalt Parking Distress Types

- Alligator Cracking
 - o Rating based on percentage of road surface affected
- Longitudinal, Transverse and Block cracking
 - o Rating based on crack width, crack spacing, and percentage of surface affected
- Rutting and Distortions
 - o Rating based on percentage of road surface affected
- Hot Mix Asphalt Patches
 - o Rating based on overall percentage of HMA patches
- Potholes and Cold Patches
 - o Rating based on percentage of road surface affected
- Surface Raveling and Bleeding
 - o Rating based on percentage of road surface affected

Concrete Parking Distress Types

- Slab Faulting at Joints
 - o Rating based on height differential between adjacent slabs or pieces of broken slabs
- Slab Cracking and breakup
 - o Rating based on quantity of cracks and if slab is acting to able distribute load as designed
- Surface Delamination and Pop-outs
 - o Rating based on percentage of road surface affected to include pop-outs, spalls and surface delamination
- Joint Distresses
 - o Rating based on sealant condition and concrete distresses at/or adjacent to joints
- Patching
 - o Rating based on percentage of road surface affected

Curb Inspection and Treatments

During inspections of manually rated parking lots and routes, the curb reveal and overall curb condition are evaluated. The curb condition is used to determine a recommendation.

Curb Reveal

The vertical distance on the curb face from the gutter flow line or pavement surface to the top of curb. When resurfacing adjacent to curb, the resulting curb reveal should be no less than 4 inches. Additionally, when resurfacing adjacent to a gutter, the resulting pavement surface should be flush with the gutter pan. In cases where a resurfacing would violate either of these parameters, the surface may need to be milled or removed to adjust to these field conditions.

Curb Recommendations

The following treatment categories are based on the overall percentage of distresses along the entire curb structure for a specific pavement structure. Distresses include spalling, cracking, loss of material and any other damage which prevents the curb from conveying storm runoff or failing to perform in its intended function.

- Overall curb damage ranging 0%-5%: o DO NOTHING
- Overall curb damage ranging 5%-20% o LIGHT REPAIR
- Overall curb damage ranging 20%-50% o MODERATE REPAIR
- Overall curb damage greater than 50%: o REPLACE

GPS for Manually Rated Roads and Parking

GPS information for Manually Collected Cycle 6 Routes will be recorded using the latest hardware and software by TRIMBLE 6000 Series GeoXT. Cycle 6 GPS collection units will allow access to GPS and GLONASS, improving overall GPS reliability, accuracy and precision to submeter accuracy. Additionally, the new GPS units have an enhanced ability to collect accurate signals underneath tree cover or adjacent to buildings or natural terrain with extreme vertical gradations that typically reduce GPS accuracy. Trees and buildings create "satellite shadows", limiting the areas where you can reliably collect high-accuracy GPS data. The updated GPS receiver will deliver improved usable data under tree canopy or in natural or urban canyons. Routes that were previously collected accurately will not be recollected in Cycle 6.

TRIMBLE 6000 SERIES GeoXT GPS SPECIFICATIONS		
Receiver	Trimble Maxwell [™] 6 GNSS chipset	
Channels	220 channels	
Systems	GPS / GLONASS / WAAS	
Accuracy	Sub-meter	
Operation Temperature	-20 °C to +60 °C (-4 °F to +140 °F)	
Cellular and Wireless	UMTS / HSDPA / GPRS / EDGE / Wi-Fi / Bluetooth	
Internal Still Camera w/ GEOTAG ability	Autofocus 5 MP (JPG) and WMV w/ Audio	

Appendix C Description of Cycle 6 Deliverables

Final Report Delivery

The Final Report will contain all data collected by Manual Inspection and the Data Collection Vehicle. All information provided in the Interim Report will be included in the Final report. Manually collected information reported in the Interim Report may be updated in the Final Report if pavement conditions have substantially changed between the Manual Inspection and Data Collection Vehicle Inspection or other unforeseen circumstances.

The final report will be released approximately 8 months after the Data Collection Vehicle completes its collection of that specific park.

Data included in the Final Report package consists of the following:

- Condition Photos: All photos taken during Cycle 6.
- **Data Video:** Data and video of each route collected by the DCV will viewable through PATHVIEW software. PATHVIEW Software and training will be provided to NPS personnel by Eastern Federal Lands.
- **GPS on All Rated Routes:** All GPS data collected from the DCV will be provided. Parking areas, some roads, and other paved areas that are not fully drivable with the DCV are collected manually by field technicians. GPS is collected for these routes using portable Trimble GPS units.
 - o GPS will be provided as Shapefiles and KMLs
 - o All GPS data related to road collection with be linear referenced to the collected length
- **Geodatabase Background and Metadata:** In addition to this park report, a geodatabase containing both tabular and spatial data specific to this park has been provided.
 - All data disseminated in the preceding report has been obtained from the tables and fields within said geodatabase. The geodatabase can be referenced for tabular data via Microsoft Access or for both tabular and spatial data via ESRI's ArcGIS Suite of software which consists of; ArcMap, ArcCatalog and ArcExplorer.
 - Consolidating the RIP data into one database creates a seamless relationship of tables and geographic data. It allows RIP to facilitate easier updates and enhancements in the future. A geodatabase can be thought of as simply a database containing spatial data. A complete and thorough description of the tables and fields contained within this geodatabase can be found in the metadata. The metadata is attached directly within the geodatabase and can be accessed via ESRI's ArcCatalog.
- **Report (RIP Report and Route ID):** A PDF report will be provided that includes a list of all routes and key data. Condition reports for each route will be included. All changes, additions and deletions to any route will be included in the report. Features along routes will not be collected in Cycle 6.

Partial DCV Collections

Additional Partial DCV Collections may be done on specific parks depending on their size and overall mileage of routes within its boundaries during Cycle 6. Parks with greater than 10 miles of paved roadways will receive at least one additional Partial DCV collection during Cycle 6. Data collected during these Partial DCV Collections will not result in the delivery of an additional report to the park.

Data collected by the DCV during Partial DCV Collection will be used to improve HPMA modeling by providing additional "snapshots in time" of park pavement conditions. This improved HMPA modeling will assist in the programing and budgeting of future projects which will help maximize the life of pavement infrastructures.

Instead of receiving a report of conditions collected during the Partial DCV collection, the park will receive a formal letter from the Road Inventory Program requesting coordination for the additional Partial DCV collection, identifying the dates of the Partial DCV Collection and will reinforce the purpose and importance of the Partial DCV Collection.

Appendix D

Glossary of Terms and Abbreviations

Glossary of Terms and Abbreviations

TERM OR ABBREVIATION	DESCRIPTION OR DEFINITION
AC	Alligator Cracking
CRS	Condition Rating Sheets (Section 5)
Curb Recommendation	Curb remediation based on overall percentage of curb distress
Curb Reveal	Height of curb exposed from gutter flow line to top of curb
DCV	Data Collection Vehicle
Excellent	Excellent rating with an index value of 95 to 100
Fair	Fair rating with an index value from 61 to 84
FUNCT_CLASS	Functional Classification (see Route ID, Section 2)
Good	Good rating with an index value from 85 to 94
IRI	International Roughness Index
HPMA	Highway Pavement Management Application
Lane Width	Width from road centerline to fogline, or from centerline to edge- of-pavement when no fogline exists
LC	Longitudinal Cracking
MRR	Manually Rated Route
MRL	Manually Rated Line
MRP	Manually Rated Polygon
N/A	Not Applicable
NC	Not Collected
РАТСН	Patching and Potholes
Paved Width	Width from edge-of-pavement to edge-of-pavement
PCR	Pavement Condition Rating
PKG	Parking Area
Poor	Poor rating with an index value of 0 to 60
RCI	Roughness Condition Index
SC	Structural Cracking
SCR	Surface Condition Rating
ТС	Transverse Cracking