
GLAC Cycle 6

Final Report

Road Inventory and Condition Assessment of Paved Routes Glacier National Park







Federal Lands Highway
Road Inventory Program

Prepared By:

Federal Highway Administration Eastern Federal Lands Highway Division Road Inventory Program (RIP)

Report Date: February 2017

Glacier National Park in Montana






Table of Contents

| SEC | TION | PAGE NO |
|-----|---|------------------|
| 1. | INTRODUCTION | 1-1 |
| 2. | PARK ROUTE INVENTORY | |
| | Route ID Report, Subcomponent Report, and Changes Report (As Applicable) | 2 - 1 |
| 3. | PARK SUMMARY INFORMATION | |
| | Parkwide Paved Route Condition Summary | 3 - 1 |
| | Explanation of Condition Descriptions | 3 - 2 |
| | Route-Level Condition Summary Reports for Data Collection Vehicle, Manually Rated, and Parking Area Routes (As Applicable) | 3 - 3 |
| 4. | PARK ROUTE LOCATION MAPS | |
| | Route Location Key Map | 4 - 1 |
| | Route Location Area Map(s) | 4 - 2 |
| | Route Condition Key Map – PCR Mile by Mile Route Condition Area Map(s) – PCR Mile by Mile | 4 - 17 4 - 18 |
| 5. | PAVED ROAD CONDITION RATING SHEETS | |
| | Paved Road Pages | 5 - 1 |
| 6. | PAVED PARKING AREA CONDITION RATING SHEETS | |
| | Paved Parking Area Pages | 6 - 1 |
| 7. | ROAD MILEPOST INFORMATION | |
| | Road Milepost Information and Logs | 7 - 1 |
| 8. | APPENDIX | |
| | Improvements to the RIP Index Equations and Determination of PCR | 8 - 1 |
| | Description of the Rating System | 8 - 2 |
| | Explanation of the Condition Descriptions | 8 - 3 |
| | Description of Pavement Treatment Types | 8 - 4 |
| | Appendix A: Methodology for Determining Condition Ratings with the Data Collection Vehicle (DCV) | 8 - 5 |
| | Appendix B: Methodology for Determining Condition Ratings Using Manual Rating Procedures | 8 - 20 |
| | Appendix C: Description of Cycle 6 Deliverables | 8 - 29 |
| | Appendix D: Glossary of Terms and Abbreviations | 8 - 33 |

Section 1 Introduction





Introduction

The Federal Highway Administration's (FHWA), Road Inventory Program (RIP) inventories all roads and parking areas in the National Park System, and performs condition inspections on all paved roads and parking areas for the National Park Service (NPS). This report contains the results of the Cycle 6 condition assessment of paved roads and parking lots for this park unit. This assessment was done using an automated, state-of-the-art pavement inspection vehicle as well as manual ratings. This information represents the condition of the paved assets at the time of the inspection. The pavement management system utilized by FHWA and the NPS uses these assessments to estimate future conditions and help prioritize pavement maintenance and rehabilitation projects. Further information about RIP data and its role in managing paved roads and bridges can be obtained by contacting the NPS Regional Transportation Program Manager.

A History of the Road Inventory Program:

The FHWA, in the mid-1970s, was charged with the task of identifying surface condition deficiencies and corrective priorities on NPS roads and parkways. Additionally, FHWA was tasked with establishing an integrated maintenance features inventory, locating features such as culverts, guardrails, and signs, among others, along NPS roads and parkways. As a result, in 1976 the NPS and FHWA entered into a Memorandum of Agreement (MOA) which established the RIP. This MOA was revised in 1980 to update RIP data collection standards and develop a long-range program to improve and maintain NPS roads to designated condition standards and establish a pavement management program.

The FHWA completed the initial phase of inventory in the early 1980s. As a result of this effort, each NPS unit included in the collection received a RIP Report known as the "Brown Book" which contained information that was inventoried during this first RIP phase. In the 1990s, a cyclical program was developed, and since then five cycles of collection have been completed. Cycle 6 is currently in progress. A summary of the RIP collection cycles is shown in the table below.

| Cycle | Years | Parks Collected |
|---------|-----------------|--|
| Cycle 1 | 1994 - 1997 | ° 44 Large Parks |
| Cycle 2 | 1997 - 2001 | 79 Large Parks5 Small Parks |
| Cycle 3 | 2001 - 2004 | All Large ParksAll Small Parks |
| Cycle 4 | 2006 - 2010 | 86 Large ParksSeveral Small Parks |
| Cycle 5 | 2010 - 2014 | All Large Parks (Only functional class 1, 2, 7, and new/modified routes collected) All Small Parks (all roads and parking areas collected) |
| Cycle 6 | 2014 – 2020 (±) | All roads and parking areas collected at all Parks Additional partial collections of functional class 1, 2, and 7 roads at Large Parks Cycle 6 is expected to last 6 years |

Note: Large Parks have ≥ 10 Paved Miles; Small Parks have < 10 Paved Miles

Since 1984, the Road Inventory Program has been funded through the Federal Lands Highway Park Roads and Parkways (PRP) Program. Currently, coordination of the RIP with Federal Lands Highway (FLH) is under the NPS Washington Headquarters Park Facility Management Division. The FLH Washington office coordinates policy and prepares national reports and needs assessment studies for Congress.

In 1998, the Transportation Equity Act for the 21st Century (TEA-21) amended Title 23 U.S.C., and inserted Section 204(a)(6) requiring the FHWA and NPS, to develop by rule, a Pavement Management System (PMS) applied to park roads and parkways serving the National Park System.

In 2012, the Moving Ahead for Progress in the 21st Century Act (MAP-21) amended Title 23 U.S.C., and under Section 203(c)(1-2) stated that the National Park Service in cooperation with the DOT/FHWA, shall maintain a comprehensive national inventory of their transportation facilities, with the goal of quantifying transportation infrastructure needs within the National Park System.

A History of the Pavement Management System:

In 2005, the FHWA began implementing the use of a pavement management system to assist the NPS in prioritizing Pavement Maintenance and Rehabilitation activities. The system used by FHWA is the Highway Pavement Management Application (HPMA), which has the ability to store inventory and condition data from RIP and forecast future performance using prediction models. Outputs include performance and condition reports at the National, Regional, Park, or Route level. Regional prioritized lists and optimizations have been produced for most regions, and the Service's overall roadway Deferred Maintenance is calculated via the HPMA.

Overview of Cycle 6:

Cycle 6 launched in the spring of 2014 and will again comprise all NPS park units that are served by paved roads and/or parking areas. For Cycle 6, all paved roads (approximately 5,700 miles) and parking areas will be collected in all parks at least once, while the primary routes (functional class 1, 2, and 7 roads) at Large Parks will have additional collections. These multiple collections will provide updated condition data on a majority of the NPS's primary road network and help build a better pavement management system, allowing for more accurate pavement performance prediction models.

FLH is responsible for the accuracy of all data presented in this report. Any questions or comments concerning the contents of this report should be directed to the national RIP Coordinator located in Sterling, Virginia.

Respectfully,

FHWA RIP Team

FHWA/Eastern Federal Lands 21400 Ridgetop Circle Sterling, VA 20166 (571) 434-1574 FHWA/Central Federal Lands 12300 West Dakota Ave Lakewood, CO 80228 (720) 963-3556

Section 2 Park Route Inventory





Page 1 of 28

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 02/27/2017

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

| | | | _ | | | ROAD INVENTORY (| 1100 SERIES FMSS | LOCATION | S) | | | | | | | |
|--------------|--------------------|------------------------|----------------|------------|---|--|---|-------------------------|--------|----------------|------------------|------------------|---------------------|-----------------|---------------|---------------------|
| Route No. | Cycle Collected | lteration Collected | FMSS Number | Concession | Route Name | Route Desc | | Maintenance District | FITP (| Paved Miles | Unpaved Miles | Total Mileage | Functional Class | Area (SQ FT) | Surf. Type | Area Map |
| 0010E | 6 | 1 | 5729 | | GOING TO THE SUN ROAD EAST | FROM LOGAN PASS AT END OF ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 31.86 | TO END OF DIVIDE CREEK BRIDGE AT MP 49.86 / EAST PARK BOUNDARY IN ST. MARY | HUDSON BAY | YES | 18.00 | 0.00 | 18.00 | 1 | | AS | 2,3,3A,3 B |
| 0010W | 6 | 1 | 6763 | | GOING TO THE SUN ROAD WEST | FROM END OF BRIDGE IN WEST GLACIER / WEST PARK BOUNDARY | TO LOGAN PASS AT BEGINNING OF ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 31.86 | WEST LAKE | YES | 31.86 | 0.00 | 31.86 | 1 | | AS | 1,1A,1B, 1D,2,2A |
| 0011 | 6 | 1 | 6821 | | CAMAS ROAD | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 1.73 | TO END OF NORTH FORK BRIDGE / WEST PARK BOUNDARY | WEST LAKE | YES | 11.58 | 0.00 | 11.58 | 1 | | AS | 1,1B,1C |
| 0012 | 6 | 1 | 6791 | | TWO MEDICINE ROAD | FROM U.S. HIGHWAY 49 | TO ROUTE 0965 (TWO MEDICINE STORE PARKING) | HUDSON BAY | YES | 7.28 | 0.00 | 7.28 | 1 | | AS | 5,5A |
| 0013 | 6 | 1 | 6781 | | CHIEF MOUNTAIN INTERNATIONAL HIGHWAY | FROM U.S. HIGHWAY 89 | TO UNITED STATES - CANADA BORDER / PARK BOUNDARY | HUDSON BAY | YES | 14.25 | 0.00 | 14.25 | 1 | | AS | 4 |
| 0014 | 6 | 1 | 6783 | | MANY GLACIER ROAD | FROM U.S. HIGHWAY 89 | TO ROUTE 0974 (SWIFTCURRENT MOTOR INN PARKING) | HUDSON BAY | YES | 12.44 | 0.00 | 12.44 | 1 | | AS | 4,4A |
| 0100A | 6 | 1 | 6823 | | FISH CREEK ACCESS ROAD | FROM ROUTE 0011 (CAMAS ROAD) AT MP 1.31 | TO END OF LOOP AT ROUTE 0100B (INSIDE NORTH FORK ROAD) | WEST LAKE | YES | 1.16 | 0.00 | 1.16 | 2 | | AS | 1C |
| 0100B | NC | | 6829 | | INSIDE NORTH FORK ROAD | FROM ROUTE 0100A (FISH CREEK ACCESS ROAD) | TO END OF LOOP AT KINTLA CAMPGROUND | WEST LAKE | NO | 0.00 | 39.40 | 39.40 | 2 | | GR | |
| 0101 | 6 | 1 | 6807 | | APGAR LOOP ROAD | FROM ROUTE 0011 (CAMAS ROAD) AT MP 0.32 | TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 2.57 | WEST LAKE | YES | 1.11 | 0.00 | 1.11 | 2 | | AS | 1 B |
| 0102 | 6 | 1 | 6769 | | ST. MARY RANGER STATION ROAD | FROM ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 49.66 | TO ROUTE 0982 (ST. MARY BONE YARD PARKING) | HUDSON BAY | YES | 0.91 | 0.00 | 0.91 | 2 | | AS | 3В |

Page 2 of 28

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 02/27/2017

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas
NC = Not Collected

GLAC

| | | | | 5 | | ROAD INVENTORY (| 1100 SERIES FMSS | LOCATION | S) | | | | <u> </u> | | | |
|--------------|--------------------|------------------------|----------------|-----------|--|---|---|-------------------------|------|----------------|------------------|------------------|----------|-----------------|---------------|-------------|
| Route No. | Cycle Collected | Iteration Collected | FMSS Number | Concessio | Route Name | Route Desc | cription To | Maintenance District | FLTP | Paved Miles | Unpaved Miles | Total Mileage | | Area (SQ FT) | Surf. Type | Area Map |
| 0200 | 6 | 1 | 6816 | | LAKE MCDONALD LODGE LOOP ROAD | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 10.76 | TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 10.31 | WEST LAKE | YES | 0.53 | 0.00 | 0.53 | 2 | | AS | 1D |
| 0201 | 6 | 1 | 37315 | | AVALANCHE CAMPGROUND ENTRANCE ROAD | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 16.20 | TO BEGINNING OF ROUTE 0201B (AVALANCHE CAMPGROUND LOOP B) | WEST LAKE | YES | 0.26 | 0.00 | 0.26 | 3 | | AS | 2A |
| 0201A | 6 | 1 | 37336 | | AVALANCHE CAMPGROUND LOOP A | FROM ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) AT MP 0.19 | TO ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) AT MP 0.14 | WEST LAKE | YES | 0.36 | 0.00 | 0.36 | 3 | | AS | 2A |
| 02018 | 6 | 1 | 38439 | | AVALANCHE CAMPGROUND LOOP B | FROM ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) AT MP 0.26 | TO ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) AT MP 0.23 | WEST LAKE | YES | 0.27 | 0.00 | 0.27 | 3 | | AS | 2A |
| 0201CZZ | 6 | 1 | 38749 | | AVALANCHE CAMPGROUND SERVICE ROAD AND SPUR | FROM ROUTE 0201A (AVALANCHE CAMPGROUND LOOP A) AND ROUTE 0934D (AVALANCHE CAMPGROUND HANDICAPPED PARKING (TRAIL OF THE CEDARS)) | TO DEAD END AT TRAIL OF THE CEDARS | WEST LAKE | NO | 0.22 | 0.00 | 0.22 | 6 | | AS | 2A |
| 0202 | 6 | 1 | 37354 | | NORTH LAKE MCDONALD ROAD (KELLY CAMP) | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 12.13 | TO END OF UNPAVED SECTION | WEST LAKE | YES | 0.41 | 1.68 | 2.09 | 2 | | AS | 1 |
| 0204 | 6 | 1 | 6812 | | FISH CREEK CAMPGROUND ENTRANCE ROAD | FROM ROUTE 0100A (FISH CREEK ACCESS ROAD) | TO INTERSECTION OF ROUTE 0204C (FISH CREEK CAMPGROUND LOOP C) ON LEFT AND ROUTE 0204D (FISH CREEK CAMPGROUND LOOP D) | WEST LAKE | YES | 0.31 | 0.00 | 0.31 | 3 | | AS | 1C |
| 0204A | 6 | 1 | 103567 | | FISH CREEK CAMPGROUND LOOP A | FROM ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD) | TO END OF LOOP | WEST LAKE | YES | 0.26 | 0.00 | 0.26 | 3 | | AS | 1C |

Page 3 of 28

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 02/27/2017

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas
NC = Not Collected

GLAC

| | | | | _ | | ROAD INVENTORY (| 1100 SERIES FMSS | LOCATION | S) | | | | <u>-</u> | | | |
|--------------|--------------------|------------------------|----------------|-----------|--|--|--|-------------------------|------|----------------|------------------|------------------|-------------------|-----------------|---------------|-------------|
| Route No. | Cycle Collected | lteration Collected | FMSS Number | Concessio | Route Name | Route Desc | cription To | Maintenance District | FLTP | Paved Miles | Unpaved Miles | Total Mileage | Function Class | Area (SQ FT) | Surf. Type | Area Map |
| 0204В | 6 | 1 | 103572 | | FISH CREEK CAMPGROUND LOOP B | FROM ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD) | TO END OF LOOP | WEST LAKE | YES | 0.38 | 0.00 | 0.38 | 3 | | AS | 1C |
| 0204C | 6 | 1 | 103578 | | FISH CREEK CAMPGROUND LOOP C | FROM END OF ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD) ON LEFT | TO END OF LOOP | WEST LAKE | YES | 0.38 | 0.00 | 0.38 | 3 | | AS | 1C |
| 0204D | 6 | 1 | 103579 | | FISH CREEK CAMPGROUND LOOP D | FROM END OF ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD) | TO END OF LOOP | WEST LAKE | YES | 0.30 | 0.00 | 0.30 | 3 | | AS | 1C |
| 0205 | 6 | 1 | 103521 | | APGAR CAMPGROUND ENTRANCE ROAD | FROM ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.66 | TO BEGINNING OF ROUTE 0205E (APGAR CAMPGROUND LOOP E (GROUP SITES)) | WEST LAKE | YES | 0.31 | 0.00 | 0.31 | 3 | | AS | 1 B |
| 0205A | 6 | 1 | 107682 | | APGAR CAMPGROUND LOOP A | FROM ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) AT MP 0.07 | TO END OF LOOP | WEST LAKE | YES | 0.60 | 0.00 | 0.60 | 3 | | AS | 1B |
| 0205B | 6 | 1 | 107684 | | APGAR CAMPGROUND LOOP B | FROM ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) AT MP 0.12 | TO ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) AT MP 0.08 | WEST LAKE | YES | 0.49 | 0.00 | 0.49 | 3 | | AS | 1B |
| 0205C | 6 | 1 | 107685 | | APGAR CAMPGROUND LOOP C | FROM ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) AT MP 0.19 | TO ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) AT MP 0.16 | WEST LAKE | YES | 0.40 | 0.00 | 0.40 | 3 | | AS | 1B |
| 0205D | 6 | 1 | 107687 | | APGAR CAMPGROUND LOOP D | FROM ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) AT MP 0.27 | TO ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) AT MP 0.23 | WEST LAKE | YES | 0.27 | 0.00 | 0.27 | 3 | | AS | 1B |
| 0205E | 6 | 1 | 107688 | | APGAR CAMPGROUND LOOP E (GROUP SITES) | FROM ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) AT MP 0.31 | TO END OF LOOP | WEST LAKE | YES | 0.33 | 0.00 | 0.33 | 3 | | AS | 1B |
| 0206 | 6 | 1 | 6804 | | WASTEWATER TREATMENT PLANT ROAD | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 0.92 | TO ROUTE 0910 (HEADQUARTERS SEWAGE LAGOON PARKING) | WEST LAKE | YES | 0.79 | 0.00 | 0.79 | 3 | | AS | 1B |

Page 4 of 28

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 02/27/2017

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

| | | | | u | | ROAD INVENTORY (| 1100 SERIES FMSS | LOCATION | S) | | | | la l | | | |
|-------|--------------|------------------------|--------|--------|---|--|--|-------------|----------|-------|---------|---------|---------------|---------|-------|------|
| Route | le lected | lteration Collected | FMSS | cessic | | Route Desc | cription | Maintenance | <u>م</u> | | Unpaved | | nctior ISS | Area | Surf. | Area |
| No. | δ̈́δ | ₹ 0 | Number | S | Route Name | From | То | District | 표 | Miles | Miles | Mileage | ⊉ ວິ | (SQ FT) | Туре | Мар |
| 0207 | 6 | 1 | 6792 | | TWO MEDICINE CAMPGROUND ENTRANCE ROAD | FROM ROUTE 0012 (TWO MEDICINE ROAD) AT MP 7.16 | TO END OF LOOP | HUDSON BAY | YES | 0.77 | 0.00 | 0.77 | 3 | | AS | 5A |
| 0207A | 6 | 1 | 107690 | | TWO MEDICINE CAMPGROUND LOOP A | ENTRANCE ROAD) AT MP 0.16 | TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.32 | HUDSON BAY | YES | 0.19 | 0.00 | 0.19 | 3 | | AS | 5A |
| 0207В | 6 | 1 | 107691 | | TWO MEDICINE CAMPGROUND LOOP B | FROM ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.43 | TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.60 | HUDSON BAY | YES | 0.22 | 0.00 | 0.22 | 3 | | AS | 5A |
| 0207C | 6 | 1 | 107692 | | TWO MEDICINE CAMPGROUND LOOP C | FROM ROUTE 0207B (TWO MEDICINE CAMPGROUND LOOP B) AT MP 0.06 | TO ROUTE 0207B (TWO MEDICINE CAMPGROUND LOOP B) AT MP 0.17 | HUDSON BAY | YES | 0.16 | 0.00 | 0.16 | 3 | | AS | 5A |
| 0208A | 6 | 1 | 103833 | | SWIFTCURRENT CABINS LOOP ROAD | FROM ROUTE 0014 (MANY GLACIER ROAD) AT MP 12.44 ON RIGHT | TO ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.04 ON RIGHT | HUDSON BAY | YES | 0.45 | 0.00 | 0.45 | 2 | | AS | 4A |
| 0208B | 6 | 1 | 103836 | | SWIFTCURRENT CABINS CUTOFF ROAD | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.10 | TO ROUTE 0974 (SWIFTCURRENT MOTOR INN PARKING) | HUDSON BAY | YES | 0.03 | 0.00 | 0.03 | 2 | | AS | 4A |
| 0208C | NC | | 231852 | | SWIFTCURRENT CABINS CROSSOVER ROAD | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.10 | TO ROUTE 1043F (SWIFTCURRENT CABIN CIRCLE I AND PARKING) | HUDSON BAY | NO | 0.00 | 0.04 | 0.04 | 3 | | GR | |
| 0209A | 6 | 1 | 6780 | | MANY GLACIER CAMPGROUND LOOP A | FROM ROUTE 0014 (MANY GLACIER ROAD) AT MP 12.35 ON LEFT | TO ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) AT MP 0.05 ON LEFT | HUDSON BAY | YES | 0.58 | 0.00 | 0.58 | 3 | | AS | 4A |
| 0209В | 6 | 1 | 103610 | | MANY GLACIER CAMPGROUND LOOP B | A) AT MP 0.34 ON RIGHT | TO ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) AT MP 0.48 ON RIGHT | HUDSON BAY | YES | 0.22 | 0.00 | 0.22 | 3 | | AS | 4A |

Page 5 of 28

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 02/27/2017

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

| | | | | | | DOAD INIVENITORY (| 1100 CEDIEC FACC | LOCATION | C \ | | | | | | | |
|--------|-----|------------------------|--------|--------|--|--|---|-------------|------------|-------|---------|---------|------|---------|-------|------|
| | 77 | 70 | | e e | | ROAD INVENTORY (| I IUU SEKIES FMSS | LOCATION | 3) | | | | ng . | | | |
| Route | cle | lteration Collected | FMSS | ıcessi | | Route Des | cription | Maintenance | FLTP | | Unpaved | | | Area | Surf. | Area |
| No. | δδ | <u>₹</u> 8 | Number | õ | Route Name | From | То | District | 균 | Miles | Miles | Mileage | ωď | (SQ FT) | Туре | Мар |
| 0209C | 6 | 1 | 103613 | | MANY GLACIER CAMPGROUND CUT THROUGH ROAD | FROM ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) AT MP 0.22 ON LEFT | TO ROUTE 0209B (MANY GLACIER CAMPGROUND LOOP B) AT MP 0.09 ON LEFT | HUDSON BAY | YES | 0.07 | 0.00 | 0.07 | 3 | | AS | 4A |
| 0210 | 6 | 1 | 6784 | | MANY GLACIER HOTEL ROAD | FROM ROUTE 0014 (MANY GLACIER ROAD) AT MP 11.52 | TO END OF LOOP | HUDSON BAY | YES | 0.69 | 0.00 | 0.69 | 3 | | AS | 4A |
| 0211ZZ | 6 | 1 | 5730 | | SUN POINT ROAD | FROM ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 40.03 | TO ROUTE 0948 (SUN POINT PICNIC AREA PARKING) | HUDSON BAY | YES | 0.27 | 0.00 | 0.27 | 3 | | AS | 3 |
| 0212A | 6 | 1 | 37391 | | RISING SUN LODGE ROAD A | FROM END OF ROUTE 0212F (RISING SUN LODGE ROAD F) | to route 0951G (RISING Sun upper motel Parking (North)) | HUDSON BAY | YES | 0.19 | 0.00 | 0.19 | 3 | | AS | 3A |
| 0212B | 6 | 1 | 103845 | | RISING SUN LODGE ROAD B | FROM ROUTE 0212A (RISING SUN LODGE ROAD A) AT MP 0.09 | TO BEGINNING OF ROUTE 0212D (RISING SUN LODGE ROAD D) | HUDSON BAY | YES | 0.06 | 0.00 | 0.06 | 3 | | AS | 3A |
| 0212C | 6 | 1 | 103846 | | RISING SUN LODGE ROAD C | FROM ROUTE 0212A (RISING SUN LODGE ROAD A) AT MP 0.17 | TO ROUTE 0212D (RISING SUN LODGE ROAD D) | HUDSON BAY | YES | 0.04 | 0.00 | 0.04 | 3 | | AS | 3A |
| 0212D | 6 | 1 | 231844 | | RISING SUN LODGE ROAD D | FROM ROUTE 0212B (RISING SUN LODGE ROAD B) AT MP 0.05 | TO ROUTE 0212B (RISING SUN LODGE ROAD B) AT MP 0.05 ON LEFT | HUDSON BAY | YES | 0.08 | 0.00 | 0.08 | 3 | | AS | 3A |
| 0212E | NC | | 231845 | | RISING SUN LODGE ROAD E | FROM ROUTE 0951G (RISING SUN UPPER MOTEL PARKING (NORTH)) | TO ROUTE 0212D (RISING SUN LODGE ROAD D) | HUDSON BAY | NO | 0.00 | 0.09 | 0.09 | 3 | | GR | |
| 0212F | 6 | 1 | 231853 | | RISING SUN LODGE ROAD F | FROM ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 43.87 | TO BEGINNING OF ROUTE 0212A (RISING SUN LODGE ROAD A) | HUDSON BAY | YES | 0.10 | 0.00 | 0.10 | 3 | | AS | 3A |
| 0213A | 6 | 1 | 6776 | | RISING SUN CAMPGROUND ROAD A | FROM ROUTE 0213B (RISING SUN CAMPGROUND ROAD B) | TO END OF LOOP | HUDSON BAY | YES | 0.40 | 0.00 | 0.40 | 3 | | AS | 3A |

Page 6 of 28

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 02/27/2017

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line MRP = Manually Rated Polygon

PKG = Parking Areas

NC = Not Collected

GLAC

| | | | | <u> </u> | | ROAD INVENTORY (| 1100 SERIES FMSS | LOCATION | S) | | | | ٦ | | | |
|-------|--------------|------------------------|--------|----------|--------------------------------------|--|--|-------------|-----|-------|------------------|---------|---------------|---------|-------|------|
| Route | le lected | lteration Collected | FMSS | cessio | | Route Desc | cription | Maintenance | ٩ | Paved | Unpaved Miles | Total | nction ISS | Area | Surf. | Area |
| No. | ۍ څ | 를 I | Number | ខំ | Route Name | From | То | District | FF | Miles | Miles | Mileage | ⊉ີ ວິ | (SQ FT) | Туре | Мар |
| 0213B | 6 | 1 | 103850 | | RISING SUN CAMPGROUND ROAD B | FROM ROUTE 0951B (RISING SUN MOTEL AND RESTAURANT PARKING) | TO END OF LOOP | hudson bay | YES | 0.40 | 0.00 | 0.40 | 3 | | AS | 3A |
| 0214 | 6 | 1 | 6770 | | ST. MARY CAMPGROUND ENTRANCE ROAD | | TO BEGINNING OF ROUTE 0214A (ST. MARY CAMPGROUND LOOP A) | HUDSON BAY | YES | 0.20 | 0.00 | 0.20 | 3 | | AS | 3В |
| 0214A | 6 | 1 | 103841 | | ST. MARY CAMPGROUND LOOP A | FROM END OF ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) | TO END OF LOOP | HUDSON BAY | YES | 0.45 | 0.00 | 0.45 | 3 | | AS | 3в |
| 0214B | 6 | 1 | 103843 | | ST. MARY CAMPGROUND LOOP B | FROM ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) AT MP 0.17 | TO ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) AT MP 0.15 | HUDSON BAY | YES | 0.48 | 0.00 | 0.48 | 3 | | AS | ЗВ |
| 0214C | 6 | 1 | 103853 | | ST. MARY CAMPGROUND LOOP C | FROM ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) AT MP 0.12 | TO END OF LOOP | HUDSON BAY | YES | 0.60 | 0.00 | 0.60 | 3 | | AS | 3в |
| 0219 | NC | | 6795 | | CUT BANK ROAD | FROM U.S. HIGHWAY 89 | TO END OF LOOP AT CUT BANK CREEK CAMPGROUND | HUDSON BAY | NO | 0.00 | 5.19 | 5.19 | 4 | | GR | |
| 0221 | NC | | 6826 | | BOWMAN LAKE ROAD | FROM ROUTE 0100B (INSIDE NORTH FORK ROAD) AT MP 27.2 | TO END OF LOOP AT BOWMAN LAKE CAMPGROUND | WEST LAKE | NO | 0.00 | 5.91 | 5.91 | 4 | | GR | |
| 0226 | NC | | 6771 | | ST. MARY 1913 RANGER STATION ROAD | FROM ROUTE 0102 (ST. MARY RANGER STATION ROAD) | TO END OF LOOP | HUDSON BAY | NO | 0.00 | 0.31 | 0.31 | 3 | | GR | |
| 0240 | 6 | 1 | 6832 | | WALTON RANGER STATION ROAD | FROM ROUTE 5000 (U.S. HIGHWAY 2) | TO UNPAVED ROUTE | WEST LAKE | YES | 0.07 | 0.00 | 0.07 | 3 | | AS | 6 |
| 0241 | 6 | 1 | 107768 | | HUCKLEBERRY MOUNTAIN ROAD | FROM ROUTE 0011 (CAMAS ROAD) AT MP 11.18 | TO END OF LOOP | WEST LAKE | YES | 0.24 | 0.00 | 0.24 | 3 | | AS | 1 |
| 0242 | 6 | 1 | 6815 | | SPRAGUE CREEK CAMPGROUND ROAD | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 9.78 | TO END OF LOOP | WEST LAKE | YES | 0.19 | 0.00 | 0.19 | 3 | | AS | 1D |

Page 7 of 28

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 02/27/2017

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

| | | | | _ | | ROAD INVENTORY (| 1100 SERIES FMSS | LOCATION | S) | | | | = | | | |
|-------|----------------|------------------------|--------|-------|--|--|--|-------------|------|-------|---------|---------|---|---------|-------|------|
| Route | cted | lteration Collected | FMSS | essio | | Route Des | cription | Maintenance | | Paved | Unpaved | Total | s | Area | Surf. | Area |
| No. | Cycle Colle | lteral Colle | Number | Conc | Route Name | From | То | District | FLTP | Miles | | Mileage | | (SQ FT) | Туре | |
| 0244 | 6 | 1 | 37217 | | MANY GLACIER BOAT RAMP ACCESS ROAD | FROM ROUTE 0014 (MANY GLACIER ROAD) AT MP 11.88 | TO BOAT LAUNCH AREA | HUDSON BAY | YES | 0.05 | 0.00 | 0.05 | 3 | | AS | 4A |
| 0245 | 6 | 1 | 231848 | | STEWART MOTEL ROAD | FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.03 | TO ROUTE 0926C (STEWART MOTEL PARKING) | WEST LAKE | YES | 0.04 | 0.00 | 0.04 | 3 | | AS | 1D |
| 0246 | 6 | 1 | 247550 | | APGAR TRANSIT CENTER SHUTTLE LOOP | FROM ROUTE 0011 (CAMAS ROAD) AT MP 0.06 | TO END OF LOOP | WEST LAKE | YES | 0.13 | 0.00 | 0.13 | 3 | | AS | 1B |
| 0400 | 6 | 1 | 6802 | | HEADQUARTERS ROAD | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 0.32 | TO INTERSECTION OF ROUTE 0407 (CAMEL'S HUMP ROAD), ROUTE 0409A (GRINNELL DRIVE), AND ROUTE 0409E (MATHER DRIVE) | WEST LAKE | YES | 0.28 | 0.00 | 0.28 | 5 | | AS | 1A |
| 0401 | 6 | 1 | 6785 | | MANY GLACIER HOUSING AREA ROAD | FROM ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) AT MP 0.01 ON LEFT | TO ROUTE 0401 (MANY GLACIER HOUSING AREA ROAD) AT MP 0.03 ON RIGHT | HUDSON BAY | YES | 0.25 | 0.00 | 0.25 | 5 | | AS | 4A |
| 0402 | 6 | 1 | 6772 | | ST. MARY HOUSING AREA ROAD | FROM ROUTE 0102 (ST. MARY RANGER STATION ROAD) AT MP 0.49 ON LEFT | TO ROUTE 0402 (ST. MARY HOUSING AREA ROAD) AT MP 0.29 ON LEFT | HUDSON BAY | NO | 0.36 | 0.00 | 0.36 | 6 | | AS | 3В |
| 0403 | NC | | 6820 | | PACKERS ROOST ROAD | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 22.21 | TO TRAILHEAD PARKING | WEST LAKE | NO | 0.00 | 0.65 | 0.65 | 3 | | GR | |
| 0404 | 6 | 1 | 6811 | | GRIST ROAD | FROM ROUTE 0011 (CAMAS ROAD) AT MP 0.60 | TO END OF UNPAVED SECTION | WEST LAKE | YES | 0.37 | 1.30 | 1.67 | 3 | | AS | 1 B |
| 0405 | NC | | 6803 | | GLACIER INSTITUTE ROAD | FROM ROUTE 0206 (WASTEWATER TREATMENT PLANT ROAD) | TO END OF LOOP AT GLACIER INSTITUTE | WEST LAKE | NO | 0.00 | 0.40 | 0.40 | 3 | | GR | |
| 0406A | NC | | 37320 | | APGAR LOOKOUT TRAILHEAD ROAD (QUARTER CIRCLE ROAD) | FROM ROUTE 0206 (WASTEWATER TREATMENT PLANT ROAD) | TO ROUTE 1001 (APGAR LOOKOUT PARKING) | WEST LAKE | NO | 0.00 | 1.92 | 1.92 | 3 | | GR | |

Page 8 of 28

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 02/27/2017

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

 $\mathsf{MRP} = \mathsf{Manually} \; \mathsf{Rated} \; \mathsf{Polygon}$

PKG = Parking Areas
NC = Not Collected

| | | | | 5 | | ROAD INVENTORY (| 1100 SERIES FMSS | LOCATION | S) | | | | <u> </u> | | | |
|--------------|--------------------|------------------------|----------------|-----------|--|---|---|-------------------------|------|----------------|------------------|------------------|-------------------|-----------------|---------------|-------------|
| Route No. | Cycle Collected | lteration Collected | FMSS Number | Concessio | Route Name | Route Desc | cription To | Maintenance District | FLTP | Paved Miles | Unpaved Miles | Total Mileage | Function Class | Area (SQ FT) | Surf. Type | Area Map |
| 0406B | NC | | 107749 | | RUBIDEAU SPRINGS ROAD (QUARTER CIRCLE ROAD) | FROM ROUTE 1001 (APGAR LOOKOUT PARKING) | TO SPRINGS | WEST LAKE | NO | 0.00 | 0.96 | 0.96 | 6 | | GR | |
| 0407 | 6 | 1 | 6805 | | CAMEL'S HUMP ROAD | FROM INTERSECTION OF ROUTE 0400 (HEADQUARTERS ROAD), ROUTE 0409A (GRINNELL DRIVE), AND ROUTE 0409E (MATHER DRIVE) | TO GRAVEL PILE ON LEFT AND BIKE PATH STRAIGHT AHEAD | WEST LAKE | YES | 0.13 | 0.11 | 0.24 | 3 | | AS | 1A |
| 0408 | 6 | 1 | 6817 | | LAKE MCDONALD HORSE STABLES ROAD | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 10.76 | TO END AT HORSE STABLES | WEST LAKE | YES | 0.07 | 0.00 | 0.07 | 5 | | AS | 1D |
| 0409A | 6 | 1 | 38466 | | GRINNELL DRIVE | FROM INTERSECTION OF ROUTE 0400 (HEADQUARTERS ROAD), ROUTE 0407 (CAMEL'S HUMP ROAD), AND ROUTE 0409E (MATHER DRIVE) | TO ROUTE 0409B (LOGAN LANE) | WEST LAKE | YES | 0.17 | 0.00 | 0.17 | 5 | | AS | 1A |
| 0409B | 6 | 1 | 107694 | | LOGAN LANE | FROM ROUTE 0409A (GRINNELL DRIVE) | TO ROUTE 0409D (ALBRIGHT CIRCLE) | WEST LAKE | YES | 0.35 | 0.00 | 0.35 | 5 | | AS | 1A |
| 0409C | 6 | 1 | 107695 | | SPERRY DRIVE | FROM ROUTE 0409E (MATHER DRIVE) | TO ROUTE 0409B (LOGAN LANE) | WEST LAKE | YES | 0.15 | 0.00 | 0.15 | 5 | | AS | 1A |
| 0409D | 6 | 1 | 107696 | | ALBRIGHT CIRCLE | FROM ROUTE 0409E (MATHER DRIVE) | TO END OF LOOP | WEST LAKE | YES | 0.33 | 0.00 | 0.33 | 5 | | AS | 1A |
| 0409E | 6 | 1 | 107697 | | MATHER DRIVE | FROM INTERSECTION OF ROUTE 0400 (HEADQUARTERS ROAD), ROUTE 0407 (CAMEL'S HUMP ROAD), AND ROUTE 0409A (GRINNELL DRIVE) | TO ROUTE 0409F (RUHLE DRIVE) AT MP 0.06 ON LEFT | WEST LAKE | YES | 0.32 | 0.00 | 0.32 | 5 | | AS | 1A |
| 0409F | 6 | 1 | 107698 | | RUHLE DRIVE | FROM ROUTE 0409E (MATHER DRIVE) AT MP 0.21 ON RIGHT | TO ROUTE 0409F (RUHLE DRIVE) AT MP 0.14 ON RIGHT | WEST LAKE | YES | 0.17 | 0.00 | 0.17 | 5 | | AS | 1A |

Page 9 of 28

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 02/27/2017

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas
NC = Not Collected

GLAC

| | | | | 5 | | ROAD INVENTORY (| 1100 SERIES FMSS | LOCATION | S) | | | | <u> </u> | | | |
|--------------|--------------------|------------------------|----------------|-----------|---|--|--|-------------------------|------|----------------|------------------|------------------|----------|-----------------|---------------|-------------|
| Route No. | Cycle Collected | Iteration Collected | FMSS Number | Concessio | Route Name | Route Des | cription To | Maintenance District | FLTP | Paved Miles | Unpaved Miles | Total Mileage | | Area (SQ FT) | Surf. Type | Area Map |
| 0410A | 6 | 1 | 107699 | | HEADQUARTERS ADMINISTRATIVE ROAD A | FROM ROUTE 0400 (HEADQUARTERS ROAD) | TO ROUTE 0901 D (HEADQUARTERS MAINTENANCE AREA PARKING (SCOYEN CIRCLE)) | WEST LAKE | YES | 0.22 | 0.00 | 0.22 | 5 | | AS | 1A |
| 0410B | 6 | 1 | 107700 | | HEADQUARTERS ADMINISTRATIVE ROAD B (VINT BOULEVARD) | FROM ROUTE 0901D (HEADQUARTERS MAINTENANCE AREA PARKING (SCOYEN CIRCLE)) | TO ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A) | WEST LAKE | YES | 0.14 | 0.00 | 0.14 | 5 | | AS | 1A |
| 0411 | NC | | 107750 | | SNYDER CREEK WATER TANK ROAD | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 10.25 | TO WATER TANK | WEST LAKE | NO | 0.00 | 0.48 | 0.48 | 6 | | GR | |
| 0412 | NC | | 107751 | | HEADQUARTERS WATER TANK ROAD | FROM ROUTE 0409D (ALBRIGHT CIRCLE) | TO WATER TANK | WEST LAKE | NO | 0.00 | 0.19 | 0.19 | 6 | | GR | |
| 0413 | NC | | 107752 | | FISH CREEK WATER TANK ROAD | FROM ROUTE 0100B (INSIDE NORTH FORK ROAD) AT MP 0.37 | to water tank | WEST LAKE | NO | 0.00 | 0.45 | 0.45 | 6 | | GR | |
| 0414 | NC | | 107753 | | QUARTER CIRCLE HAY BARN ROAD | FROM ROUTE 0206 (WASTEWATER TREATMENT PLANT ROAD) | TO HAY BARN B 1581 | WEST LAKE | NO | 0.00 | 0.21 | 0.21 | 6 | | GR | |
| 0415 | NC | | 107754 | | CAMAS DUMP ROAD | FROM ROUTE 0011 (CAMAS ROAD) | TO DUMP AREA | WEST LAKE | NO | 0.00 | 0.08 | 0.08 | 6 | | GR | |
| 0416 | NC | | 107755 | | MOOSE COUNTRY ACCESS ROAD | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 13.82 | TO END | WEST LAKE | NO | 0.00 | 0.33 | 0.33 | 6 | | GR | |
| 0417 | NC | | 107756 | | MANY GLACIER BOATHOUSE ROAD | FROM ROUTE 0210 (MANY GLACIER HOTEL ROAD) | TO BOATHOUSE | HUDSON BAY | NO | 0.00 | 0.40 | 0.40 | 5 | | GR | |
| 0418 | NC | | 107757 | | MANY GLACIER HORSE STABLES / LAGOON ROAD | FROM ROUTE 0014 (MANY GLACIER ROAD) AT MP 10.96 | TO STABLES AND LAGOON | HUDSON BAY | NO | 0.00 | 0.40 | 0.40 | 5 | | GR | |
| 0419 | NC | | 107758 | | TWO MEDICINE WATER TANK / SEWER / RADIO TOWER ROAD | FROM ROUTE 0981 (TWO MEDICINE SCENIC POINT PARKING) | TO END AT RADIO TOWER | HUDSON BAY | NO | 0.00 | 0.25 | 0.25 | 6 | | GR | |
| 0420A | NC | | 107923 | | BOWMAN LAKE PUBLIC HORSE RAMP ROAD | FROM ROUTE 0221 (BOWMAN LAKE ROAD) | TO HORSE RAMP | WEST LAKE | NO | 0.00 | 0.08 | 0.08 | 5 | | GR | |

Page 10 of 28

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas
NC = Not Collected

GLAC Glacie

Report Date: 02/27/2017

| | | | | _ | | ROAD INVENTORY (| 1100 SERIES FMSS | LOCATION | S) | | | | <u> </u> | | | |
|--------------|--------------------|------------------------|----------------|-----------|---|--|---|-------------------------|------|----------------|------------------|------------------|-------------------|-----------------|---------------|-------------|
| Route No. | Cycle Collected | Iteration Collected | FMSS Number | Concessio | Route Name | Route Des | cription To | Maintenance District | FLTP | Paved Miles | Unpaved Miles | Total Mileage | Function Class | Area (SQ FT) | Surf. Type | Area Map |
| 0420B | NC | | 107924 | | BOWMAN LAKE HORSE CORRAL ROAD | FROM END OF ROUTE 0420A (BOWMAN LAKE PUBLIC HORSE RAMP ROAD) | TO NPS CORRAL | WEST LAKE | NO | 0.00 | 0.22 | 0.22 | 6 | | GR | |
| 0422 | NC | | 6787 | | MANY GLACIER WATER TANK ROAD | FROM ROUTE 0210 (MANY GLACIER HOTEL ROAD) | to water tank area | HUDSON BAY | NO | 0.00 | 0.20 | 0.20 | 6 | | GR | |
| 0423 | NC | | 239520 | | SWIFTCURRENT WATER TANK ROAD | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.32 | TO WATER TANK | HUDSON BAY | NO | 0.00 | 0.09 | 0.09 | 6 | | GR | |
| 0424 | NC | | 239522 | | RISING SUN WATER TANK ROAD | FROM ROUTE 0213B (RISING SUN CAMPGROUND ROAD B) | to water tank | HUDSON BAY | NO | 0.00 | 0.23 | 0.23 | 6 | | GR | |
| 0425 | 6 | 1 | 247574 | | ST. MARY RESIDENCE AND HORSE STABLES ROAD | FROM ROUTE 0102 (ST. MARY RANGER STATION ROAD) | TO ROUTE 1036 (ST. MARY CORRALS PARKING) | HUDSON BAY | МО | 0.05 | 0.00 | 0.05 | 6 | | AS | 3В |
| 0426 | 6 | 1 | 247575 | · | ST. MARY RESIDENCE / DIVIDE CREEK ACCESS | FROM U.S. HIGHWAY 89 | TO ROUTE 0402 (ST. MARY HOUSING AREA ROAD) | HUDSON BAY | NO | 0.08 | 0.00 | 0.08 | 6 | | AS | 3В |

| | | | 5 | NON-NPS | ROADS INVENTO | RY | | | | عا | | | |
|--------------|--|----------------|----------------|--|---|----------------------|------|----------------|------------------|-------------------------------------|-----------------|---------------|-------------|
| Route No. | Cycle Collected Iteration Collected | FMSS Number | Route Name | Route Des | scription To | Maintenance District | FLTP | Paved Miles | Unpaved Miles | Mileage $\frac{1}{2}$ $\frac{1}{2}$ | Area (SQ FT) | Surf. Type | Area Map |
| 5000 | 4 1 | 107813 | U.S. HIGHWAY 2 | FROM END OF BRIDGE IN WALTON (NEAR GLACIER NP SIGN) / WEST PARK BOUNDARY | TO TRAIN TRESTLE (NEAR GLACIER NP SIGN) / EAST | WEST LAKE | NO | 3.48 | 0.00 | 3.48 | | AS | 6 |

Page 11 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

| | | | | PAR | KING AREA INVENTORY (| 1300 SERIES FMSS LOCATI | ONS) | | | | | |
|-------|--------------|------------------------|--------|---|--|--|-------------|------|-----------|---------|-------|------|
| Route | le lected | lteration Collected | FMSS | icession | Route De | | Maintenance | FLTP | Access | Area | Surf. | Area |
| No. | <u>ي ج</u> | 0 <u>#</u> | Number | ិ Route Name | From | То | District | 균 | Level | (SQ FT) | Туре | Мар |
| 0900 | 6 | 1 | 37337 | HEADQUARTERS VISITOR PARKING | FROM ROUTE 0400 (HEADQUARTERS ROAD) | TO HQ PARKING AND UNPAVED ACCESS TO ROUTE 0901 A (HEADQUARTERS EMPLOYEE PARKING) | WEST LAKE | YES | PUBLIC | 15,231 | AS | 1A |
| 0901A | 6 | 1 | 6806 | HEADQUARTERS EMPLOYEE PARKING | FROM ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A) | TO ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A) AND UNPAVED ACCESS TO ROUTE 0900 (HEADQUARTERS VISITOR PARKING) | WEST LAKE | NO | NONPUBLIC | 28,572 | AS | 1A |
| 0901B | 6 | 1 | 107701 | HEADQUARTERS LIBRARY PARKING | ADJACENT TO ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A) ON RIGHT | | WEST LAKE | YES | PUBLIC | 1,103 | AS | 1A |
| 0901C | 6 | 1 | 107702 | HEADQUARTERS MAINTENANCE BUILDING PARKING | ADJACENT TO ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A) ON LEFT | | WEST LAKE | NO | NONPUBLIC | 3,688 | AS | 1A |
| 0901D | 6 | 1 | 107703 | HEADQUARTERS MAINTENANCE AREA PARKING (SCOYEN CIRCLE) | FROM END OF ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A) | THROUGH MAINTENANCE AREA | WEST LAKE | NO | NONPUBLIC | 81,132 | AS | 1A |
| 0901E | 6 | 1 | 107705 | HEADQUARTERS ELECTRONIC OFFICE PARKING | ADJACENT TO ROUTE 0410B (HEADQUARTERS ADMINISTRATIVE ROAD B (VINT BOULEVARD)) ON RIGHT | | WEST LAKE | NO | NONPUBLIC | 1,219 | AS | 1A |
| 0901F | 6 | 1 | 248437 | HEADQUARTERS FUELING AREA | FROM ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A) | TO ROUTE 0410B (HEADQUARTERS ADMINISTRATIVE ROAD B (VINT BOULEVARD)) | WEST LAKE | NO | NONPUBLIC | 19,665 | AS | 1A |
| 0903 | 6 | 1 | 37390 | SCHOOL HOUSE PARKING | FROM ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.15 | TO PARKING | WEST LAKE | YES | PUBLIC | 6,453 | AS | 1 B |
| 0904A | 6 | 1 | 37311 | APGAR PUBLIC PARKING A | ADJACENT TO ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.20 | | WEST LAKE | YES | PUBLIC | 2,196 | AS | 1 B |
| 0904B | 6 | 1 | 107706 | APGAR PUBLIC PARKING B | FROM ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.23 | TO ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.28 | WEST LAKE | YES | PUBLIC | 11,973 | AS | 1 B |
| 0905 | 6 | 1 | 37314 | APGAR VILLAGE COMPLEX PARKING | FROM ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.27 | TO PARKING AROUND APGAR VILLAGE | WEST LAKE | YES | PUBLIC | 51,077 | AS | 1B |

Page 12 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line MRP = Manually Rated Polygon

PKG = Parking Areas

NC = Not Collected

| | | | | c | PAR | KING AREA INVENTORY | 1300 SERIES FMSS LOCATI | ONS) | | | | | |
|--------------|--------------------|----------------|--------|--------|---|---|---|-------------|------|-----------|----------------|-------|-----|
| Route | Cycle Collected | ation ected | FMSS | cessio | | Route De | escription | Maintenance | FLTP | Access | Area | Surf. | |
| No. | ÿ <u>§</u> | Coll | Number | ទឹ | Route Name | From | То | District | 늍 | Level | (SQ FT) | Туре | Мар |
| 0906 | 6 | 1 | 37303 | | APGAR BOAT LAUNCH PARKING | FROM ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.34 | TO ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.35 | WEST LAKE | YES | PUBLIC | 11,320 | AS | 1B |
| 0907 | 6 | 1 | 37312 | | APGAR RANGERS / RESTROOM PARKING | FROM ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.37 | TO ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.40 | WEST LAKE | YES | PUBLIC | 19,821 | AS | 1 B |
| 0908A | 6 | 1 | 6808 | | APGAR AMPHITHEATER PARKING A | ADJACENT TO ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.76 ON LEFT | | WEST LAKE | YES | PUBLIC | 2,284 | AS | 1 B |
| 0908в | 6 | 1 | 103528 | | APGAR AMPHITHEATER PARKING B | ADJACENT TO ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.77 ON RIGHT | | WEST LAKE | YES | PUBLIC | 5,345 | AS | 1 B |
| 0909 | 6 | 1 | 6810 | | APGAR PICNIC LOOP | FROM ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.93 | TO ROUTE 0101 (APGAR LOOP ROAD) AT MP 1.06 | WEST LAKE | YES | PUBLIC | 29,482 | AS | 1 B |
| 0910 | NC | | 37313 | | HEADQUARTERS SEWAGE LAGOON PARKING | FROM END OF ROUTE 0206 (WASTEWATER TREATMENT PLANT ROAD) | TO PARKING | WEST LAKE | NO | NONPUBLIC | 3,150 | GR | |
| 0911 | 6 | 1 | 6813 | | FISH CREEK PICNIC AREA PARKING | FROM ROUTE 0100A (FISH CREEK ACCESS ROAD) | TO PARKING | WEST LAKE | YES | PUBLIC | 22,616 | AS | 1C |
| 0913 | 6 | 1 | 7708 | | FISH CREEK RANGER RESIDENCE PARKING | FROM ROUTE 0100A (FISH CREEK ACCESS ROAD) | TO PARKING | WEST LAKE | NO | NONPUBLIC | 7,008 | AS | 1C |
| 0914A | 6 | 1 | 37397 | | FISH CREEK CAMPGROUND DUMP STATION | FROM ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD) | TO ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD) | WEST LAKE | YES | PUBLIC | 2,799 | AS | 1C |
| 0914B | 6 | 1 | 38754 | | FISH CREEK CAMPGROUND AMPHITHEATER PARKING | FROM ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD) | TO PARKING | WEST LAKE | YES | PUBLIC | 15,205 | AS | 1C |
| 0915 | 6 | 1 | 37371 | | MCGEE MEADOWS PARKING | FROM ROUTE 0011 (CAMAS ROAD) AT MP 5.62 | TO ROUTE 0011 (CAMAS ROAD) AT MP 5.64 | WEST LAKE | YES | PUBLIC | 7 , 995 | AS | 1 |
| 0916 | 6 | 1 | 37166 | | HUCKLEBERRY LOOKOUT TRAILHEAD PARKING | ADJACENT TO ROUTE 0011 (CAMAS ROAD) AT MP 5.86 | | WEST LAKE | YES | PUBLIC | 6,125 | AS | 1 |
| 091 <i>7</i> | 6 | 1 | 37319 | | CAMAS CREEK OVERLOOK PARKING | FROM ROUTE 0011 (CAMAS ROAD) AT MP 8.24 | TO ROUTE 0011 (CAMAS ROAD) AT MP 8.30 | WEST LAKE | YES | PUBLIC | 16,610 | AS | 1 |
| 0918 | 6 | 1 | 37318 | | CAMAS CREEK ENTRANCE STATION PARKING | ADJACENT TO ROUTE 0011 (CAMAS ROAD) AT MP 10.81 | | WEST LAKE | YES | PUBLIC | 4,615 | AS | 1 |

Page 13 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas
NC = Not Collected

GLAC

| | | | | u o | PAR | KING AREA INVENTORY (| 1300 SERIES FMSS LOCAT | TIONS) | | | | | |
|-------|--------------------|-----------------|--------|--------|---|---|--|-------------|---------|-----------|----------------|-------|-----|
| Route | Cycle Collected | ation lected | FMSS | icessi | | Route De | escription | Maintenance | FLTP | Access | Area | Surf. | |
| No. | δ̈́δ | 5 F | Number | ő | Route Name | From | То | District | <u></u> | Level | (SQ FT) | Туре | Мар |
| 0919 | 6 | 1 | 6822 | | HUCKLEBERRY MOUNTAIN TRAILHEAD PARKING | ADJACENT TO ROUTE 0241 (HUCKLEBERRY MOUNTAIN ROAD) | | WEST LAKE | YES | PUBLIC | 1,950 | AS | 1 |
| 0920 | NC | | 6831 | | QUARTZ CREEK CAMPGROUND PARKING | FROM ROUTE 0100B (INSIDE NORTH FORK ROAD) | TO PARKING | WEST LAKE | NO | PUBLIC | 1,000 | GR | |
| 0921 | NC | | 6830 | | LOGGING CREEK CAMPGROUND PARKING | FROM ROUTE 0100B (INSIDE NORTH FORK ROAD) | TO PARKING | WEST LAKE | NO | PUBLIC | 1,500 | GR | |
| 0922 | 6 | 1 | 37167 | | LAKESHORE FOREST PARKING | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 7.81 | | WEST LAKE | YES | PUBLIC | 6 , 170 | AS | 1 |
| 0923 | 6 | 1 | 37171 | | LINCOLN LAKE PARKING | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 9.29 | | WEST LAKE | YES | PUBLIC | 4,439 | AS | 1 |
| 0926A | 6 | 1 | 6818 | | LAKE MCDONALD LODGE PARKING | FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.19 | TO ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.21 | WEST LAKE | YES | PUBLIC | 10,881 | AS | 1D |
| 0926B | 6 | 1 | 103592 | | LAKE MCDONALD CABIN LOOP AND PARKING | FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.11 | TO ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.18 | WEST LAKE | YES | PUBLIC | 11,453 | AS | 1D |
| 0926C | NC | | 103599 | | STEWART MOTEL PARKING | FROM END OF ROUTE 0245 (STEWART MOTEL ROAD) | TO PARKING | WEST LAKE | NO | PUBLIC | 8,031 | GR | |
| 0926D | NC | | 231849 | | LAKE MCDONALD REAR OF STORE PARKING | FROM ROUTE 0926B (LAKE MCDONALD CABIN LOOP AND PARKING) | TO PARKING | WEST LAKE | NO | PUBLIC | 2,200 | GR | |
| 0927 | 6 | 1 | 37360 | | LAKE MCDONALD GENERAL PARKING | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 10.64 | TO ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.19 | WEST LAKE | YES | PUBLIC | 56,158 | AS | 1D |
| 0928A | 6 | 1 | 37357 | | LAKE MCDONALD RESTAURANT PARKING | FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.13 | TO ROUTE 0927 (LAKE MCDONALD GENERAL PARKING) | WEST LAKE | YES | PUBLIC | 14,575 | AS | 1D |
| 0928B | 6 | 1 | 107707 | | LAKE MCDONALD RESTAURANT REAR PARKING | FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.09 | TO PARKING | WEST LAKE | NO | NONPUBLIC | 8,955 | AS | 1D |
| 0929 | 6 | 1 | 37349 | | LAKE MCDONALD POST OFFICE PARKING | FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.08 | TO PARKING | WEST LAKE | YES | PUBLIC | 7,422 | AS | 1D |

Page 14 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line MRP = Manually Rated Polygon

PKG = Parking Areas

NC = Not Collected

GLAC

| | | | | _ | PAR | KING AREA INVENTORY (| 1300 SERIES FMSS LOCAT | IONS) | | | | | |
|--------------|--------------------|------------------------|----------------|-----------|--|---|---|-------------------------|------|-----------------|-----------------|---------------|-------------|
| Route No. | Cycle Collected | Iteration Collected | FMSS Number | Concessio | Route Name | Route De | scription | Maintenance District | FLTP | Access Level | Area (SQ FT) | Surf. Type | Area Map |
| 0930 | 6 | 1 | 8341 | | LAKE MCDONALD GENERAL STORE PARKING | ADJACENT TO ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.07 | | WEST LAKE | YES | PUBLIC | 8,554 | AS | 1D |
| 0932 | 6 | 1 | 6797 | | MCDONALD CREEK OVERLOOK | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 14.26 | | WEST LAKE | YES | PUBLIC | 9,255 | AS | 2 |
| 0934A | 6 | 1 | 38751 | | AVALANCHE CAMPGROUND PARKING A / RANGER RESIDENCE PARKING | ADJACENT TO ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) AT MP 0.05 ON RIGHT | | WEST LAKE | YES | PUBLIC | 1,179 | AS | 2A |
| 0934В | 6 | 1 | 103544 | | AVALANCHE CAMPGROUND PARKING B | ADJACENT TO ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) AT MP 0.07 ON LEFT | | WEST LAKE | YES | PUBLIC | 2,796 | AS | 2A |
| 0934C | 6 | 1 | 103550 | | AVALANCHE CAMPGROUND PARKING C | ADJACENT TO ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) AT MP 0.08 ON RIGHT | | WEST LAKE | YES | PUBLIC | 1,235 | AS | 2A |
| 0934D | 6 | 1 | 103563 | | AVALANCHE CAMPGROUND HANDICAPPED PARKING (TRAIL OF THE CEDARS) | FROM ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) AT MP 0.09 | TO ROUTE 0201CZZ (AVALANCHE CAMPGROUND SERVICE ROAD AND SPUR) | WEST LAKE | YES | PUBLIC | 4,139 | AS | 2A |
| 0935 | 6 | 1 | 247576 | | RED ROCK POINT PARKING | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 17.34 | | WEST LAKE | YES | PUBLIC | 9,624 | AS | 2 |
| 0937 | NC | | 37182 | | LOGAN CREEK PIT PARKING | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 19.94 | TO PARKING | WEST LAKE | NO | NONPUBLIC | 5,685 | GR | |
| 0938A | 6 | 1 | 6798 | | LOOP PARKING AREA A | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 24.02 | | WEST LAKE | YES | PUBLIC | 5,060 | AS | 2 |
| 0938B | 6 | 1 | 103605 | | LOOP PARKING AREA B | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 24.09 | TO PARKING | WEST LAKE | YES | PUBLIC | 6,474 | AS | 2 |
| 0939A | 6 | 1 | 6801 | | ROAD CAMP PARKING AREA A | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 26.79 ON RIGHT | | WEST LAKE | YES | PUBLIC | 2,324 | AS | 2 |

Page 15 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

| | | | | _ | PAR | KING AREA INVENTORY (| 1300 SERIES FMSS LOCATI | ONS) | | | | | |
|--------|------------|------------------------|--------|---------|-------------------------------------|--|--|-------------|-----|--------|---------|-------|------|
| Route | e ected | lteration Collected | FMSS | cessior | | Route De | scription | Maintenance | ٩ | Access | Area | Surf. | Area |
| No. | S C | College | Number | Con | Route Name | From | То | District | 댐 | Level | (SQ FT) | Туре | Мар |
| 0939В | 6 | 1 | 103861 | | ROAD CAMP PARKING AREA B | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 26.80 ON LEFT | | WEST LAKE | NO | PUBLIC | 2,327 | AS | 2 |
| 0941ZZ | 6 | 1 | 247577 | | BIG BEND PARKING AREAS | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 29.02 | | WEST LAKE | YES | PUBLIC | 20,020 | AS | 2 |
| 0942 | 6 | 1 | 37372 | | OBERLIN BEND PARKING | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 31.48 | | WEST LAKE | YES | PUBLIC | 6,396 | AS | 2 |
| 0943 | 6 | 1 | 6779 | | LOGAN PASS PARKING | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 31.86 | TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 31.96 | HUDSON BAY | YES | PUBLIC | 114,883 | AS | 2 |
| 0944 | 6 | 1 | 6765 | | LUNCH CREEK PARKING | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 32.65 | | HUDSON BAY | YES | PUBLIC | 8,587 | AS | 3 |
| 0945ZZ | 6 | 1 | 247578 | | SIYEH BEND PARKING AREAS | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 34.66 | | HUDSON BAY | YES | PUBLIC | 22,099 | AS | 3 |
| 0946A | 6 | 1 | 6766 | | JACKSON GLACIER OVERLOOK PARKING | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 36.53 | | HUDSON BAY | YES | PUBLIC | 5,167 | AS | 3 |
| 0946B | 6 | 1 | 103585 | | GUNSIGHT TRAILHEAD PARKING | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 36.62 | | HUDSON BAY | YES | PUBLIC | 6,516 | AS | 3 |
| 0947 | 6 | 1 | 6767 | | SUNRIFT GORGE PARKING (PAVED) | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 39.41 | | HUDSON BAY | YES | PUBLIC | 4,333 | AS | 3 |
| 0948 | 6 | 1 | 6768 | | SUN POINT PICNIC AREA PARKING | FROM END OF ROUTE 0211ZZ (SUN POINT ROAD) | TO PARKING | HUDSON BAY | YES | PUBLIC | 63,363 | AS | 3 |
| 0949A | 6 | 1 | 37243 | | WILD GOOSE ISLAND PARKING A | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 42.87 | | HUDSON BAY | YES | PUBLIC | 3,587 | AS | 3A |
| 0949B | 6 | 1 | 103868 | | WILD GOOSE ISLAND PARKING B | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 42.95 | | HUDSON BAY | YES | PUBLIC | 8,053 | AS | 3A |
| 0950 | 6 | 1 | 6778 | | RISING SUN BOAT TOURS PARKING | FROM ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 43.59 | TO PARKING | HUDSON BAY | YES | PUBLIC | 64,527 | AS | 3A |
| 0951A | 6 | 1 | 6775 | | RISING SUN MOTEL BUS PARKING | FROM ROUTE 0212F (RISING SUN LODGE ROAD F) | TO ROUTE 0212F (RISING SUN LODGE ROAD F) | HUDSON BAY | YES | PUBLIC | 8,481 | AS | 3A |

Page 16 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas
NC = Not Collected

GLAC

| | | | _ | _ | PAR | KING AREA INVENTORY (| 1300 SERIES FMSS LOCATI | ONS) | | | | | |
|-------|------------|------------------------|--------|---------|--|--|---|-------------|------|-----------|----------------|-------|------|
| Route | e ected | lteration Collected | FMSS | cessior | | Route De | scription | Maintenance | ے | Access | Area | Surf. | Area |
| No. | ٥٥ | Coll | Number | S | Route Name | From | То | District | FLTP | Level | (SQ FT) | Туре | Мар |
| 0951B | 6 | 1 | 103873 | | RISING SUN MOTEL AND RESTAURANT PARKING | FROM ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 43.72 | TO ROUTE 0212F (RISING SUN LODGE ROAD F) | HUDSON BAY | YES | PUBLIC | 60,203 | AS | 3A |
| 0951C | 6 | 1 | 103876 | | RISING SUN MOTEL REAR STORE PARKING | FROM ROUTE 0212A (RISING SUN LODGE ROAD A) AT MP 0.03 | TO PARKING | HUDSON BAY | NO | NONPUBLIC | 7,652 | AS | 3A |
| 0951D | 6 | 1 | 103877 | | RISING SUN LOWER MOTEL PARKING (SOUTH) | FROM ROUTE 0212A (RISING SUN LODGE ROAD A) AT MP 0.08 | TO PARKING | HUDSON BAY | YES | PUBLIC | 5,016 | AS | 3A |
| 0951E | 6 | 1 | 103878 | | RISING SUN LOWER MOTEL PARKING (NORTH) | FROM ROUTE 0212A (RISING SUN LODGE ROAD A) AT MP 0.11 | TO PARKING | HUDSON BAY | YES | PUBLIC | 3,743 | AS | 3A |
| 0951F | 6 | 1 | 103879 | | RISING SUN UPPER MOTEL PARKING (SOUTH) | FROM ROUTE 0212A (RISING SUN LODGE ROAD A) AT MP 0.14 | TO PARKING | HUDSON BAY | YES | PUBLIC | 5,143 | AS | 3A |
| 0951G | 6 | 1 | 103881 | | RISING SUN UPPER MOTEL PARKING (NORTH) | FROM ROUTE 0212A (RISING SUN LODGE ROAD A) AT MP 0.19 | TO PARKING AND ROUTE 0212E (RISING SUN LODGE ROAD E) | HUDSON BAY | YES | PUBLIC | 3,036 | AS | 3A |
| 0951H | 6 | 1 | 107708 | | RISING SUN RESTAURANT REAR PARKING | FROM ROUTE 0212F (RISING SUN LODGE ROAD F) | TO PARKING | HUDSON BAY | NO | NONPUBLIC | 5 , 380 | AS | 3A |
| 0953 | 6 | 1 | 6777 | | RISING SUN PICNIC AREA PARKING | FROM ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 43.87 | TO PARKING | HUDSON BAY | YES | PUBLIC | 44,582 | AS | 3A |
| 0954 | 6 | 1 | 37240 | | TWO DOG FLATS PARKING | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 47.35 | | HUDSON BAY | YES | PUBLIC | 3,699 | AS | 3 |
| 0955A | 6 | 1 | 103882 | | ST. MARY CAMPGROUND PARKING A / DUMP STATION | FROM ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) | TO ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) | HUDSON BAY | YES | PUBLIC | 2,108 | AS | 3В |
| 0955B | 6 | 1 | 103884 | | ST. MARY CAMPGROUND PARKING B | ADJACENT TO ROUTE 0214A (ST. MARY CAMPGROUND LOOP A) AT MP 0.07 | | HUDSON BAY | YES | PUBLIC | 897 | AS | 3В |
| 0955C | 6 | 1 | 103885 | | ST. MARY CAMPGROUND PARKING C | ADJACENT TO ROUTE 0214A (ST. MARY CAMPGROUND LOOP A) AT MP 0.20 | | HUDSON BAY | YES | PUBLIC | 2,157 | AS | 3В |
| 0955D | 6 | 1 | 103886 | | ST. MARY CAMPGROUND PARKING D | ADJACENT TO ROUTE 0214A (ST. MARY CAMPGROUND LOOP A) AT MP 0.29 | | HUDSON BAY | YES | PUBLIC | 1,123 | AS | 3В |
| 0955E | 6 | 1 | 103888 | | ST. MARY CAMPGROUND PARKING E | ADJACENT TO ROUTE 0214A (ST. MARY CAMPGROUND LOOP A) AT MP 0.34 | | HUDSON BAY | YES | PUBLIC | 467 | AS | 3В |

Page 17 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

| | | | | PAI | RKING AREA INVENTORY (| 1300 SERIES FMSS LOCAT | IONS) | | | | | |
|--------------|--------------------|------------------------|----------------|--|--|--|-------------------------|------|-----------------|-----------------|---------------|-------------|
| Route No. | Cycle Collected | lteration Collected | FMSS Number | Route Name | Route De | scription | Maintenance District | FLTP | Access Level | Area (SQ FT) | Surf. Type | Area Map |
| | | | | | 1 | 1 | | | | | | |
| 0955F | 6 | 1 | 103889 | ST. MARY CAMPGROUND PARKING F | ADJACENT TO ROUTE 0214A (ST. MARY CAMPGROUND LOOP A) AT MP 0.40 | | HUDSON BAY | YES | PUBLIC | 932 | AS | 3B |
| 0955G | 6 | 1 | 103890 | ST. MARY CAMPGROUND PARKING G | ADJACENT TO ROUTE 0214B (ST. MARY CAMPGROUND LOOP B) AT MP 0.06 | | HUDSON BAY | YES | PUBLIC | 924 | AS | 3B |
| 0955H | 6 | 1 | 103891 | ST. MARY CAMPGROUND PARKING H | ADJACENT TO ROUTE 0214B (ST. MARY CAMPGROUND LOOP B) AT MP 0.14 | | HUDSON BAY | YES | PUBLIC | 842 | AS | 3B |
| 09551 | 6 | 1 | 103892 | ST. MARY CAMPGROUND PARKING I | ADJACENT TO ROUTE 0214B (ST. MARY CAMPGROUND LOOP B) AT MP 0.16 | | HUDSON BAY | YES | PUBLIC | 945 | AS | 3B |
| 0955J | 6 | 1 | 103893 | ST. MARY CAMPGROUND PARKING J | ADJACENT TO ROUTE 0214B (ST. MARY CAMPGROUND LOOP B) AT MP 0.29 | | HUDSON BAY | YES | PUBLIC | 691 | AS | 3В |
| 0955K | 6 | 1 | 103894 | ST. MARY CAMPGROUND PARKING K | ADJACENT TO ROUTE 0214B (ST. MARY CAMPGROUND LOOP B) AT MP 0.32 | | HUDSON BAY | YES | PUBLIC | 1,097 | AS | 3В |
| 0955L | 6 | 1 | 103896 | ST. MARY CAMPGROUND PARKING L | ADJACENT TO ROUTE 0214B (ST. MARY CAMPGROUND LOOP B) AT MP 0.40 | | HUDSON BAY | YES | PUBLIC | 740 | AS | 3В |
| 0955M | 6 | 1 | 248438 | ST. MARY CAMPGROUND PARKING M | ADJACENT TO ROUTE 0214C (ST. MARY CAMPGROUND LOOP C) AT MP 0.35 | | HUDSON BAY | YES | PUBLIC | 962 | AS | 3В |
| 0955N | 6 | 1 | 248439 | ST. MARY CAMPGROUND PARKING N | ADJACENT TO ROUTE 0214C (ST. MARY CAMPGROUND LOOP C) AT MP 0.53 | | HUDSON BAY | YES | PUBLIC | 1,280 | AS | 3В |
| 0956 | 6 | 1 | 37384 | ST. MARY RIVER PARKING | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 49.14 | | HUDSON BAY | YES | PUBLIC | 2,892 | AS | 3В |
| 0957 | 6 | 1 | 6773 | ST. MARY VISITOR CENTER PARKING | FROM ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 49.36 | TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 49.53 | HUDSON BAY | YES | PUBLIC | 94,940 | AS | 3В |
| 0958 | 6 | 1 | 37385 | ST. MARY TREATMENT PLANT PARKING | FROM ROUTE 0102 (ST. MARY RANGER STATION ROAD) | TO PARKING | HUDSON BAY | NO | NONPUBLIC | 4,872 | AS | 3В |
| 0959A | 6 | 1 | 6774 | ST. MARY MAINTENANCE AREA PARKING A (HUDSON BAY DISTRICT OFFICE) | ADJACENT TO ROUTE 0102 (ST. MARY RANGER STATION ROAD) ON LEFT | | HUDSON BAY | YES | PUBLIC | 1,539 | AS | 3В |

Page 18 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

| | | | | | PAR | KING AREA INVENTORY (| 1300 SERIES FMSS LOCATI | ONS) | | | | | |
|--------------|--------------------|------------------------|----------------|------------|--|---|---|-------------------------|------|-----------------|-----------------|---------------|-------------|
| Route No. | Cycle Collected | lteration Collected | FMSS Number | Concession | Route Name | Route De | | Maintenance District | FLTP | Access Level | Area (SQ FT) | Surf. Type | Area Map |
| 0959В | 6 | 1 | 107710 | | ST. MARY MAINTENANCE AREA PARKING B (HUDSON BAY DISTRICT OFFICE) | FROM ROUTE 0102 (ST. MARY RANGER STATION ROAD) | THROUGH MAINTENANCE AREA | HUDSON BAY | NO | NONPUBLIC | 37,906 | AS | 3B |
| 0959C | 6 | 1 | 107711 | | ST. MARY MAINTENANCE AREA PARKING C (HUDSON BAY DISTRICT OFFICE) | ADJACENT TO ROUTE 0102 (ST. MARY RANGER STATION ROAD) ON LEFT | | HUDSON BAY | NO | NONPUBLIC | 1,228 | AS | ЗВ |
| 0960A | 6 | 1 | 8329 | | ST. MARY RESIDENCE AREA PARKING A | ADJACENT TO ROUTE 0402 (ST. MARY HOUSING AREA ROAD) AT MP 0.25 ON RIGHT | | HUDSON BAY | NO | NONPUBLIC | 1,925 | AS | 3В |
| 0960B | 6 | 1 | 107712 | | ST. MARY RESIDENCE AREA PARKING B | ADJACENT TO ROUTE 0402 (ST. MARY HOUSING AREA ROAD) AT MP 0.26 ON LEFT | | HUDSON BAY | NO | NONPUBLIC | 1,952 | AS | ЗВ |
| 0960C | 6 | 1 | 107714 | | ST. MARY RESIDENCE AREA PARKING C | ADJACENT TO ROUTE 0402 (ST. MARY HOUSING AREA ROAD) AT MP 0.29 ON LEFT | | HUDSON BAY | NO | NONPUBLIC | 1,582 | AS | 3B |
| 0962 | 6 | 1 | 6833 | | GOAT LICK OVERLOOK PARKING | FROM ROUTE 5000 (U.S. HIGHWAY 2) | TO PARKING | WEST LAKE | YES | PUBLIC | 34,619 | AS | 6 |
| 0963 | NC | | 6794 | | EAST GLACIER COMPOUND PARKING | FROM U.S. HIGHWAY 49 | THROUGH COMPOUND PARKING AREA | HUDSON BAY | NO | NONPUBLIC | 41,700 | GR | |
| 0964 | 6 | 1 | 37380 | | RUNNING EAGLE FALLS PARKING | FROM ROUTE 0012 (TWO MEDICINE ROAD) AT MP 5.18 | TO ROUTE 0012 (TWO MEDICINE ROAD) AT MP 5.22 | HUDSON BAY | YES | PUBLIC | 12,113 | AS | 5 |
| 0965 | 6 | 1 | 6793 | | TWO MEDICINE STORE PARKING | FROM ROUTE 0012 (TWO MEDICINE ROAD) AT MP 7.28 | TO ROUTE 0979 (TWO MEDICINE SCENIC CRUISE PARKING) | HUDSON BAY | YES | PUBLIC | 30,445 | AS | 5A |
| 0966A | 6 | 1 | 37296 | | TWO MEDICINE RANGER STATION PARKING A | ADJACENT TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.02 | | HUDSON BAY | YES | PUBLIC | 2,204 | AS | 5A |
| 0966В | 6 | 1 | 107715 | | TWO MEDICINE RANGER STATION PARKING B | FROM ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.03 | TO PARKING | HUDSON BAY | NO | NONPUBLIC | 4,032 | AS | 5A |

Page 19 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

DCV = Data Collection Vehicle

MRL = Manually Rated Line MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

| | | | | | 242 | MINIO A DE A INIVENITARY | 1000 CEDIEC BACC I 0 C + = 1 | ONIC) | | | | | |
|-------|--------------------|-----------------|--------|---------|---|--|--|-------------|------|-----------|-----------------|-------|------|
| | | | | _ | PAR | KING AREA INVENTORY (| 1300 SERIES FMSS LOCATI | ONS) | | | | | |
| Route | Cycle Collected | ation lected | FMSS | ncessio | | Route De | scription | Maintenance | FLTP | Access | Area | Surf. | Area |
| No. | ۍ څ | ₹ 2 | Number | Ŝ | Route Name | From | То | District | Œ. | Level | (SQ FT) | Туре | Мар |
| 0967 | 6 | 1 | 37234 | | POIA LAKE PARKING | ADJACENT TO ROUTE 0014 (MANY GLACIER ROAD) AT MP 10.40 | | HUDSON BAY | YES | PUBLIC | 3,978 | AS | 4 |
| 0968A | 6 | 1 | 232113 | | MANY GLACIER EMPLOYEE DORM PARKING | ADJACENT TO ROUTE 0210 (MANY GLACIER HOTEL ROAD) ON LEFT | | HUDSON BAY | NO | NONPUBLIC | 1,363 | AS | 4A |
| 0968B | 6 | 1 | 107716 | | MANY GLACIER HOTEL HANDICAP PARKING | ADJACENT TO ROUTE 0210 (MANY GLACIER HOTEL ROAD) ON RIGHT | | HUDSON BAY | YES | PUBLIC | 2,835 | AS | 4A |
| 0968C | 6 | 1 | 107717 | | MANY GLACIER HOTEL TRAILHEAD PARALLEL PARKING | ADJACENT TO ROUTE 0210 (MANY GLACIER HOTEL ROAD) ON LEFT | | HUDSON BAY | YES | PUBLIC | 1,888 | AS | 4A |
| 0968D | 6 | 1 | 107718 | | MANY GLACIER HOTEL TRAILHEAD PARKING | FROM ROUTE 0210 (MANY GLACIER HOTEL ROAD) | TO ROUTE 0210 (MANY GLACIER HOTEL ROAD) | HUDSON BAY | YES | PUBLIC | 81 <i>,</i> 798 | AS | 4A |
| 0968E | 6 | 1 | 232976 | | MANY GLACIER HOTEL SOUTH PARKING | ADJACENT TO ROUTE 0210 (MANY GLACIER HOTEL ROAD) ON RIGHT | | HUDSON BAY | YES | PUBLIC | 5,030 | AS | 4A |
| 0971 | 6 | 1 | 37222 | | MANY GLACIER HELIPAD PARKING | FROM ROUTE 0014 (MANY GLACIER ROAD) AT MP 11.93 | TO HELIPAD | HUDSON BAY | МО | NONPUBLIC | 9,496 | AS | 4A |
| 0972 | 6 | 1 | 6786 | | MANY GLACIER PICNIC AREA / GRINNELL GLACIER TRAILHEAD PARKING | FROM ROUTE 0014 (MANY GLACIER ROAD) AT MP 12.06 | TO ROUTE 0014 (MANY GLACIER ROAD) AT MP 12.12 | HUDSON BAY | YES | PUBLIC | 24,332 | AS | 4A |
| 0973A | 6 | 1 | 6790 | | SWIFTCURRENT CABINS PARKING AREA A | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.16 | TO ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.19 | HUDSON BAY | YES | PUBLIC | <i>7,</i> 691 | AS | 4A |
| 0973В | 6 | 1 | 240139 | | SWIFTCURRENT CABINS PARKING AREA B / ICEBERG LAKE TRAILHEAD PARKING | ADJACENT TO ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.24 | | HUDSON BAY | YES | PUBLIC | 3,434 | AS | 4A |
| 0973C | 6 | 1 | 103900 | | SWIFTCURRENT CABINS PARKING AREA C | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.23 | TO ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.26 | HUDSON BAY | YES | PUBLIC | 7,429 | AS | 4A |
| 0973D | 6 | 1 | 103901 | | SWIFTCURRENT CABINS PARKING AREA D | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.30 | TO ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.33 | HUDSON BAY | YES | PUBLIC | 7,944 | AS | 4A |
| 0973E | 6 | 1 | 103902 | | SWIFTCURRENT CABINS PARKING AREA E | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.36 | TO PARKING | HUDSON BAY | YES | PUBLIC | 10,266 | AS | 4A |

Page 20 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

 $\mathsf{MRP} = \mathsf{Manually} \; \mathsf{Rated} \; \mathsf{Polygon}$

PKG = Parking Areas
NC = Not Collected

GLAC

| | | | | _ | PAR | KING AREA INVENTORY (| 1300 SERIES FMSS LOCATI | ONS) | | | | | |
|-------|--------------------|---------------|--------|---------|--|--|--|-------------|------|-----------|----------------|-------|------|
| Route | Cycle Collected | tion ected | FMSS | cessior | | Route De | scription | Maintenance | ے | Access | Area | Surf. | Area |
| No. | ζςς | Coll | Number | S | Route Name | From | То | District | FLTP | Level | (SQ FT) | Туре | Мар |
| 0973F | 6 | 1 | 103899 | | SWIFTCURRENT CABINS PARKING AREA F / PINETOP MOTEL | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.44 | TO PARKING | HUDSON BAY | YES | PUBLIC | 5,214 | AS | 4A |
| 0974 | 6 | 1 | 6789 | | SWIFTCURRENT MOTOR INN PARKING | FROM ROUTE 0014 (MANY GLACIER ROAD) AT MP 12.44 | TO PARKING | HUDSON BAY | YES | PUBLIC | 58,655 | AS | 4A |
| 0975 | 6 | 1 | 37053 | | CRUSHER HILL PARKING | FROM ROUTE 0013 (CHIEF MOUNTAIN INTERNATIONAL HIGHWAY) AT MP 4.88 | TO ROUTE 0013 (CHIEF MOUNTAIN INTERNATIONAL HIGHWAY) AT MP 5.09 | HUDSON BAY | YES | PUBLIC | 41,067 | AS | 4 |
| 0976 | 6 | 1 | 6782 | | BELLY RIVER TRAILHEAD PARKING | FROM ROUTE 0013 (CHIEF MOUNTAIN INTERNATIONAL HIGHWAY)AT MP 14.07 | TO ROUTE 0013 (CHIEF MOUNTAIN INTERNATIONAL HIGHWAY) AT MP 14.14 | HUDSON BAY | YES | PUBLIC | 25,973 | AS | 4 |
| 0978 | NC | | 38006 | | TWO MEDICINE GENERAL STORE PARKING | FROM ROUTE 0012 (TWO MEDICINE ROAD) AT MP 7.28 | TO PARKING | HUDSON BAY | NO | PUBLIC | 15,048 | GR | |
| 0979 | NC | | 38007 | | TWO MEDICINE SCENIC CRUISE PARKING | FROM ROUTE 0965 (TWO MEDICINE STORE PARKING) | TO BOAT DOCK PARKING | HUDSON BAY | NO | PUBLIC | 3, 7 63 | GR | |
| 0980 | NC | | 38008 | | TWO MEDICINE EMPLOYEE HOUSING PARKING | FROM ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.08 | TO PARKING | HUDSON BAY | NO | NONPUBLIC | 5,120 | GR | |
| 0981 | NC | | 38009 | | TWO MEDICINE SCENIC POINT PARKING | FROM ROUTE 0012 (TWO MEDICINE ROAD) AT MP 6.90 | TO ROUTE 0419 (TWO MEDICINE WATER TANK / SEWER / RADIO TOWER ROAD) | HUDSON BAY | NO | PUBLIC | 15,190 | GR | |
| 0982 | NC | | 38011 | | ST. MARY BONE YARD PARKING | FROM END OF ROUTE 0102 (ST. MARY RANGER STATION ROAD) | TO PARKING | HUDSON BAY | NO | NONPUBLIC | 45,780 | GR | |
| 0983 | 6 | 1 | 38012 | | GRIZZLY POINT PARKING | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 37.33 | | HUDSON BAY | YES | PUBLIC | 14,697 | AS | 3 |
| 0984 | 6 | 1 | 107719 | | APGAR CAMPGROUND DUMP STATION | FROM ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) AT MP 0.07 | TO ROUTE 0205A (APGAR CAMPGROUND LOOP A) | WEST LAKE | YES | PUBLIC | 2,380 | AS | 1B |
| 0985 | 6 | 1 | 107720 | | TWO MEDICINE CAMPGROUND DUMP STATION | FROM ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.09 | TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.11 | HUDSON BAY | YES | PUBLIC | 2,568 | AS | 5A |

Page 21 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

| | | | | _ | PAR | KING AREA INVENTORY | (1300 SERIES FMSS LOCATI | ONS) | | | | | |
|-------|-------|------------------------|--------|---------|---|---|---|-------------|----------|-----------|---------------|-------|------|
| Route | ected | Iteration Collected | FMSS | cessior | | Route D | escription | Maintenance | <u>e</u> | Access | Area | Surf. | Area |
| No. | ζςς | Coll | Number | S | Route Name | From | То | District | FLTP | Level | (SQ FT) | Туре | Мар |
| 0986A | 6 | 1 | 107721 | | LOGAN LANE PARKING A | ADJACENT TO ROUTE 0409B (LOGAN LANE) AT MP 0.06 | | WEST LAKE | NO | NONPUBLIC | 4,237 | AS | 1A |
| 0986В | 6 | 1 | 107722 | | LOGAN LANE PARKING B | ADJACENT TO ROUTE 0409B (LOGAN LANE) AT MP 0.10 | | WEST LAKE | NO | NONPUBLIC | 7,617 | AS | 1A |
| 0987 | 6 | 1 | 107723 | | HEADQUARTERS COMMUNITY BUILDING PARKING | FROM ROUTE 0409E (MATHER DRIVE) | TO PARKING | WEST LAKE | YES | PUBLIC | 15,488 | AS | 1A |
| 0988 | 6 | 1 | 107724 | | APGAR OLD VISITOR CENTER PARKING | FROM ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.22 | TO PARKING | WEST LAKE | YES | PUBLIC | 11,730 | AS | 1 B |
| 0989A | 6 | 1 | 107725 | | MANY GLACIER PARKING A / RANGER STATION | ADJACENT TO ROUTE 0401 (MANY GLACIER HOUSING AREA ROAD) | | HUDSON BAY | YES | PUBLIC | 2,312 | AS | 4A |
| 0989В | 6 | 1 | 107726 | | MANY GLACIER PARKING B | FROM ROUTE 0401 (MANY GLACIER HOUSING AREA ROAD) | TO ROUTE 0401 (MANY GLACIER HOUSING AREA ROAD) | HUDSON BAY | YES | PUBLIC | 3,459 | AS | 4A |
| 0989C | 6 | 1 | 107727 | | MANY GLACIER PARKING C / RESIDENCES | FROM ROUTE 0401 (MANY GLACIER HOUSING AREA ROAD) | TO ROUTE 0401 (MANY GLACIER HOUSING AREA ROAD) | HUDSON BAY | NO | NONPUBLIC | 9,592 | AS | 4A |
| 0990 | 6 | 1 | 107728 | | MANY GLACIER DUMP STATION | FROM ROUTE 0014 (MANY GLACIER ROAD) AT MP 12.28 | TO ROUTE 0014 (MANY GLACIER ROAD) AT MP 12.30 | HUDSON BAY | YES | PUBLIC | 2,347 | AS | 4A |
| 0991 | 6 | 1 | 107729 | | MANY GLACIER ENTRANCE STATION PARKING | ADJACENT TO ROUTE 0014 (MANY GLACIER ROAD) AT MP 7.56 | | HUDSON BAY | YES | PUBLIC | 3,749 | AS | 4 |
| 0992A | 6 | 1 | 107730 | | TWO MEDICINE CAMPGROUND PARKING A | ADJACENT TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.20 | | HUDSON BAY | YES | PUBLIC | 1,849 | AS | 5A |
| 0992В | 6 | 1 | 107731 | | TWO MEDICINE CAMPGROUND PARKING B | ADJACENT TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.40 | | HUDSON BAY | YES | PUBLIC | 3,661 | AS | 5A |
| 0992C | 6 | 1 | 107732 | | TWO MEDICINE CAMPGROUND PARKING C | ADJACENT TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.52 | | HUDSON BAY | YES | PUBLIC | 1,50 <i>7</i> | AS | 5A |

Page 22 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle
MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas
NC = Not Collected

GLAC

| | | | | _ | PAR | KING AREA INVENTORY (| 1300 SERIES FMSS LOCAT | IONS) | | | | | |
|--------------|-------|------------------------|----------------|------------|---|--|---|-------------------------|------|-----------------|-----------------|---------------|-------------|
| Route No. | Cycle | lteration Collected | FMSS Number | Concession | Route Name | Route De | scription | Maintenance District | FLTP | Access Level | Area (SQ FT) | Surf. Type | Area Map |
| 0993 | 6 | 1 | 107693 | | TWO MEDICINE PICNIC AREA PARKING | FROM ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.03 | TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.14 | HUDSON BAY | YES | PUBLIC | 27,602 | AS | 5A |
| 0994 | 6 | 1 | 107738 | | WEST GLACIER INFO KIOSK PARKING | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 1.07 | TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 1.09 | WEST LAKE | YES | PUBLIC | 4,394 | AS | 1B |
| 0995ZZ | 6 | 1 | 107739 | | LOWER MCDONALD FALLS PARKING AREAS | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 12.40 | | WEST LAKE | YES | PUBLIC | 5,007 | AS | 1 |
| 0996 | 6 | 1 | 107740 | | RISING SUN CAMPGROUND DUMP STATION | FROM ROUTE 0213B (RISING SUN CAMPGROUND ROAD B) | TO ROUTE 0213A (RISING SUN CAMPGROUND ROAD A) | HUDSON BAY | YES | PUBLIC | 4,733 | AS | 3A |
| 0997 | 6 | 1 | 107741 | | AVALANCHE SHUTTLE STOP PARKING | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 16.16 | | WEST LAKE | YES | PUBLIC | 8,097 | AS | 2A |
| 0998 | 6 | 1 | 107742 | | PAVED HORSE BARN PARKING | ADJACENT TO ROUTE 0206 (WASTEWATER TREATMENT PLANT ROAD) | | WEST LAKE | NO | NONPUBLIC | 2,800 | AS | 1B |
| 0999 | NC | | 107925 | | QUARTER CIRCLE PARKING MULE SHOE | ADJACENT TO ROUTE 0406A (APGAR LOOKOUT TRAILHEAD ROAD (QUARTER CIRCLE ROAD)) | | WEST LAKE | NO | PUBLIC | 7,800 | GR | |
| 1000 | NC | | 107926 | | QUARTER CIRCLE HAY BARN PARKING | FROM ROUTE 0206 (WASTEWATER TREATMENT PLANT ROAD) | TO PARKING | WEST LAKE | NO | NONPUBLIC | 13,000 | GR | |
| 1001 | NC | | 107928 | | APGAR LOOKOUT PARKING | FROM END OF ROUTE 0406A (APGAR LOOKOUT TRAILHEAD ROAD (QUARTER CIRCLE ROAD)) | TO BEGINNING OF ROUTE 0406B (RUBIDEAU SPRINGS ROAD (QUARTER CIRCLE ROAD)) | WEST LAKE | NO | PUBLIC | 8,100 | GR | |
| 1002 | NC | | 108092 | | AVALANCHE PATHS PARKING | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 18.41 | | WEST LAKE | NO | PUBLIC | 11,950 | GR | |
| 1003 | NC | | 108097 | | MANY GLACIER BOAT CONCESSIONAIRE PARKING | FROM ROUTE 0210 (MANY GLACIER HOTEL ROAD) | TO END OF ROUTE 0417 (MANY GLACIER BOATHOUSE ROAD) | HUDSON BAY | NO | NONPUBLIC | 1,482 | GR | |
| 1004 | NC | | 1081 <i>57</i> | | ST. MARY RED EAGLE TRAILHEAD PARKING | ADJACENT TO ROUTE 0226 (ST. MARY 1913 RANGER STATION ROAD) | | HUDSON BAY | NO | PUBLIC | 6,060 | GR | |

Page 23 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line MRP = Manually Rated Polygon

PKG = Parking Areas
NC = Not Collected

| | PARKING AREA INVENTORY (1300 SERIES FMSS LOCATIONS) | | | | | | | | | | | |
|--------------|---|----------|---------|--|---|---|-------------|------|-----------|---------|-------|------|
| Route | Cycle Collected Iteration | FMSS | cession | | Route De | scription | Maintenance | FLTP | Access | Area | Surf. | Area |
| No. | C C S | ਲ Number | S | Route Name | From | То | District | 늍 | Level | (SQ FT) | Туре | Мар |
| 1005 | NC | 108108 | | MANY GLACIER CARETAKERS RESIDENCE AREA PARKING | FROM ROUTE 0210 (MANY GLACIER HOTEL ROAD) | TO PARKING | HUDSON BAY | NO | PUBLIC | 1,968 | GR | |
| 1006 | NC | 108158 | | ST. MARY HOUSING AREA PARKING | FROM ROUTE 0102 (ST. MARY RANGER STATION ROAD) | TO ROUTE 0425 (ST. MARY RESIDENCE AND HORSE STABLES ROAD) | HUDSON BAY | NO | NONPUBLIC | 3,960 | GR | |
| 1007 | NC | 108111 | | MANY GLACIER MULE SHOE PARKING | FROM ROUTE 0014 (MANY GLACIER ROAD) | TO ROUTE 0418 (MANY GLACIER HORSE STABLES / LAGOON ROAD) | HUDSON BAY | Ю | PUBLIC | 9,975 | GR | |
| 1008 | NC | 108161 | | ST. MARY RESIDENCE AREA DORM PARKING | ADJACENT TO ROUTE 0402 (ST. MARY HOUSING AREA ROAD) AT MP 0.17 ON RIGHT | | HUDSON BAY | NO | NONPUBLIC | 3,335 | GR | |
| 1009 | NC | 108175 | | ST. MARY COMPOUND PARKING | FROM ROUTE 0402 (ST. MARY HOUSING AREA ROAD) | TO PARKING | HUDSON BAY | NO | NONPUBLIC | 1,564 | GR | |
| 1010 | NC | 108176 | | EAST GLACIER RANGER STATION PARKING | FROM U.S. HIGHWAY 49 | TO NORTH SIDE OF RANGER STATION | HUDSON BAY | NO | PUBLIC | 3,900 | GR | |
| 1011 | NC | 108178 | | WALTON PARK / OLE CREEK TRAILHEAD PARKING | FROM ROUTE 0240 (WALTON RANGER STATION ROAD) | TO PARKING | WEST LAKE | NO | PUBLIC | 800 | GR | |
| 1012 | NC | 108180 | | WALTON FIRE CACHE PARKING | FROM ROUTE 0240 (WALTON RANGER STATION ROAD) | TO GARAGE / FIRE CACHE | WEST LAKE | NO | NONPUBLIC | 1,400 | GR | |
| 1014 | NC | 108100 | | SUNRIFT GORGE PARKING (UNPAVED) | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 39.47 | | HUDSON BAY | NO | PUBLIC | 3,584 | GR | |
| 1015 | NC | 108101 | | GTSR BARING CREEK CABIN | FROM ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 39.71 | TO PARKING | HUDSON BAY | NO | PUBLIC | 2,700 | GR | |
| 1016 | NC | 108104 | | MANY GLACIER SHERBURNE DAM (NORTH) / ENTRANCE SIGN PARKING | ADJACENT TO ROUTE 0014 (MANY GLACIER ROAD) AT MP 4.88 | | HUDSON BAY | NO | PUBLIC | 6,969 | GR | |
| 101 <i>7</i> | NC | 108109 | | MANY GLACIER SHERBURNE DAM PARKING (SOUTH) | ADJACENT TO ROUTE 0014 (MANY GLACIER ROAD) AT MP 4.79 | | HUDSON BAY | NO | PUBLIC | 9,056 | GR | |
| 1018 | NC | 108112 | | MANY GLACIER WINDY CREEK PARKING | ADJACENT TO ROUTE 0014 (MANY GLACIER ROAD) AT MP 8.89 | | HUDSON BAY | NO | PUBLIC | 2,034 | GR | |

Page 24 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line MRP = Manually Rated Polygon

PKG = Parking Areas

NC = Not Collected

| | PARKING AREA INVENTORY (1300 SERIES FMSS LOCATIONS) | | | | | | | | | | | | |
|-------|---|----------------|--------|---------|---|---|--|-------------|------|-----------|---------|-------|-----|
| Route | Cycle Collected | ation ected | FMSS | cession | | Route De | scription | Maintenance | FLTP | Access | Area | Surf. | |
| No. | δΩ | S S | Number | ŝ | Route Name | From | То | District | 5 | Level | (SQ FT) | Туре | Мар |
| 1019 | NC | | 108156 | | SWIFTCURRENT CABINS LOOP 1 PARKING | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) | TO PARKING | HUDSON BAY | NO | PUBLIC | 1,940 | GR | |
| 1020 | NC | | 108159 | | SWIFTCURRENT CABINS PUBLIC SHOWER AREA PARKING | ADJACENT TO ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.39 | | HUDSON BAY | NO | PUBLIC | 1,800 | GR | |
| 1021 | NC | | 108160 | | SWIFTCURRENT CABINS EMPLOYEE SHOWER AREA PARKING | ADJACENT TO ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.42 | | HUDSON BAY | NO | NONPUBLIC | 2,040 | GR | |
| 1022 | NC | | 108162 | | SWIFTCURRENT CABINS RESTAURANT LOADING AREA | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.06 | TO ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.07 | HUDSON BAY | NO | NONPUBLIC | 7,200 | GR | |
| 1023 | NC | | 108164 | | MANY GLACIER BOAT RAMP PARKING | ADJACENT TO ROUTE 0014 (MANY GLACIER ROAD) AT MP 11.83 | | HUDSON BAY | NO | PUBLIC | 3,000 | GR | |
| 1024 | NC | | 108166 | | MANY GLACIER HOTEL LOWER MAINTENANCE PARKING | FROM ROUTE 0210 (MANY GLACIER HOTEL ROAD) | TO PARKING | HUDSON BAY | NO | NONPUBLIC | 5,400 | GR | |
| 1036 | NC | | 108169 | | ST. MARY CORRALS PARKING | FROM END OF ROUTE 0425 (ST. MARY RESIDENCE AND HORSE STABLES ROAD) | TO PARKING | HUDSON BAY | NO | NONPUBLIC | 11,700 | GR | |
| 1037 | NC | | 108171 | | CUT BANK CREEK TRAILHEAD PARKING | FROM ROUTE 0219 (CUT BANK ROAD) | TO PARKING | HUDSON BAY | NO | PUBLIC | 6,480 | GR | |
| 1038 | NC | | 108173 | | TWO MEDICINE CAMPGROUND GROUP CAMP PARKING AREA | ADJACENT TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.65 | | HUDSON BAY | NO | PUBLIC | 2,190 | GR | |
| 1039 | NC | | 108174 | | TWO MEDICINE CAMPGROUND UNPAVED TRAILHEAD PARKING | ADJACENT TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.58 | | HUDSON BAY | NO | PUBLIC | 3,296 | GR | |
| 1040 | 6 | 1 | 228276 | | LAKE MCDONALD LEWIS DORM PARKING | ADJACENT TO ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.05 | | WEST LAKE | YES | PUBLIC | 1,090 | AS | 1D |

Page 25 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line MRP = Manually Rated Polygon

PKG = Parking Areas

NC = Not Collected

| | | | | _ | PAR | KING AREA INVENTORY (| 1300 SERIES FMSS LOCAT | IONS) | | | | | |
|-------|--------------------|----------------|--------|---------|---|---|--|-------------|------|--------|---------|-------|------|
| Route | Cycle Collected | ation ected | FMSS | cession | | Route De | scription | Maintenance | FLTP | Access | Area | Surf. | Area |
| No. | ςς | S E | Number | S | Route Name | From | То | District | 윤 | Level | (SQ FT) | Туре | Мар |
| 1041 | 6 | 1 | 230217 | | APGAR TRANSIT CENTER PARKING | FROM INTERSECTION OF ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 1.73 AND ROUTE 0011 (CAMAS ROAD) | TO PARKING | WEST LAKE | YES | PUBLIC | 127,609 | AS | 1B |
| 1042 | NC | | 229745 | | LAKE MCDONALD LODGE / SNYDER CREEK EAST PARKING | FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.26 | TO PARKING | WEST LAKE | NO | PUBLIC | 24,000 | GR | |
| 1043A | NC | | 232106 | | SWIFTCURRENT CABIN CIRCLE A AND PARKING | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.43 | TO PARKING | HUDSON BAY | NO | PUBLIC | 2,607 | GR | |
| 1043B | NC | | 232107 | | SWIFTCURRENT CABIN CIRCLE B AND PARKING | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.43 | TO PARKING | HUDSON BAY | NO | PUBLIC | 3,300 | GR | |
| 1043C | NC | | 232108 | | SWIFTCURRENT CABIN CIRCLE C AND PARKING | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.08 | TO PARKING | HUDSON BAY | NO | PUBLIC | 5,028 | GR | |
| 1043D | NC | | 232109 | | SWIFTCURRENT CABIN CIRCLE D AND PARKING | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.11 | TO PARKING | HUDSON BAY | NO | PUBLIC | 4,983 | GR | |
| 1043E | NC | | 232110 | | SWIFTCURRENT CABIN CIRCLE E AND PARKING | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.39 | TO PARKING | HUDSON BAY | NO | PUBLIC | 3,586 | GR | |
| 1043F | NC | | 247580 | | SWIFTCURRENT CABIN CIRCLE I AND PARKING | FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.37 | TO PARKING | HUDSON BAY | NO | PUBLIC | 5,028 | GR | |
| 1044 | 6 | 1 | 6819 | | AVALANCHE PICNIC AREA PARKING | FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 16.13 | TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 16.19 | WEST LAKE | YES | PUBLIC | 33,789 | AS | 2A |
| 1045 | 6 | 1 | 37389 | | SPRAGUE CREEK PICNIC AREA PARKING | FROM ROUTE 0242 (SPRAGUE CREEK CAMPGROUND ROAD) | TO PARKING LOOP | WEST LAKE | YES | PUBLIC | 12,456 | AS | 1D |
| 1046 | 6 | 1 | 247581 | | TRAIL OF THE CEDARS TRAILHEAD PARKING | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 16.31 | | WEST LAKE | YES | PUBLIC | 9,712 | AS | 2A |
| 1047 | 6 | 1 | 247582 | | ST. MARY FALLS TRAILHEAD PARKING | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 38.88 | | HUDSON BAY | YES | PUBLIC | 7,376 | AS | 3 |

Page 26 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

| Route | 7 - 7 - F | | cessio | | Route Description | | Maintenance | FLTP | Access | Area | Surf. | | |
|-------|-----------|---|------------|---------|--|--|---|------------|---------|-----------|--------|----|----|
| No. | | | Route Name | From To | | District | E | Level | (SQ FT) | Туре | Мар | | |
| 1048 | 6 | 1 | 232111 | | LAKE MCDONALD BUILDING 1012 CARETAKERS PARKING | FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.13 | TO PARKING | WEST LAKE | NO | NONPUBLIC | 1,201 | AS | 1D |
| 1049 | 6 | 1 | 232112 | | LAKE MCDONALD REAR LODGE DELIVERY PARKING | FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.23 | TO PARKING | WEST LAKE | NO | NONPUBLIC | 4,488 | AS | 1D |
| 1050 | 6 | 1 | 232113 | | MANY GLACIER HOTEL 15 MINUTE PARKING | FROM ROUTE 0210 (MANY GLACIER HOTEL ROAD) | TO ROUTE 0210 (MANY GLACIER HOTEL ROAD) | HUDSON BAY | YES | PUBLIC | 5,685 | AS | 4A |
| 1051 | NC | | 232115 | | RISING SUN BUILDING 812 PARKING | FROM ROUTE 0212D (RISING SUN LODGE ROAD D) | TO PARKING | HUDSON BAY | NO | PUBLIC | 3,137 | GR | |
| 1052 | NC | | 235027 | | HEADQUARTERS AND SHUTTLE BUS PARKING | ADJACENT TO ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A) ON LEFT | | WEST LAKE | NO | NONPUBLIC | 40,000 | GR | |
| 1053 | NC | | 239199 | | SNYDER CREEK WEST (COBB HOUSE) PARKING | FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.27 | TO PARKING | WEST LAKE | NO | PUBLIC | 6,800 | GR | |
| 1055 | 6 | 1 | 247583 | | LOGAN CREEK RESTROOM PARKING | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 20.31 | | WEST LAKE | YES | PUBLIC | 4,709 | AS | 2 |

Page 27 of 28

Cycle 6 NPS / RIP Route ID Report

Report Date: 02/27/2017 (Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

DCV = Data Collection Vehicle

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas

NC = Not Collected

Cycle 6 Summary Totals for Glacier National Park

Cycle 6 Route Totals

| | NPS Maintained | Concessionaire Maintained | Park Totals |
|--|-------------------|------------------------------|----------------|
| Paved Roads, Data Collection Vehicle Rated (Miles) | 115.71 | 0.22 | 115.93 |
| Paved Roads, Manually Rated Length (Miles) | 0.34 | 0 | 0.34 |
| Paved Roads, Manually Rated Area (Sq. Ft.) | 0 | 0 | 0 |
| Unpaved Roads (Miles) | 61.44 | 0.13 | 61.57 |
| Paved Parking (Sq. Ft.) | 1,916,718 | 0 | 1,916,718 |
| Unpaved Parking (Sq. Ft.) | 391,319 | 0 | 391,319 |

Cycle 6 Lane Miles and Overall Pavement Condition

| | Lanes Miles* | Pavement Condition Rating** |
|--------------------------------|-----------------|-----------------------------|
| Data Collection Vehicle Routes | 231.21 | 91 |
| Manually Rated Roads | 0.33 | 48 |
| Parking Areas | 33.00 | 74 |

^{*} Equivalent Lane Miles are calculated by route using the following equations:

- DCV and MRLs = $(PAVE_WIDTH \times PAVED_MI) / 11$ foot lane

- MRPs and PKGs = $SQ_FEET / 5280 / 11$ foot lane

-Excellent = 97

-Good = 90

-Fair = 73

-Poor = 53, 30, or 0

-Construction / Not Rated = -1

^{**}Parking and Manually Rated Routes are assigned the following PCR values based on the type of observed distresses:

Page 28 of 28

Report Date: 02/27/2017

Cycle 6 NPS / RIP Route ID Report

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Non-NPS Routes

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

 $\mathsf{DCV} = \mathsf{Data} \ \mathsf{Collection} \ \mathsf{Vehicle}$

MRL = Manually Rated Line

MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

General Park Road Functional Classification (FC) Table

| FC | Туре | User Access | Description | Route Numbers |
|-----|--|----------------|--|----------------------------|
| 1 | Principal Park Road Rural Parkway | Public | Roads which constitute the main access route, circulatory tour, or thoroughfare for park visitors. Rural Parkways (e.g. Natchez Trace) are numbered 0001 - 0009. | 0001 - 0009 0010 - 0099 |
| 2 | Connector Park Road | Public | Roads which provide access within a park to areas of scenic, scientific, recreational or cultural interest, such as overlooks, campgrounds, etc. | 0100 - 0199 |
| 3 | Special Purpose Park Road | Public | Roads which provide circulation within public areas, such as campgrounds, picnic areas, visitor center complexes, concessionaire facilities, etc. These roads generally serve low-speed traffic and are often designed for one-way circulation. | 0200 - 0299 |
| 4 | Primitive Park Road | Public | Roads which provide circulation through remote areas and/or access to primitive campgrounds and undeveloped areas. These roads frequently have no minimum design standards and their use may be limited to specially equipped vehicles. Note: Functional Classes 3 and 4 have the same route numbers because, historically, they were numbered similarly. | 0200 - 0299 |
| 5 | Administrative Park Road | Public | All public roads intended for access to administrative developments or structures such as park offices, employee quarters, or utility areas. | 0400 - 0499 |
| 6 | Administrative Park Road (Restricted Access) | Nonpublic | All roads normally closed to the public, including patrol roads, truck trails, and other similar roads. Note: Functional Classes 5 and 6 have the same route numbers because historically they were numbered similarly and often there is little distinction between these routes. For example, because utility areas and employee housing are often closed to the public, this restriction would result in classification of FC 6 rather than FC 5. | 0400 - 0499 |
| 7 | Urban Parkway | Public | These facilities serve high volumes of park and non-park related traffic and are restricted, limited-access facilities in an urban area. This category of roads primarily encompasses the major parkways which serve as gateways to our nation's capital. Other major park roads or portions thereof, however, may be included in this category. | 0001 - 0009 |
| 8 | City Street | Public | City streets are usually extensions of the adjoining street system that are owned and maintained by the National Park Service. The construction and/or reconstruction should conform with accepted local engineering practice and local conditions. | 0600 - 0699 |
| N/A | Non-NPS Roads | Public | State, County, or City owned roads which border, traverse, or provide access to Park Facilities or Locations. Non-NPS roads are not assigned functional classes and are driven for GPS and Video Log only. | 5000 - 5999 |

| Surface |
|---------|
| Types |

- AS Asphaltic Concrete Pavement
- BR Brick or Pavers Road Bed
- CB Cobble Stone Road Bed
- CO Portland Cement Concrete Pavement
- GR Gravel Road Bed
- NV Native or Dirt Material Road Bed
- OT Other Materials Road Bed

A park road system contains those roads within or giving access to a park or other unit of the NPS which are administered by the NPS, or by the Service in cooperation with other agencies. The assignment of a functional classification (FC) to a park road is not based on traffic volumes or design speed, but on the intended use or function of that road or route.

The historic route numbering system also included a 300 series for interpretive roads, and a 500 series for one-way roads. There are approximately 250 roads nationwide which are designated by the 300 and 500 series. The numbers for these roads will be maintained for reporting consistency. However, since these interpretive and one-way routes are not as clearly tied to a specific functional class, the 300 and 500 series will be discontinued for future use.

Page 1 of 3

NPS / RIP Subcomponent Details for GLAC

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 02/27/2017

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Paved Routes, Non-NPS

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

DCV = Data Collection Vehicle

MRL = Manually Rated Line MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

GLAC

| | SUMMARY ROUTE INVENTORY FOR ROADS (1100 SERIES FMSS LOCATIONS) | | | | | | | | | | | | |
|-----------------|--|--------------------|------------------------|----------|---|---|---|------|----------------|------------------|------------------|----------|-----------------|
| Route Number | FMSS Number | Cycle Collected | Iteration Collected | Concessi | Route Name | Route Des | cription To | FLTP | Paved Miles | Unpaved Miles | Total Mileage | Function | Area (SQ FT) |
| 0201CZZ | 38749 | 6 | 1 | | AVALANCHE CAMPGROUND SERVICE ROAD AND SPUR | FROM ROUTE 0201A (AVALANCHE CAMPGROUND LOOP A) AND ROUTE 0934D (AVALANCHE CAMPGROUND HANDICAPPED PARKING (TRAIL OF THE CEDARS)) | TO DEAD END AT TRAIL OF THE CEDARS | NO | 0.22 | 0.00 | 0.22 | 6 | |
| 0211ZZ | 5730 | 6 | 1 | | SUN POINT ROAD | FROM ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 40.03 | TO ROUTE 0948 (SUN POINT PICNIC AREA PARKING) | YES | 0.27 | 0.00 | 0.27 | 3 | |

| SUMMARY ROUTE INVENTORY FOR PARKING AREAS (1300 SERIES FMSS LOCATIONS) | | | | | | | | | | | |
|--|----------------|--------------------|------------------------|-----------|------------------------------------|--|----------------|--------|----------------|-----------------|--|
| Route Number | FMSS Number | Cycle Collected | Iteration Collected | Concessio | Route Name | Route Des | cription To | — FLTP | User Access | Area (SQ FT) | |
| 0941ZZ | 247577 | 6 | 1 | | BIG BEND PARKING AREAS | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 29.02 | | YES | PUBLIC | 20,020 | |
| 0945ZZ | 247578 | 6 | 1 | | SIYEH BEND PARKING AREAS | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 34.66 | | YES | PUBLIC | 22,099 | |
| 0995ZZ | 107739 | 6 | 1 | | LOWER MCDONALD FALLS PARKING AREAS | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 12.40 | | YES | PUBLIC | 5,007 | |

Page 2 of 3

NPS / RIP Subcomponent Details for GLAC

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 02/27/2017

White = Paved Routes, DCV Driven

Grey = Paved Routes, DCV not Driven

Black = Paved Routes, Non-NPS

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

Green = Unpaved Parking Areas

DCV = Data Collection Vehicle MRL = Manually Rated Line MRP = Manually Rated Polygon

PKG = Parking Areas NC = Not Collected

Red text denotes:

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

GLAC

Glacier National Park

| GLAC- | GLAC-0201CZZ Subcomponent Breakdown | | | | | | | | | | | | |
|-----------------|-------------------------------------|--------------------|------------------------|------------|--------------------------------------|---|---|------|----------------|------------------|------------------|------|-----------------|
| Route Number | FMSS Number | Cycle Collected | Iteration Collected | Concession | Route Name | Route Des | cription To | FLTP | Paved Miles | Unpaved Miles | Total Mileage | ~ 97 | Area (SQ FT) |
| 0201CAZ | 38749 | 6 | 1 | | AVALANCHE CAMPGROUND SERVICE ROAD | FROM ROUTE 0934D (AVALANCHE CAMPGROUND HANDICAPPED PARKING (TRAIL OF THE CEDARS)) | TO DEAD END AT TRAIL OF THE CEDARS | NO | 0.17 | 0.00 | 0.17 | 6 | |
| 0201CBZ | 38749 | 6 | 1 | | AVALANCHE CAMPGROUND SERVICE SPUR | FROM ROUTE 0201A (AVALANCHE CAMPGROUND LOOP A) | TO ROUTE 0201 CAZ (AVALANCHE CAMPGROUND SERVICE ROAD) | МО | 0.04 | 0.00 | 0.04 | 6 | |

| GLAC- | 0211Z | Z Su | bcor | mp | onent Breakdown | | | | | | | = | |
|--------|---|----------------|-------------------|----|-------------------------------|--|---|-----|---------------|-------|---------|----------------|---------|
| Route | Route FMSS O Collected Number | | Route Description | | | Paved | Unpaved | | nction ISS | Area | | | |
| Number | Number | δ ₀ | Col | ទំ | Route Name | From | То | 표 | Miles | Miles | Mileage | ∄ ⁸ | (SQ FT) |
| 0211AZ | 5730 | 6 | 1 | | SUN POINT ROAD (ONE-WAY SPUR) | FROM ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 39.97 | TO ROUTE 0211Z (SUN POINT ROAD (MAIN ROAD)) | YES | 0.08 | 0.00 | 0.08 | 3 | |
| 0211Z | 5730 | 6 | 1 | | SUN POINT ROAD (MAIN ROAD) | FROM ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 40.03 | TO ROUTE 0948 (SUN POINT PICNIC AREA PARKING) | YES | 0.19 | 0.00 | 0.19 | 3 | |

| GLAC- | GLAC-0941ZZ Subcomponent Breakdown | | | | | | | | | |
|-----------------|------------------------------------|------------------|--------|---------|--------------------|--|----|-----|----------------|-----------------|
| Route Number | FMSS | /cle ollected | ration | ncessia | Route Name | Route Description | | - ⊵ | User Access | Area (SQ FT) |
| Number | Number | ΰŭ | ≗ŏ | ŭ | Koute Name | From | То | 균 | 710000 | (04.1) |
| 0941AZ | 247577 | 6 | 1 | | BIG BEND PARKING A | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 29.02 ON RIGHT | | YES | PUBLIC | 11,649 |
| 0941BZ | 247577 | 6 | 1 | | BIG BEND PARKING B | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 29.03 ON LEFT | | YES | PUBLIC | 8,371 |

Page 3 of 3

NPS / RIP Subcomponent Details for GLAC

(Numerical By Summary Route and Subcomponent #)



Shading Color Key

Report Date: 02/27/2017

White = Paved Routes, DCV Driven

Red text denotes:

Grey = Paved Routes, DCV not Driven

Black = Paved Routes, Non-NPS

= Concession Route

Yellow = Unpaved Routes, DCV not Driven

Blue = Paved Parking Areas

*Unpaved route data was obtained from the NPS and was not collected by the Road Inventory Program (RIP).

Green = Unpaved Parking Areas

DCV = Data Collection Vehicle

MRL = Manually Rated Line MRP = Manually Rated Polygon

PKG = Parking Areas

PKG = Parking Areas
NC = Not Collected

GLAC

Glacier National Park

| GLAC- | LAC-0945ZZ Subcomponent Breakdown | | | | | | | | | |
|-----------------|-----------------------------------|---------------|-----------------|----------|----------------------|---|------------|-----|--------|---------|
| Route Number | FMSS | cle lected | ation lected | ncession | | Route De | escription | _ | User | Area |
| Number | Number | ٥٥ | ₹ 2 | Ö | Route Name | From | То | 뷴 | Access | (SQ FT) |
| 0945AZ | 247578 | 6 | 1 | | SIYEH BEND PARKING A | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 34.50 ON RIGHT | | YES | PUBLIC | 6,499 |
| 0945BZ | 247578 | 6 | 1 | | SIYEH BEND PARKING B | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 34.61 ON LEFT | | YES | PUBLIC | 3,188 |
| 0945CZ | 247578 | 6 | 1 | | SIYEH BEND PARKING C | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 34.61 ON RIGHT | | YES | PUBLIC | 3,218 |
| 0945DZ | 247578 | 6 | 1 | | SIYEH BEND PARKING D | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 34.71 ON LEFT | | YES | PUBLIC | 1,298 |
| 0945EZ | 247578 | 6 | 1 | | SIYEH BEND PARKING E | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 34.72 ON RIGHT | | YES | PUBLIC | 4,011 |
| 0945FZ | 247578 | 6 | 1 | | SIYEH BEND PARKING F | ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 34.92 ON RIGHT | | YES | PUBLIC | 3,885 |

| GLAC- | BLAC-0995ZZ Subcomponent Breakdown | | | | | | | | | |
|--|------------------------------------|-------------------|-----|---|------------|---|----|-----|--------|---------|
| Route FMSS O Clerked Number Number & Solution Route Name | | Route Description | | | User | Area | | | | |
| Number | Number | δ̈́δ | - S | ů | Route Name | From | То | Ē | Access | (SQ FT) |
| 0995AZ | 107739 | 6 | 1 | | | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 12.36 | | YES | PUBLIC | 1,196 |
| 0995BZ | 107739 | 6 | 1 | | | ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 12.44 | | YES | PUBLIC | 3,811 |

| | ROUTES REMOVED FROM PREVIOUS INVENTORY: | | | | | | | | | |
|-----------|---|----------------|--|--|--|--|--|--|--|--|
| Route No. | Route Name | Type of Change | Comments | | | | | | | |
| 0207D | TWO MEDICINE PICNIC AREA ROAD | OTHER | CYCLE 5 ROUTE 0207D WAS CHANGED TO A PARKING AREA IN ORDER TO BE CONSISTENT WITH OTHER PICNIC AREAS. IT IS NOW ROUTE 0993. | | | | | | | |
| 0239 | AVALANCHE PICNIC AREA ROAD | OTHER | CYCLE 5 ROUTE 0239 WAS CHANGED TO A PARKING AREA IN ORDER TO BE CONSISTENT WITH OTHER PICNIC AREAS. IT IS NOW ROUTE 1044. | | | | | | | |
| 0243 | SPRAGUE CREEK PICNIC AREA ROAD | OTHER | CYCLE 5 ROUTE 0243 WAS CHANGED TO A PARKING AREA IN ORDER TO BE CONSISTENT WITH OTHER PICNIC AREAS. IT IS NOW ROUTE 1045. | | | | | | | |

| | ROU | UTES ADDED FROM PRE | EVIOUS INVENTORY: |
|-----------|--|----------------------------------|--|
| Route No. | Route Name | Type of Change | Comments |
| 0246 | APGAR TRANSIT CENTER SHUTTLE LOOP | RECENTLY CONSTRUCTED ROUTE | NEW ROAD ADDED TO THE INVENTORY IN CYCLE 6. |
| 0425 | ST. MARY RESIDENCE AND HORSE STABLES ROAD | OTHER | PAVED ROUTE ADDED TO THE INVENTORY IN CYCLE 6. |
| 0426 | ST. MARY RESIDENCE / DIVIDE CREEK ACCESS | OTHER | PAVED ROUTE ADDED TO THE INVENTORY IN CYCLE 6. |
| 0901F | HEADQUARTERS FUELING AREA | OTHER | PAVED PARKING AREA ADDED TO THE INVENTORY IN CYCLE 6. |
| 0935 | RED ROCK POINT PARKING | OTHER | ROUTE 0935 WAS ADDED BACK TO THE INVENTORY IN CYCLE 6 AFTER BEING CALLED A "PULLOUT" AND REMOVED IN CYCLE 5. |
| 0941ZZ | BIG BEND PARKING AREAS | OTHER | ROUTE 0941A AND 0941B WERE ADDED BACK TO THE INVENTORY IN CYCLE 6 AFTER BEING CALLED "PULLOUTS" AND REMOVED IN CYCLE 5. |
| 0945ZZ | SIYEH BEND PARKING AREAS | OTHER | ROUTE 0945ZZ PARKING AREAS WERE ADDED BACK TO THE INVENTORY IN CYCLE 6 AFTER BEING CALLED "PULLOUTS" AND REMOVED IN CYCLE 5. |
| 0955M | ST. MARY CAMPGROUND PARKING M | OTHER | PAVED PARKING AREA ADDED TO THE INVENTORY IN CYCLE 6. |
| 0955N | ST. MARY CAMPGROUND PARKING N | OTHER | PAVED PARKING AREA ADDED TO THE INVENTORY IN CYCLE 6. |
| 0973F | SWIFTCURRENT CABINS PARKING AREA F, PINETOP MOTEL | OTHER | PAVED PARKING AREA ADDED TO THE INVENTORY IN CYCLE 6. |
| 1046 | TRAIL OF THE CEDARS TRAILHEAD PARKING | OTHER | PAVED PARKING AREA ADDED TO THE INVENTORY IN CYCLE 6. |

| | ROU | UTES ADDED FROM PRE | EVIOUS INVENTORY: |
|-----------|---|---------------------|---|
| Route No. | Route Name | Type of Change | Comments |
| 1047 | ST. MARY FALLS TRAILHEAD PARKING | OTHER | PAVED PARKING AREA ADDED TO THE INVENTORY IN CYCLE 6. |
| 1048 | LAKE MCDONALD BUILDING 1012 CARETAKERS PARKING | OTHER | PAVED PARKING AREA ADDED TO THE INVENTORY IN CYCLE 6. |
| 1049 | LAKE MCDONALD REAR LODGE DELIVERY PARKING | OTHER | PAVED PARKING AREA ADDED TO THE INVENTORY IN CYCLE 6. |
| 1050 | MANY GLACIER HOTEL 15 MINUTE PARKING | OTHER | PAVED PARKING AREA ADDED IN CYCLE 6, HOWEVER, THE FMSS NUMBER AND ROUTE NAME WERE INCORRECTLY ASSIGNED TO ROUTE 0968A IN CYCLE 5. |
| 1055 | LOGAN CREEK RESTROOM PARKING | OTHER | PAVED PARKING AREA ADDED TO THE INVENTORY IN CYCLE 6. |

| | ROUT | TES MODIFIED FROM PR | REVIOUS INVENTORY: |
|-----------|---|----------------------------|---|
| Route No. | Route Name | Type of Change | Comments |
| 0101 | APGAR LOOP ROAD | FUNCTIONAL CLASS CHANGE | FUNCTIONAL CLASS CHANGED FROM 1 TO 2 BECAUSE IT CONNECTS TO THE VISITOR CENTER AND CABINS. |
| 0201CZZ | AVALANCHE CAMPGROUND SERVICE ROAD AND SPUR | OTHER | ROUTE NAME CHANGED FROM "AVALANCHE CAMPGROUND LOOP C". FUNCTIONAL CLASS CHANGED FROM 3 TO 6 BECAUSE THIS IS A NONPUBLIC SERVICE ROAD. THE SPUR WAS ADDED AND COMBINED WITH THIS ROUTE IN CYCLE 6. |
| 0202 | NORTH LAKE MCDONALD ROAD (KELLY CAMP) | ROUTE NAME | ROUTE NAME CHANGED FROM "KELLY CAMP ROAD". |
| 0206 | WASTEWATER TREATMENT PLANT ROAD | LENGTH CHANGE | PAVED LENGTH INCREASED FROM 0.59 MILES TO 0.79 MILES. |
| 0208A | SWIFTCURRENT CABINS LOOP ROAD | FUNCTIONAL CLASS CHANGE | FUNCTIONAL CLASS CHANGED FROM 3 TO 2 BECAUSE IT IS THE MAIN CONNECTOR ROAD TO THE CABINS AND ICEBERG LAKE TRAILHEAD. |
| 0208B | SWIFTCURRENT CABINS CUTOFF ROAD | FUNCTIONAL CLASS CHANGE | FUNCTIONAL CLASS CHANGED FROM 3 TO 2 BECAUSE IT IS THE MAIN CONNECTOR ROAD TO THE CABINS. |
| 0211ZZ | SUN POINT ROAD | LENGTH CHANGE | PARKING AREA AT THE END OF THE ROAD WAS RECONSTRUCTED, AND AS A RESULT THE MAIN ROAD IS SHORTER THAN IT WAS IN CYCLE 5. |
| 0241 | HUCKLEBERRY MOUNTAIN ROAD | ROUTE NAME | ROUTE NAME CHANGED FROM "HUCKLEBERRY SCENIC VIEWPOINT". |
| 0402 | ST. MARY HOUSING AREA ROAD | ROUTE NAME | ROUTE NAME CHANGED FROM "ST. MARY RESIDENCE AREA" IN ORDER TO MATCH FMSS. |

| | ROU | TES MODIFIED FROM | PREVIOUS INVENTORY: |
|-----------|--|----------------------------|---|
| Route No. | Route Name | Type of Change | Comments |
| 0404 | GRIST ROAD | FUNCTIONAL CLASS CHANGE | FUNCTIONAL CLASS CHANGED FROM 6 TO 3 BECAUSE IT IS A PUBLIC ROAD PROVIDING ACCESS TO PRIVATE RESIDENCES. |
| 0408 | LAKE MCDONALD HORSE STABLES ROAD | FUNCTIONAL CLASS CHANGE | FUNCTIONAL CLASS CHANGED FROM 3 TO 5 BECAUSE IT IS AN ADMINISTRATIVE ROAD WITH PUBLIC ACCESS. |
| 0409C | SPERRY DRIVE | FUNCTIONAL CLASS CHANGE | FUNCTIONAL CLASS CHANGED FROM 6 TO 5 BECAUSE IT IS AN ADMINISTRATIVE ROAD WITH PUBLIC ACCESS. |
| 0409D | ALBRIGHT CIRCLE | FUNCTIONAL CLASS CHANGE | FUNCTIONAL CLASS CHANGED FROM 6 TO 5 BECAUSE IT IS AN ADMINISTRATIVE ROAD WITH PUBLIC ACCESS. |
| 0409F | RUHLE DRIVE | FUNCTIONAL CLASS CHANGE | FUNCTIONAL CLASS CHANGED FROM 6 TO 5 BECAUSE IT IS AN ADMINISTRATIVE ROAD WITH PUBLIC ACCESS. THE SPELLING OF THE ROUTE NAME WAS CORRECTED FROM "RHULE" TO "RUHLE". |
| 0903 | SCHOOL HOUSE PARKING | SQ FEET CHANGE | GPS AND SQUARE FOOTAGE UPDATED IN CYCLE 6. |
| 0904A | APGAR PUBLIC PARKING A | ROUTE NAME | ROUTE NAME CHANGED FROM "APGAR PUBLIC PARALLEL PARKING". |
| 0908A | APGAR AMPHITHEATER PARKING A | SQ FEET CHANGE | GPS AND SQUARE FOOTAGE UPDATED IN CYCLE 6. |
| 0908B | APGAR AMPHITHEATER PARKING B | SQ FEET CHANGE | GPS AND SQUARE FOOTAGE UPDATED IN CYCLE 6. |
| 0919 | HUCKLEBERRY MOUNTAIN TRAILHEAD PARKING | ROUTE NAME | ROUTE NAME CHANGED FROM "HUCKLEBERRY MOUNTAIN SCENIC VIEWPOINT". |
| 0926A | LAKE MCDONALD LODGE PARKING | ROUTE NAME | ROUTE NAME CHANGED FROM "LAKE MCDONALD LODGE PARKING A". |
| 0926B | LAKE MCDONALD CABIN LOOP AND PARKING | ROUTE NAME | ROUTE NAME CHANGED FROM "LAKE MCDONALD LODGE PARKING B". |
| 0926C | STEWART MOTEL PARKING | SURFACE TYPE CHANGE | SURFACE TYPE CHANGED FROM ASPHALT TO GRAVEL. |
| 0928B | LAKE MCDONALD RESTAURANT REAR PARKING | SQ FEET CHANGE | GPS AND SQUARE FOOTAGE UPDATED IN CYCLE 6. |
| 0934B | AVALANCHE CAMPGROUND PARKING B | SQ FEET CHANGE | GPS AND SQUARE FOOTAGE UPDATED IN CYCLE 6. |

| | ROU | TES MODIFIED FROM | PREVIOUS INVENTORY: |
|-----------|--|-------------------|---|
| Route No. | Route Name | Type of Change | Comments |
| 0934D | AVALANCHE CAMPGROUND HANDICAPPED PARKING (TRAIL OF THE CEDARS) | SQ FEET CHANGE | GPS AND SQUARE FOOTAGE UPDATED IN CYCLE 6. THE BEGINNING OF CYCLE 5 ROUTE 0201C IS NOW PART OF THE PARKING AREA. |
| 0939B | ROAD CAMP PARKING AREA B | OTHER | PARKING AREA CHANGED FROM NONPUBLIC TO PUBLIC. |
| 0946A | JACKSON GLACIER OVERLOOK PARKING | ROUTE NAME | ROUTE NAME CHANGED FROM "JACKSON GLACIER AND GUNSIGHT PASS PARKING A". |
| 0946B | GUNSIGHT TRAILHEAD PARKING | ROUTE NAME | ROUTE NAME CHANGED FROM "JACKSON GLACIER AND GUNSIGHT PASS PARKING B". |
| 0948 | SUN POINT PICNIC AREA PARKING | RECONSTRUCTED | CYCLE 5 ROUTES 0948A AND 0948B WERE RECONSTRUCTED INTO A SINGLE, LARGE PARKING AREA. |
| 0949A | WILD GOOSE ISLAND PARKING A | RECONSTRUCTED | PARKING AREA WAS RECONSTRUCTED ON THE SOUTH SIDE OF GOING TO THE SUN ROAD. GPS AND SQ FT WERE RECOLLECTED. |
| 0949B | WILD GOOSE ISLAND PARKING B | RECONSTRUCTED | PARKING AREA WAS RECONSTRUCTED ON THE SOUTH SIDE OF GOING TO THE SUN ROAD. GPS AND SQ FT WERE RECOLLECTED. |
| 0951C | RISING SUN MOTEL REAR STORE PARKING | OTHER | PARKING AREA CHANGED FROM PUBLIC TO NONPUBLIC. |
| 0957 | ST. MARY VISITOR CENTER PARKING | RECONSTRUCTED | ROUTES 0957A AND 0957B WERE RECONSTRUCTED INTO A SINGLE, LARGE PARKING AREA (NOW JUST 0957). THE FMSS NUMBER FOR ROUTE 0957A WAS KEPT (6773). |
| 0959A | ST. MARY MAINTENANCE AREA PARKING A (HUDSON BAY DISTRICT OFFICE) | OTHER | PARKING AREA CHANGED FROM PUBLIC TO NONPUBLIC. |
| 0968A | MANY GLACIER EMPLOYEE DORM PARKING | ROUTE NAME | ROUTE NAME CHANGED FROM "MANY GLACIER HOTEL 15 MINUTE PARKING". FMSS NUMBER CHANGED FROM 6788 TO 232113. THE OLD ROUTE NAME AND FMSS NUMBER NOW BELONG TO ROUTE 1050. |
| 0968B | MANY GLACIER HOTEL HANDICAP PARKING | SQ FEET CHANGE | GPS AND SQUARE FOOTAGE UPDATED IN CYCLE 6. |
| 0968C | MANY GLACIER HOTEL TRAILHEAD PARALLEL PARKING | OTHER | PARKING AREA CHANGED FROM CONCESSIONAIRE TO NON-CONCESSIONAIRE. |
| 0968D | MANY GLACIER HOTEL TRAILHEAD PARKING | OTHER | PARKING AREA CHANGED FROM CONCESSIONAIRE TO NON-CONCESSIONAIRE. |
| 0968E | MANY GLACIER HOTEL SOUTH PARKING | SQ FEET CHANGE | GPS AND SQUARE FOOTAGE UPDATED IN CYCLE 6. |

| | ROU | TES MODIFIED FROM P | REVIOUS INVENTORY: |
|-----------|--|---------------------|--|
| Route No. | Route Name | Type of Change | Comments |
| 0972 | MANY GLACIER PICNIC AREA / GRINNELL GLACIER TRAILHEAD PARKING | ROUTE NAME | ROUTE NAME CHANGED FROM "MANY GLACIER PICNIC AREA PARKING". |
| 0973B | SWIFTCURRENT CABINS PARKING AREA B, ICEBERG LAKE TRAILHEAD PARKING | OTHER | FMSS NUMBER CHANGED FROM 103899 TO 240139. |
| 0983 | GRIZZLY POINT PARKING | SQ FEET CHANGE | GPS AND SQUARE FOOTAGE UPDATED IN CYCLE 6. |
| 0986A | LOGAN LANE PARKING A | ROUTE NAME | ROUTE NAME CHANGED FROM "LOGAN LANE RESIDENCE PARKING A". |
| 0987 | HEADQUARTERS COMMUNITY BUILDING PARKING | OTHER | PARKING AREA CHANGED FROM NONPUBLIC TO PUBLIC. |
| 0988 | APGAR OLD VISITOR CENTER PARKING | ROUTE NAME | ADDED THE WORD "OLD" TO THE ROUTE NAME. |
| 0989A | MANY GLACIER PARKING A / RANGER STATION | OTHER | PARKING AREA CHANGED FROM NONPUBLIC TO PUBLIC. |
| 0993 | TWO MEDICINE PICNIC AREA PARKING | ROUTE NUMBER | CYCLE 5 ROUTES 0207D AND 0993A-E WERE COMBINED INTO A SINGLE PARKING LOT TO BE CONSISTENT WITH OTHER PICNIC AREAS. |
| 0995ZZ | LOWER MCDONALD FALLS PARKING AREAS | OTHER | ROUTE NAME CHANGED FROM "HANDICAP PARKING". SUBCOMPONENT ROUTE 0995AZ EXISTED AS ROUTE 0995 IN CYCLE 5. NEW SUBCOMPONENT ROUTE 0995BZ WAS ADDED IN CYCLE 6. |
| 1041 | APGAR TRANSIT CENTER PARKING | RECONSTRUCTED | GPS AND SQUARE FOOTAGE UPDATED IN CYCLE 6 DUE TO RECENTLY CONSTRUCTED ADDITIONS ON THE NORTH SIDE. |
| 1044 | AVALANCHE PICNIC AREA PARKING | ROUTE NUMBER | CYCLE 5 ROUTE 0239 WAS CHANGED TO A PARKING AREA TO BE CONSISTENT WITH OTHER PICNIC AREAS. |
| 1045 | SPRAGUE CREEK PICNIC AREA PARKING | ROUTE NUMBER | CYCLE 5 ROUTE 0243 WAS CHANGED TO A PARKING AREA TO BE CONSISTENT WITH OTHER PICNIC AREAS. |
| 5000 | U.S. HIGHWAY 2 | ROUTE NAME | ROUTE NAME CHANGED FROM "STATE ROUTE 2". |

Section 3 Park Summary Information



Glacier National Park



Parkwide Paved Route Condition Summary Glacier National Park

Table 1: Paved Route Miles and Parking Area Square Footages by Access Level and PCR


Breakdown of Pavement Condition Rating (PCR) Based on Access Level

| | POOR (PCR of 0 - 60) | FAIR (PCR of 61 - 84) | GOOD (PCR of 85 - 94) | EXCELLENT (PCR of 95 -100) | |
|----------------------|-------------------------|--------------------------|--------------------------|-------------------------------|---------------------|
| | | PAVED | ROADS | | |
| Functional Class | Length (miles) | Length (miles) | Length (miles) | Length (miles) | Total Mileage by FC |
| 1 | 3.76 | 12.72 | 17.74 | 61.13 | 95.34 |
| 2 | 0.99 | 1.39 | 1.61 | 0.57 | 4.56 |
| 3 | 0.80 | 3.16 | 5.23 | 3.91 | 13.10 |
| 4 | | | | | |
| 5 | 0.34 | 0.74 | 0.60 | 0.77 | 2.45 |
| 6 | 0.33 | 0.14 | 0.20 | 0.02 | 0.69 |
| 7 | | | | | |
| 8 | | | | | |
| Total Mileage by PCR | 6.22 | 18.15 | 25.38 | 66.40 | 116.15 |
| | | PAVED P | ARKING | | |
| Access Level | Area (sq. ft.) | Area (sq. ft.) | Area (sq. ft.) | Area (sq. ft.) | Total Area |
| PUBLIC | 324,098 | 191,211 | 1,002,065 | 141,782 | 1,659,156 |
| NONPUBLIC | 221,762 | 1,363 | 34,437 | | 257,562 |
| Total Area by PCR | 545,860 | 192,574 | 1,036,502 | 141,782 | 1,916,718 |

NOTES:

- 1. Data are reported in the table only for paved roads and parking lots that received a condition rating.
- 2. Non-linear roads (MRP collected routes) are measured by area and converted to equivalent route miles based on a 22-ft pavement width in order to be included in the mileage totals for paved roads shown above.
- 3. Quantities in the table above are derived from the route condition data within the PMS_20, PMS_MRL, PMS_MRP, and PMS_PKG tables in the Park geodatabase.

Parkwide Condition Percentages



Road Condition Percentages

Parking Area Condition Percentages

Figure 1: Pavement Condition Rating Breakdown for Paved Roads and Parking Areas

Explanation of the Excellent, Good, Fair, and Poor Condition Descriptions

The Road Inventory Program aims to provide assistance in translating the excellent / good / fair / poor rating categories into pavement needs categories. The PCR can be used to indicate the place in the Pavement Life Cycle and the type of treatments that should be considered now and into the future.

- Excellent / New: PCR of 95-100
 - o Pavements in this range will require only spot repairs
- Good: PCR of 85-94
 - o Pavements in this range will likely be candidates for Preventive Maintenance. Examples include Chip and Slurry Seals, Micro Surfacing and Thin Overlays.
- Fair: PCR of 61-84
 - o Pavements in this range will likely be candidates of Light Rehabilitation (L3R). Examples include singlelift overlays up to 2.5 inches in total thickness, milling and overlays.
- Poor: PCR of 0-60
 - o Pavements in this range will likely be candidates of Heavy Rehabilitation or Reconstruction (H3R or 4R). Examples include Pulverization, Multiple Lift Overlays, and Reconstruction.

CONDITION CATEGORIES AND TREATMENTS EXCELLENT / Localized Repairs Only GOOD / Preventive Maintenance FAIR / Light Rehabilitation POOR / Heavy Rehabilitation Reconstruction Payement Age

At this time, specific Maintenance and Rehabilitation activities should be evaluated and recommended at the project level. Site-specific conditions that influence treatment type should be determined based on performing a subsurface investigation and/or pavement condition survey, and not be based solely on RIP data. Additionally, RIP produces a snapshot of conditions at the time in which the data were collected. For further information or to obtain additional Pavement Management System's data from our Highway Pavement Management Application (HPMA) please contact the Eastern Federal Lands pavement team.



Road Condition Summary Report for Data Collection Vehicle (DCV) Rated Roads

Glacier National Park

Condition (Rating / Index) Legend

GOOD (85 - 94)

FAIR (61 - 84)

POOR (0 - 60)

NR = NOT RATED

Notes:

- This condition summary report contains only the roads rated with the Data Collection Vehicle (DCV).
- Condition on roads that were manually rated and parking areas are shown in separate reports.
- Additional details on individual road ratings can be found in Section 5 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

| Route No. | <u>Route-</u> FMSS No. | Level Condition for Roads Rated with the Data Collec | Functional | Surf. Type | Paved Length (Miles) | Pavement Condition Rating (PCR) | Roughness Condition Index (RCI) | Surface Condition Rating (SCR) | Structural Crack Index | r Crack I | Longitudinal Cracking Index | Transverse Cracking Index | Patch / Pothole Index | Ruffing Index |
|------------|---------------------------|--|------------|---------------|----------------------------|------------------------------------|------------------------------------|-----------------------------------|------------------------|-----------|--------------------------------|------------------------------|-----------------------|---------------|
| GLAC-0010E | 5729 | GOING TO THE SUN ROAD EAST | 1 | AS | 18.00 | 100 | 100 | 100 | 100 | 100 | 100 | 100 | | 100 |
| GLAC-0010W | 6763 | GOING TO THE SUN ROAD WEST | 1 | AS | 31.86 | 99 | 100 | 99 | 99 | 100 | 99 | 99 | 100 | 99 |
| GLAC-0011 | 6821 | CAMAS ROAD | 1 | AS | 11.58 | 97 | 100 | 95 | 99 | 100 | 99 | | 100 | 95 |
| GLAC-0012 | 6791 | TWO MEDICINE ROAD | 1 | AS | 7.28 | 85 | 74 | 92 | 100 | 100 | 100 | 100 | 100 | 92 |
| GLAC-0013 | 6781 | CHIEF MOUNTAIN INTERNATIONAL HIGHWAY | 1 | AS | 14.25 | 90 | 87 | 92 | 99 | 100 | 99 | 99 | 100 | 92 |
| GLAC-0014 | 6783 | MANY GLACIER ROAD | 1 | AS | 12.44 | 74 | 64 | 81 | 93 | 99 | 94 | 99 | 99 | 81 |
| GLAC-0100A | 6823 | FISH CREEK ACCESS ROAD | 2 | AS | 1.16 | 84 | 73 | 92 | 100 | 100 | 100 | 100 | 100 | 92 |
| GLAC-0101 | 6807 | APGAR LOOP ROAD | 2 | AS | 1.11 | 84 | 64 | 97 | 97 | 100 | 97 | 99 | 99 | 97 |
| GLAC-0102 | 6769 | ST. MARY RANGER STATION ROAD | 2 | AS | 0.91 | 58 | 47 | 66 | 66 | 80 | 86 | 96 | 99 | 88 |
| GLAC-0200 | 6816 | LAKE MCDONALD LODGE LOOP ROAD | 2 | AS | 0.53 | 66 | NR | 66 | 87 | 100 | 87 | 66 | 93 | 96 |
| GLAC-0201 | 3731 <i>5</i> | AVALANCHE CAMPGROUND ENTRANCE ROAD | 3 | AS | 0.26 | 97 | NR | 97 | 98 | 100 | 98 | 100 | 100 | 97 |
| GLAC-0201A | 37336 | AVALANCHE CAMPGROUND LOOP A | 3 | AS | 0.36 | 96 | NR | 96 | 100 | 100 | 100 | 100 | 100 | 96 |
| GLAC-0201B | 38439 | AVALANCHE CAMPGROUND LOOP B | 3 | AS | 0.27 | 95 | NR | 95 | 100 | 100 | 100 | 100 | 99 | 95 |
| GLAC-0202 | 37354 | NORTH LAKE MCDONALD ROAD (KELLY CAMP) | 2 | AS | 0.41 | 38 | NR | 38 | 38 | 99 | 39 | 74 | 99 | 95 |
| GLAC-0204 | 6812 | FISH CREEK CAMPGROUND ENTRANCE ROAD | 3 | AS | 0.31 | 94 | NR | 94 | 100 | 100 | 100 | 99 | 99 | 94 |
| GLAC-0204A | 103567 | FISH CREEK CAMPGROUND LOOP A | 3 | AS | 0.26 | 86 | NR | 86 | 98 | 100 | 98 | 100 | 100 | 86 |
| GLAC-0204B | 103572 | FISH CREEK CAMPGROUND LOOP B | 3 | AS | 0.38 | 88 | NR | 88 | 97 | 100 | 97 | 100 | 99 | 88 |
| GLAC-0204C | 103578 | FISH CREEK CAMPGROUND LOOP C | 3 | AS | 0.38 | 89 | NR | 89 | 95 | 100 | 95 | 99 | 100 | 89 |
| GLAC-0204D | 103579 | FISH CREEK CAMPGROUND LOOP D | 3 | AS | 0.30 | 89 | NR | 89 | 99 | 100 | 99 | 100 | 100 | 89 |



Road Condition Summary Report for Data Collection Vehicle (DCV) Rated Roads

Glacier National Park

Condition (Rating / Index) Legend

GOOD (85 - 94)

FAIR (61 - 84)

POOR (0 - 60)

NR = NOT RATED

Notes:

- This condition summary report contains only the roads rated with the Data Collection Vehicle (DCV).
- Condition on roads that were manually rated and parking areas are shown in separate reports.
- Additional details on individual road ratings can be found in Section 5 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

| | Route- | Level Condition for Roads Rated with the Data Collection V | ehicle (DCV) | | | ے ا | ב | | ndex | × | cking | D) | × | |
|-------------|----------|--|--------------------|-----------------|----------------------------|------------------------------------|------------------------------------|-----------------------------------|----------------------|-----------------------|------------------------------|------------------------------|-----------------------|---------------|
| Route No. | FMSS No. | Route Name | Functiona Class | l Surf. Type | Paved Length (Miles) | Pavement Condition Rating (PCR) | Roughness Condition Index (RCI) | Surface Condition Rating (SCR) | Structural Crack Ind | Alligator Crack Index | Longitudinal Cracki Index | Transverse Cracking Index | Patch / Pothole Index | Rutting Index |
| GLAC-0205 | 103521 | APGAR CAMPGROUND ENTRANCE ROAD | 3 | AS | 0.31 | 95 | NR | 95 | 100 | 100 | 100 | 100 | 100 | 95 |
| GLAC-0205A | 107682 | APGAR CAMPGROUND LOOP A | 3 | AS | 0.60 | 93 | NR | 93 | 100 | 100 | 100 | 100 | 100 | 93 |
| GLAC-0205B | 107684 | APGAR CAMPGROUND LOOP B | 3 | AS | 0.49 | 92 | NR | 92 | 100 | 100 | 100 | 100 | 100 | 92 |
| GLAC-0205C | 107685 | APGAR CAMPGROUND LOOP C | 3 | AS | 0.40 | 95 | NR | 95 | 100 | 100 | 100 | 100 | 98 | 95 |
| GLAC-0205D | 107687 | APGAR CAMPGROUND LOOP D | 3 | AS | 0.27 | 94 | NR | 94 | 100 | 100 | 100 | 100 | 100 | 94 |
| GLAC-0205E | 107688 | APGAR CAMPGROUND LOOP E (GROUP SITES) | 3 | AS | 0.33 | 97 | NR | 97 | 100 | 100 | 100 | 100 | 100 | 97 |
| GLAC-0206 | 6804 | WASTEWATER TREATMENT PLANT ROAD | 3 | AS | 0.79 | 76 | 54 | 91 | 91 | 100 | 91 | 98 | 99 | 95 |
| GLAC-0207 | 6792 | TWO MEDICINE CAMPGROUND ENTRANCE ROAD | 3 | AS | 0.77 | 92 | NR | 92 | 100 | 100 | 100 | 99 | 99 | 92 |
| GLAC-0207A | 107690 | TWO MEDICINE CAMPGROUND LOOP A | 3 | AS | 0.19 | 94 | NR | 94 | 100 | 100 | 100 | 100 | 99 | 94 |
| GLAC-0207B | 107691 | TWO MEDICINE CAMPGROUND LOOP B | 3 | AS | 0.22 | 93 | NR | 93 | 100 | 100 | 100 | 100 | 99 | 93 |
| GLAC-0207C | 107692 | TWO MEDICINE CAMPGROUND LOOP C | 3 | AS | 0.16 | 90 | NR | 90 | 100 | 100 | 100 | 100 | 100 | 90 |
| GLAC-0208A | 103833 | SWIFTCURRENT CABINS LOOP ROAD | 2 | AS | 0.45 | 92 | NR | 92 | 100 | 100 | 100 | 100 | 98 | 92 |
| GLAC-0208B | 103836 | SWIFTCURRENT CABINS CUTOFF ROAD | 2 | AS | 0.03 | 90 | NR | 90 | 97 | 100 | 97 | 99 | 100 | 90 |
| GLAC-0209A | 6780 | MANY GLACIER CAMPGROUND LOOP A | 3 | AS | 0.58 | 91 | NR | 91 | 100 | 100 | 100 | 100 | 100 | 91 |
| GLAC-0209B | 103610 | MANY GLACIER CAMPGROUND LOOP B | 3 | AS | 0.22 | 93 | NR | 93 | 100 | 100 | 100 | 100 | 100 | 93 |
| GLAC-0209C | 103613 | MANY GLACIER CAMPGROUND CUT THROUGH ROAD | 3 | AS | 0.07 | 89 | NR | 89 | 100 | 100 | 100 | 100 | 100 | 89 |
| GLAC-0210 | 6784 | MANY GLACIER HOTEL ROAD | 3 | AS | 0.69 | 83 | NR | 88 | 88 | 100 | 88 | 93 | 94 | 91 |
| GLAC-0211AZ | 5730 | SUN POINT ROAD (ONE-WAY SPUR) | 3 | AS | 0.08 | 83 | NR | 83 | 100 | 100 | 100 | 100 | 100 | 83 |
| GLAC-0211Z | 5730 | SUN POINT ROAD (MAIN ROAD) | 3 | AS | 0.19 | 98 | NR | 98 | 100 | 100 | 100 | 100 | 100 | 98 |



Road Condition Summary Report for Data Collection Vehicle (DCV) Rated Roads

Glacier National Park

Condition (Rating / Index) Legend

EXCELLENT (95 - 100)

GOOD (85 - 94) FAIR (61 - 84)

POOR (0 - 60)

NR = NOT RATED

Notes:

- This condition summary report contains only the roads rated with the Data Collection Vehicle (DCV).
- Condition on roads that were manually rated and parking areas are shown in separate reports.
- Additional details on individual road ratings can be found in Section 5 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

| Route No. | Route- | Level Condition for Roads Rated with the Data Colle Route Name | ection Vehicle (DCV) Functiona Class | l Surf. Type | Paved Length (Miles) | Pavement Condition Rating (PCR) | Roughness Condition Index (RCI) | Surface Condition Rating (SCR) | Structural Crack Index | Alligator Crack Index | Longitudinal Cracking Index | Transverse Cracking Index | Patch / Pothole Index | Rutting Index |
|------------|--------|---|--------------------------------------|-----------------|----------------------------|------------------------------------|------------------------------------|-----------------------------------|------------------------|-----------------------|--------------------------------|------------------------------|-----------------------|---------------|
| GLAC-0212A | 37391 | RISING SUN LODGE ROAD A | 3 | AS | 0.19 | 87 | NR | 87 | 97 | 100 | 97 | 99 | 97 | 87 |
| GLAC-0212B | 103845 | RISING SUN LODGE ROAD B | 3 | AS | 0.06 | 77 | NR | 77 | 97 | 100 | 97 | 98 | 92 | 77 |
| GLAC-0212C | 103846 | RISING SUN LODGE ROAD C | 3 | AS | 0.04 | 80 | NR | 80 | 98 | 100 | 98 | 90 | 100 | 80 |
| GLAC-0212D | 231844 | RISING SUN LODGE ROAD D | 3 | AS | 0.08 | 0 | NR | NR | NR | NR | NR | NR | NR | NR |
| GLAC-0212F | 231853 | RISING SUN LODGE ROAD F | 3 | AS | 0.10 | 93 | NR | 93 | 93 | 100 | 93 | 100 | 100 | 93 |
| GLAC-0213A | 6776 | rising sun campground road a | 3 | AS | 0.40 | 78 | NR | 78 | 78 | 99 | 79 | 94 | 91 | 86 |
| GLAC-0213B | 103850 | rising sun campground road b | 3 | AS | 0.40 | 83 | NR | 83 | 88 | 100 | 88 | 96 | 96 | 83 |
| GLAC-0214 | 6770 | ST. MARY CAMPGROUND ENTRANCE ROAD | 3 | AS | 0.20 | 84 | NR | 84 | 93 | 97 | 96 | 100 | 99 | 84 |
| GLAC-0214A | 103841 | ST. MARY CAMPGROUND LOOP A | 3 | AS | 0.45 | 63 | NR | 81 | 97 | 100 | 97 | 99 | 99 | 81 |
| GLAC-0214B | 103843 | ST. MARY CAMPGROUND LOOP B | 3 | AS | 0.48 | 77 | NR | 77 | 100 | 100 | 100 | 97 | 100 | 77 |
| GLAC-0214C | 103853 | ST. MARY CAMPGROUND LOOP C | 3 | AS | 0.60 | 78 | NR | 78 | 93 | 100 | 93 | 78 | 100 | 83 |
| GLAC-0240 | 6832 | WALTON RANGER STATION ROAD | 3 | AS | 0.07 | 92 | NR | 92 | 96 | 100 | 96 | 100 | 100 | 92 |
| GLAC-0241 | 107768 | HUCKLEBERRY MOUNTAIN ROAD | 3 | AS | 0.24 | 90 | NR | 90 | 99 | 100 | 99 | 100 | 100 | 90 |
| GLAC-0242 | 6815 | SPRAGUE CREEK CAMPGROUND ROAD | 3 | AS | 0.19 | 65 | NR | 65 | 65 | 97 | 68 | 80 | 98 | 89 |
| GLAC-0245 | 231848 | STEWART MOTEL ROAD | 3 | AS | 0.04 | 46 | NR | 46 | 46 | 90 | 56 | 84 | 94 | <i>7</i> 1 |
| GLAC-0246 | 247550 | APGAR TRANSIT CENTER SHUTTLE LOOP | 3 | AS | 0.13 | 92 | NR | 92 | 100 | 100 | 100 | 99 | 100 | 92 |
| GLAC-0400 | 6802 | HEADQUARTERS ROAD | 5 | AS | 0.28 | 85 | NR | 85 | 85 | 100 | 85 | 95 | 100 | 96 |
| GLAC-0401 | 6785 | MANY GLACIER HOUSING AREA ROAD | 5 | AS | 0.25 | 93 | NR | 93 | 98 | 100 | 98 | 100 | 96 | 93 |
| GLAC-0402 | 6772 | ST. MARY HOUSING AREA ROAD | 6 | AS | 0.36 | 79 | NR | 89 | 90 | 99 | 91 | 99 | 99 | 89 |



Road Condition Summary Report for Data Collection Vehicle (DCV) Rated Roads

Glacier National Park

Condition (Rating / Index) Legend

GOOD (85 - 94)

FAIR (61 - 84)

POOR (0 - 60)

NR = NOT RATED

Notes:

- This condition summary report contains only the roads rated with the Data Collection Vehicle (DCV).
- Condition on roads that were manually rated and parking areas are shown in separate reports.
- Additional details on individual road ratings can be found in Section 5 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

| Route No. | Route- | Level Condition for Roads Rated with the Data Collection Route Name | Functional | Surf. Type | Paved Length (Miles) | Pavement Condition Rating (PCR) | Roughness Condition Index (RCI) | Surface Condition Rating (SCR) | Structural Crack Index | Alligator Crack Index | Longitudinal Cracking Index | Transverse Cracking Index | Patch / Pothole Index | Rutting Index |
|------------|--------|--|------------|---------------|----------------------------|------------------------------------|------------------------------------|-----------------------------------|------------------------|-----------------------|--------------------------------|------------------------------|-----------------------|---------------|
| GLAC-0404 | 6811 | GRIST ROAD | 3 | AS | 0.37 | 91 | NR | 91 | 99 | 100 | 99 | 99 | 99 | 91 |
| GLAC-0407 | 6805 | CAMEL'S HUMP ROAD | 3 | AS | 0.13 | 94 | NR | 94 | 97 | 100 | 97 | 100 | 100 | 94 |
| GLAC-0409A | 38466 | GRINNELL DRIVE | 5 | AS | 0.17 | 81 | NR | 81 | 81 | 100 | 81 | 92 | 100 | 86 |
| GLAC-0409B | 107694 | LOGAN LANE | 5 | AS | 0.35 | 62 | NR | 62 | 62 | 100 | 62 | 81 | 99 | 94 |
| GLAC-0409C | 107695 | SPERRY DRIVE | 5 | AS | 0.15 | 98 | NR | 98 | 99 | 100 | 99 | 98 | 100 | 99 |
| GLAC-0409D | 107696 | ALBRIGHT CIRCLE | 5 | AS | 0.33 | 96 | NR | 96 | 98 | 100 | 98 | 99 | 100 | 96 |
| GLAC-0409E | 107697 | MATHER DRIVE | 5 | AS | 0.32 | 87 | NR | 87 | 87 | 99 | 88 | 97 | 100 | 94 |
| GLAC-0409F | 107698 | RUHLE DRIVE | 5 | AS | 0.17 | 82 | NR | 82 | 82 | 99 | 83 | 96 | 100 | 95 |
| GLAC-0410A | 107699 | HEADQUARTERS ADMINISTRATIVE ROAD A | 5 | AS | 0.22 | 57 | NR | 57 | 57 | 87 | 70 | 90 | 98 | 92 |
| GLAC-0410B | 107700 | HEADQUARTERS ADMINISTRATIVE ROAD B (VINT BOULEVARD) | 5 | AS | 0.14 | 82 | NR | 82 | 82 | 100 | 82 | 87 | 99 | 87 |
| GLAC-0425 | 247574 | ST. MARY RESIDENCE AND HORSE STABLES ROAD | 6 | AS | 0.05 | 36 | NR | 36 | 36 | 68 | 68 | 75 | 99 | 88 |
| GLAC-0426 | 247575 | ST. MARY RESIDENCE / DIVIDE CREEK ACCESS | 6 | AS | 0.08 | 83 | NR | 83 | 83 | 98 | 85 | 85 | 99 | 89 |



Road Condition Summary Report for Manually Rated Roads

EXCELLENT (95 - 100) GOOD (85 - 94) FAIR (61 - 84) POOR (0 - 60) NR = NOT RATED

Condition (Rating / Index) Legend

Glacier National Park

Notes:

- This condition summary report contains only the roads that were manually rated.
 - MRL = Manually Rated Line (a linear road)
 - o MRP = Manually Rated Polygon (a non-linear road)
- Condition on roads that were rated with the Data Collection Vehicle (DCV) are shown in a separate report.
- A road is manually rated when it is determined to be unsuitable for the DCV to drive.
- Additional details on individual road ratings can be found in Section 5 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

| Route No. | FMSS No. | Route-Level Condition for Manually Rated Line (MRL) Roads Route Name | Functiona Class | ıl Surf. Type | Paved Length | Pavement Condition Rating (PCR) | Roughness Condition Index (RCI) | Surface Condition Rating (SCR) | Structural Crack Index | Alligator Crack Index | Longitudinal Cracking Index | Transverse Cracking Index | Patch / Pothole Index | Ruffing Index |
|--------------|----------|---|--------------------|------------------|-----------------|------------------------------------|------------------------------------|-----------------------------------|------------------------|-----------------------|--------------------------------|------------------------------|-----------------------|---------------|
| GLAC-0201CAZ | 38749 | AVALANCHE CAMPGROUND SERVICE ROAD | 6 | AS | 0.17 | 30 | NR | 30 | NR | 30 | 73 | 73 | 30 | 53 |
| GLAC-0201CBZ | 38749 | AVALANCHE CAMPGROUND SERVICE SPUR | 6 | AS | 0.04 | 30 | NR | 30 | NR | 53 | 73 | 73 | 30 | 53 |
| GLAC-0244 | 37217 | MANY GLACIER BOAT RAMP ACCESS ROAD | 3 | AS | 0.05 | 90 | NR | 90 | NR | 90 | 97 | 90 | 90 | 90 |
| GLAC-0408 | 6817 | LAKE MCDONALD HORSE STABLES ROAD | 5 | AS | 0.07 | 73 | NR | 73 | NR | 73 | 90 | 90 | 90 | 90 |



Parking Area Condition Summary Report

Glacier National Park

EXCELLENT (97) GOOD (90) FAIR (73) POOR* (0, 30, 53) NR = NOT RATED

Condition (Rating / Index) Legend

Notes:

- A PCR of 0 indicates a paved parking area in very poor condition. Individual distresses could not be identified.
- Additional details on individual parking areas can be found in Section 6 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

| | | | | | | | <u> </u> | <u>sphalt</u> | Surfa | ce Dis | stress | <u>es</u> | Conc | rete Su | urface l | <u>Distresses</u> |
|------------|----------|--|----------------|---------------|-------------------|------------------------------------|--------------------|--------------------------------------|-----------------------|---------------------|--------------|--------------------------------|----------------|---------------|------------------|---|
| Route No. | FMSS No. | Condition Rating Details for Parking Areas Route Name | User Access | Surf. Type | Area (Sq. Ft.) | Pavement Condition Rating (PCR) | Alligator Cracking | Longitudinal / Tranverse Cracking | Rutting / Distortions | Potholes / Patching | HMA Patching | Surface Raveling / Bleeding | Joint Faulting | Slab Cracking | Joint Distresses | Delamination / Pop-Outs Potholes / Patching |
| GLAC-0900 | 37337 | HEADQUARTERS VISITOR PARKING | PUBLIC | AS | 15,231 | 30 | 30 | 53 | 53 | 53 | 97 | 90 | | | | |
| GLAC-0901A | 6806 | HEADQUARTERS EMPLOYEE PARKING | NONPUBLIC | C AS | 28,572 | 30 | 30 | 53 | 30 | 53 | 97 | 73 | | | | |
| GLAC-0901B | 107701 | HEADQUARTERS LIBRARY PARKING | PUBLIC | AS | 1,103 | 73 | 97 | 97 | 73 | 97 | 97 | 90 | | | | |
| GLAC-0901C | 107702 | HEADQUARTERS MAINTENANCE BUILDING PARKING | NONPUBLIC | C AS | 3,688 | 30 | 30 | 90 | 30 | 53 | 97 | 73 | | | | |
| GLAC-0901D | 107703 | HEADQUARTERS MAINTENANCE AREA PARKING (SCOYEN CIRCLE) | NONPUBLIC | C AS | 81,132 | 30 | 30 | 53 | 30 | 73 | 97 | 73 | | | | |
| GLAC-0901E | 107705 | HEADQUARTERS ELECTRONIC OFFICE PARKING | NONPUBLIC | C AS | 1,219 | 53 | 90 | 90 | 53 | 73 | 97 | 90 | | | | |
| GLAC-0901F | 248437 | HEADQUARTERS FUELING AREA | NONPUBLIC | C AS | 19,665 | 30 | 30 | 53 | 53 | 30 | 97 | 73 | | | | |
| GLAC-0903 | 37390 | SCHOOL HOUSE PARKING | PUBLIC | AS | 6,453 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0904A | 37311 | APGAR PUBLIC PARKING A | PUBLIC | AS | 2,196 | 90 | 97 | 97 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0904B | 107706 | APGAR PUBLIC PARKING B | PUBLIC | AS | 11,973 | 90 | 90 | 90 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0905 | 37314 | APGAR VILLAGE COMPLEX PARKING | PUBLIC | AS | 51,077 | 90 | 90 | 90 | 90 | 90 | 90 | 90 | | | | |
| GLAC-0906 | 37303 | APGAR BOAT LAUNCH PARKING | PUBLIC | AS | 11,320 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0907 | 37312 | APGAR RANGERS / RESTROOM PARKING | PUBLIC | AS | 19,821 | 73 | 73 | 90 | 73 | 90 | 90 | 90 | | | | |
| GLAC-0908A | 6808 | APGAR AMPHITHEATER PARKING A | PUBLIC | AS | 2,284 | 90 | 90 | 90 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0908B | 103528 | APGAR AMPHITHEATER PARKING B | PUBLIC | AS | 5,345 | 90 | 90 | 90 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0909 | 6810 | APGAR PICNIC LOOP | PUBLIC | AS | 29,482 | 73 | 73 | 90 | 90 | 90 | 97 | 90 | | | | |
| GLAC-0911 | 6813 | FISH CREEK PICNIC AREA PARKING | PUBLIC | AS | 22,616 | 53 | 53 | 90 | 73 | 73 | 97 | 90 | | | | |
| GLAC-0913 | 7708 | FISH CREEK RANGER RESIDENCE PARKING | NONPUBLIC | C AS | 7,008 | 53 | 53 | 90 | 73 | 97 | 97 | 90 | | | | |
| GLAC-0914A | 37397 | FISH CREEK CAMPGROUND DUMP STATION | PUBLIC | AS | 2,799 | 73 | 97 | 90 | 73 | 90 | 97 | 90 | | | | |
| GLAC-0914B | 38754 | FISH CREEK CAMPGROUND AMPHITHEATER PARKING | PUBLIC | AS | 15,205 | 53 | 73 | 53 | 73 | 90 | 97 | 90 | | | | |
| GLAC-0915 | 37371 | MCGEE MEADOWS PARKING | PUBLIC | AS | 7,995 | 90 | 97 | 97 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0916 | 37166 | HUCKLEBERRY LOOKOUT TRAILHEAD PARKING | PUBLIC | AS | 6,125 | 90 | 97 | 97 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0917 | 37319 | CAMAS CREEK OVERLOOK PARKING | PUBLIC | AS | 16,610 | 90 | 97 | 97 | 97 | 97 | 97 | 90 | | | | |
| GLAC-0918 | 37318 | CAMAS CREEK ENTRANCE STATION PARKING | PUBLIC | AS | 4,615 | 90 | 97 | 97 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0919 | 6822 | HUCKLEBERRY MOUNTAIN TRAILHEAD PARKING | PUBLIC | AS | 1,950 | 90 | 97 | 97 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0922 | 37167 | LAKESHORE FOREST PARKING | PUBLIC | AS | 6,170 | 90 | 97 | 90 | 90 | 90 | 97 | 90 | | | | |



Parking Area Condition Summary Report

Glacier National Park

EXCELLENT (97) GOOD (90) FAIR (73)

Condition (Rating / Index) Legend

POOR* (0, 30, 53)

NR = NOT RATED

Road Inventory Program

Notes:

- A PCR of 0 indicates a paved parking area in very poor condition. Individual distresses could not be identified.
- Additional details on individual parking areas can be found in Section 6 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

| | | | | | | | <u>A</u> | <u>sphalt</u> | Surfa | ice Di | stress | <u>ies</u> | Conc | rete Su | ırface | Distres | sses |
|-------------|----------|--|-----------|-------|----------------|------------------------------------|--------------------|--------------------------------------|-----------------------|---------------------|--------------|--------------------------------|--------------|-------------|----------------|----------------|---------------------|
| | | Condition Rating Details for Parking Areas | User | Surf. | Area | Pavement Condition Rating (PCR) | Alligator Cracking | Longitudinal / Tranverse Cracking | Rutting / Distortions | Potholes / Patching | HMA Patching | Surface Raveling / Bleeding | int Faulting | ıb Cracking | int Distresses | ninati Outs | Potholes / Patching |
| Route No. | FMSS No. | Route Name | Access | Type | (Sq. Ft.) | Pav Rati | ₹ | 고 논 | Ru | Po | ≨ | Su | Joint | Slab | Joint | Pop-(| Po |
| GLAC-0923 | 37171 | LINCOLN LAKE PARKING | PUBLIC | AS | 4,439 | 90 | 97 | 90 | 90 | 97 | 90 | 90 | | | · | | |
| GLAC-0926A | 6818 | LAKE MCDONALD LODGE PARKING | PUBLIC | AS | 10,881 | 73 | 97 | 97 | 90 | 73 | 97 | 73 | | | | | |
| GLAC-0926B | 103592 | LAKE MCDONALD CABIN LOOP AND PARKING | PUBLIC | AS | 11,453 | 73 | 97 | 97 | 90 | 97 | 90 | 73 | | | | | |
| GLAC-0927 | 37360 | LAKE MCDONALD GENERAL PARKING | PUBLIC | AS | 56,158 | 90 | 90 | 90 | 90 | 97 | 90 | 90 | | | | | |
| GLAC-0928A | 37357 | LAKE MCDONALD RESTAURANT PARKING | PUBLIC | AS | 14,575 | 90 | 97 | 97 | 97 | 97 | 90 | 90 | | | | | |
| GLAC-0928B | 107707 | LAKE MCDONALD RESTAURANT REAR PARKING | NONPUBLIC | : AS | 8,955 | 90 | 97 | 97 | 97 | 97 | 97 | 90 | | | | | |
| GLAC-0929 | 37349 | LAKE MCDONALD POST OFFICE PARKING | PUBLIC | AS | 7,422 | 53 | 53 | 90 | 73 | 73 | 90 | 73 | | | | | |
| GLAC-0930 | 8341 | LAKE MCDONALD GENERAL STORE PARKING | PUBLIC | AS | 8,554 | 73 | 73 | 90 | 90 | 90 | 90 | 90 | | | | | |
| GLAC-0932 | 6797 | MCDONALD CREEK OVERLOOK | PUBLIC | AS | 9,255 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-0934A | 38751 | AVALANCHE CAMPGROUND PARKING A / RANGER RESIDENCE PARKING | PUBLIC | AS | 1,179 | 90 | 97 | 97 | 90 | 97 | 97 | 97 | | | | | |
| GLAC-0934B | 103544 | AVALANCHE CAMPGROUND PARKING B | PUBLIC | AS | 2,796 | 90 | 97 | 97 | 90 | 97 | 97 | 97 | | | | | |
| GLAC-0934C | 103550 | AVALANCHE CAMPGROUND PARKING C | PUBLIC | AS | 1,235 | 90 | 97 | 97 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-0934D | 103563 | AVALANCHE CAMPGROUND HANDICAPPED PARKING (TRAIL OF THE CEDARS) | PUBLIC | AS | 4,139 | 30 | 53 | 53 | 30 | 30 | 97 | 73 | | | | | |
| GLAC-0935 | 247576 | RED ROCK POINT PARKING | PUBLIC | AS | 9,624 | 90 | 97 | 97 | 97 | 97 | 97 | 90 | | | | | |
| GLAC-0938A | 6798 | LOOP PARKING AREA A | PUBLIC | AS | 5,060 | 90 | 97 | 97 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-0938B | 103605 | LOOP PARKING AREA B | PUBLIC | AS | 6,474 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-0939A | 6801 | ROAD CAMP PARKING AREA A | PUBLIC | AS | 2,324 | 90 | 97 | 97 | 97 | 97 | 97 | 90 | | | | | |
| GLAC-0939B | 103861 | ROAD CAMP PARKING AREA B | PUBLIC | AS | 2,327 | 90 | 97 | 90 | 97 | 97 | 97 | 90 | | | | | |
| GLAC-0941AZ | 247577 | BIG BEND PARKING A | PUBLIC | AS | 11,649 | 90 | 97 | 97 | 97 | 97 | 97 | 90 | | | | | |
| GLAC-0941BZ | 247577 | BIG BEND PARKING B | PUBLIC | AS | 8 , 371 | 90 | 97 | 97 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-0942 | 37372 | OBERLIN BEND PARKING | PUBLIC | AS | 6,396 | 73 | 97 | 97 | 97 | 97 | 73 | 90 | | | | | |
| GLAC-0943 | 6779 | LOGAN PASS PARKING | PUBLIC | AS | 114,883 | 90 | 97 | 90 | 90 | 90 | 90 | 90 | | | | | |
| GLAC-0944 | 6765 | LUNCH CREEK PARKING | PUBLIC | AS | 8,587 | 90 | 97 | 97 | 97 | 97 | 97 | 90 | | | | | |
| GLAC-0945AZ | 247578 | SIYEH BEND PARKING A | PUBLIC | AS | 6,499 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | | |
| GLAC-0945BZ | 247578 | SIYEH BEND PARKING B | PUBLIC | AS | 3,188 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | | |
| GLAC-0945CZ | 247578 | SIYEH BEND PARKING C | PUBLIC | AS | 3,218 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | | |



Parking Area Condition Summary Report

Condition (Rating / Index) Legend

EXCELLENT (97)

GOOD (90)

FAIR (73)

POOR* (0, 30, 53)

NR = NOT RATED

Glacier National Park

Notes:

- A PCR of 0 indicates a paved parking area in very poor condition. Individual distresses could not be identified.
- Additional details on individual parking areas can be found in Section 6 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

| | | | | | | | <u>A</u> | <u>sphalt</u> | Surfo | ice Dis | stress | <u>es</u> | Conc | rete Si | <u>urface</u> | Distre | sses |
|-------------|----------|--|----------------|---------------|-------------------|------------------------------------|--------------------|--------------------------------------|-----------------------|---------------------|--------------|--------------------------------|----------------|---------------|------------------|----------------------------|---------------------|
| Route No. | FMSS No. | Condition Rating Details for Parking Areas Route Name | User Access | Surf. Type | Area (Sq. Ft.) | Pavement Condition Rating (PCR) | Alligator Cracking | Longitudinal / Tranverse Cracking | Rutting / Distortions | Potholes / Patching | HMA Patching | Surface Raveling / Bleeding | Joint Faulting | Slab Cracking | Joint Distresses | Delamination / Pop-Outs | Potholes / Patching |
| GLAC-0945DZ | 247578 | SIYEH BEND PARKING D | PUBLIC | AS | 1,298 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | | |
| GLAC-0945EZ | 247578 | SIYEH BEND PARKING E | PUBLIC | AS | 4,011 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | | |
| GLAC-0945FZ | 247578 | SIYEH BEND PARKING F | PUBLIC | AS | 3,885 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | | |
| GLAC-0946A | 6766 | JACKSON GLACIER OVERLOOK PARKING | PUBLIC | AS | 5,167 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | | |
| GLAC-0946B | 103585 | GUNSIGHT TRAILHEAD PARKING | PUBLIC | AS | 6,516 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | | |
| GLAC-0947 | 6767 | SUNRIFT GORGE PARKING (PAVED) | PUBLIC | AS | 4,333 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | | |
| GLAC-0948 | 6768 | SUN POINT PICNIC AREA PARKING | PUBLIC | AS | 63,363 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | | |
| GLAC-0949A | 37243 | WILD GOOSE ISLAND PARKING A | PUBLIC | AS | 3,587 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | | |
| GLAC-0949B | 103868 | WILD GOOSE ISLAND PARKING B | PUBLIC | AS | 8,053 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | | |
| GLAC-0950 | 6778 | RISING SUN BOAT TOURS PARKING | PUBLIC | AS | 64,527 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-0951A | 6775 | rising sun motel bus parking | PUBLIC | AS | 8,481 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-0951B | 103873 | RISING SUN MOTEL AND RESTAURANT PARKING | PUBLIC | AS | 60,203 | 90 | 97 | 90 | 90 | 97 | 90 | 90 | | | | | |
| GLAC-0951C | 103876 | RISING SUN MOTEL REAR STORE PARKING | NONPUBLIC | AS | 7,652 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-0951D | 103877 | RISING SUN LOWER MOTEL PARKING (SOUTH) | PUBLIC | AS | 5,016 | 30 | 90 | 90 | 30 | 30 | 97 | 73 | | | | | |
| GLAC-0951E | 103878 | rising sun lower motel parking (north) | PUBLIC | AS | 3,743 | 0 | | | | | | | | | | | |
| GLAC-0951F | 103879 | RISING SUN UPPER MOTEL PARKING (SOUTH) | PUBLIC | AS | 5,143 | 0 | | | | | | | | | | | |
| GLAC-0951G | 103881 | RISING SUN UPPER MOTEL PARKING (NORTH) | PUBLIC | AS | 3,036 | 0 | | | | | | | | | | | |
| GLAC-0951H | 107708 | RISING SUN RESTAURANT REAR PARKING | NONPUBLIC | AS | 5,380 | 53 | 73 | 53 | 53 | 53 | 97 | 73 | | | | | |
| GLAC-0953 | 6777 | rising sun picnic area parking | PUBLIC | AS | 44,582 | 90 | 97 | 90 | 90 | 90 | 97 | 90 | | | | | |
| GLAC-0954 | 37240 | TWO DOG FLATS PARKING | PUBLIC | AS | 3,699 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | | |
| GLAC-0955A | 103882 | ST. MARY CAMPGROUND PARKING A / DUMP STATION | PUBLIC | AS | 2,108 | 53 | 73 | 90 | 53 | 73 | 97 | 90 | | | | | |
| GLAC-0955B | 103884 | ST. MARY CAMPGROUND PARKING B | PUBLIC | AS | 897 | 30 | 30 | 90 | 30 | 53 | 97 | 73 | | | | | |
| GLAC-0955C | 103885 | ST. MARY CAMPGROUND PARKING C | PUBLIC | AS | 2,157 | 0 | | | | | | | | | | | |
| GLAC-0955D | 103886 | ST. MARY CAMPGROUND PARKING D | PUBLIC | AS | 1,123 | 53 | 90 | 53 | 53 | 53 | 97 | 73 | | | | | |
| GLAC-0955E | 103888 | ST. MARY CAMPGROUND PARKING E | PUBLIC | AS | 467 | 30 | 90 | 53 | 30 | 97 | 97 | 90 | | | | | |
| GLAC-0955F | 103889 | ST. MARY CAMPGROUND PARKING F | PUBLIC | AS | 932 | 73 | 97 | 97 | 73 | 97 | 97 | 73 | | | | | |



Parking Area Condition Summary Report

EXCELLENT (97) GOOD (90) FAIR (73) POOR* (0, 30, 53)

NR = NOT RATED

Condition (Rating / Index) Legend

Glacier National Park

Notes:

- A PCR of 0 indicates a paved parking area in very poor condition. Individual distresses could not be identified.
- Additional details on individual parking areas can be found in Section 6 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

| | | | | | | | <u> </u> | \sphalt | Surfa | ce Dis | stress | <u>es</u> | Conc | rete Su | urface | Distress | <u>ses</u> |
|------------|----------|--|-----------|-------|-----------|------------------------------------|--------------------|--------------------------------------|-----------------------|---------------------|--------------|--------------------------------|----------------|---------------|------------------|--------------|---------------------|
| | | Condition Rating Details for Parking Areas | User | Surf. | Area | Pavement Condition Rating (PCR) | Alligator Cracking | Longitudinal / Tranverse Cracking | Rutting / Distortions | Potholes / Patching | HMA Patching | Surface Raveling / Bleeding | Joint Faulting | Slab Cracking | Joint Distresses | = . | Potholes / Patching |
| Route No. | FMSS No. | Route Name | Access | Туре | (Sq. Ft.) | ۾ ۾ | _ | | | | | _ | <u> </u> | SI | ا ۲ | ם ק | <u>~</u> |
| GLAC-0955G | 103890 | ST. MARY CAMPGROUND PARKING G | PUBLIC | AS | 924 | 30 | 30 | 53 | 30 | 53 | 97 | 73 | | | | | |
| GLAC-0955H | 103891 | ST. MARY CAMPGROUND PARKING H | PUBLIC | AS | 842 | 30 | 30 | 53 | 53 | 73 | 97 | 73 | | | | | |
| GLAC-09551 | 103892 | ST. MARY CAMPGROUND PARKING I | PUBLIC | AS | 945 | 53 | 73 | 53 | 53 | 53 | 97 | 73 | | | | | |
| GLAC-0955J | 103893 | ST. MARY CAMPGROUND PARKING J | PUBLIC | AS | 691 | 30 | 73 | 53 | 30 | 90 | 97 | 90 | | | | | |
| GLAC-0955K | 103894 | ST. MARY CAMPGROUND PARKING K | PUBLIC | AS | 1,097 | 30 | 30 | 90 | 53 | 53 | 97 | 73 | | | | | |
| GLAC-0955L | 103896 | ST. MARY CAMPGROUND PARKING L | PUBLIC | AS | 740 | 53 | 53 | 53 | 53 | 97 | 97 | 90 | | | | | |
| GLAC-0955M | 248438 | ST. MARY CAMPGROUND PARKING M | PUBLIC | AS | 962 | 0 | | | | | | | | | | | |
| GLAC-0955N | 248439 | ST. MARY CAMPGROUND PARKING N | PUBLIC | AS | 1,280 | 0 | | | | | | | | | | | |
| GLAC-0956 | 37384 | ST. MARY RIVER PARKING | PUBLIC | AS | 2,892 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | | |
| GLAC-0957 | 6773 | ST. MARY VISITOR CENTER PARKING | PUBLIC | AS | 94,940 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-0958 | 37385 | ST. MARY TREATMENT PLANT PARKING | NONPUBLIC | C AS | 4,872 | 30 | 30 | 53 | 53 | 53 | 97 | 90 | | | | | |
| GLAC-0959A | 6774 | ST. MARY MAINTENANCE AREA PARKING A (HUDSON BAY DISTRICT OFFICE) | PUBLIC | AS | 1,539 | 73 | 90 | 90 | 73 | 97 | 97 | 73 | | | | | |
| GLAC-0959B | 107710 | ST. MARY MAINTENANCE AREA PARKING B (HUDSON BAY DISTRICT OFFICE) | NONPUBLIC | | 37,906 | 30 | 30 | 53 | 53 | 30 | 90 | 73 | | | | | |
| GLAC-0959C | 107711 | ST. MARY MAINTENANCE AREA PARKING C (HUDSON BAY DISTRICT OFFICE) | NONPUBLIC | | 1,228 | 53 | 53 | 90 | 53 | 97 | 97 | 73 | | | | | |
| GLAC-0960A | 8329 | ST. MARY RESIDENCE AREA PARKING A | NONPUBLIC | C AS | 1,925 | 53 | 73 | 53 | 73 | 97 | 97 | 90 | | | | | |
| GLAC-0960B | 107712 | ST. MARY RESIDENCE AREA PARKING B | NONPUBLIC | C AS | 1,952 | 0 | | | | | | | | | | | |
| GLAC-0960C | 107714 | ST. MARY RESIDENCE AREA PARKING C | NONPUBLIC | C AS | 1,582 | 0 | | | | | | | | | | | |
| GLAC-0962 | 6833 | GOAT LICK OVERLOOK PARKING | PUBLIC | AS | 34,619 | 53 | 90 | 53 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-0964 | 37380 | RUNNING EAGLE FALLS PARKING | PUBLIC | AS | 12,113 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-0965 | 6793 | TWO MEDICINE STORE PARKING | PUBLIC | AS | 30,445 | 53 | 90 | 53 | 73 | 73 | 97 | 73 | | | | | |
| GLAC-0966A | 37296 | TWO MEDICINE RANGER STATION PARKING A | PUBLIC | AS | 2,204 | 73 | 97 | 90 | 73 | 97 | 97 | 73 | | | | | |
| GLAC-0966B | 107715 | TWO MEDICINE RANGER STATION PARKING B | NONPUBLIC | C AS | 4,032 | 53 | 90 | 53 | 73 | 90 | 97 | 90 | | | | | |
| GLAC-0967 | 37234 | POIA LAKE PARKING | PUBLIC | AS | 3,978 | 73 | 90 | 90 | 90 | 97 | 97 | 73 | | | | | |
| GLAC-0968A | 232113 | MANY GLACIER EMPLOYEE DORM PARKING | NONPUBLIC | C AS | 1,363 | 73 | 97 | 90 | 90 | 90 | 97 | 73 | | | | | |
| GLAC-0968B | 107716 | MANY GLACIER HOTEL HANDICAP PARKING | PUBLIC | AS | 2,835 | 90 | 97 | 97 | 90 | 97 | 90 | 90 | | | | | |
| GLAC-0968C | 107717 | MANY GLACIER HOTEL TRAILHEAD PARALLEL PARKING | PUBLIC | AS | 1,888 | 30 | 30 | 53 | 73 | 90 | 97 | 90 | | | | | |



Parking Area Condition Summary Report

EXCELLENT (97) GOOD (90) **FAIR (73)** POOR* (0, 30, 53) NR = NOT RATED

Condition (Rating / Index) Legend

Glacier National Park

Notes:

- A PCR of 0 indicates a paved parking area in very poor condition. Individual distresses could not be identified.
- Additional details on individual parking areas can be found in Section 6 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

| | | | | | | | <u>A</u> | <u>sphalt</u> | Surfa | ice Di | stress | <u>ies</u> | Conci | ete Su | rface Di | stresses |
|------------|----------|---|----------------|---------------|-----------------------|------------------------------------|--------------------|--------------------------------------|-----------------------|---------------------|--------------|--------------------------------|----------------|---------------|----------------------------------|---------------------------------|
| Route No. | FMSS No. | Condition Rating Details for Parking Areas Route Name | User Access | Surf. Type | Area (Sq. Ft.) | Pavement Condition Rating (PCR) | Alligator Cracking | Longitudinal / Tranverse Cracking | Rutting / Distortions | Potholes / Patching | HMA Patching | Surface Raveling / Bleeding | Joint Faulting | Slab Cracking | Joint Distresses Delamination / | Pop-Outs Potholes / Patching |
| GLAC-0968D | 107718 | MANY GLACIER HOTEL TRAILHEAD PARKING | PUBLIC | AS | 81,798 | 30 | 30 | 53 | 30 | 73 | 97 | 90 | | | | |
| GLAC-0968E | 232976 | MANY GLACIER HOTEL SOUTH PARKING | PUBLIC | AS | 5,030 | 53 | 53 | 53 | 73 | 53 | 97 | 73 | | | | |
| GLAC-0971 | 37222 | MANY GLACIER HELIPAD PARKING | NONPUBLIC | AS | 9,496 | 53 | 73 | 53 | 90 | 90 | 97 | 90 | | | | |
| GLAC-0972 | 6786 | MANY GLACIER PICNIC AREA / GRINNELL GLACIER TRAILHEAD PARKING | PUBLIC | AS | 24,332 | 53 | 53 | 53 | 73 | 53 | 97 | 73 | | | | |
| GLAC-0973A | 6790 | SWIFTCURRENT CABINS PARKING AREA A | PUBLIC | AS | <i>7,</i> 691 | 73 | 90 | 90 | 73 | 73 | 97 | 73 | | | | |
| GLAC-0973B | 240139 | SWIFTCURRENT CABINS PARKING AREA B / ICEBERG LAKE TRAILHEAD PARKING | PUBLIC | AS | 3,434 | 0 | | | | | | | | | | |
| GLAC-0973C | 103900 | SWIFTCURRENT CABINS PARKING AREA C | PUBLIC | AS | 7,429 | 53 | 90 | 90 | 53 | 90 | 97 | 73 | | | | |
| GLAC-0973D | 103901 | SWIFTCURRENT CABINS PARKING AREA D | PUBLIC | AS | 7,944 | 53 | 90 | 90 | 53 | 73 | 97 | 73 | | | | |
| GLAC-0973E | 103902 | SWIFTCURRENT CABINS PARKING AREA E | PUBLIC | AS | 10,266 | 53 | 73 | 90 | 53 | 73 | 97 | 73 | | | | |
| GLAC-0973F | 103899 | SWIFTCURRENT CABINS PARKING AREA F / PINETOP MOTEL | PUBLIC | AS | 5,214 | 30 | 90 | 90 | 53 | 30 | 97 | 73 | | | | |
| GLAC-0974 | 6789 | SWIFTCURRENT MOTOR INN PARKING | PUBLIC | AS | 58,655 | 90 | 90 | 90 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0975 | 37053 | CRUSHER HILL PARKING | PUBLIC | AS | 41,067 | 73 | 90 | 90 | 73 | 97 | 97 | 73 | | | | |
| GLAC-0976 | 6782 | BELLY RIVER TRAILHEAD PARKING | PUBLIC | AS | 25,973 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0983 | 38012 | GRIZZLY POINT PARKING | PUBLIC | AS | 14,697 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | |
| GLAC-0984 | 107719 | APGAR CAMPGROUND DUMP STATION | PUBLIC | AS | 2,380 | 90 | 97 | 90 | 90 | 90 | 90 | 90 | | | | |
| GLAC-0985 | 107720 | TWO MEDICINE CAMPGROUND DUMP STATION | PUBLIC | AS | 2,568 | 73 | 90 | 90 | 73 | 90 | 73 | 90 | | | | |
| GLAC-0986A | 107721 | LOGAN LANE PARKING A | NONPUBLIC | : AS | 4,237 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0986B | 107722 | LOGAN LANE PARKING B | NONPUBLIC | : AS | <i>7,</i> 61 <i>7</i> | 30 | 30 | 90 | 53 | 73 | 97 | 73 | | | | |
| GLAC-0987 | 107723 | HEADQUARTERS COMMUNITY BUILDING PARKING | PUBLIC | AS | 15,488 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0988 | 107724 | APGAR OLD VISITOR CENTER PARKING | PUBLIC | AS | 11,730 | 90 | 97 | 97 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0989A | 107725 | MANY GLACIER PARKING A / RANGER STATION | PUBLIC | AS | 2,312 | 73 | 90 | 97 | 73 | 73 | 97 | 73 | | | | |
| GLAC-0989B | 107726 | MANY GLACIER PARKING B | PUBLIC | AS | 3,459 | 30 | 90 | 90 | 53 | 30 | 90 | 73 | | | | |
| GLAC-0989C | 107727 | MANY GLACIER PARKING C / RESIDENCES | NONPUBLIC | : AS | 9,592 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | |
| GLAC-0990 | 107728 | MANY GLACIER DUMP STATION | PUBLIC | AS | 2,347 | 73 | 90 | 90 | 73 | 73 | 97 | 90 | | | | |
| GLAC-0991 | 107729 | MANY GLACIER ENTRANCE STATION PARKING | PUBLIC | AS | 3,749 | 73 | 97 | 97 | 90 | 90 | 97 | 73 | | | | |
| GLAC-0992A | 107730 | TWO MEDICINE CAMPGROUND PARKING A | PUBLIC | AS | 1,849 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | |



Parking Area Condition Summary Report

EXCELLENT (97) GOOD (90) FAIR (73) POOR* (0, 30, 53) NR = NOT RATED

Condition (Rating / Index) Legend

Glacier National Park

Notes:

- A PCR of 0 indicates a paved parking area in very poor condition. Individual distresses could not be identified.
- Additional details on individual parking areas can be found in Section 6 of the Cycle 6 RIP Report.
- Refer to the RIP Report Appendix for an explanation of the rating system and rating methods.

| | | | | | | | <u>A</u> | <u>sphalt</u> | Surfa | ice Dis | stress | <u>es</u> | Conci | ete Su | <u>ırface</u> | Distre | <u>esses</u> |
|-------------|----------|--|----------------|---------------|-------------------|------------------------------------|--------------------|--------------------------------------|-----------------------|---------------------|--------------|--------------------------------|----------------|---------------|------------------|----------------------------|---------------------|
| Route No. | FMSS No. | Condition Rating Details for Parking Areas Route Name | User Access | Surf. Type | Area (Sq. Ft.) | Pavement Condition Rating (PCR) | Alligator Cracking | Longitudinal / Tranverse Cracking | Rutting / Distortions | Potholes / Patching | HMA Patching | Surface Raveling / Bleeding | Joint Faulting | Slab Cracking | Joint Distresses | Delamination / Pop-Outs | Potholes / Patching |
| GLAC-0992B | 107731 | TWO MEDICINE CAMPGROUND PARKING B | PUBLIC | AS | 3,661 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-0992C | 107732 | TWO MEDICINE CAMPGROUND PARKING C | PUBLIC | AS | 1 , 507 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-0993 | 107693 | TWO MEDICINE PICNIC AREA PARKING | PUBLIC | AS | 27,602 | 73 | 97 | 90 | 73 | 90 | 90 | 73 | | | | | |
| GLAC-0994 | 107738 | WEST GLACIER INFO KIOSK PARKING | PUBLIC | AS | 4,394 | 90 | 97 | 97 | 90 | 97 | 97 | 97 | | | | | |
| GLAC-0995AZ | 107739 | LOWER MCDONALD FALLS HANDICAPPED PARKING | PUBLIC | AS | 1,196 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-0995BZ | 107739 | LOWER MCDONALD FALLS PARKING | PUBLIC | AS | 3,811 | 90 | 97 | 90 | 97 | 97 | 97 | 90 | | | | | |
| GLAC-0996 | 107740 | RISING SUN CAMPGROUND DUMP STATION | PUBLIC | AS | 4,733 | 73 | 97 | 90 | 73 | 90 | 90 | 73 | | | | | |
| GLAC-0997 | 107741 | AVALANCHE SHUTTLE STOP PARKING | PUBLIC | AS | 8,097 | 90 | 97 | 97 | 97 | 97 | 97 | 90 | | | | | |
| GLAC-0998 | 107742 | PAVED HORSE BARN PARKING | NONPUBLIC | : AS | 2,800 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-1040 | 228276 | LAKE MCDONALD LEWIS DORM PARKING | PUBLIC | AS | 1,090 | 90 | 97 | 97 | 90 | 97 | 97 | 97 | | | | | |
| GLAC-1041 | 230217 | APGAR TRANSIT CENTER PARKING | PUBLIC | AS | 127,609 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-1044 | 6819 | AVALANCHE PICNIC AREA PARKING | PUBLIC | AS | 33,789 | 90 | 97 | 90 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-1045 | 37389 | SPRAGUE CREEK PICNIC AREA PARKING | PUBLIC | AS | 12,456 | 30 | 30 | 53 | 90 | 90 | 97 | 73 | | | | | |
| GLAC-1046 | 247581 | TRAIL OF THE CEDARS TRAILHEAD PARKING | PUBLIC | AS | 9,712 | 90 | 97 | 97 | 97 | 97 | 97 | 90 | | | | | |
| GLAC-1047 | 247582 | ST. MARY FALLS TRAILHEAD PARKING | PUBLIC | AS | 7,376 | 97 | 97 | 97 | 97 | 97 | 97 | 97 | | | | | |
| GLAC-1048 | 232111 | LAKE MCDONALD BUILDING 1012 CARETAKERS PARKING | NONPUBLIC | : AS | 1,201 | 90 | 90 | 90 | 90 | 97 | 97 | 90 | | | | | |
| GLAC-1049 | 232112 | LAKE MCDONALD REAR LODGE DELIVERY PARKING | NONPUBLIC | : AS | 4,488 | 30 | 30 | 90 | 30 | 53 | 97 | 73 | | | | | |
| GLAC-1050 | 232113 | MANY GLACIER HOTEL 15 MINUTE PARKING | PUBLIC | AS | 5,685 | 90 | 97 | 97 | 97 | 97 | 97 | 90 | | | | | |
| GLAC-1055 | 247583 | LOGAN CREEK RESTROOM PARKING | PUBLIC | AS | 4,709 | 90 | 97 | 97 | 97 | 97 | 97 | 90 | | | | | |


Section 4 Park Route Location Maps




Glacier National Park




ROUTE LOCATION MAP KEY MAP



Sources: Esri, HERE, DeLorme, USGS, Intermap, increment P Corp., NRCAN, Esri Japan, METI, Esri China (Hong Kong), Esri (Thailand), TomTom, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community



ROUTE LOCATION MAP MAP 1



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads.

| Miles | | |
|-------|---|------|
| | | |
| 0 | 5 | 5 10 |

ROUTE LOCATION MAP MAP 1A




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads.

| | Mi | les |
|---|----|-------|
| | | |
| 0 | 0. | 2 0.4 |

ROUTE LOCATION MAP MAP 1B



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads.

| Miles | | |
|-------|----|-----|
| | | |
| 0 | 0. | 5 1 |

ROUTE LOCATION MAP MAP 1C




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads. \\

| | Miles | |
|---|-------|---|
| | | |
| 0 | 0.5 | 1 |

ROUTE LOCATION MAP MAP 1D




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads.

| | Miles | |
|---|-------|---|
| | | |
| 0 | 0.5 | 1 |

ROUTE LOCATION MAP MAP 2




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads.

| Miles | | |
|-------|----|-----|
| | | |
| 0 | 2. | 5 5 |

ROUTE LOCATION MAP MAP 2A




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads.

| Miles | | |
|-------|-----|-----|
| | | |
| 0 | 0.2 | 0.4 |

ROUTE LOCATION MAP MAP 3




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads.

| | Miles | |
|---|-------|----|
| | | |
| 0 | 5 | 10 |

ROUTE LOCATION MAP MAP 3A



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads.

| | Miles | |
|---|-------|-----|
| | | |
| 0 | 0.2 | 0.4 |




ROUTE LOCATION MAP MAP 3B




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads.



ROUTE LOCATION MAP MAP 4



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads.



ROUTE LOCATION MAP MAP 4A




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads.

| | Mi | les | _ |
|---|----|-----|---|
| | | | |
| 0 | 0. | 5 | 1 |

ROUTE LOCATION MAP MAP 5



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads.

| | Miles | |
|---|-------|---|
| | | |
| 0 | 2 | 4 |

ROUTE LOCATION MAP MAP 5A



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community


Note: Unique colors are used to differentiate roads.

Non-NPS Collected Routes

| | Mi | es |
|---|----|-------|
| | | |
| 0 | 0. | 2 0.4 |




ROUTE LOCATION MAP MAP 6




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

Note: Unique colors are used to differentiate roads.


Non-NPS Collected Routes



ROUTE CONDITION MAP PCR - MILE BY MILE Key Map




Sources: Esri, HERE, DeLorme, USGS, Intermap, increment P Corp., NRCAN, Esri Japan, METI, Esri China (Hong Kong), Esri (Thailand), TomTom, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community






ROUTE CONDITION MAP PCR - MILE BY MILE Area Map 1




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community





Miles
5 10

ROUTE CONDITION MAP PCR - MILE BY MILE Area Map 1A



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community







ROUTE CONDITION MAP PCR - MILE BY MILE Area Map 1B



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community






ROUTE CONDITION MAP PCR - MILE BY MILE Area Map 1C



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community




Miles 0.5




ROUTE CONDITION MAP PCR - MILE BY MILE Area Map 1D




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community






ROUTE CONDITION MAP PCR - MILE BY MILE Area Map 2




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community






ROUTE CONDITION MAP PCR - MILE BY MILE Area Map 2A




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community




0.2 0.4



ROUTE CONDITION MAP PCR - MILE BY MILE Area Map 3



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community




Miles 5 10



ROUTE CONDITION MAP PCR - MILE BY MILE Area Map 3A




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community




0.4 0.8



ROUTE CONDITION MAP PCR - MILE BY MILE Area Map 3B




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community




| | Miles | |
|---|-------|---|
| | | |
| 0 | 0.5 | 1 |

ROUTE CONDITION MAP PCR - MILE BY MILE Area Map 4



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community






ROUTE CONDITION MAP PCR - MILE BY MILE Area Map 4A




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community




| | Mi | les | |
|---|----|-----|---|
| | | | ı |
| 0 | 0. | 5 | 1 |

ROUTE CONDITION MAP PCR - MILE BY MILE Area Map 5



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community







ROUTE CONDITION MAP PCR - MILE BY MILE Area Map 5A



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community







ROUTE CONDITION MAP PCR - MILE BY MILE Area Map 6




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community





Section 5 Paved Road Condition Rating Sheets



Glacier National Park



ROUTE 0010W: GOING TO THE SUN ROAD WEST


Data Collection Vehicle (DCV) Rating



| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | |
|--------------------------------|--|-----------------------------|-----------|-------------|------|--------|------|--|
| Poor (0 - 60) | Fair (61 | | (85 - 94) | Excellent (| | Not Ra | ted | |
| | ` | See Appendix for de | | ormulas | · · | | | |
| Inspection Date: 8/18/2 | 016 | Beginning Section MP | 0 | 1 | 2 | 3 | 4 | |
| Paved Length (Miles): 31.86 | | Section Length (MI) | 1 | 1 | 1 | 1 | 1 | |
| Surface Type: ASPH | ALT | Route Summary | | | | | | |
| Roadway Condition Informa | tion | | | | | | | |
| Pavement Condition Rating (| (PCR) | 99 | 89 | 94 | 95 | 97 | 99 | |
| Surface Condition Rating (SCI | R) | 99 | 90 | 91 | 91 | 95 | 99 | |
| Roughness Condition Index (R | CI) | 100 | 87 | 98 | 100 | 100 | 100 | |
| Distress Index Values | | | | | | | | |
| Structural Crack Index | | 99 | 91 | 96 | 91 | 95 | 100 | |
| Alligator Crack Index | | 100 | 100 | 100 | 100 | 100 | 100 | |
| Longitudinal Crack Index | | 99 | 91 | 96 | 91 | 95 | 100 | |
| Transverse Cracking Index | | 99 | 90 | 95 | 99 | 99 | 99 | |
| Patching Index | | 100 | 100 | 100 | 100 | 100 | 100 | |
| Rutting Index | | 99 | 92 | 91 | 100 | 99 | 99 | |
| International Roughness Inde | ex (IRI) | 95 | 150 | 119 | 99 | 97 | 87 | |
| Lane & Width Information | | | | | | | | |
| Number of Lanes | | 2 | 2 | 2 | 2 | 2 | 2 | |
| Paved Width (ft) | | 20.4 | 31.7 | 24.9 | 24.2 | 19.7 | 19.2 | |
| Lane Width (ft) | | 9.8 | 10.6 | 10.4 | 11.4 | 9.9 | 10 | |

ROUTE 0010W: GOING TO THE SUN ROAD WEST


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | tion Rating (| PCR) | | |
|---------------------|-------------------|-----------------------------|----------------|---------------|------|--------|------|
| Poor (0 - 60 | | | (85 - 94) | Excellent (| | Not Ra | ted |
| | | See Appendix for def | initions and f | ormulas | | | |
| Inspection Date: | 8/18/2016 | Beginning Section MP | 5 | 6 | 7 | 8 | 9 |
| Paved Length (Mile | es): 31.86 | Section Length (MI) | 1 | 1 | 1 | 1 | 1 |
| Surface Type: | ASPHALT | Route Summary | | | • | • | |
| Roadway Condition | n Information | | | | | | |
| Pavement Conditio | on Rating (PCR) | 99 | 99 | 98 | 99 | 99 | 99 |
| Surface Condition R | tating (SCR) | 99 | 98 | 97 | 98 | 99 | 99 |
| Roughness Conditio | n Index (RCI) | 100 | 100 | 100 | 100 | 100 | 100 |
| Distress Index Valu | es | | | | | | |
| Structural Crack In | dex | 99 | 98 | 97 | 98 | 99 | 100 |
| Alligator Crack Inc | lex | 100 | 100 | 100 | 100 | 100 | 100 |
| Longitudinal Crack | Index | 99 | 98 | 97 | 98 | 99 | 100 |
| Transverse Crackin | ig Index | 99 | 99 | 99 | 100 | 100 | 100 |
| Patching Index | | 100 | 100 | 100 | 100 | 100 | 100 |
| Rutting Index | | 99 | 99 | 99 | 99 | 99 | 99 |
| International Rough | hness Index (IRI) | 95 | 80 | 81 | 76 | 84 | 98 |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 2 | 2 | 2 | 2 | 2 | 2 |
| Paved Width (ft) | | 20.4 | 20.6 | 20 | 19.3 | 19.2 | 18.8 |
| Lane Width (ft) | | 9.8 | 10 | 10.3 | 9.6 | 9.4 | 9.4 |

ROUTE 0010W: GOING TO THE SUN ROAD WEST


Data Collection Vehicle (DCV) Rating



| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | |
|--------------------------------------|--|-------------------|-------------|------|--------|------|--|--|
| | | d (85 - 94) | Excellent (| | Not Ra | ted | | |
| | See Appendix for d | lefinitions and f | ormulas | | | | | |
| Inspection Date: 8/18/2016 | Beginning Section M | IP 10 | 11 | 12 | 13 | 14 | | |
| Paved Length (Miles): 31.86 | Section Length (MI) | 1 | 1 | 1 | 1 | 1 | | |
| Surface Type: ASPHALT | Route Summary | | • | | • | | | |
| Roadway Condition Information | | | | | | | | |
| Pavement Condition Rating (PCR |) 99 | 100 | 99 | 100 | 100 | 100 | | |
| Surface Condition Rating (SCR) | 99 | 100 | 99 | 100 | 100 | 100 | | |
| Roughness Condition Index (RCI) | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Distress Index Values | | | | | | | | |
| Structural Crack Index | 99 | 100 | 100 | 100 | 100 | 100 | | |
| Alligator Crack Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Longitudinal Crack Index | 99 | 100 | 100 | 100 | 100 | 100 | | |
| Transverse Cracking Index | 99 | 100 | 100 | 100 | 100 | 100 | | |
| Patching Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Rutting Index | 99 | 100 | 99 | 100 | 100 | 100 | | |
| International Roughness Index (II | RI) 95 | 76 | 78 | 80 | 89 | 76 | | |
| Lane & Width Information | | | | | | | | |
| Number of Lanes | 2 | 2 | 2 | 2 | 2 | 2 | | |
| Paved Width (ft) | 20.4 | 19.6 | 19.3 | 19.7 | 20.6 | 19.7 | | |
| Lane Width (ft) | 9.8 | 9.2 | 9.2 | 9.3 | 9.9 | 9.8 | | |

ROUTE 0010W: GOING TO THE SUN ROAD WEST


Data Collection Vehicle (DCV) Rating



| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | |
|------------------------------|--|-----------------------------|-----------|-------------|------|--------|------|--|
| Poor (0 - 60) | Fair (6) | | (85 - 94) | Excellent (| | Not Ra | ted | |
| ` , , , , | | See Appendix for de | | ormulas | · · | | | |
| Inspection Date: 8/18 | /2016 | Beginning Section MI | 15 | 16 | 17 | 18 | 19 | |
| Paved Length (Miles): 31.8 | 6 | Section Length (MI) | 1 | 1 | 1 | 1 | 1 | |
| Surface Type: ASP | HALT | Route Summary | | | | • | | |
| Roadway Condition Inform | nation | | | | | | | |
| Pavement Condition Rating | g (PCR) | 99 | 100 | 100 | 100 | 100 | 100 | |
| Surface Condition Rating (So | CR) | 99 | 100 | 100 | 100 | 100 | 100 | |
| Roughness Condition Index | (RCI) | 100 | 100 | 100 | 100 | 100 | 100 | |
| Distress Index Values | | | | | | | | |
| Structural Crack Index | | 99 | 100 | 100 | 100 | 100 | 100 | |
| Alligator Crack Index | | 100 | 100 | 100 | 100 | 100 | 100 | |
| Longitudinal Crack Index | | 99 | 100 | 100 | 100 | 100 | 100 | |
| Transverse Cracking Index | | 99 | 100 | 100 | 100 | 100 | 100 | |
| Patching Index | | 100 | 100 | 100 | 100 | 100 | 100 | |
| Rutting Index | | 99 | 100 | 100 | 100 | 100 | 100 | |
| International Roughness In | dex (IRI) | 95 | 92 | 77 | 63 | 58 | 71 | |
| Lane & Width Information | L | | | | | | | |
| Number of Lanes | | 2 | 2 | 2 | 2 | 2 | 2 | |
| Paved Width (ft) | | 20.4 | 20 | 19.7 | 20.4 | 19.7 | 18.8 | |
| Lane Width (ft) | | 9.8 | 10 | 9.9 | 9.5 | 9.4 | 9.6 | |

ROUTE 0010W: GOING TO THE SUN ROAD WEST


Data Collection Vehicle (DCV) Rating



| R | Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | |
|-----------------------------------|--|-----------------|-------------|------|--------|------|--|--|
| | | (85 - 94) | Excellent (| | Not Ra | ted | | |
| | See Appendix for de | finitions and f | ormulas | | | | | |
| Inspection Date: 8/18/2016 | Beginning Section MI | 20 | 21 | 22 | 23 | 24 | | |
| Paved Length (Miles): 31.86 | Section Length (MI) | 1 | 1 | 1 | 1 | 1 | | |
| Surface Type: ASPHALT | Route Summary | | | | • | • | | |
| Roadway Condition Information | | | | | | | | |
| Pavement Condition Rating (PCR) | 99 | 99 | 100 | 100 | 99 | 95 | | |
| Surface Condition Rating (SCR) | 99 | 99 | 100 | 100 | 100 | 98 | | |
| Roughness Condition Index (RCI) | 100 | 100 | 100 | 100 | 98 | 90 | | |
| Distress Index Values | | | | | | | | |
| Structural Crack Index | 99 | 100 | 100 | 100 | 100 | 98 | | |
| Alligator Crack Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Longitudinal Crack Index | 99 | 100 | 100 | 100 | 100 | 98 | | |
| Transverse Cracking Index | 99 | 100 | 100 | 100 | 100 | 100 | | |
| Patching Index | 100 | 99 | 100 | 100 | 100 | 100 | | |
| Rutting Index | 99 | 100 | 100 | 100 | 100 | 98 | | |
| International Roughness Index (IR | I) 95 | 75 | 83 | 92 | 121 | 139 | | |
| Lane & Width Information | | | | | | | | |
| Number of Lanes | 2 | 2 | 2 | 2 | 2 | 2 | | |
| Paved Width (ft) | 20.4 | 19 | 18.5 | 18.9 | 19.4 | 21.6 | | |
| Lane Width (ft) | 9.8 | 9.6 | 9.4 | 9.4 | 9.5 | 9.6 | | |

ROUTE 0010W: GOING TO THE SUN ROAD WEST


Data Collection Vehicle (DCV) Rating



| Ro | Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | |
|-------------------------------------|--|-----------------|-------------|------|--------|------|--|--|
| | | (85 - 94) | Excellent (| | Not Ra | ted | | |
| | See Appendix for de | finitions and f | ormulas | | | | | |
| Inspection Date: 8/18/2016 | Beginning Section MP | 25 | 26 | 27 | 28 | 29 | | |
| Paved Length (Miles): 31.86 | Section Length (MI) | 1 | 1 | 1 | 1 | 1 | | |
| Surface Type: ASPHALT | Route Summary | | | | | | | |
| Roadway Condition Information | | | | | | | | |
| Pavement Condition Rating (PCR) | 99 | 96 | 98 | 99 | 99 | 98 | | |
| Surface Condition Rating (SCR) | 99 | 98 | 99 | 99 | 99 | 100 | | |
| Roughness Condition Index (RCI) | 100 | 94 | 97 | 100 | 100 | 96 | | |
| Distress Index Values | | | | | | | | |
| Structural Crack Index | 99 | 100 | 99 | 100 | 100 | 100 | | |
| Alligator Crack Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Longitudinal Crack Index | 99 | 100 | 99 | 100 | 100 | 100 | | |
| Transverse Cracking Index | 99 | 100 | 100 | 100 | 100 | 100 | | |
| Patching Index | 100 | 100 | 100 | 100 | 99 | 100 | | |
| Rutting Index | 99 | 98 | 99 | 99 | 100 | 100 | | |
| International Roughness Index (IRI) | 95 | 130 | 123 | 93 | 97 | 124 | | |
| Lane & Width Information | | | | | | | | |
| Number of Lanes | 2 | 2 | 2 | 2 | 2 | 2 | | |
| Paved Width (ft) | 20.4 | 19.5 | 17.6 | 19.8 | 20.8 | 20.1 | | |
| Lane Width (ft) | 9.8 | 9.3 | 8.6 | 9.8 | 9.7 | 10.2 | | |

ROUTE 0010W: GOING TO THE SUN ROAD WEST

Data Collection Vehicle (DCV) Rating




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | | | |
|--|-----------------------------|-----------------|---------|----------|-----------|--|--|--|--|
| Poor (0 - 60) Fair (6 | Good (85 - 94) Excellen | | | 5 - 100) | Not Rated | | | | |
| | See Appendix for def | initions and fo | ormulas | | | | | | |
| Inspection Date: 8/18/2016 | Beginning Section MP | 30 | 31 | | | | | | |
| Paved Length (Miles): 31.86 | Section Length (MI) | 1 | 0.86 | | | | | | |
| Surface Type: ASPHALT | Route Summary | | | | • | | | | |
| Roadway Condition Information | | | | | | | | | |
| Pavement Condition Rating (PCR) | 99 | 99 | 94 | | | | | | |
| Surface Condition Rating (SCR) | 99 | 99 | 99 | | | | | | |
| Roughness Condition Index (RCI) | 100 | 100 | 87 | | | | | | |
| Distress Index Values | | | | | | | | | |
| Structural Crack Index | 99 | 99 | 100 | | | | | | |
| Alligator Crack Index | 100 | 100 | 100 | | | | | | |
| Longitudinal Crack Index | 99 | 99 | 100 | | | | | | |
| Transverse Cracking Index | 99 | 100 | 100 | | | | | | |
| Patching Index | 100 | 100 | 100 | | | | | | |
| Rutting Index | 99 | 99 | 99 | | | | | | |
| International Roughness Index (IRI) | 95 | 109 | 148 | | | | | | |
| Lane & Width Information | | | | | | | | | |
| Number of Lanes | 2 | 2 | 2 | | | | | | |
| Paved Width (ft) | 20.4 | 21.1 | 20.7 | | | | | | |
| Lane Width (ft) | 9.8 | 10.1 | 10.2 | | | | | | |

ROUTE 0010E: GOING TO THE SUN ROAD EAST

Data Collection Vehicle (DCV) Rating




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | | |
|--|-----------------------------|----------------|-------------|---------------------|-------|-------|--|--|
| Poor (0 - 60) Fair (6 | 1- 84) Good (| (85 - 94) | Excellent (| xcellent (95 - 100) | | ted | | |
| | See Appendix for def | initions and f | ormulas | | | | | |
| Inspection Date: 8/18/2016 | Beginning Section MP | 31.86 | 32.86 | 33.86 | 34.86 | 35.86 | | |
| Paved Length (Miles): 18.00 | Section Length (MI) | 1 | 1 | 1 | 1 | 1 | | |
| Surface Type: ASPHALT | Route Summary | | | | | | | |
| Roadway Condition Information | | | | | | | | |
| Pavement Condition Rating (PCR) | 100 | 99 | 100 | 100 | 100 | 100 | | |
| Surface Condition Rating (SCR) | 100 | 99 | 100 | 100 | 100 | 100 | | |
| Roughness Condition Index (RCI) | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Distress Index Values | | | | | | | | |
| Structural Crack Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Alligator Crack Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Longitudinal Crack Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Transverse Cracking Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Patching Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Rutting Index | 100 | 99 | 100 | 100 | 100 | 100 | | |
| International Roughness Index (IRI) | 52 | 80 | 78 | 69 | 37 | 39 | | |
| Lane & Width Information | | | | | | | | |
| Number of Lanes | 2 | 2 | 2 | 2 | 2 | 2 | | |
| Paved Width (ft) | 19.5 | 19.5 | 20.8 | 20.1 | 19.2 | 19.5 | | |
| Lane Width (ft) | 9.9 | 9.3 | 9.9 | 9.8 | 9.9 | 10.3 | | |

ROUTE 0010E: GOING TO THE SUN ROAD EAST

Data Collection Vehicle (DCV) Rating



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

| Route | Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | | |
|-------------------------------------|--|----------------|-------------|-----------|--------|-------|--|--|--|
| Poor (0 - 60) Fair (| 61- 84) Good (| (85 - 94) | Excellent (| 95 - 100) | Not Ra | ted | | | |
| | See Appendix for def | initions and f | Formulas | | | | | | |
| Inspection Date: 8/18/2016 | Beginning Section MP | 36.86 | 37.86 | 38.86 | 39.86 | 40.86 | | | |
| Paved Length (Miles): 18.00 | Section Length (MI) | 1 | 1 | 1 | 1 | 1 | | | |
| Surface Type: ASPHALT | Route Summary | | • | • | | | | | |
| Roadway Condition Information | | | | | | | | | |
| Pavement Condition Rating (PCR) | 100 | 100 | 100 | 100 | 100 | 100 | | | |
| Surface Condition Rating (SCR) | 100 | 100 | 100 | 100 | 100 | 100 | | | |
| Roughness Condition Index (RCI) | 100 | 100 | 100 | 100 | 100 | 100 | | | |
| Distress Index Values | | | | | | | | | |
| Structural Crack Index | 100 | 100 | 100 | 100 | 100 | 100 | | | |
| Alligator Crack Index | 100 | 100 | 100 | 100 | 100 | 100 | | | |
| Longitudinal Crack Index | 100 | 100 | 100 | 100 | 100 | 100 | | | |
| Transverse Cracking Index | 100 | 100 | 100 | 100 | 100 | 100 | | | |
| Patching Index | 100 | 100 | 100 | 100 | 100 | 100 | | | |
| Rutting Index | 100 | 100 | 100 | 100 | 100 | 100 | | | |
| International Roughness Index (IRI) | 52 | 36 | 43 | 41 | 36 | 44 | | | |
| Lane & Width Information | | | | | | | | | |
| Number of Lanes | 2 | 2 | 2 | 2 | 2 | 2 | | | |
| Paved Width (ft) | 19.5 | 19.5 | 19.4 | 19.1 | 19.6 | 19.1 | | | |
| Lane Width (ft) | 9.9 | 10.3 | 10.3 | 9.8 | 9.7 | 9.7 | | | |

ROUTE 0010E: GOING TO THE SUN ROAD EAST

Data Collection Vehicle (DCV) Rating



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | | |
|--|-----------------------------|----------------|-----------------------------|-------|-----------|-------|--|--|
| Poor (0 - 60) Fair (6 | 1- 84) Good (| (85 - 94) | Excellent (95 - 100) | | Not Rated | | | |
| | See Appendix for def | initions and f | ormulas | | | | | |
| Inspection Date: 8/18/2016 | Beginning Section MP | 41.86 | 42.86 | 43.86 | 44.86 | 45.86 | | |
| Paved Length (Miles): 18.00 | Section Length (MI) | 1 | 1 | 1 | 1 | 1 | | |
| Surface Type: ASPHALT | Route Summary | | | | | | | |
| Roadway Condition Information | | | | | | | | |
| Pavement Condition Rating (PCR) | 100 | 100 | 100 | 99 | 100 | 100 | | |
| Surface Condition Rating (SCR) | 100 | 100 | 100 | 99 | 100 | 100 | | |
| Roughness Condition Index (RCI) | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Distress Index Values | | | | | | | | |
| Structural Crack Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Alligator Crack Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Longitudinal Crack Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Transverse Cracking Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Patching Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Rutting Index | 100 | 100 | 100 | 99 | 100 | 100 | | |
| International Roughness Index (IRI) | 52 | 42 | 50 | 47 | 46 | 57 | | |
| Lane & Width Information | | | | | | | | |
| Number of Lanes | 2 | 2 | 2 | 2 | 2 | 2 | | |
| Paved Width (ft) | 19.5 | 20.1 | 19.5 | 18.9 | 19.1 | 19.3 | | |
| Lane Width (ft) | 9.9 | 9.4 | 9.8 | 10 | 9.5 | 9.6 | | |

ROUTE 0010E: GOING TO THE SUN ROAD EAST

Data Collection Vehicle (DCV) Rating



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | | |
|--|-----------------------------|----------------|-----------------------------|-------|-----------|--|--|--|
| Poor (0 - 60) Fair (62 | Good (85 - 94) | | Excellent (95 - 100) | | Not Rated | | | |
| | See Appendix for def | initions and f | ormulas | | | | | |
| Inspection Date: 8/18/2016 | Beginning Section MP | 46.86 | 47.86 | 48.86 | | | | |
| Paved Length (Miles): 18.00 | Section Length (MI) | 1 | 1 | 1 | | | | |
| Surface Type: ASPHALT | Route Summary | | | | | | | |
| Roadway Condition Information | | | | | | | | |
| Pavement Condition Rating (PCR) | 100 | 100 | 100 | 98 | | | | |
| Surface Condition Rating (SCR) | 100 | 100 | 100 | 96 | | | | |
| Roughness Condition Index (RCI) | 100 | 100 | 100 | 100 | | | | |
| Distress Index Values | | | | | | | | |
| Structural Crack Index | 100 | 100 | 100 | 96 | | | | |
| Alligator Crack Index | 100 | 100 | 100 | 100 | | | | |
| Longitudinal Crack Index | 100 | 100 | 100 | 96 | | | | |
| Transverse Cracking Index | 100 | 100 | 100 | 99 | | | | |
| Patching Index | 100 | 100 | 100 | 100 | | | | |
| Rutting Index | 100 | 100 | 100 | 99 | | | | |
| International Roughness Index (IRI) | 52 | 50 | 55 | 94 | | | | |
| Lane & Width Information | | | | | | | | |
| Number of Lanes | 2 | 2 | 2 | 2 | | | | |
| Paved Width (ft) | 19.5 | 19.7 | 19.5 | 20 | | | | |
| Lane Width (ft) | 9.9 | 9.4 | 10 | 10.5 | | | | |

ROUTE 0011: CAMAS ROAD


Data Collection Vehicle (DCV) Rating



| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | | |
|--|-------------|-------------------|----------------------|----------------------|----------|-----------|-----|--|
| Poor (0 - 60) | Fair (61- | | | Excellent (95 - 100) | | Not Rated | | |
| | | - | or definitions and f | ` | <u> </u> | | | |
| Inspection Date: 8/17/20 | 16 B | Beginning Section | MP 0 | 1 | 2 | 3 | 4 | |
| Paved Length (Miles): 11.58 | S | Section Length (N | (II) 1 | 1 | 1 | 1 | 1 | |
| Surface Type: ASPHA | LT R | Route Summary | | | | | | |
| Roadway Condition Informati | on | | | | | | | |
| Pavement Condition Rating (P | CR) | 97 | 84 | 87 | 87 | 85 | 94 | |
| Surface Condition Rating (SCR) | | 95 | 89 | 86 | 90 | 86 | 90 | |
| Roughness Condition Index (RC | I) | 100 | 77 | 88 | 82 | 84 | 100 | |
| Distress Index Values | | | | | | | | |
| Structural Crack Index | | 99 | 92 | 100 | 99 | 97 | 100 | |
| Alligator Crack Index | | 100 | 100 | 100 | 100 | 99 | 100 | |
| Longitudinal Crack Index | | 99 | 92 | 100 | 99 | 98 | 100 | |
| Transverse Cracking Index | | 100 | 99 | 100 | 100 | 100 | 100 | |
| Patching Index | | 100 | 99 | 100 | 99 | 100 | 100 | |
| Rutting Index | | 95 | 89 | 86 | 90 | 86 | 90 | |
| International Roughness Index (IRI) | | 96 | 179 | 145 | 162 | 158 | 89 | |
| Lane & Width Information | | | | | | | | |
| Number of Lanes | | 2 | 2 | 2 | 2 | 2 | 2 | |
| Paved Width (ft) | | 21.9 | 20.4 | 21.4 | 21.9 | 21.5 | 22 | |
| Lane Width (ft) | | 9.6 | 9.9 | 9.2 | 10.1 | 10.2 | 9.7 | |

ROUTE 0011: CAMAS ROAD


Data Collection Vehicle (DCV) Rating



| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | | |
|--|------------|-----------------------------|----------------|----------------------|------|-----------|------|--|
| Poor (0 - 60) | Fair (6 | | | Excellent (95 - 100) | | Not Rated | | |
| | | See Appendix for def | initions and f | ormulas | | | | |
| Inspection Date: 8/ | /17/2016 | Beginning Section MP | 5 | 6 | 7 | 8 | 9 | |
| Paved Length (Miles): 11 | 1.58 | Section Length (MI) | 1 | 1 | 1 | 1 | 1 | |
| Surface Type: A | SPHALT | Route Summary | | | | | | |
| Roadway Condition Info | ormation | | | | | | | |
| Pavement Condition Rat | ting (PCR) | 97 | 99 | 99 | 100 | 100 | 100 | |
| Surface Condition Rating | (SCR) | 95 | 99 | 99 | 100 | 100 | 100 | |
| Roughness Condition Inde | ex (RCI) | 100 | 100 | 100 | 100 | 100 | 100 | |
| Distress Index Values | | | | | | | | |
| Structural Crack Index | | 99 | 100 | 100 | 100 | 100 | 100 | |
| Alligator Crack Index | | 100 | 100 | 100 | 100 | 100 | 100 | |
| Longitudinal Crack Inde | ex | 99 | 100 | 100 | 100 | 100 | 100 | |
| Transverse Cracking Ind | lex | 100 | 100 | 100 | 100 | 100 | 100 | |
| Patching Index | | 100 | 100 | 100 | 100 | 100 | 100 | |
| Rutting Index | | 95 | 99 | 99 | 100 | 100 | 100 | |
| International Roughness Index (IRI) | | 96 | 50 | 50 | 52 | 57 | 63 | |
| Lane & Width Informat | ion | | | | | | | |
| Number of Lanes | | 2 | 2 | 2 | 2 | 2 | 2 | |
| Paved Width (ft) | | 21.9 | 22.2 | 22 | 22.3 | 22.5 | 21.7 | |
| Lane Width (ft) | | 9.6 | 9.5 | 9.3 | 9.9 | 9.4 | 9.2 | |

ROUTE 0011: CAMAS ROAD

Data Collection Vehicle (DCV) Rating



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | | |
|--|----------------------|-----------------|---------|----------------|-----------|--|--|--|
| Poor (0 - 60) Fair | (61- 84) Good | Good (85 - 94) | | - 100) | Not Rated | | | |
| | See Appendix for def | finitions and f | ormulas | | _ | | | |
| Inspection Date: 8/17/2016 | Beginning Section MP | 10 | 11 | | | | | |
| Paved Length (Miles): 11.58 | Section Length (MI) | 1 | 0.58 | | | | | |
| Surface Type: ASPHALT | Route Summary | | - | | • | | | |
| Roadway Condition Information | | | | | | | | |
| Pavement Condition Rating (PCR) | 97 | 100 | 100 | | | | | |
| Surface Condition Rating (SCR) | 95 | 100 | 100 | | | | | |
| Roughness Condition Index (RCI) | 100 | 100 | 100 | | | | | |
| Distress Index Values | | | | | | | | |
| Structural Crack Index | 99 | 100 | 100 | | | | | |
| Alligator Crack Index | 100 | 100 | 100 | | | | | |
| Longitudinal Crack Index | 99 | 100 | 100 | | | | | |
| Transverse Cracking Index | 100 | 100 | 100 | | | | | |
| Patching Index | 100 | 100 | 100 | | | | | |
| Rutting Index | 95 | 100 | 100 | | | | | |
| International Roughness Index (IRI) | 96 | 61 | 91 | | | | | |
| Lane & Width Information | | | | | | | | |
| Number of Lanes | 2 | 2 | 2 | | | | | |
| Paved Width (ft) | 21.9 | 22.2 | 23.6 | | | | | |
| Lane Width (ft) | 9.6 | 9.6 | 9.2 | | | | | |

NOTE: The very end of the route is a concrete bridge deck. Only IRI is measured on concrete.

ROUTE 0012: TWO MEDICINE ROAD


Data Collection Vehicle (DCV) Rating



| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | | |
|--|----------------|-----------------------------|----------------|-------------|------|--------|------|--|
| Poor (0 - 60 | | | (85 - 94) | Excellent (| | Not Ra | ted | |
| | | See Appendix for def | initions and f | ormulas | | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | 1 | 2 | 3 | 4 | |
| Paved Length (Mile | s): 7.28 | Section Length (MI) | 1 | 1 | 1 | 1 | 1 | |
| Surface Type: | ASPHALT | Route Summary | | • | | • | | |
| Roadway Condition | Information | | | | | | | |
| Pavement Condition | n Rating (PCR) | 85 | 82 | 83 | 81 | 86 | 89 | |
| Surface Condition R | ating (SCR) | 92 | 94 | 91 | 91 | 90 | 90 | |
| Roughness Condition | n Index (RCI) | 74 | 64 | 70 | 66 | 79 | 88 | |
| Distress Index Values | | | | | | | | |
| Structural Crack Inc | dex | 100 | 100 | 99 | 100 | 100 | 100 | |
| Alligator Crack Ind | ex | 100 | 100 | 100 | 100 | 100 | 100 | |
| Longitudinal Crack | Index | 100 | 100 | 99 | 100 | 100 | 100 | |
| Transverse Crackin | g Index | 100 | 100 | 100 | 100 | 100 | 100 | |
| Patching Index | | 100 | 100 | 100 | 100 | 100 | 100 | |
| Rutting Index | | 92 | 94 | 91 | 91 | 90 | 90 | |
| International Roughness Index (IRI) | | 187 | 224 | 203 | 217 | 172 | 145 | |
| Lane & Width Info | rmation | | | | | | | |
| Number of Lanes | | 2 | 2 | 2 | 2 | 2 | 2 | |
| Paved Width (ft) | | 27.5 | 26.3 | 27.3 | 28.2 | 27.8 | 28.2 | |
| Lane Width (ft) | | 12.4 | 12.1 | 12.2 | 12.4 | 12.4 | 13.1 | |

ROUTE 0012: TWO MEDICINE ROAD


Data Collection Vehicle (DCV) Rating



| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | |
|--|----------------|-----------------------------|----------------|-------------|------|---------|----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (| | Not Rat | ed |
| | | See Appendix for def | initions and f | ormulas | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 5 | 6 | 7 | | |
| Paved Length (Miles | s): 7.28 | Section Length (MI) | 1 | 1 | 0.28 | | |
| Surface Type: | ASPHALT | Route Summary | | • | • | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 85 | 85 | 92 | 82 | | |
| Surface Condition Ra | ating (SCR) | 92 | 93 | 95 | 93 | | |
| Roughness Condition | n Index (RCI) | 74 | 72 | 87 | 66 | | |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | lex | 100 | 100 | 100 | 99 | | |
| Alligator Crack Inde | ex | 100 | 100 | 100 | 100 | | |
| Longitudinal Crack | Index | 100 | 100 | 100 | 99 | | |
| Transverse Cracking | g Index | 100 | 100 | 99 | 98 | | |
| Patching Index | | 100 | 100 | 100 | 99 | | |
| Rutting Index | | 92 | 93 | 95 | 93 | | |
| International Roughness Index (IRI) | | 187 | 193 | 148 | 215 | | |
| Lane & Width Infor | mation | | | | | | |
| Number of Lanes | | 2 | 2 | 2 | 2 | | |
| Paved Width (ft) | | 27.5 | 27.2 | 27.8 | 26.9 | | |
| Lane Width (ft) | | 12.4 | 12.2 | 12.5 | 12.6 | | |

ROUTE 0013: CHIEF MOUNTAIN INTERNATIONAL HIGHWAY


Data Collection Vehicle (DCV) Rating



| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | | |
|--|----------------------|-----------------|---------|----------------------|------|------|--|--|
| | | | | Excellent (95 - 100) | | ted | | |
| | See Appendix for de | finitions and f | ormulas | | | | | |
| Inspection Date: 8/18/2016 | Beginning Section MP | 0 | 1 | 2 | 3 | 4 | | |
| Paved Length (Miles): 14.25 | Section Length (MI) | 1 | 1 | 1 | 1 | 1 | | |
| Surface Type: ASPHALT | Route Summary | | • | | • | • | | |
| Roadway Condition Information | | | | | | | | |
| Pavement Condition Rating (PCR) | 90 | 95 | 98 | 95 | 92 | 85 | | |
| Surface Condition Rating (SCR) | 92 | 97 | 96 | 91 | 94 | 90 | | |
| Roughness Condition Index (RCI) | 87 | 91 | 100 | 100 | 89 | 78 | | |
| Distress Index Values | | | | | | | | |
| Structural Crack Index | 99 | 99 | 98 | 100 | 100 | 99 | | |
| Alligator Crack Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Longitudinal Crack Index | 99 | 99 | 98 | 100 | 100 | 99 | | |
| Transverse Cracking Index | 99 | 98 | 98 | 99 | 100 | 99 | | |
| Patching Index | 100 | 100 | 100 | 100 | 100 | 100 | | |
| Rutting Index | 92 | 97 | 96 | 91 | 94 | 90 | | |
| International Roughness Index (IRI | 150 | 136 | 110 | 108 | 144 | 175 | | |
| Lane & Width Information | | | | | | | | |
| Number of Lanes | 2 | 2 | 2 | 2 | 2 | 2 | | |
| Paved Width (ft) | 30.1 | 31.3 | 29.9 | 30.4 | 29.1 | 29.8 | | |
| Lane Width (ft) | 12.5 | 12.5 | 12.7 | 12.5 | 12.4 | 12.5 | | |

ROUTE 0013: CHIEF MOUNTAIN INTERNATIONAL HIGHWAY


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | tion Rating (| PCR) | | |
|----------------------|-------------------|-----------------------------|----------------|-----------------------------|------|--------|------|
| Poor (0 - 60 | | | (85 - 94) | Excellent (95 - 100) | | Not Ra | ted |
| | | See Appendix for def | initions and f | ormulas | | | |
| Inspection Date: | 8/18/2016 | Beginning Section MP | 5 | 6 | 7 | 8 | 9 |
| Paved Length (Mile | es): 14.25 | Section Length (MI) | 1 | 1 | 1 | 1 | 1 |
| Surface Type: | ASPHALT | Route Summary | | | | ! | |
| Roadway Condition | 1 Information | | | | | | |
| Pavement Conditio | n Rating (PCR) | 90 | 75 | 87 | 91 | 92 | 92 |
| Surface Condition R | ating (SCR) | 92 | 82 | 90 | 91 | 94 | 94 |
| Roughness Condition | n Index (RCI) | 87 | 77 | 82 | 90 | 88 | 90 |
| Distress Index Value | es | | | | | | |
| Structural Crack In- | dex | 99 | 100 | 100 | 100 | 98 | 99 |
| Alligator Crack Ind | lex | 100 | 100 | 100 | 100 | 100 | 100 |
| Longitudinal Crack | Index | 99 | 100 | 100 | 100 | 98 | 99 |
| Transverse Crackin | g Index | 99 | 100 | 100 | 100 | 100 | 100 |
| Patching Index | | 100 | 99 | 100 | 100 | 100 | 100 |
| Rutting Index | | 92 | 82 | 90 | 91 | 94 | 94 |
| International Rough | hness Index (IRI) | 150 | 179 | 162 | 139 | 146 | 140 |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 2 | 2 | 2 | 2 | 2 | 2 |
| Paved Width (ft) | | 30.1 | 29.1 | 31.2 | 30 | 29.5 | 28.6 |
| Lane Width (ft) | | 12.5 | 12.5 | 12.8 | 12.6 | 12.7 | 12.2 |

ROUTE 0013: CHIEF MOUNTAIN INTERNATIONAL HIGHWAY


Data Collection Vehicle (DCV) Rating



| Ro | ite Condition Legend – Pav | ement Condi | tion Rating (| PCR) | | |
|-------------------------------------|----------------------------|-----------------|-----------------------------|------|-----------|------|
| | | (85 - 94) | Excellent (95 - 100) | | Not Rated | |
| | See Appendix for de | finitions and f | ormulas | | | |
| Inspection Date: 8/18/2016 | Beginning Section MP | 10 | 11 | 12 | 13 | 14 |
| Paved Length (Miles): 14.25 | Section Length (MI) | 1 | 1 | 1 | 1 | 0.25 |
| Surface Type: ASPHALT | Route Summary | oute Summary | | | | |
| Roadway Condition Information | | | | | | |
| Pavement Condition Rating (PCR) | 90 | 86 | 82 | 82 | 96 | 93 |
| Surface Condition Rating (SCR) | 92 | 85 | 87 | 89 | 99 | 98 |
| Roughness Condition Index (RCI) | 87 | 87 | 75 | 71 | 91 | 85 |
| Distress Index Values | | | | | | |
| Structural Crack Index | 99 | 99 | 99 | 100 | 100 | 100 |
| Alligator Crack Index | 100 | 100 | 100 | 100 | 100 | 100 |
| Longitudinal Crack Index | 99 | 99 | 99 | 100 | 100 | 100 |
| Transverse Cracking Index | 99 | 100 | 100 | 100 | 100 | 100 |
| Patching Index | 100 | 100 | 100 | 99 | 100 | 100 |
| Rutting Index | 92 | 85 | 87 | 89 | 99 | 98 |
| International Roughness Index (IRI) | 150 | 148 | 186 | 200 | 137 | 153 |
| Lane & Width Information | | | | | | |
| Number of Lanes | 2 | 2 | 2 | 2 | 2 | 2 |
| Paved Width (ft) | 30.1 | 29.6 | 30 | 28.3 | 31 | 43.1 |
| Lane Width (ft) | 12.5 | 12.9 | 12.4 | 11.6 | 12.4 | 13.1 |

ROUTE 0014: MANY GLACIER ROAD


Data Collection Vehicle (DCV) Rating



| | Route Condition | 1 Legend _ Pay | ement Condi | tion Rating (| PCR) | | |
|----------------------------------|------------------|-----------------|-------------|---------------|----------|--------|------|
| Poor (0 - 60) | Fair (61- 84) | | (85 - 94) | Excellent (| | Not Ra | ted |
| | , , | ppendix for def | , | , | / | | |
| Inspection Date: 8/18/201 | 6 Beginni | ng Section MP | 0 | 1 | 2 | 3 | 4 |
| Paved Length (Miles): 12.44 | Section | Length (MI) | 1 | 1 | 1 | 1 | 1 |
| Surface Type: ASPHAI | T Route S | ummary | | | | | |
| Roadway Condition Information | n | | | | | | |
| Pavement Condition Rating (PC | CR) | 74 | 76 | 81 | 62 | 63 | 62 |
| Surface Condition Rating (SCR) | | 81 | 80 | 88 | 76 | 70 | 75 |
| Roughness Condition Index (RCI |) | 64 | 71 | 71 | 53 | 52 | 53 |
| Distress Index Values | | | | | | | |
| Structural Crack Index | | 93 | 85 | 98 | 94 | 86 | 90 |
| Alligator Crack Index | | 99 | 99 | 99 | 100 | 99 | 99 |
| Longitudinal Crack Index | | 94 | 86 | 99 | 94 | 87 | 91 |
| Transverse Cracking Index | | 99 | 97 | 99 | 99 | 99 | 99 |
| Patching Index | | 99 | 100 | 100 | 99 | 99 | 99 |
| Rutting Index | | 81 | 80 | 88 | 76 | 70 | 75 |
| International Roughness Index | (IRI) | 223 | 197 | 198 | 268 | 272 | 270 |
| Lane & Width Information | | | | | | | |
| Number of Lanes | | 2 | 2 | 2 | 2 | 2 | 2 |
| Paved Width (ft) | | 23.9 | 24.1 | 24.1 | 24.9 | 24.3 | 23.6 |
| Lane Width (ft) | | 10.4 | 10.8 | 10.7 | 10.7 | 10.5 | 10 |

ROUTE 0014: MANY GLACIER ROAD


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | tion Rating (| PCR) | | |
|----------------------|-------------------|-----------------------------|----------------|---------------|------|-----------|------|
| Poor (0 - 60 | _ | | (85 - 94) | Excellent (| | Not Rated | |
| | | See Appendix for def | initions and f | ormulas | | | |
| Inspection Date: | 8/18/2016 | Beginning Section MP | 5 | 6 | 7 | 8 | 9 |
| Paved Length (Mile | es): 12.44 | Section Length (MI) | 1 | 1 | 1 | 1 | 1 |
| Surface Type: | ASPHALT | Route Summary | | | | ! | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 74 | 53 | 57 | 82 | 87 | 86 |
| Surface Condition R | ating (SCR) | 81 | 72 | 75 | 86 | 86 | 86 |
| Roughness Condition | n Index (RCI) | 64 | 29 | 51 | 75 | 88 | 85 |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | dex | 93 | 72 | 91 | 100 | 99 | 99 |
| Alligator Crack Ind | lex | 99 | 94 | 99 | 100 | 100 | 100 |
| Longitudinal Crack | Index | 94 | 78 | 92 | 100 | 99 | 99 |
| Transverse Crackin | g Index | 99 | 98 | 99 | 100 | 100 | 100 |
| Patching Index | | 99 | 94 | 99 | 100 | 99 | 100 |
| Rutting Index | | 81 | 72 | 75 | 86 | 86 | 86 |
| International Rough | nness Index (IRI) | 223 | 414 | 281 | 184 | 147 | 155 |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 2 | 2 | 2 | 2 | 2 | 2 |
| Paved Width (ft) | | 23.9 | 24.8 | 23 | 26 | 23.3 | 24 |
| Lane Width (ft) | | 10.4 | 10.2 | 10.1 | 10.8 | 10.7 | 10.9 |

ROUTE 0014: MANY GLACIER ROAD


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pa | vement Condi | tion Rating (| PCR) | | |
|-----------------------------|------------|-----------------------------|--------------|---------------|------|--------|-----|
| Poor (0 - 60) | Fair (6 | | (85 - 94) | Excellent (| | Not Ra | ted |
| | ` | See Appendix for de | | | · · | | |
| Inspection Date: 8/1 | 8/2016 | Beginning Section MI | 10 | 11 | 12 | | |
| Paved Length (Miles): 12.44 | | Section Length (MI) | 1 | 1 | 0.44 | | |
| Surface Type: AS | PHALT | Route Summary | | | | | |
| Roadway Condition Infor | mation | | | | | | |
| Pavement Condition Ratir | ng (PCR) | 74 | 86 | 87 | 84 | | |
| Surface Condition Rating (S | SCR) | 81 | 88 | 92 | 92 | | |
| Roughness Condition Index | (RCI) | 64 | 84 | 80 | 73 | | |
| Distress Index Values | | | | | | | |
| Structural Crack Index | | 93 | 100 | 99 | 100 | | |
| Alligator Crack Index | | 99 | 100 | 100 | 100 | | |
| Longitudinal Crack Index | | 94 | 100 | 99 | 100 | | |
| Transverse Cracking Inde | X | 99 | 100 | 99 | 100 | | |
| Patching Index | | 99 | 100 | 100 | 100 | | |
| Rutting Index | | 81 | 88 | 92 | 92 | | |
| International Roughness I | ndex (IRI) | 223 | 157 | 169 | 193 | | |
| Lane & Width Informatio | n | | | | | | |
| Number of Lanes | | 2 | 2 | 2 | 2 | | |
| Paved Width (ft) | | 23.9 | 23.2 | 22.3 | 21.5 | | |
| Lane Width (ft) | | 10.4 | 10.2 | 9.9 | 9.7 | | |

ROUTE 0100A: FISH CREEK ACCESS ROAD


Data Collection Vehicle (DCV) Rating



| | Pouto (| Condition Legend – Pav | ament Condi | tion Poting (| PCP) | | |
|----------------------------|-----------------|-----------------------------|-------------|---------------|------|----------|---|
| Poor (0 - 60) | Fair (6 | | (85 - 94) | Excellent (| | Not Rate | d |
| | · · | See Appendix for de | | | | | |
| Inspection Date: | 8/17/2016 | Beginning Section MP | 0 | 1 | | | |
| Paved Length (Miles): 1.16 | | Section Length (MI) | 1 | 0.16 | | | |
| Surface Type: | ASPHALT | Route Summary | | | | • | |
| Roadway Condition In | nformation | | | | | | |
| Pavement Condition F | Rating (PCR) | 84 | 85 | 95 | | | |
| Surface Condition Ratio | ng (SCR) | 92 | 93 | 95 | | | |
| Roughness Condition In | ndex (RCI) | 73 | 73 | N/A | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Index | X | 100 | 100 | 100 | | | |
| Alligator Crack Index | | 100 | 100 | 100 | | | |
| Longitudinal Crack In | dex | 100 | 100 | 100 | | | |
| Transverse Cracking I | ndex | 100 | 100 | 100 | | | |
| Patching Index | | 100 | 100 | 100 | | | |
| Rutting Index | | 92 | 93 | 95 | | | |
| International Roughne | ess Index (IRI) | 190 | 190 | N/A | | | |
| Lane & Width Inform | ation | | | | | | |
| Number of Lanes | | 2 | 2 | 2 | | | |
| Paved Width (ft) | | 20.5 | 20.8 | 18.7 | | | |
| Lane Width (ft) | | 9.5 | 9.6 | 9.3 | | | |

ROUTE 0101: APGAR LOOP ROAD

Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | tion Rating (| PCR) | | |
|----------------------------|-------------------|-----------------------------|----------------|---------------|------|-----------|--|
| Poor (0 - 60 | | | (85 - 94) | Excellent (| | Not Rated | |
| | | See Appendix for def | initions and f | ormulas | | | |
| Inspection Date: | 8/17/2016 | Beginning Section MP | 0 | 1 | | | |
| Paved Length (Miles): 1.11 | | Section Length (MI) | 1 | 0.11 | | | |
| Surface Type: | ASPHALT | Route Summary | | | | ' | |
| Roadway Condition | n Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 84 | 85 | 66 | | | |
| Surface Condition R | tating (SCR) | 97 | 97 | 78 | | | |
| Roughness Condition | n Index (RCI) | 64 | 67 | 47 | | | |
| Distress Index Valu | es | | | | | | |
| Structural Crack In | dex | 97 | 99 | 78 | | | |
| Alligator Crack Inc | lex | 100 | 100 | 100 | | | |
| Longitudinal Crack | Index | 97 | 99 | 78 | | | |
| Transverse Crackin | ig Index | 99 | 99 | 99 | | | |
| Patching Index | | 99 | 98 | 100 | | | |
| Rutting Index | | 97 | 97 | 94 | | | |
| International Roug | hness Index (IRI) | 223 | 214 | 301 | | | |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 2 | 2 | 2 | | | |
| Paved Width (ft) | | 22.2 | 22.2 | 21.6 | | | |
| Lane Width (ft) | | 11.2 | 11.2 | 10.8 | | | |

ROUTE 0102: ST. MARY RANGER STATION ROAD


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – | Pavement Cond | ition Rating (1 | PCR) | | |
|--------------------------|-------------|--------------------------|---------------------|-----------------|------|---------|-----|
| Poor (0 - 60) | Fair (6 | | ood (85 - 94) | Excellent (9 | | Not Rat | ted |
| | | * | r definitions and f | | | | |
| Inspection Date: 8 | /21/2016 | Beginning Section | MP 0 | | | | |
| Paved Length (Miles): 0 | .91 | Section Length (M | (I) 0.91 | | | | |
| Surface Type: A | SPHALT | Route Summary | | | | | |
| Roadway Condition Info | ormation | | | | | | |
| Pavement Condition Rat | ting (PCR) | 58 | 58 | | | | |
| Surface Condition Rating | (SCR) | 66 | 66 | | | | |
| Roughness Condition Ind | ex (RCI) | 47 | 47 | | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Index | | 66 | 66 | | | | |
| Alligator Crack Index | | 80 | 80 | | | | |
| Longitudinal Crack Inde | ex | 86 | 86 | | | | |
| Transverse Cracking Inc | lex | 96 | 96 | | | | |
| Patching Index | | 99 | 99 | | | | |
| Rutting Index | | 88 | 88 | | | | |
| International Roughness | Index (IRI) | 300 | 300 | | | | |
| Lane & Width Informat | ion | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 19.2 | 19.2 | | | | |
| Lane Width (ft) | | 9.6 | 9.6 | | | | |

ROUTE 0200: LAKE MCDONALD LODGE LOOP ROAD


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|------------------------|-----------------|-----------------------------|-------------|----------------|------|--------|-----|
| Poor (0 - 60) | Fair (6 | | (85 - 94) | Excellent (| | Not Ra | ted |
| | · · | See Appendix for de | | | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles): | : 0.53 | Section Length (MI) | 0.53 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition In | nformation | | | | | | |
| Pavement Condition I | Rating (PCR) | 66 | 66 | | | | |
| Surface Condition Rati | ng (SCR) | 66 | 66 | | | | |
| Roughness Condition I | ndex (RCI) | N/A | N/A | | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Index | X | 87 | 87 | | | | |
| Alligator Crack Index | | 100 | 100 | | | | |
| Longitudinal Crack In | ıdex | 87 | 87 | | | | |
| Transverse Cracking 1 | Index | 66 | 66 | | | | |
| Patching Index | | 93 | 93 | | | | |
| Rutting Index | | 96 | 96 | | | | |
| International Roughne | ess Index (IRI) | N/A | N/A | | | | |
| Lane & Width Inform | ation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 17.9 | 17.9 | | | | |
| Lane Width (ft) | | 8.9 | 8.9 | | | | |

ROUTE 0201: AVALANCHE CAMPGROUND ENTRANCE ROAD


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | tion Rating (| PCR) | | |
|----------------------------|-----------------|-----------------------------|-----------------|---------------|------|---------|-----|
| Poor (0 - 60) | Fair (6 | | (85 - 94) | Excellent (9 | | Not Rat | ted |
| | | See Appendix for def | finitions and f | ormulas | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles): 0.26 | | Section Length (MI) | 0.26 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition I | nformation | | | | | | |
| Pavement Condition l | Rating (PCR) | 97 | 97 | | | | |
| Surface Condition Rati | ing (SCR) | 97 | 97 | | | | |
| Roughness Condition I | Index (RCI) | N/A | N/A | | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Inde | X | 98 | 98 | | | | |
| Alligator Crack Index | ζ | 100 | 100 | | | | |
| Longitudinal Crack Ir | ndex | 98 | 98 | | | | |
| Transverse Cracking | Index | 100 | 100 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 97 | 97 | | | | |
| International Roughn | ess Index (IRI) | N/A | N/A | | | | |
| Lane & Width Inform | nation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 20.1 | 20.1 | | | | |
| Lane Width (ft) | | 10.1 | 10.1 | | | | |

ROUTE 0201A: AVALANCHE CAMPGROUND LOOPA


Data Collection Vehicle (DCV) Rating



| Route | Condition Legend – Pav | ement Condi | ition Rating (PCR) | |
|-------------------------------------|------------------------|-------------|----------------------|-----------|
| | | (85 - 94) | Excellent (95 - 100) | Not Rated |
| | See Appendix for def | | | |
| Inspection Date: 8/21/2016 | Beginning Section MP | | | |
| Paved Length (Miles): 0.36 | Section Length (MI) | 0.36 | | |
| Surface Type: ASPHALT | Route Summary | | | |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR) | 96 | 96 | | |
| Surface Condition Rating (SCR) | 96 | 96 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 100 | 100 | | |
| Alligator Crack Index | 100 | 100 | | |
| Longitudinal Crack Index | 100 | 100 | | |
| Transverse Cracking Index | 100 | 100 | | |
| Patching Index | 100 | 100 | | |
| Rutting Index | 96 | 96 | | |
| International Roughness Index (IRI) | N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 1 | 1 | | |
| Paved Width (ft) | 13 | 13 | | |
| Lane Width (ft) | 13 | 13 | | |

ROUTE 0201B: AVALANCHE CAMPGROUND LOOP B


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (1 | PCR) | | |
|----------------------|------------------|-----------------------------|-------------|-----------------|------|--------|-----|
| Poor (0 - 60) | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | , | | · · | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles | s): 0.27 | Section Length (MI) | 0.27 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | Rating (PCR) | 95 | 95 | | | | |
| Surface Condition Ra | ting (SCR) | 95 | 95 | | | | |
| Roughness Condition | Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | s | | | | | | |
| Structural Crack Ind | ex | 100 | 100 | | | | |
| Alligator Crack Inde | ex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 100 | 100 | | | | |
| Transverse Cracking | Index | 100 | 100 | | | | |
| Patching Index | | 99 | 99 | | | | |
| Rutting Index | | 95 | 95 | | | | |
| International Rough | ness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Infor | mation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 13.4 | 13.4 | | | | |
| Lane Width (ft) | | 13.4 | 13.4 | | | | |

ROUTE 0201CZZ: AVALANCHE CAMPGROUND SERVICE ROAD AND SPUR

Summary Route



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community


Note: The weighted average summary PCR value is calculated from only the sections of road where the PCR was collected. The overall PCR for the summary route may not reflect individual subcomponent ratings.

| oute may not reflect individual subcomponent ratings. | | | | | | | | | | |
|---|--|------------|---------------|----------------|-----------------------------|--|--------|-----|--|--|
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | | | |
| Poor (0 - 60) | Poor (0 - 60) Fair (6) | | (1-84) Good (| | Excellent (95 - 100) | | Not Ra | ted | | |
| | | See Appen | dix for def | initions and f | ormulas | | | | | |
| Inspection Date: | 7/27/2016 | | | | | | | | | |
| Paved Length (Miles) | 0.22 | | | | | | | | | |
| Surface Type: | ASPHALT | Route Summ | ary | | | | | | | |
| Roadway Condition I | Information | | | | | | | | | |
| Pavement Condition | Rating (PCR) | 30 | | | | | | | | |
| Lane & Width Inform | nation | | | | | | | | | |
| Number of Lanes | | 1 | | | | | | | | |
| Paved Width (ft) | | 10.6 | i | | | | | | | |
| Lane Width (ft) | | 10.6 | | | | | | | | |

ROUTE 0201CAZ: AVALANCHE CAMPGROUND SERVICE ROAD

Subcomponent of Route GLAC-0201CZZ

Manual Rating



| | Route (| Condition Legend – Pav | ement Condi | tion Rating (| PCR) | | |
|----------------------------|-------------------|-----------------------------|-----------------|---------------|------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (| | Not Ra | ted |
| | | See Appendix for det | finitions and f | ormulas | | | |
| Inspection Date: | 7/27/2016 | Beginning Section MP | 0.00 | | | | |
| Paved Length (Miles): 0.17 | | Section Length (MI) | 0.17 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 30 | 30 | | | | |
| Surface Condition R | ating (SCR) | 30 | 30 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | dex | N/A | N/A | | | | |
| Alligator Crack Ind | lex | 30 | 30 | | | | |
| Longitudinal Crack | Index | 73 | 73 | | | | |
| Transverse Crackin | g Index | 73 | 73 | | | | |
| Patching Index | | 30 | 30 | | | | |
| Rutting Index | | 53 | 53 | | | | |
| International Rough | nness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 10.8 | 10.8 | | | | |
| Lane Width (ft) | | 10.8 | 10.8 | | | | |

ROUTE 0201CAZ: AVALANCHE CAMPGROUND SERVICE ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GLAC_0201CAZ_3931.JPG



GLAC_0201CAZ_3933.JPG



GLAC_0201CAZ_3934.JPG



GLAC_0201CAZ_3935.JPG



GLAC_0201CAZ_3936.JPG




GLAC_0201CAZ_3937.JPG

ROUTE 0201CBZ: AVALANCHE CAMPGROUND SERVICE SPUR

Subcomponent of Route GLAC-0201CZZ

Manual Rating



| | Route (| Condition Legend – Pav | ement Condi | tion Rating (| PCR) | | |
|---------------------|-------------------|-----------------------------|----------------|---------------|------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (9 | , | Not Ra | ted |
| | | See Appendix for def | initions and f | ormulas | | | |
| Inspection Date: | 7/27/2016 | Beginning Section MP | 0.00 | | | | |
| Paved Length (Mile | es): 0.04 | Section Length (MI) | 0.04 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | n Information | | | | | | |
| Pavement Conditio | on Rating (PCR) | 30 | 30 | | | | |
| Surface Condition R | Rating (SCR) | 30 | 30 | | | | |
| Roughness Conditio | on Index (RCI) | N/A | N/A | | | | |
| Distress Index Valu | es | | | | | | |
| Structural Crack In | dex | N/A | N/A | | | | |
| Alligator Crack Inc | dex | 53 | 53 | | | | |
| Longitudinal Crack | Index | 73 | 73 | | | | |
| Transverse Crackin | ng Index | 73 | 73 | | | | |
| Patching Index | | 30 | 30 | | | | |
| Rutting Index | | 53 | 53 | | | | |
| International Rough | hness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 10 | 10 | | | | |
| Lane Width (ft) | | 10 | 10 | | | | |

ROUTE 0201CBZ: AVALANCHE CAMPGROUND SERVICE SPUR

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GLAC_0201CBZ_3939.JPG



GLAC_0201CBZ_3940.JPG



GLAC_0201CBZ_3941.JPG



GLAC_0201CBZ_3942.JPG




GLAC_0201CBZ_3943.JPG



GLAC_0201CBZ_3944.JPG

ROUTE 0202: NORTH LAKE MCDONALD ROAD (KELLY CAMP)


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|----------------------|------------------|-----------------------------|-------------|----------------|------|--------|-----|
| Poor (0 - 60) | _ | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | , | | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles | s): 0.41 | Section Length (MI) | 0.41 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | Rating (PCR) | 38 | 38 | | | | |
| Surface Condition Ra | ting (SCR) | 38 | 38 | | | | |
| Roughness Condition | Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | s | | | | | | |
| Structural Crack Ind | ex | 38 | 38 | | | | |
| Alligator Crack Inde | ex | 99 | 99 | | | | |
| Longitudinal Crack | Index | 39 | 39 | | | | |
| Transverse Cracking | Index | 74 | 74 | | | | |
| Patching Index | | 99 | 99 | | | | |
| Rutting Index | | 95 | 95 | | | | |
| International Roughi | ness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Inform | mation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 27.4 | 27.4 | | | | |
| Lane Width (ft) | | 13.7 | 13.7 | | | | |

ROUTE 0204: FISH CREEK CAMPGROUND ENTRANCE ROAD


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|----------------------------|-------------------|-----------------------------|----------------|----------------|------|---------|----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (9 | - | Not Rat | ed |
| | | See Appendix for def | initions and f | ormulas | | | |
| Inspection Date: | 8/17/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles): 0.31 | | Section Length (MI) | 0.31 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 94 | 94 | | | | |
| Surface Condition R | ating (SCR) | 94 | 94 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | dex | 100 | 100 | | | | |
| Alligator Crack Ind | ex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 100 | 100 | | | | |
| Transverse Cracking | g Index | 99 | 99 | | | | |
| Patching Index | | 99 | 99 | | | | |
| Rutting Index | | 94 | 94 | | | | |
| International Rough | nness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Infor | rmation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 23.6 | 23.6 | | | | |
| Lane Width (ft) | | 11.4 | 11.4 | | | | |

ROUTE 0204A: FISH CREEK CAMPGROUND LOOP A


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | rement Condi | ition Rating (| PCR) | | |
|-------------------------|----------------|-----------------------------|-----------------|----------------|------|---------|----|
| Poor (0 - 60) | Fair (6 | | (85 - 94) | Excellent (9 | | Not Rat | ed |
| | | See Appendix for de | finitions and f | ormulas | | | |
| Inspection Date: | 8/17/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles): | 0.26 | Section Length (MI) | 0.26 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition In | formation | | | | | | |
| Pavement Condition Ra | ating (PCR) | 86 | 86 | | | | |
| Surface Condition Ratin | g (SCR) | 86 | 86 | | | | |
| Roughness Condition In | dex (RCI) | N/A | N/A | | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Index | | 98 | 98 | | | | |
| Alligator Crack Index | | 100 | 100 | | | | |
| Longitudinal Crack Inc | lex | 98 | 98 | | | | |
| Transverse Cracking In | ıdex | 100 | 100 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 86 | 86 | | | | |
| International Roughnes | ss Index (IRI) | N/A | N/A | | | | |
| Lane & Width Informa | tion | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 12.9 | 12.9 | | | | |
| Lane Width (ft) | | 12.2 | 12.2 | | | | |

ROUTE 0204B: FISH CREEK CAMPGROUND LOOP B


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legen | d – Pavement Cond | ition Rating (| PCR) | | |
|-----------------------------|------------|-----------------|-----------------------|----------------|------|---------|-----|
| Poor (0 - 60) | Fair (6 | | Good (85 - 94) | Excellent (9 | | Not Rat | ted |
| | | - | for definitions and t | | | | |
| Inspection Date: 8/1 | 7/2016 | Beginning Secti | on MP 0 | | | | |
| Paved Length (Miles): 0.38 | | Section Length | (MI) 0.38 | | | | |
| Surface Type: AS | PHALT | Route Summar | y | | | | |
| Roadway Condition Infor | mation | | | | | | |
| Pavement Condition Ratio | ng (PCR) | 88 | 88 | | | | |
| Surface Condition Rating (| SCR) | 88 | 88 | | | | |
| Roughness Condition Index | (RCI) | N/A | N/A | | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Index | | 97 | 97 | | | | |
| Alligator Crack Index | | 100 | 100 | | | | |
| Longitudinal Crack Index | | 97 | 97 | | | | |
| Transverse Cracking Inde | X | 100 | 100 | | | | |
| Patching Index | | 99 | 99 | | | | |
| Rutting Index | | 88 | 88 | | | | |
| International Roughness I | ndex (IRI) | N/A | N/A | | | | |
| Lane & Width Information | n | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 12 | 12 | | | | |
| Lane Width (ft) | | 12 | 12 | | | | |

ROUTE 0204C: FISH CREEK CAMPGROUND LOOP C

Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | tion Rating (| PCR) | | |
|------------------------|-----------------|-----------------------------|----------------|---------------|------|---------|----|
| Poor (0 - 60) | Fair (6 | | (85 - 94) | Excellent (9 | | Not Rat | ed |
| | | See Appendix for det | initions and f | ormulas | | | |
| Inspection Date: | 8/17/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles): | : 0.38 | Section Length (MI) | 0.38 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition I | nformation | | | | | | |
| Pavement Condition F | Rating (PCR) | 89 | 89 | | | | |
| Surface Condition Rati | ng (SCR) | 89 | 89 | | | | |
| Roughness Condition I | ndex (RCI) | N/A | N/A | | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Index | X | 95 | 95 | | | | |
| Alligator Crack Index | | 100 | 100 | | | | |
| Longitudinal Crack In | ndex | 95 | 95 | | | | |
| Transverse Cracking I | Index | 99 | 99 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 89 | 89 | | | | |
| International Roughne | ess Index (IRI) | N/A | N/A | | | | |
| Lane & Width Inform | ation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 13.4 | 13.4 | | | | |
| Lane Width (ft) | | 11.1 | 11.1 | | | | |

ROUTE 0204D: FISH CREEK CAMPGROUND LOOP D


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|---------------------------|------------------|-----------------------------|-----------------|----------------|------|---------|-----|
| Poor (0 - 60) | | | (85 - 94) | Excellent (| | Not Rat | ted |
| | | See Appendix for det | finitions and f | ormulas | | | |
| Inspection Date: | 8/17/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles): 0.3 | | Section Length (MI) | 0.3 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | • | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | Rating (PCR) | 89 | 89 | | | | |
| Surface Condition Rat | ting (SCR) | 89 | 89 | | | | |
| Roughness Condition | Index (RCI) | N/A | N/A | | | | |
| Distress Index Values | S | | | | | | |
| Structural Crack Inde | ex | 99 | 99 | | | | |
| Alligator Crack Inde | X | 100 | 100 | | | | |
| Longitudinal Crack 1 | Index | 99 | 99 | | | | |
| Transverse Cracking | Index | 100 | 100 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 89 | 89 | | | | |
| International Roughr | ness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Inform | mation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 14 | 14 | | | | |
| Lane Width (ft) | | 10.5 | 10.5 | | | | |

ROUTE 0205: APGAR CAMPGROUND ENTRANCE ROAD


Data Collection Vehicle (DCV) Rating



| Route | Condition Legend – Pav | rement Cond | ition Rating (PCR) | |
|-------------------------------------|------------------------|-------------|----------------------|-----------|
| | | (85 - 94) | Excellent (95 - 100) | Not Rated |
| | See Appendix for def | | | |
| Inspection Date: 8/17/2016 | Beginning Section MP | | | |
| Paved Length (Miles): 0.31 | Section Length (MI) | 0.31 | | |
| Surface Type: ASPHALT | Route Summary | | | |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR) | 95 | 95 | | |
| Surface Condition Rating (SCR) | 95 | 95 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 100 | 100 | | |
| Alligator Crack Index | 100 | 100 | | |
| Longitudinal Crack Index | 100 | 100 | | |
| Transverse Cracking Index | 100 | 100 | | |
| Patching Index | 100 | 100 | | |
| Rutting Index | 95 | 95 | | |
| International Roughness Index (IRI) | N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 2 | 2 | | |
| Paved Width (ft) | 20.4 | 20.4 | | |
| Lane Width (ft) | 10.2 | 10.2 | | |

ROUTE 0205A: APGAR CAMPGROUND LOOPA


Data Collection Vehicle (DCV) Rating



| Davido | Condition Locand Don | | ition Doting (DCD) | |
|-------------------------------------|------------------------|-----------------|-----------------------------|-----------|
| | Condition Legend – Pav | | | N |
| Poor (0 - 60) Fair | | (85 - 94) | Excellent (95 - 100) | Not Rated |
| | See Appendix for def | finitions and f | Formulas | |
| Inspection Date: 8/17/2016 | Beginning Section MP | 0 | | |
| Paved Length (Miles): 0.6 | Section Length (MI) | 0.6 | | |
| Surface Type: ASPHALT | Route Summary | | | |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR) | 93 | 93 | | |
| Surface Condition Rating (SCR) | 93 | 93 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 100 | 100 | | |
| Alligator Crack Index | 100 | 100 | | |
| Longitudinal Crack Index | 100 | 100 | | |
| Transverse Cracking Index | 100 | 100 | | |
| Patching Index | 100 | 100 | | |
| Rutting Index | 93 | 93 | | |
| International Roughness Index (IRI) | N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 1 | 1 | | |
| Paved Width (ft) | 12.4 | 12.4 | | |
| Lane Width (ft) | 12.4 | 12.4 | | |

ROUTE 0205B: APGAR CAMPGROUND LOOP B


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | vement Condi | ition Rating (| PCR) | | |
|----------------------------|-----------------|------------------------|--------------|----------------|------|---------|-----|
| Poor (0 - 60) | Fair (6 | | (85 - 94) | Excellent (9 | | Not Rat | ted |
| | 10 (1 | See Appendix for de | | | | | |
| Inspection Date: | 8/17/2016 | Beginning Section MF | 0 | | | | |
| Paved Length (Miles): 0.49 | | Section Length (MI) | 0.49 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition In | nformation | | | | | | |
| Pavement Condition F | Rating (PCR) | 92 | 92 | | | | |
| Surface Condition Ratio | ng (SCR) | 92 | 92 | | | | |
| Roughness Condition Is | ndex (RCI) | N/A | N/A | | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Index | X | 100 | 100 | | | | |
| Alligator Crack Index | | 100 | 100 | | | | |
| Longitudinal Crack In | dex | 100 | 100 | | | | |
| Transverse Cracking I | ndex | 100 | 100 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 92 | 92 | | | | |
| International Roughne | ess Index (IRI) | N/A | N/A | | | | |
| Lane & Width Inform | ation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 12.3 | 12.3 | | | | |
| Lane Width (ft) | | 12.3 | 12.3 | | | | |

ROUTE 0205C: APGAR CAMPGROUND LOOP C


Data Collection Vehicle (DCV) Rating



| Donto | Condition Learned Day | | tion Doting (DCD) | |
|-------------------------------------|------------------------|----------------|-----------------------------|-----------|
| | Condition Legend – Pav | | | N / D / I |
| Poor (0 - 60) Fair (| | (85 - 94) | Excellent (95 - 100) | Not Rated |
| | See Appendix for def | initions and f | ormulas | |
| Inspection Date: 8/17/2016 | Beginning Section MP | 0 | | |
| Paved Length (Miles): 0.4 | Section Length (MI) | 0.4 | | |
| Surface Type: ASPHALT | Route Summary | | | • |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR) | 95 | 95 | | |
| Surface Condition Rating (SCR) | 95 | 95 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 100 | 100 | | |
| Alligator Crack Index | 100 | 100 | | |
| Longitudinal Crack Index | 100 | 100 | | |
| Transverse Cracking Index | 100 | 100 | | |
| Patching Index | 98 | 98 | | |
| Rutting Index | 95 | 95 | | |
| International Roughness Index (IRI) | N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 1 | 1 | | |
| Paved Width (ft) | 12.7 | 12.7 | | |
| Lane Width (ft) | 12.7 | 12.7 | | |

ROUTE 0205D: APGAR CAMPGROUND LOOP D


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legen | d – Pavement Cond | ition Rating (| PCR) | | |
|----------------------------|-------------|-----------------|-----------------------|----------------|------|---------|-----|
| Poor (0 - 60) | Fair (6 | | Good (85 - 94) | Excellent (| | Not Rat | ted |
| , , , | · · | , | x for definitions and | | / | | |
| Inspection Date: 8/ | 17/2016 | Beginning Sect | ion MP 0 | | | | |
| Paved Length (Miles): 0.2 | 27 | Section Length | (MI) 0.27 | | | | |
| Surface Type: AS | SPHALT | Route Summar | ·y | | | | |
| Roadway Condition Info | rmation | | | | | | |
| Pavement Condition Rati | ing (PCR) | 94 | 94 | | | | |
| Surface Condition Rating | (SCR) | 94 | 94 | | | | |
| Roughness Condition Inde | x (RCI) | N/A | N/A | | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Index | | 100 | 100 | | | | |
| Alligator Crack Index | | 100 | 100 | | | | |
| Longitudinal Crack Index | X | 100 | 100 | | | | |
| Transverse Cracking Inde | ex | 100 | 100 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 94 | 94 | | | | |
| International Roughness | Index (IRI) | N/A | N/A | | | | |
| Lane & Width Informati | on | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 12 | 12 | | | | |
| Lane Width (ft) | | 12 | 12 | | | | |

ROUTE 0205E: APGAR CAMPGROUND LOOP E (GROUP SITES)

Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|-----------------------|---------------------------------------|------------------------|-------------|----------------|------|--------|-----|
| Poor (0 - 60) | _ | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | , , , , , , , , , , , , , , , , , , , | See Appendix for det | 1 | | | | |
| Inspection Date: | 8/17/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles) |): 0.33 | Section Length (MI) | 0.33 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | Rating (PCR) | 97 | 97 | | | | |
| Surface Condition Rat | ting (SCR) | 97 | 97 | | | | |
| Roughness Condition | Index (RCI) | N/A | N/A | | | | |
| Distress Index Values | S | | | | | | |
| Structural Crack Inde | ex | 100 | 100 | | | | |
| Alligator Crack Inde | X | 100 | 100 | | | | |
| Longitudinal Crack I | Index | 100 | 100 | | | | |
| Transverse Cracking | Index | 100 | 100 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 97 | 97 | | | | |
| International Roughr | ness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Inform | mation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 12.5 | 12.5 | | | | |
| Lane Width (ft) | | 12.5 | 12.5 | | | | |

ROUTE 0206: WASTEWATER TREATMENT PLANT ROAD


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | tion Rating (| PCR) | | |
|----------------------|-------------------|-----------------------------|-------------|---------------|------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| · · | | See Appendix for def | 1 | | | | |
| Inspection Date: | 8/17/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Mile | es): 0.79 | Section Length (MI) | 0.79 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 76 | 76 | | | | |
| Surface Condition R | ating (SCR) | 91 | 91 | | | | |
| Roughness Condition | n Index (RCI) | 54 | 54 | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | dex | 91 | 91 | | | | |
| Alligator Crack Ind | lex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 91 | 91 | | | | |
| Transverse Crackin | g Index | 98 | 98 | | | | |
| Patching Index | | 99 | 99 | | | | |
| Rutting Index | | 95 | 95 | | | | |
| International Rough | nness Index (IRI) | 263 | 263 | | | | |
| Lane & Width Info | rmation | | | | · | | · |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 16 | 16 | | | | |
| Lane Width (ft) | | 7.8 | 7.8 | | | | |

ROUTE 0207: TWO MEDICINE CAMPGROUND ENTRANCE ROAD


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|----------------------|------------------|-----------------------------|-------------|----------------|------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | , | | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles | s): 0.77 | Section Length (MI) | 0.77 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 92 | 92 | | | | |
| Surface Condition Ra | ating (SCR) | 92 | 92 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | lex | 100 | 100 | | | | |
| Alligator Crack Inde | ex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 100 | 100 | | | | |
| Transverse Cracking | g Index | 99 | 99 | | | | |
| Patching Index | | 99 | 99 | | | | |
| Rutting Index | | 92 | 92 | | | | |
| International Rough | ness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Infor | mation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 19.9 | 19.9 | | | | |
| Lane Width (ft) | | 10.7 | 10.7 | | | | |

ROUTE 0207A: TWO MEDICINE CAMPGROUND LOOPA


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|----------------------|-------------------|-----------------------------|-------------|----------------|------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| · · | | See Appendix for def | , | | · · | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles | s): 0.19 | Section Length (MI) | 0.19 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 94 | 94 | | | | |
| Surface Condition Ra | ating (SCR) | 94 | 94 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | dex | 100 | 100 | | | | |
| Alligator Crack Inde | ex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 100 | 100 | | | | |
| Transverse Cracking | g Index | 100 | 100 | | | | |
| Patching Index | | 99 | 99 | | | | |
| Rutting Index | | 94 | 94 | | | | |
| International Rough | nness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Infor | rmation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 18.7 | 18.7 | | | | |
| Lane Width (ft) | | 9.3 | 9.3 | | | | |

ROUTE 0207B: TWO MEDICINE CAMPGROUND LOOP B


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Cond | ition Rating (I | PCR) | | |
|-----------------------|-----------------|-----------------------------|-----------------|-----------------|------|----------|----|
| Poor (0 - 60) | Fair (6 | | (85 - 94) | Excellent (9 | | Not Rate | ed |
| | | See Appendix for def | finitions and f | ormulas | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles) | : 0.22 | Section Length (MI) | 0.22 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition I | nformation | | | | | | |
| Pavement Condition | Rating (PCR) | 93 | 93 | | | | |
| Surface Condition Rat | ing (SCR) | 93 | 93 | | | | |
| Roughness Condition | Index (RCI) | N/A | N/A | | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Inde | ex | 100 | 100 | | | | |
| Alligator Crack Index | K | 100 | 100 | | | | |
| Longitudinal Crack In | ndex | 100 | 100 | | | | |
| Transverse Cracking | Index | 100 | 100 | | | | |
| Patching Index | | 99 | 99 | | | | |
| Rutting Index | | 93 | 93 | | | | |
| International Roughn | ess Index (IRI) | N/A | N/A | | | | |
| Lane & Width Inforn | nation | | | 1 1 | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 17.7 | 17.7 | | | | |
| Lane Width (ft) | | 8.9 | 8.9 | | | | |

ROUTE 0207C: TWO MEDICINE CAMPGROUND LOOP C


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (I | PCR) | | |
|----------------------|-------------------|-----------------------------|-------------|-----------------|------|--------|-----|
| Poor (0 - 60 | _ | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | 1 | | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Mile | es): 0.16 | Section Length (MI) | 0.16 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | • | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 90 | 90 | | | | |
| Surface Condition R | ating (SCR) | 90 | 90 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | dex | 100 | 100 | | | | |
| Alligator Crack Ind | lex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 100 | 100 | | | | |
| Transverse Crackin | g Index | 100 | 100 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 90 | 90 | | | | |
| International Rough | nness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Info | rmation | | | 1 1 | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 17.2 | 17.2 | | | | |
| Lane Width (ft) | | 8.6 | 8.6 | | | | |

ROUTE 0208A: SWIFTCURRENT CABINS LOOP ROAD


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|---------------------|-------------------|-----------------------------|-----------------|----------------|------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | finitions and f | ormulas | | | |
| Inspection Date: | 8/18/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Mile | es): 0.45 | Section Length (MI) | 0.45 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | n Information | | | | | | |
| Pavement Condition | on Rating (PCR) | 92 | 92 | | | | |
| Surface Condition R | Rating (SCR) | 92 | 92 | | | | |
| Roughness Condition | on Index (RCI) | N/A | N/A | | | | |
| Distress Index Valu | es | | | | | | |
| Structural Crack In | ıdex | 100 | 100 | | | | |
| Alligator Crack Inc | dex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 100 | 100 | | | | |
| Transverse Crackir | ng Index | 100 | 100 | | | | |
| Patching Index | | 98 | 98 | | | | |
| Rutting Index | | 92 | 92 | | | | |
| International Roug | hness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 16.5 | 16.5 | | | | |
| Lane Width (ft) | | 8.2 | 8.2 | | | | |

ROUTE 0208B: SWIFTCURRENT CABINS CUTOFF ROAD


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (P | PCR) | |
|----------------------|------------------|-----------------------------|----------------|-----------------|------|-----------|
| Poor (0 - 60) | | | (85 - 94) | Excellent (9: | | Not Rated |
| | | See Appendix for def | initions and f | ormulas | | |
| Inspection Date: | 8/18/2016 | Beginning Section MP | 0 | | | |
| Paved Length (Miles | s): 0.03 | Section Length (MI) | 0.03 | | | |
| Surface Type: | ASPHALT | Route Summary | | | | • |
| Roadway Condition | Information | | | | | |
| Pavement Condition | Rating (PCR) | 90 | 90 | | | |
| Surface Condition Ra | ating (SCR) | 90 | 90 | | | |
| Roughness Condition | Index (RCI) | N/A | N/A | | | |
| Distress Index Value | S | | | | | |
| Structural Crack Ind | lex | 97 | 97 | | | |
| Alligator Crack Inde | ex | 100 | 100 | | | |
| Longitudinal Crack | Index | 97 | 97 | | | |
| Transverse Cracking | g Index | 99 | 99 | | | |
| Patching Index | | 100 | 100 | | | |
| Rutting Index | | 90 | 90 | | | |
| International Rough | ness Index (IRI) | N/A | N/A | | | |
| Lane & Width Infor | mation | | | | | |
| Number of Lanes | | 1 | 1 | | | |
| Paved Width (ft) | | 14.5 | 14.5 | | | |
| Lane Width (ft) | | 14.5 | 14.5 | | | |

ROUTE 0209A: MANY GLACIER CAMPGROUND LOOPA


Data Collection Vehicle (DCV) Rating



| | Route Condition Legend | d – Pavement Cond | lition Rating (PCR) | |
|-----------------------------------|------------------------|---------------------|-----------------------------|-----------|
| | Fair (61- 84) | Good (85 - 94) | Excellent (95 - 100) | Not Rated |
| | See Appendix | for definitions and | formulas | |
| Inspection Date: 8/18/2016 | Beginning Secti | on MP 0 | | |
| Paved Length (Miles): 0.58 | Section Length | (MI) 0.58 | | |
| Surface Type: ASPHALT | Route Summar | y | | |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCF | 91 | 91 | | |
| Surface Condition Rating (SCR) | 91 | 91 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 100 | 100 | | |
| Alligator Crack Index | 100 | 100 | | |
| Longitudinal Crack Index | 100 | 100 | | |
| Transverse Cracking Index | 100 | 100 | | |
| Patching Index | 100 | 100 | | |
| Rutting Index | 91 | 91 | | |
| International Roughness Index (I | RI) N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 2 | 2 | | |
| Paved Width (ft) | 18.7 | 18.7 | | |
| Lane Width (ft) | 9.4 | 9.4 | | |

ROUTE 0209B: MANY GLACIER CAMPGROUND LOOP B


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|-----------------------|------------------|-----------------------------|-------------|----------------|------|--------|-----|
| Poor (0 - 60) | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | , | | * | | |
| Inspection Date: | 8/18/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles) |): 0.22 | Section Length (MI) | 0.22 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | Rating (PCR) | 93 | 93 | | | | |
| Surface Condition Rat | ting (SCR) | 93 | 93 | | | | |
| Roughness Condition | Index (RCI) | N/A | N/A | | | | |
| Distress Index Values | 3 | | | | | | |
| Structural Crack Inde | ex | 100 | 100 | | | | |
| Alligator Crack Inde | X | 100 | 100 | | | | |
| Longitudinal Crack I | Index | 100 | 100 | | | | |
| Transverse Cracking | Index | 100 | 100 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 93 | 93 | | | | |
| International Roughr | ness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Inform | nation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 18.7 | 18.7 | | | | |
| Lane Width (ft) | | 9.3 | 9.3 | | | | |

ROUTE 0209C: MANY GLACIER CAMPGROUND CUT THROUGH ROAD

Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (F | PCR) | | |
|------------------------|-----------------|-----------------------------|-----------------|-----------------|------|---------|----|
| Poor (0 - 60) | Fair (6 | | (85 - 94) | Excellent (9 | | Not Rat | ed |
| | | See Appendix for de | finitions and f | ormulas | | | |
| Inspection Date: | 8/18/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles) | : 0.07 | Section Length (MI) | 0.07 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition I | nformation | | | | | | |
| Pavement Condition | Rating (PCR) | 89 | 89 | | | | |
| Surface Condition Rati | ing (SCR) | 89 | 89 | | | | |
| Roughness Condition l | Index (RCI) | N/A | N/A | | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Inde | X | 100 | 100 | | | | |
| Alligator Crack Index | ζ | 100 | 100 | | | | |
| Longitudinal Crack In | ndex | 100 | 100 | | | | |
| Transverse Cracking | Index | 100 | 100 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 89 | 89 | | | | |
| International Roughn | ess Index (IRI) | N/A | N/A | | | | |
| Lane & Width Inforn | nation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 17.9 | 17.9 | | | | |
| Lane Width (ft) | | 9 | 9 | | | | |

ROUTE 0210: MANY GLACIER HOTEL ROAD


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | tion Rating (| PCR) | | |
|-----------------------|------------------|-----------------------------|-------------|---------------|------|--------|-----|
| Poor (0 - 60) | _ | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | 1 | | | | |
| Inspection Date: | 8/18/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles) |): 0.69 | Section Length (MI) | 0.69 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition 1 | Information | | | | | | |
| Pavement Condition | Rating (PCR) | 83 | 83 | | | | |
| Surface Condition Rat | ting (SCR) | 88 | 88 | | | | |
| Roughness Condition | Index (RCI) | N/A | N/A | | | | |
| Distress Index Values | S | | | | | | |
| Structural Crack Inde | ex | 88 | 88 | | | | |
| Alligator Crack Inde | X | 100 | 100 | | | | |
| Longitudinal Crack I | ndex | 88 | 88 | | | | |
| Transverse Cracking | Index | 93 | 93 | | | | |
| Patching Index | | 94 | 94 | | | | |
| Rutting Index | | 91 | 91 | | | | |
| International Roughr | ness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Inforr | nation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 21.5 | 21.5 | | | | |
| Lane Width (ft) | | 10.8 | 10.8 | | | | |

ROUTE 0211ZZ: SUN POINT ROAD

Summary Route



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community


Note: The weighted average summary PCR value is calculated from only the sections of road where the PCR was collected. The overall PCR for the summary route may not reflect individual subcomponent ratings.

| Toute may not reflect murv | bute may not reflect individual subcomponent ratings. | | | | | | | |
|----------------------------|---|---------------|--------------|--------------------------------|---------------|-----------|-----------|--|
| | Route C | Condition Leg | gend – Pav | ement Condi | tion Rating (| PCR) | | |
| Poor (0 - 60) | Fair (62 | 1- 84) | Good | (85 - 94) Excellent (95 - 100) | | 95 - 100) | Not Rated | |
| | | See Apper | ndix for def | initions and f | ormulas | | | |
| Inspection Date: | 8/21/2016 | | | | | | | |
| Paved Length (Miles) |): 0.27 | | | | | | | |
| Surface Type: | ASPHALT | Route Sumn | nary | | • | | | |
| Roadway Condition I | Information | | | | | | | |
| Pavement Condition | Rating (PCR) | 95 | | | | | | |
| Lane & Width Inform | nation | | | | | | | |
| Number of Lanes | | 1 | | | | | | |
| Paved Width (ft) | | 20. | 1 | | | | | |
| Lane Width (ft) | | 9.2 | 2 | | | | | |

ROUTE 0211AZ: SUN POINT ROAD (ONE-WAY SPUR)

Subcomponent of Route GLAC-0211ZZ


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | tion Rating (| PCR) | | |
|---------------------|-------------------|-----------------------------|----------------|---------------|------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | initions and f | ormulas | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Mile | es): 0.08 | Section Length (MI) | 0.08 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | n Information | | | | | | |
| Pavement Condition | on Rating (PCR) | 83 | 83 | | | | |
| Surface Condition R | Rating (SCR) | 83 | 83 | | | | |
| Roughness Condition | on Index (RCI) | N/A | N/A | | | | |
| Distress Index Valu | es | | | | | | |
| Structural Crack In | dex | 100 | 100 | | | | |
| Alligator Crack Inc | dex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 100 | 100 | | | | |
| Transverse Crackin | ng Index | 100 | 100 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 83 | 83 | | | | |
| International Roug | hness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 15.3 | 15.3 | | | | |
| Lane Width (ft) | | 7.7 | 7.7 | | | | |

ROUTE 0211Z: SUN POINT ROAD (MAIN ROAD)


Subcomponent of Route GLAC-0211ZZ Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|-------------------------|----------------|-----------------------------|-----------------|----------------|------|---------|-----|
| Poor (0 - 60) | Fair (6 | | (85 - 94) | Excellent (9 | | Not Rat | ted |
| | | See Appendix for de | finitions and f | ormulas | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles): | 0.19 | Section Length (MI) | 0.19 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition In | formation | | | | | | |
| Pavement Condition R | ating (PCR) | 98 | 98 | | | | |
| Surface Condition Ratin | ng (SCR) | 98 | 98 | | | | |
| Roughness Condition In | ndex (RCI) | N/A | N/A | | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Index | | 100 | 100 | | | | |
| Alligator Crack Index | | 100 | 100 | | | | |
| Longitudinal Crack Inc | dex | 100 | 100 | | | | |
| Transverse Cracking In | ndex | 100 | 100 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 98 | 98 | | | | |
| International Roughne | ss Index (IRI) | N/A | N/A | | | | |
| Lane & Width Informa | ation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 22.1 | 22.1 | | | | |
| Lane Width (ft) | | 9.8 | 9.8 | | | | |

ROUTE 0212A: RISING SUN LODGE ROAD A


Data Collection Vehicle (DCV) Rating



| R | Soute Condition Legend | – Pavement Cond | lition Rating (PCR) | |
|-----------------------------------|------------------------|--------------------|-----------------------------|-----------|
| | | Good (85 - 94) | Excellent (95 - 100) | Not Rated |
| | See Appendix f | or definitions and | formulas | |
| Inspection Date: 8/21/2016 | Beginning Section | n MP 0 | | |
| Paved Length (Miles): 0.19 | Section Length (1 | MI) 0.19 | | |
| Surface Type: ASPHALT | Route Summary | | | |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR | 87 | 87 | | |
| Surface Condition Rating (SCR) | 87 | 87 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 97 | 97 | | |
| Alligator Crack Index | 100 | 100 | | |
| Longitudinal Crack Index | 97 | 97 | | |
| Transverse Cracking Index | 99 | 99 | | |
| Patching Index | 97 | 97 | | |
| Rutting Index | 87 | 87 | | |
| International Roughness Index (IR | I) N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 2 | 2 | | |
| Paved Width (ft) | 17.3 | 17.3 | | |
| Lane Width (ft) | 8.7 | 8.7 | | |

ROUTE 0212B: RISING SUN LODGE ROAD B


Data Collection Vehicle (DCV) Rating



| Rout | e Condition Legend – Pav | ement Cond | ition Rating (PCR) | |
|-------------------------------------|--------------------------|------------|----------------------|-----------|
| | | (85 - 94) | Excellent (95 - 100) | Not Rated |
| | See Appendix for def | | | |
| Inspection Date: 8/21/2016 | Beginning Section MP | 0 | | |
| Paved Length (Miles): 0.06 | Section Length (MI) | 0.06 | | |
| Surface Type: ASPHALT | Route Summary | | | - |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR) | 77 | 77 | | |
| Surface Condition Rating (SCR) | 77 | 77 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 97 | 97 | | |
| Alligator Crack Index | 100 | 100 | | |
| Longitudinal Crack Index | 97 | 97 | | |
| Transverse Cracking Index | 98 | 98 | | |
| Patching Index | 92 | 92 | | |
| Rutting Index | 77 | 77 | | |
| International Roughness Index (IRI) | N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 1 | 1 | | |
| Paved Width (ft) | 11.5 | 11.5 | | |
| Lane Width (ft) | 11.5 | 11.5 | | |

ROUTE 0212C: RISING SUN LODGE ROAD C


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (1 | PCR) | | |
|---------------------------------------|-------------------|-----------------------------|-------------|-----------------|------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| , , , , , , , , , , , , , , , , , , , | | See Appendix for det | 1 | | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Mile | s): 0.04 | Section Length (MI) | 0.04 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 80 | 80 | | | | |
| Surface Condition R | ating (SCR) | 80 | 80 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | dex | 98 | 98 | | | | |
| Alligator Crack Ind | ex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 98 | 98 | | | | |
| Transverse Crackin | g Index | 90 | 90 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 80 | 80 | | | | |
| International Rough | nness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Infor | rmation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 12.1 | 12.1 | | | | |
| Lane Width (ft) | | 12.1 | 12.1 | | | | |

ROUTE 0212D: RISING SUN LODGE ROAD D

Data Collection Vehicle (DCV) Rating




Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

| Route (| Condition Legend – Pav | ement Condi | ition Rating (PCR) | |
|-------------------------------------|-----------------------------|----------------|-----------------------------|-----------|
| Poor (0 - 60) Fair (6 | 1- 84) Good (| (85 - 94) | Excellent (95 - 100) | Not Rated |
| | See Appendix for def | initions and f | ormulas | |
| Inspection Date: 8/21/2016 | Beginning Section MP | 0 | | |
| Paved Length (Miles): 0.08 | Section Length (MI) | 0.08 | | |
| Surface Type: ASPHALT | Route Summary | | | |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR) | 0 | 0 | | |
| Surface Condition Rating (SCR) | N/A | N/A | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | N/A | N/A | | |
| Alligator Crack Index | N/A | N/A | | |
| Longitudinal Crack Index | N/A | N/A | | |
| Transverse Cracking Index | N/A | N/A | | |
| Patching Index | N/A | N/A | | |
| Rutting Index | N/A | N/A | | |
| International Roughness Index (IRI) | N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 2 | 2 | | |
| Paved Width (ft) | 18.6 | 18.6 | | |
| Lane Width (ft) | 9.3 | 9.3 | | |

NOTE: The pavement of this route is severely deteriorated. The PCR was provided, but no other distress indices were calculated.

ROUTE 0212F: RISING SUN LODGE ROAD F


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|----------------------|-------------------|-----------------------------|-------------|----------------|------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | 1 | | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Mile | es): 0.1 | Section Length (MI) | 0.1 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 93 | 93 | | | | |
| Surface Condition R | ating (SCR) | 93 | 93 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | dex | 93 | 93 | | | | |
| Alligator Crack Ind | lex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 93 | 93 | | | | |
| Transverse Crackin | g Index | 100 | 100 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 93 | 93 | | | | |
| International Rough | nness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 24.8 | 24.8 | | | | |
| Lane Width (ft) | | 12.4 | 12.4 | | | | |

ROUTE 0213A: RISING SUN CAMPGROUND ROAD A


Data Collection Vehicle (DCV) Rating



| Route | Condition Legend – Pav | ement Cond | ition Rating (PCR) | |
|-------------------------------------|------------------------|------------|----------------------|-----------|
| | | (85 - 94) | Excellent (95 - 100) | Not Rated |
| | See Appendix for def | 1 | | |
| Inspection Date: 8/21/2016 | Beginning Section MP | 0 | | |
| Paved Length (Miles): 0.4 | Section Length (MI) | 0.4 | | |
| Surface Type: ASPHALT | Route Summary | | ' | |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR) | 78 | 78 | | |
| Surface Condition Rating (SCR) | 78 | 78 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 78 | 78 | | |
| Alligator Crack Index | 99 | 99 | | |
| Longitudinal Crack Index | 79 | 79 | | |
| Transverse Cracking Index | 94 | 94 | | |
| Patching Index | 91 | 91 | | |
| Rutting Index | 86 | 86 | | |
| International Roughness Index (IRI) | N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 1 | 1 | | |
| Paved Width (ft) | 14.4 | 14.4 | | |
| Lane Width (ft) | 13.3 | 13.3 | | |

ROUTE 0213B: RISING SUN CAMPGROUND ROAD B


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Cond | ition Rating (F | PCR) | | |
|---------------------|-------------------|-----------------------------|------------|-----------------|---------------------------------------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | | | , , , , , , , , , , , , , , , , , , , | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Mile | es): 0.4 | Section Length (MI) | 0.4 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | n Information | | | | | | |
| Pavement Conditio | n Rating (PCR) | 83 | 83 | | | | |
| Surface Condition R | ating (SCR) | 83 | 83 | | | | |
| Roughness Conditio | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Valu | es | | | | | | |
| Structural Crack In | dex | 88 | 88 | | | | |
| Alligator Crack Inc | lex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 88 | 88 | | | | |
| Transverse Crackin | ig Index | 96 | 96 | | | | |
| Patching Index | | 96 | 96 | | | | |
| Rutting Index | | 83 | 83 | | | | |
| International Rough | hness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 15.6 | 15.6 | | | | |
| Lane Width (ft) | | 11.7 | 11.7 | | | | |

ROUTE 0214: ST. MARY CAMPGROUND ENTRANCE ROAD


Data Collection Vehicle (DCV) Rating



| | Route Condi | tion Legend – Pa | vement Condi | tion Rating (| PCR) | | |
|---------------------------------|--------------|-------------------|------------------|---------------|------|---------|-----|
| Poor (0 - 60) | Fair (61- 84 | | l (85 - 94) | Excellent (| | Not Rat | ted |
| | S | ee Appendix for d | efinitions and f | ormulas | | | |
| Inspection Date: 8/21/20 | 016 Begi | nning Section M | P 0 | | | | |
| Paved Length (Miles): 0.2 | Sect | ion Length (MI) | 0.2 | | | | |
| Surface Type: ASPHA | ALT Rou | te Summary | | | • | | |
| Roadway Condition Informat | ion | | | | | | |
| Pavement Condition Rating (F | PCR) | 84 | 84 | | | | |
| Surface Condition Rating (SCR |) | 84 | 84 | | | | |
| Roughness Condition Index (RO | CI) | N/A | N/A | | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Index | | 93 | 93 | | | | |
| Alligator Crack Index | | 97 | 97 | | | | |
| Longitudinal Crack Index | | 96 | 96 | | | | |
| Transverse Cracking Index | | 100 | 100 | | | | |
| Patching Index | | 99 | 99 | | | | |
| Rutting Index | | 84 | 84 | | | | |
| International Roughness Index | k (IRI) | N/A | N/A | | | | |
| Lane & Width Information | | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 17 | 17 | | | | |
| Lane Width (ft) | | 8.3 | 8.3 | | | | |

ROUTE 0214A: ST. MARY CAMPGROUND LOOPA


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | tion Rating (| PCR) | | |
|----------------------|-------------------|-----------------------------|-------------|---------------|------|--------|-----|
| Poor (0 - 60 | _ | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | , | | * | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Mile | es): 0.45 | Section Length (MI) | 0.45 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 63 | 63 | | | | |
| Surface Condition R | ating (SCR) | 81 | 81 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | dex | 97 | 97 | | | | |
| Alligator Crack Ind | lex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 97 | 97 | | | | |
| Transverse Crackin | g Index | 99 | 99 | | | | |
| Patching Index | | 99 | 99 | | | | |
| Rutting Index | | 81 | 81 | | | | |
| International Rough | nness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 12.1 | 12.1 | | | | |
| Lane Width (ft) | | 12.1 | 12.1 | | | | |

ROUTE 0214B: ST. MARY CAMPGROUND LOOP B


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|----------------------|------------------|-----------------------------|-------------|----------------|------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | 1 | | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles | s): 0.48 | Section Length (MI) | 0.48 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 77 | 77 | | | | |
| Surface Condition Ra | ating (SCR) | 77 | 77 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | lex | 100 | 100 | | | | |
| Alligator Crack Inde | ex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 100 | 100 | | | | |
| Transverse Cracking | g Index | 97 | 97 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 77 | 77 | | | | |
| International Rough | ness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Infor | mation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 12.5 | 12.5 | | | | |
| Lane Width (ft) | | 12.5 | 12.5 | | | | |

ROUTE 0214C: ST. MARY CAMPGROUND LOOP C


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | | |
|---------------------------|-----------------|-----------------------------|----------------|----------------|------|-----------|--|--|
| Poor (0 - 60) | Fair (6 | | (85 - 94) | Excellent (9 | | Not Rated | | |
| | | See Appendix for def | initions and f | ormulas | | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | | |
| Paved Length (Miles): 0.6 | | Section Length (MI) | 0.6 | | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | | |
| Roadway Condition I | Information | | | | | | | |
| Pavement Condition | Rating (PCR) | 78 | 78 | | | | | |
| Surface Condition Rat | ing (SCR) | 78 | 78 | | | | | |
| Roughness Condition | Index (RCI) | N/A | N/A | | | | | |
| Distress Index Values | } | | | | | | | |
| Structural Crack Inde | ex | 93 | 93 | | | | | |
| Alligator Crack Index | X | 100 | 100 | | | | | |
| Longitudinal Crack I | ndex | 93 | 93 | | | | | |
| Transverse Cracking | Index | 78 | 78 | | | | | |
| Patching Index | | 100 | 100 | | | | | |
| Rutting Index | | 83 | 83 | | | | | |
| International Roughn | ess Index (IRI) | N/A | N/A | | | | | |
| Lane & Width Inforn | nation | | | | | | | |
| Number of Lanes | | 1 | 1 | | | | | |
| Paved Width (ft) | | 13.3 | 13.3 | | | | | |
| Lane Width (ft) | | 11.3 | 11.3 | | | | | |

ROUTE 0240: WALTON RANGER STATION ROAD


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|---------------------------------------|-------------------|-----------------------------|-------------|----------------|------|--------|-----|
| Poor (0 - 60 | _ | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| , , , , , , , , , , , , , , , , , , , | | See Appendix for def | 1 | | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Mile | es): 0.07 | Section Length (MI) | 0.07 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 92 | 92 | | | | |
| Surface Condition R | ating (SCR) | 92 | 92 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | dex | 96 | 96 | | | | |
| Alligator Crack Ind | ex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 96 | 96 | | | | |
| Transverse Crackin | g Index | 100 | 100 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 92 | 92 | | | | |
| International Rough | nness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Infor | rmation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 18.6 | 18.6 | | | | |
| Lane Width (ft) | | 9.3 | 9.3 | | | | |

ROUTE 0241: HUCKLEBERRY MOUNTAIN ROAD


Data Collection Vehicle (DCV) Rating



| Rout | e Condition Legend – Pav | ement Cond | ition Rating (PCR) | |
|-------------------------------------|--------------------------|------------|----------------------|---------------|
| | | (85 - 94) | Excellent (95 - 100) | Not Rated |
| 2 002 (0 02) | See Appendix for def | 1 | | - 100 - 100 0 |
| Inspection Date: 8/17/2016 | Beginning Section MP | | | |
| Paved Length (Miles): 0.24 | Section Length (MI) | 0.24 | | |
| Surface Type: ASPHALT | Route Summary | | | l l |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR) | 90 | 90 | | |
| Surface Condition Rating (SCR) | 90 | 90 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 99 | 99 | | |
| Alligator Crack Index | 100 | 100 | | |
| Longitudinal Crack Index | 99 | 99 | | |
| Transverse Cracking Index | 100 | 100 | | |
| Patching Index | 100 | 100 | | |
| Rutting Index | 90 | 90 | | |
| International Roughness Index (IRI) | N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 2 | 2 | | |
| Paved Width (ft) | 20.6 | 20.6 | | |
| Lane Width (ft) | 12.1 | 12.1 | | |

ROUTE 0242: SPRAGUE CREEK CAMPGROUND ROAD


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|-----------------------|------------------|-----------------------------|-------------|----------------|------|--------|-----|
| Poor (0 - 60) | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for det | | | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles) |): 0.19 | Section Length (MI) | 0.19 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | Rating (PCR) | 65 | 65 | | | | |
| Surface Condition Rat | ting (SCR) | 65 | 65 | | | | |
| Roughness Condition | Index (RCI) | N/A | N/A | | | | |
| Distress Index Values | 3 | | | | | | |
| Structural Crack Inde | ex | 65 | 65 | | | | |
| Alligator Crack Inde | X | 97 | 97 | | | | |
| Longitudinal Crack I | Index | 68 | 68 | | | | |
| Transverse Cracking | Index | 80 | 80 | | | | |
| Patching Index | | 98 | 98 | | | | |
| Rutting Index | | 89 | 89 | | | | |
| International Roughr | ness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Inform | nation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 14.6 | 14.6 | | | | |
| Lane Width (ft) | | 13.1 | 13.1 | | | | |

ROUTE 0244: MANY GLACIER BOAT RAMP ACCESS ROAD

Manual Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (I | PCR) | | |
|---------------------|-------------------|-----------------------------|----------------|-----------------|------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | initions and f | ormulas | | | |
| Inspection Date: | 7/29/2016 | Beginning Section MP | 0.00 | | | | |
| Paved Length (Mile | es): 0.05 | Section Length (MI) | 0.05 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | n Information | | | | | | |
| Pavement Conditio | on Rating (PCR) | 90 | 90 | | | | |
| Surface Condition R | Rating (SCR) | 90 | 90 | | | | |
| Roughness Conditio | on Index (RCI) | N/A | N/A | | | | |
| Distress Index Valu | es | | | | | | |
| Structural Crack In | dex | N/A | N/A | | | | |
| Alligator Crack Inc | dex | 90 | 90 | | | | |
| Longitudinal Crack | Index | 97 | 97 | | | | |
| Transverse Crackin | ng Index | 90 | 90 | | | | |
| Patching Index | | 90 | 90 | | | | |
| Rutting Index | | 90 | 90 | | | | |
| International Rough | hness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 11.5 | 11.5 | | | | |
| Lane Width (ft) | | 11.5 | 11.5 | | | | |

ROUTE 0244: MANY GLACIER BOAT RAMP ACCESS ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GLAC_0244_4488.JPG



GLAC_0244_4489.JPG



GLAC_0244_4490.JPG



GLAC_0244_4491.JPG




GLAC_0244_4494.JPG



GLAC_0244_4497.JPG

ROUTE 0245: STEWART MOTEL ROAD


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|------------------------|-----------------|-----------------------------|-------------|----------------|------|--------|-----|
| Poor (0 - 60) | Fair (6 | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for det | 1 | | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles) | : 0.04 | Section Length (MI) | 0.04 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition I | nformation | | | | | | |
| Pavement Condition | Rating (PCR) | 46 | 46 | | | | |
| Surface Condition Rati | ing (SCR) | 46 | 46 | | | | |
| Roughness Condition | Index (RCI) | N/A | N/A | | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Inde | ex | 46 | 46 | | | | |
| Alligator Crack Index | K | 90 | 90 | | | | |
| Longitudinal Crack In | ndex | 56 | 56 | | | | |
| Transverse Cracking | Index | 84 | 84 | | | | |
| Patching Index | | 94 | 94 | | | | |
| Rutting Index | | 71 | 71 | | | | |
| International Roughn | ess Index (IRI) | N/A | N/A | | | | |
| Lane & Width Inforn | nation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 12.6 | 12.6 | | | | |
| Lane Width (ft) | | 12.6 | 12.6 | | | | |

ROUTE 0246: APGAR TRANSIT CENTER SHUTTLE LOOP


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|----------------------|-------------------|-----------------------------|-------------|----------------|------|--------|-----|
| Poor (0 - 60 | _ | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | 1 | | · · | | |
| Inspection Date: | 8/17/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Mile | s): 0.13 | Section Length (MI) | 0.13 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 92 | 92 | | | | |
| Surface Condition Ra | ating (SCR) | 92 | 92 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | dex | 100 | 100 | | | | |
| Alligator Crack Ind | ex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 100 | 100 | | | | |
| Transverse Cracking | g Index | 99 | 99 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 92 | 92 | | | | |
| International Rough | nness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Infor | rmation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 24.3 | 24.3 | | | | |
| Lane Width (ft) | | 12.2 | 12.2 | | | | |

ROUTE 0400: HEADQUARTERS ROAD


Data Collection Vehicle (DCV) Rating



| Route | Condition Legend – Pav | ement Condi | ition Rating (PCR) | |
|-------------------------------------|------------------------|-------------|----------------------|-----------|
| | | (85 - 94) | Excellent (95 - 100) | Not Rated |
| | See Appendix for def | | | |
| Inspection Date: 8/17/2016 | Beginning Section MP | 0 | | |
| Paved Length (Miles): 0.28 | Section Length (MI) | 0.28 | | |
| Surface Type: ASPHALT | Route Summary | | | • |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR) | 85 | 85 | | |
| Surface Condition Rating (SCR) | 85 | 85 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 85 | 85 | | |
| Alligator Crack Index | 100 | 100 | | |
| Longitudinal Crack Index | 85 | 85 | | |
| Transverse Cracking Index | 95 | 95 | | |
| Patching Index | 100 | 100 | | |
| Rutting Index | 96 | 96 | | |
| International Roughness Index (IRI) | N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 2 | 2 | | |
| Paved Width (ft) | 24.2 | 24.2 | | |
| Lane Width (ft) | 12.1 | 12.1 | | |

ROUTE 0401: MANY GLACIER HOUSING AREA ROAD


Data Collection Vehicle (DCV) Rating



| Rou | te Condition Legend – Pav | ement Cond | ition Rating (PCR) | |
|-------------------------------------|---------------------------|------------|----------------------|------------|
| | | (85 - 94) | Excellent (95 - 100) | Not Rated |
| 1 001 (0 00) | See Appendix for det | | | 2100 21000 |
| Inspection Date: 8/18/2016 | Beginning Section MP | | | |
| Paved Length (Miles): 0.25 | Section Length (MI) | 0.25 | | |
| Surface Type: ASPHALT | Route Summary | | | |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR) | 93 | 93 | | |
| Surface Condition Rating (SCR) | 93 | 93 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 98 | 98 | | |
| Alligator Crack Index | 100 | 100 | | |
| Longitudinal Crack Index | 98 | 98 | | |
| Transverse Cracking Index | 100 | 100 | | |
| Patching Index | 96 | 96 | | |
| Rutting Index | 93 | 93 | | |
| International Roughness Index (IRI) | N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 2 | 2 | | |
| Paved Width (ft) | 17.5 | 17.5 | | |
| Lane Width (ft) | 12 | 12 | | |

ROUTE 0402: ST. MARY HOUSING AREA ROAD

Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|----------------------|-------------------|-----------------------------|-------------|----------------|------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | 1 | | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles | s): 0.36 | Section Length (MI) | 0.36 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 79 | 79 | | | | |
| Surface Condition Ra | ating (SCR) | 89 | 89 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | lex | 90 | 90 | | | | |
| Alligator Crack Inde | ex | 99 | 99 | | | | |
| Longitudinal Crack | Index | 91 | 91 | | | | |
| Transverse Cracking | g Index | 99 | 99 | | | | |
| Patching Index | | 99 | 99 | | | | |
| Rutting Index | | 89 | 89 | | | | |
| International Rough | nness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Infor | mation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 17.7 | 17.7 | | | | |
| Lane Width (ft) | | 8.9 | 8.9 | | | | |

ROUTE 0404: GRIST ROAD


Data Collection Vehicle (DCV) Rating



| Rout | e Condition Legend – Pav | rement Cond | ition Rating (PCR) | |
|-------------------------------------|--------------------------|-------------|----------------------|-----------|
| | | (85 - 94) | Excellent (95 - 100) | Not Rated |
| | See Appendix for det | | | |
| Inspection Date: 8/17/2016 | Beginning Section MP | 0 | | |
| Paved Length (Miles): 0.37 | Section Length (MI) | 0.37 | | |
| Surface Type: ASPHALT | Route Summary | | | |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR) | 91 | 91 | | |
| Surface Condition Rating (SCR) | 91 | 91 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 99 | 99 | | |
| Alligator Crack Index | 100 | 100 | | |
| Longitudinal Crack Index | 99 | 99 | | |
| Transverse Cracking Index | 99 | 99 | | |
| Patching Index | 99 | 99 | | |
| Rutting Index | 91 | 91 | | |
| International Roughness Index (IRI) | N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 2 | 2 | | |
| Paved Width (ft) | 16.8 | 16.8 | | |
| Lane Width (ft) | 11.3 | 11.3 | | |

ROUTE 0407: CAMEL'S HUMP ROAD


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (I | PCR) | | |
|----------------------|-------------------|-----------------------------|-------------|-----------------|----------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | 1 | | <u> </u> | | |
| Inspection Date: | 8/17/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Mile | es): 0.13 | Section Length (MI) | 0.13 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | n Information | | | | | | |
| Pavement Conditio | n Rating (PCR) | 94 | 94 | | | | |
| Surface Condition R | tating (SCR) | 94 | 94 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack In- | dex | 97 | 97 | | | | |
| Alligator Crack Ind | lex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 97 | 97 | | | | |
| Transverse Crackin | ig Index | 100 | 100 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 94 | 94 | | | | |
| International Rough | hness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 14.4 | 14.4 | | | | |
| Lane Width (ft) | | 8.8 | 8.8 | | | | |

ROUTE 0408: LAKE MCDONALD HORSE STABLES ROAD

Manual Rating



| | Route (| Condition Legend – Pav | ement Condi | tion Rating (| PCR) | | |
|----------------------|-------------------|-----------------------------|-----------------|---------------|------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (| | Not Ra | ted |
| | | See Appendix for def | finitions and f | ormulas | | | |
| Inspection Date: | 7/26/2016 | Beginning Section MP | 0.00 | | | | |
| Paved Length (Mile | es): 0.07 | Section Length (MI) | 0.07 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Conditio | n Rating (PCR) | 73 | 73 | | | | |
| Surface Condition R | ating (SCR) | 73 | 73 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Valu | es | | | | | | |
| Structural Crack Inc | dex | N/A | N/A | | | | |
| Alligator Crack Ind | lex | 73 | 73 | | | | |
| Longitudinal Crack | Index | 90 | 90 | | | | |
| Transverse Crackin | g Index | 90 | 90 | | | | |
| Patching Index | | 90 | 90 | | | | |
| Rutting Index | | 90 | 90 | | | | |
| International Rough | nness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 11 | 11 | | | | |
| Lane Width (ft) | | 11 | 11 | | | | |

ROUTE 0408: LAKE MCDONALD HORSE STABLES ROAD

Condition Photos

Condition photos are shown only for manually rated roads. Use the PathView program to see images of DCV rated roads.



GLAC_0408_3878.JPG



GLAC_0408_3879.JPG



GLAC_0408_3880.JPG



GLAC_0408_3881.JPG




GLAC_0408_3882.JPG



GLAC_0408_3883.JPG

ROUTE 0409A: GRINNELL DRIVE


Data Collection Vehicle (DCV) Rating



| D | C 122 | | Programme (DCD) | |
|-------------------------------------|-----------------------------|----------------|-----------------------------|-----------|
| | Condition Legend – Pav | | | |
| Poor (0 - 60) Fair (6 | Good (| (85 - 94) | Excellent (95 - 100) | Not Rated |
| | See Appendix for def | initions and f | ormulas | |
| Inspection Date: 8/17/2016 | Beginning Section MP | 0 | | |
| Paved Length (Miles): 0.17 | Section Length (MI) | 0.17 | | |
| Surface Type: ASPHALT | Route Summary | | | |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR) | 81 | 81 | | |
| Surface Condition Rating (SCR) | 81 | 81 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 81 | 81 | | |
| Alligator Crack Index | 100 | 100 | | |
| Longitudinal Crack Index | 81 | 81 | | |
| Transverse Cracking Index | 92 | 92 | | |
| Patching Index | 100 | 100 | | |
| Rutting Index | 86 | 86 | | |
| International Roughness Index (IRI) | N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 2 | 2 | | |
| Paved Width (ft) | 22.5 | 22.5 | | |
| Lane Width (ft) | 11.2 | 11.2 | | |

ROUTE 0409B: LOGAN LANE


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|----------------------|-------------------|-----------------------------|-----------------|----------------|------|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for def | finitions and f | ormulas | | | |
| Inspection Date: | 8/17/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Mile | es): 0.35 | Section Length (MI) | 0.35 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | n Rating (PCR) | 62 | 62 | | | | |
| Surface Condition R | ating (SCR) | 62 | 62 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack Inc | dex | 62 | 62 | | | | |
| Alligator Crack Ind | lex | 100 | 100 | | | | |
| Longitudinal Crack | Index | 62 | 62 | | | | |
| Transverse Crackin | g Index | 81 | 81 | | | | |
| Patching Index | | 99 | 99 | | | | |
| Rutting Index | | 94 | 94 | | | | |
| International Rough | nness Index (IRI) | N/A | N/A | | | | |
| Lane & Width Infor | rmation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 23.3 | 23.3 | | | | |
| Lane Width (ft) | | 11.6 | 11.6 | | | | |

ROUTE 0409C: SPERRY DRIVE


Data Collection Vehicle (DCV) Rating



| Poute | Condition Legend – Pav | oment Cond | ition Dating (DCD) | |
|-------------------------------------|------------------------|------------|----------------------|------------|
| | | (85 - 94) | Excellent (95 - 100) | Not Rated |
| 1001 (0 00) | See Appendix for def | 1 | | 110t Rateu |
| 1 1 D 1 0/17/2016 | | | I | I I |
| Inspection Date: 8/17/2016 | Beginning Section MP | | | |
| Paved Length (Miles): 0.15 | Section Length (MI) | 0.15 | | |
| Surface Type: ASPHALT | Route Summary | | | |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR) | 98 | 98 | | |
| Surface Condition Rating (SCR) | 98 | 98 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 99 | 99 | | |
| Alligator Crack Index | 100 | 100 | | |
| Longitudinal Crack Index | 99 | 99 | | |
| Transverse Cracking Index | 98 | 98 | | |
| Patching Index | 100 | 100 | | |
| Rutting Index | 99 | 99 | | |
| International Roughness Index (IRI) | N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 2 | 2 | | |
| Paved Width (ft) | 17.5 | 17.5 | | |
| Lane Width (ft) | 8.7 | 8.7 | | |

ROUTE 0409D: ALBRIGHT CIRCLE


Data Collection Vehicle (DCV) Rating



| Por | te Condition Legend – Pav | ement Cond | ition Rating (PCR) | |
|-------------------------------------|---------------------------|------------|----------------------|-----------|
| | | (85 - 94) | Excellent (95 - 100) | Not Rated |
| | See Appendix for def | | | |
| Inspection Date: 8/17/2016 | Beginning Section MP | | | |
| Paved Length (Miles): 0.33 | Section Length (MI) | 0.33 | | |
| Surface Type: ASPHALT | Route Summary | | | <u> </u> |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR) | 96 | 96 | | |
| Surface Condition Rating (SCR) | 96 | 96 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 98 | 98 | | |
| Alligator Crack Index | 100 | 100 | | |
| Longitudinal Crack Index | 98 | 98 | | |
| Transverse Cracking Index | 99 | 99 | | |
| Patching Index | 100 | 100 | | |
| Rutting Index | 96 | 96 | | |
| International Roughness Index (IRI) | N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 2 | 2 | | |
| Paved Width (ft) | 15.7 | 15.7 | | |
| Lane Width (ft) | 7.9 | 7.9 | | |

ROUTE 0409E: MATHER DRIVE


Data Collection Vehicle (DCV) Rating



| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | |
|--|--------------|----------------------|-----------|-------------|--|--------|-----|
| Poor (0 - 60) | Fair (6 | | (85 - 94) | Excellent (| | Not Ra | ted |
| | 10 (1 | See Appendix for de | , | | | | |
| Inspection Date: | 8/17/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles): | 0.32 | Section Length (MI) | 0.32 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition In | nformation | | | | | | |
| Pavement Condition F | Rating (PCR) | 87 | 87 | | | | |
| Surface Condition Ration | ng (SCR) | 87 | 87 | | | | |
| Roughness Condition I | ndex (RCI) | N/A | N/A | | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Index | X | 87 | 87 | | | | |
| Alligator Crack Index | | 99 | 99 | | | | |
| Longitudinal Crack In | dex | 88 | 88 | | | | |
| Transverse Cracking I | ndex | 97 | 97 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 94 | 94 | | | | |
| International Roughness Index (IRI) | | N/A | N/A | | | | |
| Lane & Width Inform | ation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 20.8 | 20.8 | | | | |
| Lane Width (ft) | | 11.3 | 11.3 | | | | |

ROUTE 0409F: RUHLE DRIVE


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | ition Rating (| PCR) | | |
|-------------------------------------|----------------|-----------------------------|-------------|----------------|------|--------|-----|
| Poor (0 - 60 | _ | | (85 - 94) | Excellent (9 | | Not Ra | ted |
| | | See Appendix for det | 1 | | * | | |
| Inspection Date: | 8/17/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Mile | es): 0.17 | Section Length (MI) | 0.17 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | Information | | | | | | |
| Pavement Conditio | n Rating (PCR) | 82 | 82 | | | | |
| Surface Condition R | ating (SCR) | 82 | 82 | | | | |
| Roughness Condition | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Value | es | | | | | | |
| Structural Crack In- | dex | 82 | 82 | | | | |
| Alligator Crack Ind | lex | 99 | 99 | | | | |
| Longitudinal Crack | Index | 83 | 83 | | | | |
| Transverse Crackin | g Index | 96 | 96 | | | | |
| Patching Index | | 100 | 100 | | | | |
| Rutting Index | | 95 | 95 | | | | |
| International Roughness Index (IRI) | | N/A | N/A | | | | |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 20.1 | 20.1 | | | | |
| Lane Width (ft) | | 10.1 | 10.1 | | | | |

ROUTE 0410A: HEADQUARTERS ADMINISTRATIVE ROAD A


Data Collection Vehicle (DCV) Rating



| | Route (| Condition Legend – Pav | ement Condi | tion Rating (| PCR) | | |
|-------------------------------------|--------------|-----------------------------|-------------|---------------|------|--------|-----|
| Poor (0 - 60) | | | (85 - 94) | Excellent (| | Not Ra | ted |
| | | See Appendix for def | , | | | | |
| Inspection Date: | 8/17/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Miles) |): 0.22 | Section Length (MI) | 0.22 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | • | |
| Roadway Condition | Information | | | | | | |
| Pavement Condition | Rating (PCR) | 57 | 57 | | | | |
| Surface Condition Rat | ting (SCR) | 57 | 57 | | | | |
| Roughness Condition | Index (RCI) | N/A | N/A | | | | |
| Distress Index Values | 3 | | | | | | |
| Structural Crack Inde | ex | 57 | 57 | | | | |
| Alligator Crack Inde | X | 87 | 87 | | | | |
| Longitudinal Crack I | Index | 70 | 70 | | | | |
| Transverse Cracking | Index | 90 | 90 | | | | |
| Patching Index | | 98 | 98 | | | | |
| Rutting Index | | 92 | 92 | | | | |
| International Roughness Index (IRI) | | N/A | N/A | | | | |
| Lane & Width Inforr | nation | | | | | | |
| Number of Lanes | | 2 | 2 | | | | |
| Paved Width (ft) | | 25.8 | 25.8 | | | | |
| Lane Width (ft) | | 12.9 | 12.9 | | | | |

ROUTE 0410B: HEADQUARTERS ADMINISTRATIVE ROAD B (VINT BOULEVARD)


Data Collection Vehicle (DCV) Rating



| Pout | Condition Legend – Pav | ament Cond | ition Poting (PCP) | |
|-------------------------------------|------------------------|------------|----------------------|-----------|
| | | (85 - 94) | Excellent (95 - 100) | Not Rated |
| | See Appendix for def | 1 | | - 100 |
| Inspection Date: 8/17/2016 | Beginning Section MP | | | |
| Paved Length (Miles): 0.14 | Section Length (MI) | 0.14 | | |
| Surface Type: ASPHALT | Route Summary | | | |
| Roadway Condition Information | | | | |
| Pavement Condition Rating (PCR) | 82 | 82 | | |
| Surface Condition Rating (SCR) | 82 | 82 | | |
| Roughness Condition Index (RCI) | N/A | N/A | | |
| Distress Index Values | | | | |
| Structural Crack Index | 82 | 82 | | |
| Alligator Crack Index | 100 | 100 | | |
| Longitudinal Crack Index | 82 | 82 | | |
| Transverse Cracking Index | 87 | 87 | | |
| Patching Index | 99 | 99 | | |
| Rutting Index | 87 | 87 | | |
| International Roughness Index (IRI) | N/A | N/A | | |
| Lane & Width Information | | | | |
| Number of Lanes | 2 | 2 | | |
| Paved Width (ft) | 26.7 | 26.7 | | |
| Lane Width (ft) | 13.3 | 13.3 | | |

ROUTE 0425: ST. MARY RESIDENCE AND HORSE STABLES ROAD


Data Collection Vehicle (DCV) Rating



| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | | |
|--|----------------|-----------------------------|-----------------|-------------|--|--------|-----|
| Poor (0 - 60 | | | (85 - 94) | Excellent (| | Not Ra | ted |
| | | See Appendix for def | finitions and f | ormulas | | | |
| Inspection Date: | 8/21/2016 | Beginning Section MP | 0 | | | | |
| Paved Length (Mile | es): 0.05 | Section Length (MI) | 0.05 | | | | |
| Surface Type: | ASPHALT | Route Summary | | | | | |
| Roadway Condition | n Information | | | | | | |
| Pavement Conditio | n Rating (PCR) | 36 | 36 | | | | |
| Surface Condition R | tating (SCR) | 36 | 36 | | | | |
| Roughness Conditio | n Index (RCI) | N/A | N/A | | | | |
| Distress Index Valu | es | | | | | | |
| Structural Crack In | dex | 36 | 36 | | | | |
| Alligator Crack Inc | lex | 68 | 68 | | | | |
| Longitudinal Crack | Index | 68 | 68 | | | | |
| Transverse Crackin | ig Index | 75 | 75 | | | | |
| Patching Index | | 99 | 99 | | | | |
| Rutting Index | | 88 | 88 | | | | |
| International Roughness Index (IRI) | | N/A | N/A | | | | |
| Lane & Width Info | rmation | | | | | | |
| Number of Lanes | | 1 | 1 | | | | |
| Paved Width (ft) | | 11.3 | 11.3 | | | | |
| Lane Width (ft) | | 11.3 | 11.3 | | | | |

ROUTE 0426: ST. MARY RESIDENCE / DIVIDE CREEK ACCESS

Data Collection Vehicle (DCV) Rating



Sources: Esri, HERE, DeLorme, TomTom, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), swisstopo, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

| Route (| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | |
|-------------------------------------|--|-----------|-----------------------------|-----------|--|--|--|
| Poor (0 - 60) Fair (6 | 1- 84) Good (| (85 - 94) | Excellent (95 - 100) | Not Rated | | | |
| | See Appendix for definitions and formulas | | | | | | |
| Inspection Date: 8/21/2016 | Beginning Section MP | 0 | | | | | |
| Paved Length (Miles): 0.08 | Section Length (MI) | 0.08 | | | | | |
| Surface Type: ASPHALT | Route Summary | | | | | | |
| Roadway Condition Information | | | | | | | |
| Pavement Condition Rating (PCR) | 83 | 83 | | | | | |
| Surface Condition Rating (SCR) | 83 | 83 | | | | | |
| Roughness Condition Index (RCI) | N/A | N/A | | | | | |
| Distress Index Values | | | | | | | |
| Structural Crack Index | 83 | 83 | | | | | |
| Alligator Crack Index | 98 | 98 | | | | | |
| Longitudinal Crack Index | 85 | 85 | | | | | |
| Transverse Cracking Index | 85 | 85 | | | | | |
| Patching Index | 99 | 99 | | | | | |
| Rutting Index | 89 | 89 | | | | | |
| International Roughness Index (IRI) | N/A | N/A | | | | | |
| Lane & Width Information | | | | | | | |
| Number of Lanes | 2 | 2 | | | | | |
| Paved Width (ft) | 19.7 | 19.7 | | | | | |
| Lane Width (ft) | 12.6 | 12.6 | | | | | |

NOTE: Route has a very short section with deteriorated asphalt.

Section 6 Paved Parking Area Condition Rating Sheets



Glacier National Park




ROUTE 0900: HEADQUARTERS VISITOR PARKING

Manual Rating

FROM ROUTE 0400 (HEADQUARTERS ROAD)

TO HQ PARKING AND UNPAVED ACCESS TO ROUTE 0901A (HEADQUARTERS EMPLOYEE PARKING)

| Inspection Date | FMSS Number | User Access | Surface Type | | | |
|---|--|------------------------------|---------------------|--|--|--|
| 7/25/2016 | 37337 | PUBLIC | ASPHALT | | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | | |
| 15,231 | 0.262 | NOT APPLICABLE | MODERATE REPAIR | | | |
| Curb | Туре | Curb & Gutter Type | | | | |
| NO C | CURB | CONCRETE | | | | |
| Pavement Rec | commendation | Condition Rating / PCR | | | | |
| RECONST | RUCTION | POOR / 30 | | | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | | |
| Poor (0 - 60) | | (85 - 94) Excellent (95 - 10 | 0) Not Rated | | | |
| See Appendix for definitions and formulas | | | | | | |



ROUTE 0901A: HEADQUARTERS EMPLOYEE PARKING

Manual Rating

FROM ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A)


TO ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A) AND UNPAVED ACCESS TO ROUTE 0900 (HEADQUARTERS VISITOR PARKING)

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|--|-------------------------|------------------------------|---------------------|--|--|
| 7/25/2016 | 6806 | NONPUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 28,572 | 0.492 | NOT APPLICABLE | MODERATE REPAIR | | |
| Curb | Туре | Curb & Gutter Type | | | |
| NO C | CURB | CONCRETE | | | |
| Pavement Rec | commendation | Condition Rating / PCR | | | |
| RECONST | RUCTION | POOR / 30 | | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |










ROUTE 0901B: HEADQUARTERS LIBRARY PARKING

Manual Rating

ADJACENT TO ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A) ON RIGHT

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|--|-------------------------|------------------------------|---------------------|--|--|
| 7/25/2016 | 107701 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 1,103 | 0.019 | NOT APPLICABLE | NOT APPLICABLE | | |
| Curb | Туре | Curb & Gutter Type | | | |
| NO C | CURB | NO CURB AND GUTTER | | | |
| Pavement Rec | commendation | Condition Rating / PCR | | | |
| LIGHT 3R TI | REATMENTS | FAIR | / 73 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| See Appendix for definitions and formulas | | | | | |





ROUTE 0901C: HEADQUARTERS MAINTENANCE BUILDING PARKING


Manual Rating

ADJACENT TO ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A) ON LEFT

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|--|-------------------------|------------------------|---------------------|--|--|
| 7/25/2016 | 107702 | NONPUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 3,688 | 0.063 | NOT APPLICABLE | NOT APPLICABLE | | |
| Curk | Туре | Curb & Gutter Type | | | |
| NO (| CURB | NO CURB AND GUTTER | | | |
| Pavement Re | commendation | Condition Rating / PCR | | | |
| RECONST | TRUCTION | POOR / 30 | | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | |
| Poor (0, 60) Fair (61, 84) Cood (85, 94) Evcellent (95, 100) Not Roted | | | | | |







ROUTE 0901D: HEADQUARTERS MAINTENANCE AREA PARKING (SCOYEN CIRCLE)

Manual Rating

FROM END OF ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A)


THROUGH MAINTENANCE AREA

| Inspection Date | FMSS Number | User Access | Surface Type | | | |
|---|--|------------------------------|---------------------|--|--|--|
| 7/25/2016 | 107703 | NONPUBLIC | ASPHALT | | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | | |
| 81,132 | 1.397 | NOT APPLICABLE | NOT APPLICABLE | | | |
| Curb | Туре | Curb & Gutter Type | | | | |
| NO 0 | CURB | NO CURB AND GUTTER | | | | |
| Pavement Rec | commendation | Condition Rating / PCR | | | | |
| RECONST | RUCTION | POOR / 30 | | | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | | |
| Poor (0 - 60) | Fair (61- 84) Good | (85 - 94) Excellent (95 - 10 | 0) Not Rated | | | |
| See Appendix for definitions and formulas | | | | | | |



Note: Street name sign in parking lot calls this area "Scoyen Circle". Maintenance area consists of multiple surface types; 1 part asphalt at 80,306 square feet and 1 part concrete at 826 square feet.







ROUTE 0901E: HEADQUARTERS ELECTRONIC OFFICE PARKING

Manual Rating


ADJACENT TO ROUTE 0410B (HEADQUARTERS ADMINISTRATIVE ROAD B (VINT BOULEVARD)) ON RIGHT

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|--|-------------------------|------------------------------|---------------------|--|--|
| 7/25/2016 | 107705 | NONPUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 1,219 | 0.021 | NOT APPLICABLE | NOT APPLICABLE | | |
| Curb | Туре | Curb & Gutter Type | | | |
| NO C | CURB | NO CURB AND GUTTER | | | |
| Pavement Rec | commendation | Condition Rating / PCR | | | |
| HEAVY 3R T | REATMENTS | POOR | 2 / 53 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | |
| Poor (0 - 60) | | (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| See Appendix for definitions and formulas | | | | | |









ROUTE 0901F: HEADQUARTERS FUELING AREA

Manual Rating

FROM ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A)

TO ROUTE 0410B (HEADQUARTERS ADMINISTRATIVE ROAD B (VINT BOULEVARD))


| Inspection Date | FMSS Number | User Access | Surface Type | |
|---|--|------------------------------|---------------------|--|
| 7/26/2016 | 248437 | NONPUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 19,665 | 0.339 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| RECONST | RUCTION | POOR / 30 | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |



Fuel area consists of multiple surface types; 2 parts asphalt at 16,389 square feet and 1 part concrete at 3,276 square feet. The concrete section is in poor condition.







ROUTE 0903: SCHOOL HOUSE PARKING

Manual Rating

FROM ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.15

TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------|---------------------|
| 7/26/2016 | 37390 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 6,453 | 0.111 | 6 | DO NOTHING |
| Curb Type | | Curb & Gutter Type | |
| WOOD | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |

Poor (0 - 60)


Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated






ROUTE 0904A: APGAR PUBLIC PARKING A

Manual Rating

ADJACENT TO ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.20

| Inspection Date | FMSS Number | User Access | Surface Type | |
|---|--|------------------------------|---------------------|--|
| 7/26/2016 | 37311 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 2,196 | 0.038 | NOT APPLICABLE | DO NOTHING | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB | | CONCRETE | | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| PREVENTIVE MAINTENANCE GOOD / 90 | | 0 / 90 | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) | ` ' | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |




ROUTE 0904B: APGAR PUBLIC PARKING B

Manual Rating

FROM ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.23

TO ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.28

| Inspection Date | FMSS Number | User Access | Surface Type | |
|---|---|----------------------|---------------------|--|
| 7/26/2016 | 107706 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 11,973 | 0.206 | 4 | MODERATE REPAIR | |
| Curb Type | | Curb & Gutter Type | | |
| WOOD | | CONCRETE | | |
| Pavement Recommendation | | Condition R | ating / PCR | |
| PREVENTIVE N | PREVENTIVE MAINTENANCE | | GOOD / 90 | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) | Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated | | | |
| See Appendix for definitions and formulas | | | | |



ROUTE 0905: APGAR VILLAGE COMPLEX PARKING


Manual Rating

FROM ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.27

TO PARKING AROUND APGAR VILLAGE INN

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|---|--|------------------------------|---------------------|--|--|
| 7/26/2016 | 37314 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 51,077 | 0.879 | NOT APPLICABLE | DO NOTHING | | |
| Curb Type | | Curb & Gutter Type | | | |
| NO C | NO CURB | | CONCRETE | | |
| Pavement Recommendation | | Condition Rating / PCR | | | |
| PREVENTIVE MAINTENANCE GOOD / 90 | | 0 / 90 | | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| See Appendix for definitions and formulas | | | | | |






ROUTE 0906: APGAR BOAT LAUNCH PARKING

Manual Rating

FROM ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.34

TO ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.35

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/26/2016 | 37303 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 11,320 | 0.195 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb Type Curb & Gutter Ty | | utter Type | | |
| NO CURB | | NO CURB AND GUTTER | | |
| Pavement Rec | commendation | Condition Rating / PCR | | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | <u> </u> | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |




ROUTE 0907: APGAR RANGERS / RESTROOM PARKING

Manual Rating

FROM ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.37

TO ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.40

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/26/2016 | 37312 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 19,821 | 0.341 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB NO CURE | | NO CURB AI | ND GUTTER | |
| Pavement Rec | commendation | tion Condition Rating / PCR | | |
| LIGHT 3R TREATMENTS | | FAIR | / 73 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |



ROUTE 0908A: APGAR AMPHITHEATER PARKING A

Manual Rating

ADJACENT TO ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.76 ON LEFT

| Inspection Date | FMSS Number | User Access | Surface Type |
|----------------------------------|-------------------------|----------------------|---------------------|
| 7/26/2016 | 6808 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 2,284 | 0.039 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Rec | Pavement Recommendation | | ating / PCR |
| PREVENTIVE MAINTENANCE GOOD / 90 | | 0 / 90 | |
| | | | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Good (85 - 94)


Excellent (95 - 100)

Not Rated









ROUTE 0908B: APGAR AMPHITHEATER PARKING B

Manual Rating


ADJACENT TO ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.77 ON RIGHT

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|----------------------|---------------------|
| 7/26/2016 | 103528 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 5,345 | 0.092 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation Condition Rating / PCR | | ating / PCR | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) | | | 0) Not Rated |
| See Appendix for definitions and formulas | | | |









ROUTE 0909: APGAR PICNIC LOOP

Manual Rating

FROM ROUTE 0101 (APGAR LOOP ROAD) AT MP $0.93\,$

TO ROUTE 0101 (APGAR LOOP ROAD) AT MP 1.06

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------|---------------------|
| 7/26/2016 | 6810 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 29,482 | 0.508 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO C | CURB | NO CURB A | ND GUTTER |
| Pavement Recommendation | | Condition Rating / PCR | |
| LIGHT 3R TREATMENTS | | FAIR / 73 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)


Not Rated












ROUTE 0911: FISH CREEK PICNIC AREA PARKING

Manual Rating

FROM ROUTE 0100A (FISH CREEK ACCESS ROAD)

TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/26/2016 | 6813 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 22,616 | 0.389 | 4 | DO NOTHING | |
| Curb Type | | Curb & Gutter Type | | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| HEAVY 3R T | HEAVY 3R TREATMENTS | | POOR / 53 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | · / | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |




ROUTE 0913: FISH CREEK RANGER RESIDENCE PARKING

Manual Rating

FROM ROUTE 0100A (FISH CREEK ACCESS ROAD)

TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|----------------------|---------------------|--|
| 7/26/2016 | 7708 | NONPUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 7,008 | 0.121 | 6 | LIGHT REPAIR | |
| Curb Type | | Curb & Gutter Type | | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition R | ating / PCR | |
| HEAVY 3R T | HEAVY 3R TREATMENTS | | POOR / 53 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | | | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |



ROUTE 0914A: FISH CREEK CAMPGROUND DUMP STATION


Manual Rating

FROM ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD)

TO ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD)


| Inspection Date | FMSS Number | User Access | Surface Type |
|-------------------------|--|-------------------------|---------------------|
| 7/26/2016 | 37397 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 2,799 | 0.048 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | |
| LIGHT 3R TREATMENTS | | FAIR / 73 | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | |
| Poor (0 60) | Foir (61 84) | (85 04) Evadlant (05 10 | Not Poted |











ROUTE 0914B: FISH CREEK CAMPGROUND AMPHITHEATER PARKING

Manual Rating

FROM ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD)


TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/26/2016 | 38754 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 15,205 | 0.262 | 6 | DO NOTHING | |
| Curb | Curb Type | | Curb & Gutter Type | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition R | ating / PCR | |
| HEAVY 3R T | REATMENTS | POOR / 53 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |









ROUTE 0915: MCGEE MEADOWS PARKING

Manual Rating

FROM ROUTE 0011 (CAMAS ROAD) AT MP 5.62

TO ROUTE 0011 (CAMAS ROAD) AT MP 5.64

| Inspection Date | FMSS Number | User Access | Surface Type | |
|------------------------------|-------------------------|------------------------------|---------------------|--|
| 7/26/2016 | 37371 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 7,995 | 0.138 | NOT APPLICABLE | DO NOTHING | |
| Curb | Curb Type | | Curb & Gutter Type | |
| NO C | CURB | CONC | CRETE | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| PREVENTIVE N | PREVENTIVE MAINTENANCE | | O / 90 | |
| Route Condition Legend – Pay | | ement Condition Rating (PCR) | | |

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated









ROUTE 0916: HUCKLEBERRY LOOKOUT TRAILHEAD PARKING

Manual Rating

ADJACENT TO ROUTE 0011 (CAMAS ROAD) AT MP 5.86

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|--------------------------------------|----------------------|---------------------|
| 7/26/2016 | 37166 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 6,125 | 0.105 | NOT APPLICABLE | NOT APPLICABLE |
| Curb | Curb Type Curb & Gutter Type | | utter Type |
| NO C | CURB | NO CURB AND GUTTER | |
| Pavement Rec | ecommendation Condition Rating / PCR | | ating / PCR |
| PREVENTIVE N | MAINTENANCE | GOOD / 90 | |
| Pouts Condition Logand Devement Condition Dating (DCD) | | | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated










ROUTE 0917: CAMAS CREEK OVERLOOK PARKING

Manual Rating

FROM ROUTE 0011 (CAMAS ROAD) AT MP 8.24

TO ROUTE 0011 (CAMAS ROAD) AT MP 8.30

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|--|----------------------|---------------------|--|
| 7/26/2016 | 37319 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 16,610 | 0.286 | 5 | DO NOTHING | |
| Curb | Curb Type | | Curb & Gutter Type | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Rec | Pavement Recommendation Condition Rating / PCR | | Rating / PCR | |
| PREVENTIVE N | PREVENTIVE MAINTENANCE | | O / 90 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| | | 0) Not Rated | | |
| | | | | |




ROUTE 0918: CAMAS CREEK ENTRANCE STATION PARKING

Manual Rating

ADJACENT TO ROUTE 0011 (CAMAS ROAD) AT MP 10.81

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/26/2016 | 37318 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 4,615 | 0.079 | NOT APPLICABLE | DO NOTHING | |
| Curb | Type | Curb & Gutter Type | | |
| NO CURB | | CONCRETE | | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| PREVENTIVE N | MAINTENANCE | GOOD / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| | initions and formulas | | | |
| | | | | |



ROUTE 0919: HUCKLEBERRY MOUNTAIN TRAILHEAD PARKING

Manual Rating


ADJACENT TO ROUTE 0241 (HUCKLEBERRY MOUNTAIN ROAD)

| Inspection Date | FMSS Number | User Access | Surface Type |
|---|-------------------------|------------------------|---------------------|
| 7/26/2016 | 6822 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 1,950 | 0.034 | NOT APPLICABLE | DO NOTHING |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | CONCRETE | |
| Pavement Recommendation | | Condition Rating / PCR | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) Fair (61 - 84) Good (85 - 94) Excellent (95 - 10) | | Not Rated | |











ROUTE 0922: LAKESHORE FOREST PARKING

Manual Rating

ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 7.81

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------|---------------------|--|
| 7/26/2016 | 37167 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 6,170 | 0.106 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb | Curb Type | | Curb & Gutter Type | |
| NO C | CURB | NO CURB AND GUTTER | | |
| Pavement Rec | commendation | Condition Rating / PCR | | |
| PREVENTIVE N | MAINTENANCE | GOOD / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated









ROUTE 0923: LINCOLN LAKE PARKING

Manual Rating


ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP $9.29\,$

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|----------------------|---------------------|--|
| 7/26/2016 | 37171 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 4,439 | 0.076 | 5 | DO NOTHING | |
| Curb Type | | Curb & Gutter Type | | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition R | ating / PCR | |
| PREVENTIVE N | MAINTENANCE | GOOD / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated See Appendix for definitions and formulas | | | 0) Not Rated | |









ROUTE 0926A: LAKE MCDONALD LODGE PARKING

Manual Rating

FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.19


TO ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.21

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|--|--|------------------------------|---------------------|--|--|
| 7/26/2016 | 6818 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 10,881 | 0.187 | 5 | DO NOTHING | | |
| Curb Type | | Curb & Gutter Type | | | |
| WOOD | | NO CURB AND GUTTER | | | |
| Pavement Recommendation Condition Rating / | | ating / PCR | | | |
| LIGHT 3R TREATMENTS | | FAIR / 73 | | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| See Appendix for definitions and formulas | | | | | |









ROUTE 0926B: LAKE MCDONALD CABIN LOOP AND PARKING

Manual Rating

FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.11


TO ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.18

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------|---------------------|--|
| 7/26/2016 | 103592 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 11,453 | 0.197 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb Type Curb & Gutter Type | | utter Type | | |
| NO CURB | | NO CURB AND GUTTER | | |
| Pavement Rec | commendation | Condition Rating / PCR | | |
| LIGHT 3R TREATMENTS | | FAIR / 73 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | | | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |










ROUTE 0927: LAKE MCDONALD GENERAL PARKING

Manual Rating

FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 10.64

TO ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.19

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/26/2016 | 37360 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 56,158 | 0.967 | 4 | LIGHT REPAIR | |
| Curb Type | | Curb & Gutter Type | | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition R | ating / PCR | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |




ROUTE 0928A: LAKE MCDONALD RESTAURANT PARKING

Manual Rating

FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.13

TO ROUTE 0927 (LAKE MCDONALD GENERAL PARKING)

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/26/2016 | 37357 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 14,575 | 0.251 | 5 | DO NOTHING | |
| Curb Type | | Curb & Gutter Type | | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition R | ating / PCR | |
| PREVENTIVE N | MAINTENANCE | GOOD / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |



ROUTE 0928B: LAKE MCDONALD RESTAURANT REAR PARKING


Manual Rating

FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.09

TO PARKING


| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|---|------------------------|---------------------|--|
| 7/26/2016 | 107707 | NONPUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 8,955 | 0.154 | NOT APPLICABLE | DO NOTHING | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB | | CONCRETE | | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 60) | Poor (0, 60) Foir (61, 84) Cood (85, 94) Evapling (95, 100) Not Poted | | | |















ROUTE 0929: LAKE MCDONALD POST OFFICE PARKING

Manual Rating

FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.08

TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/26/2016 | 37349 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 7,422 | 0.128 | NOT APPLICABLE | NOT APPLICABLE | |
| Curt | Curb Type | | Curb & Gutter Type | |
| NO CURB | | NO CURB AND GUTTER | | |
| Pavement Recommendation Condition Rating / PCR | | Rating / PCR | | |
| HEAVY 3R TREATMENTS | | POOR / 53 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |




ROUTE 0930: LAKE MCDONALD GENERAL STORE PARKING

Manual Rating

ADJACENT TO ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.07

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|---|--|------------------------------|---------------------|--|--|
| 7/26/2016 | 8341 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 8,554 | 0.147 | NOT APPLICABLE | NOT APPLICABLE | | |
| Curb | Curb Type | | Curb & Gutter Type | | |
| NO CURB | | NO CURB AND GUTTER | | | |
| Pavement Recommendation | | Condition Rating / PCR | | | |
| LIGHT 3R TREATMENTS FAIR / 73 | | / 73 | | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | | (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| See Appendix for definitions and formulas | | | | | |




ROUTE 0932: MCDONALD CREEK OVERLOOK

Manual Rating

ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 14.26 $\,$

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|---------------------------------------|------------------------------|---------------------|--|
| 7/27/2016 | 6797 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 9,255 | 0.159 | 7 | MODERATE REPAIR | |
| Curb Type | | Curb & Gutter Type | | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Recommendation Condition Rating / PCF | | ating / PCR | | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | · · · · · · · · · · · · · · · · · · · | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |





ROUTE 0934A: AVALANCHE CAMPGROUND PARKING A / RANGER RESIDENCE PARKING

Manual Rating


ADJACENT TO ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) AT MP 0.05 ON RIGHT

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/27/2016 | 38751 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 1,179 | 0.02 | 7 | DO NOTHING | |
| Curb Type | | Curb & Gutter Type | | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition R | ating / PCR | |
| PREVENTIVE | PREVENTIVE MAINTENANCE | | GOOD / 90 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | • | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |









ROUTE 0934B: AVALANCHE CAMPGROUND PARKING B

Manual Rating


ADJACENT TO ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) AT MP 0.07 ON LEFT

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------------|---------------------|
| 7/27/2016 | 103544 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 2,796 | 0.048 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition R | Rating / PCR |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) | Fair (61- 84) Good | (85 - 94) Excellent (95 - 10 | 0) Not Rated |










ROUTE 0934C: AVALANCHE CAMPGROUND PARKING C

Manual Rating

ADJACENT TO ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) AT MP 0.08 ON RIGHT

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/27/2016 | 103550 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 1,235 | 0.021 | 6 | LIGHT REPAIR | |
| Curb Type | | Curb & Gutter Type | | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition R | ating / PCR | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |





ROUTE 0934D: AVALANCHE CAMPGROUND HANDICAPPED PARKING (TRAIL OF THE CEDARS)

Manual Rating

FROM ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) AT MP 0.09

TO ROUTE 0201CZZ (AVALANCHE CAMPGROUND SERVICE ROAD AND SPUR)

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|---|--|------------------------------|---------------------|--|--|
| 7/27/2016 | 103563 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 4,139 | 0.071 | NOT APPLICABLE | NOT APPLICABLE | | |
| Curb | Туре | Curb & Gutter Type | | | |
| NO CURB | | NO CURB AND GUTTER | | | |
| Pavement Recommendation | | Condition Rating / PCR | | | |
| RECONSTRUCTION | | POOR / 30 | | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) Fair (61- 84) Good | | (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| See Appendix for definitions and formulas | | | | | |
| | | | | | |




ROUTE 0935: RED ROCK POINT PARKING

Manual Rating

ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 17.34

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|---|--|------------------------------|---------------------|--|--|
| 7/27/2016 | 247576 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 9,624 | 0.166 | NOT APPLICABLE | NOT APPLICABLE | | |
| Curb Type | | Curb & Gutter Type | | | |
| NO CURB | | NO CURB AND GUTTER | | | |
| Pavement Recommendation | | Condition Rating / PCR | | | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| See Appendix for definitions and formulas | | | | | |





ROUTE 0938A: LOOP PARKING AREA A

Manual Rating


ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 24.02 $\,$


| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------------|---------------------|
| 7/27/2016 | 6798 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 5,060 | 0.087 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition R | Rating / PCR |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated |












ROUTE 0938B: LOOP PARKING AREA B

Manual Rating

FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 24.09

TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type |
|---|----------------------------------|------------------------------|---------------------|
| 7/27/2016 | 103605 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 6,474 | 0.111 | 5 | DO NOTHING |
| Curb Type | | Curb & Gutter Type | |
| STONE | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | |
| PREVENTIVE N | PREVENTIVE MAINTENANCE GOOD / 90 | |) / 90 |
| | Route Condition Legend - Pav | ement Condition Rating (PCR) | |
| Poor (0 - 60) | · / | (85 - 94) Excellent (95 - 10 | 0) Not Rated |
| See Appendix for definitions and formulas | | | |



ROUTE 0939A: ROAD CAMP PARKING AREA A

Manual Rating

ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 26.79 ON RIGHT

| Inspection Date | FMSS Number | User Access | Surface Type |
|------------------------|-------------------------|-------------------------------|----------------------------|
| 7/27/2016 | 6801 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 2,324 | 0.04 | NOT APPLICABLE | NOT APPLICABLE |
| | Туре | Curb & G | utter Type |
| NO C | CURB | NO CURB A | ND GUTTER |
| Pavement Rec | | | ating / PCR |
| PREVENTIVE N | | GOOI |) / 90 |
| | | rement Condition Rating (PCR) | |
| Poor (0 - 60) | Fair (61- 84) Good | (85 - 94) Excellent (95 - 10 | 0) Not Rated |
| | See Appendix for det | finitions and formulas | |
| | | Rte. 0939B Rte. 0010W | |

Feet 70


140

ROUTE 0939B: ROAD CAMP PARKING AREA B

Manual Rating

ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 26.80 ON LEFT

| Inspection Date | FMSS Number | User Access | Surface Type | |
|---|------------------------------|------------------------------|---------------------|--|
| 7/27/2016 | 103861 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 2,327 | 0.04 | NOT APPLICABLE | NOT APPLICABLE | |
| Curl | Туре | Curb & G | utter Type | |
| NO (| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| PREVENTIVE | MAINTENANCE | GOOL | GOOD / 90 | |
| | Route Condition Legend - Pav | ement Condition Rating (PCR) | | |
| Poor (0 - 60) Fair (61- 84) Good | | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |
| 600 | | | | |




ROUTE 0941ZZ: BIG BEND PARKING AREAS

Summary Route Manual Rating

ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 29.02

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|--|------------------------------|--------------|
| 7/29/2016 | 247577 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) Condition Rating / PCR | | ating / PCR |
| 20,020 | 0.345 | SUMMA | RY / 90 |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated |
| See Appendix for definitions and formulas | | | |

The condition shown on this page reflects the overall route condition and may not reflect individual subcomponent ratings.




ROUTE 0941AZ: BIG BEND PARKING A

Subcomponent of Route GLAC-0941ZZ Manual Rating

ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 29.02 ON RIGHT

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|------------------------------|------------------------------|---------------------|--|
| 7/29/2016 | 247577 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 11,649 | 0.201 | 0 | DO NOTHING | |
| Curb Type | | Curb & Gutter Type | | |
| CONCRETE | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition R | Rating / PCR | |
| PREVENTIVE N | MAINTENANCE | GOOI | O / 90 | |
| | Route Condition Legend - Pav | ement Condition Rating (PCR) | | |
| Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated See Appendix for definitions and formulas | | | | |



ROUTE 0941BZ: BIG BEND PARKING B

Subcomponent of Route GLAC-0941ZZ Manual Rating

ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 29.03 ON LEFT

| Inspection Date | FMSS Number | User Access | Surface Type | |
|------------------------|---|------------------------------|---------------------|--|
| 7/29/2016 | 247577 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 8,371 | 0.144 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb Type | | Curb & Gutter Type | | |
| NO C | NO CURB | | NO CURB AND GUTTER | |
| Pavement Rec | Pavement Recommendation | | ating / PCR | |
| PREVENTIVE N | MAINTENANCE | GOOL | 0 / 90 | |
| | Route Condition Legend - Pav | ement Condition Rating (PCR) | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| | See Appendix for definitions and formulas | | | |



ROUTE 0942: OBERLIN BEND PARKING

Manual Rating

ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 31.48

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------|---------------------|
| 7/27/2016 | 37372 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 6,396 | 0.11 | NOT APPLICABLE | DO NOTHING |
| Curb Type | | Curb & Gutter Type | |
| NO C | NO CURB CONCRETE | | CRETE |
| Pavement Recommendation | | Condition Rating / PCR | |
| LIGHT 3R TREATMENTS | | FAIR / 73 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated









ROUTE 0943: LOGAN PASS PARKING

Manual Rating

FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 31.86

TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 31.96

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------|---------------------|
| 7/27/2016 | 6779 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 114,883 | 1.978 | NOT APPLICABLE | LIGHT REPAIR |
| Curb Type | | Curb & Gutter Type | |
| NO C | NO CURB CONCRETE | | RETE |
| Pavement Recommendation | | Condition Rating / PCR | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | |
| Route Condition Legend – Payement Condition Rating (PCR) | | | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61-84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated


See Appendix for definitions and formulas




Parking area consists of multiple surface types; 1 part asphalt at 112,208 square feet and 3 parts concrete at 2,675 square feet. The concrete bus stop pads and handicapped parking spot are in good condition.









ROUTE 0944: LUNCH CREEK PARKING

Manual Rating

ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 32.65

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|----------------------------------|------------------------|---------------------|
| 7/27/2016 | 6765 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 8,587 | 0.148 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO C | CURB | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | |
| PREVENTIVE N | PREVENTIVE MAINTENANCE GOOD / 90 | |) / 90 |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated

See Appendix for definitions and formulas









Rte. 0010E




ROUTE 0945ZZ: SIYEH BEND PARKING AREAS

Summary Route Manual Rating

ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 34.66 $\,$

| Inspection Date | FMSS Number | User Access | Surface Type | |
|---|--|--|--------------|--|
| 8/21/2016 | 247578 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Lane Miles (11' Widths) Condition Rating / PCR | | |
| 22,099 | 0.38 | SUMMA | RY / 97 | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |

The condition shown on this page reflects the overall route condition and may not reflect individual subcomponent ratings.



ROUTE 0945AZ: SIYEH BEND PARKING A

Subcomponent of Route GLAC-0945ZZ Manual Rating


ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 34.50 ON RIGHT

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|-----------------|--|------------------------------|---------------------|--|--|
| 8/21/2016 | 247578 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 6,499 | 0.112 | NOT APPLICABLE | NOT APPLICABLE | | |
| Curb | Curb Type Curb & Gutter Type | | utter Type | | |
| NO C | NO CURB | | NO CURB AND GUTTER | | |
| Pavement Rec | Pavement Recommendation Condition Rating / PCR | | ating / PCR | | |
| DO NO | THING | EXCELLI | ENT / 97 | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| | See Appendix for definitions and formulas | | | | |









ROUTE 0945BZ: SIYEH BEND PARKING B

Subcomponent of Route GLAC-0945ZZ Manual Rating

ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 34.61 ON LEFT

| Inspection Date | FMSS Number | User Access | Surface Type |
|--------------------------|-------------------------|----------------------|---------------------|
| 8/21/2016 | 247578 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 3,188 | 0.055 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition R | ating / PCR |
| DO NOTHING EXCELLENT / 9 | | ENT / 97 | |
| | | | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated









ROUTE 0945CZ: SIYEH BEND PARKING C

Subcomponent of Route GLAC-0945ZZ Manual Rating


ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 34.61 ON RIGHT

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------------|---------------------|
| 8/21/2016 | 247578 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 3,218 | 0.055 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type Curb & Gutter Type | | utter Type | |
| NO (| CURB | NO CURB AND GUTTER | |
| Pavement Re- | Pavement Recommendation | | Rating / PCR |
| DO NOTHING EXCELLENT / 97 | | ENT / 97 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) | Fair (61- 84) Good | (85 - 94) Excellent (95 - 10 | Not Rated |









ROUTE 0945DZ: SIYEH BEND PARKING D

Subcomponent of Route GLAC-0945ZZ Manual Rating

ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 34.71 ON LEFT

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------|---------------------|
| 8/21/2016 | 247578 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 1,298 | 0.022 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO C | CURB | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | |
| DO NOTHING | | EXCELLENT / 97 | |
| Pouts Condition Logard Poyoment Condition Pating (PCP) | | | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated









ROUTE 0945EZ: SIYEH BEND PARKING E

Subcomponent of Route GLAC-0945ZZ **Manual Rating**

ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 34.72 ON RIGHT

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|------------------------------|------------------------|---------------------|
| 8/21/2016 | 247578 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 4,011 | 0.069 | NOT APPLICABLE | NOT APPLICABLE |
| Curb | Curb Type Curb & Gutter Type | | utter Type |
| NO C | CURB | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | |
| DO NOTHING | | EXCELLENT / 97 | |
| Route Condition Legend – Payement Condition Rating (PCR) | | | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61-84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated










ROUTE 0945FZ: SIYEH BEND PARKING F

Subcomponent of Route GLAC-0945ZZ Manual Rating

ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 34.92 ON RIGHT

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------|---------------------|
| 8/21/2016 | 247578 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 3,885 | 0.067 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | |
| DO NOTHING | | EXCELLENT / 97 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) Fycallent (05 - 100) Not Poted | | | |





ROUTE 0946A: JACKSON GLACIER OVERLOOK PARKING

Manual Rating

ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 36.53

| Inspection Date | FMSS Number | User Access | Surface Type |
|-----------------------------------|-------------------------|------------------------|---------------------|
| 7/27/2016 | 6766 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 5,167 | 0.089 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type Curb & Gutter Type | | utter Type | |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | |
| DO NOTHING EXCELL | | ENT / 97 | |
| D + G 114 Y 1 D + G 114 D + (DGD) | | | • |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated

See Appendix for definitions and formulas




Parking area consists of multiple surface types; 2 parts asphalt at 4,812 square feet and 1 part concrete at 355 square feet. The concrete shuttle pad is in excellent condition.





Rie. 0946A



ROUTE 0946B: GUNSIGHT TRAILHEAD PARKING

Manual Rating

ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 36.62

| Inspection Date | FMSS Number | User Access | Surface Type |
|-----------------|------------------------------|------------------------------|---------------------|
| 7/27/2016 | 103585 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 6,516 | 0.112 | NOT APPLICABLE | NOT APPLICABLE |
| Curl | Туре | ype Curb & Gutter Type | |
| NO (| CURB | NO CURB AND GUTTER | |
| Pavement Re | Pavement Recommendation | | Rating / PCR |
| DO NO | DO NOTHING EXCELLENT / 97 | | ENT / 97 |
| | Route Condition Legend - Pay | ement Condition Rating (PCR) | |
| Poor (0 - 60) | Fair (61- 84) Good | (85 - 94) Excellent (95 - 10 | Not Rated |

See Appendix for definitions and formulas





Rte. 0946B



ROUTE 0947: SUNRIFT GORGE PARKING (PAVED)

Manual Rating

ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 39.41

| Inspection Date | FMSS Number | User Access | Surface Type |
|------------------------------|-------------------------|------------------------|---------------------|
| 7/27/2016 | 6767 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 4,333 | 0.075 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type Curb & Gutter Type | | utter Type | |
| NO C | NO CURB AND GUTTER | | ND GUTTER |
| Pavement Recommendation | | Condition Rating / PCR | |
| DO NOTHING | | EXCELLENT / 97 | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)


Not Rated











ROUTE 0948: SUN POINT PICNIC AREA PARKING

Manual Rating

FROM END OF ROUTE 0211ZZ (SUN POINT ROAD)

TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------|---------------------|
| 7/29/2016 | 6768 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 63,363 | 1.091 | 6 | DO NOTHING |
| Curb Type | | Curb & Gutter Type | |
| CONCRETE AND STONE | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | |
| DO NOTHING | | EXCELLENT / 97 | |
| Pouts Condition Logand Poyament Condition Pating (PCP) | | | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)


Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)


Not Rated














ROUTE 0949A: WILD GOOSE ISLAND PARKING A

Manual Rating


ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 42.87 $\,$

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|------------------------------|------------------------------|---------------------|
| 7/27/2016 | 37243 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 3,587 | 0.062 | NOT APPLICABLE | NOT APPLICABLE |
| Curb | Curb Type Curb & Gutter Type | | utter Type |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation Condition Rating / PCR | | ating / PCR | |
| DO NOTHING EXCELLENT / 97 | | ENT / 97 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated |
| See Appendix for definitions and formulas | | | |










ROUTE 0949B: WILD GOOSE ISLAND PARKING B

Manual Rating

ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 42.95 $\,$

| Inspection Date | FMSS Number | User Access | Surface Type | |
|---|--|------------------------------|---------------------|--|
| 7/27/2016 | 103868 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 8,053 | 0.139 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb | Туре | Curb & Gutter Type | | |
| NO C | NO CURB AND GUTT | | ND GUTTER | |
| Pavement Rec | commendation | Condition Rating / PCR | | |
| DO NO | THING | EXCELLI | ENT / 97 | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |






ROUTE 0950: RISING SUN BOAT TOURS PARKING

Manual Rating

FROM ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 43.59

TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|---|--|------------------------------|---------------------|--|--|
| 7/27/2016 | 6778 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 64,527 | 1.111 | NOT APPLICABLE | DO NOTHING | | |
| Curb Type | | Curb & Gutter Type | | | |
| NO CURB | | CONCRETE | | | |
| Pavement Recommendation | | Condition Rating / PCR | | | |
| PREVENTIVE N | MAINTENANCE | GOOD / 90 | | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good | (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| See Appendix for definitions and formulas | | | | | |



ROUTE 0951A: RISING SUN MOTEL BUS PARKING

Manual Rating


FROM ROUTE 0212F (RISING SUN LODGE ROAD F)

TO ROUTE 0212F (RISING SUN LODGE ROAD F)

| Inspection Date | FMSS Number | User Access | Surface Type |
|---|-------------------------|------------------------|---------------------|
| 7/27/2016 | 6775 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 8,481 | 0.146 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated | | | |







ROUTE 0951B: RISING SUN MOTEL AND RESTAURANT PARKING

Manual Rating

FROM ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 43.72

TO ROUTE 0212F (RISING SUN LODGE ROAD F)

User Access

PUBLIC

Surface Type

ASPHALT

6-66

FMSS Number

103873

Inspection Date

7/27/2016

| Curb Type Curb & Gutter Type | Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
|---|----------------|--|-----------------------------------|------------------------------------|
| NO CURB Pavement Recommendation Condition Rating / PCR PREVENTIVE MAINTENANCE Route Condition Legend – Pavement Condition Rating (PCR) Fair (61-84) See Appendix for definitions and formulas Note: This parking area contains bridge structure 1430-004 (Rising Sun Campground Bridge). Refe. 0951A Refe. 0951A Refe. 09212F | 60,203 | 1.037 | NOT APPLICABLE | DO NOTHING |
| Pavement Recommendation Condition Rating / PCR PREVENTIVE MAINTENANCE Route Condition Legend – Pavement Condition Rating (PCR) Fair (61-84) Good (85-94) Excellent (95-100) Not Rated See Appendix for definitions and formulas Note: This parking area contains bridge structure 1430-004 (Rising Sun Campground Bridge). Refe. 0951C Refe. 0951B Refe. 0951H Refe. 0951H | | | Curb & Gutter Type | |
| Route Condition Legend – Pavement Condition Rating (PCR) Fair (61-84) See Appendix for definitions and formulas Note: This parking area contains bridge structure 1430-004 (Rising Sun Campground Bridge). Refe. 0951A Refe. 0951B Refe. 0951H | NO CURB | | CONC | RETE |
| Route Condition Legend – Pavement Condition Rating (PCR) Fair (61-84) See Appendix for definitions and formulas Note: This parking area contains bridge structure 1430-004 (Rising Sun Campground Bridge). Refe. 0951C Refe. 0951A Refe. 0951H | | | | |
| Poor (0 - 60) Fair (61- 84) See Appendix for definitions and formulas Note: This parking area contains bridge structure 1430-004 (Rising Sun Campground Bridge). Refe. 0951C Refe. 0951B Refe. 0951H | PREVENTIVE M | | | D / 90 |
| See Appendix for definitions and formulas Note: This parking area contains bridge structure 1430-004 (Rising Sun Campground Bridge). Ref. 0951C Ref. 0951B Ref. 0951B Ref. 0951H | | | | |
| Note: This parking area contains bridge structure 1430-004 (Rising Sun Campground Bridge). Refe. 0951C Refe. 0951B Refe. 0951B Refe. 0951B | Poor (0 - 60) | | | Not Rated |
| N Feet | | Note: This parking area of Refer to 213B | Rte. 0951C Rte. 0951C Rte. 0951 | Rte. 0951A Rte. 0951A Rte. 0951H |

ROUTE 0951C: RISING SUN MOTEL REAR STORE PARKING

Manual Rating

FROM ROUTE 0212A (RISING SUN LODGE ROAD A) AT MP 0.03

TO PARKING


| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/27/2016 | 103876 | NONPUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 7,652 | 0.132 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb | Curb Type | | Curb & Gutter Type | |
| NO (| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation Condition Rating / PCR | | Rating / PCR | | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good | (85 - 94) Excellent (95 - 10 | Not Rated | |

See Appendix for definitions and formulas









ROUTE 0951D: RISING SUN LOWER MOTEL PARKING (SOUTH)

Manual Rating

FROM ROUTE 0212A (RISING SUN LODGE ROAD A) AT MP 0.08

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------------|---------------------|
| 7/27/2016 | 103877 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 5,016 | 0.086 | 4 | MODERATE REPAIR |
| Curb Type | | Curb & Gutter Type | |
| WOOD | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition R | Rating / PCR |
| RECONSTRUCTION | | POOR / 30 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) | ` ' | (85 - 94) Excellent (95 - 10 | 0) Not Rated |
| See Appendix for definitions and formulas | | | |




ROUTE 0951E: RISING SUN LOWER MOTEL PARKING (NORTH)

Manual Rating

FROM ROUTE 0212A (RISING SUN LODGE ROAD A) AT MP 0.11

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/27/2016 | 103878 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 3,743 | 0.064 | 2 | REPLACE | |
| Curb | Curb Type | | Curb & Gutter Type | |
| WC | WOOD | | NO CURB AND GUTTER | |
| Pavement Rec | Pavement Recommendation | | ating / PCR | |
| RECONSTRUCTION | | POOR / 0 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |




ROUTE 0951F: RISING SUN UPPER MOTEL PARKING (SOUTH)

Manual Rating

FROM ROUTE 0212A (RISING SUN LODGE ROAD A) AT MP 0.14

| Inspection Date | FMSS Number | User Access | Surface Type |
|---|-------------------------|----------------------|---------------------|
| 7/27/2016 | 103879 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 5,143 | 0.089 | 5 | LIGHT REPAIR |
| Curb Type | | Curb & Gutter Type | |
| WOOD | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition R | Rating / PCR |
| RECONSTRUCTION | | POOR / 0 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated | | | |
| See Appendix for definitions and formulas | | | |



ROUTE 0951G: RISING SUN UPPER MOTEL PARKING (NORTH)

Manual Rating

FROM END OF ROUTE 0212A (RISING SUN LODGE ROAD A) AT MP 0.19


TO PARKING AND ROUTE 0212E (RISING SUN LODGE ROAD E)

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/27/2016 | 103881 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 3,036 | 0.052 | 4 | LIGHT REPAIR | |
| Curb | Туре | Curb & Gutter Type | | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| RECONST | RECONSTRUCTION POOR / 0 | | R / 0 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | · · · · · | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |











ROUTE 0951H: RISING SUN RESTAURANT REAR PARKING

Manual Rating


FROM ROUTE 0212F (RISING SUN LODGE ROAD F)


| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|--|------------------------------|---------------------|--|
| 7/27/2016 | 107708 | NONPUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 5,380 | 0.093 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb | Curb Type | | Curb & Gutter Type | |
| NO C | NO CURB | | NO CURB AND GUTTER | |
| Pavement Rec | Pavement Recommendation Condition Rating / PCR | | ating / PCR | |
| HEAVY 3R TREATMENTS | | POOR / 53 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |












ROUTE 0953: RISING SUN PICNIC AREA PARKING

Manual Rating

FROM ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 43.87

| FMSS Number | User Access | Surface Type | | |
|---|--|---|--|--|
| 6777 | PUBLIC | ASPHALT | | |
| Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 0.768 | 6 | REPLACE | | |
| Curb Type | | Curb & Gutter Type | | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| PREVENTIVE MAINTENANCE GOOD / 90 | |) / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated | | | | |
| | Cood of Cood o | 6777 PUBLIC Lane Miles (11' Widths) Curb Reveal (Inches) 0.768 6 Type Curb & G OD NO CURB AD ommendation Condition R MAINTENANCE GOOD Route Condition Legend – Pavement Condition Rating (PCR) | | |



ROUTE 0954: TWO DOG FLATS PARKING

Manual Rating

ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 47.35

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|----------------------|---------------------|
| 7/28/2016 | 37240 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 3,699 | 0.064 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO C | NO CURB AND GUTTER | | ND GUTTER |
| Pavement Rec | Pavement Recommendation | | Rating / PCR |
| DO NO | DO NOTHING | | ENT / 97 |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)


Not Rated

See Appendix for definitions and formulas









ROUTE 0955A: ST. MARY CAMPGROUND PARKING A / DUMP STATION

Manual Rating

FROM ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD)

TO ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD)

| Inspection Date | FMSS Number | User Access | Surface Type |
|------------------------|-------------------------|----------------------|---------------------|
| 7/28/2016 | 103882 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 2,108 | 0.036 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Rec | Pavement Recommendation | | Rating / PCR |
| HEAVY 3R T | HEAVY 3R TREATMENTS | | R / 53 |
| D 4 G 100 Y 1 D | | AC III DAI (DCD) | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61-84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated


See Appendix for definitions and formulas



Dump station consists of multiple surface types; 2 parts asphalt at 1,738 square feet and 1 part concrete at 370 square feet. The concrete section is in good condition.







ROUTE 0955B: ST. MARY CAMPGROUND PARKING B

Manual Rating

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|--------------------------|------------------------------|---------------------|--|
| 7/28/2016 | 103884 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 897 | 0.015 | 7 | DO NOTHING | |
| Curb | Curb Type | | Curb & Gutter Type | |
| WC | WOOD | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition R | ating / PCR | |
| RECONST | RECONSTRUCTION POOR / 30 | | 2 / 30 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |













ROUTE 0955C: ST. MARY CAMPGROUND PARKING C


Manual Rating

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|--|------------------------------|---------------------|--|
| 7/28/2016 | 103885 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 2,157 | 0.037 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb | Curb Type Curb & Gutter Type | | utter Type | |
| NO (| NO CURB | | NO CURB AND GUTTER | |
| Pavement Re | Pavement Recommendation Condition Rating / PCR | | Rating / PCR | |
| RECONSTRUCTION | | POOR / 0 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |










ROUTE 0955D: ST. MARY CAMPGROUND PARKING D

Manual Rating

| Inspection Date | FMSS Number | User Access | Surface Type | |
|---|------------------------------|------------------------------|---------------------|--|
| 7/28/2016 | 103886 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 1,123 | 0.019 | 8 | MODERATE REPAIR | |
| Curb Type | | Curb & Gutter Type | | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| HEAVY 3R T | REATMENTS | TS POOR / 53 | | |
| | Route Condition Legend - Pav | ement Condition Rating (PCR) | | |
| Poor (0 - 60) | Poor (0 - 60) | | | |
| See Appendix for definitions and formulas | | | | |



ROUTE 0955E: ST. MARY CAMPGROUND PARKING E

Manual Rating

ADJACENT TO ROUTE 0214A (ST. MARY CAMPGROUND LOOP A) AT MP 0.34

| Inspection Date | FMSS Number | User Access | Surface Type |
|------------------------|-------------------------|-------------------------------|---------------------|
| 7/28/2016 | 103888 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 467 | 0.008 | 6 | DO NOTHING |
| | Туре | | Gutter Type |
| | OOD | NO CURB A | ND GUTTER |
| Pavement Rec | | | Rating / PCR |
| RECONST | RUCTION | 1 | R / 30 |
| | | rement Condition Rating (PCR) | |
| Poor (0 - 60) | | (85 - 94) Excellent (95 - 10 | Not Rated |
| | See Appendix for det | finitions and formulas | |
| | | Rte. 0955E Rte. 0214A | |

10

20

ROUTE 0955F: ST. MARY CAMPGROUND PARKING F


Manual Rating

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------|---------------------|--|
| 7/28/2016 | 103889 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 932 | 0.016 | 4 | LIGHT REPAIR | |
| Curb Type | | Curb & Gutter Type | | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition R | ating / PCR | |
| LIGHT 3R TREATMENTS | | FAIR / 73 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | | | | |
| | See Appendix for def | finitions and formulas | | |












ROUTE 0955G: ST. MARY CAMPGROUND PARKING G

Manual Rating

| Inspection Date | FMSS Number | User Access | Surface Type | |
|---|------------------------------|------------------------------|---------------------|--|
| 7/28/2016 | 103890 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 924 | 0.016 | 7 | LIGHT REPAIR | |
| Curb Type | | Curb & Gutter Type | | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| RECONSTRUCTION | | POOR / 30 | | |
| | Route Condition Legend - Pav | ement Condition Rating (PCR) | | |
| Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) | | | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |
| | | | | |



ROUTE 0955H: ST. MARY CAMPGROUND PARKING H


Manual Rating

| Inspection Date | FMSS Number | User Access | Surface Type |
|------------------------|------------------------------|------------------------------|---------------------|
| 7/28/2016 | 103891 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 842 | 0.014 | 8 | LIGHT REPAIR |
| | Туре | Curb & G | |
| | WOOD | | ND GUTTER |
| | commendation | | ating / PCR |
| RECONST | RUCTION | POOR | 2 / 30 |
| | Route Condition Legend - Pav | | |
| Poor (0 - 60) | | (85 - 94) Excellent (95 - 10 | 0) Not Rated |
| | See Appendix for def | initions and formulas | |
| | | Rte. 0214B | |
| | N 0 | Feet | |

ROUTE 0955I: ST. MARY CAMPGROUND PARKING I

Manual Rating

| Inspection Date | FMSS Number | User Access | Surface Type |
|---|------------------------------|------------------------------|---------------------|
| 7/28/2016 | 103892 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 945 | 0.016 | 6 | LIGHT REPAIR |
| Curb Type | | Curb & Gutter Type | |
| WOOD | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition R | ating / PCR |
| HEAVY 3R TREATMENTS | | POOR / 53 | |
| | Route Condition Legend - Pav | ement Condition Rating (PCR) | |
| Poor (0 - 60) | Fair (61- 84) | | |
| See Appendix for definitions and formulas | | | |



ROUTE 0955J: ST. MARY CAMPGROUND PARKING J

Manual Rating

| Inspection Date | FMSS Number | User Access | Surface Type |
|------------------------|-------------------------|------------------------------|---------------------|
| 7/28/2016 | 103893 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 691 | 0.012 | 6 | DO NOTHING |
| | Туре | Curb & G | |
| WC | WOOD | | ND GUTTER |
| | commendation | Condition R | _ |
| RECONST | RUCTION | POOR | . / 30 |
| | | ement Condition Rating (PCR) | |
| Poor (0 - 60) | | (85 - 94) Excellent (95 - 10 | Not Rated |
| | See Appendix for def | finitions and formulas | |
| | | Rte. 0214B Rte. 0955J | |

ROUTE 0955K: ST. MARY CAMPGROUND PARKING K


Manual Rating

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/28/2016 | 103894 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 1,097 | 0.019 | 6 | DO NOTHING | |
| Curb Type | | Curb & Gutter Type | | |
| WOOD | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| RECONSTRUCTION POO | | POOR | 2 / 30 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |











ROUTE 0955L: ST. MARY CAMPGROUND PARKING L

Manual Rating

| Inspection Date | FMSS Number | User Access | Surface Type |
|------------------------|--|-----------------------------------|---------------------|
| 7/28/2016 | 103896 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 740 | 0.013 | 7 | DO NOTHING |
| Curb | | Curb & G | |
| WO | OD | NO CURB A | ND GUTTER |
| Pavement Rec | | Condition R | |
| HEAVY 3R TI | | POOR | 2 / 53 |
| | Route Condition Legend – Pav | | |
| Poor (0 - 60) | The state of the s | (85 - 94) Excellent (95 - 10 | 0) Not Rated |
| | See Appendix for def | initions and formulas | |
| | N O | Rte. 0214B Rte. 0955L Feet 20 40 | |

ROUTE 0955M: ST. MARY CAMPGROUND PARKING M


Manual Rating

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|--|-------------------------|-----------------------|---------------------|--|--|
| 7/28/2016 | 248438 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 962 | 0.017 | 5 | DO NOTHING | | |
| Curb Type | | Curb & Gutter Type | | | |
| WOOD | | NO CURB AND GUTTER | | | |
| Pavement Recommendation Condition Rating / PCR | | ating / PCR | | | |
| RECONST | RECONSTRUCTION POOR / 0 | | R / 0 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | |
| Poor (0 - 60) | | | | | |
| 1 | See Appendix for def | initions and formulas | | | |












ROUTE 0955N: ST. MARY CAMPGROUND PARKING N

Manual Rating

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|--|--|----------------------|---------------------|--|--|
| 7/28/2016 | 248439 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 1,280 | 0.022 | NOT APPLICABLE | NOT APPLICABLE | | |
| Curb Type Curb & Gutter Type | | utter Type | | | |
| NO CURB | | NO CURB AND GUTTER | | | |
| Pavement Recommendation Condition Rating / PCR | | ating / PCR | | | |
| RECONST | RECONSTRUCTION POOR / 0 | | | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | | | | | |
| | See Appendix for definitions and formulas | | | | |




ROUTE 0956: ST. MARY RIVER PARKING

Manual Rating

ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP $49.14\,$

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|--|--|----------------------|---------------------|--|--|
| 7/28/2016 | 37384 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 2,892 | 0.05 | NOT APPLICABLE | NOT APPLICABLE | | |
| Curb Type Curb & Gutter Type | | | utter Type | | |
| NO CURB | | NO CURB AND GUTTER | | | |
| Pavement Recommendation Condition Rating / PCR | | | ating / PCR | | |
| DO NO | THING | EXCELLI | ENT / 97 | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated See Appendix for definitions and formulas | | | | | |



ROUTE 0957: ST. MARY VISITOR CENTER PARKING

Manual Rating

FROM ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 49.36

TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 49.53

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------|---------------------|
| 7/28/2016 | 6773 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 94,940 | 1.635 | 5 | DO NOTHING |
| Curb Type | | Curb & Gutter Type | |
| CONCRETE | | CONCRETE | |
| Pavement Recommendation | | Condition Rating / PCR | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | |
| Poyto Condition Logard Devement Condition Poting (PCP) | | | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated


See Appendix for definitions and formulas



Parking area consists of multiple surface types; 1 part asphalt at 92,436 square feet and 1 part concrete at 2,504 square feet. The concrete bus stop pad is in good condition.







ROUTE 0958: ST. MARY TREATMENT PLANT PARKING

Manual Rating

FROM ROUTE 0102 (ST. MARY RANGER STATION ROAD)

TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type |
|------------------------------|-------------------------|------------------------------|---------------------|
| 7/28/2016 | 37385 | NONPUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 4,872 | 0.084 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | |
| RECONSTRUCTION | | POOR / 30 | |
| Route Condition Legend – Pav | | ement Condition Rating (PCR) | |
| Poor (0 - 60) | Fair (61- 84) Good | (85 - 94) Excellent (95 - 10 | 0) Not Rated |


See Appendix for definitions and formulas



Parking area consists of multiple surface types; 2 parts asphalt at 3,462 square feet and 1 part concrete at 1,410 square feet. The concrete section is in good condition.








ROUTE 0959A: ST. MARY MAINTENANCE AREA PARKING A (HUDSON BAY DISTRICT OFFICE)

Manual Rating

ADJACENT TO ROUTE 0102 (ST. MARY RANGER STATION ROAD) ON LEFT

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/28/2016 | 6774 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 1,539 | 0.026 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb Type Curb & Gutter Type | | utter Type | | |
| NO CURB | | NO CURB AND GUTTER | | |
| Pavement Recommendation Condition Rating / PCR | | ating / PCR | | |
| LIGHT 3R TREATMENTS FAIR / 73 | | / 73 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | , , | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |



ROUTE 0959B: ST. MARY MAINTENANCE AREA PARKING B (HUDSON BAY DISTRICT OFFICE)

Manual Rating

FROM ROUTE 0102 (ST. MARY RANGER STATION ROAD)

THROUGH MAINTENANCE AREA


| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/28/2016 | 107710 | NONPUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 37,906 | 0.653 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| RECONST | RUCTION | POOR / 30 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | · / | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |



Maintenance area consists of multiple surface types; 1 part asphalt at 35,115 square feet and 4 parts concrete at 2,791 square feet.








ROUTE 0959C: ST. MARY MAINTENANCE AREA PARKING C (HUDSON BAY DISTRICT OFFICE)

Manual Rating

ADJACENT TO ROUTE 0102 (ST. MARY RANGER STATION ROAD) ON LEFT

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/28/2016 | 107711 | NONPUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 1,228 | 0.021 | NOT APPLICABLE | REPLACE | |
| Curb Type Curb & Gutter | | utter Type | | |
| NO CURB | | CONCRETE | | |
| Pavement Recommendation | | Condition R | ating / PCR | |
| HEAVY 3R TREATMENTS | | POOR | 2 / 53 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |



ROUTE 0960A: ST. MARY RESIDENCE AREA PARKING A

Manual Rating


ADJACENT TO ROUTE 0402 (ST. MARY HOUSING AREA ROAD) AT MP 0.25 ON RIGHT

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/28/2016 | 8329 | NONPUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 1,925 | 0.033 | NOT APPLICABLE | REPLACE | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB | | CONCRETE | | |
| Pavement Recommendation | | Condition R | ating / PCR | |
| HEAVY 3R TREATMENTS | | POOR / 53 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | · · · · · | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |












ROUTE 0960B: ST. MARY RESIDENCE AREA PARKING B

Manual Rating

ADJACENT TO ROUTE 0402 (ST. MARY HOUSING AREA ROAD) AT MP 0.26 ON LEFT

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|--|------------------------------|---------------------|--|
| 7/28/2016 | 107712 | NONPUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 1,952 | 0.034 | NOT APPLICABLE | MODERATE REPAIR | |
| Curb Type Curb & Gutter Type | | utter Type | | |
| NO CURB | | CONCRETE | | |
| Pavement Re- | Pavement Recommendation Condition Rating / PCR | | ating / PCR | |
| RECONST | RECONSTRUCTION POOR / 0 | | R / 0 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |



ROUTE 0960C: ST. MARY RESIDENCE AREA PARKING C

Manual Rating


ADJACENT TO ROUTE 0402 (ST. MARY HOUSING AREA ROAD) AT MP 0.29 ON LEFT

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|----------------------|---------------------|
| 7/28/2016 | 107714 | NONPUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 1,582 | 0.027 | NOT APPLICABLE | MODERATE REPAIR |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | CONCRETE | |
| Pavement Recommendation Condition Rating / PCR | | ating / PCR | |
| RECONST | RECONSTRUCTION POOR / 0 | | R / 0 |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) | | | |
| See Appendix for definitions and formulas | | | |










ROUTE 0962: GOAT LICK OVERLOOK PARKING


Manual Rating

FROM ROUTE 5000 (U.S. HIGHWAY 2)

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|----------------------|---------------------|
| 7/28/2016 | 6833 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 34,619 | 0.596 | 5 | DO NOTHING |
| Curb Type | | Curb & Gutter Type | |
| ASPHALT | | NO CURB AND GUTTER | |
| Pavement Recommendation Condition Ratin | | Rating / PCR | |
| HEAVY 3R T | REATMENTS | ATMENTS POOR / 53 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) | | | |
| See Appendix for definitions and formulas | | | |







ROUTE 0964: RUNNING EAGLE FALLS PARKING

Manual Rating

FROM ROUTE 0012 (TWO MEDICINE ROAD) AT MP 5.18

TO ROUTE 0012 (TWO MEDICINE ROAD) AT MP 5.22

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------|---------------------|
| 7/28/2016 | 37380 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 12,113 | 0.209 | NOT APPLICABLE | DO NOTHING |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | CONCRETE | |
| Pavement Recommendation | | Condition Rating / PCR | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | |
| Pouts Condition Logard Poyament Condition Pating (PCP) | | | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)


Not Rated

See Appendix for definitions and formulas









ROUTE 0965: TWO MEDICINE STORE PARKING

Manual Rating

FROM END OF ROUTE 0012 (TWO MEDICINE ROAD) AT MP 7.28

TO ROUTE 0979 (TWO MEDICINE SCENIC CRUISE PARKING)

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------|---------------------|
| 7/28/2016 | 6793 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 30,445 | 0.524 | NOT APPLICABLE | DO NOTHING |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | CONCRETE | |
| Pavement Recommendation | | Condition Rating / PCR | |
| HEAVY 3R TREATMENTS | | POOR / 53 | |
| Pouts Condition Logand Poyament Condition Poting (PCP) | | | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)


Not Rated


See Appendix for definitions and formulas












ROUTE 0966A: TWO MEDICINE RANGER STATION PARKING A

Manual Rating

ADJACENT TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.02

| Inspection Date | FMSS Number | User Access | Surface Type | |
|---|--|------------------------------|---------------------|--|
| 7/28/2016 | 37296 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 2,204 | 0.038 | NOT APPLICABLE | DO NOTHING | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB | | CONCRETE | | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| LIGHT 3R TREATMENTS FAIR / 73 | | / 73 | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 - 60) | | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |




ROUTE 0966B: TWO MEDICINE RANGER STATION PARKING B

Manual Rating

FROM ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.03

TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|--|------------------------------|---------------------|--|
| 7/28/2016 | 107715 | NONPUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 4,032 | 0.069 | NOT APPLICABLE | MODERATE REPAIR | |
| Curb | Curb Type | | Curb & Gutter Type | |
| NO CURB | | CONCRETE | | |
| Pavement Rec | Pavement Recommendation Condition Rating / PCR | | ating / PCR | |
| HEAVY 3R TREATMENTS POO | | POOR | 2 / 53 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | Not Rated | |
| See Appendix for definitions and formulas | | | | |



ROUTE 0967: POIA LAKE PARKING

Manual Rating

ADJACENT TO ROUTE 0014 (MANY GLACIER ROAD) AT MP 10.40

| Inspection Date | FMSS Number | User Access | Surface Type |
|-------------------------|-------------------------|------------------------|---------------------|
| 7/29/2016 | 37234 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 3,978 | 0.068 | NOT APPLICABLE | NOT APPLICABLE |
| Curb | Туре | Curb & Gutter Type | |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | |
| LIGHT 3R TREATMENTS | | FAIR / 73 | |
| | | | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated











ROUTE 0968A: MANY GLACIER EMPLOYEE DORM PARKING

Manual Rating


ADJACENT TO ROUTE 0210 (MANY GLACIER HOTEL ROAD) ON LEFT

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|---|--------------------------------|---------------------|--|
| 7/29/2016 | 232113 | NONPUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 1,363 | 0.023 | NOT APPLICABLE | LIGHT REPAIR | |
| Curb | Туре | Curb & Gutter Type | | |
| NO CURB | | CONCRETE | | |
| Pavement Rec | commendation | ndation Condition Rating / PCR | | |
| LIGHT 3R TREATMENTS | | FAIR / 73 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated | | | |
| See Appendix for definitions and formulas | | | | |











ROUTE 0968B: MANY GLACIER HOTEL HANDICAP PARKING

Manual Rating

ADJACENT TO ROUTE 0210 (MANY GLACIER HOTEL ROAD) ON RIGHT

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|----------------------|---------------------|--|
| 7/29/2016 | 107716 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 2,835 | 0.049 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb | Curb Type | | Curb & Gutter Type | |
| NO CURB | | NO CURB A | ND GUTTER | |
| Pavement Recommendation | | Condition R | ating / PCR | |
| PREVENTIVE MAINTENANCE | | GOOI |) / 90 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |

Poor (0 - 60)

Fair (61-84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated









ROUTE 0968C: MANY GLACIER HOTEL TRAILHEAD PARALLEL PARKING

Manual Rating

ADJACENT TO ROUTE 0210 (MANY GLACIER HOTEL ROAD) ON LEFT


| Inspection Date | FMSS Numl | ber | User Access | Surface Type | |
|------------------------------|-------------------------|----------------|------------------------|---------------------|--|
| 7/29/2016 | 107717 | | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' V | Widths) Curl | Reveal (Inches) | Curb Recommendation | |
| 1,888 | 0.033 | NO' | ΓAPPLICABLE | LIGHT REPAIR | |
| Curb Type | | | Curb & Gutter Type | | |
| NO CURB | | | CONCRETE | | |
| Pavement Re | Pavement Recommendation | | Condition Rating / PCR | | |
| RECONS | RECONSTRUCTION | | POOR | 2 / 30 | |
| Route Condition Legend – Pav | | | ndition Rating (PCR) | | |
| Poor (0 - 60) | Fair (61- 84) | Good (85 - 94) | Excellent (95 - 10 | 0) Not Rated | |

Feet 75










ROUTE 0968D: MANY GLACIER HOTEL TRAILHEAD PARKING

Manual Rating

FROM ROUTE 0210 (MANY GLACIER HOTEL ROAD)

TO ROUTE 0210 (MANY GLACIER HOTEL ROAD)

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|---|--|----------------------|---------------------|--|--|
| 7/29/2016 | 107718 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 81,798 | 1.408 | NOT APPLICABLE | LIGHT REPAIR | | |
| Curb Type | | Curb & Gutter Type | | | |
| NO CURB | | CONCRETE | | | |
| Pavement Recommendation | | Condition R | ating / PCR | | |
| RECONST | RUCTION | POOR | 2 / 30 | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated | | | | | |
| See Appendix for definitions and formulas | | | | | |



ROUTE 0968E: MANY GLACIER HOTEL SOUTH PARKING

Manual Rating


ADJACENT TO ROUTE 0210 (MANY GLACIER HOTEL ROAD) ON RIGHT

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|---|--|------------------------------|---------------------|--|--|
| 7/29/2016 | 232976 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 5,030 | 0.087 | 7 | LIGHT REPAIR | | |
| Curb Type | | Curb & Gutter Type | | | |
| CONCRETE | | CONCRETE | | | |
| Pavement Recommendation | | Condition R | ating / PCR | | |
| HEAVY 3R T | HEAVY 3R TREATMENTS | | 2 / 53 | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| See Appendix for definitions and formulas | | | | | |










ROUTE 0971: MANY GLACIER HELIPAD PARKING

Manual Rating

FROM ROUTE 0014 (MANY GLACIER ROAD) AT MP 11.93

TO HELIPAD

| FMSS Number | User Access | Surface Type | | |
|---|---|---|--|--|
| 37222 | NONPUBLIC | ASPHALT | | |
| Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 0.163 | 0.163 NOT APPLICABLE | | | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | ating / PCR | | |
| HEAVY 3R TREATMENTS | | 2 / 53 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated | | | | |
| | 37222 Lane Miles (11' Widths) 0.163 Type CURB commendation REATMENTS Route Condition Legend – Pav Fair (61- 84) Good (| 37222 NONPUBLIC Lane Miles (11' Widths) Curb Reveal (Inches) 0.163 NOT APPLICABLE Type Curb & G URB NO CURB AI ommendation Condition R REATMENTS POOR Route Condition Legend – Pavement Condition Rating (PCR) | | |



ROUTE 0972: MANY GLACIER PICNIC AREA / GRINNELL GLACIER TRAILHEAD PARKING

Manual Rating

FROM ROUTE 0014 (MANY GLACIER ROAD) AT MP 12.06

TO ROUTE 0014 (MANY GLACIER ROAD) AT MP 12.12

| Inspection Date | FMSS Num | ber | User Access | Surface Type | |
|---|-----------------|----------------|---------------------------|---------------------|--|
| 7/29/2016 | 6786 | | PUBLIC ASP | | |
| Area (Sq. Ft.) | Lane Miles (11' | Widths) Cu | rb Reveal (Inches) | Curb Recommendation | |
| 24,332 | 0.419 | N | OT APPLICABLE | NOT APPLICABLE | |
| Curb Type | | | Curb & Gutter Type | | |
| NO CURB | | | NO CURB AND GUTTER | | |
| Pavement Recommendation Condition Ratin | | | lating / PCR | | |
| HEAVY 3R TREATMENTS | | | POOR / 53 | | |
| Route Condition Legend – Pav | | | ondition Rating (PCR) | | |
| Poor (0 - 60) | Fair (61- 84) | Good (85 - 94) | Excellent (95 - 10 | 0) Not Rated | |


Fair (61- 84) Good (85 - 94) Excellent (9














ROUTE 0973A: SWIFTCURRENT CABINS PARKING AREA A

Manual Rating

FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.16


TO ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.19

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|-------------------------|---|----------------------|---------------------|--|--|
| 7/28/2016 | 6790 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 7,691 | 0.132 | 7 | LIGHT REPAIR | | |
| Curb | Curb Type | | utter Type | | |
| WOOD | | NO CURB AND GUTTER | | | |
| Pavement Recommendation | | Condition R | ating / PCR | | |
| LIGHT 3R TREATMENTS | | FAIR / 73 | | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated | | | | |
| | See Appendix for definitions and formulas | | | | |









ROUTE 0973B: SWIFTCURRENT CABINS PARKING AREA B, ICEBERG LAKE TRAILHEAD PARKING

Manual Rating


ADJACENT TO ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.24

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|--|---|------------------------------|---------------------|--|--|
| 7/28/2016 | 240139 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 3,434 | 0.059 | 9 | LIGHT REPAIR | | |
| Curb Type | | Curb & Gutter Type | | | |
| WOOD | | NO CURB AND GUTTER | | | |
| Pavement Recommendation | | Condition R | ating / PCR | | |
| RECONSTRUCTION | | POOI | R / 0 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| | See Appendix for definitions and formulas | | | | |










ROUTE 0973C: SWIFTCURRENT CABINS PARKING AREA C

Manual Rating

FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.23

TO ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.26

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|---|--|------------------------------|---------------------|--|--|
| 7/28/2016 | 103900 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 7,429 | 0.128 | 7 | DO NOTHING | | |
| Curb | Curb Type | | Curb & Gutter Type | | |
| WOOD | | NO CURB AND GUTTER | | | |
| Pavement Rec | Pavement Recommendation | | ating / PCR | | |
| HEAVY 3R T | HEAVY 3R TREATMENTS | | 2 / 53 | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good | (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| See Appendix for definitions and formulas | | | | | |




ROUTE 0973D: SWIFTCURRENT CABINS PARKING AREA D

Manual Rating

FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.30

TO ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.33

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|--|--|----------------------|---------------------|--|--|
| 7/28/2016 | 103901 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 7,944 | 0.137 | 9 | LIGHT REPAIR | | |
| Curb Type | | Curb & Gutter Type | | | |
| WOOD | | NO CURB AND GUTTER | | | |
| Pavement Recommendation | | Condition R | Rating / PCR | | |
| HEAVY 3R T | HEAVY 3R TREATMENTS | | POOR / 53 | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated See Appendix for definitions and formulas | | | | | |



ROUTE 0973E: SWIFTCURRENT CABINS PARKING AREA E


Manual Rating

FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.36

TO PARKING


| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------|---------------------|
| 7/28/2016 | 103902 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 10,266 | 0.177 | 9 | LIGHT REPAIR |
| Curb Type | | Curb & Gutter Type | |
| WOOD | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | |
| HEAVY 3R TREATMENTS | | POOR / 53 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |
| Poor (0 = 60) Fycollant (05 = 100) Not Poted | | | |















ROUTE 0973F: SWIFTCURRENT CABINS PARKING AREA F, PINETOP MOTEL

Manual Rating

FROM ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) AT MP 0.44

TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type |
|---|------------------------------|------------------------------|---------------------|
| 7/28/2016 | 103899 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 5,214 | 0.09 | 7 | LIGHT REPAIR |
| Cur | ь Туре | Curb & G | utter Type |
| W | OOD | NO CURB A | ND GUTTER |
| Pavement Re | commendation | Condition Rating / PCR | |
| RECONSTRUCTION | | POOR / 30 | |
| | Route Condition Legend – Pav | ement Condition Rating (PCR) | |
| Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated | | | |
| | See Appendix for def | initions and formulas | |
| | Rte. 0208A | | |



220

110


ROUTE 0974: SWIFTCURRENT MOTOR INN PARKING

Manual Rating

FROM END OF ROUTE 0014 (MANY GLACIER ROAD) AT MP 12.44

TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type | |
|------------------------|---|-------------------------------|---------------------|--|
| 7/28/2016 | 6789 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 58,655 | 1.01 | 8 | LIGHT REPAIR | |
| Cur | ъ Туре | Curb & G | utter Type | |
| W | OOD | NO CURB A | ND GUTTER | |
| Pavement R | ecommendation | Condition Rating / PCR | | |
| PREVENTIVE | PREVENTIVE MAINTENANCE | | GOOD / 90 | |
| | Route Condition Legend - Pav | rement Condition Rating (PCR) | | |
| Poor (0 - 60) | Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated | | | |
| | See Appendix for def | finitions and formulas | | |
| | | | Rie. 0208A | |



ROUTE 0975: CRUSHER HILL PARKING

Manual Rating

FROM ROUTE 0013 (CHIEF MOUNTAIN INTERNATIONAL HIGHWAY) AT MP 4.88

TO ROUTE 0013 (CHIEF MOUNTAIN INTERNATIONAL HIGHWAY) AT MP 5.09

| Inspection Date | FMSS Number | User Access | Surface Type |
|------------------------|---|------------------------------|---------------------|
| 7/29/2016 | 37053 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 41,067 | 0.707 | NOT APPLICABLE | NOT APPLICABLE |
| Curb | Туре | Curb & G | utter Type |
| NO (| CURB | NO CURB AI | ND GUTTER |
| Pavement Re | commendation | Condition Rating / PCR | |
| LIGHT 3R T | REATMENTS | FAIR / 73 | |
| | Route Condition Legend - Pav | ement Condition Rating (PCR) | |
| Poor (0 - 60) | Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated | | |
| | See Appendix for def | initions and formulas | |
| | | | |



ROUTE 0976: BELLY RIVER TRAILHEAD PARKING

Manual Rating

FROM ROUTE 0013 (CHIEF MOUNTAIN INTERNATIONAL HIGHWAY)AT MP 14.07

TO ROUTE 0013 (CHIEF MOUNTAIN INTERNATIONAL HIGHWAY) AT MP 14.14

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------|---------------------|--|
| 7/29/2016 | 6782 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 25,973 | 0.447 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB | | NO CURB A | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| | | | | |

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated









ROUTE 0983: GRIZZLY POINT PARKING

Manual Rating

ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 37.33

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------|---------------------|--|
| 7/27/2016 | 38012 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 14,697 | 0.253 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB AND GUT | | ND GUTTER | | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| DO NOTHING | | EXCELLENT / 97 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 (0) (1 94) Cool (95 (04) Freellant (05 (100) Not Poted | | | | |

See Appendix for definitions and formulas









Rte. 0983



ROUTE 0984: APGAR CAMPGROUND DUMP STATION


Manual Rating

FROM ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) AT MP 0.07


TO ROUTE 0205A (APGAR CAMPGROUND LOOP A)

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|---|--|------------------------|---------------------|--|--|
| 7/26/2016 | 107719 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 2,380 | 0.041 | NOT APPLICABLE | NOT APPLICABLE | | |
| Curb Type | | Curb & Gutter Type | | | |
| NO CURB | | NO CURB AND GUTTER | | | |
| Pavement Recommendation | | Condition Rating / PCR | | | |
| PREVENTIVE MAINTENANCE GOOD / 90 | | 0 / 90 | | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | | | | | |
| See Appendix for definitions and formulas | | | | | |









ROUTE 0985: TWO MEDICINE CAMPGROUND DUMP STATION


Manual Rating

FROM ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.09

TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.11


| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/28/2016 | 107720 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 2,568 | 0.044 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB AND GUT | | ND GUTTER | | |
| Pavement Rec | Pavement Recommendation | | Rating / PCR | |
| LIGHT 3R TREATMENTS FAIR / 73 | | / 73 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |











ROUTE 0986A: LOGAN LANE PARKING A

Manual Rating


ADJACENT TO ROUTE 0409B (LOGAN LANE) AT MP 0.06

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/25/2016 | 107721 | NONPUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 4,237 | 0.073 | NOT APPLICABLE | MODERATE REPAIR | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB | | CONCRETE | | |
| Pavement Recommendation Condit | | Condition R | ating / PCR | |
| PREVENTIVE MAINTENANCE GOOD / 90 | | 0 / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |










ROUTE 0986B: LOGAN LANE PARKING B

Manual Rating

ADJACENT TO ROUTE 0409B (LOGAN LANE) AT MP 0.10

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|--|--|------------------------------|---------------------|--|--|
| 7/25/2016 | 107722 | NONPUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 7,617 | 0.131 | NOT APPLICABLE | NOT APPLICABLE | | |
| Curb Type | | Curb & Gutter Type | | | |
| NO CURB | | NO CURB AND GUTTER | | | |
| Pavement Recommendation Condition Rating / PCR | | ating / PCR | | | |
| RECONST | RECONSTRUCTION POOR / 30 | | 2 / 30 | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | · / | (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| See Appendix for definitions and formulas | | | | | |



ROUTE 0987: HEADQUARTERS COMMUNITY BUILDING PARKING

Manual Rating

FROM ROUTE 0409E (MATHER DRIVE)

TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------|---------------------|--|
| 7/25/2016 | 107723 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 15,488 | 0.267 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb Type | | Curb & Gutter Type | | |
| NO C | NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | | |
| Pouts Condition Logand Poyament Condition Pating (PCP) | | | | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated











ROUTE 0988: APGAR OLD VISITOR CENTER PARKING

Manual Rating

FROM ROUTE 0101 (APGAR LOOP ROAD) AT MP 0.22


TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/26/2016 | 107724 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 11,730 | 0.202 | NOT APPLICABLE | DO NOTHING | |
| Curb Type | | Curb & G | utter Type | |
| NO CURB | | CONCRETE | | |
| Pavement Recommendation Condition Rating / PCR | | ating / PCR | | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |









ROUTE 0989A: MANY GLACIER PARKING A / RANGER STATION

Manual Rating

ADJACENT TO ROUTE 0401 (MANY GLACIER HOUSING AREA ROAD)

FMSS Number User Access

Inspection Date

| Inspection Date | FMSS Number | User Access | Surface Type |
|-----------------|-------------------------|---|---------------------|
| 7/28/2016 | 107725 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 2,312 | 0.04 | NOT APPLICABLE | NOT APPLICABLE |
| Curb | Туре | Curb & (| Gutter Type |
| NO (| CURB | NO CURB A | ND GUTTER |
| Pavement Rec | commendation | Condition 1 | Rating / PCR |
| LIGHT 3R TI | REATMENTS | FAIF | R / 73 |
| Poor (0 - 60) | Fair (61- 84) Good | tefinitions and formulas Average Excellent (95 - 10) | |
| | | Rte. 0401 | 0989B |
| | Rte. 0401 | Rte. 0989A | |

30

60

Surface Type

ROUTE 0989B: MANY GLACIER PARKING B

Manual Rating

FROM ROUTE 0401 (MANY GLACIER HOUSING AREA ROAD)

TO ROUTE 0401 (MANY GLACIER HOUSING AREA ROAD)

| Inspection Date | FMSS Number | User Access | Surface Type |
|-------------------------|-------------------------|------------------------|---------------------|
| 7/28/2016 | 107726 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 3,459 | 0.06 | NOT APPLICABLE | NOT APPLICABLE |
| Curb | Curb Type | | utter Type |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | |
| RECONSTRUCTION | | POOR / 30 | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)

Not Rated









ROUTE 0989C: MANY GLACIER PARKING C / RESIDENCES

Manual Rating

FROM ROUTE 0401 (MANY GLACIER HOUSING AREA ROAD)

TO ROUTE 0401 (MANY GLACIER HOUSING AREA ROAD)

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|----------------------------------|----------------------|---------------------|
| 7/28/2016 | 107727 | NONPUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 9,592 | 0.165 | NOT APPLICABLE | NOT APPLICABLE |
| Curb | Curb Type Curb & Gutter Type | | utter Type |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition R | Rating / PCR |
| PREVENTIVE N | PREVENTIVE MAINTENANCE GOOD / 90 | | O / 90 |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)


Excellent (95 - 100)


Not Rated











ROUTE 0990: MANY GLACIER DUMP STATION

Manual Rating

FROM ROUTE 0014 (MANY GLACIER ROAD) AT MP 12.28

TO ROUTE 0014 (MANY GLACIER ROAD) AT MP 12.30

| | Inspection Date | FMSS Number | User Access | Surface Type |
|--|------------------------|------------------------------|-------------------------------|---------------------|
| | 7/28/2016 | 107728 | PUBLIC | ASPHALT |
| | Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| | 2,347 | 0.04 | NOT APPLICABLE | NOT APPLICABLE |
| | Curb Type | | Curb & Gutter Type | |
| | NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation Condition Rating / PCR | | Rating / PCR | | |
| LIGHT 3R TREATMENTS FAIR / 73 | | R / 73 | | |
| Γ | | Route Condition Legend – Par | vement Condition Rating (PCR) | |
| | Poor (0 - 60) | Fair (61- 84) Good | (85 - 94) Excellent (95 - 1 | Not Rated |


See Appendix for definitions and formulas




Dump station consists of multiple surface types; 2 parts asphalt at 2,094 square feet and 1 part concrete at 253 square feet. The concrete section is in excellent condition.










ROUTE 0991: MANY GLACIER ENTRANCE STATION PARKING

Manual Rating

ADJACENT TO ROUTE 0014 (MANY GLACIER ROAD) AT MP 7.56

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|------------------------|--|------------------------------|---------------------|--|--|
| 7/28/2016 | 107729 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 3,749 | 0.065 | NOT APPLICABLE | DO NOTHING | | |
| Curb | Туре | Curb & Gutter Type | | | |
| NO C | NO CURB | | CONCRETE | | |
| Pavement Rec | commendation | Condition Rating / PCR | | | |
| LIGHT 3R TREATMENTS | | FAIR / 73 | | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| | See Appendix for definitions and formulas | | | | |




ROUTE 0992A: TWO MEDICINE CAMPGROUND PARKING A

Manual Rating

ADJACENT TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.20 $\,$

| Inspection Date | FMSS Number | User Access | Surface Type | |
|------------------------|---|------------------------------|---------------------|--|
| 7/28/2016 | 107730 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 1,849 | 0.032 | NOT APPLICABLE | LIGHT REPAIR | |
| Curb | Curb Type Curb & Gutter Type | | utter Type | |
| NO CURB | | CONC | CRETE | |
| Pavement Rec | commendation | Condition Rating / PCR | | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | | |
| | Route Condition Legend - Pav | ement Condition Rating (PCR) | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| | See Appendix for definitions and formulas | | | |



ROUTE 0992B: TWO MEDICINE CAMPGROUND PARKING B

Manual Rating


ADJACENT TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.40 $\,$

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|---|------------------------------|---------------------|--|
| 7/28/2016 | 107731 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 3,661 | 0.063 | NOT APPLICABLE | DO NOTHING | |
| Curl | Туре | Curb & G | utter Type | |
| NO CURB | | CONCRETE | | |
| Pavement Recommendation Condition Rating / PCR | | ating / PCR | | |
| PREVENTIVE MAINTENANCE | | TENANCE GOOD / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| | See Appendix for definitions and formulas | | | |









ROUTE 0992C: TWO MEDICINE CAMPGROUND PARKING C

Manual Rating

ADJACENT TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.52

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|------------------------------|----------------------|---------------------|
| 7/28/2016 | 107732 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 1,507 | 0.026 | NOT APPLICABLE | NOT APPLICABLE |
| Curb | Curb Type Curb & Gutter Type | | utter Type |
| NO C | NO CURB AND GUTTER | | ND GUTTER |
| Pavement Recommendation | | Condition R | ating / PCR |
| PREVENTIVE MAINTENANCE | | GOOI |) / 90 |
| Pouts Condition Logard Devement Condition Poting (PCD) | | | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61-84)

Good (85 - 94)


Excellent (95 - 100)


Not Rated











ROUTE 0993: TWO MEDICINE PICNIC AREA PARKING


Manual Rating

FROM ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.03

TO ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) AT MP 0.14

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|------------------------------|------------------------------|---------------------|--|
| 8/21/2016 | 107693 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 27,602 | 0.475 | NOT APPLICABLE | DO NOTHING | |
| Curb | Curb Type Curb & Gutter Type | | utter Type | |
| NO C | NO CURB CONCRETE | | RETE | |
| Pavement Rec | commendation | Condition Rating / PCR | | |
| LIGHT 3R TREATMENTS | | FAIR / 73 | | |
| | Route Condition Legend - Pav | ement Condition Rating (PCR) | | |
| Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated See Appendix for definitions and formulas | | | | |






ROUTE 0994: WEST GLACIER INFO KIOSK PARKING


Manual Rating

FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 1.07 $\,$

TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 1.09 $\,$

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|---------------------------|------------------------------|---------------------|--|
| 7/26/2016 | 107738 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 4,394 | 0.076 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb | b Type Curb & Gutter Type | | utter Type | |
| NO C | CURB | NO CURB AND GUTTER | | |
| Pavement Rec | Pavement Recommendation | | ating / PCR | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |






ROUTE 0995ZZ: LOWER MCDONALD FALLS PARKING AREAS

Summary Route Manual Rating

ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 12.40

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|--------------|--|
| 7/27/2016 | 107739 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Condition R | ating / PCR | |
| 5,007 | 0.087 | SUMMA | RY / 90 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |

The condition shown on this page reflects the overall route condition and may not reflect individual subcomponent ratings.



ROUTE 0995AZ: LOWER MCDONALD FALLS HANDICAPPED PARKING

Subcomponent of Route GLAC-0995ZZ Manual Rating

ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 12.36

| Inspection Date | FMSS Number | User Access | Surface Type |
|------------------------|-------------------------|----------------------|---------------------|
| 7/27/2016 | 107739 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 1,196 | 0.021 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Rec | Pavement Recommendation | | ating / PCR |
| PREVENTIVE N | PREVENTIVE MAINTENANCE | | 0 / 90 |
| | ~ | | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)


Not Rated

See Appendix for definitions and formulas










ROUTE 0995BZ: LOWER MCDONALD FALLS PARKING

Subcomponent of Route GLAC-0995ZZ Manual Rating

ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 12.44

| Inspection Date | FMSS Number | User Access | Surface Type |
|------------------------|--|------------------------------|---------------------|
| 7/27/2016 | 107739 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 3,811 | 0.066 | 5 | LIGHT REPAIR |
| Curb Type | | Curb & Gutter Type | |
| WOOD | | NO CURB AND GUTTER | |
| Pavement Rec | Pavement Recommendation Condition Rating / PCR | | Rating / PCR |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | |
| | Route Condition Legend - Pav | ement Condition Rating (PCR) | |
| Poor (0 - 60) | | (85 - 94) Excellent (95 - 10 | 0) Not Rated |
| | See Appendix for def | initions and formulas | |





ROUTE 0996: RISING SUN CAMPGROUND DUMP STATION

Manual Rating

FROM ROUTE 0213B (RISING SUN CAMPGROUND ROAD B)

TO ROUTE 0213A (RISING SUN CAMPGROUND ROAD A)

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------|---------------------|--|
| 7/27/2016 | 107740 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 4,733 | 0.081 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| LIGHT 3R TREATMENTS | | FAIR / 73 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |

Poor (0 - 60)

Fair (61- 84)

Good (85 - 94)

Excellent (95 - 100)

Not Rated


See Appendix for definitions and formulas



Dump station consists of multiple surface types; 1 part asphalt at 4,463 square feet and 1 part concrete at 270 square feet. The concrete section is in excellent condition.










ROUTE 0997: AVALANCHE SHUTTLE STOP PARKING

Manual Rating

ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 16.16

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|---|--|------------------------------|---------------------|--|--|
| 7/27/2016 | 107741 | PUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 8,097 | 0.139 | NOT APPLICABLE | NOT APPLICABLE | | |
| Curb Type | | Curb & Gutter Type | | | |
| NO CURB | | NO CURB AND GUTTER | | | |
| Pavement Recommendation | | Condition R | Rating / PCR | | |
| PREVENTIVE N | PREVENTIVE MAINTENANCE | | O / 90 | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| See Appendix for definitions and formulas | | | | | |



ROUTE 0998: PAVED HORSE BARN PARKING

Manual Rating


ADJACENT TO ROUTE 0206 (WASTEWATER TREATMENT PLANT ROAD)

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|---|--|----------------------|---------------------|--|--|
| 7/26/2016 | 107742 | NONPUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 2,800 | 0.048 | NOT APPLICABLE | NOT APPLICABLE | | |
| Curb Type | | Curb & Gutter Type | | | |
| NO CURB | | NO CURB AND GUTTER | | | |
| Pavement Recommendation Condition Rating / PCR | | ating / PCR | | | |
| PREVENTIVE MAINTENANCE GOOD / 90 | |) / 90 | | | |
| | Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) Fair (61- 84) Good (85 - 94) Excellent (95 - 100) Not Rated | | | 0) Not Rated | | |

See Appendix for definitions and formulas









ROUTE 1040: LAKE MCDONALD LEWIS DORM PARKING

Manual Rating

ADJACENT TO ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.05

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|--|----------------------|---------------------|--|
| 7/26/2016 | 228276 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 1,090 | 0.019 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB | | NO CURB AND GUTTER | | |
| Pavement Rec | Pavement Recommendation Condition Rating / PCR | | ating / PCR | |
| PREVENTIVE N | PREVENTIVE MAINTENANCE | | 0 / 90 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |

Poor (0 - 60)

Fair (61- 84)


Good (85 - 94)

Excellent (95 - 100)


Not Rated


See Appendix for definitions and formulas












ROUTE 1041: APGAR TRANSIT CENTER PARKING

Manual Rating

FROM INTERSECTION OF ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 1.73 AND ROUTE 0011 (CAMAS ROAD)

TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type |
|---|------------------------------|------------------------------|---------------------|
| 7/26/2016 | 230217 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 127,609 | 2.197 | NOT APPLICABLE | DO NOTHING |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | CONCRETE | |
| Pavement Recommendation | | Condition R | Rating / PCR |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | |
| | Route Condition Legend - Pav | ement Condition Rating (PCR) | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated |
| See Appendix for definitions and formulas | | | |



ROUTE 1044: AVALANCHE PICNIC AREA PARKING


Manual Rating

FROM ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 16.13


TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 16.19

| Inspection Date | FMSS Number | User Access | Surface Type | |
|--|-------------------------|------------------------------|---------------------|--|
| 7/27/2016 | 6819 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 33,789 | 0.582 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB | | NO CURB AND GUTTER | | |
| Pavement Recommendation | | Condition Rating / PCR | | |
| PREVENTIVE MAINTENANCE GOOD / 90 | | 0 / 90 | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | |
| Poor (0 - 60) | Fair (61- 84) Good | (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |









ROUTE 1045: SPRAGUE CREEK PICNIC AREA PARKING

Manual Rating

FROM ROUTE 0242 (SPRAGUE CREEK CAMPGROUND ROAD)

TO PARKING LOOP

| | Inspection Date | FMSS Number | User Access | Surface Type |
|-------------------------|-----------------|------------------------------|------------------------------|---------------------|
| | 8/19/2016 | 37389 | PUBLIC | ASPHALT |
| | Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| | 12,456 | 0.214 | NOT APPLICABLE | NOT APPLICABLE |
| | Curb Type | | Curb & Gutter Type | |
| | NO (| CURB | NO CURB AND GUTTER | |
| Pavement Recommendation | | | Condition I | Rating / PCR |
| | RECONSTRUCTION | | POOR / 30 | |
| | | Route Condition Legend - Pav | ement Condition Rating (PCR) | |
| | Poor (0 - 60) | Fair (61- 84) Good | (85 - 94) Excellent (95 - 10 | 0) Not Rated |


Fair (61- 84) Good (85 - 94) Excell

See Appendix for definitions and formulas










ROUTE 1046: TRAIL OF THE CEDARS TRAILHEAD PARKING

Manual Rating

ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 16.31 $\,$

| Inspection Date | FMSS Number | User Access | Surface Type | |
|---|------------------------------|------------------------------|---------------------|--|
| 7/29/2016 | 247581 | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | |
| 9,712 | 0.167 | NOT APPLICABLE | NOT APPLICABLE | |
| Curb Type | | Curb & Gutter Type | | |
| NO CURB | | NO CURB AND GUTTER | | |
| Pavement Rec | commendation | Condition Rating / PCR | | |
| PREVENTIVE MAINTENANCE | | GOOD / 90 | | |
| | Route Condition Legend - Pav | ement Condition Rating (PCR) | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | |
| See Appendix for definitions and formulas | | | | |





ROUTE 1047: ST. MARY FALLS TRAILHEAD PARKING

Manual Rating

ADJACENT TO ROUTE 0010E (GOING TO THE SUN ROAD EAST) AT MP 38.88

| Inspection Date | FMSS Number | User Access | Surface Type |
|--|-------------------------|------------------------|---------------------|
| 7/27/2016 | 247582 | PUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 7,376 | 0.127 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO CURB | | NO CURB AND GUTTER | |
| Pavement Recommendation | | Condition Rating / PCR | |
| DO NOTHING EXCELLENT / 97 | | ENT / 97 | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | |

Poor (0 - 60)

Fair (61-84)

Good (85 - 94)

Excellent (95 - 100)


Not Rated

See Appendix for definitions and formulas











ROUTE 1048: LAKE MCDONALD BUILDING 1012 CARETAKERS PARKING

Manual Rating

FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.13

TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type |
|----------------------------------|-------------------------|------------------------|---------------------|
| 7/26/2016 | 232111 | NONPUBLIC | ASPHALT |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation |
| 1,201 | 0.021 | NOT APPLICABLE | NOT APPLICABLE |
| Curb Type | | Curb & Gutter Type | |
| NO CURB NO CUR | | NO CURB A | ND GUTTER |
| Pavement Recommendation | | Condition Rating / PCR | |
| PREVENTIVE MAINTENANCE GOOD / 90 | |) / 90 | |
| | | | |

Route Condition Legend – Pavement Condition Rating (PCR)

Poor (0 - 60)

Fair (61-84)

Good (85 - 94)

Excellent (95 - 100)


Not Rated

See Appendix for definitions and formulas









ROUTE 1049: LAKE MCDONALD REAR LODGE DELIVERY PARKING

Manual Rating

FROM ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) AT MP 0.23


TO PARKING

| Inspection Date | FMSS Number | User Access | Surface Type | | |
|--|-------------------------|------------------------------|---------------------|--|--|
| 7/26/2016 | 232112 | NONPUBLIC | ASPHALT | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | |
| 4,488 | 0.077 | NOT APPLICABLE | NOT APPLICABLE | | |
| Curb | Туре | Curb & Gutter Type | | | |
| NO C | CURB | NO CURB AND GUTTER | | | |
| Pavement Rec | commendation | Condition Rating / PCR | | | |
| RECONST | RUCTION | POOR / 30 | | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | | |
| See Appendix for definitions and formulas | | | | | |









ROUTE 1050: MANY GLACIER HOTEL 15 MINUTE PARKING

Manual Rating


FROM ROUTE 0210 (MANY GLACIER HOTEL ROAD)

TO ROUTE 0210 (MANY GLACIER HOTEL ROAD)

| Inspection Date | FMSS Numb | er | User Access | Surface Type | |
|------------------------|-------------------------|-------------------|---------------------------|---------------------|--|
| 7/29/2016 | 6788 | | PUBLIC | ASPHALT | |
| Area (Sq. Ft.) | Lane Miles (11' V | Vidths) Cu | rb Reveal (Inches) | Curb Recommendation | |
| 5,685 | 0.098 | | 6 | DO NOTHING | |
| Curl | Туре | | Curb & Gutter Type | | |
| CONC | CRETE | | CONCRETE | | |
| Pavement Re | Pavement Recommendation | | | Rating / PCR | |
| PREVENTIVE | MAINTENANCE | | GOOI | O / 90 | |
| | Route Condition Leg | gend – Pavement C | ondition Rating (PCR) | | |
| Poor (0 - 60) | Fair (61- 84) | Good (85 - 94) | Excellent (95 - 10 | 0) Not Rated | |


See Appendix for definitions and formulas












ROUTE 1055: LOGAN CREEK RESTROOM PARKING

Manual Rating

ADJACENT TO ROUTE 0010W (GOING TO THE SUN ROAD WEST) AT MP 20.31 $\,$

| Inspection Date | FMSS Number | User Access | Surface Type | | | |
|--|-------------------------|------------------------------|---------------------|--|--|--|
| 7/27/2016 | 247583 | PUBLIC | ASPHALT | | | |
| Area (Sq. Ft.) | Lane Miles (11' Widths) | Curb Reveal (Inches) | Curb Recommendation | | | |
| 4,709 | 0.081 | NOT APPLICABLE | NOT APPLICABLE | | | |
| Curb | Туре | Curb & Gutter Type | | | | |
| NO C | CURB | NO CURB AND GUTTER | | | | |
| Pavement Rec | commendation | Condition Rating / PCR | | | | |
| PREVENTIVE N | MAINTENANCE | GOOD / 90 | | | | |
| Route Condition Legend – Pavement Condition Rating (PCR) | | | | | | |
| Poor (0 - 60) | Fair (61- 84) Good (| (85 - 94) Excellent (95 - 10 | 0) Not Rated | | | |
| See Appendix for definitions and formulas | | | | | | |



Section 7 Road Milepost Information



Glacier National Park



Road Milepost Information

This report section contains road milepost information for all paved roads in the park that were collected with the Data Collection Vehicle (DCV). The milepost data is obtained from the DCV by using a distance measuring instrument (DMI) that is calibrated to record mileage to the nearest thousandth of a mile. Park roads that were manually rated did not have milepost data collected, and thus are not included in this report section.

For Cycle 6, the information presented in this section differs from previous RIP cycles in that it does not contain the roadside features inventories for the paved park roads. Some examples of the features previously collected are signs, culverts/drop inlets, guardrails, curbing, pullouts, etc. If the park was collected in a previous RIP cycle, then the latest features data can be obtained by referencing the following:

Where to find the latest Features Inventories for NPS Parks:

- For Small Parks (parks with less than 10 miles of paved roads):
 - o Refer to Cycle 5 data (collected 2010 2014)
 - Features were reported in Section 9 of the *Cycle 5* RIP report
 - Video of features can be viewed using the PathViewVO program and Cycle 5 data
- For Large Parks (parks with more than 10 miles of paved roads):
 - o Refer to Cycle 4 data (collected 2006 2009)
 - Features were reported in Section 9 of the *Cycle 4* RIP report
 - Video of features can be viewed using the VisiData program and Cycle 4 data
 - O Note: Features inventories were updated in Large Parks in *Cycle 5* only on a route by route basis if the route was new or modified in *Cycle 5*. If this is the case for a particular route, then features for the route can be obtained using the *PathViewVO* program and *Cycle 5* data (same as above for Small parks).

Milepost Events Verified in Cycle 6

In Cycle 6, the following events were collected and reported in Section 7 of this report:

- Intersections with roads and parking areas
- All bridges and culverts with BIP Numbers (bridge inspection program numbers)
- Mile Marker Signs
- One-Way travel directions
- Overpasses
- Tunnels
- Low Water Crossings (LWCR)
- Surface type changes
- Construction areas where no pavement condition data was obtained

GPS Mileage Matching

A consistent survey milepost and constant route length as recorded by the Data Collection Vehicle (DCV) is a challenge to maintain from one collection cycle to the next. The challenge is due to many factors such as driver characteristics, DMI calibration, tire pressure etc. After Cycle 4 (~2010), a decision was made to hold constant the length of roads so long as there was no physical change from reconstruction projects or realignments that would result in a change to the length of a road. Consequently, the "GPS Mileage Match" was implemented to specify which cycle the route length is being matched. Route mileages and GPS are matched to a previous collection whenever there is no physical change to a route alignment. The route mileage and GPS is not matched to previous cycles whenever it is determined that a road length and GPS needs to be updated. When this happens the GPS and length is updated to the cycle that displays the change, and that collection cycle is used as the matching cycle in subsequent collections of the road. Thus, the Cycle 6 GIS could be either the survey length collected in Cycle 4, Cycle 5, or Cycle 6 and therefore, may not match the survey milepost displayed in the latest Cycle 6 DCV video which is viewable in *PathView VO*.

The features inventories and road logs collected on NPS routes contain mileposts that are determined from the corresponding cycle that the GPS is matched to. Therefore, the mileposts contained in the Cycle 4 or 5 features inventories or the Cycle 6 road logs may not exactly match the survey milepost collected in the latest Cycle 6 video of the road.

Locating Mile Marker Signs

For routes that have mile marker signs along them, the milepost reported by RIP will most likely not line up exactly with the sign located in the field. This could be happening for many reasons, most likely due to either the error falling within the acceptable calibration range of the vehicle, or the level of accuracy that the mile marker signs were placed in the field.

Because mile marker signs are important features in many project plans and location descriptions, RIP is reporting locations of mile marker signs in three ways in Cycle 6:

- 1. Mileposts from Cycle 6 GIS: the official RIP milepost taken from the features inventories and the matching GPS/mileage cycle as described above. This is the milepost that should be used on project plans and when finding locations in the field
- 2. Mileposts from Cycle 6 Video: milepost shown to help locate the mile marker sign in the latest *PathView VO* video.
- 3. Latitude / Longitude: a constant way of locating a mile marker sign so long as the park has not moved the sign

The mileposts from Cycle 6 Video and GIS should be nearly the same, but on longer roads it has been observed that the Video milepost deviates more from the official GIS milepost that comes from the matching cycle.

ROUTE 0010W: GOING TO THE SUN ROAD WEST

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|---|
| 0.00 | 0.00 | INTERSECTION | N/A | PAVED ROUTE (GOING TO THE SUN ROAD (NON NPS)) |
| 0.00 | 0.00 | PARK BOUNDARY | N/A | N/A |
| 0.32 | 0.32 | INTERSECTION | R | ROUTE 0400 (HEADQUARTERS ROAD) |
| 0.92 | 0.92 | INTERSECTION | L | ROUTE 0206 (WASTEWATER TREATMENT PLANT ROAD) |
| 1.07 | 1.07 | INTERSECTION | R | ROUTE 0994 (WEST GLACIER INFO KIOSK PARKING) |
| 1.09 | 1.09 | INTERSECTION | R | ROUTE 0994 (WEST GLACIER INFO KIOSK PARKING) |
| 1.73 | 1.73 | INTERSECTION | L | ROUTE 1041 (APGAR TRANSIT CENTER PARKING) |
| 1.73 | 1.73 | INTERSECTION | L | ROUTE 0011 (CAMAS ROAD) |
| 2.57 | 2.57 | INTERSECTION | L | ROUTE 0101 (APGAR LOOP ROAD) |
| 7.81 | 7.81 | INTERSECTION | L | ROUTE 0922 (LAKESHORE FOREST PARKING) |
| 9.29 | 9.29 | INTERSECTION | R | ROUTE 0923 (LINCOLN LAKE PARKING) |
| 9.78 | 9.78 | INTERSECTION | L | ROUTE 0242 (SPRAGUE CREEK CAMPGROUND ROAD) |
| 10.16 | 10.16 | INTERSECTION | L | PAVED PULLOUT (2003 FIRE EXHIBIT) |
| 10.25 | 10.25 | INTERSECTION | R | ROUTE 0411 (SNYDER CREEK WATER TANK ROAD) |
| 10.31 | 10.31 | INTERSECTION | L | ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) |
| 10.36 | 10.36 | INTERSECTION | L | UNPAVED ROUTE (AUTHORIZED VEHICLES ONLY) |
| 10.59 | 10.61 | BRIDGE | N/A | 1430-017 (SNYDER CREEK BRIDGE #1) |
| 10.64 | 10.64 | INTERSECTION | L | ROUTE 0927 (LAKE MCDONALD GENERAL PARKING) |
| 10.66 | 10.66 | INTERSECTION | L | ROUTE 0927 (LAKE MCDONALD GENERAL PARKING) |
| 10.76 | 10.76 | INTERSECTION | L | ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) |
| 10.76 | 10.76 | INTERSECTION | R | ROUTE 0408 (LAKE MCDONALD HORSE STABLES ROAD) |
| 11.17 | 11.17 | INTERSECTION | L | UNPAVED ROUTE |
| 12.02 | 12.02 | INTERSECTION | R | PAVED PULLOUT (JOHNS LAKE TRAILHEAD) |
| 12.13 | 12.13 | INTERSECTION | L | ROUTE 0202 (NORTH LAKE MCDONALD ROAD (KELLY CAMP)) |
| 12.36 | 12.36 | INTERSECTION | L | ROUTE 0995AZ (LOWER MCDONALD FALLS HANDICAPPED PARKING) |
| 12.44 | 12.44 | INTERSECTION | L | ROUTE 0995BZ (LOWER MCDONALD FALLS PARKING) |
| 13.82 | 13.82 | INTERSECTION | R | ROUTE 0416 (MOOSE COUNTRY ACCESS ROAD) |
| 14.26 | 14.26 | INTERSECTION | L | ROUTE 0932 (MCDONALD CREEK OVERLOOK) |
| 16.13 | 16.13 | INTERSECTION | L | ROUTE 1044 (AVALANCHE PICNIC AREA PARKING) |
| | | | | |

ROUTE 0010W: GOING TO THE SUN ROAD WEST

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| \mathcal{E} | | 3 | | , and the second se |
|------------------|----------------|--------------|------|--|
| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
| 16.16 | 16.16 | INTERSECTION | L | ROUTE 0997 (AVALANCHE SHUTTLE STOP PARKING) |
| 16.19 | 16.19 | INTERSECTION | L | ROUTE 1044 (AVALANCHE PICNIC AREA PARKING) |
| 16.20 | 16.20 | INTERSECTION | R | ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) |
| 16.22 | 16.25 | BRIDGE | N/A | 1430-018 (AVALANCHE CREEK BRIDGE) |
| 16.31 | 16.31 | INTERSECTION | R | ROUTE 1046 (TRAIL OF THE CEDARS TRAILHEAD PARKING) |
| 17.34 | 17.34 | INTERSECTION | L | ROUTE 0935 (RED ROCK POINT PARKING) |
| 17.37 | 17.37 | BRIDGE | N/A | 1430-051 (RED ROCK BRIDGE) |
| 18.41 | 18.41 | INTERSECTION | R | PAVED PULLOUT (AVALANCHE INTERPRETIVE PULLOFF) |
| 18.41 | 18.41 | INTERSECTION | R | ROUTE 1002 (GTSR AVALANCHE PATHS PARKING) |
| 19.59 | 19.59 | BRIDGE | N/A | 1430-052 (NARROW BRIDGE) |
| 19.94 | 19.94 | INTERSECTION | L | ROUTE 0937 (LOGAN CREEK PIT PARKING) |
| 20.31 | 20.31 | INTERSECTION | R | ROUTE 1055 (LOGAN CREEK RESTROOM PARKING) |
| 20.69 | 20.71 | BRIDGE | N/A | 1430-026 (LOGAN CREEK BRIDGE) |
| 22.21 | 22.21 | INTERSECTION | L | ROUTE 0403 (PACKERS ROOST ROAD) |
| 23.44 | 23.48 | TUNNEL | N/A | 1430-036 (WEST TUNNEL) |
| 24.02 | 24.02 | INTERSECTION | R | ROUTE 0938A (LOOP PARKING AREA A) |
| 24.09 | 24.09 | INTERSECTION | R | ROUTE 0938B (LOOP PARKING AREA B) |
| 26.48 | 26.48 | INTERSECTION | R | PAVED PULLOUT (MCDONALD CREEK VALLEY EXHIBIT) |
| 26.79 | 26.79 | INTERSECTION | R | ROUTE 0939A (ROAD CAMP PARKING AREA A) |
| 26.80 | 26.80 | INTERSECTION | L | ROUTE 0939B (ROAD CAMP PARKING AREA B) |
| 26.89 | 26.89 | INTERSECTION | R | PAVED PULLOUT (BIRD WOMAN FALLS OVERLOOK) |
| 27.13 | 27.16 | BRIDGE | N/A | 1430-041 (HAYSTACK CREEK BRIDGE) |
| 27.65 | 27.65 | INTERSECTION | R | PAVED PULLOUT (HANGING VALLEY EXHIBIT) |
| 29.02 | 29.02 | INTERSECTION | R | ROUTE 0941AZ (BIG BEND PARKING A) |
| 29.03 | 29.03 | INTERSECTION | L | ROUTE 0941BZ (BIG BEND PARKING B) |
| 29.91 | 29.92 | BRIDGE | N/A | 1430-038 (TRIPLE ARCHES BRIDGE) |
| 31.48 | 31.48 | INTERSECTION | R | ROUTE 0942 (OBERLIN BEND PARKING) |
| 31.86 | 31.86 | INTERSECTION | N/A | ROUTE 0010E (GOING TO THE SUN ROAD EAST) |
| | | | | |

NOTE: Mileposts continue sequentially from Route 0010W (MP 0 to 31.86) to Route 0010E (MP 31.86 to 49.86).

ROUTE 0010E: GOING TO THE SUN ROAD EAST

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 31.86 | 31.86 | INTERSECTION | N/A | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 31.86 | 31.86 | INTERSECTION | R | ROUTE 0943 (LOGAN PASS PARKING) |
| 31.96 | 31.96 | INTERSECTION | R | ROUTE 0943 (LOGAN PASS PARKING) |
| 32.65 | 32.65 | INTERSECTION | R | ROUTE 0944 (LUNCH CREEK PARKING) |
| 33.00 | 33.08 | TUNNEL | N/A | 1430-037 (EAST TUNNEL) |
| 34.50 | 34.50 | INTERSECTION | R | ROUTE 0945AZ (SIYEH BEND PARKING A) |
| 34.61 | 34.61 | INTERSECTION | L | ROUTE 0945BZ (SIYEH BEND PARKING B) |
| 34.61 | 34.61 | INTERSECTION | R | ROUTE 0945CZ (SIYEH BEND PARKING C) |
| 34.71 | 34.71 | INTERSECTION | L | ROUTE 0945DZ (SIYEH BEND PARKING D) |
| 34.72 | 34.72 | INTERSECTION | R | ROUTE 0945EZ (SIYEH BEND PARKING E) |
| 34.92 | 34.92 | INTERSECTION | R | ROUTE 0945FZ (SIYEH BEND PARKING F) |
| 36.53 | 36.53 | INTERSECTION | R | ROUTE 0946A (JACKSON GLACIER OVERLOOK PARKING) |
| 36.62 | 36.62 | INTERSECTION | R | ROUTE 0946B (GUNSIGHT TRAILHEAD PARKING) |
| 37.33 | 37.33 | INTERSECTION | R | ROUTE 0983 (GRIZZLY POINT PARKING) |
| 38.88 | 38.88 | INTERSECTION | R | ROUTE 1047 (ST. MARY FALLS TRAILHEAD PARKING) |
| 39.35 | 39.39 | BRIDGE | N/A | 1430-008 (BARING CREEK BRIDGE) |
| 39.41 | 39.41 | INTERSECTION | R | ROUTE 0947 (SUNRIFT GORGE PARKING (PAVED)) |
| 39.47 | 39.47 | INTERSECTION | R | ROUTE 1014 (SUNRIFT GORGE PARKING (UNPAVED)) |
| 39.71 | 39.71 | INTERSECTION | L | ROUTE 1015 (GTSR BARING CREEK CABIN) |
| 39.97 | 39.97 | INTERSECTION | R | ROUTE 0211AZ (SUN POINT ROAD (ONE-WAY SPUR)) |
| 40.03 | 40.03 | INTERSECTION | R | ROUTE 0211Z (SUN POINT ROAD (MAIN ROAD)) |
| 40.40 | 40.40 | INTERSECTION | R | PAVED PULLOUT (DEAD HORSE CURVE OVERLOOK) |
| 42.87 | 42.87 | INTERSECTION | R | ROUTE 0949A (WILD GOOSE ISLAND PARKING A) |
| 42.95 | 42.95 | INTERSECTION | R | ROUTE 0949B (WILD GOOSE ISLAND PARKING B) |
| 43.59 | 43.59 | INTERSECTION | R | ROUTE 0950 (RISING SUN BOAT TOURS PARKING) |
| 43.72 | 43.72 | INTERSECTION | L | ROUTE 0951B (RISING SUN MOTEL AND RESTAURANT PARKING) |
| 43.74 | 43.76 | BRIDGE | N/A | 1430-003 (ROES CREEK BRIDGE) |
| 43.87 | 43.87 | INTERSECTION | R | ROUTE 0953 (RISING SUN PICNIC AREA PARKING) |
| 43.87 | 43.87 | INTERSECTION | L | ROUTE 0212F (RISING SUN LODGE ROAD F) |
| | | | | |

NOTE: Mileposts continue sequentially from Route 0010W (MP 0 to 31.86) to Route 0010E (MP 31.86 to 49.86).

ROUTE 0010E: GOING TO THE SUN ROAD EAST

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|--|
| 45.59 | 45.59 | INTERSECTION | R | PAVED PULLOUT (TRIPLE DIVIDE PEAK EXHIBIT) |
| 47.35 | 47.35 | INTERSECTION | L | ROUTE 0954 (TWO DOG FLATS PARKING) |
| 49.00 | 49.00 | INTERSECTION | L | ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) |
| 49.14 | 49.14 | INTERSECTION | R | ROUTE 0956 (ST. MARY RIVER PARKING) |
| 49.16 | 49.20 | BRIDGE | N/A | 1430-027 (ST. MARY RIVER BRIDGE) |
| 49.36 | 49.36 | INTERSECTION | L | ROUTE 0957 (ST. MARY VISITOR CENTER PARKING) |
| 49.53 | 49.53 | INTERSECTION | L | ROUTE 0957 (ST. MARY VISITOR CENTER PARKING) |
| 49.66 | 49.66 | INTERSECTION | R | ROUTE 0102 (ST. MARY RANGER STATION ROAD) |
| 49.84 | 49.86 | BRIDGE | N/A | 1430-028 (DIVIDE CREEK BRIDGE) |
| 49.86 | 49.86 | PARK BOUNDARY | N/A | N/A |
| 49.86 | 49.86 | INTERSECTION | N/A | PAVED ROUTE (GOING TO THE SUN ROAD (NON NPS)) |

ROUTE 0011: CAMAS ROAD

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 1041 (APGAR TRANSIT CENTER PARKING) |
| 0.06 | 0.06 | INTERSECTION | R | ROUTE 0246 (APGAR TRANSIT CENTER SHUTTLE LOOP) |
| 0.32 | 0.32 | INTERSECTION | R | ROUTE 0101 (APGAR LOOP ROAD) |
| 0.46 | 0.49 | BRIDGE | N/A | 1430-005 (MCDONALD CREEK BRIDGE) |
| 0.60 | 0.60 | INTERSECTION | R | ROUTE 0404 (GRIST ROAD) |
| 1.31 | 1.31 | INTERSECTION | R | ROUTE 0100A (FISH CREEK ACCESS ROAD) |
| 2.73 | 2.73 | INTERSECTION | R | PAVED PULLOUT (WILDFIRE EXHIBIT) |
| 5.62 | 5.62 | INTERSECTION | R | ROUTE 0915 (MCGEE MEADOWS PARKING) |
| 5.64 | 5.64 | INTERSECTION | R | ROUTE 0915 (MCGEE MEADOWS PARKING) |
| 5.86 | 5.86 | INTERSECTION | L | ROUTE 0916 (HUCKLEBERRY LOOKOUT TRAILHEAD PARKING) |
| 8.24 | 8.24 | INTERSECTION | R | ROUTE 0917 (CAMAS CREEK OVERLOOK PARKING) |

ROUTE 0011: CAMAS ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|---|
| 8.30 | 8.30 | INTERSECTION | R | ROUTE 0917 (CAMAS CREEK OVERLOOK PARKING) |
| 8.81 | 8.81 | INTERSECTION | L | PAVED PULLOUT (SWEET HUCKLEBERRY PIE, ICE CREAM NOT INCLUDED EXHIBIT) |
| 10.51 | 10.51 | INTERSECTION | R | ROUTE 0415 (CAMAS DUMP ROAD) |
| 10.81 | 10.81 | INTERSECTION | L | ROUTE 0918 (CAMAS CREEK ENTRANCE STATION PARKING) |
| 11.18 | 11.18 | INTERSECTION | L | ROUTE 0241 (HUCKLEBERRY MOUNTAIN ROAD) |
| 11.50 | 11.58 | BRIDGE | N/A | 1430-006 (NORTH FORK BRIDGE) |
| 11.58 | 11.58 | PARK BOUNDARY | N/A | N/A |
| 11.58 | 11.58 | INTERSECTION | N/A | PAVED ROUTE (CAMAS ROAD (NON NPS)) |

ROUTE 0012: TWO MEDICINE ROAD

| MILEPOST | MILEPOST | FEATURE | SIDE | COMMENT |
|----------|----------|---------------|------|--|
| 0.00 | 0.00 | INTERSECTION | L | STATE ROUTE 49 |
| 0.00 | 0.00 | INTERSECTION | R | STATE ROUTE 49 |
| 1.10 | 1.10 | INTERSECTION | L | UNPAVED ROUTE |
| 1.41 | 1.41 | INTERSECTION | L | UNPAVED ROUTE |
| 1.49 | 1.49 | INTERSECTION | L | UNPAVED ROUTE |
| 2.98 | 2.98 | PARK BOUNDARY | N/A | N/A |
| 4.06 | 4.06 | INTERSECTION | L | UNPAVED ROUTE |
| 5.18 | 5.18 | INTERSECTION | R | ROUTE 0964 (RUNNING EAGLE FALLS PARKING) |
| 5.22 | 5.22 | INTERSECTION | R | ROUTE 0964 (RUNNING EAGLE FALLS PARKING) |
| 5.22 | 5.25 | BRIDGE | N/A | 1430-002 (TWO MEDICINE RIVER BRIDGE) |
| 6.90 | 6.90 | INTERSECTION | L | ROUTE 0981 (TWO MEDICINE SCENIC POINT PARKING) |
| 7.16 | 7.16 | INTERSECTION | R | ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE ROAD) |
| 7.19 | 7.21 | BRIDGE | N/A | 1430-009 (APPISTOKI CREEK BRIDGE) |
| 7.22 | 7.22 | INTERSECTION | R | UNPAVED PARKING (UTILITY BUILDING) |
| 7.28 | 7.28 | INTERSECTION | R | ROUTE 0978 (TWO MEDICINE GENERAL STORE PARKING) |
| 7.28 | 7.28 | INTERSECTION | N/A | ROUTE 0965 (TWO MEDICINE STORE PARKING) |

ROUTE 0013: CHIEF MOUNTAIN INTERNATIONAL HIGHWAY

| 0.05 INTERSECTION L UNPAVED ROUTE 0.08 0.08 INTERSECTION R UNPAVED PARKING (CHIEF MOUNTAIN STORE PARK 0.11 0.11 INTERSECTION R UNPAVED ROUTE 0.20 0.20 INTERSECTION L UNPAVED ROUTE 0.34 0.34 INTERSECTION L UNPAVED ROUTE 0.48 0.48 INTERSECTION L UNPAVED ROUTE 0.49 0.49 INTERSECTION R UNPAVED ROUTE 0.71 0.71 INTERSECTION R UNPAVED ROUTE 0.87 0.87 INTERSECTION R UNPAVED ROUTE 1.71 1.71 INTERSECTION R UNPAVED ROUTE 2.09 2.09 INTERSECTION R UNPAVED ROUTE 2.25 2.25 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R UNPAVED ROUTE 4.88 4.88 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) | FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|---|------------------|----------------|--------------|------|--|
| 0.04 0.04 INTERSECTION R UNPAVED PARKING (CHIEF MOUNTAIN STORE PARK 0.05 0.05 INTERSECTION L UNPAVED ROUTE 0.08 0.08 INTERSECTION R UNPAVED PARKING (CHIEF MOUNTAIN STORE PARK 0.11 0.11 INTERSECTION R UNPAVED ROUTE 0.20 0.20 INTERSECTION L UNPAVED ROUTE 0.34 0.34 INTERSECTION L UNPAVED ROUTE 0.48 0.48 INTERSECTION L UNPAVED ROUTE 0.49 0.49 INTERSECTION R UNPAVED ROUTE 0.71 0.71 INTERSECTION R UNPAVED ROUTE 0.87 0.87 INTERSECTION R UNPAVED ROUTE 1.71 1.71 INTERSECTION R UNPAVED ROUTE 2.09 2.09 INTERSECTION R UNPAVED ROUTE 2.25 2.25 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R UNPAVED ROUTE | 0.00 | 0.00 | INTERSECTION | L | U.S. HIGHWAY 89 |
| 0.05 INTERSECTION L UNPAVED ROUTE 0.08 0.08 INTERSECTION R UNPAVED PARKING (CHIEF MOUNTAIN STORE PARK 0.11 0.11 INTERSECTION R UNPAVED ROUTE 0.20 0.20 INTERSECTION L UNPAVED ROUTE 0.23 0.23 INTERSECTION L UNPAVED ROUTE 0.48 0.48 INTERSECTION L UNPAVED ROUTE 0.49 0.49 INTERSECTION R UNPAVED ROUTE 0.71 0.71 INTERSECTION R UNPAVED ROUTE 0.87 0.87 INTERSECTION R UNPAVED ROUTE 1.71 1.71 INTERSECTION R UNPAVED ROUTE 2.09 2.09 INTERSECTION R UNPAVED ROUTE 2.25 2.25 INTERSECTION R UNPAVED ROUTE 2.95 2.95 INTERSECTION R UNPAVED ROUTE 4.88 4.88 INTERSECTION R UNPAVED ROUTE 4.89 | 0.00 | 0.00 | INTERSECTION | R | U.S. HIGHWAY 89 |
| 0.08 0.08 INTERSECTION R UNPAVED PARKING (CHIEF MOUNTAIN STORE PARK 0.11 0.11 INTERSECTION R UNPAVED ROUTE 0.20 0.20 INTERSECTION L UNPAVED ROUTE 0.23 0.23 INTERSECTION R UNPAVED ROUTE 0.48 0.34 INTERSECTION L UNPAVED ROUTE 0.49 0.48 INTERSECTION R UNPAVED ROUTE 0.71 0.71 INTERSECTION R UNPAVED ROUTE 0.87 INTERSECTION R UNPAVED ROUTE 0.93 1.71 INTERSECTION R UNPAVED ROUTE 1.71 1.71 INTERSECTION R UNPAVED ROUTE 2.09 2.09 INTERSECTION R UNPAVED ROUTE 2.25 2.25 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R UNPAVED ROUTE 4.88 4.88 INTERSECTION R UNPAVED ROUTE 4.89 | 0.04 | 0.04 | INTERSECTION | R | UNPAVED PARKING (CHIEF MOUNTAIN STORE PARKING) |
| 0.11 0.11 INTERSECTION R UNPAVED ROUTE 0.20 0.20 INTERSECTION L UNPAVED ROUTE 0.23 0.23 INTERSECTION R UNPAVED ROUTE 0.34 0.34 INTERSECTION L UNPAVED ROUTE 0.48 0.48 INTERSECTION R UNPAVED ROUTE 0.49 0.49 INTERSECTION R UNPAVED ROUTE 0.71 0.71 INTERSECTION R UNPAVED ROUTE 0.87 INTERSECTION R UNPAVED ROUTE 0.93 0.93 INTERSECTION R UNPAVED ROUTE 1.71 1.71 INTERSECTION R UNPAVED ROUTE 2.09 2.09 INTERSECTION R UNPAVED ROUTE 2.25 2.25 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R UNPAVED ROUTE 4.88 4.88 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.09 5 | 0.05 | 0.05 | INTERSECTION | L | UNPAVED ROUTE |
| 0.20 0.20 INTERSECTION L UNPAVED ROUTE 0.23 0.23 INTERSECTION R UNPAVED ROUTE 0.34 0.34 INTERSECTION L UNPAVED ROUTE 0.48 0.48 INTERSECTION L UNPAVED ROUTE 0.49 0.49 INTERSECTION R UNPAVED ROUTE 0.71 0.71 INTERSECTION R UNPAVED ROUTE 0.87 0.87 INTERSECTION R UNPAVED ROUTE 0.93 0.93 INTERSECTION R UNPAVED ROUTE 1.71 1.71 INTERSECTION R UNPAVED ROUTE 2.09 2.09 INTERSECTION R UNPAVED ROUTE 2.95 2.25 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.09 5.09 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.61 INTERSECTION R UNPAVED ROUTE 6.4 | 0.08 | 0.08 | INTERSECTION | R | UNPAVED PARKING (CHIEF MOUNTAIN STORE PARKING) |
| 0.23 0.23 INTERSECTION R UNPAVED ROUTE 0.34 0.34 INTERSECTION L UNPAVED ROUTE 0.48 0.48 INTERSECTION L UNPAVED ROUTE 0.49 0.49 INTERSECTION R UNPAVED ROUTE 0.71 0.71 INTERSECTION L UNPAVED ROUTE 0.87 0.87 INTERSECTION R UNPAVED ROUTE 0.93 0.93 INTERSECTION R UNPAVED ROUTE 1.71 1.71 INTERSECTION R UNPAVED ROUTE 2.09 2.09 INTERSECTION R UNPAVED ROUTE 2.25 2.25 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R UNPAVED ROUTE 4.88 4.88 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.09 5.09 INTERSECTION R UNPAVED ROUTE 6.43 6.43 INTERSECTION R UNPAVED ROUTE 7 | 0.11 | 0.11 | INTERSECTION | R | UNPAVED ROUTE |
| 0.34 0.34 INTERSECTION L UNPAVED ROUTE 0.48 0.48 INTERSECTION L UNPAVED ROUTE 0.49 0.49 INTERSECTION R UNPAVED ROUTE 0.71 0.71 INTERSECTION L UNPAVED ROUTE 0.87 0.87 INTERSECTION R UNPAVED ROUTE 0.93 0.93 INTERSECTION R UNPAVED ROUTE 1.71 1.71 INTERSECTION R UNPAVED ROUTE 2.09 2.09 INTERSECTION R UNPAVED ROUTE 2.95 2.95 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R UNPAVED ROUTE 4.88 4.88 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.09 5.09 INTERSECTION R UNPAVED ROUTE 6.43 6.43 INTERSECTION R UNPAVED ROUTE 7.07 7.07 INTERSECTION L UNPAVED ROUTE 7 | 0.20 | 0.20 | INTERSECTION | L | UNPAVED ROUTE |
| 0.48 0.48 INTERSECTION L UNPAVED ROUTE 0.49 0.49 INTERSECTION R UNPAVED ROUTE 0.71 0.71 INTERSECTION L UNPAVED ROUTE 0.87 0.87 INTERSECTION R UNPAVED ROUTE 0.93 0.93 INTERSECTION R UNPAVED ROUTE 1.71 1.71 INTERSECTION R UNPAVED ROUTE 2.09 2.09 INTERSECTION R UNPAVED ROUTE 2.95 2.95 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R UNPAVED ROUTE 4.88 4.88 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.09 5.09 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.61 5.61 INTERSECTION R UNPAVED ROUTE 7.07 1.07 INTERSECTION L UNPAVED ROUTE 7.28 7.28 INTERSECTION L UNPAVED ROUTE | 0.23 | 0.23 | INTERSECTION | R | UNPAVED ROUTE |
| 0.49 INTERSECTION R UNPAVED ROUTE 0.71 0.71 INTERSECTION L UNPAVED ROUTE 0.87 0.87 INTERSECTION R UNPAVED ROUTE 0.93 0.93 INTERSECTION R UNPAVED ROUTE 1.71 1.71 INTERSECTION R UNPAVED ROUTE 2.09 2.09 INTERSECTION R UNPAVED ROUTE 2.25 2.25 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R UNPAVED ROUTE 4.88 4.88 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.09 5.09 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.61 5.61 INTERSECTION R UNPAVED ROUTE 6.43 6.43 INTERSECTION R UNPAVED ROUTE 7.28 7.28 INTERSECTION L UNPAVED ROUTE 8.10 INTERSECTION R UNPAVED ROUTE 8.10 INT | 0.34 | 0.34 | INTERSECTION | L | UNPAVED ROUTE |
| 0.71 0.71 INTERSECTION L UNPAVED ROUTE 0.87 0.87 INTERSECTION R UNPAVED ROUTE 0.93 0.93 INTERSECTION R UNPAVED ROUTE 1.71 1.71 INTERSECTION R UNPAVED ROUTE 2.09 2.09 INTERSECTION R UNPAVED ROUTE 2.25 2.25 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R UNPAVED ROUTE 4.88 4.88 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.09 5.09 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.61 5.61 INTERSECTION R UNPAVED ROUTE 6.43 6.43 INTERSECTION R UNPAVED ROUTE 7.28 7.28 INTERSECTION L UNPAVED ROUTE 8.10 INTERSECTION R UNPAVED ROUTE 8.10 INTERSECTION R UNPAVED ROUTE | 0.48 | 0.48 | INTERSECTION | L | UNPAVED ROUTE |
| 0.87 0.87 INTERSECTION R UNPAVED ROUTE 0.93 0.93 INTERSECTION R UNPAVED ROUTE 1.71 1.71 INTERSECTION L UNPAVED ROUTE 2.09 2.09 INTERSECTION R UNPAVED ROUTE 2.25 2.25 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R UNPAVED ROUTE 4.88 4.88 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.09 5.09 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.61 5.61 INTERSECTION R UNPAVED ROUTE 6.43 6.43 INTERSECTION R UNPAVED ROUTE 7.07 7.07 INTERSECTION L UNPAVED ROUTE 7.71 7.71 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION R UNPAVED ROUTE | 0.49 | 0.49 | INTERSECTION | R | UNPAVED ROUTE |
| 0.93 0.93 INTERSECTION R UNPAVED ROUTE 1.71 1.71 INTERSECTION L UNPAVED ROUTE 2.09 2.09 INTERSECTION R UNPAVED ROUTE 2.25 2.25 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R UNPAVED ROUTE 4.88 4.88 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.09 5.09 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.61 5.61 INTERSECTION R UNPAVED ROUTE 6.43 6.43 INTERSECTION R UNPAVED ROUTE 7.07 7.07 INTERSECTION L UNPAVED ROUTE 7.71 7.71 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION R UNPAVED ROUTE | 0.71 | 0.71 | INTERSECTION | L | UNPAVED ROUTE |
| 1.71 1.71 INTERSECTION L UNPAVED ROUTE 2.09 2.09 INTERSECTION R UNPAVED ROUTE 2.25 2.25 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R UNPAVED ROUTE 4.88 4.88 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.09 5.09 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.61 5.61 INTERSECTION R UNPAVED ROUTE 6.43 6.43 INTERSECTION R UNPAVED ROUTE 7.07 7.07 INTERSECTION L UNPAVED ROUTE 7.71 7.71 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION R UNPAVED ROUTE | 0.87 | 0.87 | INTERSECTION | R | UNPAVED ROUTE |
| 2.09 2.09 INTERSECTION R UNPAVED ROUTE 2.25 2.25 INTERSECTION R UNPAVED ROUTE 2.95 2.95 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R UNPAVED ROUTE 4.88 4.88 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.09 5.09 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.61 5.61 INTERSECTION R UNPAVED ROUTE 6.43 6.43 INTERSECTION R UNPAVED ROUTE 7.07 7.07 INTERSECTION L UNPAVED ROUTE 7.28 7.28 INTERSECTION L UNPAVED ROUTE 7.71 7.71 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION L UNPAVED ROUTE | 0.93 | 0.93 | INTERSECTION | R | UNPAVED ROUTE |
| 2.25 2.25 INTERSECTION R UNPAVED ROUTE 2.95 2.95 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.09 5.09 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.61 5.61 INTERSECTION R UNPAVED ROUTE 6.43 6.43 INTERSECTION R UNPAVED ROUTE 7.07 7.07 INTERSECTION L UNPAVED ROUTE 7.28 7.28 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION R UNPAVED ROUTE 8.10 INTERSECTION R UNPAVED ROUTE | 1.71 | 1.71 | INTERSECTION | L | UNPAVED ROUTE |
| 2.95 2.95 INTERSECTION R UNPAVED ROUTE 3.72 3.72 INTERSECTION R UNPAVED ROUTE 4.88 4.88 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.09 5.09 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.61 5.61 INTERSECTION R UNPAVED ROUTE 6.43 6.43 INTERSECTION R UNPAVED ROUTE 7.07 7.07 INTERSECTION L UNPAVED ROUTE 7.28 7.28 INTERSECTION L UNPAVED ROUTE 7.71 7.71 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION L UNPAVED ROUTE | 2.09 | 2.09 | INTERSECTION | R | UNPAVED ROUTE |
| 3.72 INTERSECTION R UNPAVED ROUTE 4.88 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.09 5.09 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.61 INTERSECTION R UNPAVED ROUTE 6.43 6.43 INTERSECTION R UNPAVED ROUTE 7.07 7.07 INTERSECTION L UNPAVED ROUTE 7.28 7.28 INTERSECTION L UNPAVED ROUTE 7.71 7.71 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION L UNPAVED ROUTE | 2.25 | 2.25 | INTERSECTION | R | UNPAVED ROUTE |
| 4.88 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.09 5.09 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.61 5.61 INTERSECTION R UNPAVED ROUTE 6.43 6.43 INTERSECTION R UNPAVED ROUTE 7.07 7.07 INTERSECTION L UNPAVED ROUTE 7.28 7.28 INTERSECTION L UNPAVED ROUTE 7.71 7.71 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION R UNPAVED ROUTE | 2.95 | 2.95 | INTERSECTION | R | UNPAVED ROUTE |
| 5.09 5.09 INTERSECTION R ROUTE 0975 (CRUSHER HILL PARKING) 5.61 INTERSECTION R UNPAVED ROUTE 6.43 6.43 INTERSECTION R UNPAVED ROUTE 7.07 7.07 INTERSECTION L UNPAVED ROUTE 7.28 7.28 INTERSECTION L UNPAVED ROUTE 7.71 7.71 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION R UNPAVED ROUTE | 3.72 | 3.72 | INTERSECTION | R | UNPAVED ROUTE |
| 5.615.61INTERSECTIONRUNPAVED ROUTE6.436.43INTERSECTIONRUNPAVED ROUTE7.077.07INTERSECTIONLUNPAVED ROUTE7.287.28INTERSECTIONLUNPAVED ROUTE7.717.71INTERSECTIONLUNPAVED ROUTE8.108.10INTERSECTIONLUNPAVED ROUTE8.108.10INTERSECTIONRUNPAVED ROUTE | 4.88 | 4.88 | INTERSECTION | R | ROUTE 0975 (CRUSHER HILL PARKING) |
| 6.43 INTERSECTION R UNPAVED ROUTE 7.07 7.07 INTERSECTION L UNPAVED ROUTE 7.28 7.28 INTERSECTION L UNPAVED ROUTE 7.71 7.71 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION R UNPAVED ROUTE | 5.09 | 5.09 | INTERSECTION | R | ROUTE 0975 (CRUSHER HILL PARKING) |
| 7.07 7.07 INTERSECTION L UNPAVED ROUTE 7.28 7.28 INTERSECTION L UNPAVED ROUTE 7.71 7.71 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION R UNPAVED ROUTE | 5.61 | 5.61 | INTERSECTION | R | UNPAVED ROUTE |
| 7.28 7.28 INTERSECTION L UNPAVED ROUTE 7.71 7.71 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION R UNPAVED ROUTE | 6.43 | 6.43 | INTERSECTION | R | UNPAVED ROUTE |
| 7.71 7.71 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION R UNPAVED ROUTE | 7.07 | 7.07 | INTERSECTION | L | UNPAVED ROUTE |
| 8.10 8.10 INTERSECTION L UNPAVED ROUTE 8.10 8.10 INTERSECTION R UNPAVED ROUTE | 7.28 | 7.28 | INTERSECTION | L | UNPAVED ROUTE |
| 8.10 8.10 INTERSECTION R UNPAVED ROUTE | 7.71 | 7.71 | INTERSECTION | L | UNPAVED ROUTE |
| | 8.10 | 8.10 | INTERSECTION | L | UNPAVED ROUTE |
| 0.00 DOLLER SECTION D. LINDAVED BOUTE | 8.10 | 8.10 | INTERSECTION | R | UNPAVED ROUTE |
| 8.00 8.00 INTERSECTION R UNPAVED ROUTE | 8.66 | 8.66 | INTERSECTION | R | UNPAVED ROUTE |
| 9.00 9.00 INTERSECTION R UNPAVED ROUTE | 9.00 | 9.00 | INTERSECTION | R | UNPAVED ROUTE |
| 9.01 9.01 INTERSECTION L UNPAVED ROUTE | 9.01 | 9.01 | INTERSECTION | L | UNPAVED ROUTE |

ROUTE 0013: CHIEF MOUNTAIN INTERNATIONAL HIGHWAY

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|----------------|------|--|
| 9.99 | 9.99 | INTERSECTION | R | UNPAVED ROUTE |
| 10.09 | 10.09 | INTERSECTION | L | UNPAVED ROUTE |
| 10.60 | 10.60 | INTERSECTION | R | UNPAVED ROUTE |
| 10.65 | 10.65 | INTERSECTION | L | UNPAVED ROUTE |
| 10.74 | 10.74 | PARK BOUNDARY | N/A | N/A |
| 12.16 | 12.20 | BRIDGE | N/A | 1430-032 (LEE CREEK BRIDGE) |
| 14.07 | 14.07 | INTERSECTION | L | ROUTE 0976 (BELLY RIVER TRAILHEAD PARKING) |
| 14.14 | 14.14 | INTERSECTION | L | ROUTE 0976 (BELLY RIVER TRAILHEAD PARKING) |
| 14.25 | 14.25 | STATE BOUNDARY | N/A | U.S. (MONTANA) / CANADA INTERNATIONAL BORDER |

ROUTE 0014: MANY GLACIER ROAD

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|---|
| 0.00 | 0.00 | INTERSECTION | L | U.S. HIGHWAY 89 |
| 0.00 | 0.00 | INTERSECTION | R | U.S. HIGHWAY 89 |
| 0.02 | 0.02 | INTERSECTION | R | UNPAVED PARKING (SUPPER CLUB PARKING) |
| 0.06 | 0.06 | INTERSECTION | L | SPUR TO U.S. HIGHWAY 89 |
| 0.33 | 0.33 | INTERSECTION | L | UNPAVED ROUTE |
| 0.81 | 0.81 | INTERSECTION | R | UNPAVED ROUTE |
| 3.84 | 3.84 | INTERSECTION | R | UNPAVED ROUTE |
| 4.14 | 4.14 | INTERSECTION | L | UNPAVED ROUTE |
| 4.29 | 4.29 | INTERSECTION | R | UNPAVED ROUTE |
| 4.52 | 4.52 | INTERSECTION | L | UNPAVED ROUTE TO LAKE SHERBURNE DAM |
| 4.68 | 4.68 | INTERSECTION | R | UNPAVED ROUTE |
| 4.74 | 4.74 | INTERSECTION | L | UNPAVED ROUTE ON LAKE SHERBURNE DAM |
| 4.75 | 4.75 | INTERSECTION | R | UNPAVED ROUTE |
| 4.79 | 4.79 | INTERSECTION | L | ROUTE 1017 (MANY GLACIER SHERBURNE DAM PARKING (SOUTH)) |
| 4.87 | 4.87 | PARK BOUNDARY | N/A | N/A |
| | | | | |

ROUTE 0014: MANY GLACIER ROAD

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 4.88 | 4.88 | INTERSECTION | R | ROUTE 1016 (MANY GLACIER SHERBURNE DAM (NORTH) / ENTRANCE SIGN PARKING) |
| 7.11 | 7.11 | INTERSECTION | L | PAVED PULLOUT (EXHIBIT) |
| 7.49 | 7.49 | INTERSECTION | L | UNPAVED ROUTE (AUTHORIZED VEHICLES ONLY) |
| 7.52 | 7.52 | INTERSECTION | R | UNPAVED DRIVEWAY (PRIVATE) |
| 7.56 | 7.56 | INTERSECTION | R | ROUTE 0991 (MANY GLACIER ENTRANCE STATION PARKING) |
| 7.85 | 7.85 | INTERSECTION | L | UNPAVED ROUTE (SERVICE ROAD) |
| 8.89 | 8.89 | INTERSECTION | L | ROUTE 1018 (MANY GLACIER WINDY CREEK PARKING) |
| 9.04 | 9.05 | BRIDGE | N/A | 1430-031 (WINDY CREEK BRIDGE) |
| 9.80 | 9.80 | INTERSECTION | L | UNPAVED ROUTE |
| 10.40 | 10.40 | INTERSECTION | R | ROUTE 0967 (POIA LAKE PARKING) |
| 10.46 | 10.48 | BRIDGE | N/A | 1430-030 (APIKUNI CREEK BRIDGE) |
| 10.96 | 10.96 | INTERSECTION | L | ROUTE 0418 (MANY GLACIER HORSE STABLES / LAGOON ROAD) |
| 11.52 | 11.52 | INTERSECTION | L | ROUTE 0210 (MANY GLACIER HOTEL ROAD) |
| 11.83 | 11.83 | INTERSECTION | L | ROUTE 1023 (MANY GLACIER BOAT RAMP PARKING) |
| 11.88 | 11.88 | INTERSECTION | L | ROUTE 0244 (MANY GLACIER BOAT RAMP ACCESS ROAD) |
| 11.93 | 11.93 | INTERSECTION | L | ROUTE 0971 (MANY GLACIER HELIPAD PARKING) |
| 12.06 | 12.06 | INTERSECTION | L | ROUTE 0972 (MANY GLACIER PICNIC AREA / GRINNELL GLACIER TRAILHEAD PARKING) |
| 12.12 | 12.12 | INTERSECTION | L | ROUTE 0972 (MANY GLACIER PICNIC AREA / GRINNELL GLACIER TRAILHEAD PARKING) |
| 12.14 | 12.14 | INTERSECTION | L | UNPAVED DRIVEWAY |
| 12.28 | 12.28 | INTERSECTION | L | ROUTE 0990 (MANY GLACIER DUMP STATION) |
| 12.30 | 12.30 | INTERSECTION | L | ROUTE 0990 (MANY GLACIER DUMP STATION) |
| 12.35 | 12.35 | INTERSECTION | L | ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) |
| 12.44 | 12.44 | INTERSECTION | R | ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) |
| 12.44 | 12.44 | INTERSECTION | N/A | ROUTE 0974 (SWIFTCURRENT MOTOR INN PARKING) |

ROUTE 0100A: FISH CREEK ACCESS ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0011 (CAMAS ROAD) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0011 (CAMAS ROAD) |
| 1.03 | 1.03 | INTERSECTION | R | ROUTE 0911 (FISH CREEK PICNIC AREA PARKING) |
| 1.07 | 1.07 | INTERSECTION | R | ROUTE 0913 (FISH CREEK RANGER RESIDENCE PARKING) |
| 1.10 | 1.10 | INTERSECTION | L | ROUTE 0100A (FISH CREEK ACCESS ROAD) |
| 1.12 | 1.12 | INTERSECTION | R | ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD) |
| 1.13 | 1.13 | INTERSECTION | R | ROUTE 0100B (INSIDE NORTH FORK ROAD) |
| 1.15 | 1.15 | INTERSECTION | L | ROUTE 0100A (FISH CREEK ACCESS ROAD) |
| 1.15 | 1.15 | INTERSECTION | R | ROUTE 0100A (FISH CREEK ACCESS ROAD) |

ROUTE 0101: APGAR LOOP ROAD

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0011 (CAMAS ROAD) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0011 (CAMAS ROAD) |
| 0.15 | 0.15 | INTERSECTION | R | ROUTE 0903 (SCHOOL HOUSE PARKING) |
| 0.20 | 0.20 | INTERSECTION | R | ROUTE 0904A (APGAR PUBLIC PARKING A) |
| 0.22 | 0.22 | INTERSECTION | L | ROUTE 0988 (APGAR OLD VISITOR CENTER PARKING) |
| 0.23 | 0.23 | INTERSECTION | R | ROUTE 0904B (APGAR PUBLIC PARKING B) |
| 0.27 | 0.27 | INTERSECTION | L | ROUTE 0905 (APGAR VILLAGE COMPLEX PARKING) |
| 0.28 | 0.28 | INTERSECTION | R | ROUTE 0904B (APGAR PUBLIC PARKING B) |
| 0.30 | 0.30 | INTERSECTION | L | ROUTE 0905 (APGAR VILLAGE COMPLEX PARKING) |
| 0.34 | 0.34 | INTERSECTION | L | ROUTE 0906 (APGAR BOAT LAUNCH PARKING) |
| 0.35 | 0.35 | INTERSECTION | L | ROUTE 0906 (APGAR BOAT LAUNCH PARKING) |
| 0.37 | 0.37 | INTERSECTION | R | ROUTE 0907 (APGAR RANGERS / RESTROOM PARKING) |
| 0.40 | 0.40 | INTERSECTION | R | ROUTE 0907 (APGAR RANGERS / RESTROOM PARKING) |
| 0.66 | 0.66 | INTERSECTION | R | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |
| 0.76 | 0.76 | INTERSECTION | L | ROUTE 0908A (APGAR AMPHITHEATER PARKING A) |
| | | | | <u> </u> |

ROUTE 0101: APGAR LOOP ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.77 | 0.77 | INTERSECTION | R | ROUTE 0908B (APGAR AMPHITHEATER PARKING B) |
| 0.93 | 0.93 | INTERSECTION | L | ROUTE 0909 (APGAR PICNIC LOOP) |
| 1.06 | 1.06 | INTERSECTION | L | ROUTE 0909 (APGAR PICNIC LOOP) |
| 1.11 | 1.11 | INTERSECTION | L | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 1.11 | 1.11 | INTERSECTION | R | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |

ROUTE 0102: ST. MARY RANGER STATION ROAD

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0010E (GOING TO THE SUN ROAD EAST) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0010E (GOING TO THE SUN ROAD EAST) |
| 0.31 | 0.31 | INTERSECTION | R | ROUTE 0226 (ST. MARY 1913 RANGER STATION ROAD) |
| 0.41 | 0.41 | INTERSECTION | R | UNPAVED PARKING |
| 0.48 | 0.48 | INTERSECTION | L | ROUTE 0958 (ST. MARY TREATMENT PLANT PARKING) |
| 0.49 | 0.49 | INTERSECTION | L | ROUTE 0402 (ST. MARY HOUSING AREA ROAD) |
| 0.57 | 0.57 | INTERSECTION | R | ROUTE 0425 (ST. MARY RESIDENCE AND HORSE STABLES ROAD) |
| 0.62 | 0.62 | INTERSECTION | R | ROUTE 1006 (ST. MARY HOUSING AREA PARKING) |
| 0.64 | 0.64 | INTERSECTION | L | ROUTE 0959A (ST. MARY MAINTENANCE AREA PARKING A (HUDSON BAY DISTRICT OFFICE)) |
| 0.68 | 0.68 | INTERSECTION | R | ROUTE 0959B (ST. MARY MAINTENANCE AREA PARKING B (HUDSON BAY DISTRICT OFFICE)) |
| 0.72 | 0.72 | INTERSECTION | L | ROUTE 0959C (ST. MARY MAINTENANCE AREA PARKING C (HUDSON BAY DISTRICT OFFICE)) |
| 0.91 | 0.91 | INTERSECTION | N/A | ROUTE 0982 (ST. MARY BONE YARD PARKING) |

ROUTE 0200: LAKE MCDONALD LODGE LOOP ROAD

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|--|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0408 (LAKE MCDONALD HORSE STABLES ROAD) |
| 0.03 | 0.03 | INTERSECTION | R | ROUTE 0245 (STEWART MOTEL ROAD) |
| 0.05 | 0.05 | INTERSECTION | L | ROUTE 1040 (LAKE MCDONALD LEWIS DORM PARKING) |
| 0.07 | 0.07 | INTERSECTION | R | ROUTE 0930 (LAKE MCDONALD GENERAL STORE PARKING) |
| 0.08 | 0.08 | INTERSECTION | L | ROUTE 0929 (LAKE MCDONALD POST OFFICE PARKING) |
| 0.09 | 0.09 | INTERSECTION | L | ROUTE 0928B (LAKE MCDONALD RESTAURANT REAR PARKING) |
| 0.11 | 0.11 | INTERSECTION | R | ROUTE 0926B (LAKE MCDONALD CABIN LOOP AND PARKING) |
| 0.13 | 0.13 | INTERSECTION | L | ROUTE 0928A (LAKE MCDONALD RESTAURANT PARKING) |
| 0.13 | 0.13 | INTERSECTION | R | ROUTE 1048 (LAKE MCDONALD BUILDING 1012 CARETAKERS PARKING) |
| 0.18 | 0.18 | INTERSECTION | R | ROUTE 0926B (LAKE MCDONALD CABIN LOOP AND PARKING) |
| 0.19 | 0.19 | INTERSECTION | R | ROUTE 0926A (LAKE MCDONALD LODGE PARKING) |
| 0.19 | 0.19 | INTERSECTION | L | ROUTE 0927 (LAKE MCDONALD GENERAL PARKING) |
| 0.21 | 0.21 | INTERSECTION | L | ROUTE 0927 (LAKE MCDONALD GENERAL PARKING) |
| 0.21 | 0.21 | INTERSECTION | R | ROUTE 0926A (LAKE MCDONALD LODGE PARKING) |
| 0.23 | 0.23 | INTERSECTION | R | ROUTE 1049 (LAKE MCDONALD REAR LODGE DELIVERY PARKING) |
| 0.24 | 0.25 | BRIDGE | N/A | 1430-019 (SNYDER CREEK BRIDGE #2) |
| 0.26 | 0.26 | INTERSECTION | L | ROUTE 1042 (LAKE MCDONALD PARKING) |
| 0.27 | 0.27 | ONE-WAY START | N/A | N/A |
| 0.27 | 0.27 | INTERSECTION | R | ROUTE 1053 (SNYDER CREEK WEST (COBB HOUSE) PARKING) |
| 0.53 | 0.53 | ONE-WAY END | N/A | N/A |
| 0.53 | 0.53 | INTERSECTION | L | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 0.53 | 0.53 | INTERSECTION | R | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |

ROUTE 0201: AVALANCHE CAMPGROUND ENTRANCE ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 0.05 | 0.05 | INTERSECTION | R | ROUTE 0934A (AVALANCHE CAMPGROUND PARKING A / RANGER RESIDENCE PARKING) |
| 0.07 | 0.07 | INTERSECTION | L | ROUTE 0934B (AVALANCHE CAMPGROUND PARKING B) |
| 0.08 | 0.08 | INTERSECTION | R | ROUTE 0934C (AVALANCHE CAMPGROUND PARKING C) |
| 0.09 | 0.09 | INTERSECTION | L | ROUTE 0934D (AVALANCHE CAMPGROUND HANDICAPPED PARKING (TRAIL OF THE CEDARS)) |
| 0.14 | 0.14 | INTERSECTION | L | ROUTE 0201A (AVALANCHE CAMPGROUND LOOP A) |
| 0.19 | 0.19 | INTERSECTION | L | ROUTE 0201A (AVALANCHE CAMPGROUND LOOP A) |
| 0.23 | 0.23 | INTERSECTION | L | ROUTE 0201B (AVALANCHE CAMPGROUND LOOP B) |
| 0.26 | 0.26 | INTERSECTION | N/A | ROUTE 0201B (AVALANCHE CAMPGROUND LOOP B) |

ROUTE 0201A: AVALANCHE CAMPGROUND LOOP A

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|---|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | ONE-WAY START | N/A | N/A |
| 0.29 | 0.29 | INTERSECTION | R | ROUTE 0201CBZ (AVALANCHE CAMPGROUND SERVICE SPUR) |
| 0.36 | 0.36 | ONE-WAY END | N/A | N/A |
| 0.36 | 0.36 | INTERSECTION | L | ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) |
| 0.36 | 0.36 | INTERSECTION | R | ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) |

ROUTE 0201B: AVALANCHE CAMPGROUND LOOP B

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|---|
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | ONE-WAY START | N/A | N/A |
| 0.27 | 0.27 | ONE-WAY END | N/A | N/A |
| 0.27 | 0.27 | INTERSECTION | L | ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) |
| 0.27 | 0.27 | INTERSECTION | R | ROUTE 0201 (AVALANCHE CAMPGROUND ENTRANCE ROAD) |

ROUTE 0202: NORTH LAKE MCDONALD ROAD (KELLY CAMP)

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 0.11 | 0.11 | INTERSECTION | L | UNPAVED ROUTE |
| 0.15 | 0.19 | BRIDGE | N/A | 1430-001 (KELLY CAMP BRIDGE) |
| 0.25 | 0.25 | INTERSECTION | L | UNPAVED ROUTE (NON-NPS) |
| 0.34 | 0.34 | INTERSECTION | R | PAVED PULLOUT (MCDONALD CREEK TRAILHEAD) |
| 0.41 | 0.41 | INTERSECTION | N/A | ROUTE 0202 (NORTH LAKE MCDONALD ROAD (KELLY CAMP)) UNPAVED SECTION |

ROUTE 0204: FISH CREEK CAMPGROUND ENTRANCE ROAD

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0100A (FISH CREEK ACCESS ROAD) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0100A (FISH CREEK ACCESS ROAD) |
| 0.02 | 0.02 | INTERSECTION | L | ROUTE 0914A (FISH CREEK CAMPGROUND DUMP STATION) |
| 0.03 | 0.03 | INTERSECTION | R | ROUTE 0204A (FISH CREEK CAMPGROUND LOOP A) |
| 0.04 | 0.04 | INTERSECTION | L | ROUTE 0914A (FISH CREEK CAMPGROUND DUMP STATION) |
| 0.14 | 0.14 | INTERSECTION | R | ROUTE 0914B (FISH CREEK CAMPGROUND AMPHITHEATER PARKING) |

ROUTE 0204: FISH CREEK CAMPGROUND ENTRANCE ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.14 | 0.16 | BRIDGE | N/A | 1430-007 (FISH CREEK BRIDGE) |
| 0.23 | 0.23 | INTERSECTION | L | ROUTE 0204B (FISH CREEK CAMPGROUND LOOP B) |
| 0.31 | 0.31 | INTERSECTION | N/A | ROUTE 0204D (FISH CREEK CAMPGROUND LOOP D) |
| 0.31 | 0.31 | INTERSECTION | L | ROUTE 0204C (FISH CREEK CAMPGROUND LOOP C) |

ROUTE 0204A: FISH CREEK CAMPGROUND LOOP A

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|--|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | ONE-WAY START | N/A | N/A |
| 0.02 | 0.02 | INTERSECTION | L | ROUTE 0204A (FISH CREEK CAMPGROUND LOOP A) |
| 0.26 | 0.26 | ONE-WAY END | N/A | N/A |
| 0.26 | 0.26 | INTERSECTION | R | ROUTE 0204A (FISH CREEK CAMPGROUND LOOP A) |
| 0.26 | 0.26 | INTERSECTION | L | ROUTE 0204A (FISH CREEK CAMPGROUND LOOP A) |

ROUTE 0204B: FISH CREEK CAMPGROUND LOOP B

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|--|
| 0.00 | 0.00 | ONE-WAY START | N/A | N/A |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD) |
| 0.02 | 0.02 | INTERSECTION | L | ROUTE 0204B (FISH CREEK CAMPGROUND LOOP B) |
| 0.38 | 0.38 | ONE-WAY END | N/A | N/A |
| 0.38 | 0.38 | INTERSECTION | R | ROUTE 0204B (FISH CREEK CAMPGROUND LOOP B) |
| 0.38 | 0.38 | INTERSECTION | L | ROUTE 0204B (FISH CREEK CAMPGROUND LOOP B) |

ROUTE 0204C: FISH CREEK CAMPGROUND LOOP C

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|--|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0204D (FISH CREEK CAMPGROUND LOOP D) |
| 0.00 | 0.00 | ONE-WAY START | N/A | N/A |
| 0.09 | 0.09 | INTERSECTION | L | ROUTE 0204C (FISH CREEK CAMPGROUND LOOP C) |
| 0.16 | 0.16 | INTERSECTION | R | UNPAVED ROUTE |
| 0.38 | 0.38 | ONE-WAY END | N/A | N/A |
| 0.38 | 0.38 | INTERSECTION | L | ROUTE 0204C (FISH CREEK CAMPGROUND LOOP C) |
| 0.38 | 0.38 | INTERSECTION | R | ROUTE 0204C (FISH CREEK CAMPGROUND LOOP C) |

ROUTE 0204D: FISH CREEK CAMPGROUND LOOP D

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|--|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0204C (FISH CREEK CAMPGROUND LOOP C) |
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0204 (FISH CREEK CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | ONE-WAY START | N/A | N/A |
| 0.09 | 0.09 | INTERSECTION | L | ROUTE 0204D (FISH CREEK CAMPGROUND LOOP D) |
| 0.30 | 0.30 | INTERSECTION | R | ROUTE 0204D (FISH CREEK CAMPGROUND LOOP D) |
| 0.30 | 0.30 | INTERSECTION | L | ROUTE 0204D (FISH CREEK CAMPGROUND LOOP D) |
| 0.30 | 0.30 | ONE-WAY END | N/A | N/A |

ROUTE 0205: APGAR CAMPGROUND ENTRANCE ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0101 (APGAR LOOP ROAD) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0101 (APGAR LOOP ROAD) |
| 0.07 | 0.07 | INTERSECTION | L | ROUTE 0984 (APGAR CAMPGROUND DUMP STATION) |
| 0.07 | 0.07 | INTERSECTION | L | ROUTE 0205A (APGAR CAMPGROUND LOOP A) |
| 0.08 | 0.08 | INTERSECTION | L | ROUTE 0205B (APGAR CAMPGROUND LOOP B) |
| 0.12 | 0.12 | INTERSECTION | L | ROUTE 0205B (APGAR CAMPGROUND LOOP B) |
| 0.16 | 0.16 | INTERSECTION | L | ROUTE 0205C (APGAR CAMPGROUND LOOP C) |
| 0.19 | 0.19 | INTERSECTION | L | ROUTE 0205C (APGAR CAMPGROUND LOOP C) |
| 0.23 | 0.23 | INTERSECTION | L | ROUTE 0205D (APGAR CAMPGROUND LOOP D) |
| 0.27 | 0.27 | INTERSECTION | L | ROUTE 0205D (APGAR CAMPGROUND LOOP D) |
| 0.31 | 0.31 | INTERSECTION | N/A | ROUTE 0205E (APGAR CAMPGROUND LOOP E (GROUP SITES)) |
| 0.31 | 0.31 | INTERSECTION | L | ROUTE 0205E (APGAR CAMPGROUND LOOP E (GROUP SITES)) |

ROUTE 0205A: APGAR CAMPGROUND LOOP A

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|---|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0984 (APGAR CAMPGROUND DUMP STATION) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | ONE-WAY START | N/A | N/A |
| 0.02 | 0.02 | INTERSECTION | L | ROUTE 0205A (APGAR CAMPGROUND LOOP A) |
| 0.20 | 0.20 | INTERSECTION | L | ROUTE 0984 (APGAR CAMPGROUND DUMP STATION) |
| 0.60 | 0.60 | INTERSECTION | N/A | ROUTE 0205A (APGAR CAMPGROUND LOOP A) |
| 0.60 | 0.60 | ONE-WAY END | N/A | N/A |
| 0.60 | 0.60 | INTERSECTION | L | ROUTE 0205A (APGAR CAMPGROUND LOOP A) |

ROUTE 0205B: APGAR CAMPGROUND LOOP B

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| _ | FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|---|------------------|----------------|---------------|------|---|
| - | 0.00 | 0.00 | ONE-WAY START | N/A | N/A |
| | 0.00 | 0.00 | INTERSECTION | L | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |
| | 0.00 | 0.00 | INTERSECTION | R | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |
| | 0.49 | 0.49 | ONE-WAY END | N/A | N/A |
| | 0.49 | 0.49 | INTERSECTION | L | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |
| | 0.49 | 0.49 | INTERSECTION | R | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |

ROUTE 0205C: APGAR CAMPGROUND LOOP C

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|---|
| 0.00 | 0.00 | ONE-WAY START | N/A | N/A |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |
| 0.40 | 0.40 | INTERSECTION | R | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |
| 0.40 | 0.40 | ONE-WAY END | N/A | N/A |
| 0.40 | 0.40 | INTERSECTION | L | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |

ROUTE 0205D: APGAR CAMPGROUND LOOP D

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|---|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | ONE-WAY START | N/A | N/A |
| 0.27 | 0.27 | INTERSECTION | L | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |
| 0.27 | 0.27 | INTERSECTION | R | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |
| 0.27 | 0.27 | ONE-WAY END | N/A | N/A |

ROUTE 0205E: APGAR CAMPGROUND LOOP E (GROUP SITES)

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|---|
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | ONE-WAY START | N/A | N/A |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0205E (APGAR CAMPGROUND LOOP E (GROUP SITES)) |
| 0.33 | 0.33 | INTERSECTION | L | ROUTE 0205E (APGAR CAMPGROUND LOOP E (GROUP SITES)) |
| 0.33 | 0.33 | INTERSECTION | R | ROUTE 0205 (APGAR CAMPGROUND ENTRANCE ROAD) |
| 0.33 | 0.33 | ONE-WAY END | N/A | N/A |

ROUTE 0206: WASTEWATER TREATMENT PLANT ROAD

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 0.20 | 0.20 | INTERSECTION | L | UNPAVED PARKING |
| 0.37 | 0.37 | INTERSECTION | L | ROUTE 0405 (GLACIER INSTITUTE ROAD) |
| 0.42 | 0.42 | INTERSECTION | L | ROUTE 1001 (APGAR LOOKOUT PARKING) |
| 0.42 | 0.42 | INTERSECTION | L | ROUTE 0406A (APGAR LOOKOUT TRAILHEAD ROAD) |
| 0.45 | 0.45 | INTERSECTION | L | UNPAVED ROUTE (SPUR TO ROUTE 0406A (APGAR LOOKOUT TRAILHEAD ROAD)) |
| 0.45 | 0.45 | INTERSECTION | R | ROUTE 1000 (QUARTER CIRCLE HAY BARN PARKING) |
| 0.57 | 0.57 | INTERSECTION | L | ROUTE 0414 (QUARTER CIRCLE HAY BARN ROAD) |
| 0.57 | 0.57 | INTERSECTION | L | UNPAVED ROUTE |
| 0.72 | 0.72 | INTERSECTION | L | ROUTE 0998 (PAVED HORSE BARN PARKING) |
| 0.79 | 0.79 | INTERSECTION | N/A | ROUTE 0910 (HEADQUARTERS SEWAGE LAGOON PARKING) |
| | | | | , |

ROUTE 0207: TWO MEDICINE CAMPGROUND ENTRANCE ROAD

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|---|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0012 (TWO MEDICINE ROAD) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0012 (TWO MEDICINE ROAD) |
| 0.02 | 0.02 | INTERSECTION | R | ROUTE 0966A (TWO MEDICINE RANGER STATION PKG A) |
| 0.03 | 0.03 | INTERSECTION | L | ROUTE 0993 (TWO MEDICINE PICNIC AREA PARKING) |
| 0.03 | 0.03 | INTERSECTION | R | ROUTE 0966B (TWO MEDICINE RANGER STATION PKG B) |
| 0.08 | 0.08 | INTERSECTION | R | ROUTE 0980 (TWO MEDICINE EMPLOYEE HOUSING PKG) |
| 0.09 | 0.09 | INTERSECTION | L | ROUTE 0985 (TWO MEDICINE CAMPGROUND DUMP STATION) |
| 0.11 | 0.11 | INTERSECTION | L | ROUTE 0985 (TWO MEDICINE CAMPGROUND DUMP STATION) |
| 0.14 | 0.14 | INTERSECTION | L | ROUTE 0993 (TWO MEDICINE PICNIC AREA PARKING) |
| 0.16 | 0.16 | INTERSECTION | R | ROUTE 0207A (TWO MEDICINE CAMPGROUND LOOP A) |
| 0.20 | 0.20 | INTERSECTION | L | ROUTE 0992A (TWO MEDICINE CAMPGROUND PARKING A) |
| 0.32 | 0.32 | INTERSECTION | R | ROUTE 0207A (TWO MEDICINE CAMPGROUND LOOP A) |
| 0.40 | 0.40 | INTERSECTION | L | ROUTE 0992B (TWO MEDICINE CAMPGROUND PARKING B) |
| 0.43 | 0.43 | INTERSECTION | R | ROUTE 0207B (TWO MEDICINE CAMPGROUND LOOP B) |
| 0.52 | 0.52 | INTERSECTION | L | ROUTE 0992C (TWO MEDICINE CAMPGROUND PARKING C) |
| 0.58 | 0.58 | INTERSECTION | L | ROUTE 1039 (TWO MEDICINE CAMPGROUND UNPAVED TRAILHEAD PARKING) |
| 0.60 | 0.60 | INTERSECTION | R | ROUTE 0207B (TWO MEDICINE CAMPGROUND LOOP B) |
| 0.65 | 0.65 | INTERSECTION | R | ROUTE 1038 (TWO MEDICINE CAMPGROUND GROUP CAMP PARKING AREA) |
| 0.69 | 0.69 | ONE-WAY START | N/A | N/A |
| 0.69 | 0.69 | INTERSECTION | L | ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE RD) |
| 0.77 | 0.77 | ONE-WAY END | N/A | N/A |
| 0.77 | 0.77 | INTERSECTION | N/A | ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE RD) |
| 0.77 | 0.77 | INTERSECTION | L | ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE RD) |
| | | | | |

ROUTE 0207A: TWO MEDICINE CAMPGROUND LOOP A

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| | FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|---|------------------|----------------|--------------|------|--|
| • | 0.00 | 0.00 | INTERSECTION | R | ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE RD) |
| | 0.00 | 0.00 | INTERSECTION | L | ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE RD) |
| | 0.19 | 0.19 | INTERSECTION | R | ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE RD) |
| | 0.19 | 0.19 | INTERSECTION | L | ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE RD) |

ROUTE 0207B: TWO MEDICINE CAMPGROUND LOOP B

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE RD) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE RD) |
| 0.06 | 0.06 | INTERSECTION | R | ROUTE 0207C (TWO MEDICINE CAMPGROUND LOOP C) |
| 0.17 | 0.17 | INTERSECTION | R | ROUTE 0207C (TWO MEDICINE CAMPGROUND LOOP C) |
| 0.22 | 0.22 | INTERSECTION | R | ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE RD) |
| 0.22 | 0.22 | INTERSECTION | L | ROUTE 0207 (TWO MEDICINE CAMPGROUND ENTRANCE RD) |

ROUTE 0207C: TWO MEDICINE CAMPGROUND LOOP C

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0207B (TWO MEDICINE CAMPGROUND LOOP B) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0207B (TWO MEDICINE CAMPGROUND LOOP B) |
| 0.16 | 0.16 | INTERSECTION | R | ROUTE 0207B (TWO MEDICINE CAMPGROUND LOOP B) |
| 0.16 | 0.16 | INTERSECTION | L | ROUTE 0207B (TWO MEDICINE CAMPGROUND LOOP B) |

ROUTE 0208A: SWIFTCURRENT CABINS LOOP ROAD

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0014 (MANY GLACIER ROAD) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0014 (MANY GLACIER ROAD) |
| 0.01 | 0.01 | INTERSECTION | R | UNPAVED PKG (PINETOP MOTEL FRONT ROOMS 43-52) |
| 0.04 | 0.04 | INTERSECTION | L | UNPAVED PARKING (SWIFTCURRENT GENERAL STORE) |
| 0.04 | 0.04 | INTERSECTION | R | ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) |
| 0.06 | 0.06 | INTERSECTION | L | ROUTE 1022 (SWIFTCURRENT CABINS RESTAURANT LOADING AREA) |
| 0.07 | 0.07 | INTERSECTION | L | ROUTE 1022 (SWIFTCURRENT CABINS RESTAURANT LOADING AREA) |
| 0.08 | 0.08 | INTERSECTION | R | ROUTE 1043C (SWIFTCURRENT CABIN CIRCLE C AND PKG) |
| 0.10 | 0.10 | INTERSECTION | R | ROUTE 0208C (SWIFTCURRENT CABINS CROSSOVER ROAD) |
| 0.10 | 0.10 | INTERSECTION | L | ROUTE 0208B (SWIFTCURRENT CABINS CUTOFF ROAD) |
| 0.11 | 0.11 | INTERSECTION | R | ROUTE 1043D (SWIFTCURRENT CABIN CIRCLE D AND PKG) |
| 0.16 | 0.16 | INTERSECTION | R | ROUTE 0973A (SWIFTCURRENT CABINS PARKING AREA A) |
| 0.19 | 0.19 | INTERSECTION | R | ROUTE 0973A (SWIFTCURRENT CABINS PARKING AREA A) |
| 0.23 | 0.23 | INTERSECTION | R | ROUTE 0973C (SWIFTCURRENT CABINS PARKING AREA C) |
| 0.24 | 0.24 | INTERSECTION | L | ROUTE 0973B (SWIFTCURRENT CABINS PARKING AREA B, ICEBERG LAKE TRAILHEAD PARKING) |
| 0.26 | 0.26 | INTERSECTION | R | ROUTE 0973C (SWIFTCURRENT CABINS PARKING AREA C) |
| 0.30 | 0.30 | INTERSECTION | R | ROUTE 0973D (SWIFTCURRENT CABINS PARKING AREA D) |
| 0.32 | 0.32 | INTERSECTION | L | ROUTE 0423 (SWIFTCURRENT WATER TANK ROAD) |
| 0.33 | 0.33 | INTERSECTION | R | ROUTE 0973D (SWIFTCURRENT CABINS PARKING AREA D) |
| 0.36 | 0.36 | INTERSECTION | R | ROUTE 0973E (SWIFTCURRENT CABINS PARKING AREA E) |
| 0.37 | 0.37 | INTERSECTION | R | ROUTE 1043F (SWIFTCURRENT CABIN CIRCLE I AND PKG) |
| 0.39 | 0.39 | INTERSECTION | L | ROUTE 1043E (SWIFTCURRENT CABIN CIRCLE E AND PKG) |
| 0.39 | 0.39 | INTERSECTION | R | ROUTE 1020 (SWIFTCURRENT CABINS PUBLIC SHOWER AREA PARKING) |
| 0.42 | 0.42 | INTERSECTION | L | ROUTE 1021 (SWIFTCURRENT CABINS EMPLOYEE SHOWER AREA PARKING) |
| 0.43 | 0.43 | INTERSECTION | R | ROUTE 1043A (SWIFTCURRENT CABIN CIRCLE A AND PKG) |
| 0.43 | 0.43 | INTERSECTION | R | ROUTE 1043B (SWIFTCURRENT CABIN CIRCLE B AND PKG) |
| 0.44 | 0.44 | INTERSECTION | L | ROUTE 0973F (SWIFTCURRENT CABINS PARKING AREA F, PINETOP MOTEL) |
| 0.45 | 0.45 | INTERSECTION | R | ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) |
| 0.45 | 0.45 | INTERSECTION | L | ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) |

ROUTE 0208B: SWIFTCURRENT CABINS CUTOFF ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0208A (SWIFTCURRENT CABINS LOOP ROAD) |
| 0.03 | 0.03 | INTERSECTION | L | ROUTE 0974 (SWIFTCURRENT MOTOR INN PARKING) |
| 0.03 | 0.03 | INTERSECTION | R | ROUTE 0974 (SWIFTCURRENT MOTOR INN PARKING) |

ROUTE 0209A: MANY GLACIER CAMPGROUND LOOP A

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0014 (MANY GLACIER ROAD) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0014 (MANY GLACIER ROAD) |
| 0.02 | 0.02 | INTERSECTION | L | ROUTE 0401 (MANY GLACIER HOUSING AREA ROAD) |
| 0.05 | 0.05 | INTERSECTION | L | ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) |
| 0.22 | 0.22 | INTERSECTION | L | ROUTE 0209C (MANY GLACIER CAMPGROUND CUT THROUGH ROAD) |
| 0.34 | 0.34 | INTERSECTION | R | ROUTE 0209B (MANY GLACIER CAMPGROUND LOOP B) |
| 0.38 | 0.38 | INTERSECTION | L | ROUTE 0209C (MANY GLACIER CAMPGROUND CUT THROUGH ROAD) |
| 0.38 | 0.38 | INTERSECTION | R | ROUTE 0209C (MANY GLACIER CAMPGROUND CUT THROUGH ROAD) |
| 0.48 | 0.48 | INTERSECTION | R | ROUTE 0209B (MANY GLACIER CAMPGROUND LOOP B) |
| 0.58 | 0.58 | INTERSECTION | L | ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) |
| 0.58 | 0.58 | INTERSECTION | R | ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) |

ROUTE 0209B: MANY GLACIER CAMPGROUND LOOP B

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) |
| 0.09 | 0.09 | INTERSECTION | L | ROUTE 0209C (MANY GLACIER CAMPGROUND CUT THROUGH ROAD) |
| 0.22 | 0.22 | INTERSECTION | L | ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) |
| 0.22 | 0.22 | INTERSECTION | R | ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) |

ROUTE 0209C: MANY GLACIER CAMPGROUND CUT THROUGH ROAD

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) |
| 0.04 | 0.04 | INTERSECTION | R | ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) |
| 0.04 | 0.04 | INTERSECTION | L | ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) |
| 0.07 | 0.07 | INTERSECTION | L | ROUTE 0209B (MANY GLACIER CAMPGROUND LOOP B) |
| 0.07 | 0.07 | INTERSECTION | R | ROUTE 0209B (MANY GLACIER CAMPGROUND LOOP B) |

ROUTE 0210: MANY GLACIER HOTEL ROAD

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|---|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0014 (MANY GLACIER ROAD) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0014 (MANY GLACIER ROAD) |
| 0.04 | 0.04 | INTERSECTION | L | UNPAVED PARKING |
| 0.07 | 0.09 | BRIDGE | N/A | 1430-029 (SWIFTCURRENT CREEK BRIDGE) |
| 0.09 | 0.09 | INTERSECTION | R | UNPAVED ROUTE |
| 0.13 | 0.13 | INTERSECTION | L | ROUTE 0210 (MANY GLACIER HOTEL ROAD) |
| 0.13 | 0.13 | ONE-WAY START | N/A | N/A |
| 0.18 | 0.18 | INTERSECTION | L | ROUTE 0968A (MANY GLACIER EMPLOYEE DORM PARKING) |
| 0.20 | 0.20 | OVERPASS | N/A | 1430-053 (MANY GLACIER HOTEL NORTH HORSE BRIDGE) |
| 0.24 | 0.24 | INTERSECTION | R | ROUTE 1050 (MANY GLACIER HOTEL 15 MINUTE PARKING) |
| 0.28 | 0.28 | INTERSECTION | R | ROUTE 1050 (MANY GLACIER HOTEL 15 MINUTE PARKING) |
| 0.30 | 0.30 | INTERSECTION | R | ROUTE 0968B (MANY GLACIER HOTEL HANDICAP PARKING) |
| 0.31 | 0.31 | INTERSECTION | R | ROUTE 0968E (MANY GLACIER HOTEL SOUTH PARKING) |
| 0.34 | 0.34 | INTERSECTION | R | UNPAVED ROUTE |
| 0.42 | 0.42 | OVERPASS | N/A | 1430-054 (MANY GLACIER HOTEL SOUTH HORSE BRIDGE) |
| 0.45 | 0.45 | INTERSECTION | R | ROUTE 0968D (MANY GLACIER HOTEL TRAILHEAD PARKING) |
| 0.45 | 0.45 | ONE-WAY END | N/A | N/A |
| 0.48 | 0.48 | INTERSECTION | L | ROUTE 0968C (MANY GLACIER HOTEL TRAILHEAD PARALLEL PARKING) |
| 0.55 | 0.55 | INTERSECTION | L | UNPAVED PARKING |
| 0.59 | 0.59 | INTERSECTION | R | ROUTE 0968D (MANY GLACIER HOTEL TRAILHEAD PARKING) |
| 0.64 | 0.64 | INTERSECTION | L | UNPAVED PARKING |
| 0.68 | 0.68 | INTERSECTION | R | UNPAVED ROUTE |
| 0.69 | 0.69 | INTERSECTION | R | ROUTE 0210 (MANY GLACIER HOTEL ROAD) |
| 0.69 | 0.69 | INTERSECTION | L | ROUTE 0210 (MANY GLACIER HOTEL ROAD) |

ROUTE 0211AZ: SUN POINT ROAD (ONE-WAY SPUR)

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

| | FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|---|------------------|----------------|---------------|------|--|
| | 0.00 | 0.00 | ONE-WAY START | N/A | N/A |
| | 0.00 | 0.00 | INTERSECTION | L | ROUTE 0010E (GOING TO THE SUN ROAD EAST) |
| | 0.00 | 0.00 | INTERSECTION | R | ROUTE 0010E (GOING TO THE SUN ROAD EAST) |
| | 0.08 | 0.08 | INTERSECTION | N/A | ROUTE 0211Z (SUN POINT ROAD (MAIN ROAD)) |
| | 0.08 | 0.08 | INTERSECTION | L | ROUTE 0211Z (SUN POINT ROAD (MAIN ROAD)) |
| • | 0.08 | 0.08 | ONE-WAY END | N/A | N/A |

ROUTE 0211Z: SUN POINT ROAD (MAIN ROAD)

| FROM MILEPO | TO ST MILEPOST | FEATURE | SIDE | COMMENT |
|----------------|-------------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0010E (GOING TO THE SUN ROAD EAST) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0010E (GOING TO THE SUN ROAD EAST) |
| 0.03 | 0.03 | INTERSECTION | R | ROUTE 0211AZ (SUN POINT ROAD (ONE-WAY SPUR)) |
| 0.19 | 0.19 | INTERSECTION | N/A | ROUTE 0948 (SUN POINT PICNIC AREA PARKING) |

ROUTE 0212A: RISING SUN LODGE ROAD A

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0951B (RISING SUN MOTEL AND RESTAURANT PARKING) |
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0212F (RISING SUN LODGE ROAD F) |
| 0.03 | 0.03 | INTERSECTION | L | ROUTE 0951C (RISING SUN MOTEL REAR STORE PARKING) |
| 0.05 | 0.05 | INTERSECTION | L | UNPAVED ROUTE |
| 0.08 | 0.08 | INTERSECTION | R | ROUTE 0951D (RISING SUN LOWER MOTEL PARKING (SOUTH)) |
| 0.09 | 0.09 | INTERSECTION | L | ROUTE 0212B (RISING SUN LODGE ROAD B) |
| 0.11 | 0.11 | INTERSECTION | R | ROUTE 0951E (RISING SUN LOWER MOTEL PARKING (NORTH)) |
| 0.12 | 0.12 | INTERSECTION | L | UNPAVED PARKING |
| 0.14 | 0.14 | INTERSECTION | R | ROUTE 0951F (RISING SUN UPPER MOTEL PARKING (SOUTH)) |
| 0.15 | 0.15 | INTERSECTION | L | UNPAVED PARKING |
| 0.16 | 0.16 | INTERSECTION | L | UNPAVED PARKING |
| 0.17 | 0.17 | INTERSECTION | L | ROUTE 0212C (RISING SUN LODGE ROAD C) |
| 0.19 | 0.19 | INTERSECTION | N/A | ROUTE 0951G (RISING SUN UPPER MOTEL PARKING (NORTH)) |

ROUTE 0212B: RISING SUN LODGE ROAD B

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---------------------------------------|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0212A (RISING SUN LODGE ROAD A) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0212A (RISING SUN LODGE ROAD A) |
| 0.03 | 0.03 | INTERSECTION | L | UNPAVED PARKING |
| 0.06 | 0.06 | INTERSECTION | L | ROUTE 0212D (RISING SUN LODGE ROAD D) |
| 0.06 | 0.06 | INTERSECTION | N/A | ROUTE 0212D (RISING SUN LODGE ROAD D) |

ROUTE 0212C: RISING SUN LODGE ROAD C

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---------------------------------------|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0212A (RISING SUN LODGE ROAD A) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0212A (RISING SUN LODGE ROAD A) |
| 0.01 | 0.01 | INTERSECTION | R | UNPAVED PARKING |
| 0.04 | 0.04 | INTERSECTION | L | ROUTE 0212D (RISING SUN LODGE ROAD D) |
| 0.04 | 0.04 | INTERSECTION | R | ROUTE 0212D (RISING SUN LODGE ROAD D) |

ROUTE 0212D: RISING SUN LODGE ROAD D

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---------------------------------------|
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0212B (RISING SUN LODGE ROAD B) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0212D (RISING SUN LODGE ROAD D) |
| 0.01 | 0.01 | INTERSECTION | R | ROUTE 0212C (RISING SUN LODGE ROAD C) |
| 0.02 | 0.02 | INTERSECTION | L | UNPAVED PARKING |
| 0.02 | 0.02 | INTERSECTION | R | UNPAVED PARKING |
| 0.04 | 0.04 | INTERSECTION | R | ROUTE 0212E (RISING SUN LODGE ROAD E) |
| 0.04 | 0.04 | INTERSECTION | R | UNPAVED PARKING |
| 0.05 | 0.05 | INTERSECTION | R | UNPAVED PARKING |
| 0.05 | 0.05 | INTERSECTION | L | UNPAVED PARKING |
| 0.06 | 0.06 | INTERSECTION | R | UNPAVED PARKING |
| 0.07 | 0.07 | INTERSECTION | R | UNPAVED PARKING |
| 0.07 | 0.07 | INTERSECTION | L | UNPAVED PARKING |
| 0.08 | 0.08 | INTERSECTION | R | UNPAVED PARKING |
| 0.08 | 0.08 | INTERSECTION | R | ROUTE 0212B (RISING SUN LODGE ROAD B) |
| 0.08 | 0.08 | INTERSECTION | L | ROUTE 0212D (RISING SUN LODGE ROAD D) |
| | | | | |

ROUTE 0212F: RISING SUN LODGE ROAD F

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 5.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0953 (RISING SUN PICNIC AREA PARKING) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0010E (GOING TO THE SUN ROAD EAST) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0010E (GOING TO THE SUN ROAD EAST) |
| 0.03 | 0.03 | INTERSECTION | L | ROUTE 0951H (RISING SUN RESTAURANT REAR PARKING) |
| 0.04 | 0.04 | INTERSECTION | R | ROUTE 0951A (RISING SUN MOTEL BUS PARKING) |
| 0.07 | 0.07 | INTERSECTION | R | ROUTE 0951A (RISING SUN MOTEL BUS PARKING) |
| 0.07 | 0.07 | INTERSECTION | L | ROUTE 0951B (RISING SUN MOTEL AND RESTAURANT PARKING) |
| 0.09 | 0.09 | INTERSECTION | L | ROUTE 0951B (RISING SUN MOTEL AND RESTAURANT PARKING) |
| 0.10 | 0.10 | INTERSECTION | N/A | ROUTE 0212A (RISING SUN LODGE ROAD A) |

ROUTE 0213A: RISING SUN CAMPGROUND ROAD A

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|---|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0213B (RISING SUN CAMPGROUND ROAD B) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0213B (RISING SUN CAMPGROUND ROAD B) |
| 0.02 | 0.02 | INTERSECTION | L | ROUTE 0996 (RISING SUN CAMPGROUND DUMP STATION) |
| 0.04 | 0.04 | ONE-WAY START | N/A | N/A |
| 0.04 | 0.04 | INTERSECTION | L | ROUTE 0213A (RISING SUN CAMPGROUND ROAD A) |
| 0.08 | 0.08 | INTERSECTION | R | UNPAVED PARKING (RESTROOM) |
| 0.40 | 0.40 | ONE-WAY END | N/A | N/A |
| 0.40 | 0.40 | INTERSECTION | R | ROUTE 0213A (RISING SUN CAMPGROUND ROAD A) |
| 0.40 | 0.40 | INTERSECTION | L | ROUTE 0213A (RISING SUN CAMPGROUND ROAD A) |

ROUTE 0213B: RISING SUN CAMPGROUND ROAD B

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|---|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0951B (RISING SUN MOTEL AND RESTAURANT PARKING) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0951B (RISING SUN MOTEL AND RESTAURANT PARKING) |
| 0.04 | 0.04 | INTERSECTION | R | UNPAVED PARKING (RANGER RESIDENCE) |
| 0.06 | 0.06 | INTERSECTION | L | ROUTE 0996 (RISING SUN CAMPGROUND DUMP STATION) |
| 0.09 | 0.09 | INTERSECTION | L | ROUTE 0213A (RISING SUN CAMPGROUND ROAD A) |
| 0.15 | 0.15 | INTERSECTION | L | ROUTE 0213B (RISING SUN CAMPGROUND ROAD B) |
| 0.15 | 0.15 | ONE-WAY START | N/A | N/A |
| 0.25 | 0.25 | INTERSECTION | R | ROUTE 0424 (RISING SUN WATER TANK ROAD) |
| 0.40 | 0.40 | INTERSECTION | L | ROUTE 0213B (RISING SUN CAMPGROUND ROAD B) |
| 0.40 | 0.40 | ONE-WAY END | N/A | N/A |
| 0.40 | 0.40 | INTERSECTION | R | ROUTE 0213B (RISING SUN CAMPGROUND ROAD B) |

ROUTE 0214: ST. MARY CAMPGROUND ENTRANCE ROAD

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0010E (GOING TO THE SUN ROAD EAST) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0010E (GOING TO THE SUN ROAD EAST) |
| 0.07 | 0.07 | INTERSECTION | L | ROUTE 0955A (ST. MARY CAMPGROUND PARKING A / DUMP STATION) |
| 0.07 | 0.07 | INTERSECTION | L | ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) OPPOSITE LANE |
| 0.09 | 0.09 | INTERSECTION | L | ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) OPPOSITE LANE |
| 0.09 | 0.09 | INTERSECTION | L | ROUTE 0955A (ST. MARY CAMPGROUND PARKING A / DUMP STATION) |
| 0.12 | 0.12 | INTERSECTION | L | ROUTE 0214C (ST. MARY CAMPGROUND LOOP C) |
| 0.15 | 0.15 | INTERSECTION | L | ROUTE 0214B (ST. MARY CAMPGROUND LOOP B) |
| 0.17 | 0.17 | INTERSECTION | L | ROUTE 0214B (ST. MARY CAMPGROUND LOOP B) |
| 0.20 | 0.20 | INTERSECTION | L | ROUTE 0214A (ST. MARY CAMPGROUND LOOP A) |
| 0.20 | 0.20 | INTERSECTION | N/A | ROUTE 0214A (ST. MARY CAMPGROUND LOOP A) |

ROUTE 0214A: ST. MARY CAMPGROUND LOOP A

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|--|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0214A (ST. MARY CAMPGROUND LOOP A) |
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | ONE-WAY START | N/A | N/A |
| 0.07 | 0.07 | INTERSECTION | L | ROUTE 0955B (ST. MARY CAMPGROUND PARKING B) |
| 0.20 | 0.20 | INTERSECTION | L | ROUTE 0955C (ST. MARY CAMPGROUND PARKING C) |
| 0.29 | 0.29 | INTERSECTION | L | ROUTE 0955D (ST. MARY CAMPGROUND PARKING D) |
| 0.34 | 0.34 | INTERSECTION | R | ROUTE 0955E (ST. MARY CAMPGROUND PARKING E) |
| 0.40 | 0.40 | INTERSECTION | L | ROUTE 0955F (ST. MARY CAMPGROUND PARKING F) |
| 0.45 | 0.45 | ONE-WAY END | N/A | N/A |
| 0.45 | 0.45 | INTERSECTION | N/A | ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) |
| 0.45 | 0.45 | INTERSECTION | L | ROUTE 0214A (ST. MARY CAMPGROUND LOOP A) |

ROUTE 0214B: ST. MARY CAMPGROUND LOOP B

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|--|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | ONE-WAY START | N/A | N/A |
| 0.06 | 0.06 | INTERSECTION | L | ROUTE 0955G (ST. MARY CAMPGROUND PARKING G) |
| 0.14 | 0.14 | INTERSECTION | R | ROUTE 0955H (ST. MARY CAMPGROUND PARKING H) |
| 0.16 | 0.16 | INTERSECTION | L | ROUTE 0955I (ST. MARY CAMPGROUND PARKING I) |
| 0.29 | 0.29 | INTERSECTION | L | ROUTE 0955J (ST. MARY CAMPGROUND PARKING J) |
| 0.32 | 0.32 | INTERSECTION | R | ROUTE 0955K (ST. MARY CAMPGROUND PARKING K) |
| 0.40 | 0.40 | INTERSECTION | L | ROUTE 0955L (ST. MARY CAMPGROUND PARKING L) |
| 0.48 | 0.48 | ONE-WAY END | N/A | N/A |
| 0.48 | 0.48 | INTERSECTION | R | ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) |
| 0.48 | 0.48 | INTERSECTION | L | ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) |
| _ | | | | |

ROUTE 0214C: ST. MARY CAMPGROUND LOOP C

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|--|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0214 (ST. MARY CAMPGROUND ENTRANCE ROAD) |
| 0.12 | 0.12 | INTERSECTION | L | ROUTE 0214C (ST. MARY CAMPGROUND LOOP C) |
| 0.12 | 0.12 | ONE-WAY START | N/A | N/A |
| 0.13 | 0.13 | INTERSECTION | L | ROUTE 0214C (ST. MARY CAMPGROUND LOOP C) SPUR |
| 0.35 | 0.35 | INTERSECTION | L | ROUTE 0955M (ST. MARY CAMPGROUND PARKING M) |
| 0.53 | 0.53 | INTERSECTION | L | ROUTE 0955N (ST. MARY CAMPGROUND PARKING N) |
| 0.59 | 0.59 | INTERSECTION | L | ROUTE 0214C (ST. MARY CAMPGROUND LOOP C) SPUR |
| 0.60 | 0.60 | INTERSECTION | N/A | ROUTE 0214C (ST. MARY CAMPGROUND LOOP C) |
| 0.60 | 0.60 | INTERSECTION | L | ROUTE 0214C (ST. MARY CAMPGROUND LOOP C) |
| 0.60 | 0.60 | ONE-WAY END | N/A | N/A |

ROUTE 0240: WALTON RANGER STATION ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--------------------------------|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 5000 (U.S. HIGHWAY 2) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 5000 (U.S. HIGHWAY 2) |
| 0.07 | 0.07 | INTERSECTION | N/A | UNPAVE ROUTE (END OF PAVEMENT) |

ROUTE 0241: HUCKLEBERRY MOUNTAIN ROAD

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0011 (CAMAS ROAD) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0011 (CAMAS ROAD) |
| 0.15 | 0.15 | INTERSECTION | L | ROUTE 0241 (HUCKLEBERRY MOUNTAIN ROAD) |
| 0.17 | 0.17 | INTERSECTION | L | ROUTE 0241 (HUCKLEBERRY MOUNTAIN ROAD) SPUR |
| 0.22 | 0.22 | INTERSECTION | L | ROUTE 0919 (HUCKLEBERRY MOUNTAIN TRAILHEAD PKG) |
| 0.23 | 0.23 | INTERSECTION | L | ROUTE 0241 (HUCKLEBERRY MOUNTAIN ROAD) SPUR |
| 0.24 | 0.24 | INTERSECTION | L | ROUTE 0241 (HUCKLEBERRY MOUNTAIN ROAD) |
| 0.24 | 0.24 | INTERSECTION | N/A | ROUTE 0241 (HUCKLEBERRY MOUNTAIN ROAD) |

ROUTE 0242: SPRAGUE CREEK CAMPGROUND ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|--|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 0.02 | 0.02 | INTERSECTION | L | ROUTE 0242 (SPRAGUE CREEK CAMPGROUND ROAD) |
| 0.02 | 0.02 | INTERSECTION | R | ROUTE 1045 (SPRAGUE CREEK PICNIC AREA PARKING) |
| 0.02 | 0.02 | ONE-WAY START | N/A | N/A |
| 0.19 | 0.19 | ONE-WAY END | N/A | N/A |
| 0.19 | 0.19 | INTERSECTION | L | ROUTE 0242 (SPRAGUE CREEK CAMPGROUND ROAD) |
| 0.19 | 0.19 | INTERSECTION | R | ROUTE 0242 (SPRAGUE CREEK CAMPGROUND ROAD) |

ROUTE 0245: STEWART MOTEL ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0200 (LAKE MCDONALD LODGE LOOP ROAD) |
| 0.02 | 0.02 | INTERSECTION | R | UNPAVED ROUTE |
| 0.04 | 0.04 | INTERSECTION | N/A | ROUTE 0926C (STEWART MOTEL PARKING) |

ROUTE 0246: APGAR TRANSIT CENTER SHUTTLE LOOP

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|--|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0011 (CAMAS ROAD) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0011 (CAMAS ROAD) |
| 0.04 | 0.04 | ONE-WAY START | N/A | N/A |
| 0.04 | 0.04 | INTERSECTION | L | ROUTE 0246 (APGAR TRANSIT CENTER SHUTTLE LOOP) |
| 0.13 | 0.13 | INTERSECTION | L | ROUTE 0246 (APGAR TRANSIT CENTER SHUTTLE LOOP) |
| 0.13 | 0.13 | INTERSECTION | R | ROUTE 0246 (APGAR TRANSIT CENTER SHUTTLE LOOP) |
| 0.13 | 0.13 | ONE-WAY END | N/A | N/A |

ROUTE 0400: HEADQUARTERS ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0010W (GOING TO THE SUN ROAD WEST) |
| 0.06 | 0.06 | INTERSECTION | R | ROUTE 0900 (HEADQUARTERS VISITOR PARKING) |
| 0.12 | 0.12 | INTERSECTION | R | ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A) |
| 0.24 | 0.24 | INTERSECTION | L | UNPAVED PARKING |
| 0.28 | 0.28 | INTERSECTION | N/A | ROUTE 0409A (GRINNELL DRIVE) |
| 0.28 | 0.28 | INTERSECTION | R | ROUTE 0409E (MATHER DRIVE) |
| 0.28 | 0.28 | INTERSECTION | L | ROUTE 0407 (CAMEL'S HUMP ROAD) |

ROUTE 0401: MANY GLACIER HOUSING AREA ROAD

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0209A (MANY GLACIER CAMPGROUND LOOP A) |
| 0.02 | 0.02 | INTERSECTION | L | ROUTE 0989B (MANY GLACIER PARKING B) |
| 0.03 | 0.03 | INTERSECTION | R | ROUTE 0401 (MANY GLACIER HOUSING AREA ROAD) |
| 0.04 | 0.04 | INTERSECTION | R | ROUTE 0989A (MANY GLACIER PARKING A / RANGER STATION) |
| 0.04 | 0.04 | INTERSECTION | L | ROUTE 0989B (MANY GLACIER PARKING B) |
| 0.22 | 0.22 | INTERSECTION | L | ROUTE 0989C (MANY GLACIER PARKING C / RESIDENCES) |
| 0.23 | 0.23 | INTERSECTION | L | ROUTE 0989C (MANY GLACIER PARKING C / RESIDENCES) |
| 0.25 | 0.25 | INTERSECTION | R | ROUTE 0401 (MANY GLACIER HOUSING AREA ROAD) |
| 0.25 | 0.25 | INTERSECTION | L | ROUTE 0401 (MANY GLACIER HOUSING AREA ROAD) |

ROUTE 0402: ST. MARY HOUSING AREA ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0102 (ST. MARY RANGER STATION ROAD) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0102 (ST. MARY RANGER STATION ROAD) |
| 0.11 | 0.11 | INTERSECTION | L | ROUTE 0426 (ST. MARY RESIDENCE / DIVIDE CREEK ACCESS) |
| 0.17 | 0.17 | INTERSECTION | R | ROUTE 1008 (ST. MARY RESIDENCE AREA DORM PARKING) |
| 0.25 | 0.25 | INTERSECTION | R | ROUTE 0960A (ST. MARY RESIDENCE AREA PARKING A) |
| 0.26 | 0.26 | INTERSECTION | L | ROUTE 0960B (ST. MARY RESIDENCE AREA PARKING B) |
| 0.29 | 0.29 | INTERSECTION | L | ROUTE 0960C (ST. MARY RESIDENCE AREA PARKING C) |
| 0.29 | 0.29 | INTERSECTION | L | ROUTE 0402 (ST. MARY HOUSING AREA ROAD) |
| 0.36 | 0.36 | INTERSECTION | L | ROUTE 0402 (ST. MARY HOUSING AREA ROAD) |
| 0.36 | 0.36 | INTERSECTION | N/A | ROUTE 0402 (ST. MARY HOUSING AREA ROAD) |

ROUTE 0404: GRIST ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0011 (CAMAS ROAD) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0011 (CAMAS ROAD) |
| 0.14 | 0.14 | INTERSECTION | R | UNPAVED ROUTE |
| 0.35 | 0.35 | INTERSECTION | R | UNPAVED ROUTE |
| 0.37 | 0.37 | INTERSECTION | N/A | ROUTE 0404 (GRIST ROAD) UNPAVED SECTION |
| 0.37 | 0.37 | INTERSECTION | R | UNPAVED ROUTE |

ROUTE 0407: CAMEL'S HUMP ROAD

| FROM | TO | | | |
|----------|----------|--------------|------|--------------------------------|
| MILEPOST | MILEPOST | FEATURE | SIDE | COMMENT |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0400 (HEADQUARTERS ROAD) |
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0409E (MATHER DRIVE) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0409A (GRINNELL DRIVE) |
| 0.13 | 0.13 | INTERSECTION | L | UNPAVED ROUTE |
| 0.13 | 0.13 | INTERSECTION | N/A | END AT BIKE PATH |

ROUTE 0409A: GRINNELL DRIVE

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--------------------------------|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0409E (MATHER DRIVE) |
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0400 (HEADQUARTERS ROAD) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0407 (CAMEL'S HUMP ROAD) |
| 0.06 | 0.06 | INTERSECTION | L | ROUTE 0409B (LOGAN LANE) |
| 0.17 | 0.17 | INTERSECTION | R | ROUTE 0409B (LOGAN LANE) |
| 0.17 | 0.17 | INTERSECTION | L | ROUTE 0409B (LOGAN LANE) |

ROUTE 0409B: LOGAN LANE

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|------------------------------------|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0409A (GRINNELL DRIVE) |
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0409A (GRINNELL DRIVE) |
| 0.06 | 0.06 | INTERSECTION | L | ROUTE 0986A (LOGAN LANE PARKING A) |
| 0.10 | 0.10 | INTERSECTION | L | ROUTE 0986B (LOGAN LANE PARKING B) |
| 0.23 | 0.23 | INTERSECTION | R | ROUTE 0409A (GRINNELL DRIVE) |
| 0.31 | 0.31 | INTERSECTION | R | ROUTE 0409C (SPERRY DRIVE) |
| 0.35 | 0.35 | INTERSECTION | R | ROUTE 0409D (ALBRIGHT CIRCLE) |
| 0.35 | 0.35 | INTERSECTION | L | ROUTE 0409D (ALBRIGHT CIRCLE) |

ROUTE 0409C: SPERRY DRIVE

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|----------------------------|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0409E (MATHER DRIVE) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0409E (MATHER DRIVE) |
| 0.15 | 0.15 | INTERSECTION | L | ROUTE 0409B (LOGAN LANE) |
| 0.15 | 0.15 | INTERSECTION | R | ROUTE 0409B (LOGAN LANE) |

ROUTE 0409D: ALBRIGHT CIRCLE

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|---------------|------|--|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0409E (MATHER DRIVE) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0409E (MATHER DRIVE) |
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0987 (HEADQUARTERS COMMUNITY BUILDING PARKING) |
| 0.03 | 0.03 | ONE-WAY START | N/A | N/A |
| 0.03 | 0.03 | INTERSECTION | R | ROUTE 0409D (ALBRIGHT CIRCLE) |
| 0.11 | 0.11 | INTERSECTION | L | ROUTE 0409B (LOGAN LANE) |
| 0.13 | 0.13 | INTERSECTION | L | UNPAVED PARKING |
| 0.18 | 0.18 | INTERSECTION | L | ROUTE 0412 (HEADQUARTERS WATER TANK ROAD) |
| 0.33 | 0.33 | INTERSECTION | R | ROUTE 0409D (ALBRIGHT CIRCLE) |
| 0.33 | 0.33 | INTERSECTION | L | ROUTE 0409D (ALBRIGHT CIRCLE) |
| 0.33 | 0.33 | ONE-WAY END | N/A | N/A |

ROUTE 0409E: MATHER DRIVE

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|--|
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0407 (CAMEL'S HUMP ROAD) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0409A (GRINNELL DRIVE) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0400 (HEADQUARTERS ROAD) |
| 0.08 | 0.08 | INTERSECTION | L | ROUTE 0409C (SPERRY DRIVE) |
| 0.15 | 0.15 | INTERSECTION | L | ROUTE 0409D (ALBRIGHT CIRCLE) |
| 0.15 | 0.15 | INTERSECTION | R | ROUTE 0987 (HEADQUARTERS COMMUNITY BUILDING PARKING) |
| 0.21 | 0.21 | INTERSECTION | R | ROUTE 0409F (RUHLE DRIVE) |
| 0.25 | 0.25 | INTERSECTION | L | UNPAVED PARKING (RIVER TRAIL) |
| 0.32 | 0.32 | INTERSECTION | L | ROUTE 0409F (RUHLE DRIVE) |
| 0.32 | 0.32 | INTERSECTION | R | ROUTE 0409F (RUHLE DRIVE) |

ROUTE 0409F: RUHLE DRIVE

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0409E (MATHER DRIVE) |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0409E (MATHER DRIVE) |
| 0.05 | 0.05 | INTERSECTION | R | ROUTE 0901D (HEADQUARTERS MAINTENANCE AREA PARKING (SCOYEN CIRCLE)) |
| 0.06 | 0.06 | INTERSECTION | L | ROUTE 0409E (MATHER DRIVE) |
| 0.15 | 0.15 | INTERSECTION | R | ROUTE 0409F (RUHLE DRIVE) |
| 0.17 | 0.17 | INTERSECTION | R | ROUTE 0409F (RUHLE DRIVE) |
| 0.17 | 0.17 | INTERSECTION | N/A | ROUTE 0409F (RUHLE DRIVE) |

ROUTE 0410A: HEADQUARTERS ADMINISTRATIVE ROAD A

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0400 (HEADQUARTERS ROAD) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0400 (HEADQUARTERS ROAD) |
| 0.04 | 0.04 | INTERSECTION | R | ROUTE 0901A (HEADQUARTERS EMPLOYEE PARKING) |
| 0.05 | 0.05 | INTERSECTION | L | UNPAVED ROUTE |
| 0.07 | 0.07 | INTERSECTION | L | ROUTE 1052 (HEADQUARTERS AND SHUTTLE BUS PARKING) |
| 0.08 | 0.08 | INTERSECTION | L | ROUTE 0410B (HEADQUARTERS ADMINISTRATIVE ROAD B (VINT BOULEVARD)) |
| 0.10 | 0.10 | INTERSECTION | R | UNPAVED DRIVEWAY |
| 0.13 | 0.13 | INTERSECTION | R | ROUTE 0901A (HEADQUARTERS EMPLOYEE PARKING) |
| 0.14 | 0.14 | INTERSECTION | L | ROUTE 0901F (HEADQUARTERS FUELING AREA) |
| 0.20 | 0.20 | INTERSECTION | L | ROUTE 0901C (HEADQUARTERS MAINTENANCE BUILDING PARKING) |
| 0.21 | 0.21 | INTERSECTION | R | ROUTE 0901B (HEADQUARTERS LIBRARY PARKING) |
| 0.21 | 0.21 | INTERSECTION | L | UNPAVED PARKING |
| 0.21 | 0.21 | INTERSECTION | R | UNPAVED PARKING |
| 0.22 | 0.22 | INTERSECTION | N/A | ROUTE 0901D (HEADQUARTERS MAINTENANCE AREA PARKING (SCOYEN CIRCLE)) |

ROUTE 0410B: HEADQUARTERS ADMINISTRATIVE ROAD B (VINT BOULEVARD)

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 4.

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 0.00 | 0.00 | INTERSECTION | N/A | ROUTE 0901D (HEADQUARTERS MAINTENANCE AREA PARKING (SCOYEN CIRCLE)) |
| 0.02 | 0.02 | INTERSECTION | L | UNPAVED PARKING |
| 0.03 | 0.03 | INTERSECTION | R | ROUTE 0901E (HEADQUARTERS ELECTRONIC OFFICE PARKING) |
| 0.06 | 0.06 | INTERSECTION | R | UNPAVED PARKING (COMMUNITY BUILDING) |
| 0.08 | 0.08 | INTERSECTION | L | ROUTE 0901F (HEADQUARTERS FUELING AREA) |
| 0.10 | 0.10 | INTERSECTION | R | UNPAVED ROUTE TO NATIVE PLANT NURSERY |
| 0.13 | 0.13 | INTERSECTION | R | ROUTE 1052 (HEADQUARTERS AND SHUTTLE BUS PARKING) |
| 0.14 | 0.14 | INTERSECTION | N/A | ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A) |
| 0.14 | 0.14 | INTERSECTION | L | ROUTE 0410A (HEADQUARTERS ADMINISTRATIVE ROAD A) |

ROUTE 0425: ST. MARY RESIDENCE AND HORSE STABLES ROAD

Road logs are verified in Cycle 6 and mileposts for this route are matched to GPS collected in Cycle 6.

| FROM | TO | | CIDE | COMMENT |
|----------|----------|--------------|------|--|
| MILEPOST | MILEPOST | FEATURE | SIDE | COMMENT |
| 0.00 | 0.00 | INTERSECTION | R | ROUTE 0102 (ST. MARY RANGER STATION ROAD) |
| 0.00 | 0.00 | INTERSECTION | L | ROUTE 0102 (ST. MARY RANGER STATION ROAD) |
| 0.01 | 0.01 | INTERSECTION | L | ROUTE 1006 (ST. MARY HOUSING AREA PARKING) |
| 0.05 | 0.05 | INTERSECTION | N/A | ROUTE 1036 (ST. MARY CORRALS PARKING) |

ROUTE 0426: ST. MARY RESIDENCE / DIVIDE CREEK ACCESS

| FROM MILEPOST | TO MILEPOST | FEATURE | SIDE | COMMENT |
|------------------|----------------|--------------|------|---|
| 0.00 | 0.00 | INTERSECTION | R | PAVED ROUTE (U.S. HIGHWAY 89 / NON-NPS) |
| 0.00 | 0.00 | INTERSECTION | L | PAVED ROUTE (U.S. HIGHWAY 89 / NON-NPS) |
| 0.01 | 0.01 | INTERSECTION | L | UNPAVED ROUTE |
| 0.03 | 0.05 | BRIDGE | N/A | 1430-045 (UPPER DIVIDE CREEK BRIDGE) |
| 0.08 | 0.08 | INTERSECTION | R | ROUTE 0402 (ST. MARY HOUSING AREA ROAD) |

Section 8 Appendix



Glacier National Park



Improvements to the RIP Index Equations and Determination of PCR

In 2005, the Federal Highway Administration (FHWA) began implementing the use of a Pavement Management System (PMS) to assist the National Park Service (NPS) in prioritizing Pavement Maintenance and Rehabilitation activities. The PMS used by FHWA is the Highway Pavement Management Application (HPMA) which has the ability to store inventory and condition data from the Road Inventory Program (RIP) and forecast future performance using prediction models. Outputs include performance and condition reports at the National, Region, Park, or Route level. A regional prioritized list and optimization have been produced for most regions and the Federal Highway Deferred Maintenance is calculated via the HPMA as well.

In an effort to improve the accuracy of treatment recommendations and pavement condition descriptions the distresses and indexes that comprise the Pavement Condition Rating (PCR), an extensive study was completed throughout 2010 that has resulted in changes to the RIP condition reporting method and specifically, the calculation of PCR. It was determined that a better representation of PCR could be achieved by modifying the relative impact certain distresses would have on the overall rating.

Through the use of HPMA data, it was noted that false failure indicators existed with the existing PCR model, and that it would be necessary to reduce their impact. The distresses affected in this way were Rutting and Roughness. Conversely, experience showed that roadways with extensive cracking present were often shown to have a high PCR. Therefore, the crack index models were adjusted to be more sensitive to changes in crack severity or quantity. It was also determined that these issues were not due to a problem with data acquisition (i.e. the RIP "van"), but with the way the collected data was processed. The final change was to provide guidance on when to use the Roughness Condition Index (RCI) in the PCR calculation. Roughness data is of little value to determining overall condition on routes that, due to their length or geometrics, have lower vehicle operating speeds. Therefore, in Cycle 5, only routes that have lengths of one half mile or greater and posted speed limits of 25 mph or greater will have RCI reported and included in the PCR calculations.

Additionally, methodologies were updated in 2013 for Manually Rated Routes (paved routes that the collection vehicle is unable to drive) as well as Parking Areas to provide more accurate condition data to the HPMA. These updated methodologies allow for the efficient assessment of pavement conditions using a visual inspection method to denote specific distresses. These distresses are indicative of current conditions, the causes for current and future deterioration, and identify the level of targeted repair and rehabilitation practices required.

The changes that were implemented were endorsed by management at both the FHWA and NPS. In order to show the effectiveness of these changes, several sites were ground truth tested in early 2014 to ensure that an improvement was achieved between the relationship of PCR and the actual Maintenance and Rehabilitation needs that were represented. The changes will allow greater use of RIP and HPMA data for not simply condition data reporting, but also as a reliable tool for project identification and selection.

Description of the Rating System

The Federal Highway Administration, National Park Service Road Inventory Program (NPS-RIP), collects roadway condition data on paved surfaces (asphalt, concrete, brick, and cobblestone) on roads, parkways, and parking areas in national parks nationwide. The road surface condition data is collected using an automated Data Collection Vehicle (DCV) and manually using Manually Rated Route (MRR) procedures. Roads having brick or cobblestone surfacing are not normally surveyed with the DCV, but are manually rated for condition rating.

The FHWA RIP is implemented based on the premise that an accurate pavement surface condition assessment can be accomplished using automated crack detection technology as applied to digital images. Various methods of pavement condition assessment have been developed over the years with varying degrees of accuracy and acceptance. The use of digital photography to record pavement images and subsequent crack detection and classification has undergone continuous improvements over the past decade. Digital cameras with increasingly superior resolution and high definition have become more affordable, and the proprietary programming code and algorithms have been improved in crack detection software.

With the use of quality digital photography and automated crack detection software, FHWA RIP is tasked with executing a pavement condition assessment on a network of roughly 5,700 miles of National Park Service roads and parkways. Because a subset of roads will be collected multiple times this cycle, the total collection length will be around 13,000 miles. Foremost in setting up the basis of pavement distress identification is employing the distress identification protocols used by FHWA. There is no single distress identification system that is universal among entities conducting a program of distress identification. For the purpose of the NPS RIP, FHWA employs distress identification protocols that are specific to this program.

FHWA has referenced the "Distress Identification Manual for the Long-Term Pavement Performance Program", Publication No. FHWA-RD 03-031, June 2003, as the point-of- reference for distress types on NPS pavement. In truth, the FHWA RIP distress types are similar to those described in the LTPP manual with some modifications. This document, "Distress Identification Manual for the NPS Road Inventory Program, Cycle 6, 2014-2020" was developed using the "Distress Identification Manual for the Long-Term Pavement Performance Program" as a guideline. Definitions of severity levels based on crack width contained in this document adhere to the LTPP Distress ID Manual. Modifications have been made to the definition of Alligator and Longitudinal Cracking and determination of Alligator Cracking severity. This manual also addresses Rutting and Roughness and its application to RIP.

Cycle 6 has launched in the spring of 2014 and will again comprise all parks, large and small, that are served by paved roads and/or parking areas. For Cycle 6, roughly 333 large and small parks will have all paved routes and parking areas collected at least once in the cycle, some will have multiple collections depending on the size of the park and the functional class of the route.

This "Distress Identification Manual for the NPS Road Inventory Program, Cycle 6, 2014-2020" will be used as a reference resource in crack detection and classification, determination of distress severity and extent, and in the calculation of distress index values for the FHWA RIP Cycle 6.

Explanation of the Condition Descriptions

In addition to the RIP Index changes that were implemented in Cycle 5, we will also aim to provide greater assistance in translating good/fair/poor categories into pavement needs categories. The PCR can be used to indicate the place in the Pavement Life Cycle and the types of treatments that should be considered now and into the future.

- Excellent/New: PCR of 95-100. Pavements in this range will require only spot repairs
- Good: PCR of 85-94. Pavements in this range will likely be candidates for preventive maintenance. Examples include Chip and Slurry Seals, Micro Surfacing and Thin Overlays.
- Fair: PCR of 61-84. Pavements in this range will likely be candidates of Light Rehabilitation (L3R). Examples include single-lift overlays up to 2.5 inches in total thickness, milling and overlays.
- Poor: PCR of 60 or below. Pavements in this range will likely be candidates of Heavy Rehabilitation or Reconstruction (H3R or 4R). Examples include Pulverization, Multiple Lift Overlays, and Reconstruction.

At this time, specific maintenance and rehabilitation activities should be evaluated and recommended at the project level. Site-specific conditions that influence treatment type should be determined based on performing a subsurface investigation and/or pavement condition survey, and not be based solely on RIP data. Additionally, RIP produces a snapshot of conditions the year in which the data was collected. For further information or to obtain additional PMS data from our (HPMA) please contact the Eastern Federal Lands pavement team.

Condition Categories and Treatments



Pavement Age

Description of Pavement Treatment Types

- 1. **Preventive Maintenance** is a planned strategy of cost-effective treatments to an existing roadway system and its appurtenances that preserves the system, retards future deterioration, and maintains or improves the functional condition of the system (without significantly increasing the structural capacity). Preventive maintenance is typically applied to pavements in good condition having significant remaining service life. As a major component of pavement preservation, preventive maintenance is a strategy of extending the service life by applying cost-effective treatments to the surface or near-surface of structurally sound pavements. Examples of preventive treatments include asphalt crack sealing, chip sealing, slurry or micro-surfacing, thin and ultrathin hot-mix asphalt overlay, concrete joint sealing, diamond grinding, dowel-bar retrofit, and isolated, partial and/or full-depth concrete repairs to restore functionality of individual slabs.
- 2. Pavement Rehabilitation consists of structural enhancements that extend the service life of an existing pavement and/or improve its load carrying capacity. Rehabilitation techniques include restoration treatments and structural overlays. Rehabilitation projects extend the life of existing pavement structures either by restoring existing structural capacity through the elimination of age-related, environmental cracking of embrittled pavement surface or by increasing pavement thickness to strengthen existing pavement sections to accommodate existing or projected traffic loading conditions. Two sub-categories result from these distinctions, which are directly related to the restoration or increase of structural capacity.
 - **Light Rehabilitation** (**L3R**) Examples include single-lift overlays up to 2.5 inches in total thickness and milling and overlays for flexible pavements
 - **Heavy Rehabilitation (H3R)** Requires rehabilitation with grade improvement. H3R stands for resurfacing, restoration, and rehabilitation projects. H3R projects typically involve multi-depth (overlays greater than 2.5 inches) pavement improvement work (short of full-depth replacement) and targeted safety improvements. H3R projects generally involve retention of the existing three-dimensional alignment.
- 3. **Reconstruction** (4R) is defined as the replacement of the entire existing pavement structure by the placement of the equivalent or increased pavement structure. Reconstruction usually requires the complete removal and replacement of the existing pavement structure. Reconstruction may utilize either new or recycled materials incorporated into the materials used for the reconstruction of the complete pavement section. Reconstruction is required when a pavement has either failed or has become functionally obsolete.

Appendix A

Methodology for Determining Condition Ratings with the Data Collection Vehicle (DCV)

Surface Distresses Identified by the Data Collection Vehicle

<u>Surface Condition Rating – SCR</u>

Surface distresses are measured in the primary lane only. In the classification and measurement of all paved surface condition data, results will be reported in the database in record intervals of 0.02 miles (105.6 feet) (smallest granularity) along the route.

Surface distresses and rutting are determined from digital images that provide both the longitudinal and transverse profile. The images also provide an elevation profile of the road, creating a 3-dimensional image of the paved surface.

- Transverse Cracks
- Longitudinal Cracks
- Alligator Cracks
- Patching/Potholes
- Rutting

Each of the five surface distresses is assigned a computed surface distress index

- Transverse Crack Index
- Longitudinal Crack Index
- Alligator Crack Index
- Patching/Pothole Index
- Rutting Index

Surface distress data are classified as listed above, measured for severity, and quantified for extent. Classification, severity, and extent of these five surface distresses comprise the three main elements for calculation of Surface Condition Rating (SCR).

In addition to the five surface distresses, a Structural Crack Index is computed, which is a combination of the Longitudinal Crack Index and the Alligator Crack Index. The Structural Crack Index is then used in lieu of the LC and AC indices to compute SCR.

Roughness Condition Index - RCI

Additional condition data measured by DCV (lasers and accelerometers)

• Roughness (IRI)

Roughness is measured by FHWA's DCV and reported as International Roughness Index (IRI) in inches/mile. Using IRI, the Roughness Condition Index (RCI) is computed.

Pavement Condition Rating - PCR

Using the SCR (computed from the five surface distresses) and the RCI, an overall Pavement Condition Rating (PCR) is computed. The formula for PCR is:

```
Asphalt PCR = (0.60 * SCR) + (0.40 * RCI)
Concrete PCR = RCI
```

A detailed description of each distress index formula, roughness index formula, SCR and PCR is provided in this document.

Each classified surface distress will fall into one or more severity - LOW, MEDIUM, or HIGH based on criteria listed. For each severity, an extent is established based on the measured quantity of the distress within that severity. Within each severity individual distresses are assigned a Maximum Allowable Extent (MAE). For example, LOW severity transverse cracking may be allowed up to 21.1 cracks within a 0.02 mile interval before it reaches MAE and fails.

The index formulas are based on a scale of 0 to 100. A PCR index value of 100 would indicate a "new" road with no measurable distresses or rough ride. A PCR value of 60 is determined to be terminable serviceability and the road is considered failed. The range of index values with condition descriptors is:

POOR = (less than or equal to 60), FAIR= (61 – 84), GOOD= (85 - 94), EXCELLENT= (95 - 100)

Index values are generally computed based on cumulative deducts of the measured severities. As shown in the index formulas below, as any single severity reaches or exceeds MAE, the index computes to a value of 60 or less, and the road fails for that 0.02 interval.

Note: As a result of a unique combination of measured surface distresses and IRI, index values occasionally compute to less than 0 or greater than 100. In this instance, an index value less than 0 defaults to 0. Index values greater than 100 defaults to 100. For all indices, a higher value indicates a better road condition, and a lower value indicates a poorer road condition.

On the following page, Table 1 summarizes the different types of distresses measured.

| ASPHALT-SURFACED PAVEMENT DISTRESS TYPES WITH RUTTING AND ROUGHNESS | | | | | |
|---|--------------------------------|--|--------------------------------|---------------------------------------|--|
| Distress Type | Units Of Measure Converted To | | Defined Severity Levels? | Measured By | |
| Alligator Cracking | Square Feet | Percent of Lane Per 0.02 Mile | Yes | 3 Dimensional pavement imaging system | |
| Transverse Cracking | Linear feet | Number of Cracks Per 0.02 Mile | Yes | 3 Dimensional pavement imaging system | |
| Longitudinal Cracking | Linear feet | Percent of Lane Length Per 0.02 Mile | Yes | 3 Dimensional pavement imaging system | |
| Patching / Potholes | Square Feet | Percent of Lane Per 0.02 Mile | No | 3 Dimensional pavement imaging system | |
| Rutting | Inches | Rut Depth Per 0.02 Mile | Yes | 3 Dimensional pavement imaging system | |
| Roughness | IRI | *RCI Per 0.02 Mile | No | DCV – Lasers / Accelerometers | |

^{*}Note: Roughness is measured on concrete roadways, but surface distresses and rutting are not measured.

For concrete, PCR = RCI

Table 1. Distress summary

Alligator Cracking

Description:

Alligator cracking is considered a combination of fatigue and block cracking. It is a series of interconnected cracks in various stages of development. Alligator cracking develops into a many-sided pattern that resembles chicken wire or alligator skin. It can occur anywhere in the road lane. Alligator cracking must have a quantifiable area.

Severity Levels:

LOW

An area with little to no interconnecting cracks with no visible spalling. Cracks are less than or equal to a mean width of 0.25 in. (6mm). Cracks in the pattern are no further apart than 1 foot (0.328 m). May be sealed cracks with sealant in good condition and a crack width that cannot be determined.

MEDIUM

An area of interconnected cracks that form a complete pattern. Cracks may be slightly spalled. Cracks are greater than 0.25 in. (6 mm) but less than or equal to 0.75 in. (19 mm) or any crack with a mean width less than or equal to 0.75 in. (19 mm) and adjacent low severity cracking. Cracks in the pattern are no further apart than 6 in. (150 mm).

HIGH

An area of interconnected cracks forming a complete pattern. Cracks are moderately or severely spalled. Cracks are greater than 0.75 in. (19mm) or any crack with a mean width less than or equal to 0.75 in. (19mm) and adjacent medium to high severity random cracking.

A combination of observed crack width and crack pattern is used to determine overall severity of alligator cracking. Based on above description of each severity, the highest level of crack width and crack pattern determines overall severity as shown in Table 2.

| ALLIGATOR CRACKING SEVERITY LEVELS | | | | | | |
|------------------------------------|----------|---------------|------|------|--|--|
| | CRACK | CRACK PATTERN | | | | |
| | SEVERITY | LOW | MED | HIGH | | |
| CD A CIZ | LOW | LOW | MED | HIGH | | |
| CRACK WIDTH | MED | MED | MED | HIGH | | |
| WIDIII | HIGH | HIGH | HIGH | HIGH | | |

Table 2. Alligator Crack Severity Levels

Longitudinal Cracking

Description:

Longitudinal cracking occurs predominantly parallel to the pavement centerline. It can occur anywhere within the lane. Longitudinal cracks occurring in the wheelpath may be noteworthy.

Severity Levels:

LOW

Cracks with a mean width less than or equal to 0.25 in. (6 mm). This also includes sealed cracks with sealant in good condition and a width that cannot be determined.

MEDIUM

Cracks with a mean width greater than 0.25 in. (6 mm) but less than 0.75 in. (19 mm). Also, any crack with a mean width less than 0.75 in. (19 mm) and adjacent random low severity cracking.

HIGH

Cracks with a mean width greater than 0.75 in. (19 mm). Also, any crack with a mean width less than 0.75 in. (19 mm) and adjacent random medium to high severity cracking.

Transverse Cracking

Description:

Transverse cracking occurs predominantly perpendicular to the pavement centerline. It can occur anywhere within the lane.

Severity Levels:

LOW

Cracks with a mean width of less than or equal to 0.25 in. (6 mm). Sealed cracks with sealant in good condition and a width that cannot be determined.

MEDIUM

Cracks with a mean width greater 0.25 in. (6 mm) and less than or equal to 0.75 in. (19 mm). Also, any crack with a mean width less than 0.75 in. (19 mm) and adjacent random low severity cracking.

HIGH

Cracks with a mean width greater than 0.75 in. (19 mm). Also, any crack with a mean width less than 0.75 in. (19 mm) and adjacent random medium to high severity cracking.

Patching and Potholes

Description:

Patching is an area of pavement surface that has been removed and replaced with patching material or an area of pavement surface that has had additional patching material applied. Patching may encompass partial lane or full lane width. On full lane width patching; the total, contiguous length of patch may not exceed 0.100 mi. (0.161 km). (Any full-lane patch exceeding 0.100 mi. in length is considered a pavement change). Patching must have a quantifiable area.

Potholes are bowl-shaped holes of various sizes occurring in the pavement surface.

Manhole covers should not be rated as patches unless there is obvious patching around the manhole.

Speed bumps should not be rated as patches

Severity Levels:

There are no stratified severities for Patching and Potholes. They either are present or they are not.

RUTTING

Description:

Rutting is a longitudinal surface depression in the wheelpath.

Severity Levels:

LOW

Ruts with a measured depth of 0.20 inches to 0.49 inches Ruts less than 0.20 in. are not included in the distress calculations.

MEDIUM

Ruts with a measured depth of 0.50 inches to 0.99 inches

HIGH

Ruts with a measured depth greater than 1.00 inch

ROUGHNESS

Description:

Roughness is the measurement of the unevenness of the pavement in the direction of travel. It is measured in units of IRI (International Roughness Index), inches per mile, and is indicative of ride comfort.

Severity Levels:

There are no stratified severity levels for roughness. The roughness (or smoothness) of a road surface can be defined by IRI in the following table.

| IRI DESCRIPTIONS | | | | |
|-----------------------------------|-----------------------|--|--|--|
| Type of Road | Typical IRI (in/mile) | | | |
| New Road, no noticeable roughness | <90 | | | |
| Small level of roughness | 90 – 126 | | | |
| Road of average roughness | 126 – 190 | | | |
| Road with above average roughness | 190 – 253 | | | |
| Road with severe roughness | 253 – 380 | | | |
| Nearly impassable | >380 | | | |

Table 3. International Roughness Index

Roughness Collection Parameters

On shorter roads with a lower speed limit the usefulness in collecting and reporting IRI is negligible. Lower, inconsistent speeds can lead to a less accurate IRI value. Therefore RIP has put in place the following protocols for reporting IRI.

International Roughness Index (IRI) is not reported on routes with the following criteria:

- Posted speed limit is less than 25 mph
- Length of route is less than 0.50 miles

When a collected route has a posted speed limit of at least 25 mph and length of at least 0.50 miles, IRI will be collected except on road sections where the speed is less than 20 mph

Other situations may arise where the speed and length factors are met, but reporting IRI could lead to an inaccurate PCR. RIP will determine whether or not it is reasonable to report IRI on these routes on a case by case basis.

Index Formulas

Note: All index formulas listed below contain MAE applicable to 0.02 mile (105.6 feet) interval.

Alligator Crack Index

AC INDEX =
$$100 - 40 * [(\%LOW / 35) + (\%MED / 15) + (\%HI / 5)]$$

Where:

The values %LOW, %MED and %HI report the percentage of the observed pavement (0.02 mile, primary lane) that contains alligator cracking within the respective severities. These values range from 0 to 100.

%LOW = Percent of total area (primary lane, 0.02 in length), low severity %MED = Percent of total area (primary lane, 0.02 in length), medium severity %HI = Percent of total area (primary lane, 0.02 in length), high severity

Percent of total area is computed as:

square foot area of alligator crack severity (0.02 mile)*(lane width)

In AC_INDEX, the denominators 35, 15, and 5 are the Maximum Allowable Extents (MAE) for each severity. In other words, we will allow up to 35% of low severity alligator cracking for a 0.02 interval before failure, 15% for medium severity, and so on. As you can see, if any single severity reaches MAE the resulting index value is 60, or failure.

Longitudinal Crack Index

$$LC_{INDEX} = 100 - 40 * [(\%LOW / 175) + (\%MED / 75) + (\%HI / 25)]$$

Where:

The values %LOW, %MED, and %HI report the length of longitudinal cracking within each severity as a percent of the section length (0.02 mile, primary lane). These values are greater than or equal to 0 and can exceed 100.

%LOW = Percent of interval length (primary lane, 0.02 in length), low severity %MED = Percent of interval length (primary lane, 0.02 in length), medium severity %HI = Percent of interval length (primary lane, 0.02 in length), high severity

Percent of interval length is computed as:

length of respective longitudinal cracking (0.02 mile)*(105.6 ft.)

In LC_INDEX, the denominators 175, 75, and 25 are the Maximum Allowable Extents (MAE) for each severity. In other words, we will allow up to 175% of low severity longitudinal cracking for a 0.02 interval before failure, 75% for medium severity, and so on. As you can see, if any single severity reaches MAE the resulting index value is 60, or failure.

Structural Crack Index

$$SC_{INDEX} = [100 - ((100 - AC_{INDEX}) + (100 - LC_{INDEX}))]$$

Structural Crack Index is a combination of Alligator Cracking and Longitudinal Cracking, and is used in the SCR formula in lieu of AC and LC separately.

Transverse Crack Index

$$TC_{INDEX} = 100 - 40 * [(LOW / 21.1) + (MED / 4.4) + (HI / 2.6)]$$

Where:

The values LOW, MED and HI report a count of the total number of transverse cracks (reported to three decimals) within each severity level, where one transverse crack is equal to the lane width. These values are greater than or equal to 0.

LOW = Number of cracks in interval (primary lane, 0.02 in length), low severity MED = Number of cracks in interval (primary lane, 0.02 in length), medium severity HI = Number of cracks in interval (primary lane, 0.02 in length), high severity

Number of cracks is computed as:

Total length of transverse cracks
Lane width

In TC_INDEX, the denominators 21.1, 4.4, and 2.6 are the Maximum Allowable Extents (MAE) for each severity. In other words, we will allow up to 21.1 low severity transverse cracks for a 0.02 interval before failure, 4.4 cracks for medium severity, and so on. As you can see, if any single severity reaches MAE the resulting index value is 60, or failure.

Patching Index

PATCH_INDEX =
$$(100 - 40) * (\% PATCHING / 80)$$

Where:

The value %PATCHING reports the percentage of the observed pavement (0.02 mile, primary lane) that contains patching/potholes. This value ranges from 0 to 100.

%PATCHING = Percent of total area (primary lane, 0.02 in length)

Percent of total area is computed as:

square foot area of patching/potholes (0.02 mile)*(lane width)

There are no severity levels for patching. It either exists or does not.

There are no severity levels for patching. It either exists or does not. In PATCH_INDEX, the denominator 80 is the Maximum Allowable Extent (MAE) for each severity. In other words, we will allow up to 80% patching for a 0.02 interval before failure. As you can see, if patching/potholes reaches MAE the resulting index value is 60, or failure.

Rutting Index

RUT_INDEX =
$$100 - 40 * [(\%LOW / 535) + (\%MED / 205) + (\%HI / 40)]$$

Where:

20 rut depth measurements are taken per 0.02 interval for each of 2 wheel paths (left and right), resulting in a total of 40 measurements taken for both wheel paths. Each wheelpath is analyzed independently for rut severities. The values %LOW, %MED and %HI report the percentage of the 40 measurements within that severity. These values range from 0 to 200.

%LOW = Percent of LOW ruts in left wheelpath based on 20 ruts, plus percent of LOW ruts in right wheelpath based on 20 ruts.

%MED = Percent of MED ruts in left wheelpath based on 20 ruts, plus percent of MED ruts in right wheelpath based on 20 ruts.

%HI = Percent of HI ruts in left wheelpath based on 20 ruts, plus percent of HI ruts in right wheel path based on 20 ruts.

Percent of rut measurements within each severity can also be computed as:

$$\frac{(total\ number\ of\ ruts\ within\ each\ severity\ in\ both\ wheelpaths)}{20} \times 100$$

In RUT_INDEX, the denominators 535, 205, and 40 are the Maximum Allowable Extents for each severity; Low, Medium, and High, respectively. Only the MAE for high severity rutting can fail a section, since 200% of *only* low severity ruts would yield a rut index of 85 and 200% of *only* medium severity ruts would yield a rut index of 61.

Roughness Condition Index (Asphalt)

$$RCI = 32 * [5 * (2.718282^{(-.0041 * AVG IRI)})]$$

Where:

The value AVG IRI reports the average value of the Left IRI and Right IRI measurements for the interval (0.02 mile, primary lane). This value can range from approximately 40 to 999.0.

Average IRI is computed as:

There is no applicable threshold for failure for this index.

Roughness Condition Index (Concrete)

$$RCI = (-0.0012)(IRI^2) + (0.0499)(IRI) + 99.542$$

For concrete, PCR = RCI

Surface Condition Rating Index

SCR = Lowest Index Value Of: [SC_INDEX, TC_INDEX, PATCH_INDEX, RUT_INDEX]

Note: The modified SCR equation above combines AC_INDEX and LC_INDEX, and considers that a single AC/LC index value of the Structural Crack Index (SC_INDEX). The lowest of the four computed index values (SC_INDEX, TC_INDEX, PATCH_INDEX, or RUT_INDEX) becomes the SCR.

Where:

See above for determinations of SC_INDEX, TC_INDEX, PATCH_INDEX and RUT_INDEX.

The threshold for failure for this index is SCR = 60.Data Collection Vehicle Subsystems

Data on paved roads is collected by FHWA using a Pathway Services Inc. Data Collection Vehicle (DCV), called a PathRunner. The DCV is driven in the primary-direction lane at posted speed limits and less.

Cameras

Forward-facing and rear-facing video is collected as jpeg digital imagery files at a frequency of every 26.4feet.

Two forward-facing cameras are mounted above the vehicle cab, one pointed straight ahead and the other to the right shoulder providing seamless roughly 120 degree viewing. A third camera is mounted in the rear of the vehicle, recording the left shoulder.

| CAMERA SPECIFICATIONS TWO FORWARD / ONE REAR FACING CAMERA | | |
|---|--|--|
| Camera lens/type | Prosilica GT 2750 (GigE Technology) | |
| Image format | *.jpg | |
| Image resolution | 2750 x 2200, 18 frames/second | |
| Image pixel size | depends on distance | |
| Zoom ratio | 16mm Fixed | |
| | Aperture Range F 1.8 – Infinity (P-Iris, | |
| Iris range | Automatic | |

Pavement Imaging and Rutting

High resolution rutting data and surface imaging are collected in a single data stream using a three-dimensional (3D) pavement surface transverse profile data acquisition system. The 3D camera captures a laser line as it is projected over the pavement surface and uses the location of this line to measure the height deviations of the pavement surface. These height deviations can be used to calculate rutting in both wheelpaths. These deviations also provide a grayscale image detailing the change in height throughout the surface, i.e. providing depth measurements for cracking.

| THREE-DIMENSIONAL PAVEMENT SURFACE AND TRANSVERSE PROFILE DATA ACQUISITION SYSTEM Surface Image Specifications | | |
|--|--|--|
| | | |
| Image width | 4 meters (3950 mm nominal) | |
| Laser class | 3B | |
| Power | 16W (Two lasers @ 8W Ea) | |
| Vehicle speed limitations | 62 mph | |
| Environment | Dry pavement, day or night | |
| Sensor size (approximate) | 1536 pixels x 512 pixels | |
| Image display length | 26.4 feet | |
| Rutting Specifications | | |
| Reported rut depth units | Inches | |
| Vehicle speed limitations | Up to 62 mph | |
| Sampling rate | 3000 profiles/second | |
| Transverse resolution | 1536 points/profile | |
| Transverse field-of-view | 14 feet | |
| Depth accuracy (nominal) | <1mm | |
| Environment | Dry pavement, day or night, above 32 degrees F | |
| Adherence to specifications | ASTM E1703M-95 (reapproved 2005) | |

Distance Measuring Instrument (DMI)

The DMI (Distance Measuring Instrument) obtains road length measurements that are accurate to 0.15% for speeds up to 60 mph. The DMI is connected to the hub of the rear wheel on the driver's side, and is calibrated to the revolutions of the rear vehicle axle on a regular basis.

Roughness (IRI)

| IRI SPECIFICATIONS | | |
|-----------------------------|--|--|
| Reported IRI units | Inches/mile | |
| Vehicle speed limitations | 12-62 mph | |
| IRI equipment certification | Texas Transportation Institute (TTI) | |
| Wavelengths accommodated | 0.5 feet to 300 feet | |
| IRI computed & reported | World Bank Technical Paper Number 46 | |
| Environment | Dry pavement, day or night, above 32 degrees | |
| Adherence to specifications | ASTM E950 Class 1 & AASHTO M 328 | |

The collection system includes a South Dakota type laser profiler manufactured based on active Class 1 ASTM E950 standards. The dynamic profile of the pavement surface is collected from which the IRI roughness data is computed. The sensors include one accelerometer on each wheelpath, one height sensor (laser) on each wheelpath, and a distance transducer.

GPS & Inertial Systems

GPS is collected by an onboard system employing Omnistar real time correction and a spinning gyroscope to provide accurate positioning data in instances of satellite obstruction. All GPS coordinates are tied to an image and linear distance measurements.

| GPS SPECIFICATIONS | | |
|-----------------------------|----------------------------------|--|
| Static accuracy | Sub-meter | |
| Dynamic accuracy | 2-3 meters | |
| Receiver | 12 satellite tracking | |
| Coordinate system | Lat Lon WGS 84 | |
| Environment | Day or night | |
| Cross-slope | ± 1.75% | |
| Grade | ± 1.75% | |
| Adherence to specifications | ASTM E1703M-95 (reapproved 2005) | |

*NOTE – GPS accuracy is dependent on many different factors. Satellite constellation, tree coverage, GPS receiver quality, and real-time correction availability can all affect the locational and elevation accuracies. The elevation (z coordinate) accuracy is less dependable than locational or horizontal accuracy (x/y coordinates or latitude/longitude). In areas of heavy tree coverage or poor satellite constellations, elevation data can vary by as much as +/- 100 feet.

Appendix B

Methodology for Determining Condition Ratings Using Manual Rating Procedures

Description of Manual Rating Methods

In 2013, the Federal Highway Administration updated existing Manual Rating Procedures in an effort to better align pavement conditions for Manually Rated Routes and Parking with the Highway Pavement Management Application (HPMA). HPMA is the Pavement Management System used by the FHWA to store inventory and condition data from the Road Inventory Program (RIP) and forecast future performance using prediction models. HPMA uses pavement condition data (collected by the Road Inventory Program) to develop life cycles for pavements and recommend treatments to maximize useable pavement life while minimizing costs associated with maintenance and repair.

The Federal Highway Administration (FHWA) developed a set of manual rating methods for pavement that are appropriate for Federal Roadways. Two different methods were developed for linear roads and a separate method was developed for parking areas and nonlinear roads. These methods employ a 0 to 100 rating scale and improve consistency and objectivity in the manual evaluation of surface distresses. They are compatible with ratings that are collected by the automated Data Collection Vehicle (DCV).

- The first of the two manual evaluation methods for roads uses rating criteria to assign index values to each distress type based on a visual evaluation of severity and extent.
- The second manual evaluation method for roads is very time demanding and is best employed on only a select set of routes which may have the highest visitor use and require a more intensive assessment. This method will be used for the Manual Rating of Function Class 1, 2, 7, and 8 Roads. This method is based on measurements that are recorded for each instance of a surface distress. These measurements are converted into index values using conversion formulas.
- Parking areas and non-linear roads are rated similar to the first method shown above, however, there are some slight differences due to the non-linear nature.

The details and criteria used for each of these rating methods are outlined below.

Visual Inspection Method for Manually Rating Secondary Roads

The visual inspection method for manually rated roads uses condition rating criteria that have been developed by FHWA. This criteria is based on a visual evaluation of the severity and extent of distresses to determine the overall condition of the roadway. This method is used for secondary roads that are Functional Class 3, 4, 5, and 6. This constitutes the majority of manually rated roads collected by the Road Inventory Program.

Rating Section Lengths

For this method, Manually Rated Roads are rated in sections. These sections may be made based on length of changes in surface type or condition as described below. The ratings are then aggregated to give an overall rating for the Route:

- Rating sections should be no longer than 0.25 miles in order to keep the area being rated manageable.
- A new rating section may be started based on changes in condition, width, or surface type if these changes represent a significant portion of the route (are not isolated instances).
- If the road condition, width, and surface type remain constant then new sections do not need to be created unless the road exceeds 0.25 miles.

Rating Criteria

For this method, Manually Rated Roads are evaluated using a visual inspection of the six distress types listed below. Each distress is assigned one of five index values. An overall Surface Condition Rating (SCR) and Pavement Condition Rating (PCR) are calculated based on these index values.

- Alligator Cracking
 - o Rating based on percentage of road surface affected
- Longitudinal Cracking
 - o Rating based on severity level (crack width) and percentage of road section length of longitudinal cracks
- Transverse Cracking
 - o Rating based on crack width, crack spacing, and percentage of surface affected
- Patching
 - o Rating based on percentage of road surface affected
- Rutting
 - o Rating based on percentage of road section length affected by visible rutting (>1 inch depth) that requires remediation
- Roughness
 - o Manual assessments of roughness are not made due to the subjectivity of the measurement. Therefore, roughness is not incorporated into the PCR calculation of manually rated roads.

Concrete Routes also receive a PCR rating based on visual evaluation of the following six distress types.

- Slab Faulting at Joints
- Slab Cracking and breakup
- Surface Delamination and Pop-outs
- Joint Distresses
- Patching

Distress Measurement Method for Manually Rating Primary Roads

A more intensive and time demanding assessment than our standard method was developed for Primary roads that are functional class 1, 2, 7, or 8. These high visitation roads are usually accessible by the automated Data Collection Vehicle but in rare instances may need to be manually rated. The method developed is based on measuring each instance of a distress. These measurements are totaled over each section length being measured and are then converted into index values between 0 and 100 (100 being a road with no distress) using index formula equations outlined below. The goal of this method is to produce measured index values which are directly comparable to the automated DCV.

Rating Section Lengths

For the distress measurement method roads are broken into sections in order to rate. Distress measurements are totaled for each section separately in order to determine the index value for that particular section. The section length to be rated is determined based on the following rules:

- Rating sections are between 0.25 and 0.50 miles long
- A new rating section is created if there is a significant change in condition or pavement width
- If there are no significant changes in condition or pavement width, rating sections are broken at equal intervals, typically 0.50 miles

Manual Distress Measurements

Alligator Cracking

- Alligator cracking is measured by area (square feet). Instances of Alligator cracking are measured along the length and multiplied by the average width of the distressed area.
- The index for alligator cracking takes the total area of cracking compared to the interval length and converts it to a percentage. That percentage is then input into an index formula that yields a value between 0 and 100 (0 being the most distressed).
- Severity levels are not defined for manually measured Alligator cracks. The Alligator Crack Index formula is calculated based on an assumption of medium severity.

Longitudinal Cracking

- Longitudinal cracking (cracking in the direction parallel to the roadway) is measured by length (ft.).
- The index for longitudinal cracking takes the total length of cracking compared to the interval length and converts it to a percentage broken down by severity. That percentage is then input into a formula that yields a value between 0 and 100 (0 being the most distressed).
- Two severity levels are defined for manually measured Longitudinal Cracks. Lower severity cracks are those with a mean width of less than 0.25 inches. Sealed cracks with sealant in good condition are also considered lower severity. Higher severity cracks are those with a mean width of greater than 0.25 inches.

Transverse Cracking

- Transverse cracking (cracking in the direction perpendicular to the roadway) is measured by length (ft).
- The index for transverse cracking takes the total number of cracks (1 crack would encompass the full lane) broken down by severity. The total numbers of each severity are then put into a formula that yields a value between 0 and 100 (0 being the most distressed).
- Two severity levels are defined for manually measured Transverse Cracks. Lower severity cracks are those with a mean width of less than or equal to 0.25 inches. Sealed cracks with sealant in

good condition are also considered lower severity. Higher severity cracks are those with a mean width of greater than 0.25 inches.

Patching and Potholes

- Patching and Potholes are measured by area (square feet). Instances of Patching are measured along the length and multiplied by the average width of the patch.
- Instances of full lane width patching cannot be longer than 0.100 miles, otherwise is should be considered a pavement change rather than a distress.
- There are no stratified severities for Patching. It is either present or it is not.

Rutting

- Visible rutting is measured by length (ft.) in each wheel path. Only visible ruts are rated, which are ruts greater than 1 inch deep.
- All rutting recorded in a manual rating is considered to be high severity (> 1 inch). Lesser severities are generally not distinguishable in a visual inspection.

Roughness

• Manual assessments of roughness are not made due to the subjectivity of the measurement. Therefore, roughness is not incorporated into the PCR calculation of manually rated roads.

Index Formulas for Distress Measurement Method:

The method used to convert distress measurements into index values is shown below. The Surface Condition Rating and Pavement Condition Rating are calculated based on these index values.

Alligator Crack Index for Manual Rating:

AC INDEX =
$$100 - 40 * (\% ALLIGATOR / 15)$$

Where:

% ALLIGATOR = Percent of total area of section being rated that contains Alligator cracking.

Longitudinal Crack Index for Manual Rating:

$$LC_{INDEX} = 100 - 40 * [(\%LOW / 175) + (\%MED / 75)]$$

Where:

%LOW = Percent length of longitudinal cracks where crack width less than or equal to 0.25 inches

%HIGH = Percent length of longitudinal cracks where crack width greater than 0.25 inches

Transverse Crack Index for Manual Rating:

$$TC_{INDEX} = (100 - 40) * [(LOW / 21.1) + (MED / 4.4)]$$

Where:

LOW = Count of the total number of transverse cracks within the section length where one transverse crack is equal to the lane width and the crack width ≤ 0.25 inches HIGH = Count of the total number of transverse cracks within the section length where one transverse crack is equal to the lane width and the crack width ≥ 0.25 inches

Number of cracks is computed as:

Total length of transverse cracks/Lane width

Patching Index for Manual Rating:

Where:

%PATCHING = Percentage of pavement section that contains patching/potholes.

Rutting Index for Manual Rating:

$$RUT_INDEX = 100 - 40 * (\%RUTTING / 40)$$

Where:

%RUTTING = Percentage length of high severity rutting within the section being measured.

Method for Manually Rating Paved Parking Areas and Non-Linear Roads

Parking areas are evaluated based on a visual inspection using condition rating criteria that has been developed by FHWA. This criteria is based on a visual evaluation of the severity and extent of distresses to determine the overall condition of the parking area. This overall condition rating is linked to the level of repair and rehabilitation practices required.

A distress index is determined for each of the distresses listed below for Asphalt and Concrete Parking areas. The overall Pavement Condition Rating (PCR) of the parking lot is driven by the most severe distress present.

Rating Criteria:

Asphalt Parking Distress Types

- Alligator Cracking
 - o Rating based on percentage of road surface affected
- Longitudinal, Transverse and Block cracking
 - o Rating based on crack width, crack spacing, and percentage of surface affected
- Rutting and Distortions
 - o Rating based on percentage of road surface affected
- Hot Mix Asphalt Patches
 - o Rating based on overall percentage of HMA patches
- Potholes and Cold Patches
 - o Rating based on percentage of road surface affected
- Surface Raveling and Bleeding
 - o Rating based on percentage of road surface affected

Concrete Parking Distress Types

- Slab Faulting at Joints
 - o Rating based on height differential between adjacent slabs or pieces of broken slabs
- Slab Cracking and breakup
 - o Rating based on quantity of cracks and if slab is acting to able distribute load as designed
- Surface Delamination and Pop-outs
 - o Rating based on percentage of road surface affected to include pop-outs, spalls and surface delamination
- Joint Distresses
 - o Rating based on sealant condition and concrete distresses at/or adjacent to joints
- Patching
 - o Rating based on percentage of road surface affected

Curb Inspection and Treatments

During inspections of manually rated parking lots and routes, the curb reveal and overall curb condition are evaluated. The curb condition is used to determine a recommendation.

Curb Reveal

The vertical distance on the curb face from the gutter flow line or pavement surface to the top of curb. When resurfacing adjacent to curb, the resulting curb reveal should be no less than 4 inches. Additionally, when resurfacing adjacent to a gutter, the resulting pavement surface should be flush with the gutter pan. In cases where a resurfacing would violate either of these parameters, the surface may need to be milled or removed to adjust to these field conditions.

Curb Recommendations

The following treatment categories are based on the overall percentage of distresses along the entire curb structure for a specific pavement structure. Distresses include spalling, cracking, loss of material and any other damage which prevents the curb from conveying storm runoff or failing to perform in its intended function.

- Overall curb damage ranging 0%-5%:
 - o DO NOTHING
- Overall curb damage ranging 5%-20%
 - o LIGHT REPAIR
- Overall curb damage ranging 20%-50%
 - o MODERATE REPAIR
- Overall curb damage greater than 50%:
 - o REPLACE

GPS for Manually Rated Roads and Parking

GPS information for Manually Collected Cycle 6 Routes will be recorded using the latest hardware and software by TRIMBLE 6000 Series GeoXT. Cycle 6 GPS collection units will allow access to GPS and GLONASS, improving overall GPS reliability, accuracy and precision to submeter accuracy. Additionally, the new GPS units have an enhanced ability to collect accurate signals underneath tree cover or adjacent to buildings or natural terrain with extreme vertical gradations that typically reduce GPS accuracy. Trees and buildings create "satellite shadows", limiting the areas where you can reliably collect high-accuracy GPS data. The updated GPS receiver will deliver improved usable data under tree canopy or in natural or urban canyons. Routes that were previously collected accurately will not be recollected in Cycle 6.

| TRIMBLE 6000 SERIES GeoXT GPS SPECIFICATIONS | | |
|--|--|--|
| Receiver | Trimble Maxwell™ 6 GNSS chipset | |
| Channels | 220 channels | |
| Systems | GPS / GLONASS / WAAS | |
| Accuracy | Sub-meter | |
| Operation Temperature | -20 °C to +60 °C (-4 °F to +140 °F) | |
| Cellular and Wireless | UMTS / HSDPA / GPRS / EDGE / Wi-Fi / Bluetooth | |
| Internal Still Camera w/ GEOTAG ability | Autofocus 5 MP (JPG) and WMV w/ Audio | |

Appendix C Description of Cycle 6 Deliverables

Interim Report Delivery

Partial report will be primarily focused on manually collected routes. The report will be released approximately four months after manual collection of parking lots and other manually collected routes to provide NPS an immediate report on the condition of routes collected manually.

The Interim Report Delivery consists of an Interim Report PDF that contains the following:

- Parking lot and manually rated route conditions
- Route ID Reports
- Route ID Changes Report.

Please note that since the Data Collection Vehicle will have not collected data at this point in time, the following will not be in the Interim Report:

- No park summary information will be provided in the report
- No DCV data will be provided in report
- No road logs will be provided in report
- No maps will be provided in report
- Any mileages collected will be approximate

All data provided in the Interim Report will also be included in the Final Report.

Final Report Delivery

The Final Report will contain all data collected by Manual Inspection and the Data Collection Vehicle. All information provided in the Interim Report will be included in the Final report. Manually collected information reported in the Interim Report may be updated in the Final Report if pavement conditions have substantially changed between the Manual Inspection and Data Collection Vehicle Inspection or other unforeseen circumstances.

The final report will be released approximately 8 months after the Data Collection Vehicle completes its collection of that specific park.

Data included in the Final Report package consists of the following:

- Condition Photos: All photos taken during Cycle 6.
- **Data Video:** Data and video of each route collected by the DCV will viewable through PATHVIEW software. PATHVIEW Software and training will be provided to NPS personnel by Eastern Federal Lands.
- **GPS on All Rated Routes:** All GPS data collected from the DCV will be provided. Parking areas, some roads, and other paved areas that are not fully drivable with the DCV are collected manually by field technicians. GPS is collected for these routes using portable Trimble GPS units.
 - o GPS will be provided as Shapefiles and KMLs
 - o All GPS data related to road collection with be linear referenced to the collected length
- Geodatabase Background and Metadata: In addition to this park report, a geodatabase containing both tabular and spatial data specific to this park has been provided.
 - o All data disseminated in the preceding report has been obtained from the tables and fields within said geodatabase. The geodatabase can be referenced for tabular data via Microsoft Access or for both tabular and spatial data via ESRI's ArcGIS Suite of software which consists of; ArcMap, ArcCatalog and ArcExplorer.
 - o Consolidating the RIP data into one database creates a seamless relationship of tables and geographic data. It allows RIP to facilitate easier updates and enhancements in the future. A geodatabase can be thought of as simply a database containing spatial data. A complete and thorough description of the tables and fields contained within this geodatabase can be found in the metadata. The metadata is attached directly within the geodatabase and can be accessed via ESRI's ArcCatalog.
- **Report (RIP Report and Route ID):** A PDF report will be provided that includes a list of all routes and key data. Condition reports for each route will be included. All changes, additions and deletions to any route will be included in the report. Features along routes will not be collected in Cycle 6.

Partial DCV Collections

Additional Partial DCV Collections may be done on specific parks depending on their size and overall mileage of routes within its boundaries during Cycle 6. Parks with greater than 10 miles of paved roadways will receive at least one additional Partial DCV collection during Cycle 6. Data collected during these Partial DCV Collections will not result in the delivery of an additional report to the park.

Data collected by the DCV during Partial DCV Collection will be used to improve HPMA modeling by providing additional "snapshots in time" of park pavement conditions. This improved HMPA modeling will assist in the programing and budgeting of future projects which will help maximize the life of pavement infrastructures.

Instead of receiving a report of conditions collected during the Partial DCV collection, the park will receive a formal letter from the Road Inventory Program requesting coordination for the additional Partial DCV collection, identifying the dates of the Partial DCV Collection and will reinforce the purpose and importance of the Partial DCV Collection.

Appendix D Glossary of Terms and Abbreviations

Glossary of Terms and Abbreviations

| TERM OR ABBREVIATION | DESCRIPTION OR DEFINITION |
|----------------------|--|
| AC | Alligator Cracking |
| CRS | Condition Rating Sheets (Section 5) |
| Curb Recommendation | Curb remediation based on overall percentage of curb distress |
| Curb Reveal | Height of curb exposed from gutter flow line to top of curb |
| DCV | Data Collection Vehicle |
| Excellent | Excellent rating with an index value of 95 to 100 |
| Fair | Fair rating with an index value from 61 to 84 |
| FUNCT_CLASS | Functional Classification (see Route ID, Section 2) |
| Good | Good rating with an index value from 85 to 94 |
| IRI | International Roughness Index |
| HPMA | Highway Pavement Management Application |
| Lane Width | Width from road centerline to fogline, or from centerline to edge- of-pavement when no fogline exists |
| LC | Longitudinal Cracking |
| MRR | Manually Rated Route |
| MRL | Manually Rated Line |
| MRP | Manually Rated Polygon |
| N/A | Not Applicable |
| NC | Not Collected |
| PATCH | Patching and Potholes |
| Paved Width | Width from edge-of-pavement to edge-of-pavement |
| PCR | Pavement Condition Rating |
| PKG | Parking Area |
| Poor | Poor rating with an index value of 0 to 60 |
| RCI | Roughness Condition Index |
| SC | Structural Cracking |
| SCR | Surface Condition Rating |
| TC | Transverse Cracking |